


# DIE-CUTTING BASICS




## CUTTING UNIT / CYLINDERS



$$\text{Gap} = \frac{\varnothing \text{ bearer rings} - \varnothing \text{ magnetic zone}}{2}$$

European standard = 0.480 mm (0.0189")  
US standard = 0.483 mm (0.019")

### Proper cylinder dimensions




### Recommendations

- Use an **adjustable anvil roller** (e.g., Wink SmartGap) for variable gap adjustment
- Install **pressure gauges** (e.g., Wink ForceControl) for continuous monitoring of cutting pressure



## LABEL STOCK




- **Paper** bursts easily and can be cut with a wider blade angle, while soft **filmic materials** need (almost) full penetration and sharper angles
- **Abrasive facestocks** increase tool wear, thus special coatings like MCR are recommended
- Extreme **adhesives** (e.g. hotmelt) require non-stick coating of the die
- **Liner** type & thickness determine die height


### Die-cutting = compressing

The cutting tool has to cut through the face material and the adhesive layer, without damaging the liner material.

The die blade compresses the face material until it bursts.




## FLEXIBLE DIES




Every flexible die is custom-made for the desired application.

The combination of cutting unit/cylinders and label material determines the die specifications.




### SUPER CUT

#### Basic versions




#### SuperCut 90

Standard adhesive and thermal papers



#### SuperCut 70

Films such as PE 85, PP, PET; also paper materials



#### SuperCut Special

Special films and other difficult materials


### Finishing options

- For maximum performance and longer lifetime
- Flexibility, tolerance and magnetic adhesion of the dies are not impaired




#### Laser hardening

Cutting through of filmic materials




#### Non-stick coating

Against adhesive and ink residues; four variants available



#### MCR coating

Abrasive facestocks (thermal paper, opaque white, etc.)




#### MCR + Laser

Cutting-through of very abrasive materials; long runs

### ABC of Die-Cutting

For more detailed information, please see our free "ABC of Die-Cutting" brochure.

The guide describes possible causes of unsatisfactory cutting results and how you can avoid or remove these problems.



## CARE INSTRUCTIONS

### Careful handling

- Never bend a flexible die or put it down on the blades.
- Always clean cylinders and reverse side of the die with certified cleaners before usage.
- Only use special die lifters to remove dies.
- Lift cylinders into and out of the machine carefully.
- Increase cutting pressure very slowly.

### Safe storage

- Remove all ink and adhesive residues after usage.
- Oil tools with acid-free oil before storing.
- Store the dies in file hangers or in the original cardboard tubes/packages.
- Keep certificate of quality and the cutting sample.

### Flawless conditions

- Measure the gap regularly.
- Check bearers, bearings, pressure rollers and gears regularly.
- Ensure that bearings and shafts are running free from backlash.
- Pay attention to adequate pressure between magnetic and anvil cylinder.



## TROUBLE-SHOOTING

When cutting problems occur, always check these points first:



### Cutting unit / cylinders

- Contaminants / Wear
- Pretension / cutting pressure
- Gap (Clearance)
- Circumference-width relation



### Material

- Type and composition of the material
- Liner thickness
- Application (kiss-cutting and/or cutting-through etc.)



### Flexible die

- Contaminants
- Wear
- Production errors

Apart from this, you should always **recheck the order details**.