

# OTCO Annual Class III & IV Workshop *for Water and Wastewater Operators*

## **Large Diameter Sewer Rehabilitation, a New Approach**

July 31, 2019

Matthew Kiefer, P.E.

Columbus, Ohio



# Safety Moment

ILLNESS TYPE	SYMPTOMS	RESPONSE
Heat Cramps	<ul style="list-style-type: none"><li>• Painful cramps in arms, legs, stomach or back that occur suddenly at work or later at home</li><li>• Tingling in hands and feet</li><li>• Heavy sweating.</li></ul>	<ul style="list-style-type: none"><li>• Drink water and electrolyte solutions such as Gatorade</li><li>• Eat fruit such as bananas</li><li>• Take a break in a cool area.</li></ul>
Heat Exhaustion	<ul style="list-style-type: none"><li>• Heavy sweating</li><li>• Headache</li><li>• Cool, pale, and moist skin</li><li>• Tired and weak</li><li>• Very thirsty</li><li>• Panting or breathing rapidly</li><li>• Blurred vision</li></ul>	<ul style="list-style-type: none"><li>• <b>Get medical attention</b></li><li>• Move to an air-conditioned room or shaded area</li><li>• Lie down with feet slightly elevated</li><li>• Loosen or remove excess clothing and apply cool-water-soaked cloths or ice packs to the body</li><li>• Drink water or electrolyte drinks in moderate amounts</li></ul>
Heat Stroke	<ul style="list-style-type: none"><li>• Sweating stops, causing body temperature to rise</li><li>• Person is weak, confused, upset or acting strangely</li><li>• Hot, dry, red skin</li><li>• Headache or dizziness.</li><li>• In later stages the person can pass out and have convulsions.</li></ul>	<ul style="list-style-type: none"><li>• <b>This is a medical emergency – call for assistance immediately.</b></li><li>• Cool the individual by any means possible, including pouring water on them, ice pack and fanning.</li><li>• Do not give the individual anything to drink.</li></ul>

# About Myself

- Originally from Toledo area
- Civil Engineer (University of Dayton)
- Cheap, frugal, stingy...according to my wife
  - Building a wood deck instead of composite (that my wife requested)

# About Myself

- Worked extensively on sewer assessment and rehabilitation projects
- **Alum Creek (North & Middle) LDSA & Detailed Design** – Project Manager for the assessment, detailed design, and services during construction of around 87,000 LF of 42-inch to 96-inch reinforced concrete sewer using CCTV, Sonar, Laser, and man entry methods. The sewer was repaired with Shotcrete and CIPP lining.
- **Blacklick Creek Main Trunk LDSA** – Project Manager for the assessment and detailed design of 116,000 LF of 42-inch to 96-inch reinforced concrete sewer using CCTV, Sonar, Laser, and man entry methods.
- **Scioto Main Trunk LDCA** – Project Manager for the assessment of 105,000 feet of 36-inch to 180-inch sewer using CCTV, Sonar, and man entry methods. Portions of the project include a deep tunnel with access shafts spaced at around 2,000-3,000 feet making access a challenge. Performed analysis of the concrete using multiple.
- Over 800,000 LF of sewer inspection oversight
- 314,000 LF of Large Diameter Sewer Inspection

# The Need

- EPA estimates \$271 Billion is needed over the next 25 years for water/wastewater
- 95% is spent at the local level
  - U.S. Conference of Mayors
- Value is important to our clients

# No wonder we can't keep up

- Sewer repair costs are astronomical
  - Especially when all costs are factored in
- 2,100 LF 48” Cured In Place - \$2.5M
  - Cleaning, televising, bypass pumping, pavement repairs, seeding...
  - Not counting engineering and CM fees
- City of Columbus
  - 2,800 miles of Sanitary Sewers
  - 2,500 miles of Storm Sewers

# No wonder we can't keep up

- Need a more efficient inspection and prioritization process
- And a surgical approach to repairs
- Cannot afford to be ultra conservative
  - Wholesale lining just won't work

# Typical Inspection Approach

- Large Diameter >36”
  - But were talking 60”+
- CCTV Crawler
  - Simple to advanced





# Typical Inspection Approach

- More Advanced Track Steered Systems
  - Debris
  - High Flow / Velocity
  - Long Distance – 5,000'
  - Around Bends

# Typical Inspection Approach

- Floating system available for high flows
- Advanced Sensors include:
  - HD CCTV
  - Sonar
  - Laser Profiling
  - H<sub>2</sub>S
  - Temperature



## ...and the Results?


- Excellent lighting and HD CCTV
- Sonar and sediment data every foot of pipe
  - Profile plot showing total sediment
- Laser measurements showing internal diameter and wall loss
- Continuous H<sub>2</sub>S readings
- Continuous temperature readings

# ...how do we use this data and did we need it?

- HD CCTV of debris build up, grease, deposits...
  - Often was not seeing the concrete surface
  - Had to enter sewers to remove build up and see the pipe
- Sonar
  - Found that deposits were overall predictable based on CCTV
  - Crawler struggling over debris
  - Worse at surcharging locations w/low flow

-cont-

...how do we use this data  
and did we need it?




...how do we use this data  
and did we need it?

- Laser Profiling
  - Not necessary for every foot
  - Spot checks would be sufficient
- H<sub>2</sub>S
  - Not necessary every foot
  - Spot checks with Odalog
- Temperature
  - Never used the information

# Blacklick Creek Sanitary Subtrunk

- 13,870 feet
- 42-inch RCP
- 40 years old



# Blacklick Creek Sanitary Subtrunk

- Inspected with HD CCTV
- Contractor was concerned about pipe collapse
- Concrete falling off walls





# Blacklick Creek Sanitary Subtrunk

- Hire sewer cleaning contractor to power wash
- Man Entry Inspection at Manholes
- Concrete Sounding
- pH Measurement



# Blacklick Creek Sanitary Subtrunk

- Condition was much better than appeared on CCTV
  - Many times can't see the actual concrete (but you think you do)
- Softened concrete paste and exposed aggregates
- Poor durability properties (high permeability)



# Blacklick Creek Sanitary Subtrunk

- Deferred \$6M in repair costs
- Allowed higher priority repairs to move forward



# Alum Creek Trunk North

- Minimal rebar cover
- Only 1/2" concrete loss



# Alum Creek Trunk North

- Sound concrete between the spot defects
- Full lining is unnecessary
  - CIPP, etc.
- Condition looks worse on CCTV than it really is



# We Propose a Different Approach

- Basic CCTV Inspection
- Man Entry Concrete Testing
- H<sub>2</sub>S Testing

# We Propose a Different Approach

## – Basic CCTV Inspection

- Rent your own / buy your own?
- PACP Coding needed?
  - GO pro?
- Train your staff
- Get a representative sample
  - Target critical locations
- Pole camera spot checks at manholes
- Use GIS or Asset Management to prioritize condition

# We Propose a Different Approach

- Man Entry Inspection to Test Concrete Condition
  - Concrete Sounding & Scraping





# We Propose a Different Approach

- Man Entry Inspection to Test Concrete Condition
  - Core Samples
    - Strength, Petrographic Analysis
    - Depth of acid penetration
    - Permeability of concrete



# We Propose a Different Approach

- Use Man-Entry Inspection to Test Concrete Condition
  - pH Readings
    - Needed for surface preparation and application of repair materials
  - Limits of Spot Defects
    - Help with bid quantities
  - Rebar locator
    - Verify cover, size, spacing



# We Propose a Different Approach


- Measure H<sub>2</sub>S at strategic locations
- Rather inexpensive to rent and easy to deploy



Inspection is Complete...  
now what?


# Alum Creek Trunk North

- 2010 Condition Assessment and BCE
- 50 years old
- 38,000 LF
- 42" to 78" RCP



# Alum Creek Trunk North

**Good Condition**  
6 Segments (9%)



**Fair Condition**  
29 Segments (43%)



**Poor Condition**  
32 Segments (48%)



# Alum Creek Trunk North

Alternative	Includes	Length of Repair
Do nothing (Televising)	Routine CCTV/Sonar	N/A
Spot repair	2" thick Shotcrete, pipe cleaning, and routine CCTV/Sonar	Grade 4 & 5 defects in the sewer segment that can be spot repaired
Lining	Cured in place pipe (CIPP), pipe cleaning, and routine CCTV/Sonar	Entire sewer segment
Pipe replacement	Open cut replacement and routine CCTV/Sonar	Entire sewer segment


# Alum Creek Trunk North

- Spot Repair
- Replacement
- Lining
  - CIPP
  - Sliplining
  - Grout in Place Lining
    - spiral wound, panel, segmental



# Alum Creek Trunk North

- Rigorous Alternatives Analysis of Each Sewer Segment
  - Lifecycle Costs
  - Consequence of Failure
  - Probability of Failure
  - “Triple Bottom Line”
    - Environmental
    - Social
    - Economic



# Alum Creek Trunk North

- BCR>1 is a good investment
- Wholesale lining = 1.14
- Spot repairs = 14.5

Financial Metrics	Do Nothing	Spot Repair	Lining	Replacement	Combined
Net Present Value (NPV)	\$ (81,366,887)	\$ (67,716,157)	\$ (76,600,459)	\$ (103,617,001)	\$ (67,427,490)
Total Annual Cost	\$ (9,908,909)	\$ (2,444,563)	\$ (1,869,002)	\$ (2,284,558)	\$ (2,139,274)
Total Project Capital Cost	\$ -	\$ (1,000,250)	\$ (27,117,055)	\$ (63,966,617)	\$ (5,884,555)
Total O&M Cost	\$ (710,742)	\$ (580,904)	\$ (430,270)	\$ (345,356)	\$ (535,575)
Total Risk Cost	\$ (80,656,145)	\$ (66,135,002)	\$ (49,053,134)	\$ (39,305,027)	\$ (61,007,360)
Total Reduced Risk	N/A	\$ (14,521,143)	\$ (31,603,011)	\$ (41,351,118)	\$ (19,648,785)
Benefit / Cost Ratio (BCR)	N/A	14.52	1.17	0.65	3.34

# Alum Creek Trunk North

- Rehabilitation Included:
  - Cementitious spot repairs
    - Surface prep to sound concrete
    - Restore surface to original condition
  - Cementitious Continuous Lining
    - 2” thick shotcrete w/polypropylene fibers
    - Many products available
    - Many admixtures with corrosion resistance
    - Want a mix that has low permeability
    - High strength mix is available
    - Pipe within a pipe

# Shotcrete

- Placed shotcrete field tested at 8,000 - 10,000 psi average




# Polymeric coatings

- Polyurethane Coatings
  - Requires dry surface
- Epoxy Coatings
- Materials are very costly
  - Less favorable BCR

# Scioto Main 120”

- Linabond
- PVC panels adhered by primer and epoxy
- Failed after 8 years



# Scioto Main 120"

- Linabond can't be repaired
- Must be removed if another coating is installed
  - Grinding?
  - Abrasive Blasting?
- Plastic liners can be hard to maintain when they fail



# Summary

- Increase Inspection Frequency
- Decrease Inspection Cost
- Repair what is critical
- Avoid ultra conservative repairs (i.e. wholesale lining)
- Use a surgical approach
- Consider cementitious products first



Thank you for your time.  
Any questions?



This concludes this Session for the 2019 OTCO  
Class III & Class IV Annual Workshop for Water  
and Wastewater Operators

Matthew Kiefer, P.E.

Project Manager  
Hatch Associates  
88 E Broad Street,  
Columbus, OH 43215  
Matthew.Kiefer@hatch.com  
Ph: 614-745-8957



**HATCH**

# Blacklick Creek Trunk South

- 20 segments with surface reinforcement visible at random locations (spot defects)
- 3,650 feet of 96-inch RCP showing continuous severe concrete corrosion with visible reinforcement

So....how do you fix THAT?

