

Thermographic Inspection at

Our Clients Office

Nov-19

Ву

Hope Electrical



Hope Electrical
07786432916 www.hope-electrical.co.uk

Thermography Inspection at Our Clients



Inspection Site information

Customer Our Client
Address Home / Office

Contact Owner

Email <u>stuart@hope-electrical.co.uk</u>

Thermographer Stuart Hope




Summary of inspection		
Location	Equipment	Fault Page
Switch room	Fused switches	2
Income room	Main fuses	2
Plant room	Contactor	1
Electric Cuboard	Distribution board	3
Plant room	Change over switch	2
Switch room	Distribution board	2
Income room	Main terninals	2
Switch room	Fused switches	2
Electric Cuboard	Fused switches	2
Mains area	Main income	2
Mains room	Incomming supply	2
Switch room	Sub main	2





Location Plant room Equipment Fused switch

Type Fuses fault 2
Recommendation Upgrade



Analysis:

Fused switch running hot in comparison


Recommendation:

Loading and circuit design to be checked





Location	Income room	
Equipment	Main fuses	
Туре	Fuses	
fault	2	
Recommendation	Check balance	



This image and graph shows an imbalanced supply


Recommendation:

Check loadings and balance where possible.





Location	Plant room
Equipment	Contactor
Туре	Oil filled
fault	1
Recommendation	Monitor




Oil filled contactor running hot possible cause low oil level or poor contacts.


Recommendation:


Check oil level and contacts.





Location	Electric Cupboard
Equipment	Distribution board
Туре	Neutral bar
fault	3
Recommendation	Replace





The melted neutral bar has been caused by all neutrals on one side of the bar also red phase is running hot which is not visible to the eye.


Recommendation:

Balance loads and replace neutral bar





Electric Cupboard
Distribution board
Neutral bar
3
Replace



View of top changeover contactor running hot on red & yellow phases.

Recommendation:

Check connections and circuit design.





Location	Switch room
Equipment	Distribution board
Туре	Fuses
fault	2
Recommendation	Replace



Top part of fuse holder and cable running hot which points to a poor connect


Recommendation:

Check and re-terminate connection.





Location	Income room
Equipment	Main terminals
Туре	Income room
fault	2
Recommendation	Inform board



L2 phase running hot possible poor connection


Recommendation:

Re-terminate at next available shutdown.





Location	Income room
Equipment	Main terminals
Туре	Income room
fault	2
Recommendation	Inform board



Switch front running hot, this is being heated from connections / fuses inside.


Recommendation:

Requires internal visual investigation.





Location	Income room
Equipment	Main terminals
Туре	Income room
fault	2
Recommendation	Inform board



Fuse holder running hot due to poor connection.


Recommendation:

Re-terminate and check for damage / Replace





Location	Income room	
Equipment	Main terminals	
Туре	Income room	
fault	2	
Recommendation	Inform board	




Fuse holder running hot due to loading which can be seen at meter and service connector. Phase cable at meter has a poor connection due to being under stress caused by being too short.

Recommendation:

Check maximum demand and resize supply as required.





Location	Mains room
Equipment	Incoming supply
Туре	Supply cable
fault	2
Recommendation	Investigate





Image shows dual supply cables with one cable running hotter in comparison


Recommendation:

To be investigated





Location	Switch room
Equipment	Sub main
Туре	Tails
fault	2
Recommendation	Investigate



Supply running out of balance.

Recommendation:

Balance where possible.