Instrument #:2025007432 Recorded: 04/29/2025 10:19:14 AM Fee Amt: \$26.00 Page 1 of 11

Harnett County, North Carolina Matthew S. Willis, Register of Deeds BK 4282 PG 1525 - 1535 (11)

COVER SHEET

STORMWATER TREATMENT OPERATION AND MAINTENANCE AGREEMENT & DEED RESTRICTIONS FOR DUCKS LANDING

RECORDED IN HARNETT COUNTY MATTHEW S. WILLIS REGISTER OF DEEDS

STORMWATER TREATMENT OPERATION AND MAINTENANCE AGREEMENT & DEED RESTRICTIONS FOR DUCKS LANDING

HARNETT COUNTY, NORTH CAROLINA

D&L ENGINEERING, PLLC 150 S. PAGE STREET SOUTHERN PINES, NORTH CAROLINA FIRM No. P-1275

MARCH 2025

High Density Residential Subdivisions Deed Restrictions & Protective Covenances

In accordance with Title 15 NCAC 2H.1000 and S.L. 2006-246, the Stormwater Management Regulations, deed restrictions and protective covenants are required for **High Density Residential Subdivisions** where lots will be subdivided and sold and runoff will be treated in an engineered stormwater control facility. Deed restrictions and protective covenants are necessary to ensure that the development maintains a "built-upon" area consistent with the design criteria used to size the stormwater control facility.

area c	consistent with the design criteria used to size the stormwater control facility.		!		
I, below,	Travis Greene , acknowledge, affirm and w, that I will cause the following deed restrictions and covenants to be recorded	agree by my signatued agree by my signatued agree by my signature agree of the sale of	re any lot:		
1.	The following covenants are intended to ensure ongoing compliance with State Stormwater Management Permit Number, as issued by the Division of Energy, Mineral a Land Resources under the Stormwater Management Regulations.				
2.	The State of North Carolina is made a beneficiary of these covenants to the extent necessary to maintain compliance with the stormwater management permit.				
3.	These covenants are to run with the land and be binding on all persons an them.	d parties claiming un	der		
4.	The covenants pertaining to stormwater may not be altered or rescinded we consent of the State of North Carolina, Division of Energy, Mineral and Lai	ithout the express want	ritten		
5.	Alteration of the drainage as shown on the approved plan may not take pla of the Division of Energy, Mineral and Land Resources.	ice without the concu	ırrence		
6.	The maximum allowable built-upon area per lot is 4,000 square feet. This allotted an includes any built-upon area constructed within the lot property boundaries, and that portion of the right-of-way between the front lot line and the edge of the pavement. Built upon area includes, but limited to, structures, asphalt, concrete, gravel, brick, stone, slate, coquina and parking areas, but not include raised, open wood decking, or the water surface of swimming pools.				
OR, if	if the proposed built-upon areas per lot will vary, please REPLACE #6 al	oove with the follow	ving:		
6.	The maximum built-upon area per lot, in square feet, is as listed below:				
	Lot # BUA Lot # BUA Lot #	<u>BUA</u>			
	This allotted amount includes any built-upon area constructed within the lot that portion of the right-of-way between the front lot line and the edge of the includes, but is not limited to, structures, asphalt, concrete, gravel, brick, s parking areas, but does not include raised, open wood decking, or the wat pools.	e pavement. Built up tone, slate, coquina a	on area and		
7.	Each lot will maintain a 30** foot wide vegetated buffer between all imperv waters.	ious areas and surfa	ce		
**50 fc	foot for projects located in the 20 coastal counties.		· • • • • • • • • • • • • • • • • • • •		
8.	All runoff from the built-upon areas on the lot must drain into the permitted accomplished through a variety of means including roof drain gutters which the lot to drain toward the street, or grading perimeter swales to collect the	h drain to the street,	grading		

into a component of the stormwater collection system. Lots that will naturally drain into the system are

Form DRPC-3 Rev.2 05Nov2009

not required to provide these additional measures.

High Density Residential Subdivisions Deed Restrictions & Protective Covenances

Signature: 100 AM	Date: /- 26-23
1, Melissa G Wahl	, a Notary Public in the
State of North Corolina , County of	Moore
do hereby certify that Travis A Greene	personally appeared
before me this the <u>76</u> day of <u>Jenuery</u>	, 20 <u>23</u> , and acknowledge
the due execution of the foregoing instrument. Witness my	hand and official seal,
Signature My Commission expires 05 · 01 · 2027	Op. 05-01-27

Project Location: Darro	ch Road, Lilling	ton, Harnett Cou	inty, NC	·
laintenance records shall be kept on the follow				
ny deficient SCM elements noted in the inspec	ction will be corrected	repaired or replaced in	nmediately Th	nn a known set location. Sese deficiencies can
ffect the integrity of structures, safety of the pu	blic, and the pollutant	removal efficiency of th	e SCM(s)	icac denoiencies cari
		omoral omolomoy of the	C CCIVI(3).	
he SCM(s) on this project include (check all the	at annly & correspondi	na O&M choote will bo	addad automa	tioally)
Infiltration Basin	Quantity: 3			
Infiltration Trench	Quantity:	Location(s):	LUC 34 / Z. LUC	30 / J. LUC 02
Bioretention Cell	Quantity:	Location(s):		
Wet Pond	Quantity: 2	Location(s): 4:	ot 46 / 5: Lot	25
Stormwater Wetland	Quantity:	Location(s):		
Permeable Pavement	Quantity:	Location(s):		
Sand Filter	Quantity:	Location(s):		······································
Rainwater Harvesting	Quantity:	Location(s):		······································
Green Roof	Quantity:	Location(s):		;
Level Spreader - Filter Strip	Quantity:	Location(s):		<u> </u>
Proprietary System	Quantity:	Location(s):		
Treatment Swale	Quantity:	Location(s):		· · · · · · · · · · · · · · · · · · ·
Dry Pond	Quantity:	Location(s):		
Disconnected Impervious Surface	Present: No	Location(s):	, , , , , , , , , , , , , , , , , , , 	
User Defined SCM	Present: No	Location(s):		
Low Density	Present: No	Type:	, , , , , , , , , , , , , , , , , , ,	
Responsible Party: Travis C	ireene			
Title & Organization: Presid		Construction Inc		
Street address: 4200 N		Consudencia, inc.		
City, state, zip: Whisper		· · · · · · · · · · · · · · · · · · ·		· · · · · ·
Phone number(s): 910-725		······································		
·	Builder@gmail.com	· · · · · · · · · · · · · · · · · · ·		
/ Carolina	abunder wyman.com	· · · · · · · · · · · · · · · · · · ·		
Signature: Jaw Anh			Date:	1-24-23
Melissa G Wahl	, a Notar	y Public for the State of	Mor	th Carolina
ounty of Moore	, do here	by certify that	TAVIS A	Greene.
ersonally appeared before me this	day of	Jenuary 3	2023	and
cknowledge the due execution of the Operation	ns and Maintenance Ag	greement.		
itness my hand and official seal,	KWA In			
				·
				· .
G WA!				•
Sign F.			•	
EW. SARVO.				
= = O = O =				· · ·
PUBLIC				

05-01-2027

O&M Agreement

Project Name: Ducks Landing

My commission expires

eal

ORM-EZ

rsion 1.5

1/25/2023 Page 1 of 1 nportant operation and maintenance procedures:

- The drainage area will be carefully managed to reduce the sediment load to the infiltration basin.

 No portion of the infiltration basin will be fertilized after the initial fertilization that is required to establish
- the vegetation. Lime may be allowed if vegetation is planted on the surface of the infiltration basin and a soil test shows that it is needed.
- The vegetation in and around the basin will be maintained at a height of four to six inches.

After the infiltration basin is established, it will be inspected quarterly and within 24 hours after every storm event preater than 1.0 inches (or 1.5 inches if in a Coastal County). Records of operation and maintenance shall be kept in a known set location and shall be available upon request.

Inspection activities shall be performed as follows. Any problems that are found shall be repaired immediately.

CM element:	Potential problem:	How to remediate the problem:	
he entire infiltration asin	Trash/debris is present.	Remove the trash/debris.	
he grass filter strip or	erosive gullies have	Regrade the soil if necessary to remove the gully, plant ground cover and water until it is established. Provide lime and a one-time fertilizer application.	
ther pretreatment area	to a depth of greater than	Search for the source of the sediment and remedy the problem if possible. Remove the sediment and dispose of it in a location where it will not cause impacts to streams or the SCM.	
he flow diversion	I I DE STRUCTURE IS CIOCOEO	Unclog the conveyance and dispose of any sediment in a location where it will not cause impacts to streams or the SCM.	
tructure (if applicable)	The structure is damaged.	Make any necessary repairs or replace if damage is too much for repair.	
		Unclog the pipe and dispose of any sediment in a location where it will not cause impacts to streams or the SCM.	
	The inlet pipe is cracked or otherwise damaged (if applicable).	Repair or replace the pipe.	
'he inlet device	THEOSION IS OCCULTING IN THE	Regrade the swale if necessary and provide erosion control devices such as reinforced turf matting or riprap to avoid future erosion problems.	
	Stone verge is clogged or covered in sediment (if applicable).	Remove sediment and clogged stone and replace with clean stone.	
	sediment has accumulated	Search for the source of the sediment and remedy the problem if possible. Remove the sediment and dispose of it in a location where it will not cause impacts to streams or the SCM.	
'he basin	ISHTACA DAS OCCUITAT OT	Provide additional erosion protection such as reinforced turf matting or riprap if needed to prevent future erosion problems.	
		Replace the top few inches of soil to see if this corrects the standing water problem. If not, consult an appropriate professional for a more extensive repair.	

CM element:	Potential problem:	How to remediate the problem:
	Shrubs or trees are growing on the embankment.	Remove shrubs and trees immediately.
he embankment	An annual inspection by an appropriate professional shows that the embankment needs repair.	Make needed repairs immediately.
he outlet device	Clogging has occurred.	Clean out the outlet device and dispose of sediment in a location where it will not cause impacts to streams or the SCM.
	The outlet device is damaged	Repair or replace the outlet device.
	Erosion or other signs of damage have occurred at the outlet.	Repair the damage and improve the flow dissipation structure.
The receiving water	Discharges from the infiltration basin are causing erosion or sedimentation in the receiving water.	Contact the local NCDEQ Regional Office.

nportant operation and maintenance procedures:

- Immediately after the wet detention basin is established, the plants on the vegetated shelf and
- perimeter of the basin should be watered twice weekly if needed, until the plants become established (commonly six weeks).
- No portion of the wet pond should be fertilized after the initial fertilization that is required to establish the plants on the vegetated shelf.
- Stable groundcover will be maintained in the drainage area to reduce the sediment load to the wet pond.
- If the pond must be drained for an emergency or to perform maintenance, the flushing of sediment through the emergency drain will be minimized as much as possible.
- At least once annually, a dam safety expert will inspect the embankment. Any problems that are found will be repaired immediately.
- The measuring device used to determine the sediment elevation shall be such that it will give an accurate depth reading and not readily penetrate into accumulated sediments.

After the wet pond is established, it will be inspected quarterly and within 24 hours after every storm event greater than 1.0 inches (or 1.5 inches if in a Coastal County). Records of operation and maintenance shall be kept in a known set location and shall be available upon request.

Inspection activities shall be performed as follows. Any problems that are found shall be repaired immediately.

CM element:	Potential problem:	How to remediate the problem:
he entire wet pond	Trash/debris is present.	Remove the trash/debris.
he perimeter of the wet ond	erosive gullies have	Regrade the soil if necessary to remove the gully, plant ground cover and water until it is established. Provide lime and a one-time fertilizer application.
	The inlet pipe is clogged (if applicable).	Unclog the pipe. Dispose of the sediment off-site.
he inlet device	The inlet pipe is cracked or otherwise damaged (if applicable).	Repair or replace the pipe.
	swale (if applicable)	Regrade the swale if necessary and provide erosion control devices such as reinforced turf matting or riprap to avoid future problems with erosion.
'la a £a a la a a	greater than the original	Search for the source of the sediment and remedy the problem if possible. Remove the sediment and dispose of it in a location where it will not cause impacts to streams or the SCM.
he forebay	I H TORION NOR OCCUITAD	Provide additional erosion protection such as reinforced turf matting or riprap if needed to prevent future erosion problems.
	IVVAANE STA NTACANI	Remove the weeds, preferably by hand. If pesticide is used, wipe it on the plants rather than spraying.

SCM element:	Potential problem:	How to remediate the problem:
	greater than the original	Search for the source of the sediment and remedy the problem if possible. Remove the sediment and dispose of it in a location where it will not cause impacts to streams or the SCM.
The main treatment area	Algal growth covers over 50% of the area.	Consult a professional to remove and control the algal growth.
	Cattails, phragmites or other invasive plants cover 50% of the basin surface.	Remove the plants by wiping them with pesticide (do not spray).
	Best professional practices show that pruning is needed to maintain optimal plant health.	Prune according to best professional practices.
The vegetated shelf	Plants are dead, diseased	Determine the source of the problem: soils, hydrology, disease, etc. Remedy the problem and replace plants. Provide a one-time fertilizer application to establish the ground cover if a soil test indicates it is necessary.
	Weeds are present.	Remove the weeds, preferably by hand. If pesticide is used, wipe it on the plants rather than spraying.
	Shrubs have started to grow on the embankment.	Remove shrubs immediately.
	Evidence of muskrat or beaver activity is present.	Consult a professional to remove muskrats or beavers and repair any holes or erosion.
The embankment	A tree has started to grow on the embankment.	Consult a dam safety specialist to remove the tree.
	An annual inspection by an appropriate professional shows that the embankment needs repair.	Make all needed repairs immediately.
The outlet device	Clogging has occurred.	Clean out the outlet device and dispose of any sediment in a location where it will not cause impacts to streams or the SCM.
	The outlet device is damaged.	Repair or replace the outlet device.
Flasting wetland island	Weeds or volunteer trees are growing on the mat.	Remove the weeds or trees.
Floating wetland island (if applicable)	The anchor cable is damaged, disconnected or missing.	Restore the anchor cable to its design state.

.

SCM element:	Potential problem:	How to remediate the problem:
	Erosion or other signs of damage have occurred at the outlet.	Repair the damage and improve the flow dissipation structure.
The receiving water	Discharges from the wet pond are causing erosion or sedimentation in the receiving water.	Contact the local NCDEQ Regional Office.

Wet Pond Diagram							
WET POND ID	FOREBAY		MAIN POND				
4	Permanent Pool El.	185	Permanent Pool El.	185			
	Temporary Pool El:	185.7	Temporary Pool El:	185.7			
Pretreatment other No	Clean Out Depth:	3	Clean Out Depth:	5			
than forebay?	Sediment Removal E	182	Sediment Removal El	180			
Has Veg. Filter? No	Bottom Elevation:	181	Bottom Elevation:	179			
				· · · · · · · · · · · · · · · · · · ·			
WET POND ID	FOREBAY	<u></u>	MAIN POND	·			
5	Permanent Pool El.	210	Permanent Pool El.	210			
	Temporary Pool El:	210.5	Temporary Pool El:	210.5			
Pretreatment other No	Clean Out Depth:	3	Clean Out Depth:	5			
than forebay?	Sediment Removal E	207	Sediment Removal E	205			
Has Veg. Filter? No	Bottom Elevation:	206	Bottom Elevation:	204			