

City Hall
Nine Dale Avenue
Gloucester, MA 01930



TEL 978-281-9700
FAX 978-281-9738
mayor@gloucester-ma.gov

MAYOR GREG VERGA

CITY OF GLOUCESTER
OFFICE OF THE MAYOR

TO: City Council

FROM: Jill Cahill, Chief Administrative Officer and Mike Hale, Director of Public Works

CC: Board of Health

DATE: January 12, 2023

RE: Woodard & Curran Report - Good Harbor Creek

The City of Gloucester, as well as all other communities in Massachusetts, are required to sample surface waters at public beaches to minimize the risk of illness from contaminated water.

In order to test for potentially harmful fecal material and fecal pathogens, MA law requires sampling for "indicator" bacteria (enterococci is indicator bacteria for salt water).

Previous water quality samples taken at Good Harbor Creek in 2021 and 2022 have resulted in elevated levels of enterococci in the waters coming from Good Harbor Creek, resulting in mandated closures to minimize the risk of illness from contaminated water.

Although these bacteria are not typically disease causing, they are associated with fecal contamination. When at high concentrations their presence is indicative of the likely presence of waterborne pathogens.

Over the past few years, the Department of Public Works has been working diligently to investigate, identify, and eliminate potential sources of bacteria within the drainage catchment area of Good Harbor Creek which discharges to the waters of Good Harbor Beach. The drainage catchment area of Good Harbor Creek (and tributaries) covers a large area in excess of 500 acres, and includes a complex network of City drainage and sanitary sewer infrastructure. The City has completed investigations and repairs to the drainage and sewer infrastructure in several areas to eliminate potential sources of bacteria.

In 2022 the City of Gloucester, through the Health Department, also contracted with Woodard & Curran to undertake a bacteria source investigation along Good Harbor Creek. In this packet you will find a summary memorandum as well as the full report from Woodard & Curran.

Upon receiving the report and a presentation from Woodard & Curran, the Mayor's office met with the Health Director, Director of Public Works, Board of Health Chair, and the Title 5 Sanitarian to discuss next steps. Through this collaborative effort, and with the additional information provided by the Woodard & Curran report, it has been determined that additional sewer infrastructure investigation is needed in order for the DPW to determine next steps for the infrastructure repairs needed.

DPW is currently under contract to complete additional investigations and rehabilitations, including some of the recommendations from the "Good Harbor Creek - Bacterial Source Investigation Summary Memorandum", dated December 22, 2022.

The Health Department will resume the traditional weekly beach testing, as prescribed by the Massachusetts Department of Public Health under 105 CMR 445.000, in May 2023. These regulations prescribe in detail the role of local boards of health in beach testing and public notification.

Through DPW's continued investigation we will collect wet and dry surface water samples throughout the winter and spring and share the data with the Board of Health/Health Department. We anticipate that we will continue to see the trend of elevated bacteria detections that coincide with short-duration, high-intensity precipitation events. If this trend continues you can expect creek closures that coincide with these precipitation events throughout the beach season.

The collaboration of the DPW and the Health Department is key to a successful beach season. To this end we have established an internal working group with representatives from these departments as well as Engineering and Conservation. They will provide regular updates to the Mayor's office that we will then share with the City Council and Board of Health.

Another key to a successful beach season is clear and concise communication regarding the roles of each department (as described above) and the open/close status of Good Harbor Creek. The Health Department remains responsible for testing, determining if closure is needed, and public notification as prescribed by Massachusetts Department of Public Health under 105 CMR 445.000.

The full report and accompanying memos will be posted to the City's website. In the meantime, City Councilors should send all questions or concerns to the Mayor's office.

MEMORANDUM



TO: Mary Ellen Rose (Health Department Director – City of Gloucester)

CC: Michael Hale (Director of Public Works – City of Gloucester)
Garrett Bergey (Director of Field Operations – SDE)

FROM: Janelle Bonn (Technical Manager – Woodard & Curran)
Scott Salvucci, PE (Project Manager – Woodard & Curran)

DATE: December 22, 2022

RE: Summary of Bacteria Source Investigation Results – Good Harbor Creek

EXECUTIVE SUMMARY

Good Harbor Beach, including the section along Good Harbor Creek, attracts thousands of visitors to the City and surrounding areas each summer and also provides important ecological habitat. We understand the importance of keeping this destination fully accessible and open to the public during its peak seasonal demand, considering the public and economic benefits. High bacteria concentrations have contributed to the closure of the Creek to recreation for the past two summer seasons, creating public health and environmental concerns. This memorandum summarizes the bacteria source investigation completed in 2022, highlights the findings, and outlines recommended next steps.

Bacteria source investigation was performed through a comprehensive sampling and visual inspection program, as defined by the EPA. Surface water sampling and drainage outfall sampling were performed along Good Harbor Creek to identify the areas experiencing the highest bacteria concentrations. Working with the Health Department and with support from the Public Works Department, Woodard & Curran along with our subcontractor SDE performed strategic investigations of the City's drainage and sanitary sewer infrastructure. These investigations were conducted with the goal of identifying illicit discharges of wastewater entering the drainage system or structural defects of the sanitary sewer pipelines which could lead to wastewater exfiltrating from the pipes into the groundwater or surrounding waterbodies.

Investigation Findings

- No substantial bacteria sources were identified in the investigated drainage infrastructure discharging to Good Harbor Creek. This suggests there are no non-stormwater discharges entering the drainage network from a sewer source that would contribute to previously detected high bacteria concentrations.
- CCTV investigations identified locations in the Neptune Place cross-country sewer main and the Hartz Street sewer main where sewage is susceptible to leaking out of the pipes when flows reach an elevated or surcharged capacity.
- Surface water samples collected from both sides of the Creek during dry weather conditions identified bacteria concentrations above water quality standards (WQS) in select samples. However, laboratory analyses of the samples did not identify a significant human source for the detected bacteria.



- Surface water samples collected from the Creek during wet weather identified bacteria concentrations above WQS in all the eastern and western parts of the Creek. Additional laboratory analyses of the samples identified a significant human source for detected bacteria in samples collected immediately downstream of the Neptune Place cross-country sewer main, the Hartz Street sewer main, and the Thatcher Road crossing of the Creek.

Conclusions

Elevated bacteria detections coincide with short duration, high intensity precipitation events across all evaluated sampling events (City and Woodard & Curran), indicating Beach and Creek closures are currently dependent on rainfall. The City can expect Beach and Creek closures to continue when samples are collected immediately after these types of precipitation events.

Sewer infrastructure appears to be exfiltrating sewage from minor pipe defects observed during CCTV into the western portion of the Creek during short duration, high intensity precipitation events. Evidence of surcharging (when the pipe is transporting flow at higher capacities) was observed in the Hartz Street sewer main. This indicates non-sewer related flow is entering the sewer system from a currently undefined source, likely linked to the precipitation events.

In the eastern portion of the Creek, human derived bacteria were detected immediately downstream of the sewer force main located within Thatcher Road. The force main has not been investigated, but since there is less sewer infrastructure in this area and upstream samples did not contain human derived bacteria, it is probable the Thatcher Road force main is an additional source of bacteria contributions to the Creek.

Non-human derived bacteria were also present in surface water samples collected from the eastern and western portions of the Creek, in significantly higher concentrations during wet weather sampling. Based on the abundance of wildlife habitat adjacent to sample locations, notably birds, it is suspected that birds are contributing bacteria to the Creek.

Recommendations

- Additional sewer infrastructure investigations are recommended at the Neptune Place cross-country sewer main, the Hartz Street sewer main, and the Thatcher Road force main to determine the scope and nature of rehabilitation/repairs required to prevent sewage exfiltration and, for Hartz Street, the reason why the sewer main is experiencing surcharging.
- Wet and dry weather samples are recommended to be collected and submitted for laboratory analysis for avian-derived bacteria to determine the impact birds are having on the bacteria levels in the Creek. If birds are identified as a significant bacteria source, we recommend conducting an avian population assessment to determine whether the birds are native or non-native. Mitigation measures for non-native species are commonly implemented to decrease bacteria contributions to waterbodies.

MEMORANDUM

TO: Mary Ellen Rose (Health Department Director – City of Gloucester)

CC: Garrett Bergey (Director of Field Operations – SDE)

FROM: Janelle Bonn (Technical Manager – Woodard & Curran)
Scott Salvucci, PE (Project Manager – Woodard & Curran)

DATE: November 2, 2022

RE: Good Harbor Creek – Bacterial Source Investigation Summary Memorandum



PURPOSE AND BACKGROUND

This Bacterial Source Investigation Summary Memorandum describes the results of drainage and sanitary sewer infrastructure investigations conducted proximal to Good Harbor Creek and surface water sampling events conducted within Good Harbor Creek. The purpose of these investigations was to evaluate the potential source(s) of elevated bacteria concentrations previously detected in surface waters collected from Good Harbor Creek that caused sporadic closures of Good Harbor Beach and/or Good Harbor Creek to recreational activities during the 2021 and 2022 recreational seasons.

As part of the investigations, sections of drainage infrastructure conveying stormwater to Good Harbor Creek were visually inspected in accordance with the methodology prescribed in the illicit discharge detection and elimination (IDDE) requirements of the US EPA MS4 General Permit (Permit). Additional components of the investigations included the collection of dry and wet weather surface water samples from Good Harbor Creek and closed-circuit television (CCTV) inspections of two sewer pipe segments that extend across Good Harbor Creek.

The City's recent monitoring data is summarized below and provided the initial basis for the investigation rationale, methodology, evaluation criteria, and findings, as described in the following sections. Additionally, conclusions and recommendations for future investigations and actions are provided within this memorandum to assist the City with potential actions to mitigate and/or eliminate bacteria contributions to Good Harbor Creek and, ultimately Good Harbor Beach.

CITY MONITORING DATA

The City's Department of Public Works (DPW) collected surface water samples from Good Harbor Creek and a tributary draining to Good Harbor Creek between August 2 and August 20, 2021 and submitted the samples for laboratory analysis for enterococci. This information was provided to Woodard & Curran in an Excel spreadsheet that summarized the location, date, tide at the time of sample collection, and laboratory results.

The DPW surface water sample results identified elevated enterococci concentrations at several locations adjacent to the western and eastern branches of Good Harbor Creek, with decreasing enterococci concentrations in samples located farther away from the creek. This data was used to determine the investigation area described in this memorandum. The DPW surface water sampling summary table and associated maps of surface water sample locations provided by the City are included as **Attachment A**.



INVESTIGATION APPROACH

The Study Area was developed based on a review of mapped MS4 and sanitary sewer infrastructure locations discharging to Good Harbor Creek in relation to the locations of surface water samples collected by the DPW in August 2021 and the associated detected enterococcus concentrations. Additional discussion describing the Study Area selection is provided below, and an overview map depicting the Study Area is provided as **Figure 1**.

Drainage Infrastructure

Drainage infrastructure investigations focused on areas where the infrastructure was identified proximal to sanitary sewer infrastructure and discharged to Good Harbor Creek to determine whether the drainage infrastructure network was a source of bacterial input to the creek through an illicit cross connection or effluent migration from the sanitary sewer. Drainage infrastructure investigation locations were selected based on information provided by the City of Gloucester's (City) GIS consultant, AppGeo, that included GIS geospatial datasets depicting the location of drainage infrastructure discharging to Good Harbor Creek and nearby sanitary sewer infrastructure.

Surface Water

Surface water sample locations were selected after evaluating the City's surface water sampling data from Good Harbor Creek in 2021. Dry weather surface water samples were collected during low tide in locations that corresponded to the most elevated 2021 enterococci concentrations. Wet weather samples were collected from the same sample locations, as well as an additional downstream location, during slack tide into low tide. Wet weather sampling was conducted during a high intensity, short duration precipitation event that occurred on September 22, 2022 where 0.56-inches of precipitation fell within a 45-minute period to replicate weather conditions that occurred during a similar August 2021 event that corresponded with the most elevated detected enterococci concentrations identified in samples collected by the DPW. These weather conditions were targeted to determine whether increased precipitation is causing exfiltration of sewage from the sanitary sewer pipes that is reaching Good Harbor Creek.

Sanitary Sewer

CCTV investigations were performed on two sanitary sewer pipes that spanned segments of Good Harbor Creek based on their locations relative to elevated bacteria concentrations detected in the August 2021 surface water samples.

The methodology, evaluation criteria, and results for each component of the investigations are described below.

DRAINAGE INFRASTRUCTURE INVESTIGATION METHODOLOGY

Between May 9 and May 17, 2022, Stacey DePasquale Engineering, Inc. (SDE) of Lawrence, Massachusetts performed strategic investigations of drainage infrastructure draining to outfalls DO_100, DO_101, DO_127, DO_1717, DO_1724, DO_1727, and DO_6223. GIS-based information provided by the City's consultant, AppGeo, did not contain catchment delineations and no additional catchment delineation information was available. Investigations proceeded at the most upstream mapped representative drainage structure connected by drainage pipe to the outfall and continued downstream to the outfall.



Dry weather drainage infrastructure investigations were conducted during periods where <0.1 inches of precipitation occurred within the preceding 24-hour period, in accordance with Permit requirements. Using the methodology prescribed in Part 2.3.4.8 of the Permit, drain manholes, and in some cases catch basins, were opened, and examined to determine the presence or absence of dry weather flow and visible and/or olfactory indicators of sewage. When dry weather flow was observed, samples were collected and screened using field test kits and/or laboratory analyses for potential illicit discharge indicators, as described below. Field test kit results were evaluated to determine whether parameters indicative of potential illicit discharges were present in dry weather flow that warranted investigation of adjacent drainage structures. When dry weather flow was not observed, sandbags were placed in the inlets of accessed drainage structures for 48-hours to determine whether intermittent flows were present.

Information obtained during outfall screening and limited drainage infrastructure investigation activities was recorded in ESRI's ArcGIS Field Maps application. The resulting GIS geospatial datasets will be provided to the City electronically concurrently with this submittal.

DRY WEATHER DRAINAGE INFRASTRUCTURE SCREENING DATA EVALUATION CRITERIA

The Permit considers dry weather flow collected from MS4 screening locations that exceed the one of the following threshold criteria as a potential indication of sewer contribution to drainage infrastructure and therefore, represent a potential illicit discharge:

- Olfactory or visual evidence of sewage;
- Ammonia ≥ 0.5 ppm, Surfactants ≥ 0.25 ppm, enterococci ≥ 130 cfu/100 mL (based on the Massachusetts Department of Environmental Protection (MassDEP) applicable surface water criteria); or
- Ammonia ≥ 0.5 ppm, Surfactants ≥ 0.25 ppm, and detectable chlorine.

Test kit results where ammonia and/or surfactants are detected above their individual Permit threshold criteria are potential indicators of other illicit discharges, such as incorrectly connected washing machine laterals, or the result of diluted flow from sewer-related sources. Under the Permit, these types of potential illicit discharge indicators require additional investigation, but potential sewer indicators are generally given higher priority for additional investigation due to the detrimental impacts to public health from sewage exposure.

In addition to the Permit required dry weather flow parameter sample analysis, the City elected to submit samples for laboratory analysis for total bacteroides and human bacteroides. The results of these analyses are used to differentiate whether bacteria present in dry weather flow is primarily originating from a human source or other sources such as birds or dog by analyzing samples for DNA markers present in different types of feces. There are no established regulatory threshold criteria for bacteroides in water samples; however, academic literature suggests that human bacteroides concentrations between 500 – 1,000 copies/100 mL of bacteroides indicate human waste impacts are present that warrant additional investigation to determine the source (Boehm and Soller, "Refined ambient water quality thresholds for human-associated fecal indicator HF183 for recreational waters with and without co-occurring gull fecal contamination", Elsevier, Microbial Risk Analysis 16, 2020).

Dry weather sample screening results obtained during limited drainage infrastructure investigations were compared against these criteria to determine the potential presence of human sewage related illicit discharges.



DRAINAGE INFRASTRUCTURE INVESTIGATION RESULTS

An evaluation of the dry weather drainage infrastructure investigation results did not identify Permit-defined potential illicit discharges related to sanitary sewer contributions in investigated infrastructure. Elevated concentrations of two potential illicit discharge parameters were identified in one isolated pipe segment within drainage infrastructure discharging to DO_100. Dry weather flow was also observed in drainage infrastructure discharging to DO_127 but did not contain concentrations of potential illicit discharge parameters above Permit threshold criteria. Sample results in these locations are discussed further below. The remaining investigated infrastructure was observed to be dry. A summary of the investigation findings is provided in **Table 1**.

Table 1: Summary of Limited Drainage Infrastructure Investigation Results

Drainage Outfall ID	Potential Illicit Discharge(s) Detected	Notes
DO_100	No	Dry weather flow observed in one drainage pipe segment upstream of the outfall containing low levels of potential illicit discharges associated with sewage below Permit criteria. Remaining investigated downstream infrastructure contained standing water, impeding further screening efforts.
DO_101	No	Standing water was observed in investigated infrastructure, impeding screening efforts.
DO_127	No	Standing water was observed in one pipe segment connected to the drainage manhole immediately upgradient of the outfall. Dry weather flow was observed the other drainage pipe segment connected to the drainage manhole immediately upstream of the outfall. No potential illicit discharge parameters were identified in the sample collected from the dry weather flow.
DO_1717	No	No dry weather flow observed in investigated infrastructure.
DO_1724	No	Standing water was present in most of the investigated infrastructure along Abbott Road. However, pipe segment connected to DO_1724 was observed to be dry.
DO_1727	No	No dry weather flow observed in upstream infrastructure. Standing water in downstream infrastructure impeded further investigations and/or confirmation of pipe connectivity to DO_1727.
DO_6223	No	No dry weather flow observed in investigated infrastructure.

DO 100 Drainage Area Investigation Findings

Outfall DO_100 is located on Witham Street north of the intersection with Thatcher Road and discharges to a marshy area near a tributary to Good Harbor Creek. The drainage area, as mapped, collects stormwater from the northeastern portion of Thatcher Road, discharging to the outfall. Two potential illicit discharge parameters were identified above Permit individual



threshold criteria for illicit discharges in a drainage pipe discharging to DO_100. The results from testing dry weather flow present in the drainage pipe, located between the Good Harbor Beach Condominiums at 78 Thatcher Road and the building to the northeast located at 76 Witham Street (**Figure 2**), suggests non-stormwater discharges are entering the drainage infrastructure in this location.

Surfactants were detected at a concentration of 0.55 mg/L, and chlorine was detected at a concentration of 0.2 mg/L, which is above the Permit individual threshold criteria of 0.25 mg/L and "detectable concentrations", respectively. Ammonia, which was detected at 0.20 mg/L, was below the Permit individual threshold criteria of 0.5 mg/L and enterococci detections were below the Massachusetts Surface Water Quality Standard (WQS) of 130 cfu/100 mL.

Standing water was observed in surrounding drainage infrastructure and was not sampled because it is not representative of conditions where flowing non-stormwater sources are present and can cause elevated detections of bacteria because it is stagnant. The drainage outfall DO_100 could not be screened because it was submerged.

DO 127 Drainage Area Investigation Findings

Outfall DO_127 is located southwest of the Marina Drive and Loma Drive intersection and discharges to a marshy area adjacent to Good Harbor Creek. The drainage area, as mapped, collects stormwater from a nearby portion of Marina Drive and the intersection of Loma Drive. Standing water was observed in the northwest inlet of the drainage manhole immediately upgradient of DO_127. Dry weather flow was detected in the other drainage pipe segment connected to this manhole and was sampled at the northeast inlet entering DMH_396. No potential illicit discharge indicators were detected in the sample above Permit threshold concentrations. Drainage infrastructure upstream of DO_127 was either dry or contained standing water. DO_127 was not located. Although dry weather flow was present in a small drainage pipe segment discharging to the drainage outfall, no potential illicit discharges were identified in investigated infrastructure during this investigation. Investigations of drainage infrastructure discharging to DO_127, as mapped, are complete. The DO_127 drainage area investigations are depicted on **Figure 3**.

Table 2, below, summarizes the screening results obtained from dry weather flow observed in infrastructure discharging to DO-100 and DO_127. Laboratory analytical reports are provided as **Attachment B**.



Table 2: Dry Weather Screening Results for DO_100 and DO_127

Associated Drainage Outfall	DO_100	DO_127
Sample Date	5/17/2022	5/12/2022
Pipe ID	DMH_3490: DMH_13804	DML_1299
Flow/Velocity/Color	Yes/Slow/Clear	Yes/Slow/Clear
Ammonia (mg/L)	0.20	<0.05
Surfactants (mg/L)	0.55*	<0.125
Chlorine (mg/L)	0.20	<0.02
Enterococci (MPN/100mL)	75	1
Total Bacteroides (CE/100mL)	5,261	480
Human Bacteroides (CE/100mL)	Not Detected	Not Detected

Notes:

* = surfactant value obtained via laboratory sample analysis.

Bold values exceed Permit individual threshold criteria for this parameter.

DO 101 and DO 6223 Drainage Area Investigation Findings

Outfall DO_101 is located on Witham Street south of Joppa Way and discharges to a marshy area adjacent to a tributary of Good Harbor Creek. The drainage area, as mapped, collects stormwater from the northern portion of Witham Street in the vicinity of Joppa Way. Mapped drainage infrastructure discharging to DO_101 was accessed and observed to contain standing water.

Outfall DO_6223 is north of Bass Avenue, approaching a cross-country sanitary sewer line originating from Neptune Place to the north. This outfall discharges to Good Harbor Creek. The drainage area, as mapped, collects stormwater from the intersection of Bass Avenue with Amero Court. Mapped drainage infrastructure No dry weather flow was observed in mapped drainage infrastructure discharging to DO_6223. Investigations of drainage infrastructure, as currently mapped in these areas, are considered complete, as shown in **Figures 4 and 5**.

DO 1717 and DO 1724 Drainage Area Investigation Findings

Outfall DO_1717 is located northeast of the intersections of Abbott Road, Eastern Avenue, and Helen’s Way. The outfall discharges to a marshy area adjacent to Good Harbor Creek. The drainage area, as mapped, collects stormwater from the vicinity of Eastern Avenue and Abbott Road.

Outfall DO_1724 is located at the end of Abbott Road and discharges to a marshy area adjacent to Good Harbor Creek. The drainage area, as mapped, appears to collect stormwater from Abbott Road.

Limited drainage infrastructure draining to DO_1717 and DO_1724 has been investigated and no potential illicit discharges were identified, as shown in **Figure 6**.



DO 1727 Drainage Area Investigation Findings

Outfall DO_1727 is located northeast of the intersections of Hartz Street and Bass Avenue, behind the sewer pump station. The outfall discharges to a marshy area adjacent to Good Harbor Creek. The drainage area, as mapped, collects stormwater from Brightside Avenue; however, the connection between upstream drainage infrastructure on Brightside Avenue and DO_1727 was not able to be verified during the investigation.

Attempts were made to inspect drainage infrastructure draining to outfall DO_1727, however, lack of mapped connectivity and the presence of standing water in accessed structures impeded this process. Drainage infrastructure located within Brightside Avenue approaching Bass Avenue was observed to be dry. Drainage infrastructure located at the approximate intersection of Bass Avenue and Hartz Street was observed to contain standing water, impeding further investigations, and limiting visibility to determine pipe connectivity within the accessed structures (CB_296, DMH_189, and DMH-190). AT DO_1727, the outfall was not directly observed, but water was overflowing in the area where the outfall was mapped, indicating that the outfall may be partially submerged.

The DO_1727 drainage area investigations are depicted on **Figure 7**.

SURFACE WATER SAMPLING METHODOLOGY

Dry weather samples were collected between May 9 and May 19, 2022. No precipitation was recorded during the previous 24-hour period prior to sample collection. Wet weather sampling was conducted during a high intensity, short duration precipitation event that occurred on September 22, 2022 where 0.56-inches of precipitation fell within a 45-minute period. Samples were collected from approximately surface to 6-inches below surface within Good Harbor Creek from either the creek bank or an upstream location to avoid sediment disturbance when entering the creek. Where possible, samples were collected directly using laboratory supplied bottles. In locations where this was not possible, samples were collected using a sampling rod equipped with a collection bottle pre-cleaned with fresh water and then purged with flow to be sampled prior to sample collection. Water collected in the collection bottle was then decanted into a laboratory supplied bottle. Upon collection, sample bottles were labelled with laboratory provided labels and placed on ice within a cooler for submittal to the laboratory.

The dry weather surface water samples were submitted to Rhode Island Analytical Laboratory (RIAL) in Warwick, RI and the wet weather samples were submitted to Biomarine Laboratory in Gloucester, MA for analysis for enterococci via the IDEXX Enterolert method. Additionally, surfactant samples were collected during dry weather surface water sampling at each location and submitted to RIAL for laboratory analysis via the SM5540C 18-21ed method to provide information to correlate concentrations of this parameter that may be present in drainage outfall discharges with concentrations potentially present in Good Harbor Creek.

Total bacteroides and human bacteroides samples collected during dry and wet weather sampling events were submitted to EMSL Analytical, Inc. laboratory in Cinnaminson, NJ for analysis by Quantitative PCR.

Note that the sample point identification numbers used to identify samples correlate with the DPW sample point identification used during the August 2021 surface water sampling event.



SURFACE WATER SAMPLE DATA EVALUATION CRITERIA

Surface water sample results were evaluated against the Massachusetts Surface Water Quality Standard (WQS) in 314 CMR 4.00 and the Massachusetts Department of Public Health criteria for enterococci in marine waters, which is 104 cfu/100 mL. Note that the DPH criteria relates to the statistical threshold value (STV); however, if more than five recent samples are collected, the geomean average of 35 cfu/100 mL applies. As discussed in the Dry Weather Drainage Infrastructure Screening Evaluation Criteria section above, there are no established regulatory threshold criteria for bacteroides in water samples; however, academic literature suggests that human bacteroides concentrations between 500 – 1,000 CEs/100 mL of bacteroides indicate human waste impacts are present that warrant additional investigation to determine the source.

DRY WEATHER SURFACE WATER SAMPLE RESULTS

Dry weather surface water sample results identified elevated concentrations of enterococci above WQS in the Marina and Loma Drive Outfall sample (sample point 16), collected from the western portion of Good Harbor Creek. However, detected total and human bacteroides concentrations in this sample does not indicate a human-derived source of bacteria. Low levels of human bacteroides were detected in the samples collected adjacent to the Cross-Country Sewer Line south of Neptune Place and the Hartz Street Culvert, but below concentrations that suggest human waste impacts to surface water. Both dry weather surface water samples collected from the eastern portion of Good Harbor Creek contained enterococci above WQS. Like the Marina and Loma Drive Outfall sample, total and human bacteroides results did not identify a significant concentration of human-derived bacteria. A summary of laboratory analytical data from dry weather surface water samples is presented in **Table 3**.

Table 3: Summary of Dry Weather Surface Water Sampling Results

Sample Location	Sample Date	Enterococci (MPN/100mL)	Total Bacteroides (CE/100mL)	Human Bacteroides (CE/100mL)	Surfactants (mg/L)
Western Good Harbor Creek Samples					
Cross-Country Sewer Line/Creek Intersection; North of DO-6223, South of Neptune Place (Sample Point 15)	5/09/2022	2	2,296	421	<0.12
Hartz Street Culvert (Sample Point 5)	5/10/2022	11	19,409	450	0.18
Marina and Loma Drive Outfall (Sample Point 16)	5/19/2022	884	119,821	None Detected	1.8
Eastern Good Harbor Creek Samples					
Thatcher Road Crossing (Sample Point 13)	5/19/2022	556	2,506	None Detected	1.2
Witham at Western End of Pond (Sample Point 39)	5/19/2022	301	90,655	None Detected	1.1



WET WEATHER SURFACE WATER SAMPLE RESULTS

Wet weather surface water sample results identified elevated concentrations of enterococci above WQS in all samples. Total and human bacteroides results indicate a human source of bacteria is entering the creek in samples collected from downgradient locations adjacent to sanitary sewer infrastructure located at the cross-country sewer line south of Neptune Place, the Hartz Street Culvert, and point where Thatcher Road crosses Good Harbor Creek. Human bacteroides was not present in samples collected from surface water adjacent to the drainage outfall located at Marina and Loma Drive and the western side of the pond abutting Witham Street, at Joppa Way. Low concentrations of human bacteroides were detected at the Good Harbor Beach Boardwalk.

A summary of laboratory analytical data from wet weather surface water samples is presented in **Table 4** below.

Table 4: Summary of Wet Weather Surface Water Sampling Results

Sample Location	Sample Date	Enterococci (MPN/100mL)	Total Bacteroides (CE/100mL)	Human Bacteroides (CE/100mL)
Western Good Harbor Creek Samples				
Cross-Country Sewer Line/Creek Intersection; North of DO-6223, South of Neptune Place (Sample Point 15)	9/22/2022	14,136	48,821	4,344
Hartz Street Culvert (Sample Point 5)	9/22/2022	19,863	148,839	50,133
Marina and Loma Drive Outfall (Sample Point 16)	9/22/2022	3,654	26,973	None Detected
Eastern Good Harbor Creek Samples				
Thatcher Road Crossing (Sample Point 13)	9/22/2022	15,531	42,114	7,950
Witham at Western End of Pond (Sample Point 39)	9/22/2022	>24,196	3,187,990	None Detected
Downgradient Good Harbor Creek Sample				
Good Harbor Beach Boardwalk (Sample Point 1-GHB)	9/22/2022	1,616	48,821	1,180

Surface water sample locations are provided in **Figure 8**. Surface water laboratory analytical reports are provided as **Attachment B**.

CCTV INVESTIGATION METHODOLOGY AND EVALUATION CRITERIA

In May 2022, Next Level Environmental (Next Level) of Canton, Massachusetts conducted CCTV inspections of sanitary sewer pipes on Hartz Street and south of Neptune Place. These



inspections were conducted in accordance with the National Association of Sewer Service Companies (NASSCO) Pipeline Assessment Certification Program (PACP) Version 7.0.3 and are described in more detail below. The targeted sewer infrastructure included three (3) 8-inch sewer segments from SMH-1895 to SMH-1892 and two (2) 10-inch sewer segments from SMH-700 to SMH-708.


Hartz Street Sanitary Sewer Main Inspection Results

Next Level inspected a portion of the sanitary sewer main on Hartz Street, including the pipe segment SMH-1894 to SMH-1893 which crosses directly over the Hartz Street culvert, to evaluate the potential of sewage exfiltration from defects in the pipe. **Figure 9** depicts the extent of sewer main inspected.

Beginning at SMH-1985, it was observed that the 8-inch pipe had a Cured-in-Place-Pipe (CIPP) installed and original pipe material was unknown. Four sewer service connections were observed in the pipe segment downstream, which all showed evidence of infiltration. Additionally, heavy grease deposits were observed along the top of the main sewer pipe and sewer services, which is evidence of surcharging within the sewer main. Build-up of fats, oils, and greases (FOG) were observed at the top of the sewer main and service connections located approximately 38 and 46 linear feet downstream of SMH-1895, as shown in **Photograph 1** and **Photograph 2** below.



Photograph 1: Fats, oils, and greases observed 38 feet downstream of SMH_1895



Photograph 2: Fats, oils, and greases observed 46 feet downstream of SMH_1895

Next Level then mobilized at SMH_1894, to continue their inspection of the sewer main, which also had a CIPP Liner installed. Approximately 17 linear feet downstream of SMH_1894 a polyvinyl chloride (PVC) sewer service wye was observed, which appears to have been installed after the CIPP liner and appeared to be in acceptable condition. Next Level documented offsets between the CIPP pipe and PVC wye on the upstream and downstream ends due to the installation.

Evidence of infiltration drips were identified approximately 30 linear feet downstream of SMH_1894 and grease deposits were observed in several locations, extending to the downstream sewer manhole, SMH_1893. Beginning at approximately 60 linear feet downstream of SMH_1894, Next Level observed both major and minor sags in the sewer main, causing standing water and limiting the ability to fully inspect this portion of the pipe. A major sag located approximately 145 linear feet downstream of SMH_1894 is shown in **Photograph 3** below.



Photograph 3: Major pipe sag observed 145 linear feet downstream of SMH_1894

Next Level moved to the next downstream manhole, SMH_1893, to finish their inspection of this portion of the Hartz Street 8-inch sewer main. This pipe segment also had a CIPP liner installed. Infiltration staining approximately 78 linear feet downstream of SMH_1893 and grease deposits throughout the entire pipe segment were observed. Grease was observed at the top of the pipe in some locations, as shown in **Photograph 4** below, which is evidence of surcharging within the sewer main.



Photograph 4: Grease observed at the top of the pipe approximately 110 linear feet downstream of SMH_1893.

Neptune Place Cross-Country Sanitary Sewer Main Inspection Results

Next Level inspected a portion of the cross-country sanitary sewer line that runs from Neptune Place to Bass Ave to evaluate the potential of sewage exfiltration from defects in the pipe. Next Level were unable to access the full length of the pipe for inspections due to obstructions caused by wrinkling of the pipe's CIPP liner. Next Level observed two sewer services in the pipe segment downstream of sewer manhole SMH_700. Both sewer services were not sealed with grout, exhibited penetrations from tree roots, and showed evidence of infiltration. If infiltration is present at each of these locations, which are adjacent to Good Harbor Creek, it is likely that high flows and surcharging in the sewer main could cause exfiltration of sewage into the surrounding soils. **Photograph 5**, below, shows one of the sewer service connections.



Photograph 5: Sewer service located approximately 56 linear feet down stream of SMH_700

Next Level moved to the manhole SMH_700A, which was reportedly installed during a 2021 repair to the cross-country sewer main to continue their inspection of the pipe. Cracks were observed at the connection between the manhole and the downstream pipe, which could possibly allow exfiltration of sewage if water level rises within the manhole. Next Level had to abandon their inspection approximately 62 linear feet downstream of SMH_700A, due to wrinkles and bulges within the pipe's CIPP liner. The liner walls in this section of the pipe were observed to be darker than the rest of the pipe. This could be a result of wastewater contents building up inside of the pipe or could be an indicator of infiltration. Further investigation of the pipe would be required to determine the source of this discoloration.

The extent of investigated sewer main, as well as the approximate location of the unmapped manhole SMH_700A, is provided in **Figure 10**, below.

BACTERIA SOURCE INVESTIGATION FINDINGS

Dry weather surface water sample results did not identify a significant source of enterococci present in Good Harbor Creek. One dry weather surface water sample collected from the western portion of Good Harbor Creek (Marina and Loma Drive Outfall, sample point 16) contained enterococci above WQS, but it isn't apparent that the detected concentration would be sufficient to exceed WQS downgradient in the portion of the creek adjacent to Good Harbor Beach. Human bacteroides were not detected in this sample. Low levels of enterococci below WQS were detected in dry weather surface water samples collected adjacent to sanitary sewer



infrastructure located south of Neptune Place and the Hartz Street culvert, along with low levels of human bacteroides.

Wet weather surface water sample enterococci results significantly exceeded WQS in all locations sampled within the western and eastern portions of Good Harbor Creek. Human bacteroides were detected in the samples collected adjacent to sanitary sewer infrastructure (cross-country sewer line south of Neptune Place, Hartz Street culvert, and the Thatcher Road crossing) in concentrations that indicate this infrastructure is introducing elevated enterococci concentrations from a sanitary sewer source into Good Harbor Creek. Negligible enterococci concentrations were detected in the downgradient point of convergence where Good Harbor Creek discharges to Good Harbor Beach and are likely the result of diluted human bacteroides concentrations detected upstream at the Thatcher Road crossing sample.

Although high concentrations of enterococci were detected in samples collected from the vicinity of the Marina and Loma Drive outfall and Witham Street at the western end of the adjacent pond, no human bacteroides were detected. This suggests that detected enterococci in these locations is derived from a non-human source such as birds. Both locations contain considerable amounts of marsh, providing suitable habitat for shoreline birds, which were observed in these areas during the investigation.

Based on the results of the dry and wet weather sampling program, in conjunction with sanitary sewer conditions observed during CCTV investigations, sewage appears to be exfiltrating from sewer infrastructure in the western portion of the creek during high intensity, short duration precipitation events in quantities large enough to cause significantly elevated concentrations of enterococci in Good Harbor Creek.

Enterococci concentrations detected in the eastern side of Good Harbor Creek appear to be driven by wildlife, except for less elevated but still significant concentrations of enterococci and human bacteroides detected adjacent to the sanitary sewer force main located within Thatcher Road that crosses the creek. In this area, it is likely that the sewer infrastructure is contributing to the detected elevated enterococci concentrations.

Drainage infrastructure investigated during dry weather conditions does not appear to be contributing bacteria to Good Harbor Creek.

RECOMMENDATIONS

Woodard & Curran's initial recommendations focus on continued investigation of sanitary sewer infrastructure, along with potential repair and/or rehabilitation of the infrastructure depending on the findings of the investigation. Additionally, we recommend additional investigation of low-level concentrations of some illicit discharge parameters detected in drainage infrastructure associated with network draining to DO_100, and further evaluation of enterococci detections attributed to non-human sources in the western portion of Good Harbor Creek to verify the source. Where sanitary sewer recommendations are enacted, the City should continue to monitor water quality post-infrastructure improvements, where applicable, to verify the bacteria sources have been abated.

A discussion of recommended actions related to the sanitary sewer system, drainage system, and watershed management is provided below.



Sanitary Sewer System

Hartz Street Sewer Main Recommendations

Based on the completed inspection of the 8-inch sewer main on Hartz Street from SMH_1895 to SMH_1892, we recommend the following rehabilitation and additional investigations to confirm the source of sanitary sewerage exfiltration, further investigate the source of FOG within the system and identify operational issues that could be causing surcharging:

- Perform grouting of the sanitary service connections found to be in poor conditions. This will eliminate the possibility of sewerage exfiltration sources at the service connections.
- Utilize a lateral launching CCTV camera to perform inspection of the sanitary service laterals on the Hartz Street sewer main. This will confirm the condition of the service laterals and identify any sewerage exfiltration sources.
- Perform manhole inspections for sanitary sewer manholes on Hartz Street near Good Harbor Creek. This will identify any defects, structural issues, and evidence of surface surcharging at the sewer manholes.
- Perform additional CCTV investigations within the upstream contributing sewershed area contributing to the Hartz Street sewer main. Although it is currently unknown if the surcharging in the system is being caused fully or partially by the presence of FOG, it is critical to identify and eliminate sources of excessive FOG.
- Continue to monitor flows and operation at the Hartz Street/Bass Ave Pump Station during storm events and high flow circumstances to confirm there are no downstream operational issues that could be causing surcharging sewer conditions upstream.

Neptune Place Cross-Country Sewer Main Recommendations

Based on the incomplete inspection of the 10-inch Neptune Place Cross-Country Sewer Main from SMH_700 to SMH_710, we recommend the following additional investigations and rehabilitation to confirm the source of sanitary sewerage exfiltration:

- Due to the reduced size of the wrinkled CIPP lined sewer main, utilize a lateral launching CCTV camera to inspect the Neptune Place Cross-Country sewer main. This will confirm the condition of the sewer main and identify any sewerage exfiltration sources.
- Perform manhole inspections for sanitary sewer manholes on the Neptune Place Cross-Country sewer main close to Good Harbor Creek. This will identify any defects, structural issues, and evidence of surface surcharging at the sewer manholes.
- Perform root removal and grouting of the sanitary service connections found to be in poor conditions. This will eliminate the possibility of sewerage exfiltration sources at the service connections.
- Once service connection rehabilitation is complete, utilize a lateral launching CCTV camera to perform inspection the sanitary service laterals on the Neptune Place Cross-Country sewer main. This will confirm the condition of the service laterals and identify any sewerage exfiltration sources.



Thatcher Road Force Main Recommendations

This sewer infrastructure has not been investigated as part of the activities discussed in this memorandum. Woodard & Curran recommends the City investigate the condition of the sewer force main segment extending over Good Harbor Creek to determine whether pipe defects are present that have the potential to contribute sewage to the creek.

Drainage System

DO-100 Drainage Area Investigations

Concentrations of surfactants, chlorine, and ammonia detected in the pipe segment DMH_3490 : DMH_13804, located between the Good Harbor Beach Condominiums at 78 Thatcher Road and the building to the northeast located at 76 Witham Street (**Figure 1**) indicate a non-stormwater discharge is entering the City's drainage infrastructure in this location. Standing water was observed in surrounding drainage infrastructure, which may be due to blockages in the pipe network or tidal influence. This portion of the MS4 should be inspected to remove blockage sources, if present, to promote proper flow through the drainage pipes, and proximal drainage pipes should be investigated to determine the source of the detections. Additionally, building inspections including dye testing of sanitary sewer and drainage infrastructure should be conducted at 78 Thatcher Road and 76 Witham Street to determine whether service connections in these buildings are properly connected to the appropriate City infrastructure.


The City should investigate locations where drainage structure was accessed and observed to contain standing water to determine whether blockages are present that are impeding flow or infrastructure is subject to tidal influence. Blockages should be removed, where identified, to promote stormwater flow through the MS4.

Watershed Management

Further evaluation of the source of enterococci concentrations not attributed to human sources is recommended to refine the City's understanding of bacterial contributions to Good Harbor Creek not attributed to sanitary sewer infrastructure. Recommended initial actions include collection of surface water samples for avian bacteroides analysis to verify that bacteria concentrations are coming from bird populations. This data can be used to determine future mitigation options for non-human enterococci contributions to the creek.



FIGURES



Study Area Overview
Good Harbor Creek
Bacterial Source Investigation
Figure 1

- Legend**
- Surface Water Sample
 - Sewer Manhole
 - Investigated Areas
 - Study Area
 - ◆ Outfall
 - Drainage Pipe
 - Sewer Main
 - Storm Manhole
 - Sewer Lateral
 - Catch Basin


N

Project #: 0234330.00
Map Created: November 2022

0 200 400 800 Feet

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

Dry Weather Screening Results DO_100	Sample
Associated Drainage Outfall	DO_100
Sample Date	5/17/2022
Pipe ID	DMH_3490 : DMH_13804
Flow/Velocity/Color	Yes/Slow/Clear
Ammonia (mg/L)	0.2
Surfactants (mg/L)	0.55*
Chlorine (mg/L)	0.20
Enterococci (MPN/100mL)	75
Total Bacteroides (CE/100mL)	5,261
Human Bacteroides (CE/100mL)	Not Detected



Study Area Detail

Drainage Investigation to DO_100

Figure 2


Legend

- Surface Water Sample
- ◆ Outfall
- ◇ Inspected Outfall
- Storm Manhole
- Inspected Storm Manhole
- Catch Basin
- Inspected Catch Basin
- Sewer Manhole
- Sewer Pump Station

Drainage Pipe Inspection Status

- Confirmed - Visual Indicator
- Suspected - Positive Test Kit
- Assessed - Upstream Indicator
- Cleared - No Evidence
- N/A - Standing Water
- Other
- Not Assessed

- Sewer Lateral
- Drainage Pipe
- Sewer Main
- ⋮ Investigated Areas




Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

Figure Exported: 11/17/2022 By: M.Landin Using: \woodardcurran.net\shared\Projects\0234330.00 Gloucester MA - Good Harbor Creek (DDE)\wp\GIS\Map\GIS\Gloucester_Bacteria_Sources_Investigation.aprx Layout: Figure 2.Rail

Figure Exported: 11/1/2022 By: M.Landin Using: \woodardcurran.net\shared\Projects\0234330.00 Gloucester MA - Good Harbor Creek (DDE)\wp\GIS\Map\Gaussreiter_Bacteria_Sources_ Investigation.aprx Layout: Figure 3 Rrail



Study Area Detail

Drainage Investigation
to DO_127

Figure 3

Legend

- | | | |
|--|---|--|
| ● Surface Water Sample | ■ Confirmed - Visual Indicator | — Sewer Lateral |
| ◆ Outfall | ■ Suspected - Positive Test Kit | — Drainage Pipe |
| ◇ Inspected Outfall | ■ Assessed - Upstream Indicator | — Sewer Main |
| ○ Storm Manhole | ■ Cleared - No Evidence | Investigated Areas |
| ○ Inspected Storm Manhole | ■ N/A - Standing Water | |
| ■ Catch Basin | ■ Other | |
| □ Inspected Catch Basin | ■ Not Assessed | |
| ● Sewer Manhole | | |


0 5 10 20 Feet



**Woodard
& Curran**

Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**




Study Area Detail

Drainage Investigation to DO_101

Figure 4

Legend	● Surface Water Sample	— Sewer Lateral
	◆ Outfall	— Drainage Pipe
	◆ Inspected Outfall	— Sewer Main
	○ Storm Manhole	 Investigated Areas
	○ Inspected Storm Manhole	
□ Catch Basin	■ Confirmed - Visual Indicator	■ Suspected - Positive Test Kit
□ Inspected Catch Basin	■ Assessed - Upstream Indicator	■ Cleared - No Evidence
● Sewer Manhole	■ N/A - Standing Water	■ Other
	■ Not Assessed	




Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

Figure Exported: 11/1/2022 By: M.Landin Using: woodardcurran.net\shared\Projects\0234330.00 Gloucester MA - Good Harbor Creek (DDE)\wp\GIS\Map\Gloucester_Bacteria_Sources_ Investigation.aprx Layout: Figure 4.Rail

Figure Exported: 11/1/2022, By: M. Andina, Using: \\woodardcurran.net\share\Projects\0234330.00 Gloucester MA - Good Harbor Creek (DDE)\wp\GIS\Map\Gloucester, Bacteria - Source Investigation\src Layout - Study Area Detail Figure 4-REAL




Study Area Detail

Drainage Investigation
to DO_6223

Figure 5


Legend

- | | | |
|---------------------------|---------------------------------|----------------------|
| ● Surface Water Sample | ■ Confirmed - Visual Indicator | — Sewer Lateral |
| ◆ Outfall | ■ Suspected - Positive Test Kit | — Drainage Pipe |
| ◇ Inspected Outfall | ■ Assessed - Upstream Indicator | — Sewer Main |
| ○ Storm Manhole | ■ Cleared - No Evidence | ⋮ Investigated Areas |
| ○ Inspected Storm Manhole | ■ N/A - Standing Water | |
| □ Catch Basin | ■ Other | |
| □ Inspected Catch Basin | ■ Not Assessed | |
| ● Sewer Manhole | | |



Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**




Study Area Detail

Drainage Investigation
to DO_1727

Figure 6

Legend

- | | | |
|------------------------|---------------------------|------------------------|
| ● Surface Water Sample | ● Sewer Pump Station | — Sewer Lateral |
| ◆ Outfall | ◆ Inspected Outfall | — Drainage Pipe |
| ○ Storm Manhole | ○ Inspected Storm Manhole | — Sewer Main |
| □ Catch Basin | □ Inspected Catch Basin | --- Investigated Areas |
| ● Sewer Manhole | | |
-
- | Drainage Pipe Inspection Status | |
|---------------------------------|---------------------------------|
| ■ Confirmed - Visual Indicator | ■ Assessed - Upstream Indicator |
| ■ Suspected - Positive Test Kit | ■ Cleared - No Evidence |
| ■ N/A - Standing Water | ■ Other |
| ■ Not Assessed | |




Woodard & Curran

Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

Figure Exported: 11/1/2022 By: M.A. Using: ArcGIS Pro 2.9.1.0.00 Gloucester MA - Good Harbor Creek (DDE) w/ GIS Maps/Gloucester, Bacteria - Source: Investigation area Layout: Figure 6 Rial




Study Area Detail

Drainage Investigations
to DO_1717 and DO_1724

Figure 7

Legend


- | | | | | | | | | | |
|--------------------------------|---------------------------------|---------------------------------|-------------------------|---------------------------|---------------|-------------------------|-----------------|-----------------------------------|----------------------|
| ● Surface Water Sample | ◆ Outfall | ◆ Inspected Outfall | ● Storm Manhole | ● Inspected Storm Manhole | ■ Catch Basin | ■ Inspected Catch Basin | ● Sewer Manhole | ● Drainage Pipe Inspection Status | — Sewer Lateral |
| ● Confirmed - Visual Indicator | ● Suspected - Positive Test Kit | ● Assessed - Upstream Indicator | ● Cleared - No Evidence | ● N/A - Standing Water | ● Other | ● Not Assessed | — Drainage Pipe | — Sewer Main | ■ Investigated Areas |



Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

Figure Exported: 11/1/2022, By: N.Landin, Url: \\woodardcurran.net\shared\Projects\0234330.00 Gloucester MA - Good Harbor Creek IDDE\wp\GIS\Map\GisUser\Bacteria_Sources_ Investigation.aprx Layout: Figure 7.aprx



Sample Location Map

Wet Water & Dry Water
Surface Water Sampling

Figure 8

Surface Water Sample Results

Sample Location	Sample Point 15	Sample Point 15	Sample Point 5	Sample Point 5	Sample Point 16	Sample Point 16	Sample Point 13	Sample Point 13	Sample Point 39	Sample Point 39	Sample Point 1-GHB	Sample Point 1-GHB
Weather Type	Dry	Wet	Dry	Wet	Dry	Wet	Dry	Wet	Dry	Wet	Dry	Wet
Sample Date	5/09/2022	9/22/2022	5/10/2022	9/22/2022	5/19/2022	9/22/2022	5/19/2022	9/22/2022	5/19/2022	9/22/2022	Not Sampled	9/22/2022
Enterococci (MPN/100mL)	2	14,136	11	19,863	884	3,654	556	15,531	301	>24,196	Not Sampled	1,616
Total Bacteroides (CE/100mL)	2,296	48,821	19,409	148,839	119,821	26,973	2,506	42,114	90,655	3,187,990	Not Sampled	48,821
Human Bacteroides (CE/100mL)	421	4,344	450	50,133	None Detected	None Detected	None Detected	7,950	None Detected	None Detected	Not Sampled	1,180
Surfactants (mg/L)	<0.12	Not Analyzed	0.18	Not Analyzed	1.8	Not Analyzed	1.2	Not Analyzed	1.1	Not Analyzed	Not Sampled	Not Analyzed



Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**





Figure Exported: 11/1/2022 By: M. Andina Using: \\woodardcurran.net\shared\Projects\0234330.00 Gloucester MA - Good Harbor Creek (DDE)\wp\GIS\Map\Gaussreiter_Bacteria_Sources_ Investigation.aprx Layout: Figure 9 Rial

Study Area Detail

Approximate Extent of CCTV Inspection:
Cross-Country Sanitary Sewer Line at Neptune Place
Figure 9

Legend


- | | | |
|---------------------------|---------------------------------|------------------------|
| ● Surface Water Sample | Drainage Pipe Inspection Status | — Sewer Lateral |
| ◆ Outfall | ■ Confirmed - Visual Indicator | — Drainage Pipe |
| ◇ Inspected Outfall | ■ Suspected - Positive Test Kit | — Sewer Main |
| ● Storm Manhole | ■ Assessed - Upstream Indicator | --- Investigated Areas |
| ● Inspected Storm Manhole | ■ Cleared - No Evidence | |
| ■ Catch Basin | ■ N/A - Standing Water | |
| ■ Inspected Catch Basin | ■ Other | |
| ● Sewer Manhole | ■ Not Assessed | |



Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

Figure Exported: 11/1/2022, By: N.Amadi, Using: woodardcurran.net\shared\Projects\0234330.00 Gloucester MA - Good Harbor Creek (DDE)\wp\GIS\Map\Gauss\Bacteria_Sources_ Investigation.aprx Layout: Figure 10 Real




Approximate extent of CCTV Investigation

Study Area Detail

Approximate Extent of Sanitary Sewer CCTV Inspection: Hartz Street

Figure 10

Legend		Drainage Pipe Inspection Status
●	Surface Water Sample	 Confirmed - Visual Indicator
◆	Outfall	 Suspected - Positive Test Kit
◆	Inspected Outfall	 Assessed - Upstream Indicator
○	Storm Manhole	 Cleared - No Evidence
○	Inspected Storm Manhole	 N/A - Standing Water
□	Catch Basin	 Other
□	Inspected Catch Basin	 Not Assessed
●	Sewer Manhole	
●	Sewer Pump Station	
—	Sewer Lateral	
—	Drainage Pipe	
—	Drainage Pipe - Field Sketch	
—	Sewer Main	
	Investigated Areas	



Project #: 0234330.00
Map Created: November 2022

Third Party GIS Disclaimer: This map is for reference and graphical purposes only and should not be relied upon by third parties for any legal decisions. Any reliance upon the map or data contained herein shall be at the users' sole risk. **Data Sources:**

**ATTACHMENT A: CITY OF GLOUCESTER DEPARTMENT OF PUBLIC
WORKS SURFACE WATER SAMPLING RESULTS –
AUGUST 2021**




Good Harbor Creek					
Asset (S - #)	Date Collected	Time	Enterococci- CSU/ML	Tidal	Sample Location
1	08/20/2021	7:30 AM	7700	Low	Creek
1	08/13/2021	8:10 AM	389	Low	Creek
1	08/10/2021	1:06 PM	30	High	Creek
1	08/09/2021	8:34 AM	1309	Low	Creek
1	08/05/2021	9:05 AM	5475	Incoming	Creek at footbridge
2	08/02/2021	12:18 PM	431	-	
2	08/03/2021	7:44 AM	512	-	Creek
2	08/05/2021	10:00 AM	3076	Incoming	Creek
3	08/02/2021	12:45 PM	241	-	
3	08/05/2021	10:55 AM	2481	-	Drain Outfall
4	08/09/2021	10:05 AM	121	Low	Stream
4	08/10/2021	2:10 PM	161	High	Culvert
5	08/17/2021	5:15 PM	1050	Incoming	Creek
5	08/13/2021	8:35 AM	1070	Low	Creek at culvert
5	08/17/2021	6:25 PM	464	Incoming	Creek
5	08/03/2021	7:52 AM	1178		Creek
5	08/02/2021	12:55 PM	1043		
5	08/04/2021	2:00 PM	1223		Creek at culvert
5	08/18/2021	1:00 PM		Low	Creek
5	08/19/2021	12:00 PM	24200	Outgoing	Creek
5	08/17/2021	7:45 PM	216	High	Creek
5	08/05/2021	12:20 PM	2909	Outgoing	Creek
5	08/09/2021	10:50 AM	565	Low	Creek at culvert
5	08/17/2021	9:10 AM	1100	Outgoing	Creek
5	08/20/2021	7:55 AM	2610	Low	Creek
5	08/19/2021	10:15 AM	2810	Outgoing	Creek
5	08/10/2021	1:20 PM	771	High	Creek at culvert
5	08/17/2021	8:35 PM	1170	Outgoing	Creek
5	08/17/2021	1:15 PM	1080	Low	Creek
5	08/19/2021	1:50 PM	24200	Low	Creek
6	08/10/2021	2:35 PM	435	High	Stream
6	08/09/2021	10:40 AM	313	Low	Stream
7	08/02/2021	1:20 PM	10		Outfall
7	08/03/2021	8:00 AM	10		Outfall
7	08/13/2021	8:25 AM	10	Low	Drain Outfall
7	08/04/2021	2:05 PM	10		Outfall
11	08/02/2021	8:37 AM	10		Good Harbor Beach
13	08/11/2021	8:30 AM	2987	Low	Creek
13	08/09/2021	8:50 AM	990	Low	Creek
13	08/05/2021	9:45 AM	24196	Incoming	Creek
13	08/11/2021	4:30 PM	882	Outgoing	Creek
13	08/11/2021	2:15 PM	20	High	Creek
13	08/20/2021	8:20 AM		Incoming	Creek
13	8/13/2021	9:50 AM	512	Low	Creek
13	08/11/2021	6:05 PM	714	Low	Creek


Good Harbor Creek					
Asset (S - #)	Date Collected	Time	Enterococci- CSU/ML	Tidal	Sample Location
13	08/10/2021	1:45 PM	121	High	Creek
13	08/11/2021	12:25 PM	546	Incoming	Creek
14	08/02/2021	1:00 PM	1314		Outfall
15	08/17/2021	6:35 PM	627	Incoming	Creek
15	08/17/2021	1:20 PM	708	Low	Creek
15	08/20/2021	8:15 AM	933	Low	Creek
15	08/05/2021	12:40 PM	3076	Incoming	Creek
15	08/03/2021	8:00 AM	495		Creek Culvert
15	08/02/2021	1:10 PM	754		
15	08/17/2021	7:50 PM	820	High	Creek
15	08/04/2021	1:50 PM	556		Creek
15	08/13/2021	8:30 AM	537	Low	Creek
16	08/05/2021	10:35 AM	24196	Incoming	Creek
17	8/20/2021	7:45 AM	5480	Low	Creek
17	08/09/2021	10:45 AM	631	Low	Creek
17	08/19/2021	2:00 PM	24200	Outgoing	Creek
17	08/05/2021	8:50 AM	17329	Incoming	Creek
17	08/19/2021	10:25 AM	670	Outgoing	Creek
17	08/17/2021	5:05 PM	110	Incoming	Creek
17	08/10/2021	1:30 PM	160	High	Creek
17	08/19/2021	12:10 PM	10400	Outgoing	Creek
17	8/13/2021	8:55 AM	1520	Low	Creek
17	08/17/2021	6:15 PM	30	Incoming	Creek
17	08/17/2021	7:35 PM	72	High	Creek
17	08/17/2021	12:55 PM	135	Low	Creek
18	08/17/2021	7:40 PM	226	High	Creek
18	08/20/2021	7:50 AM	3870	Low	Creek
18	08/17/2021	6:20 PM	122	Incoming	Creek
18	08/17/2021	9:00 AM	538	Outgoing	Creek
18	08/19/2021	10:20 AM	860	Outgoing	Creek
18	08/17/2021	5:10 PM	377	Incoming	Creek
18	08/19/2021	1:55 PM	24200	Outgoing	Creek
18	08/19/2021	12:05 PM	24200	Outgoing	Creek
18	8/17/2021	1:00 PM	173	Low	Creek
19	08/05/2021	8:40 AM	1317	Incoming	Drain Manhole
20	08/05/2021	8:30 AM	7270	Incoming	Drain Manhole
21	08/05/2021	8:24 AM	480	Incoming	Drain Manhole
22	08/11/2021	4:20 PM	226	Outgoing	Creek
22	08/17/2021	5:00 PM	41	Incoming	Creek
22	08/11/2021	6:00 PM	414	Low	Creek
22	8/19/2021	12:15 PM	2760	Outgoing	Creek
22	08/11/2021	7:55 AM	3448	Low	Creek
22	08/17/2021	7:30 PM	75	High	Creek
22	8/19/2021	10:30 AM	109	Outgoing	Creek
22	08/10/2021	1:40 PM	10	High	Creek
22	08/09/2021	8:43 AM	2247	Low	Creek
22	08/11/2021	12:20 PM	262	Incoming	Creek
22	08/17/2021	12:50 PM	85	Low	Creek
22	08/11/2021	2:10 PM	10	High	Creek
22	8/19/2021	2:05 PM	24200	Outgoing	Creek
22	8/20/2021	7:40 AM	9140	Low	Creek

Good Harbor Creek					
Asset (S - #)	Date Collected	Time	Enterococci- CSU/ML	Tidal	Sample Location
22	08/13/2021	9:55 AM	1370	Low	Creek
22	08/17/2021	6:10 PM	20	Incoming	Creek
24	08/09/2021	10:30 AM	110	-	Outfall stream
26	8/10/2021	2:20 PM	364	High	Stream
26	08/09/2021	10:20 AM	63	Low	Stream
27	08/11/2021	6:15 PM	1529	Low	Creek
27	08/11/2021	4:40 PM	2064	Outgoing	Creek
27	08/11/2021	8:10 AM	1106	Low	Creek
27	08/13/2021	9:35 AM	862	Low	Creek
27	08/16/2021	11:30 AM	364	Outgoing	Creek
27	08/17/2021	3:15 PM	776	Low	Creek
27	08/11/2021	12:40 PM	573	Incoming	Creek
27	8/11/2021	2:30 PM	108	High	Creek
27	08/17/2021	8:35 AM	703	Outgoing	Creek
27	08/20/2021	8:55 AM	10500	Incoming	Creek
28	08/09/2021	9:00 AM	637	Low	Outfall culvert
28	08/10/2021	1:50 PM	1989	High	Culvert Creek
28	08/13/2021	9:45 AM	1990	Low	Creek
28	08/17/2021	3:30 PM	2140	Low	Creek
28	08/17/2021	8:50 AM	2490	Outgoing	Creek
29	08/17/2021	8:25 AM	733	Outgoing	Creek
29	08/09/2021	9:30 AM	201	Low	Creek
29	08/11/2021	12:45 PM	323	Incoming	Creek
29	08/16/2021	11:25 AM	384	Outgoing	Creek
29	08/20/2021	8:35 AM	2380	Incoming	Creek
29	08/11/2021	2:35 PM	223	High	Creek
29	08/11/2021	8:15 AM	355	Low	Creek
29	08/17/2021	3:10 PM	309	Low	Creek
29	08/11/2021	4:45 PM	884	Outgoing	Creek
29	08/10/2021	2:00 PM	855	High	Creek
29	08/13/2021	9:30 AM	1400	Low	Creek
29	08/11/2021	6:20 PM	144	Low	Creek
30	08/16/2021	11:40 PM	0	Low	Creek
30	08/20/2021	9:05 AM	122	Incoming	Creek
30	08/13/2021	9:05 AM	10	Low	Drain Outfall
30	08/08/2021	9:00 AM	1956	Incoming	Creek
31	08/17/2021	5:20 PM	7270	Incoming	Creek
31	08/17/2021	1:25 PM	2910	Low	Creek
31	08/13/2021	9:20 AM	3260	Low	Outfall
31	08/20/2021	10:00 AM	1190	Low	Creek
31	08/16/2021	11:50 AM	132	Low	Creek
31	08/17/2021	6:30 PM	1850	Incoming	Creek
32	08/11/2021	8:05 AM	1529	Low	Creek
32	08/20/2021	8:50 AM	3260	Incoming	Creek
32	08/11/2021	4:35 PM	3255	Outgoing	Creek
32	08/11/2021	6:10 PM	354	Low	Creek
32	08/17/2021	8:45 AM	241	Outgoing	Creek
32	08/11/2021	12:35 PM	457	Incoming	Creek
32	08/17/2021	3:25 PM	41	Low	Creek
32	08/10/2021	1:55 PM	789	High	Creek
32	08/11/2021	2:25 PM	631	High	Creek

Good Harbor Creek					
Asset (S - #)	Date Collected	Time	Enterococci- CSU/ML	Tidal	Sample Location
32	08/09/2021	9:50 AM	1439	Low	Creek
33	08/13/2021	8:20 AM	529	Low	Drain Outfall
34	08/13/2021	8:15 AM	144	Low	Drain Outfall
34	08/20/2021	7:35 AM	512	Low	Creek
35	08/16/2021	11:45 AM	130	Low	Creek
35	08/20/2021	9:10 AM	262	Incoming	Creek
35	08/13/2021	9:10 AM	1380	Low	Creek
36	08/20/2021	8:00 AM	7270	Low	Creek
36	08/16/2021	8:45 AM	161	Outgoing	Creek
37	08/16/2021	8:50 AM	473	Outgoing	Creek
38	08/20/2021	8:05 AM	14100	Low	Creek
38	08/16/2021	9:00 AM	379	Outgoing	Creek
39	08/19/2021	10:40 AM	14100	Outgoing	Creek
39	08/20/2021	9:25 AM	19900	Incoming	Creek
39	08/16/2021	9:10 AM	1300	Outgoing	Creek
40	08/17/2021	8:15 AM	1220	Outgoing	Creek
40	08/17/2021	3:00 PM	1110	Low	Creek
40	08/16/2021	11:15 AM	520	Outgoing	Creek
40	08/20/2021	8:25 AM	1010	Incoming	Creek
41	08/20/2021	8:30 AM	1150	Incoming	Creek
41	08/17/2021	8:20 AM	776	Outgoing	Creek
41	08/16/2021	11:20 AM	246	Outgoing	Creek
41	08/20/2021	8:45 AM	1920	Incoming	Creek
41	08/17/2021	3:05 PM	583	Low	Creek
42	08/17/2021	8:35 AM	908	Outgoing	Creek
42	08/20/2021	9:00 AM	5480	Incoming	Creek
42	08/17/2021	3:20 PM	1790	Low	Creek
43	08/17/2021	8:40 AM	393	Outgoing	Creek
45	08/18/2021	12:25 PM		Low	Creek
46	08/20/2021	9:15 AM	3080	Incoming	Creek
46	08/19/2021	10:35 AM	85	Outgoing	Creek
48	08/20/2021	9:20 AM	13000	Incoming	Creek
48	08/19/2021	10:45 AM	4880	Outgoing	Creek
49	08/20/2021	8:40 AM	2760	Incoming	Creek



Entero sampling - Good harbor area (1)



Entero Sampling - Good harbor area (2)

ATTACHMENT B: LABORATORY ANALYTICAL REPORTS





CERTIFICATE OF ANALYSIS

CUSTOMER INFORMATION:

Janelle Bonn
Woodard & Curran
40 Shattuck Rd.
Andover, MA 01810

SAMPLE INFORMATION:

Sample(s) Collected By: Hector Ortega
Sample Information: Collected 9/22/22 see location and time below
Date and Time Received: 9/22/22, 1615
Date and Time Analyzed: 9/22/22, 1630

FINDINGS:

Biomarine Sample ID	Sample Location	Time Sampled	Enterococci/100 mL
75072 A	15-Good Harbor Creek-Cross Country Sewer Line	1545	14,136
75072 B	5-GHC-Hartz St. Culvert	1518	19,863
75072 C	1-GHB- Good Harbor Beach Boardwalk	1415	1,616
75072 D	13-GHC-Thatcher Road Crossing	1445	15,531

METHOD: IDEXX Enterolert (MPN)

Jim Groleau, Laboratory Director



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612202151
 EMSL CUSTOMER ID: WOCU33

Attention: Janelle Bonn
 Woodard & Curran
 40 Shattuck Road, Suite 110
 Andover, MA 01810

Phone: (978) 557-8150
 Email:

Customer PO:
 LIMS Project ID:
 Project ID: Gloucester IDDE

Date Received: 9/24/2022
 Date Analyzed: 9/28/2022
 Date Reported: 9/29/2022
 Date Amended:

Test Report: Rapid Detection of Human Bacteroides by Quantitative PCR

EMSL Test: M199

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
2151-1	13	GHC - Thaichee Road Crossing	550	550	7,950
2151-2	5	GHC - Hartz Street Culvert	550	550	50,133
2151-3	1	GHC - Good Harbor Beach Boardwalk	925	925	1,180
2151-4	16	Marina Drive & Lenna Drive MS4 Outfall	180	180	None Detected
2151-5	39	Witham St, South of Juppa Way at Wester End of Pond	150	150	None Detected
2151-6	15	Good Harbor Creek - Cross Country Sewer Line	500	500	4,344

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it

Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612202151
 EMSL CUSTOMER ID: WOCU33

Attention: Janelle Bonn
 Woodard & Curran
 40 Shattuck Road, Suite 110
 Andover, MA 01810

Customer PO:
LIMS Project ID:
Project ID: Gloucester IDDE

Phone: (978) 557-8150
Email:

Date Received: 9/24/2022
Date Analyzed: 9/28/2022
Date Reported: 9/29/2022
Date Amended:


Test Report: Rapid Detection of Total Bacteroides by Quantitative PCR

EMSL Test: M095

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
2151-1	13	GHC - Thaichee Road Crossing	550	550	42,114
2151-2	5	GHC - Hartz Street Culvert	550	550	148,839
2151-3	1	GHC - Good Harbor Beach Boardwalk	925	925	5,853
2151-4	16	Marina Drive & Lenna Drive MS4 Outfall	180	180	26,973
2151-5	39	Witham St, South of Juppa Way at Wester End of Pond	150	150	3,187,990
2151-6	15	Good Harbor Creek - Cross Country Sewer Line	500	500	48,821

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity


 Sergey Balashov, Ph.D.

CERTIFICATE OF ANALYSIS

CUSTOMER INFORMATION:

Janelle Bonn
Woodard & Curran
40 Shattuck Rd.
Andover, MA 01810

SAMPLE INFORMATION:

Sample(s) Collected By: Hector Ortega
Collected 9/22/22 see location and time below
(Samples received out of hold time. The client was notified and requested that samples be run out of holding time).


Sample Information:

Date and Time Received: 9/23/22, 1145
Date and Time Analyzed: 9/23/22, 1600

FINDINGS:

Biomarine Sample ID	Sample Location	Time Sampled	Enterococci/100 mL
75077 A	16-Marina Dr. and Loma Dr. MS4 Outfall	1700	3,654
75077 B	39-Whitham St. south of Topra Way at western end of pond	1745	>24,196

METHOD: IDEXX Enterolert (MPN)



Jim Groleau, Laboratory Director



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201048
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Customer PO: SDEC42
LIMS Project ID:
Project ID: Gloucester IDDE

Phone: (978) 975-0500
Email:

Date Received: 5/10/2022
Date Analyzed: 5/12/2022
Date Reported: 5/13/2022
Date Amended:

Test Report: Rapid Detection of Total Bacteroides by Quantitative PCR

EMSL Test: M095

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
1048-2	Creek	Surface Water	275	275	2,296

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity

Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201048
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Customer PO: SDEC42
LIMS Project ID:
Project ID: Gloucester IDDE

Phone: (978) 975-0500
Email:


Date Received: 5/10/2022
Date Analyzed: 5/12/2022
Date Reported: 5/13/2022
Date Amended:

Test Report: Rapid Detection of Human Bacteroides by Quantitative PCR

EMSL Test: M199

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
1048-1	Creek	Surface Water	275	275	421

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.
 EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of


Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201056
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergy
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Phone: (978) 975-0500

Email:

Customer PO: 22.016

LIMS Project ID:

Project ID: Gloucester IDDE

Date Received: 5/11/2022

Date Analyzed: 5/13/2022

Date Reported: 5/16/2022

Date Amended:


Test Report: Rapid Detection of Total Bacteroides by Quantitative PCR

EMSL Test: M095

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs /100 mL
1056-2	Hartz Culvert	Surface Water/Culvert	280	280	19,409

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity



Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201056
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergy
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Customer PO: 22.016
LIMS Project ID:
Project ID: Gloucester IDDE

Date Received: 5/11/2022
Date Analyzed: 5/13/2022
Date Reported: 5/16/2022
Date Amended:

Phone: (978) 975-0500
Email:

Test Report: Rapid Detection of Human Bacteroides by Quantitative PCR

EMSL Test: M199

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
1056-1	Hartz Culvert	Surface Water/Culvert	275	275	450

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of

Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201144
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Customer PO: 22.016
LIMS Project ID:
Project ID: Gloucester IDDE

Phone: (978) 975-0500
Email:

Date Received: 5/20/2022
Date Analyzed: 5/24/2022
Date Reported: 5/25/2022
Date Amended:


Test Report: Rapid Detection of Total Bacteroides by Quantitative PCR

EMSL Test: M095

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs /100 mL
1144-1	13	Creek	1050	1050	2,506
1144-2	39	Creek	1000	1000	90,655
1144-3	16	Creek	1050	1050	119,821

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity



Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201144
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Customer PO: 22.016
LIMS Project ID:
Project ID: Gloucester IDDE

Phone: (978) 975-0500
Email:

Date Received: 5/20/2022
Date Analyzed: 5/24/2022
Date Reported: 5/25/2022
Date Amended:


Test Report: Rapid Detection of Human Bacteroides by Quantitative PCR

EMSL Test: M199

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
1144-1	13	Creek	1050	1050	None Detected
1144-2	39	Creek	1000	1000	None Detected
1144-3	16	Creek	1050	1050	None Detected

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of



Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
200 Route 130 North,
Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201090
EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
SDE Civil & Environmental Engineering
354 Merrimack Street, Suite 200
Lawrence, MA 01843

Phone: (978) 975-0500
Email:

Customer PO: 22.016
LIMS Project ID:
Project ID: Gloucester IDDE
Date Received: 5/13/2022
Date Analyzed: 5/17/2022
Date Reported: 5/18/2022
Date Amended:

Test Report: Rapid Detection of Total Bacteroides by Quantitative PCR

EMSL Test: M095

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs /100 mL
1090-2	DMH_396	Storm Drain Manhole	260	260	480

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity

Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201090
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Customer PO: 22.016
 LIMS Project ID:
 Project ID: Gloucester IDDE

Phone: (978) 975-0500
 Email:

Date Received: 5/13/2022
 Date Analyzed: 5/17/2022
 Date Reported: 5/18/2022
 Date Amended:

Test Report: Rapid Detection of Human Bacteroides by Quantitative PCR

EMSL Test: M199

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
1090-1	DMH-396	Storm Drain Manhole	250	250	None Detected

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of

Sergey Balashov, Ph.D.



EMSL ANALYTICAL, INC.
 200 Route 130 North,
 Cinnaminson, NJ 08077
DNALab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201124
 EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
 SDE Civil & Environmental Engineering
 354 Merrimack Street, Suite 200
 Lawrence, MA 01843

Customer PO: 22.016
LIMS Project ID:
Project ID: Gloucester IDDE

Phone: (978) 975-0500
Email:

Date Received: 5/18/2022
Date Analyzed: 5/19/2022
Date Reported: 5/23/2022
Date Amended:

Test Report: Rapid Detection of Total Bacteroides by Quantitative PCR

EMSL Test: M095

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
1124-1	DMH_13804	Storm Drain Manhole	1025	1025	5,261

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity

Sergey Balashov, Ph.D.

LABORATORY REPORT

Woodard & Curran
Attn: Janelle Bonn
33 Broad Street
One Weybosset Hill, Floor 7
Providence, RI 02903

Date Received: 5/10/2022
Date Reported: 5/12/2022
P.O. Number

Work Order #: 2205-07633

Project Name: PROJECT # 22.01B GLOUCESTER IDDE

Enclosed are the analytical results and Chain of Custody for your project referenced above. The sample(s) were analyzed by our Warwick, RI laboratory unless noted otherwise. When applicable subcontracted results are noted and subcontracted reports are enclosed in their entirety.

All samples were analyzed within the established guidelines of US EPA approved methods with all requirements met, unless otherwise noted at the end of a given sample's analytical results or in a case narrative.

The Detection Limit is defined as the lowest level that can be reliably achieved during routine laboratory conditions.

These results only pertain to the samples submitted for this Work Order # and this report shall not be reproduced except in its entirety.

We certify that the following results are true and accurate to the best of our knowledge. If you have questions or need further assistance, please contact our Customer Service Department.

Approved by:



Nicole Skyleson
Data Reporting Manager

R.I. Analytical Laboratories, Inc.

Laboratory Report

Woodard & Curran

Work Order #: 2205-07633

Project Name: PROJECT # 22.01B GLOUCESTER IDDE

Sample Number: 001
Sample Description: TB-1
Sample Type : GRAB
Sample Date / Time : 5/10/2022 @ 09:58

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
E. Coli 18 Hour	<1.0	1.0	MPN/100 ml	SM9223B	5/10/2022 16:59	LKB

Sample Number: 002
Sample Description: HARTZ CULVERT
Sample Type : GRAB
Sample Date / Time : 5/10/2022 @ 10:00

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
Enterococci	10.9	1.0	MPN/100 ml	IDEXX Enterolert	5/10/2022 17:02	LKB
LAS Surfactants (MBAS)	0.18	0.12	mg/l	SM5540C 18-21ed	5/10/2022 17:58	JEP



CHAIN OF CUSTODY RECORD

41 Illinois Avenue
Warwick, RI 02888-3007
Tel: 800-937-2580

131 Coolidge St., Suite 105
Hudson, MA 01749-1331
Tel: 800-937-2580

Date Time Field Sample Identification

5/10/22 9:58 AM TB-1
5/10/22 10:00 AM Hartz Culvert

Grab or Composite	# of Containers & Type ^C	Preservation Code ^P	Matrix Code ^M	F. coli ¹	Enterococci ²	Surfactants ³
G	15 T	SW	SW	✓	✓	✓
G	25 VP T/MSW					

(Handwritten initials)

Client Information

Company Name: Woodard and Curran, Inc
 Address: 33 Broad Street / One Weybosset
 Providence RI 02903
 Main Telephone: 401-743-2661
 Contact Person: Janelle Bonn

Project Information

Project Name: Gloucester INDE
 Project Number: 22.016
 Report To: Janelle Bonn/Berger
 Email addresses: jbonn@woodardcurran.com
 Phone: 978-975-0800
 Quote No: 9berger@side-inc.com

Relinquished By Signatures	Date	Time	Received By Signature	Date	Time
<i>(Signature)</i>	5/10/22	2:56 PM	<i>(Signature)</i>	5/10/22	14:55
<i>(Signature)</i>	5/10/22	12:55	<i>(Signature)</i>	5/10/22	14:55
<i>(Signature)</i>	5/10/22	4:615	<i>(Signature)</i>	5/10/22	16:00

Reporting Options

MCP Standard

MWRA eSMART

State Report & Upload

Lab Use Only

Sample Pick Up Only

RIAL sampled; attach field hours

Received on Ice No Ice

Workorder No: 2205-07633

Turn Aaround Time: Normal EMAIL Report
 5-7 Business days

Rush - Date Due: / /

Term: Uranium Receipt *3.19*

Containers: P=Poly, G=Glass, AG=Amber Glass, V=Vial, St=Sterile Preservatives: A=Ascorbic Acid, NH4=NH4Cl, DI=DI-H2O, H=HCl, M=MeOH, N=HNO3, NP=None, S=H2SO4, SH=NaOH, T=Na2S2O5, Z=ZnOAc
 Matrix Codes: GW=Groundwater, SW=Surface Water, WW=Wastewater, DW=Drinking Water, S=Soil, SL=Sludge, A=Air, B=Bulk/Solid, WP=Wipe, O=



EMSL ANALYTICAL, INC.
200 Route 130 North,
Cinnaminson, NJ 08077
DnaLab2@emsl.com | www.emsl.com

EMSL ORDER ID: 612201124
EMSL CUSTOMER ID: SDEC42

Attention: Garrett Bergey
SDE Civil & Environmental Engineering
354 Merrimack Street, Suite 200
Lawrence, MA 01843

Phone: (978) 975-0500
Email:

Customer PO: 22.016
LIMS Project ID:
Project ID: Gloucester IDDE

Date Received: 5/18/2022
Date Analyzed: 5/19/2022
Date Reported: 5/23/2022
Date Amended:

Test Report: Rapid Detection of Human Bacteroides by Quantitative PCR

EMSL Test: M199

Lab Sample Number	Client Sample ID	Description	Water Received (mL)	Water Sampled (mL)	CEs */100 mL
1124-1	DMH_13804	Storm Drain Manhole	1025	1025	None Detected

CEs: Cell Equivalent, measured by PCR using genomic DNA standards.

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of

Sergey Balashov, Ph.D.

LABORATORY REPORT

Woodard & Curran
Attn: Janelle Bonn
33 Broad Street
One Weybosset Hill, Floor 7
Providence, RI 02903

Date Received: 5/19/2022
Date Reported: 5/24/2022
P.O. Number

Work Order #: 2205-08258

Project Name: PROJECT# 22.016 GLOUCESTER IDDE

Enclosed are the analytical results and Chain of Custody for your project referenced above. The sample(s) were analyzed by our Warwick, RI laboratory unless noted otherwise. When applicable subcontracted results are noted and subcontracted reports are enclosed in their entirety.

All samples were analyzed within the established guidelines of US EPA approved methods with all requirements met, unless otherwise noted at the end of a given sample's analytical results or in a case narrative.

The Detection Limit is defined as the lowest level that can be reliably achieved during routine laboratory conditions.

These results only pertain to the samples submitted for this Work Order # and this report shall not be reproduced except in its entirety.

We certify that the following results are true and accurate to the best of our knowledge. If you have questions or need further assistance, please contact our Customer Service Department.

Approved by:



Nicole Skyleson
Data Reporting Manager

Laboratory Certification Numbers (as applicable to sample's origin state):

Warwick RI * RI LAI00033, MA M-RI015, CT PH-0508

R.I. Analytical Laboratories, Inc.

Laboratory Report

Woodard & Curran

Work Order #: 2205-08258

Project Name: PROJECT# 22.016 GLOUCESTER IDDE

Sample Number: 001
Sample Description: TB-1
Sample Type : GRAB
Sample Date / Time : 5/19/2022 @ 09:08

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
E. Coli 18 Hour	<1.0	1.0	MPN/100 ml	SM9223B	5/19/2022 18:51	MS

The E.Coli coliform sample was received and analyzed outside the recommended hold time.

Sample Number: 002
Sample Description: 13
Sample Type : GRAB
Sample Date / Time : 5/19/2022 @ 09:28

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
LAS Surfactants (MBAS)	1.2	0.12	mg/l	SM5540C 18-21ed	5/19/2022 15:17	JEP
Enterococci	556	10	MPN/100 ml	IDEXX Enterolert	5/19/2022 17:49	HMA

The Enterococci coliform sample was received close to hold time expiration and was analyzed outside the recommended hold time.

Sample Number: 003
Sample Description: 39
Sample Type : GRAB
Sample Date / Time : 5/19/2022 @ 09:10

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
LAS Surfactants (MBAS)	1.8	0.12	mg/l	SM5540C 18-21ed	5/19/2022 15:17	JEP
Enterococci	301	10	MPN/100 ml	IDEXX Enterolert	5/19/2022 17:49	HMA

The Enterococci coliform sample was received and analyzed outside the recommended hold time.

R.I. Analytical Laboratories, Inc.

Laboratory Report

Woodard & Curran

Work Order #: 2205-08258

Project Name: PROJECT# 22.016 GLOUCESTER IDDE

Sample Number: 004
Sample Description: 16
Sample Type : GRAB
Sample Date / Time : 5/19/2022 @ 10:00

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
LAS Surfactants (MBAS)	1.1	0.12	mg/l	SM5540C 18-21ed	5/19/2022 15:17	JEP
Enterococci	884	10	MPN/100 ml	IDEXX Enterolert	5/19/2022 17:49	HMA



R.I. ANALYTICAL
Specialists in Environmental Services

CHAIN OF CUSTODY RECORD

41 Illinois Avenue
Warwick, RI 02888-3007
800-937-2580 • Fax: 401-738-1970

131 Coolidge St., Suite 105
Hudson, MA 01749-1331
800-937-2580 • Fax: 978-568-0078

Date	Time Collected	Field Sample Identification
5/19	9:08	TB-1
5/19	9:28 am	13
5/19	9:10 am	39
5/19	10:00 am	16

Grab or Composite	# of Containers & Type	Preservation Code	Matrix Code	Surfactants	Entero	E. coli
G	2/P NP	SW	SW	✓	✓	✓
G	2/P NP	SW	SW	✓	✓	
G	2/P NP	SW	SW	✓	✓	
G	2/P NP	SW	SW	✓	✓	

(17)

Client Information		Project Information	
Company Name:	Woodard & Curran, Inc.	Project Name:	Gloucester IDDE
Address:	33 Broad Street/One Weybosset Hill	P.O. Number:	22.016
City / State / Zip:	Providence, RI 02903	Report To:	Janelle Boon
Telephone:	401-793-2661	Sampled by:	Janelle Boon
Contact Person:	Janelle Bonn	Quote No.:	
		Project Number:	22.016
		Phone:	
		Fax:	
		Email report to these addresses:	jboonn@woodardcurran.com gbergey@sde-inc.com

Relinquished By Signatures	Date	Time	Received By Signature	Date	Time
	5/19/22	3:18		5/19/22	15:18
	5/19/22	15:50		5/19/22	15:50
	5/19/22	17:15		5/19/22	17:15

Project Comments	
Circle if applicable:	GW-1, GW-2, GW-3, S-1, S-2, S-3 MCP Data Enhancement QC Package? Yes No
	38
	Temp. Upon Receipt 10.2°C

Containers: P=Poly, G=Glass, AG=Amber Glass, V=Vial, S=Sterile Preservatives: A=Ascorbic Acid, NH4=NH4Cl, H=HCl, M=MeOH, N=HNO3, NP=None, S=H2SO4, SB=NaHSO4, SH=NaOH, T=Na2S2O8, Z=ZnOAc

Workorder No: 20250258

Turn Around Time	
Normal	EMAIL Report
X	5-7 Business days
Rush - Date Due: / /	

Lab Use Only	
Sample Pick Up Only	
RIAL sampled; attach field hours	
Shipped on ice	

LABORATORY REPORT

Woodard & Curran
Attn: Janelle Bonn
33 Broad Street
One Weybosset Hill, Floor 7
Providence, RI 02903

Date Received: 5/9/2022
Date Reported: 5/12/2022
P.O. Number

Work Order #: 2205-07553

Project Name: PROJECT# 22.016 GLOUCESTER IDDE

Enclosed are the analytical results and Chain of Custody for your project referenced above. The sample(s) were analyzed by our Warwick, RI laboratory unless noted otherwise. When applicable subcontracted results are noted and subcontracted reports are enclosed in their entirety.

All samples were analyzed within the established guidelines of US EPA approved methods with all requirements met, unless otherwise noted at the end of a given sample's analytical results or in a case narrative.

The Detection Limit is defined as the lowest level that can be reliably achieved during routine laboratory conditions.

These results only pertain to the samples submitted for this Work Order # and this report shall not be reproduced except in its entirety.

We certify that the following results are true and accurate to the best of our knowledge. If you have questions or need further assistance, please contact our Customer Service Department.

Approved by:



Nicole Skyleson
Data Reporting Manager

Laboratory Certification Numbers (as applicable to sample's origin state):

Warwick RI * RI LAI00033, MA M-RI015, CT PH-0508

R.I. Analytical Laboratories, Inc.

Laboratory Report

Woodard & Curran

Work Order #: 2205-07553

Project Name: PROJECT# 22.016 GLOUCESTER IDDE

Sample Number: 001
Sample Description: TB-1
Sample Type : GRAB
Sample Date / Time : 5/09/2022 @ 11:15

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
E. Coli 18 Hour	<1.0	1.0	MPN/100 ml	SM9223B	5/9/2022 16:40	MS

Sample Number: 002
Sample Description: CREEK
Sample Type : GRAB
Sample Date / Time : 5/09/2022 @ 11:20

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
Enterococci	2.0	1.0	MPN/100 ml	IDEXX Enterolert	5/9/2022 16:19	MS
LAS Surfactants (MBAS)	<0.12	0.12	mg/l	SM5540C 18-21ed	5/10/2022 17:58	JEP



R.I. ANALYTICAL
Specialists in Environmental Services

CHAIN OF CUSTODY RECORD

41 Illinois Avenue
Warwick, RI 02888-3007
Tel: 800-937-2580

131 Coolidge St., Suite 105
Hudson, MA 01749-1331
Tel: 800-937-2580

Date Collected	Time Collected	Field Sample Identification	Grab or Composite	# of Containers & Type	Preservation Code	Matrix Code	Coli	Enter	Surfactants
5/9/22	11:15	TB-1	G	1st T	SW	X			
5/12/22	11:20	Creek	G	2 # 1/2 M SW	SW	X			

Client Information

Company Name: Woodard & Curran

Address: 33 Broad St / One Wombosset Hill FL7

City / State / Zip: Providence RI 02903

Main Telephone: _____

Contact Person: Janelle Bonn

Project Information

Project Name: Gloucester DDE

P.O. Number: _____

Report To: Janelle Bonn / jbonn@woodardcurran.com

Sampled by: NK/SR

Quote No: _____

Project Number: 22-016

Phone: 978 975 0500

Email addresses: jbonn@woodardcurran.com

Relinquished By Signatures	Date	Time	Received By Signatures	Date	Time
	5/9/22	2:47		6/9/22	14:00
	8/9/22	1:00		5/9/22	16:00

Reporting Options

MCP Standard

MWRA eSMART

State Report & Upload

Project Comments: Expect bacteria results between 0-80,000

Temp. Upon Receipt: 3.9 °C

Turn Around Time

Normal: _____

5-7 Business days

Rush - Date Due: _____

EMAIL Report

Lab Use Only

Sample Pick Up Only

RIAL sampled; attach field hours

Received on ice: _____

No Ice: _____

Workorder: NB205-0155

Containers: P=Poly, G=Glass, AG=Amber Glass, V=Vial, SL=Sterile Preservatives: A=Ascorbic Acid, NH4=NH4Cl, DI=DI-H2O, H=HCl, M=MeOH, N=HNO3, NP=None, S=H2SO4, SH=NaOH, T=Na2S2O8, Z=ZnOAC

Matrix Codes: GW=Groundwater, SW=Surface Water, WW=Wastewater, DW=Drinking Water, S=Soil, SL=Sludge, A=Air, B=Bulk/Solid, WP=Wipe, O=

Page _____ of _____

LABORATORY REPORT

Woodard & Curran
Attn: Mr. Garrett Rose
33 Broad Street
One Weybosset Hill, Floor 7
Providence, RI 02903

Date Received: 5/12/2022
Date Reported: 5/16/2022
P.O. Number

Work Order #: 2205-07816

Project Name: PROJECT#22.016 GLOUCESTER IDDE

Enclosed are the analytical results and Chain of Custody for your project referenced above. The sample(s) were analyzed by our Warwick, RI laboratory unless noted otherwise. When applicable subcontracted results are noted and subcontracted reports are enclosed in their entirety.

All samples were analyzed within the established guidelines of US EPA approved methods with all requirements met, unless otherwise noted at the end of a given sample's analytical results or in a case narrative.

The Detection Limit is defined as the lowest level that can be reliably achieved during routine laboratory conditions.

These results only pertain to the samples submitted for this Work Order # and this report shall not be reproduced except in its entirety.

We certify that the following results are true and accurate to the best of our knowledge. If you have questions or need further assistance, please contact our Customer Service Department.

Approved by:



Nicole Skyleson
Data Reporting Manager

Laboratory Certification Numbers (as applicable to sample's origin state):

Warwick RI * RI LAI00033, MA M-RI015, CT PH-0508

R.I. Analytical Laboratories, Inc.

Laboratory Report

Woodard & Curran

Work Order #: 2205-07816

Project Name: PROJECT#22.016 GLOUCESTER IDDE

Sample Number: 001
Sample Description: TB-1
Sample Type : GRAB
Sample Date / Time : 5/12/2022 @ 10:45

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
E. Coli 18 Hour	<1.0	1.0	MPN/100 ml	SM9223B	5/12/2022 18:37	MS

Sample Number: 002
Sample Description: DMH_396
Sample Type : GRAB
Sample Date / Time : 5/12/2022 @ 10:50

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
Enterococci	1.0	1.0	MPN/100 ml	IDEXX Enterolert	5/12/2022 18:35	MS



CHAIN OF CUSTODY RECORD
 Specialists in Environmental Services
 41 Illinois Avenue
 Warwick, RI 02888-3007
 800-937-2580 • Fax: 401-738-1970
 131 Coolidge St., Suite 105
 Hudson, MA 01749-1331
 800-937-2580 • Fax: 978-568-0078

Date Collected	Time Collected	Field Sample Identification
5/12/22	10:45	TB-1
5/12	10:50	DMH-396

Grab or Composite	# of Containers & Type	Preservation Code ^P	Matrix Code ^M	Notes
G	1st T	T	SW	Enter
G	1st T	T	SW	X

Client Information
 Company Name: **Woodard & Curran, Inc.**
 Address: **33 Broad Street/One Weybosset Hill**
 City / State / Zip: **Providence, RI 02903**
 Telephone: **401-793-2661** Fax:
 Contact Person: **Janelle Bonn**

Project Information
 Project Name: **Gloucester IDDE**
 P.O. Number: **22.016**
 Project Number:
 Report To: **Janelle Bonn** Phone:
 Sampled by: **SRINK** Email report to these addresses: **jbonn@woodardcurran.com**
 Quote No: **gbergey@scde-inc.com** Fax

Relinquished By Signatures	Date	Time	Received By Signatures	Date	Time
	5/12	2:58		5/12/22	14:58
	5/12/22			5/12/22	16:55
	5/12/22	17:30		5-12-22	17:30

Project Comments
 Circle if applicable: GW-1, GW-2, GW-3, S-1, S-2, S-3 MCP Data Enhancement QC Package? Yes No
 Temp. Upon Receipt: **4.6**
 7.5°C

Turn Around Time
 Normal EMAIL Report
 5-7 Business days X
 Rush - Date Due: / /

Lab Use Only
 Sample Pick Up Only
 RIAL sampled; attach field hours
 Shipped on ice X
 Workorder No: **2205-02814**

Containers: P=Poly, G=Glass, AG=Amber Glass, V=Vial, SF=Sterile Preservatives; A=Ascorbic Acid, NH4=NH4Cl, H=HCl, M=MeOH, N=HNO3, NP=None, S=H2SO4, SB=NaHSO4, SH=NaOH, T=Na2S2O3, Z=ZnOAc

LABORATORY REPORT

Woodard & Curran
Attn: Janelle Bonn
33 Broad Street
One Weybosset Hill, Floor 7
Providence, RI 02903

Date Received: 5/17/2022
Date Reported: 5/19/2022
P.O. Number

Work Order #: 2205-08052

Project Name: PROJECT# 22.016 GLOUCESTER IDDE

Enclosed are the analytical results and Chain of Custody for your project referenced above. The sample(s) were analyzed by our Warwick, RI laboratory unless noted otherwise. When applicable subcontracted results are noted and subcontracted reports are enclosed in their entirety.

All samples were analyzed within the established guidelines of US EPA approved methods with all requirements met, unless otherwise noted at the end of a given sample's analytical results or in a case narrative.

The Detection Limit is defined as the lowest level that can be reliably achieved during routine laboratory conditions.

These results only pertain to the samples submitted for this Work Order # and this report shall not be reproduced except in its entirety.

We certify that the following results are true and accurate to the best of our knowledge. If you have questions or need further assistance, please contact our Customer Service Department.

Approved by:



Nicole Skyleson
Data Reporting Manager

Laboratory Certification Numbers (as applicable to sample's origin state):

Warwick RI * RI LAI00033, MA M-RI015, CT PH-0508

R.I. Analytical Laboratories, Inc.

Laboratory Report

Woodard & Curran

Work Order #: 2205-08052

Project Name: PROJECT# 22:016 GLOUCESTER IDDE

Sample Number: 001
Sample Description: TB-1
Sample Type : GRAB
Sample Date / Time : 5/17/2022 @ 09:05

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
E. Coli 18 Hour	<1.0	1.0	MPN/100 ml	SM9223B	5/17/2022 17:37	HMA

Sample Number: 002
Sample Description: DMH_13804
Sample Type : GRAB
Sample Date / Time : 5/17/2022 @ 09:15

PARAMETER	SAMPLE RESULTS	DET. LIMIT	UNITS	METHOD	DATE/TIME ANALYZED	ANALYST
Enterococci	75	10	MPN/100 ml	IDEXX Enterolert	5/17/2022 17:39	HMA
LAS Surfactants (MBAS)	0.55	0.12	mg/l	SM5540C 18-21ed	5/17/2022 19:40	JEP

The E.Coli/Enterococci coliform samples were received close to hold time expiration and were analyzed outside the recommended hold time.



CHAIN OF CUSTODY RECORD
 41 Illinois Avenue
 Warwick, RI 02888-3007
 800-937-2580 • Fax: 401-738-1970 800-937-2580 • Fax: 978-568-0078

Date Collected	Time Collected	Field Sample Identification
5/17	9:05	TB-1
5/17	9:15	DMF-13804

Grab or Composite	# of Containers & Type	Preservation Code ^P	Matrix Code ^M	F. coli	Enter	Surfactants
G 1/P NP		NP	SW	X		
G 2/P NP		NP	SW	X		

Client Information
 Company Name: Woodard & Curran, Inc.
 Address: 33 Broad Street/One Weybosset Hill
 Providence, RI 02903
 Telephone: 401-793-2661
 Contact Person: Janelle Bonn

Project Information
 Project Name: Gloucester IDDE
 P.O. Number: 22.016
 Report To: Janelle Bonn
 Sampled by: SR
 Quote No:

Relinquished By Signatures	Date	Time	Received By Signatures	Date	Time
	5/17	2:30		5/17/22	14:30
	5/17/22	15:20		5/17/22	15:20
	5/17/22	16:40		5-7-22	16:40

Turn Around Time
Normal
5-7 Business days
Rush - Date Due: 1/1

Project Comments
 Circle if applicable: GW-1, GW-2, GW-3, S-1, S-2, S-3
 MCP Data Enhancement QC Package? Yes No
 Expect bacteria results between 0-80000
 Temp. Upon Receipt 2.16°C

Lab Use Only
 Sample Pick Up Only
 RIAL sampled; attach field hours
 Shipped on ice
 Workorder No: 220508052