



Triangle Pond Management
 405 S Rogers Ln
 Raleigh, NC 27610
 (919)398-3221
 Office@TrianglePondManagement.com
 www.TrianglePondManagement.com
Maintenance Service Report

| | | | |
|--------------------------------------|---------------------------|--------------------|--|
| Customer Name: | | Date: | |
| Chandler Woods MOA | | 6/20/2024 | |
| Address: | | | |
| 214 Abbot Pl | | | |
| Aquatic Technician: | | | |
| Justin Tripp | | | |
| Time of Arrival: | Time of Departure: | Drive Time: | |
| 6:00 AM | 8:08 AM | 15 min | |
| Type of Device(s) Maintained: | | | |
| BMP 1, BMP 2, BMP 3 | | | |

| | | | |
|---|--|--|--|
| Unwanted Vegetation: | | | |
| <input type="checkbox"/> Filamentous Algae | <input type="checkbox"/> Planktonic Algae | <input type="checkbox"/> Emergent Aquatics | <input type="checkbox"/> Submersed Aquatics |
| <input type="checkbox"/> Free Floating Aquatics | <input checked="" type="checkbox"/> Broadleaf/Invasive Grasses | <input checked="" type="checkbox"/> Other (see additional notes) | |
| Method of Treatment Used: | | | |
| <input type="checkbox"/> Algaecide | <input type="checkbox"/> Herbicide | <input type="checkbox"/> Dye (Black/Blue) | <input checked="" type="checkbox"/> Other (see additional notes) |

| General Inspection: | Comment: |
|---|--------------------------------|
| Was any trash found in or around the devices? | Yes Removed all trash |
| Were the Inlets & Outlets clear of all debris and functioning properly? | Yes |
| Was the Rip Rap clear of any unwanted vegetation? | No Controlled |
| Was the required beneficial vegetation healthy and flourishing? | Yes |
| Was any Beaver/Muskrat activity observed? | No |
| Was the water at the proper elevation? | No Low at BMP 1 and BMP 2 |
| Were the devices draining properly? | No See additional notes |
| Was the Riser/Trash Rack clear of trash and debris? | Yes |
| Was any erosion observed during the visit? | No |

| Optional Services: | | Comment: |
|---|-----|----------|
| Were Mowing services completed? | No | |
| Was the Rip Rap in the correct position? | Yes | |
| Were overseeding services performed this visit? | No | |
| Was the Drain Valve exercised? | No | |
| Was the Fountain/Aerator functioning properly? | N/A | |

Wildlife Observations





| Healthy for Aquatic Environment: | | Unhealthy for Aquatic Environment (Removal/Remediation Recommended): |
|-------------------------------------|---|---|
| <input type="checkbox"/> Bass | <input type="checkbox"/> Bluegill/Sunfish | <input type="checkbox"/> Geese |
| <input type="checkbox"/> Grass Carp | <input type="checkbox"/> Minnows/Gambusia | <input type="checkbox"/> Excessive Turtles |
| <input type="checkbox"/> Cray Fish | <input type="checkbox"/> Turtles | <input type="checkbox"/> Snakes |



| Repairs? | Comment: |
|---------------------------|----------------------|
| Are repairs required? Yes | See additional notes |

| Overall Condition of Devices: |
|---|
| <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor |

| Additional Notes: |
|--|
| <p>The devices were walked and all trash was removed.</p> <p>Unwanted/Invasive vegetation throughout the devices were controlled.</p> <p>Invasive hardwood saplings were cut and removed.</p> <p>The water level at BMP 1 and BMP 2 was significantly low. This could possibly be due to leaks within the risers.</p> <p>Please contact our office with any questions, concerns, or to schedule repairs.</p> |

| Technician's Signature: |
|---|
|  |

| Photo 1: | Photo 2: |
|---|--|
|  |  |
| BMP 1 | BMP 1 |
| Photo 3: | Photo 4: |
|  |  |
| BMP 1 riser | BMP 1 inside riser |

| Photo 5: | Photo 6: |
|---|--|
|  |  |
| BMP 1 inlet | BMP 1 outlet |
| Photo 7: | Photo 8: |
|  |  |
| BMP 2 | BMP 2 |

| Photo 9: | Photo 10: |
|---|--|
|  |  |
| BMP 2 riser | BMP 2 inside riser |
| Photo 11: | Photo 12: |
|  |  |
| BMP 2 inlet | BMP 2 backside of dam |

| Photo 13: | Photo 14: |
|--|---|
|  <p>A photograph showing a concrete pipe outlet for a Best Management Practice (BMP) 2. The pipe is surrounded by a bed of dark grey gravel, which is partially covered by a layer of brown mulch. The area is bordered by green grass and a dense line of trees in the background.</p> |  <p>A wide-angle photograph of a large, rectangular gravel area, identified as BMP 3. The area is filled with dark grey gravel and is bordered by green grass. Several white plastic markers are visible in the gravel. In the background, there is a wooden fence and a line of trees.</p> |
| BMP 2 outlet | BMP 3 |
| Photo 15: | Photo 16: |
|  <p>A photograph of a concrete riser for BMP 3. The riser is a rectangular structure with a metal grate on top, set into a bed of dark grey gravel. There are some small green plants and white flowers nearby.</p> |  <p>An interior view of the BMP 3 riser. The structure is made of concrete and has two circular openings. The openings are covered with metal grates. The floor of the riser is a smooth, light-colored concrete surface.</p> |
| BMP 3 riser | BMP 3 inside riser |

| Photo 17: | Photo 18: |
|---|--|
|  |  |
| BMP 3 inlet | BMP 3 outlet |
| Photo 19: | Photo 20: |
| | |
| | |