



Property Inspection Report

9204 Golfview Circle, Covington GA 30014

Inspection Date:

01/15/2019

Prepared For:

Debra Lewis

Prepared By:

**Property Inspectors of Atlanta
4269 Westside Drive,
Acworth GA, 30101**

Office: 404-590-0012

Inspector: 678-914-9333

Morgan.Bailey@PropertyInspectorsofAtlanta.com

Report Number:

11519

Inspector:

Morgan Z. Bailey

TABLE OF CONTENTS

REPORT OVERVIEW

RECEIPT/INVOICE

GROUNDS

ROOF

EXTERIOR

ELECTRICAL/AC-HEAT PUMP

GARAGE

KITCHEN/LAUNDRY ROOM

BATHROOMS

ROOMS

INTERIOR

BASEMENT

CRAWL SPACE

PLUMBING

HEATING SYSTEM

ELECTRIC/COOLING SYSTEM

SUMMARY

REPORT OVERVIEW

THE HOUSE IN PERSPECTIVE

CONVENTIONS USED IN THIS REPORT

SATISFACTORY - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL - Indicates the component will probably require repair or replacement anytime within five years.

POOR - Indicates the component will need repair or replacement now or in the very near future.

MAJOR CONCERNS - A system or component that is considered significantly deficient or is unsafe.

SAFETY HAZARD - Denotes a condition that is unsafe and in need of prompt attention.

THE SCOPE OF THE INSPECTION

All components designated for inspection in the ASHI® Standards of Practice are inspected, except as may be noted in the "Limitations of Inspection" sections within this report.

It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind.

Please refer to the pre-inspection contract for a full explanation of the scope of the inspection.

BUILDING DATA

Year Built:	2019
Style:	Single Family
Overall Area Condition	Satisfactory
State of Occupancy:	Vacant
Weather Conditions:	Sunny
Recent Rain:	Yes
Ground cover:	Wet



SERVICE WALKS None *Public sidewalk needs repair*
Material: Concrete Flagstone Gravel Brick Other
Condition: Satisfactory Marginal Poor *Trip Hazard*
 Pitched towards home *Settling cracks* Not visible Typical cracks

DRIVEWAY/PARKING None
Material: Concrete Asphalt Gravel/Dirt Brick Other
Condition: Satisfactory Marginal Poor Fill cracks and seal
 Pitched towards home *Trip hazard* *Settling Cracks* Typical cracks

PORCH (covered entrance) None
Material: Concrete Wood Not visible Other
Condition: Satisfactory Marginal Poor *Railing/Balusters recommended*
Floor: Satisfactory Marginal Poor *Safety Hazard*

STOOPS/STEPS None *Uneven risers*
Material: Concrete Wood Other *Railing/Balusters recommended*
Condition: Satisfactory Marginal Poor *Cracked* *Settled*
 Rotted/Damaged *Safety Hazard*

PATIO None
Material: Concrete Flagstone Kool-Deck® Brick *Trip hazard*
Condition: Satisfactory Marginal Poor *Settling Cracks*
 Pitched towards home (See remarks page) Drainage provided Typical cracks

DECK/BALCONY (flat, floored, roofless area) None
Material: Wood Metal Composite Not visible *Railing/Balusters recommended*
Finish: Treated Painted/Stained Other
 Improper attachment to house *Railing loose*
Condition: Satisfactory Marginal Poor *Wood in contact with soil*

FENCE/WALL Not evaluated None
Type: Brick/Block Wood Metal Chain Link *Rusted* Other
Condition: Satisfactory Marginal Incomplete *Loose Blocks/Caps* Typical cracks
Gate: N/A Satisfactory Marginal Poor *Planks missing/damaged*

LANDSCAPING (See remarks page)
Negative Grade: East West North South Satisfactory *Recommend additional backfill*
 Sewer cleanout not incased in cast iron ring with cover Yard drain(s) recommended
 Trim back trees/shrubberies *Wood in contact with/improper clearance to soil*
 Large trees may be effecting underground plumbing

HOSE BIBS None
Operates: Yes No Not tested Improper Attachment

GENERAL COMMENTS

Sewer clean out access in the front yard is not encased in an iron cover
Recommend trimming tree branches present in close proximity to the left side of the home/roof
Portion of wood beam is exposed above the front porch
Wood fence in the backyard is incomplete
Sitting water present in the right side of the backyard; recommend waterflow expert evaluate



ROOF VISIBILITY All Partial None Limited by:

INSPECTED FROM Roof Ladder at eaves Ground (*Inspection Limited*) With Binoculars

STYLE OF ROOF

Type: Gable Hip Mansard Shed Flat Other

Pitch: Low Medium Steep Flat

ROOF COVERING

Roof #1: Type: **Gable** Estimated Layers: **1 Layer** Approximate age of cover: **< 1** year

Roof #2: Type: Estimated Layers: Approximate age of cover: years

Roof #3: Type: Estimated Layers: Approximate age of cover: years

VENTILATION SYSTEM **Type:** Soffit Ridge Gable Roof

Appears Adequate: Yes No Turbine Powered Other

(See Interior remarks page) (See Attic section)

FLASHING

Material: Galv/Alum Asphalt Not visible Rubber

Copper Foam Other Lead

Condition: Not visible Satisfactory Marginal Poor *Rusted*

Separated from chimney/roof Recommend Sealing Other

VALLEYS

N/A **Material:** Galv/Alum Asphalt Lead Copper

Not visible Other

Condition: Not visible Satisfactory Marginal Poor

Rusted Holes Recommend Sealing

CONDITION OF ROOF COVERINGS

Roof #1: Satisfactory Marginal Poor

Roof #2: Satisfactory Marginal Poor

Roof #3: Satisfactory Marginal Poor

Condition: Curling Cracking Raised shingle(s) Burn Spots Damaged Tiles/Shingles

Nail popping Granules missing Alligatoring Blistering Missing Tabs/Shingles/Tiles

Moss buildup Exposed nails Cupping Trim back tree branches in close proximity

SKYLIGHTS

N/A Cracked/Broken Not visible

Condition: Satisfactory Marginal Poor

PLUMBING VENTS

Yes No Satisfactory Marginal Poor

Recommend roofer evaluate Not Visible Recommend sealing

Conditions reported above reflect visible portion only

GENERAL COMMENTS

Raised shingle present on the roof by the chimney chase; recommend roofer evaluate/repair
Dryer exhaust vent louver does not fully cover the vent opening on the roof; may allow pest/water entry
Recommend sealing exposed nails present on the roof shingles and roof vents/boots
Slight damage/exposed felt present on a few shingles on the roof; recommend roofer evaluate and repair



CHIMNEY(S) None Location(s): Left side of the home/roof

Viewed From: Roof Ladder at eaves Ground with binoculars

Rain Cap/Spark Arrestor: Yes No **Recommended**

Chase: Brick Stone Metal Blocks Framed

Evidence of: Holes in metal Cracked chimney cap Loose mortar joints Flaking Loose Brick Rust

Flue: Tile Metal **Unlined** Not visible

Evidence of: Scaling Cracks Creosote **Not evaluated (See remarks page)**

Have flue(s) cleaned and re-evaluated **Recommend Cricket/Saddle/Flashing**

Condition: Satisfactory Marginal Poor

GUTTERS/SCUPPERS/EAVESTROUGH None **Needs to be cleaned** **Downspouts needed**

Material: Copper Vinyl/Plastic Galvanized/Aluminum End missing

Condition: Satisfactory Marginal Poor **Rusting**

Leaking: Corners Joints **Hole in main run**

Attachment: Loose **Missing spikes** **Improperly sloped (See remarks page)**

SIDING (*See remarks page EIFS)

Material: Stone Slate Block/Brick Fiberboard Fiber-cement Stucco

EIFS* Asphalt Wood Metal/Vinyl Asbestos

Typical cracks **Monitor** **Wood rot** Peeling paint **Loose/Missing/Holes**

Condition: Satisfactory Marginal Poor **Recommend repair/painting**

TRIM, SOFFIT, FASCIA

Material: Wood Fiberboard Metal/Vinyl Fiber Cement Stucco

Recommend repair/painting **Damaged wood** Other

Condition: Satisfactory Marginal Poor

CAULKING

Condition: Satisfactory Marginal Poor

Recommend around windows/doors/masonry ledges/corners/utility penetrations

WINDOWS & SCREENS **Failed/fogged insulated glass**

Material: Wood Metal Vinyl Aluminum/Vinyl Clad

Screens: Torn Bent Not installed Glazing/caulk needed

Condition: Satisfactory Marginal Poor **Wood rot** **Recommend repair/painting**

STORMS WINDOWS None Not installed Wood Clad comb. Wood/metal comb.

Putty: Satisfactory **Glazing/caulk needed** N/A

Condition: Satisfactory **Broken/cracked** **Wood rot** **Recommend repair/painting**

SLAB-ON-GRADE/FOUNDATION N/A (See Basement/Crawl Space)

Stem Wall: Concrete block Poured concrete Other

Condition: Satisfactory Marginal Poor Not visible

Slab: Post tensioned Poured concrete Other

Condition: Satisfactory Marginal Poor (See comments page)

GENERAL COMMENTS

No window screens are present on the home
Recommend installing splash blocks at all gutter downspouts leading into soil
Recommend sealing around the condensation line on the soffit on the back of the home

**SERVICE ENTRY**

- Underground Overhead *Weather head/mast needs repair*
Exterior outlets: Yes No **Operative:** Yes No Condition: Sat. Marginal Poor
GFCI present: Yes No **Operative:** Yes No *Overhead wires too low*
 Reverse polarity *Open ground* *Safety Hazard* *Less than 3' from balcony/deck/windows*
 Exterior light fixture damaged or missing *Missing / Damaged housing*

BUILDING(S) EXTERIOR WALL CONSTRUCTION

- Type:** Not visible Framed Masonry Other
Condition: Satisfactory Marginal Poor Not visible

EXTERIOR DOORS

- | | | | | |
|--|--|--|--|----------------------------------|
| Weather stripping: <input checked="" type="checkbox"/> Satisfactory | Patio <input type="checkbox"/> Marginal | Storm <input type="checkbox"/> Poor | Entrance <input type="checkbox"/> Missing | <input type="checkbox"/> Replace |
| Door Condition: <input checked="" type="checkbox"/> Satisfactory | <input type="checkbox"/> Marginal | <input type="checkbox"/> Poor | | |

EXTERIOR A/C - HEAT PUMP

- UNIT #1:** N/A **Location:** **Right side of the home**
Brand: **International Comfort** Approximate age: **2014**
Outside Disconnect: Yes No
Level: Yes No *Cabinet/housing rusted* *Improperly sized fuses/breakers*
Condenser Fins: *Damaged* Need cleaning *Damaged base/pad*
Condition: Satisfactory Marginal Poor

- UNIT #2:** N/A **Location:**
Brand: Approximate age:
Outside Disconnect: Yes No
Level: Yes No *Cabinet/housing rusted* *Improperly sized fuses/breakers*
Condenser Fins: *Damaged* Need cleaning *Damaged base/pad*
Condition: Satisfactory Marginal Poor

GENERAL COMMENTS

Unable to test HVAC cooling system due to exterior temperature
AC unit is not level; recommend leveling to extend life expectancy
AC unit was manufactured in 2014 and Furnace was manufactured in 2016
Front exterior door is not square; recommend adjustment/repair



TYPE None
 Attached Detached 1-car 2-car 3-car 4-car

AUTOMATIC OPENER
 Yes No Operable Inoperable

SAFETY REVERSE
Operable: Pressure reverse Electric eye *Need(s) adjusting* *Safety hazard*

ROOFING
Material: Same as house Type: Approx. Age: Approx. layers:

SIDING / TRIM
Siding: Same as house Wood Metal Vinyl
 Stucco Masonry Slate Fiberboard
Trim: Same as house Wood Aluminum Vinyl

FLOOR
Material: Concrete Gravel Asphalt Dirt Other
Condition: Satisfactory Typical cracks *Large settling cracks* *Recommend evaluation/repair*

SILL PLATES
 Not visible Floor level Elevated *Rotted/Damaged* *Recommend repair*

OVERHEAD DOOR(S) N/A
Material: Wood Fiberglass Masonite Metal *Recommend repair*
Condition: Satisfactory Marginal Poor *Overhead door hardware loose*

EXTERIOR SERVICE DOOR None
Condition: Satisfactory Marginal Poor *Damaged/Rusted*

ELECTRICITY PRESENT Yes No Not visible
Reverse polarity: Yes No **Open ground:** Yes No *Safety hazard*
GFCI Present: Yes No **Operates:** Yes No *Handyman/extension cord wiring*

FIRE SEPARATION WALLS & CEILING (*Between garage & living area*)
 N/A Present *Missing*
Condition: Satisfactory *Safety hazard(s)* *Recommend repair* *Holes walls/ceiling*
Fire door: Not verifiable *Not a fire door* *Needs repair* Satisfactory
 N/A Satisfactory Inoperative Missing *Needs repair*
Moisture Stains Present: Yes No **Typical Cracks:** Yes No

GENERAL COMMENTS

Garage interior door does not seal properly when closed
Typical crack present on the garage concrete floor; recommend monitoring
Recommend lowering the garage overhead door safety reverse sensors below 6" to account for small animals/children
Slight damage present at the base of the garage metal overhead door
Garage overhead door automatic opener was not operating at the time of inspection and light bulb is missing

**COUNTERTOPS**

Satisfactory Marginal *Recommend repair/caulking*

CABINETS

Satisfactory Marginal *Recommend repair/adjustment*

PLUMBING COMMENTS

Faucet Leaks: Yes No **Pipes leak/corroded:** Yes No
Sink/Faucet: Satisfactory Corroded Chipped Cracked *Recommend repair*
Functional Drainage: Adequate Poor **Functional Flow:** Adequate Poor

WALLS & CEILING

Condition: Satisfactory Marginal Poor Typical cracks *Moisture stains*

HEATING / COOLING SOURCE

Yes No

FLOOR

Condition: Satisfactory Marginal Poor Sloping Squeaks

APPLIANCES

(See remarks page)

<input type="checkbox"/> Disposal	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Trash compactor	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Oven	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Exhaust fan	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Range	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Refrigerator	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Dishwasher	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Microwave	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Other	Operates: <input type="checkbox"/> Yes <input type="checkbox"/> No		

Outlets Present: Yes No Operable: Yes No

G.F.C.I.: Yes No Operable: Yes No

Open ground/Reverse polarity within 6' of water: Yes No *Potential safety hazard(s)*

GENERAL COMMENTS

Kitchen appliances were not installed at the time of inspection; unable to test
Kitchen and bathroom cabinet door and drawer pulls are missing throughout the home
Recommend sealing around the kitchen refrigerator water supply port
Kitchen countertop backsplash is missing
Kitchen right wall outlets labeled "GFCI protected" do not trip when tested; recommend electrician repair
Poorly cut plumbing penetration holes present in the kitchen cabinet beneath the sink
Several kitchen cabinet shelves are not installed
Two kitchen drawers are not operating properly to the left of the stove
Kitchen lower rotating metal shelf is not operating properly; recommend adjustment/repair
Breaker #21 in the electrical panel labeled "kitchen GFI" trips when reset; recommend electrician repair

LAUNDRY ROOM**ROOM COMPONENTS**

Laundry sink: N/A **Faucet leaks:** Yes No **Pipes leak:** Yes No
Cross connections: Yes No **Heat source present:** Yes No **Room vented:** Yes No
Dryer vented: N/A Wall Ceiling Floor Not vented
 Not vented to Exterior *Safety hazard* **We do not test dryer outlets**
Electrical: Open ground/reverse polarity within 6' of water: Yes No *Safety hazard*
G.F.C.I. present: Yes No **Operates:** Yes No
Appliances: Washer Dryer Water heater Furnace
Washer hook-up lines/valves: Leaking Corroded Not visible
Gas Shut-off Valve: N/A Yes No Cap Needed *Safety hazard* Not visible

GENERAL COMMENTS

Laundry room washer supply valve housing frame is missing
Laundry room outlet is not GFCI protected

**BATH: HALF****SINKS / TUBS / SHOWERS**

Faucet leaks: Yes No **Loose:** Yes No **Pipes leak:** Yes No
Fixture(s) Condition: Satisfactory Marginal Poor Sink stopper not operating

TOILET

Bowl Loose: Yes No **Operates:** Yes No Toilet leaks Cracked bowl/tank Cross connection

SHOWER / TUB AREA / SINK(S)

Material: Ceramic/Plastic Fiberglass Masonite Other
Condition: Satisfactory Marginal Poor Rotted floors
Functional Drainage: Adequate Poor **Functional Flow:** Adequate Poor

WALLS / CEILING / CABINETS

Moisture stains present: Yes No **Outlets present:** Yes No
G.F.C.I. Present: Yes No **Operates:** Yes No
Open ground/Reverse polarity within 6' of water: Yes No **Potential safety hazards present:** Yes No

HEATING / COOLING SOURCE

Yes No
Window/Door: Yes No Satisfactory Marginal Poor
Exhaust Fan: Yes No **Operates:** Yes No **Noisy:** Yes No

GENERAL COMMENTS

Kitchen and bathroom cabinet door and drawer pulls are missing throughout the home

BATH: MASTER**SINKS / TUBS / SHOWERS**

Faucet leaks: Yes No **Loose:** Yes No **Pipes leak:** Yes No
Fixture(s) Condition: Satisfactory Marginal Poor Sink stopper not operating

TOILET

Bowl Loose: Yes No **Operates:** Yes No Toilet leaks Cracked bowl/tank Cross connection

SHOWER / TUB AREA / SINK(S)

Material: Ceramic/Plastic Fiberglass Masonite Other
Condition: Satisfactory Marginal Poor Rotted floors
Functional Drainage: Adequate Poor **Functional Flow:** Adequate Poor

WALLS / CEILING / CABINETS

Moisture stains present: Yes No **Outlets present:** Yes No
G.F.C.I. present: Yes No **Operates:** Yes No
Open ground/Reverse polarity within 6' of water: Yes No **Potential safety hazards present:** Yes No

HEAT / COOLING SOURCE

Yes No
Window/Door: Yes No Satisfactory Marginal Poor
Exhaust Fan: Yes No **Operates:** Yes No **Noisy:** Yes No

GENERAL COMMENTS

Kitchen and bathroom cabinet door and drawer pulls are missing throughout the home

Master bath right outlet is not GFCI protected

Leak uncovered beneath the master bath left sink; recommend plumber repair

Master bath right light fixture is not installed

Master bath tub does not drain properly due to debris present in the tub/drain

Unable to fully test the master bath tub Jacuzzi due to debris present in the tub

Master bath shower hot and cold water controls are reversed; recommend plumber repair

Master bath toilet room window is very difficult to operate; recommend adjustment/repair

**BATH: HALL****SINKS / TUBS / SHOWERS**

Faucet leaks: Yes No **Loose:** Yes No **Pipes leak:** Yes No
Fixture(s) Condition: Satisfactory Marginal Poor Sink stopper not operating

TOILET

Bowl Loose: Yes No **Operates:** Yes No Toilet leaks Cracked bowl/tank Cross connection

SHOWER / TUB AREA / SINK(S)

Material: Ceramic/Plastic Fiberglass Masonite Other
Condition: Satisfactory Marginal Poor Rotted floors
Functional Drainage: Adequate Poor **Functional Flow:** Adequate Poor

WALLS / CEILING / CABINETS

Moisture stains present: Yes No **Outlets present:** Yes No
G.F.C.I. present: Yes No **Operates:** Yes No
Open ground/Reverse polarity within 6' of water: Yes No **Potential safety hazards present:** Yes No

HEAT / COOLING SOURCE

Yes No
Window/Door: Yes No Satisfactory Marginal Poor
Exhaust Fan: Yes No **Operates:** Yes No **Noisy:** Yes No

GENERAL COMMENTS

Kitchen and bathroom cabinet door and drawer pulls are missing throughout the home
Recommend installing a proper threshold at the hall bath doorway
Hall bath outlet is not GFCI protected
Low water pressure observed at the hall bath tub and shower; recommend plumber repair

**INTERIOR WINDOWS / GLASS**

Condition: Satisfactory Marginal Poor Needs repair
Evidence of Leaking Insulated Glass: Yes No N/A **Safety Glazing Needed:** Yes No
 Glazing compound needed Cracked glass Hardware missing Broken counter-balance mechanism
Security Bars Present: Yes No Not tested Safety hazard Test release mechanism before moving in

FIREPLACE

None Location(s): **Family room**
Type: Gas (Not Tested) Wood Woodburner stove (See remarks page) Electric Ventless
Material: Masonry Metal (pre-fabricated) Metal insert
Miscellaneous: **Damper operates:** Yes No
 Open joints or cracks in firebrick/panels should be sealed Fireplace doors need repair
Hearth Adequate: Yes No **Mantle:** N/A Satisfactory Adequate Loose/missing
Physical Condition: Satisfactory Marginal Poor Recommend having flue cleaned and re-examined

STAIRS / STEPS / BALCONIES

Satisfactory Marginal Poor None
Handrail: Satisfactory Marginal Poor Safety hazard
Risers/Treads: Satisfactory Marginal Poor Risers/Treads uneven

SMOKE / CARBON MONOXIDE DETECTORS (See remarks page)

Present: Smoke Detector: Yes No **Operates:** Yes No Not tested

ATTIC/STRUCTURE/FRAMING/INSULATION

N/A
Access: Stairs Pulldown Scuttlehole/Hatch No access Other
Inspected From: Access panel In the attic Other
Flooring: Complete Partial None
Insulation: Batts Loose
 Damaged Displaced Missing Compressed Recommend Baffles @ Eaves
Installed In: Rafters Walls Between ceiling joists Not visible
 Recommend additional insulation
Ventilation: Ventilation appears adequate Recommend additional ventilation
Fans Exhausted To: N/A Attic: Yes No Outside: Yes No Not visible
HVAC Duct: Satisfactory Damaged Split Disconnected Leaking Repair/Replace
Structural Problems Observed: Yes No Recommend repair Recommend Structural Engineer
Roof Structure: Rafters Trusses Wood Metal Other
Roof Sheathing: Plywood OSB lx Wood Rotted Stained Delaminated
Evidence of Condensation/Moisture Leaking: Yes No (See remarks page)
Ceiling Joists: Wood Metal Other Not visible
Firewall Between Units: N/A Yes No Needs repair/sealing (See remarks page)
Electrical: Open junction box(es) Handyman wiring Visible knob-and-tube

GENERAL COMMENTS

Recommend repairing cosmetic items throughout the home as marked by blue tape
Two dining room light fixture housings are missing and light fixture is crooked; recommend repair
Recommend repainting walls/ceiling throughout the home where previous yellow paint is still visible
Threshold is cracked/damaged at the top of the interior stairs
Front bedroom light fixture housing is missing
Upper level hallway rear light fixture housing is missing
Back bedroom closet light fixture is missing
Recommend installing weather stripping at the attic entry door
Bonus room door hits the ceiling; recommend installing a proper door stop
Bonus room right window left latch does not engage; recommend adjustment/repair

**WATER SERVICE****Main Shut-off Location:** Garage

Water Entry Piping: Not visible Copper/Galv. **Plastic*** (PVC, CPVC, Polybutylene, PEX) Unknown
Visible Water Distribution Piping: Copper Galvanized **Plastic*** (PVC, CPVC, Polybutylene, PEX) Unknown
Condition: Satisfactory Marginal Poor
Lead Other Than Solder Joints: Yes No Unknown Service entry
Functional Flow: Adequate Poor **Water pressure over 80 psi**
Pipes, Supply/Drain: *Corroded* *Leaking* *Valves broken/missing* *Dissimilar metal*
Drain/Waste/Vent Pipe: Copper Cast iron Galvanized PVC ABS
Condition: Satisfactory Marginal Poor
Traps Proper P-Type: N/A Yes No **P-traps recommended**
Functional Drainage: Adequate Poor **Recommend plumber evaluate**
Gas Line: Copper Brass Black iron Stainless steel CSST N/A
Condition: Satisfactory Marginal Poor

MAIN FUEL SHUT-OFF LOCATION N/A**WELL PUMP** N/A Submersible

Location: In basement Well house Well pit Shared well
Pressure Gauge Operates: Yes No Unknown Well pressure: ??? psi Not visible

SANITARY / GRINDER PUMP N/A

Sealed Crock: Yes No **Check Valve:** Yes No **Vented:** Yes No

WATER HEATER #1 N/A**Condition:** Satisfactory Marginal Poor**Brand name:** Rheem

Type: Gas Electric Oil Other

Unit Elevated: Yes No N/A *Tank/Piping corroded/leaking*

Capacity: 50 gallons Approximate age: 2018

Combustion Air Venting Present: Yes No N/A Seismic restraints needed: Yes No N/A

Relief Valve: Yes No **Extension proper:** Yes No *Missing* *Recommend repair*

Vent Pipe: N/A Satisfactory Pitch proper *Improper* *Rusted* *Recommend repair*

WATER SOFTENER*(Unit not evaluated)*

Loop Installed: Yes No **Plumbing Hooked Up:** Yes No

Softener Present: Yes No **Plumbing Leaking:** Yes No

GENERAL COMMENTS

Plumbing is in satisfactory condition



HEATING SYSTEM

HEATING SYSTEM - UNIT #1

Location: **Attic**

(See remarks page)

Brand Name: International ComfortApproximate age: **2016**

Energy Source: Gas LP Oil Electric Solid Fuel

Warm Air System: Belt drive Direct drive Gravity Central system Floor/Wall unit

Heat Exchanger: N/A (sealed) Visual w/mirror *Flame distortion* *Rusted* *Carbon/soot buildup*

Carbon Monoxide: N/A Detected at Plenum/Register Not tested

CO Test: Tester: **Combustion Air Venting Present:** Yes No N/A

Controls: Disconnect: Yes No

Distribution: Metal duct Insul. flex duct Cold air returns Duct board *Asbestos-like wrap*

Flue Piping: N/A Rusted Improper slope *Safety hazard*

Filter: Standard Electrostatic Satisfactory Recommend cleaning/replacement

When Turned On By Thermostat: Fired Did not fire Proper Operation: Yes No Not tested

System Not Operated Due To: Exterior temperature Other

Recommend technician examine **System Condition:** Satisfactory Marginal Poor

BOILER SYSTEM

 N/A**Brand Name:**Approximate age: year(s) Unknown

Model #: ???

Serial #: ???

 System not operated due to:

Energy Source: Gas LP Oil Electric

Distribution: Hot water Baseboard Steam Radiator

Circulator: Pump Gravity Multiple zones

Controls: Temp/pressure gauge exist: Yes No **Operating:** Yes No

Oil Fired Units: Disconnect: Yes No **Combustion Air Venting Present:** Yes No N/A

Relief valve: Yes No Missing Extension proper: Yes No

Operated: **When turned on by thermostat:** Fired Did not fire

Operation: Satisfactory: Yes No *Recommend HVAC technician examine* *Before closing*

OTHER SYSTEMS

 N/A Electric baseboard Radiant ceiling cable Gas space heater Woodburning stove (See Remarks page)

Proper Operation: Yes No

System Condition: Satisfactory Marginal Poor

GENERAL COMMENTS

AC unit was manufactures in 2014 and Furnace was manufactured in 2016



ELECTRIC/COOLING SYSTEM

MAIN PANEL Location: **Garage**

Condition: Satisfactory Marginal Poor

Adequate Clearance To Panel: Yes No Amperage: 200 Breakers Fuses

G.F.C.I. present: Yes No **Operative:** Yes No

A.F.C.I. present: Yes No **Operative:** Yes No

MAIN WIRE: Copper Aluminum Copper clad aluminum Not visible

Tapping before the main breaker *Double tapping of the main wire*

Condition: Satisfactory Poor **Federal Pacific Panel Stab Lok® (See remarks page)***

BRANCH WIRE: Copper **Aluminum*** Copper clad aluminum Not visible

Condition: Satisfactory Poor *Recommend electrician evaluate/repair**

Romex BX cable Conduit *Knob & tube***

Double tapping *Wires undersized/oversized breaker/fuse*

Panel not accessible Not evaluated **Reason:**

SUB PANEL(S) None apparent

Location 1:

Location 2:

Location 3:

Panel not accessible Not evaluated **Reason:**

Branch Wire: Copper Aluminum Copper clad aluminum

Neutral/ground separated: Yes No Neutral isolated: Yes No *Safety hazard*

Condition: Satisfactory Marginal Poor *Recommend separating/isolating neutrals*

ELECTRICAL FIXTURES

A representative number of installed lighting fixtures, switches, and receptacles located inside the house, garage, and exterior walls were tested and found to be:

Condition: Satisfactory Marginal Poor

Open grounds Reverse polarity GFCIs not operating

Solid conductor aluminum branch wiring circuits (See remarks page)*

Ungrounded 3-prong outlets *Recommend electrician evaluate/repair**

GENERAL COMMENTS

Breaker #21 in the electrical panel labeled "kitchen GFI" trips when reset; recommend electrician repair



ITEMS NOT OPERATING

- Unable to test HVAC cooling system due to exterior temperature
- Wood fence in the backyard is incomplete
- Dryer exhaust vent louver does not fully cover the vent opening on the roof; may allow pest/water entry
- Kitchen appliances were not installed at the time of inspection; unable to test
- Kitchen and bathroom cabinet door and drawer pulls are missing throughout the home
- Several kitchen cabinet shelves are not installed
- Two kitchen drawers are not operating properly to the left of the stove
- Kitchen lower rotating metal shelf is not operating properly; recommend adjustment/repair
- Garage interior door does not seal properly when closed
- Garage overhead door automatic opener was not operating at the time of inspection and light bulb is missing
- Master bath right light fixture is not installed
- Master bath tub does not drain properly due to debris present in the tub/drain
- Unable to fully test the master bath tub Jacuzzi due to debris present in the tub
- Master bath toilet room window is very difficult to operate; recommend adjustment/repair
- Back bedroom closet light fixture is missing
- Low water pressure observed at the hall bath tub and shower; recommend plumber repair
- Bonus room right window left latch does not engage; recommend adjustment/repair

MAJOR CONCERNS

- Raised shingle present on the roof by the chimney chase; may cause leaking; recommend roofer evaluate/repair
- Slight damage/exposed felt present on a few shingles on the roof; recommend roofer evaluate and repair
- Breaker #21 in the electrical panel labeled "kitchen GFI" trips when reset; recommend electrician repair
- Leak uncovered beneath the master bath left sink; recommend plumber repair

POTENTIAL SAFETY HAZARDS

- Kitchen right wall outlets labeled "GFCI protected" do not trip when tested; recommend electrician repair
- Laundry room outlet is not GFCI protected
- Recommend lowering the garage overhead door safety reverse sensors below 6" to account for small animals/children
- Master bath right outlet is not GFCI protected
- Hall bath outlet is not GFCI protected

DEFERRED COST ITEMS AND COSMETIC ITEMS

Items that have reached or are reaching their normal life expectancy or show indications that they may require repair or replacement anytime during the next five (5) years.

- No window screens are present on the home
- Sewer clean out access in the front yard is not encased in an iron cover
- Recommend trimming tree branches present in close proximity to the left side of the home/roof
- Recommend installing splash blocks at all gutter downspouts leading into soil
- Portion of wood beam is exposed above the front porch
- AC unit is not level; recommend leveling to extend life expectancy
- AC unit was manufactured in 2014 and Furnace was manufactured in 2016
- Sitting water present in the right side of the back yard; recommend waterflow expert evaluate
- Recommend sealing around the condensation line on the soffit on the back of the home
- Recommend sealing exposed nails present on the roof shingles and roof vents/boots
- Recommend repairing cosmetic items throughout the home as marked by blue tape
- Front exterior door is not square; recommend adjustment/repair

- Two dining room light fixture housings are missing and light fixture is crooked; recommend repair**
- Recommend sealing around the kitchen refrigerator water supply port**
- Kitchen countertop backsplash is missing**
- Poorly cut plumbing penetration holes present in the kitchen cabinet beneath the sink**
- Laundry room washer supply valve housing frame is missing**
- Typical crack present on the garage concrete floor; recommend monitoring**
- Slight damage present at the base of the garage metal overhead door**
- Master bath shower hot and cold water controls are reversed; recommend plumber repair**
- Recommend repainting walls/ceiling throughout the home where previous yellow paint is still visible**
- Threshold is cracked/damaged at the top of the interior stairs**
- Front bedroom light fixture housing is missing**
- Upper level hallway rear light fixture housing is missing**
- Recommend installing weather stripping at the attic entry door**
- Recommend installing a proper threshold at the hall bath doorway**
- Bonus room door hits the ceiling; recommend installing a proper door stop**

* Items listed in this report may inadvertently have been left off the Summary Sheet. Customer should read the entire report, including the Remarks.



Low water pressure observed at the hall bath tub and shower; recommend plumber repair



Bonus room right window left latch does not engage; recommend adjustment/repair



Hall bath outlet is not GFCI protected



Recommend installing a proper threshold at the hall bath doorway

Recommend installing weather stripping at the attic entry door



Back bedroom closet light fixture is missing



Front bedroom light fixture housing is missing



Threshold is cracked/damaged at the top of the interior stairs



Master bath shower hot and cold water controls are reversed; recommend plumber repair




Master bath right light fixture is not installed





Unable to fully test the master bath tub Jacuzzi due to debris present in the tub



Master bath tub does not drain properly due to debris present in the tub/drain



Leak uncovered beneath the master bath left sink; recommend plumber repair



Master bath right outlet is not GFCI protected



Slight damage present at the base of the garage metal overhead door



Garage overhead door automatic opener was not operating at the time of inspection and light bulb is missing



Typical crack present on the garage concrete floor; recommend monitoring



Recommend lowering the garage overhead door safety reverse sensors below 6" to account for small animals/children



Breaker #21 in the electrical panel labeled "kitchen GFI" trips when reset; recommend electrician repair



Garage interior door does not seal properly when closed



Laundry room outlet is not GFCI protected



Laundry room washer supply valve housing frame is missing



Kitchen lower rotating metal shelf is not operating properly; recommend adjustment/repair



Two kitchen drawers are not operating properly to the left of the stove



Several kitchen cabinet shelves are not installed



Poorly cut plumbing penetration holes present in the kitchen cabinet beneath the sink



Kitchen right wall outlets labeled "GFCI protected" do not trip when tested; recommend electrician repair

Recommend sealing around the kitchen refrigerator water supply port



Kitchen countertop backsplash is missing

Kitchen and bathroom cabinet door and drawer pulls are missing throughout the home



Kitchen appliances were not installed at the time of inspection; unable to test



Two dining room light fixture housings are missing and light fixture is crooked; recommend repair

Recommend repairing cosmetic items throughout the home as marked by blue tape





Front exterior door is not square; recommend adjustment/repair



Slight damage/exposed felt present on a few shingles on the roof; recommend roofer evaluate and repair






Wood fence in the backyard is incomplete



Recommend sealing around the condensation line on the soffit on the back of the home

AC unit was manufactured in 2014 and Furnace was manufactured in 2016




AC unit is not level; recommend leveling to extend life expectancy



Portion of wood beam is exposed above the front porch



Recommend installing splash blocks at all gutter downspouts leading into soil




Sitting water present in the right side of the back yard. recommend waterflow expert evaluate





Sewer clean out access in the front yard is not encased in an iron cover



Recommend trimming tree branches present in close proximity to the left side of the home/roof



No window screens are present on the home



Bonus room door hits the ceiling; recommend installing a proper door stop

FOR FREE QUOTES ON REPAIRS CALL



GREY CASTLE
CONSTRUCTION
404-502-8353



REMARKS

SERVICE WALKS/DRIVEWAYS

Spalling concrete cannot be patched with concrete because the new will not bond with the old. Water will freeze between the two layers, or the concrete will break up from movement or wear. Replacement of the damaged section is recommended. Walks or driveways that are close to the property should be properly pitched away to direct water away from the foundation. Asphalt driveways should be kept sealed and larger cracks filled so as to prevent damage from frost.

Patios that have settled towards the structure should be mudjacked or replaced to assure proper pitch. Improperly pitched patios are one source of wet basements.

EXTERIOR WOOD SURFACES

All surfaces of untreated wood need regular applications of paint or special chemicals to resist damage. Porch or deck columns and fence posts which are buried in the ground and made of untreated wood will become damaged within a year or two.

Decks should always be nailed with galvanized, stainless steel or aluminum nails. Decks that are not painted or stained should be treated with a water sealer.

GRADING AND DRAINAGE

Any system of grading or landscaping that creates positive drainage (moving water away from the foundation walls) will help to keep a basement dry. Where negative grade exists and additional backfill is suggested, it may require digging out around the property to get a proper pitch. Dirt shall be approximately 6" below the bottom sill and should not touch wood surfaces.

Flower beds, loose mulched areas, railroad ties and other such landscaping items close to the foundation trap moisture and contribute to wet basements. To establish a positive grade, a proper slope away from the house is 1" per foot for approximately 5-6 feet. Recommend ground cover planting or grass up to foundation.

ROOF AND SURFACE WATER CONTROL

Roof and surface water must be controlled to maintain a dry basement. This means keeping gutters cleaned out and aligned, extending downspouts, installing splashblocks, and building up the grade so that roof and surface water is diverted away from the building.

WINDOW WELLS

The amount of water which enters a window well from falling rain is generally slight, but water will accumulate in window wells if the yard is improperly graded. Plastic window well covers are useful in keeping out leaves and debris.

RETAINING WALLS

Retaining walls deteriorate because of excessive pressure buildup behind them, generally due to water accumulation. Conditions can often be improved by excavating a trench behind the retaining wall and filling it with coarse gravel. Drain holes through the wall will then be able to relieve the water pressure.

Retaining walls sometime suffer from tree root pressure or from general movement of topsoil down the slope. Normally, these conditions require rebuilding the retaining wall.

RAILINGS

It is recommended that railings be installed for any stairway over 3 steps and porches over 30" for safety reasons. Balusters for porches, balconies, and stairs should be close enough to assure children cannot squeeze through.



REMARKS

Valleys and Flashings that are covered with shingles and/or tar or any other material are considered not visible and are not part of the inspection.

Tar and Gravel Roofs are a type of covering on a pitched roof requires ongoing annual maintenance. We recommend that a roofing contractor evaluate this type of roof. Infra-red photography is best used to determine areas of potential leaks.

Flat roofs are very vulnerable to leaking. It is very important to maintain proper drainage to prevent the ponding of water. We recommend that a roofing contractor evaluate this type of roof.

ROOF TYPE	LIFE EXPECTANCY	SPECIAL REMARKS
<i>Asphalt Shingles</i>	15-20 years	Used on nearly 80% of all residential roofs; requires little maintenance
<i>Asphalt Multi-Thickness Shingles*</i>	20-30 years	Heavier and more durable than regular asphalt shingles
<i>Asphalt Interlocking Shingles*</i>	15-25 years	Especially good in high-wind areas
<i>Asphalt Rolls</i>	10 years	Used on low slope roofs
<i>Built-up Roofing</i>	10-20 years	Used on low slope roofs; 2 to 3 times as costly as asphalt shingles
<i>Wood Shingles*</i>	10-40 years ¹	Treat with preservative every 5 years to prevent decay
<i>Clay Tiles*</i> <i>Cement Tiles*</i>	20 + years 20 + years	Durable, fireproof, but not watertight, requiring a good subsurface base
<i>Slate Shingles*</i>	30-100 years ²	Extremely durable, but brittle and expensive
<i>Asbestos Cement Shingles*</i>	30-75 years	Durable, but brittle and difficult to repair
<i>Metal Roofing</i>	15-40 + years	Comes in sheets & shingles; should be well grounded for protection from lightning; certain metals must be painted
<i>Single Ply Membrane</i>	15-25 years (mfr's claim)	New material; not yet passed test of time
<i>Polyurethane with Elastomeric Coating</i>	5-10 years ¹	Used on low slope roofs.

* Not recommended for use on low slope roof

¹ Depending on local conditions and proper installation

² Depending on quality of slate

Roof coverings should be visually checked in the spring and fall for any visible missing shingles, damaged coverings or other defects. Before re-roofing, the underside of the roof structure and roof sheathing should be inspected to determine that the roof structure can support the additional weight of the shingles.

Wood shakes and shingles will vary in aging, due to the quality of the material, installation, maintenance, and surrounding shade trees. Ventilation and drying of the wood material is critical in extending the life expectancy of the wood. Commercial preservatives are available on the market, which could be applied to wood to impede deterioration.

This confidential report is prepared exclusively for Debra Lewis
© 2019 Property Inspectors of Atlanta



REMARKS

CHIMNEYS

Chimneys built of masonry will eventually need tuckpointing. A cracked chimney top that allows water and carbonic acid to get behind the surface brick/stone will accelerate the deterioration. Moisture will also deteriorate the clay flue liner. Periodic chimney cleaning will keep you apprised of the chimney's condition. The flashing around the chimney may need resealing and should be inspected every year or two. Fireplace chimneys should be inspected and evaluated by a chimney professional before using. Chimneys must be adequate height for proper drafting. Spark arrestors are recommended for a wood burning chimney, and chimney caps for fossil fuels.

Unlined Chimney should be re-evaluated by a chimney technician.

Have flue cleaned and re-evaluated. The flue lining is covered with soot or creosote and no representation can be made as to the condition.

NOT EVALUATED

The flue was not evaluated due to inaccessibility such as roof pitch, cap, cleanout not accessible, etc.

CRICKET FLASHING

Small, sloped structure made of metal and designed to drain moisture away from a chimney. Usually placed at the back of a chimney.

GUTTERS AND DOWNSPOUTS

This is an extremely important element in basement dampness control. Keep gutters clean and downspout extensions in place (4' or more). Paint the inside of galvanized gutters, which will extend the life. Shortly after a rain or thaw in winter, look for leaks at seams in the gutters. These can be recaulked before they cause damage to fascia or soffit boards. If no gutters exist, it is recommended that they be added.

SIDING

Wood siding should not come in contact with the ground. The moisture will cause rotting to take place and can attract carpenter ants. See page 34 for siding that have known problems, but are not always recognizable. EIFS This type of siding is a synthetic stucco and has experienced serious problems. It requires a certified EIFS inspector to determine condition.

Brick and stone veneer must be monitored for loose or missing mortar. Some brick and stone are susceptible to spalling. This can be caused when moisture is trapped and a freeze/thaw situation occurs. There are products on the market that can be used to seal out the moisture. This holds true for brick and stone chimneys also.

Metal siding will dent and scratch. Oxidation is a normal reaction in aluminum. There are good cleaners on the market and it is recommended that they be used occasionally. Metal siding can be painted.

DOORS AND WINDOWS

These can waste an enormous amount of energy. Maintain the caulking around the frames on the exterior. Check for drafts in the winter and improve the worst offenders first. Windows that have leaky storm windows will usually have a lot of sweating. Likewise, well-sealed storms that sweat indicate a leaky window. It is the tighter unit that will sweat (unless the home has excess humidity to begin with).

Wood that exhibits blistering or peeling paint should be examined for possible moisture sources: roof leaks, bad gutters, interior moisture from baths or laundry or from a poorly vented crawl space. Some paint problems have no logical explanation, but many are a symptom of an underlying problem. A freshly painted house may mask these symptoms, but after you have lived in the home for a year or two, look for localized paint blistering (peeling). It may be a clue.

New glazing will last longer if the raw wood is treated with boiled linseed oil prior to glazing. It prevents the wood from drawing the moisture out of the new glazing.

CAULKING

Many different types of caulk are available on the market today. Check with a paint or hardware store for the kind of application you need.



REMARKS

EXTERIOR DOORS

The exposed side of exterior doors needs to be painted or properly stained and varnished to prevent discoloring and delamination. Weatherstripping is a must to prevent drafts.

ELECTRICAL

Extension cord wiring to an automatic door opener should be removed and an outlet should be installed by the opener.



REMARKS

OVERHEAD DOOR OPENERS

We recommend that a separate electrical outlet be provided. Openers that do not have a **safety reverse** are considered a safety hazard. Small children and pets are especially vulnerable. We recommend the operating switches be set high enough so children cannot reach them. If a electric sensor is present, it should be tested occasionally to ensure it is working.

GARAGE SILL PLATES should be elevated or treated lumber should be used. If this is not the case, try to direct water away to prevent rotting.

A/C COMPRESSORS

They should not become overgrown with foliage. Clearance requirements vary, but 2' on all sides should be considered minimal with up to 6' of air discharge desirable. If a clothes dryer vent is within five to ten feet, either relocate the vent or do not run when the A/C is running. The lint will quickly reduce the efficiency of the A/C unit. Typical lifespan of an AC compressor is 15yrs.

BURNERS

Any appliance such as a water heater, furnace, etc. should have the flame a minimum of 18" above the floor. Any open flame less than 18" from the floor is a potential safety hazard. The appliance should also be protected from vehicle damage.



KITCHEN REMARKS

PLASTER ON WOOD LATH

Plaster on wood lath is an old technique and is no longer in general use. Wood lath shrinks with time and the nails rust and loosen. As a result, the plaster may become fragile and caution is needed in working with this type of plastering system. Sagging ceilings are best repaired by laminating drywall over the existing plaster and screwing it to the ceiling joists.

PLASTER ON GYPSUM LATH (ROCK LATH)

Plaster on gypsum lath will sometimes show the seams of the 16" wide gypsum lath, but this does not indicate a structural fault. The scalloping appearance can be leveled with drywall joint compound and fiberglass mesh joint tape or drywall can be laminated over the existing plaster on the ceiling.

WOOD FLOORING

Always attempt to clean wood floors first before making the decision to refinish the floor. Wax removers and other mild stripping agents plus a good waxing and buffing will usually produce satisfactory results. Mild bleaching agents help remove deep stains. Sanding removes some of the wood in the floor and can usually be done safely only once or twice in the life of the floor.

NAIL POPS

Drywall nail pops are due to normal expansion and contraction of the wood members to which the drywall is nailed and are usually of no structural significance.

CARPETING

Where carpeting has been installed, the materials and condition of the floor underneath cannot be determined.

APPLIANCES

(If report indicated appliances were operated, the following applies) Dishwashers are tested to see if the motor operates and water sprays properly. Stoves are tested to see that burners are working and oven and broiler get hot. Timer and controls are not tested. Refrigerators are not tested.

No representation is made to continued life expectancy of any appliance.

ASBESTOS AND OTHER HAZARDS

Asbestos fibers in some form are present in many homes, but are often not visible and cannot be identified without testing.

If there is reason to suspect that asbestos may be present and if it is of particular concern, a sample of the material in question may be removed and analyzed in a laboratory. However, detecting or inspecting for the presence or absence of asbestos is not a part of our inspection.

Also excluded from this inspection and report are the possible presence of, or danger from, radon gas, lead-based paint, urea formaldehyde, toxic or flammable chemicals and all other similar or potentially harmful substances and environmental hazards.

WINDOWS

A representative number of windows are inspected.



REMARKS

STALL SHOWER

The metal shower pan in a stall shower has a potential or probable life of 10-20 years depending on quality of the pan installed. Although a visible inspection is made to determine whether a shower pan is currently leaking, it cannot be stated with certainty that no defect is present or that one may not soon develop. Shower pan leaks often do not show except when the shower is in actual use.

CERAMIC TILE

Bathroom tile installed in a mortar bed is excellent. It is still necessary to keep the joint between the tile and the tub/shower caulked or sealed to prevent water spillage from leaking through and damaging the ceilings below. Ceramic tile is often installed in mastic. It is important to keep the tile caulked or water will seep behind the tile and cause deterioration in the wallboard. Special attention should be paid to the area around faucets and other tile penetrations.

EXHAUST FANS

Bathrooms with a shower should have exhaust fans when possible. This helps to remove excess moisture from the room, preventing damage to the ceiling and walls and wood finishes. The exhaust fan should not be vented into the attic. The proper way to vent the fan(s) is to the outside. Running the vent pipe horizontally and venting into a gable end or soffit is preferred. Running the vent pipe vertically through the roof may cause condensation to run down the vent pipe, rusting the fan and damaging the wallboard. Insulating the vent pipe in the attic will help to reduce this problem.

SLOW DRAINS on sinks, tubs, and showers are usually due to build up of hair and soap scum. Most sink popups can be easily removed for cleaning. Some tubs have a spring attached to the closing lever that acts as a catch for hair. It may require removing a couple of screws to disassemble. If you cannot mechanically remove the obstruction, be kind to your pipes. *Don't use a caustic cleaner.* There are several bacteria drain cleaners available. They are available at hardware stores in areas where septic tanks are used. These drain cleaners take a little longer to work, but are safe for you and your pipes.

SAFETY HAZARDS

Typical safety hazards found in bathrooms are open grounds or reverse polarity by water.
Replacing these outlets with G.F.C.I.'s are recommended.

WHIRLPOOL TUBS

This relates to interior tubs hooked up to interior plumbing. Where possible, the motor will be operated to see that the jets are working. Hot tubs and spas are not inspected.



ROOMS REMARKS

DOOR STOPS

All swinging doors should be checked for door stops. Broken or missing door stops can result in door knobs breaking through drywall or plaster.

CLOSET GUIDES

Sliding closet doors should be checked to see that closet guides are in place. Missing or broken closet guides can cause scratches and damage to doors.

COLD AIR RETURNS

Bedrooms that do not have cold air returns in them should have a 3/4" gap under the doors to allow cold air to be drawn into the hall return.

AN INSPECTION VERSUS A WARRANTY

A home inspection is just what the name indicates, an inspection of a home...usually a home that is being purchased. The purpose of the inspection is to determine the condition of the various systems and structures of the home. While an inspection performed by a competent inspection company will determine the condition of the major components of the home, no inspection will pick up every minute latent defect. The inspector's ability to find all defects is limited by access to various parts of the property, lack of information about the property and many other factors. A good inspector will do his or her level best to determine the condition of the home and to report it accurately. The report that is issued is an opinion as to the condition of the home. This opinion is arrived at by the best technical methods available to the home inspection industry. It is still only an opinion.

A warranty is a policy sold to the buyer that warrants that specific items in the home are in sound condition and will remain in sound condition for a specified period of time. Typically, the warranty company never inspects the home. The warranty company uses actuarial tables to determine the expected life of the warranted items and charges the customer a fee for the warranty that will hopefully cover any projected loss and make a profit for the warranty seller. It is essentially an insurance policy.

The service that we have provided you is an inspection. We make no warranty of this property. If you desire warranty coverage, please see your real estate agent for details about any warranty plan to which their firm may have access.



INTERIOR

REMARKS

WINDOW FRAMES AND SILLS

Window frames and sills are often found to have surface deterioration due to condensation that has run off the window and damaged the varnish. Usually this can be repaired with a solvent style refinisher and fine steel wool. This is sometimes a sign of excess humidity in the house.

See comments regarding caulking doors and windows.

FIREPLACES

It is important that a fireplace be cleaned on a routine basis to prevent the buildup of creosote in the flue, which can cause a chimney fire.

Masonry fireplace chimneys are normally required to have a terra cotta flue liner or 8 inches of masonry surrounding each flue in order to be considered safe and to conform with most building codes.

During visual inspections, it is not uncommon to be unable to detect the absence of a flue liner either because of stoppage at the firebox, a defective damper or lack of access from the roof.

WOODBURNERS

Once installed, it can be difficult to determine proper clearances for woodburning stoves. Manufacturer specifications, which are not usually available to the inspector, determine the proper installation. We recommend you ask the owner for paperwork, verifying that it was installed by a professional contractor.

VENTILATION

Ventilation is recommended at the rate of one square foot of vent area to 300 square feet of attic floor space, this being divided between soffit and rooftop. Power vents should ideally have both a humidistat and a thermostat, since ventilation is needed to remove winter moisture as well as summer heat. Evidence of condensation such as blackened roof sheathing, frost on nail heads, etc. is an indication that ventilation may have been or is blocked or inadequate.

INSULATION

The recommended insulation in the attic area is R-38, approximately 12". If insulation is added, it is important that the ventilation is proper.

SMOKE DETECTORS

Smoke detectors should be tested monthly. At least one detector should be on each level. CO detectors are not required by most states, but for safety reasons, are highly recommended.

VAPOR BARRIERS

The vapor barrier should be on the warm side of the surface. Most older homes were built without vapor barriers. If the vapor barrier is towards the cold side of the surface, it should be sliced or removed. Most vapor barriers in the attic are covered by insulation and therefore, not visible.

SAFETY GLAZING

Safety glazing requirements vary depending on the age of the home. Every attempt is made to identify areas where the lack of safety glazing presents an immediate safety hazard, such as a shower door. In some older homes it is difficult to determine if safety glazing is present, since the glass is not marked. Therefore, no representation is made that safety glazing exists in all appropriate areas.

INSULATED GLASS

Broken seal in thermopane/insulated windows are not always visible nor detectible due to humidity and temperature changes during the day. Other factors such as window covering, dirty windows, and lack of accessibility, personal property placed in front of the windows all effect the view of the windows at the time of the inspection.



REMARKS

BASEMENT

Any basement that has cracks or leaks is technically considered to have failed. Most block basements have step cracks in various areas. If little or no movement has occurred and the step cracks are uniform, this is considered acceptable. Horizontal cracks in the third or fourth block down indicate the block has moved due to outside pressure. They can be attributed to many factors such as improper grading, improperly functioning gutter and downspout system, etc. Normally if little or no movement has taken place and proper grading and downspouts exist, this is considered acceptable. If the wall containing the stress crack(s) has moved considerably, this will require some method of reinforcement. Basements that have been freshly painted or tuckpointed should be monitored for movement. This will be indicated by cracks reopening. If cracks reappear, reinforcement may be necessary. Reinforcing a basement wall can become expensive.

FOUNDATION (COVERED WALLS)

Although an effort has been made to note any major inflections or weaknesses, it is difficult at best to detect these areas when walls are finished off, or basement storage makes areas inaccessible. **No representation is made as to the condition of these walls.**

MONITOR indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

HAVE EVALUATED We recommend that the walls be re-evaluated by a structural engineer or basement repair company and estimates be obtained if work is required.

VAPOR BARRIER

Floors that are dirt or gravel should be covered with a vapor barrier.

MOISTURE PRESENT

Basement dampness is frequently noted in houses and in most cases the stains, moisture or efflorescence present is a symptom denoting that a problem exists outside the home. Usual causes are improper downspout extensions or leaking gutters and/or low or improper grade (including concrete surfaces) at the perimeter of the house. A proper slope away from the house is one inch per foot for four to six feet.

Expensive solutions to basement dampness are frequently offered. It is possible to spend thousands of dollars on solutions such as pumping out water that has already entered or pumping of chemical preparations into the ground around the house, when all that may be necessary are a few common sense solutions at the exterior perimeter. However, this is not intended to be an exhaustive list of causes and solutions to the presence of moisture. **No representation is made to future moisture that may appear.**

PALMER VALVE

Many older homes have a valve in the floor drain. This drain needs to remain operational.

DRAIN TILE

We offer no opinion about the existence or condition of the drain tile, as it cannot be visibly inspected.

BASEMENT ELECTRICAL OUTLETS

We recommend that you have an outlet within 6' of each appliance. The appliance you plan to install may be different than what exists, therefore the inspection includes testing a representative number of receptacles that exist. It is also recommended to have ground fault circuit interrupts for any outlet in the unfinished part of the basement and crawl spaces.



REMARKS

CRAWL SPACES

Crawl spaces are shallow spaces between the first level floor joist and the ground. Access to this area may be from the inside, outside or not accessible at all. Ductwork, plumbing, and electrical may be installed in the space in which access may be necessary. The floor of the crawl space may be covered with concrete, gravel, or may be the original soil. A vapor barrier may be a sheet of plastic or tar paper and installed over or under this material. The vapor barrier will deter the moisture from the earth from escaping into the crawl space and causing a musty smell. Ventilation is also important to control excess moisture buildup. Vents may be located on the outside of the house and are normally kept open in the summer and closed for the winter (where freezing may occur).

The basement/crawl space diagram indicates areas that are covered and not part of a visual inspection. Every attempt is made to determine if paneling is warped, moisture stains are bleeding through, etc. Storage that blocks the visibility of a wall is not removed to examine that area. Therefore, it is important that on your walk-through before closing, you closely examine these areas.

Closed crawl spaces that have vents to the outside should have insulation under the floor above the crawl space.

HAVE EVALUATED

We recommend that the walls be re-evaluated by a structural engineer or basement repair company and estimates be obtained if work is required.

MONITOR

Indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.



REMARKS

WELLS

Examination of wells is not included in this visual inspection. It is recommended that you have well water checked for purity by the local health authorities and, if possible, a check on the flow of the well in periods of drought. A well pit should have a locked cover on it to prevent anyone from falling into the pit.

SEPTIC SYSTEMS

The check of septic systems is not included in our visual inspection. You should have the local health authorities or other qualified experts check the condition of the septic system.

In order for the septic system to be checked, the house must have been occupied within the last 30 days.

WATER PIPES

Galvanized water pipes rust from the inside out and may have to be replaced within 20 to 30 years. This is usually done in two stages: horizontal piping in the basement first, and vertical pipes throughout the house later as needed. Copper pipes usually have more life expectancy and may last as long as 60 years before needing to be replaced.

HOSE BIBS

During the winter months it is necessary to make sure the outside faucets are winterized. This can be done by means of a valve located in the basement. Leave the outside faucets open to allow any water standing in the pipes to drain, preventing them from freezing. Hose bibs cannot be tested when winterized.

WATER HEATER

The life expectancy of a water heater is 5-10 years. Water heaters generally need not be replaced unless they leak. It is a good maintenance practice to drain 5-10 gallons from the heater several times a year. Missing relief valves or improper extension present a safety hazard.

WATER SOFTENERS

During a visual inspection it is not possible to determine if water is being properly softened.

PLUMBING

The temperature/pressure valve should be tested several times a year by lifting the valve's handle. Caution: very hot water will be discharged. If no water comes out, the valve is defective and must be replaced.

SHUT-OFF VALVES

Most shut-off valves have not been operated for long periods of time. We recommend operating each shut-off valve to: toilet bowl, water heater, under sinks, main shut-off, hose faucets, and all others. We recommend you have a plumber do this, as some of the valves may need to be repacked or replaced. Once the valves are in proper operating order, we recommend opening and closing these valves several times a year.

POLYBUTYLENE PIPING

This type of piping has a history of problems and should be examined by a licensed plumber and repaired or replaced as necessary.

MECHANICAL DEVICES MAY OPERATE AT ONE MOMENT AND LATER MALFUNCTION; THEREFORE, LIABILITY IS SPECIFICALLY LIMITED TO THOSE SITUATIONS WHERE IT CAN BE CONCLUSIVELY SHOWN THAT THE MECHANICAL DEVICE INSPECTED WAS INOPERABLE OR IN THE IMMEDIATE NEED OF REPAIR OR NOT PERFORMING THE FUNCTION FOR WHICH IS IT WAS INTENDED AT THE TIME OF INSPECTION.

CSST

Corrugated Stainless Steel Tubing is an alternative to traditional black iron gas piping. It is a continuous, flexible, stainless steel pipe with an exterior PVC covering.



REMARKS

HEATING AND AIR CONDITIONING units have limited lives. Normal lives are:

GAS-FIRED HOT AIR.....	15-25 years
OIL-FIRED HOT AIR.....	20-30 years
CAST IRON BOILER.....	30-50 years
(Hot water or steam)	or more
STEEL BOILER.....	30-40 years
(Hot water or steam)	or more
COPPER BOILER.....	10-20 years
(Hot water or steam)	
CIRCULATING PUMP (Hot water).....	10-15 years
AIR CONDITIONING COMPRESSOR...	8-12 years
HEAT PUMP.....	8-12 years

Gas-fired hot air units that are close to or beyond their normal lives have the potential of becoming a source of carbon monoxide in the home. You may want to have such a unit checked every year or so to assure yourself that it is still intact. Of course a unit of such an age is a good candidate for replacement with one of the new, high efficiency furnaces. The fuel savings alone can be very attractive.

Boilers and their systems may require annual attention. If you are not familiar with your system, have a heating contractor come out in the fall to show you how to do the necessary thing **Caution: do not add water to a hot boiler!**

Forced air systems should have filters changed every 30 to 60 days of the heating and cooling season. This is especially true if you have central air conditioning. A dirty air system can lead to premature failure of your compressor - a \$1,500 machine.

Oil-fired furnaces and boilers should be serviced by a professional each year. Most experts agree you will pay for the service cost in fuel saved by having a properly tuned burner.

Read the instructions for maintaining the humidifier on your furnace. A malfunctioning humidifier can rust out a furnace rather quickly. It is recommended that the humidifier be serviced at the same time as the furnace, and be cleaned regularly. **During a visual inspection it is not possible to determine if the humidifier is working.**

Have HVAC technician examine - A condition was found that suggests a heating contractor should do a further analysis. We suggest doing this before closing.

Heat exchangers cannot be examined nor their condition determined without being disassembled. Since this is not possible during a visual, non-technically exhaustive inspection, you may want to obtain a service contract on the unit or contact a furnace technician regarding a more thorough examination.

Testing pilot safety switch requires blowing out the pilot light. Checking safety limit controls requires disconnecting blower motor or using other means beyond the scope of this inspection. If the furnace has not been serviced in last 12 months you may want to have a furnace technician examine.

CO Test This is not part of a non-technical inspection. If a test was performed, the type of tester is indicated on the Heating System page.


Combustible Gas Detector If a gas detector was used during the inspection of the furnace and evidence of possible combustible gases was noted, we caution you that our test instrument is sensitive to many gases and not a foolproof test. None-the-less, this presents the possibility that a hazard exists and could indicate that the heat exchanger is, or will soon be, defective.



REMARKS

Every effort has been made to evaluate the size of the service. Three wires going into the home indicate 240 volts. The total amperage can be difficult to determine. We highly recommend that ground fault circuit interrupters (G.F.C.I.) be connected to all outlets around water. This device automatically shuts the circuit off when it senses a current leak to ground. This device can be purchased in most hardware stores. G.F.C.I.'s are recommended by all outlets located near water, outside outlets, or garage outlets. Pool outlets should also be protected with a G.F.C.I.

See diagram below:



If you do have G.F.C.I.'s, it is recommended that you test (and reset) them monthly. When you push the test button, the reset button should pop out, shutting off the circuit. If it doesn't, the breaker is not working properly. If you don't test them once a month, the breakers have a tendency to stick and may not protect you when needed.

Knob and tube wiring found in older homes should be checked by an electrician to insure that the wire cover is in good condition. Under no circumstances should this wire be covered with insulation. Recess light fixtures should have a baffle around them so that they are not covered with insulation. The newer recessed fixtures will shut off if they overheat. (no representation is made as to proper recess lighting fixtures).

Federal Pacific Stab-Lok® Electrical panels may be unsafe.

See www.google.com (Federal Pacific)

Aluminum wiring in general lighting circuits has a history of over heating, with the potential of a fire. If this type of wiring exists, a licensed electrical contractor should examine the whole system.

ARC FAULTS

In some areas arc faults are required in new homes, starting in 2002 and these control outlets in the bedrooms.

REVERSE POLARITY

A common problem that surfaces in many homes is reverse polarity. This is a potentially hazardous situation in which the hot and neutral wires of a circuit are reversed at the outlet, thereby allowing the appliance to incorrectly be connected. This is an inexpensive item to correct.

Each receptacle has a brass and silver screw. The black wire should be wired to the brass screw and the white wire should go to the silver screw. When these wires are switched, this is called "reverse polarity." Turning off the power and switching these wires will correct the problem.

Main service wiring for housing is typically 240 volts. The minimum capacity for newer homes is 100 amps though many older homes still have 60 amp service. Larger homes or all electric homes will likely have a 200 amp service.

Main service wiring may be protected by one or more circuit breakers or fuses. While most areas allow up to six main turnoffs, expanding from these panels is generally not allowed.

COOLING

Testing A/C System and Heat Pump- The circuit breakers to A/C should be on for a minimum of 24 hours and the outside temperature at least 60 degrees for the past 24 hours or an A/C system cannot be operated without possible damage to the compressor. Check the instructions in your A/C manual or on the outside compressor before starting up in the summer. Heat pump can only be tested in the mode it's running in. Outside temperature should be at least 65° for the past 24 hours to run in cooling mode.

Temperature differential, between 14°-22°, is usually acceptable. If out of this range, have an HVAC contractor examine it. It is not always feasible to do a differential test due to high humidity, low outside temperature, etc.

COSTS OF REMODELING OR REPAIR

The prices quoted below include a range of prices based on a typical metropolitan area. Individual prices from contractors can vary substantially from these ranges. We advise that several bids be obtained on any work exceeding \$500 dollars. **DO NOT RELY ON THESE PRICES... GET FURTHER ESTIMATES.**

ITEM	UNIT	ESTIMATED PRICE
Masonry fireplace	Each	\$4,000 - \$8,000
Install prefab fireplace	Each	2,000 - 4,000
Insulate attic	Square foot	.75 - 1.25
Install attic ventilating fan	Each	200 - 300
Install new drywall over plaster	Square foot	1.75 - 2.75
Install new warm air furnace	Each	1,800 - 3,500
Replace central air conditioning/heat pump	Per ton	1,000 - 1,500
Install humidifier	Each	300 - 500
Install electrostatic air cleaner	Each	800 - 1,500
Increase electrical service to 200 amps	Each	1,000 - 1,500
Run separate elec. line for dryer	Each	125 - 200
Run separate elec. line for A/C	Each	135 - 200
Install hardwired smoke detector	Each	100 - 180
Install new disposal	Each	150 - 250
Install new dishwasher	Each	500 - 1,000
Install new hot water boiler	Each	2,000 - 4,000
Install new 30-50 gallon water heater	Each	350 - 650
Install new 75 gallon water heater	Each	750 - 1,000
Dig and install new well	Each	get estimate
Install new septic system	Each	get estimate
Re-grade around exterior	Each	get estimate
Install new sump pump	Each	150 - 300
Build new redwood or pressure-treated deck	Square foot	15 - 30
Install storm windows	Each	60 - 150
Install wood replacement windows	Each	400 - 800
Install aluminum or vinyl replacement window	Each	150 - 400
Install new gutters and downspouts	Lineal foot	4.00 - 8.00
Install asphalt shingle o/existing	Square foot	1.20 - 1.70
Tear off existing roof and install new asphalt shingle roof	Square foot	2.50 - 4.00
Install 1-ply membrane rubberized roof	Square foot	get estimate
Install new 4-ply built-up tar & gravel	Square foot	get estimate
Remove asbestos from pipes in basement	Lineal foot	get estimate
Concrete drive or patio	Square foot	4.50 - 9.00
Plus removal of old	Square foot	1.50 - 3.00
Clean chimney flue	Each	100 - 200
Add flue liner for gas fuel	Each	900 - 1,200
Add flue liner for oil or wood	Each	2,800 - 3,500

Deferred Costs - It is impossible to determine how long these items will last before needing replacement. The report addresses most of these items from a "condition" standpoint.

PREVENTIVE MAINTENANCE TIPS

- I. **FOUNDATION & MASONRY:** *Basements, Exterior Walls:* To prevent seepage and condensation problems.
 - a. Check basement for dampness & leakage after wet weather.
 - b. Check chimneys, deteriorated chimney caps, loose and missing mortar.
 - c. Maintain grading sloped away from foundation walls.

- II. **ROOFS & GUTTERS:** To prevent roof leaks, condensation, seepage and decay problems.
 - a. Check for damaged, loose or missing shingles, blisters.
 - b. Clean gutters, leaders, strainers, window wells, drains. Be sure downspouts direct water away from foundation. Cut back tree limbs.
 - c. Check flashings around roof stacks, vents, skylights, chimneys, as sources of leakage. Check vents, louvers and chimneys for birds nests, squirrels, insects.
 - d. Check fascias and soffits for paint flaking, leakage & decay.

- III. **EXTERIOR WALLS:** To prevent paint failure, decay and moisture penetration problems.
 - a. Check painted surface for paint flaking or paint failure. Cut back shrubs.
 - b. Check exterior masonry walls for cracks, looseness, missing or broken mortar.

- IV. **DOORS AND WINDOWS:** To prevent air and weather penetration problems.
 - a. Check caulking for decay around doors, windows, corner boards, joints. Recaulk and weatherstrip as needed. Check glazing, putty around windows.

- V. **ELECTRICAL:** For safe electrical performance, mark & label each circuit.
 - a. Trip circuit breakers every six months and ground fault circuit interrupters (G.F.C.I.) monthly.
 - b. Check condition of lamp cords, extension cords & plugs. Replace at first sign of wear & damage.
 - c. Check exposed wiring & cable for wear or damage.
 - d. If you experience slight tingling shock from handling or touching any appliance, disconnect the appliance & have it repaired. If lights flicker or dim, or if appliances go on and off unnecessarily, call a licensed electrician.

- VI. **PLUMBING:** For preventive maintenance.
 - a. Drain exterior water lines, hose bibs, sprinklers, pool equipment in the fall.
 - b. Draw off sediment in water heaters monthly or per manufacturer's instructions.
 - c. Have septic tank cleaned every 2 years.

- VII. **HEATING & COOLING:** For comfort, efficiency, energy conservation and safety.
 - a. Change or clean furnace filters, air condition filters, electronic filters as needed.
 - b. Clean and service humidifier. Check periodically and annually.
 - c. Have oil burning equipment serviced annually.

- VIII. **INTERIOR:** General house maintenance.
 - a. Check bathroom tile joints, tub grouting & caulking. Be sure all tile joints in bathrooms are kept well sealed with tile grout to prevent damage to walls, floors & ceilings below.
 - b. Close crawl vents in winter and open in summer.
 - c. Check underside of roof for water stains, leaks, dampness & condensation, particularly in attics and around chimneys.

- IX. **Know the location of:**
 - Main water shutoff valve.
 - Main electrical disconnect or breaker.
 - Main emergency shutoff switch for the heating system.