

AIRFRAME MAINTENANCE RECORDS

		Log No
Aircraft Regis	stration No	N57055
Aircraft Mfg. MOONE Y	Model _	Maok serial No. 25-0784
TELEDYNE		
Engine Mfg. COUTINENTAL Engine Mfg.	Model _	TSIO-3(6)-(81 Serial No. 316004
		2434C216_ Serial No. 791971
Blade Design No GODHB	- 16E	Hub Serial NoBlade Serial No's. CKIII & CKII.7
Propeller Mfg.	Model _	Serial No.
Hub Design No		Hub Serial No.
Blade Design No		Blade Serial No's



ALROTECH PUBLICATIONS INC.

www.ddiog.cor PO BOX 1359 / SOUTHOLD, NY 11971-096 (631) 765-937

(All applicable information must be filled in)

1-800-235-644 FAX: (631) 765-935

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		TOTAL broug	ght forward from previous page
113.07	Com	plied us	the annual Inspection. CILV A.D. 85. 2403.
	(rese	and fre	I filler caps) C/W A.A. 76.07.1721 (mit
	test)	CINA	D, 84.26.02 (induction filter replaced David
	cont	with for	dereglier patch, repaired extens should de
	regai	red + tree	tel battery box. Donored HSI for repair of
	Dr.	when u	corporation + Reinstell after repairs (10 830.)
	della	11-3.67)	Reported both peoples deice boots. Relied both lester
	ampe	too Ect	Dr FAR91, 2070 (latting expriss 7.09) A, D'S chaper
	the	ugh- ?	603-23. all work accomplished Isis manufacturers
D.	Inain	Tenho 9	rando and FAR 43 approved. W.O. 18412
		 I certify th accordance 	AIR-CRAFTSMAN, PRESCOTT, ARIZONA at this AIRCRAFT has been inspected in swith a AN UV A inspection and was to be in airworthy condition.
5%.		Eng. SMOI	H 312.6 Aircraft Total Time (377.3 H) NK Engine Total Time (377.3
		John Atterf	Date: 11.12.07
==	1.55	y+'	Jan Stude
		Tach: 4	
r	aulty alterneplaced dri	nator was re- ve clutch. Re	moved and installed after overhaul by Midland Aviation also eturn to service 8130-3 tag provided in this book. RRMANNA 4+11 28-35988
		SUB-TOTAL this	S. Dade
			orward to next page

TOTAL TACH OR RECORDING RECORDING NETER SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

SERVICE TIME

TOTAL brought forward from previous page

3/2/2009 Aircraft Total Time: 2530.3 Tach: 471.5

Removed all inspection panels for inspection. Checked and lubed all control rods and flight controls. Cleaned and treated battery compartment. Removed ELT, checked for corrosion and operation. Cleaned fuel gascolator strainer and replaced seals. Replaced wing fuel cap o-rings. Placed aircraft on jacks and performed retraction tests and emergency extension. Lubed gear doors, retraction control rods and pivot points. Pulled wheels, cleaned inspected and repacked wheel bearings. Replaced brake linings. Replaced instrument vacuum filter. Inspected intake air filter. This aircraft has been inspected IAW an annual/100hour inspection and found to be airworthy at this time.

Parts:

3/1/2010

DATE

2 AN380-4-8 Cotter Pin 2CT
8 105-00200 Rivet Brass Brake
4 RA66-105 Brake Lining RAPCO
1 MS29513-031 O-Ring Fuel
1 MS29513-036 O-Ring Fuel
2 MS29513-338 O-Ring Fuel

Aircraft Total Time: 2655.8 Tach: 597

Removed all inspection panels for inspection. Checked and lubed all control rods and flight controls. Cleaned and treated battery compartment. Removed ELT, and installed new Ameri-king AK 451, 406 MHz Elt, and SER # 8228, Hex # AE2C4080900002CD in accordance with manufacturer's instructions. Performed operation and self tests as required. Completed FAA Form 337 this date. Cleaned fuel gascolator strainer and replaced seals. Placed aircraft on jacks, performed retraction tests and emergency extension. Lubed gear doors, retraction control rods and pivot points. Pulled wheels, cleaned inspected and repacked wheel bearings. Replaced instrument vacuum filter. Inspected intake air filter. Replaced both engine driven vacuum pump PN 216cw, Ser # 8485 and electric standby vacuum pump PN 215cc, Ser #22103. This aircraft has been inspected IAW an annual/100hour inspection and found to be airworthy at this time.

Jam abor 283370. 18

2833 7W 1A

TE .	TOTAL TIME IN SERVICE	TACH CR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
	SERVICE	TOTAL brought fo	orward from previous page
_			
	3/31/2011		and flight control. Cleaned and treated battery
	compartmen	t. Replaced broken Batt	tery negative can't classes deep doors, retraction control rods and pivot points. Pulled wheels,
	jacks, perform	med retraction tests and acted and repacked who	el bearings This aircraft has been inspected IAW an annual/100hour inspection and found to be a. C. Duff 333100 (A

3/31/2011 Aircraft Total Time: 2760.3 Tach: 701.5

Compiled with annual inspection IAW FAA part 43 appendix D and manufacturers maintenance manual. Removed all inspection panels for inspection. Reviewed all AD's, complied with AD 2012-05-09 by visual inspection of trim fitting hinge and filler plate, no defects noted. Checked and lubed all control rods and flight controls. Placed aircraft on jacks, replaced Rt mlg tire. Replaced shock discs, rotors, and brake linings on both Lt and Rt mlg. Performed retraction tests and emergency extension. Lubed gear doors, retraction control rods and pivot points. Inspected and tested ELT IAW 91.207(D) This aircraft has been inspected IAW an annual inspection and found to be airworthy at this time.

4/12/2013 Aircraft Total Time: 2778.0 Tach: 719.2

Complied with annual inspection IAW FAA part 43 appendix D and manufacturers maintenance manual. Removed all inspection panels for inspection. Reviewed all AD's, Checked and lubed all control rods and flight controls. Replaced fuel indicator on right wing tank and baggage door hardware. Replaced Rapco Vacuum instrument filter P/N RA-D9 behind instrument panel. Removed JPI engine monitor for repair and reinstalled. Removed Honeywell Flight Director KI-256 Ser no 17872 for overhaul and reinstalled. Placed aircraft on jacks, replaced nose gear shock discs P/N J11968-14, performed retraction tests and emergency extension. Lubed gear doors, retraction control rods and pivot points. Inspected and tested ELT IAW 91.207(D) This aircraft has been inspected

IAW an annual inspection and found to be airworthy at this time.

R **Infelled** 2

pe airworthy at this time.

P Juffella 28-35988 A11 IA

ATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		TOTAL brough	nt forward from previous page
9000		I I	
5/	/03/2014	Aircraft	Total Time: 2811.4 Tach: 752.6
the co El rep air wl ex Ar	aintenance rough 12- ontrol rod ectronics pair and re- reraft batte heel Pn 4 tension. L meri-king	e manual. Re 05-09. Comp s and flight International einstalled. Ro ery with Con 0-87. Placed ubed gear do AK 451, 40 been inspects	inspection IAW FAA part 43 appendix D and manufacturers moved all inspection panels for inspection. Reviewed all AD's plied with Bendix switch AD 76-07-12. Checked and lubed all controls. Removed and replaced left main tire. Removed Tach for repair and reinstalled. Removed fuel flow indicator for epair tags located within owner logs. Removed and replaced gill corde RG-35axe direct replacement battery. Replaced nose gear aircraft on jacks, performed retraction tests and emergency ors, retraction control rods and pivot points. Inspected and tested 6 ELT IAW 91.207(D) battery due replacement 5/2015 This ed IAW an annual inspection and found to be airworthy at this
tin	ne. 🎏	Rulse	My IA # 28-35 88-8
			7.0
	1		Name - Na
18/09	/2014 Tag	ch: 764.3	
ound or da	metal two	eezers laying	from under instrument panel. Inspected panel from under side and on instrument switches, removed tweezers and inspected switches. Performed engine run-up and checked operation of all electrical PILululu IAH 28 3588
	_		
			WO 23551 M20K SN 25-0784 N57055 TACH 794.6
-			flap actuator. Adjust up limit micro switch. Operations check
		Troubleshoot	flap actuator. Adjust up limit micro switch. Operations check John Atterholt
		Troubleshoot good. A&P 328717	flap actuator. Adjust up limit micro switch. Operations check John Atterholt Craftsman
		Troubleshoot good. A&P 328717 Arizona Air-G	flap actuator. Adjust up limit micro switch. Operations check John Atterholt Craftsman

	TOTAL	FACH OR RECORDING	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
DATE	TIME N SERVICE		tem greyious page
_		TOTAL brow	ght forward from previous page
			,
three con eme Insp	mplied wi intenance ough 12-0 itrol rods a ergency e pected and eri-king P F control s again 5/2	th annual it manual. Re 5-09. Comp and flight c xtension. I I tested An N 11-06686 switch PN 0	nspection IAW FAA part 43 appendix D and manufacturer's moved all inspection panels for inspection. Reviewed all AD's moved all inspection panels for inspection. Reviewed all AD's filled with Bendix switch AD 76-07-12. Checked and lubed all controls. Placed aircraft on jacks, performed retraction tests and mubed gear doors, retraction control rods and pivot points, are liking AK 451, 406 ELT IAW 91.207(D) replaced battery in due replacement again 5/2020, also replaced lithium battery in CR 1/3N. Removed Oxygen bottle for hydro test and reinstalled and both fuel cap O-rings PN ms29513-338. Replaced intake air 125685-004 due again 5/2018. This aircraft has been inspected and found to be airworthy at this time.
N:		20 K Sn 2	
12.0	27/2016		Total Time: 2900.9 Tach: 842.1
Cor ma thr cor em Ins	omplied waintenance ough 12-0 ntrol rods ergency e pected an lacement 5	ith annual manual. Re 5-09. Comp and flight of extension. I d tested A	inspection IAW FAA part 43 appendix D and manufacturer's moved all inspection panels for inspection. Reviewed all AD's blied with Bendix switch AD 76-07-12. Checked and lubed all controls. Placed aircraft on jacks, performed retraction tests and subed gear doors, retraction control rods and pivot points. meri-king AK 451, 406 ELT IAW 91.207(D) Battery due aircraft has been inspected IAW an annual inspection and found e. Phulluly IA 28-35 98-8
Cor ma thr cor em Ins	omplied waintenance ough 12-0 ntrol rods ergency e pected an lacement 5	ith annual manual. Re 15-09. Comp and flight o extension. I d tested A: 5/2020, This	emoved all inspection panels for inspection. Reviewed all AD's blied with Bendix switch AD 76-07-12. Checked and lubed all controls. Placed aircraft on jacks, performed retraction tests and cubed gear doors, retraction control rods and pivot points. The principle of the princip

DATE TOTAL TACH OR RECORDING SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

TOTAL TIME RECORDING SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

TOTAL brought forward from previous page

N57055 M20 K Sn 25-0784

4/2/2017 Aircraft Total Time: 2936.5 Tach: 877.7

Complied with annual inspection IAW FAA part 43 appendix D and manufacturer's maintenance manual. Removed all inspection panels for inspection. Reviewed all AD's through AD 12-05-09. Complied with Bendix switch AD 76-07-12. Checked and lubed all control rods and flight controls. Removed speed brakes and for overhaul to Precise Flight reinstalled and checked operation FAA 8130-3 located in this book. Replaced Lt and Rt Fuel Cap O-rings P/N MS29513-338. Replaced vacuum instrument filter P/N RA D9-18-1. Placed aircraft on jacks, cleaned, inspected and greased wheel bearings Replaced Lt and Rt Brake cylinder seals (1EA) P/N MS28775-224, replaced Lt and Rt brake linings, (2EA) P/N RA66-105, Replaced seals in parking brake valve (3EA) P/N MS28775-010, (2EA) MS28775-012 performed retraction tests and emergency extension. Lubed gear doors, retraction control rods and pivot points. Inspected and tested Ameri-king AK 451, 406 ELT IAW 91.207(D) Battery due replacement 5/2020, This aircraft has been inspected IAW an annual inspection and found to be airworthy at this time.

RRallela IA 2835888

11.30-17 TACHTIME 926.3

AIRCRAFTSMAN REPLACED THE WP-1 DOWN
- ELECTRIC GEAR MOTORS. AND REPAIRED AN

D2 LEAK BY CHANGING THE PORT SERVICE

VALUE. THIS WORK WAS PERFORMED ON

11.30-17 TACH TIME OF 926.3 HRS.

N57055 M20 K Sn 25-0784

4/23/2018 Aircraft Total Time: 3005.2 Tach: 946.4

Complied with annual inspection IAW FAA part 43 appendix D and manufacturer's maintenance manual. Removed all inspection panels for inspection. Reviewed all AD's through AD 12-05-09. Complied with Bendix switch AD 76-07-12. performed retraction tests and emergency extension. Lubed gear doors, retraction control rods and pivot points. Inspected and tested Ameri-king AK 451, 406 ELT IAW 91.207(D) Battery due replacement 5/2020, This aircraft has been inspected IAW an annual inspection and found to be airworthy at this time.

DATE

TOTAL TIME IN SERVICE

TACH OR RECORDING METER TIME

DESCRIPTION OF WORK PERFORMED-SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

MAKE Mooney Aircraft Corp MODEL MOCK S/N 25-0784 REG NO N57055 WORK ORDER 20002



Legend Aviation LLC

2020 Clubhouse Drive Prescott, AZ 86301 Phone 928 717,1690

DATE: 5/6/2019 A/C TSN 3033 3 TACH 974 5

Airframe Entries

We.

(2) Installed Overhauded 02 bottle and Regulator assembly. PM: 801977-04 SN ST270379 by Compressed Gas Systems LLC, see form 8130-3 for details. Filled system with 1850ps: of 02 and rigged shutoff valve per Mooney M20K MM. Ground ops check good.

Technicians Who Worked On The Items Listed Above

Clare Boy

MANTENANCE RELEASE

The above identified aircraft, component or appliance has been repaired and inspected in accordance with current regulations of the Federal Aviation

Administration and is approved for return to service. Perment details are on file at this agency

Work Order: 26002

DATE: 5/6/2019

SIGNED ME Claire Boy, ASP, 418225

Printed by EBis 3 (datcomedia.com)

MAKE: Mooney Aircraft

MODEL: M20k S/N 25-0784 REG NO N57065 WORK ORDER 26132



Legend Aviation LLC

2020 Clubhouse Drive Prescot, AZ 86301 Phone 928 717.1680

DATE: 1/28/2020 A/C TSN 3059 5 TACH 1000.7

Airframe Entries

(1) Removed right caliper Cleaned and rebuilt right caliper with new oring PAL MS28775-224. Inspected rotor Installed new brake linings PAL 10500(Gy-2) with new nexts (Gy-4). Filled brake reservoir and bled brakes. Ops check good at this time

Technicians Who Worked On The Items Listed Above. Bill Samuelson, Chris Kahl

MAINTENANCE RELEASE

The above identified aircraft, component or app Administration and is approved for return to se

d and inspected in accordance with current regulations of the Federal Aviation • on file of this agency.

DATE: 1/28/2020


SIGNED 15206 Work Order: 26132

Printed by EBis 3 (datcomedia.com)

SUB-TOTAL this page

TOTAL-Carry forward to next page

MAKE: Mooney Aircraft Corp MODEL: M2DK S/N: 25-0784 BEG: NO: N57055 WORK ORDER: 26178



DATE 4/15/2020 A/C TSN 3061 6 TACH 1002 8

Airframe Entries

17

20

25

- Complied with and Annual Inspection IAW FAR 43 Appendix(d) using Legend Aviations Annual / 100Hr. Inspection checklist and manufactures maintenance manuals. Inspected and lubricated wings, tail, landing gear, Hingres, pubeys, rod ends, Cabin, Juselage and belicratis. Inspected Landing gear and vilveois, reported bearings and reinstalled: replaced instrument air filtors. Inspected the strainer bowl and screen. All applicable ADS complied with
- Removed Basic Aircraft Products, INC Turbo-Afternator system P.N. 50-2025-105 S.N. A1171, fabricated flush repair in accordance with Mooney M20K 51-00-00 and AC43 13 submitted Faa 337 Form for Removal Cf. STC# SA02431AT.
- Believed to be caused by low voltage, see item 15 for details, no action this visit.
- 8 Removed worn bolt and nut on prop governor rod end. Installed a new bolt P/N: AN3-11 and Nut P/N: AN320-3 with new cotter pin.
- 14 Installed hardware to bonding strap on Aspen EFD Antenna mount. No further action.
- 16 Found missing AGC1 Fuse and Broken Wire At Fuse holder for prop heat ammeter, installed Fuse And Re-Soldered Wire, Operational Check Normal.
- 7 Removed Left Torque Pressure Plate. Installed New Surplus Pressure Plate from KRN P/N: 075-01600 IAW Money MM 32-40-00.
- Troubleshot inop fail strobe, found Molex Connector had one pin disengaged, reengaged and performed operational check normal.
 Replaced loose elevator aft belicrank Bolt with new, Jound belicrank needs replaced, Replaced with serviceable belicrank P/N 913033-000, work performed
 - per Mooney NM 27-30-00.
 Cleaned and vacuumed F.O.D. in Empennage as Required.
- 23 Fabricated 2 aluminum reinforcement backing plates, installed onto lower cowl heat shield to attach to lower nose cowl.
- 24 Removed deteriorated and cracked fuel cap o-rings. Installed new (Qty.2) MS29513-338 and (Qty.2) MS29513-010 o-rings.
 - Removed Ameri-King 451 Elt, Installed ACK E-04 S/N 024817 Per Ack Installation Manual P/N E04M Rev date 03/24/2017 Tested Elt per FAR 91.207(D) Elt
- test and function normal, Battery Oue Date Aug 2023, Remote Battery Due 5 Years 4-2025, Elt Hex ID 2DC88 AC2AA FFBFF.

 Weight and Balance Updated and Installed In POH.

Technicians Who Worked On The Items Listed Above Chris Kahl, Eliot Cluff, Jesse Ruiz

- 27 Complied with A.D. 76-07-12 Bendix ignition switch test during Run Up, No defets Noted Next due at 100 hrs. Tach. 1102.8.
- 28 Removed broken RAM Vacuum Pump Cooling Shroud. Installed new McFarlane Vacuum Pump Cooling Shroud IAW. McFarlane Aviation Inc. STC#SA1074G and cooling shroud instructions drawing 7153. See form 337 for additional details.

TE: 4/15/2020	SIGNED Elliot CLM	Work Order: 26176	
	Elliot Cluff, IA: 601444958	Printed by EBis 3 (datcomedia.com)	
1	I I		
	SUB-TOTAL this page		