

“Can Tilting Pad Bearings Whirl?”

Talmadge D. Ward Jr.
Duke Energy Florida

Piedmont Chapter Vibration Institute Meeting
May 17, 2019 - Lake Junaluska N.C.

ABSTRACT

Intermittent Fluid Film Instability was observed on a GE 7A6 80 MW generator with tilting pad bearings which caused high vibration and sub-synchronous frequencies. Direct shaft vibration as measured by proximeter probes was above 10 mils. Cause was determined to be a combination of excessing bearing clearance, excessive pad pre-load and misalignment.

Background


This particular generator has been in operation since 1992 with no indication of fluid film instabilities. Four GE 7EA gas turbines with 7A6 generators were installed at that time and none have shown signs or symptoms of issues other than the occasional need to field balance the generator rotor. These units have both a Bently Nevada 3300 system using 2 orthogonal prox probes on each of the five bearings and a vibration protection system using Metrix 5485C high temperature velocity transducers. Operation has been typical for peaking combustion turbine units and routine scheduled minor and major outages have been performed. Both Generator bearings have 5 tilting pads, load on center and are of the single axis tilting variety.

Event

On February 15, 2016 at approximately 1500 hours I was walking between units 7 and 9 and noticed that the concrete pad was vibrating significantly. The vibration lasted only about 4 seconds and stopped only to restart about 8 seconds later. This cycle was observed several times and so I walked to unit 9 and the vibration became stronger. I entered the Non-Drive End (NDE) housing of the generator and the vibration of the structural was very high during the 4 seconds and then dissipated. Next, I checked the Bently 3300 panel and found that the Drive End (DE) vibration was modulating between 1 mil and 7 mils while the NDE was modulating between 2 mils and 10 mils – full scale range. Next, I installed a Bently Nevada ADRE system to capture the Orbit data. The orbits were stable during the “quite period” and greatly disturbed during the excited period.

Event (cont)

The installed vibration protection system, which uses transducers mounted on the bearing housings at TDC, showed very little increase in vibration during the events. This is likely due to the low frequency energy of the sub-synchronous problem and the inherent filtering of the velocity transducer. As a result, this unit had begun this abnormal behavior and excessive vibration pattern several weeks before, however It generated no vibration alarms by the protection system and so went unnoticed by operations. This emphasizes the need for prox probe monitoring systems, a gap in some monitoring strategies and the need for periodic local observation of critical equipment



Can Tilting Pad Bearings Whirl?

Babbitt As A Bearing Material

Invented by Isaac Babbitt (born July 26, 1799) in 1839. Called it a white metal alloy with excellent bearing properties. The original formula was 89.3% tin, 7.1% antimony and 3.6% copper. This alloy is still used today and sold as ASTM B-23 Grade 2 Babbitt, aka "Genuine Babbitt".

History Of Tilt Pad Bearings

Albert Kingsbury pioneered the tilting pad bearing for thrust bearing applications. His success is legendary. Consider reading the article of published in the October 2003 Sound and Vibration magazine https://www.kingsbury.com/pdf/albert_kingsbury.pdf

After his thrust bearing success in vertical machines the same concept was applied to radial bearings. Opinion – Without Mr. Babbitt and Mr. Kingsbury machinery reliability would be very poor. They changed the world.


Why They Work

Tilting pads, in either thrust or radial applications, work because the segments allow heated oil to escape and fresh cooler oil to enter the clearance gap. This doesn't allow the oil to circulate continuously in the clearance gap thus breaking up or stopping the sub-synchronous flow and forces that cause Whirl and Whip. Each pad segment also produces a force that lifts the shaft surface away from the bearing surface, just like radial bearings.

The oil wedge is critical to reliability of these bearings and diagnostics is best performed by prox probes, not casing sensors. Understanding the shaft centerline movement with load and speed help us identify overall bearing health and find misalignment as well as other issues.

Oil Wedge


The oil wedge is key to the babbit bearing performance. Many think that, with proper lubrication, a correctly designed babbit bearing has almost infinite life, unlike rolling element bearings.



FROM - Tilting Pad Bearing Overview - <http://wiki.vintagemachinery.org/BabbittWhatIsIt.ashx>

Important Term

Preload – Basically the difference of shaft radius and pad radius. This causes the pad to rock or tilt when the oil wedge is present.




$$R_b = R + c_b$$

$R_p =$ PAD RADIUS
OF CURVATURE

$$\text{PRELOAD} = m = 0$$

$$R_p = R_b$$

Figure 14. Zero Preloaded Tilting Pad.



c_p = PAD CLEARANCE

Tilt Pad Advantages:

Damping and Stability – designs can be alter to compensate for rotor design issues by shifting rotor critical speeds or reducing the amplification factor to reach an acceptable vibration level.

Disadvantages – Complexity, cost, and a much more involved repair processes.


Whirl and Whip

Whirl is more common than Whip and is caused by the rotation velocity of the oil within the annular clearance created by the shaft journal and bearing inside diameter. It tends to be seen at a fraction of shaft speed – 0.42 to 0.48% and can generate very high and destructive forces. Whip occurs when the sub-synchronous frequency coincides with a rotor critical and is both highly destructive and rare.

See Article by Jim Berry - <https://www.machinerylubrication.com/Read/754/oil-whirl-whip>

Tangential Force

- In a properly loaded bearing, the tangential force is low
- For a rotor improperly loaded, as speed increases, tangential forces become stronger while spring and damping forces do not. High tangential forces generate fluid instability




Click to animate


Example of Elliptical Bearing Whirl GE 7EA with misalignment


May 26, 2006

35 mils

Shook the control room 250 ft. away.








Diagnostic Steps

My initial theory was a fluid film instability based on previous experience with a GE 7B gas turbine that displayed similar intermittent “Shakes the Earth” vibration some 10 years prior. However, following the easiest and cheapest approach to diagnostics and correction, other causes were considered. Top of this list is a rotor rub at the air or oil deflectors of the generator bearings. Looking at the Polar data this seemed reasonable. We considered oil temperature as a contributing cause but the running temperature was well within the normal range for this and other units. In fact it usually ran at the top end of the temperature range. Cold oil is considered a contributor to Whirl and Whip but this was not our condition. Unbalance was not considered a possible cause since the vibration levels were low during the quiet periods. Pad flutter was also considered however we found little diagnostic information to help this pursue this theory.

TREND PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vib

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 5 GEN BRG #1A $\angle 45^\circ$ Left DIRECT 3.78 mil pp
MACHINE: 5 GEN BRG #1A 15FEB2016
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup 15:14:51.0



COMMENTS


Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16

TREND PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 6 GEN BRG #1B $\angle 45^\circ$ Right DIRECT
MACHINE: 6 GEN BRG #1B
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup

6.16 mil pp
15FEB2016
15:14:51.0




COMMENTS

Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16

TREND PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 7 GEN BRG #2A /45° Left DIRECT
MACHINE: 7 GEN BRG #2A
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup
3.45 mil pp
15FEB2016
15:14:51.0



COMMENTS

Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Frenq VIBs; B channels are Right Side; TDW 2/15/16


SENTINEL
NEVADIAN

TREND PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 8 GEN BRG #2B $\angle 45^\circ$ Right DIRECT
MACHINE: 8 GEN BRG #2B
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup

4.16 mil pp
15FEB2016
15:14:51.0



COMMENTS


Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16

POLAR PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 5 GEN BRG #1A $\angle 45^\circ$ Left 1X UNCOMP
MACHINE: 5 GEN BRG #1A
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup

1.06 $\angle 167^\circ$ @3600 rpm



2 mil pp FULL SCALE

CCW ROTATION

COMMENTS


Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16

POLAR PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 6 GEN BRG #1B $\angle 45^\circ$ Right 1X UNCOMP
MACHINE: 6 GEN BRG #1B
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup

2.10 $\angle 151^\circ$ @3600 rpm



5 mil pp FULL SCALE


CCW ROTATION

COMMENTS

Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16

POINT: 7 GEN BRG #2A $\angle 45^\circ$ Left 1X UNCOMP
MACHINE: 7 GEN BRG #2A
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup

0.267 $\angle 270^\circ$ @3600 rpm



2 mil pp FULL SCALE

CCW ROTATION

COMMENTS


Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16

POLAR PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 8 GEN BRG #2B $\angle 45^\circ$ Right 1X UNCOMP
MACHINE: 8 GEN BRG #2B
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup

2.00/ $\angle 345^\circ$ @3600 rpm



5 mil pp FULL SCALE

CCW ROTATION


COMMENTS

Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16

FULL SPECTRUM WATERFALL PLOT
COMPANY: Duke Energy
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: IC P-9
JOB REFERENCE: 2/15/16

POINT: 5 GEN BRG #1A $\angle 45^\circ$ Left
POINT: 6 GEN BRG #1B $\angle 45^\circ$ Right
MACHINE: 5 GEN BRG #1A
From 15FEB2016 15:14:51.1 To 01JAN1980 00:00:00.0 Startup 15:59:17.2
WINDOW: Hanning SPECTRAL LINES: 400 RESOLUTION: 75 CPM




COMMENTS
Session started with Database: 15 Feb 16 - 15:14:51. IC P-9 GENERATOR LF VIBs; B channels are Right Side; TDW 2/15/16

FULL SPECTRUM WATERFALL PLOT
COMPANY: Duke Energy
MACHINE TRAIN: Gen Vibs

PLOT NO. _____
PLANT: IC P-9
JOB REFERENCE: 2/15/16

POINT: 7 GEN BRG #2A $\angle 45^\circ$ Left
POINT: 8 GEN BRG #2B $\angle 45^\circ$ Right
MACHINE: 7 GEN BRG #2A
From 15FEB2016 15:14:51.1 To 01JAN1980 00:00:00.0 Startup 15:59:17.2
WINDOW: Hanning SPECTRAL LINES: 400 RESOLUTION: 75 CPM




COMMENTS
Session started with Database: 15 Feb 16 - 15:14:51. IC P-9 GENERATOR LF VIBs; B channels are Right Side; TDW 2/15/16

SHAFT AVERAGE CENTERLINE PLOT
COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vib

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

POINT: 5 GEN BRG #1A /45° Left REF: -9.38 Volts
POINT: 6 GEN BRG #1B /45° Right REF: -9.31 Volts
MACHINE: 5 GEN BRG #1A
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup
(not orbit or polar plot)

0
0
(0, 0) 3600



0.2 mil /div

COMMENTS

Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16


BRUNNEN
NEVADA

COMPANY: 7A6 Generator
MACHINE TRAIN: Gen Vibs

POINT: 7 GEN BRG #2A /45° Left REF: -9.24 Volts
POINT: 8 GEN BRG #2B /45° Right REF: -9.09 Volts
MACHINE: 7 GEN BRG #2A
From 15FEB2016 15:14:51.1 To 15FEB2016 16:05:22.2 Startup
(not orbit or polar plot)

PLOT NO. _____
PLANT: Tilt
JOB REFERENCE: 2/15/16

0
0
(0, 0) 3600



COMMENTS

Session started with Database: 15 Feb 16 - 15:14:51. P-9 GENERATOR Low Freq VIBs; B channels are Right Side; TDW 2/15/16


Outage Inspection Results

The unit was inspected the following day and in fact the NDE air seal was rubbing more than 180 degrees around and included both 90 degree left and right locations. These rubs were cleared and the unit retested however no change was observed. The unit was placed in a “Last On and First Off” operating scheme to minimize the potential damage. Numerous meetings and discussions were had with staff, vendors and experts during the following weeks to confirm a diagnosis and develop a plan. This plan would include capturing as found alignment and bearing data. During this time the unit remained in service and it was noted that the excited period was lasting longer and the quiet period was getting shorter. The possibility of no quiet period was then realized.


Inspection Results

Alignment - The Turbine to Generator alignment was found out of spec by 122 mils with the generator high and 132 to the right with the coupling faces open 6 mils at the bottom. Final alignment was Gen 6 mils high and “Fair” on horizontal and 11 mils open at the top.

Bearings - Radial clearances were checked using a Bearing Mandrel and found to be 28 mils instead of 21 mils, oversized by 7 mils. The “Preload” was also out of spec.



Can Tilting Pad Bearings Whirl?







Can Tilting Pad Bearings Whirl?

Corrections Made

All parameters were restored to within GE specification and the unit reassembled for testing

Post Maintenance Test

The unit was started and brought to full load. The generator vibration was well within limits and no instability was observed

Other Industry Experience

Since this sub-synchronous event another GE 7A6 generator at the Sheridan Road plant in NJ, operated by Calpine, suffered a similar problem (May of 2018). Using the knowledge gained on Unit 9 their contractor, TOPS, quickly diagnosed and then solved the issue.

In the future I would recommend only an alignment check and correction as a first step to ensure that the Generator drive end bearing is sufficiently loaded.

Questions?