

Serving Colorado – (Mailing Address)  
1301 Arapahoe St. #105  
Golden, CO 80401  
(303) 394-9181  
www.reservestudy.com



ASSOCIATION  
RESERVES™

Serving Utah  
159 Broadway Suite 200-147  
Salt Lake City, UT 84101  
(877) 344-8868  
www.reservestudy.com

*Planning For The Inevitable™*



## The Boundary Carbondale, CO



Report #: 22010-1  
Beginning: January 1, 2025  
Expires: December 31, 2025

# RESERVE STUDY

## Update "With-Site-Visit"

January 20, 2025

# Welcome to your Reserve Study!

**A** Reserve Study is a valuable tool to help you budget responsibly for your property. This report contains all the information you need to avoid surprise expenses, make informed decisions, save money, and protect property values.

**R**egardless of the property type, it's a fact of life that the very moment construction is completed, every major building component begins a predictable process of physical deterioration. The operative word is "predictable" because planning for the inevitable is what a Reserve Study by **Association Reserves** is all about!

In this Report, you will find three key results:

- **Component List**

Unique to each property, the Component List serves as the foundation of the Reserve Study and details the scope and schedule of all necessary repairs & replacements.

- **Reserve Fund Strength**

A calculation that measures how well the Reserve Fund has kept pace with the property's physical deterioration.

- **Reserve Funding Plan**

A multi-year funding plan based on current Reserve Fund strength that allows for component repairs and replacements to be completed in a timely manner, with an emphasis on fairness and avoiding "catch-up" funding.

## Questions?

Please contact your Project Manager directly.



[www.reservestudy.com](http://www.reservestudy.com)

The logo used within this report is the registered trademark of Association Reserves, Inc., All rights reserved.

## Table of Contents

<b>Executive Summary</b>	<b>4</b>
Executive Summary (Component List)	5
<b>Introduction, Objectives, and Methodology</b>	<b>6</b>
Which Physical Assets are Funded by Reserves?	7
How do we establish Useful Life and Remaining Useful Life estimates?	7
How do we establish Current Repair/Replacement Cost Estimates?	7
How much Reserves are enough?	8
How much should we transfer to Reserves?	9
What is our Recommended Funding Goal?	9
<b>Site Inspection Notes</b>	<b>10</b>
<b>Projected Expenses</b>	<b>11</b>
Annual Reserve Expenses Graph	11
<b>Reserve Fund Status &amp; Recommended Funding Plan</b>	<b>12</b>
Annual Reserve Funding Graph	12
30-Yr Cash Flow Graph	13
Percent Funded Graph	13
<b>Table Descriptions</b>	<b>14</b>
Reserve Component List Detail	15
Fully Funded Balance	16
Component Significance	17
30-Year Reserve Plan Summary	18
30-Year Income/Expense Detail	19
<b>Accuracy, Limitations, and Disclosures</b>	<b>25</b>
<b>Terms and Definitions</b>	<b>26</b>
<b>Component Details</b>	<b>27</b>
Sites and Grounds	28
Building Exteriors	32
Mechanicals	54



### The Boundary

Carbondale, CO

Level of Service: **Update "With-Site-Visit"**

Report #: **22010-1**

# of Units: **33**


**January 1, 2025 through December 31, 2025**

### Findings & Recommendations

as of January 1, 2025

Starting Reserve Balance	\$172,000
Fully Funded Reserve Balance	\$1,337,159
Annual Rate (Cost) of Deterioration	\$162,167
Percent Funded	12.9 %
Recommended 2025 Annual "Fully Funding" Reserve Transfers	\$230,000
Alternate/Baseline Annual Minimum Transfers to Keep Reserves Above \$0	\$119,000
Recommended 2025 Special Assessments for Reserves	\$0
Most Recent Annual Reserve Transfer Rate	\$70,909

**Reserve Fund Strength: 12.9%**



**Risk of Special Assessment:**

### Economic Assumptions:

Net Annual "After Tax" Interest Earnings Accruing to Reserves	1.50 %
Annual Inflation Rate	3.00 %

- This Update "With-Site-Visit" is based on a prior Reserve Study for your 2022 Fiscal Year. We performed the site inspection on 12/12/2024.
- The Reserve Study was reviewed by a credentialed Reserve Specialist (RS).
- Your Reserve Fund is currently 12.9 % Funded. This means the client's special assessment & deferred maintenance risk is currently High.
- Based on this starting point and your anticipated future expenses, our recommendation is to budget the Annual Reserve transfers at \$230,000 with 3% annual increases in order to be within the 70% to 130% level as noted above. 100% "Full" transfer rates are designed to achieve these funding objectives by the end of our 30-year report scope.
- The goal of the Reserve Study is to help the client offset the inevitable annual deterioration of the common area components. The Reserve Study will guide the client to establish an appropriate Reserve transfer rate that offsets the annual deterioration of the components and 'keeps pace' with the rate of ongoing deterioration. No assets appropriate for Reserve designation were excluded. See the appendix for component details; the basis of our assumptions.
- We recommend that this Reserve Study be updated annually, with a With-Site-Visit Reserve Study every three years. Clients that update their Reserve Study annually with a No-Site-Visit Reserve Study reduce their risk of special assessment by ~ 35%.
- Please watch this 5-minute video to understand the key results of a Reserve Study - <https://youtu.be/u83t4BRRIRE>

# Component	Useful Life (yrs)	Rem. Useful Life (yrs)	Current Average Cost
<b>Sites and Grounds</b>			
21050 Driveway Concrete - Repair - 5%	5	1	\$7,450
21090 Concrete Patio/Walkways Repair - 5%	5	0	\$7,750
21190 Asphalt - Seal/Repair	4	0	\$6,400
21200 Asphalt - Resurface	25	12	\$110,000
<b>Building Exteriors</b>			
23020 Ext. Lights (Decorative) - Replace	25	12	\$46,000
23180 Trex Decks - Replace	25	9	\$18,500
23190 Wood Deck - Seal/Repair	3	0	\$4,300
23200 Wood Deck - Resurface/Restore	25	9	\$46,000
23220 Balcony Rails - Paint	5	0	\$15,000
23230 Balcony Rails - Replace	40	27	\$50,500
23310 Wood Siding – Paint/Repair (Ph 1)	5	4	\$35,000
23310 Wood Siding – Paint/Repair (Ph 2)	5	2	\$33,600
23310 Wood Siding – Paint/Repair (Ph 3)	5	0	\$85,750
23310 Wood Siding – Paint/Repair (Ph 4)	5	2	\$32,950
23320 Wood Siding – Replace (Ph 1)	50	26	\$532,800
23320 Wood Siding – Replace (Ph 2)	50	33	\$487,600
23320 Wood Siding – Replace (Ph 3)	50	43	\$1,137,800
23320 Wood Siding – Replace (Ph 4)	50	47	\$273,050
23410 Metal Siding - Repair/Replace	60	36	\$185,000
23570 Comp. Shingle Roof - Replace (Ph 1)	20	17	\$152,700
23570 Metal Roof - Replace (Ph 1)	30	6	\$61,500
23571 Comp. Shingle Roof - Replace (Ph 2)	20	19	\$127,100
23571 Metal Roof - Replace (Ph 2)	30	13	\$49,000
23573 Comp. Shingle Roof - Replace (Ph 3)	20	13	\$435,000
23573 Metal Roof - Replace (Ph 3)	30	23	\$101,500
23574 Comp. Shingle Roof - Replace (Ph 4)	20	16	\$185,000
23650 Gutters/Downspouts - Replace	30	6	\$40,500
<b>Mechanicals</b>			
25570 Irrigation Clocks - Replace	15	7	\$6,550

**28 Total Funded Components**

## Introduction



A Reserve Study is the art and science of anticipating, and preparing for, an association's major common area repair and replacement expenses. Partially art, because in this field we are making projections about the future. Partially science, because our work is a combination of research and well-defined computations, following consistent National Reserve Study Standard principles.

The foundation of this and every Reserve Study is your Reserve Component List (what you are reserving for). This is because the Reserve Component List defines the *scope and schedule* of all your anticipated upcoming Reserve projects. Based on that List and your starting balance, we calculate the association's Reserve Fund Strength (reported in terms of "Percent Funded"). Then we compute a Reserve Funding Plan to provide for the Reserve needs of the association. These form the three results of your Reserve Study.



Reserve funding is not "for the future". Ongoing Reserve transfers are intended to offset the ongoing, daily deterioration of your Reserve assets. Done well, a stable, budgeted Reserve Funding Plan will collect sufficient funds from the owners who enjoyed the use of those assets, so the association is financially prepared for the irregular expenditures scattered through future years when those projects eventually require replacement.

## Methodology




For this [Update With-Site-Visit Reserve Study](#), we started with a review of your prior Reserve Study, then looked into recent Reserve expenditures, evaluated how expenditures are handled (ongoing maintenance vs Reserves), and researched any well-established association

precedents. We performed an on-site inspection to evaluate your common areas, updating and adjusting your Reserve Component List as appropriate.

### *Which Physical Assets are Funded by Reserves?*

There is a national-standard three-part test to determine which projects should appear in a Reserve Component List. First, it must be a common area maintenance obligation. Second, both the need and schedule of a component's project can be reasonably anticipated. Third, the project's total cost is material to the client, can be reasonably anticipated, and includes all direct and related costs. A project cost is commonly considered *material* if it is more than 0.5% to 1% of the total annual budget. This limits Reserve components to major, predictable expenses. Within this framework, it is inappropriate to include *lifetime* components, unpredictable expenses (such as damage due to natural disasters and/or insurable events), and expenses more appropriately handled from the Operational budget.



### *How do we establish Useful Life and Remaining Useful Life estimates?*

- 1) Visual Inspection (observed wear and age)
- 2) Association Reserves database of experience
- 3) Client History (install dates & previous life cycle information)
- 4) Vendor Evaluation and Recommendation

### *How do we establish Current Repair/Replacement Cost Estimates?*

In this order...

- 1) Actual client cost history, or current proposals
- 2) Comparison to Association Reserves database of work done at similar associations
- 3) Vendor Recommendations
- 4) Reliable National Industry cost estimating guidebooks

## How much Reserves are enough?

Reserve adequacy is not measured in cash terms. Reserve adequacy is found when the *amount* of current Reserve cash is compared to Reserve component deterioration (the *needs of the association*). Having *enough* means the association can execute its projects in a timely manner with existing Reserve funds. Not having *enough* typically creates deferred maintenance or special assessments.

Adequacy is measured in a two-step process:

- 1) Calculate the *value of deterioration* at the association (called Fully Funded Balance, or FFB).
- 2) Compare that to the Reserve Fund Balance, and express as a percentage.



Each year, the *value of deterioration* at the association changes. When there is more deterioration (as components approach the time they need to be replaced), there should be more cash to offset that deterioration and prepare for the expenditure. Conversely, the *value of deterioration* shrinks after projects are accomplished. The *value of deterioration* (the FFB) changes each year, and is a moving but predictable target.

There is a high risk of special assessments and deferred maintenance when the Percent Funded is *weak*, below 30%. Approximately 30% of all associations are in this high risk range. While the 100% point is Ideal (indicating Reserve cash is equal to the *value of deterioration*), a Reserve Fund in the 70% - 130% range is considered strong (low risk of special assessment).

Measuring your Reserves by Percent Funded tells how well prepared your association is for upcoming Reserve expenses. New buyers should be very aware of this important disclosure!

## How much should we transfer to Reserves?



According to National Reserve Study Standards, there are four Funding Principles to balance in developing your Reserve Funding Plan. Our first objective is to design a plan that provides you with sufficient cash to perform your Reserve projects on time. Second, a stable rate of ongoing Reserve transfers is desirable because it keeps these naturally irregular expenses from unsettling the budget.

Reserve transfers that are evenly distributed over current and future owners enable each owner to pay their fair share of the association's Reserve expenses over the years. And finally, we develop a plan that is fiscally responsible and safe for Board members to recommend to their association. Remember, it is the Board's job to provide for the ongoing care of the common areas. Board members invite liability exposure when Reserve transfers are inadequate to offset ongoing common area deterioration.

### What is our Recommended Funding Goal?

Maintaining the Reserve Fund at a level equal to the *value* of deterioration is called "Full Funding" (100% Funded). As each asset ages and becomes "used up," the Reserve Fund grows proportionally. **This is simple, responsible, and our recommendation.** Evidence shows that associations in the 70 - 130% range *enjoy a low risk of special assessments or deferred maintenance.*



Allowing the Reserves to fall close to zero, but not below zero, is called Baseline Funding. Doing so allows the Reserve Fund to drop into the 0 - 30% range, where there is a high risk of special assessments & deferred maintenance. Since Baseline Funding still provides for the timely execution of all Reserve projects, and only the "margin of safety" is different, recommended Reserve transfers for Baseline Funding average only 10% to 15% less than Full Funding recommendations. Threshold Funding is the title of all other Cash or Percent Funded objectives *between* Baseline Funding and Full Funding.

## Site Inspection Notes

During our site visit on 12/12/2024 we visually inspected the common area assets and were able to see a majority of the common areas. Please see photo appendix for component details; the basis of our assumptions.



# Projected Expenses

While this Reserve Study looks forward 30 years, we have no expectation that all these expenses will all take place as anticipated. This Reserve Study needs to be updated annually because we expect the timing of these expenses to shift and the size of these expenses to change. We do feel more certain of the timing and cost of near-term expenses than expenses many years away. Please be aware of your near-term expenses, which we are able to project more accurately than the more distant projections. The figure below summarizes the projected future expenses as defined by your Reserve Component List. A summary of these expenses are shown in the 30-Year Reserve Plan Summary Table, while details of the projects that make up these expenses are shown in the 30-Year Income/Expense Detail.




Figure 1

Reserve Fund Status

As of 1/1/2025 your Reserve Fund balance is projected to be \$172,000 and your Fully Funded Balance is computed to be \$1,337,159 (see the Fully Funded Balance Table). The Fully Funded Balance represents the deteriorated value of your common area components. Comparing your Reserve Balance to your Fully Funded Balance indicates your Reserves are 12.9 % Funded.

Recommended Funding Plan

Based on your current Percent Funded and your near-term and long-term Reserve needs, we are recommending Annual budgeted transfers of \$230,000. The overall 30-Year Plan, in perspective, is shown below in the Annual Reserve Funding (Fig. 2). This same information is shown numerically in both the 30-Year Reserve Plan Summary Table and the 30-Year Income/Expense Detail.




Figure 2

The reserve balance under our recommended Full Funding Plan, an alternate Baseline Funding Plan, and at your current budgeted transfer rate, compared to your always—changing Fully Funded Balance target is shown in the 30-Yr Cash Flow (Fig. 3).




Figure 3

The information from Figure 3 is plotted on a Percent Funded scale in Figure 4. It is clear here to see how your Reserve Fund strength approaches the 100% Funded level under our recommended multi-yr Funding Plan. A client that has a percent funded level of <30% may experience an ~ 20%-60% chance risk of special assessment. A client that is between 30% and 70% may experience an ~ 20%-5% chance risk of special assessment. A client that has a percent funded of >70% may experience an ~ <1% chance risk of special assessment.




Figure 4



## Table Descriptions

Executive Summary is a summary of your Reserve Components

Reserve Component List Detail discloses key Component information, providing the foundation upon which the financial analysis is performed.

Fully Funded Balance shows the calculation of the Fully Funded Balance for each of your components, and their specific proportion related to the property total. For each component, the Fully Funded Balance is the fraction of life used up multiplied by its estimated Current Replacement Cost.

Component Significance shows the relative significance of each component to Reserve funding needs of the property, helping you see which components have more (or less) influence than others on your total Reserve funding requirements. The deterioration cost/yr of each component is calculated by dividing the estimated Current Replacement Cost by its Useful Life, then that component's percentage of the total is displayed.

30-Yr Reserve Plan Summary provides a one-page 30-year summary of the cash flowing into and out of the Reserve Fund, with a display of the Fully Funded Balance, Percent Funded, and special assessment risk at the beginning of each year.

30-Year Income/Expense Detail shows the detailed income and expenses for each of the next 30 years. This table makes it possible to see which components are projected to require repair or replacement in a particular year, and the size of those individual expenses.



# ComponentQuantityUseful LifeRem. Useful Life					Current Cost Estimate	
					Best Case	Worst Case
Sites and Grounds						
21050	Driveway Concrete - Repair - 5%	5% of ~ 10900 GSF	5	1	\$5,900	\$9,000
21090	Concrete Patio/Walkways Repair - 5%	5% of ~ 12000 GSF	5	0	\$6,600	\$8,900
21190	Asphalt - Seal/Repair	~ 36400 GSF	4	0	\$5,600	\$7,200
21200	Asphalt - Resurface	~ 36400 GSF	25	12	\$100,000	\$120,000
Building Exteriors						
23020	Ext. Lights (Decorative) - Replace	~ (170) Lights	25	12	\$37,000	\$55,000
23180	Trex Decks - Replace	~ 530 GSF	25	9	\$17,000	\$20,000
23190	Wood Deck - Seal/Repair	~ 1100 GSF	3	0	\$3,700	\$4,900
23200	Wood Deck - Resurface/Restore	~ 1100 GSF	25	9	\$43,000	\$49,000
23220	Balcony Rails - Paint	~ 540 LF	5	0	\$12,000	\$18,000
23230	Balcony Rails - Replace	~ 540 LF	40	27	\$48,000	\$53,000
23310	Wood Siding – Paint/Repair (Ph 1)	~ 24800 GSF	5	4	\$30,000	\$40,000
23310	Wood Siding – Paint/Repair (Ph 2)	~ 22700 GSF	5	2	\$31,600	\$35,600
23310	Wood Siding – Paint/Repair (Ph 3)	~ 64300 GSF	5	0	\$155,000	\$16,500
23310	Wood Siding – Paint/Repair (Ph 4)	~ 13700 GSF	5	2	\$31,500	\$34,400
23320	Wood Siding – Replace (Ph 1)	~ 24800 GSF	50	26	\$446,100	\$619,500
23320	Wood Siding – Replace (Ph 2)	~ 22700 GSF	50	33	\$408,200	\$567,000
23320	Wood Siding – Replace (Ph 3)	~ 64300 GSF	50	43	\$952,600	\$1,323,000
23320	Wood Siding – Replace (Ph 4)	~ 13700 GSF	50	47	\$228,600	\$317,500
23410	Metal Siding - Repair/Replace	~ 5300 GSF	60	36	\$170,000	\$200,000
23570	Comp. Shingle Roof - Replace (Ph 1)	~ 15300 GSF	20	17	\$130,100	\$175,300
23570	Metal Roof - Replace (Ph 1)	~ 5700 GSF	30	6	\$49,000	\$74,000
23571	Comp. Shingle Roof - Replace (Ph 2)	~ 12200 GSF	20	19	\$120,100	\$134,100
23571	Metal Roof - Replace (Ph 2)	~ 4500 GSF	30	13	\$39,000	\$59,000
23573	Comp. Shingle Roof - Replace (Ph 3)	~ 28600 GSF	20	13	\$370,000	\$500,000
23573	Metal Roof - Replace (Ph 3)	~ 9500 GSF	30	23	\$83,000	\$120,000
23574	Comp. Shingle Roof - Replace (Ph 4)	~ 12000 GSF	20	16	\$160,000	\$210,000
23650	Gutters/Downspouts - Replace	~ 2000 LF	30	6	\$36,000	\$45,000
Mechanicals						
25570	Irrigation Clocks - Replace	~ (10) Controllers	15	7	\$6,000	\$7,100

28 Total Funded Components



#	Component	Current Cost Estimate	X	Effective Age	/	Useful Life	=	Fully Funded Balance
<b>Sites and Grounds</b>								
21050	Driveway Concrete - Repair - 5%	\$7,450	X	4	/	5	=	\$5,960
21090	Concrete Patio/Walkways Repair - 5%	\$7,750	X	5	/	5	=	\$7,750
21190	Asphalt - Seal/Repair	\$6,400	X	4	/	4	=	\$6,400
21200	Asphalt - Resurface	\$110,000	X	13	/	25	=	\$57,200
<b>Building Exteriors</b>								
23020	Ext. Lights (Decorative) - Replace	\$46,000	X	13	/	25	=	\$23,920
23180	Trex Decks - Replace	\$18,500	X	16	/	25	=	\$11,840
23190	Wood Deck - Seal/Repair	\$4,300	X	3	/	3	=	\$4,300
23200	Wood Deck - Resurface/Restore	\$46,000	X	16	/	25	=	\$29,440
23220	Balcony Rails - Paint	\$15,000	X	5	/	5	=	\$15,000
23230	Balcony Rails - Replace	\$50,500	X	13	/	40	=	\$16,413
23310	Wood Siding – Paint/Repair (Ph 1)	\$35,000	X	1	/	5	=	\$7,000
23310	Wood Siding – Paint/Repair (Ph 2)	\$33,600	X	3	/	5	=	\$20,160
23310	Wood Siding – Paint/Repair (Ph 3)	\$85,750	X	5	/	5	=	\$85,750
23310	Wood Siding – Paint/Repair (Ph 4)	\$32,950	X	3	/	5	=	\$19,770
23320	Wood Siding – Replace (Ph 1)	\$532,800	X	24	/	50	=	\$255,744
23320	Wood Siding – Replace (Ph 2)	\$487,600	X	17	/	50	=	\$165,784
23320	Wood Siding – Replace (Ph 3)	\$1,137,800	X	7	/	50	=	\$159,292
23320	Wood Siding – Replace (Ph 4)	\$273,050	X	3	/	50	=	\$16,383
23410	Metal Siding - Repair/Replace	\$185,000	X	24	/	60	=	\$74,000
23570	Comp. Shingle Roof - Replace (Ph 1)	\$152,700	X	3	/	20	=	\$22,905
23570	Metal Roof - Replace (Ph 1)	\$61,500	X	24	/	30	=	\$49,200
23571	Comp. Shingle Roof - Replace (Ph 2)	\$127,100	X	1	/	20	=	\$6,355
23571	Metal Roof - Replace (Ph 2)	\$49,000	X	17	/	30	=	\$27,767
23573	Comp. Shingle Roof - Replace (Ph 3)	\$435,000	X	7	/	20	=	\$152,250
23573	Metal Roof - Replace (Ph 3)	\$101,500	X	7	/	30	=	\$23,683
23574	Comp. Shingle Roof - Replace (Ph 4)	\$185,000	X	4	/	20	=	\$37,000
23650	Gutters/Downspouts - Replace	\$40,500	X	24	/	30	=	\$32,400
<b>Mechanicals</b>								
25570	Irrigation Clocks - Replace	\$6,550	X	8	/	15	=	\$3,493
								\$1,337,159



## Component Significance

Report # 22010-1  
With-Site-Visit

#	Component	Useful Life (yrs)	Current Cost Estimate	Deterioration Cost/Yr	Deterioration Significance
<b>Sites and Grounds</b>					
21050	Driveway Concrete - Repair - 5%	5	\$7,450	\$1,490	0.92 %
21090	Concrete Patio/Walkways Repair - 5%	5	\$7,750	\$1,550	0.96 %
21190	Asphalt - Seal/Repair	4	\$6,400	\$1,600	0.99 %
21200	Asphalt - Resurface	25	\$110,000	\$4,400	2.71 %
<b>Building Exteriors</b>					
23020	Ext. Lights (Decorative) - Replace	25	\$46,000	\$1,840	1.13 %
23180	Trex Decks - Replace	25	\$18,500	\$740	0.46 %
23190	Wood Deck - Seal/Repair	3	\$4,300	\$1,433	0.88 %
23200	Wood Deck - Resurface/Restore	25	\$46,000	\$1,840	1.13 %
23220	Balcony Rails - Paint	5	\$15,000	\$3,000	1.85 %
23230	Balcony Rails - Replace	40	\$50,500	\$1,263	0.78 %
23310	Wood Siding – Paint/Repair (Ph 1)	5	\$35,000	\$7,000	4.32 %
23310	Wood Siding – Paint/Repair (Ph 2)	5	\$33,600	\$6,720	4.14 %
23310	Wood Siding – Paint/Repair (Ph 3)	5	\$85,750	\$17,150	10.58 %
23310	Wood Siding – Paint/Repair (Ph 4)	5	\$32,950	\$6,590	4.06 %
23320	Wood Siding – Replace (Ph 1)	50	\$532,800	\$10,656	6.57 %
23320	Wood Siding – Replace (Ph 2)	50	\$487,600	\$9,752	6.01 %
23320	Wood Siding – Replace (Ph 3)	50	\$1,137,800	\$22,756	14.03 %
23320	Wood Siding – Replace (Ph 4)	50	\$273,050	\$5,461	3.37 %
23410	Metal Siding - Repair/Replace	60	\$185,000	\$3,083	1.90 %
23570	Comp. Shingle Roof - Replace (Ph 1)	20	\$152,700	\$7,635	4.71 %
23570	Metal Roof - Replace (Ph 1)	30	\$61,500	\$2,050	1.26 %
23571	Comp. Shingle Roof - Replace (Ph 2)	20	\$127,100	\$6,355	3.92 %
23571	Metal Roof - Replace (Ph 2)	30	\$49,000	\$1,633	1.01 %
23573	Comp. Shingle Roof - Replace (Ph 3)	20	\$435,000	\$21,750	13.41 %
23573	Metal Roof - Replace (Ph 3)	30	\$101,500	\$3,383	2.09 %
23574	Comp. Shingle Roof - Replace (Ph 4)	20	\$185,000	\$9,250	5.70 %
23650	Gutters/Downspouts - Replace	30	\$40,500	\$1,350	0.83 %
<b>Mechanicals</b>					
25570	Irrigation Clocks - Replace	15	\$6,550	\$437	0.27 %
28	Total Funded Components			\$162,167	100.00 %



## 30-Year Reserve Plan Summary

Report # 22010-1  
With-Site-Visit

Fiscal Year Start: 2025

Net After Tax Interest:

1.50 %

Avg 30-Yr Inflation:

3.00 %

Reserve Fund Strength: as-of Fiscal Year Start Date

Projected Reserve Balance Changes

Year	Starting Reserve Balance	Fully Funded Balance	Percent Funded	Special Assmt Risk	% Increase In Annual		Reserve Funding	Reserve Funding	Loan or Special Assmts	Interest Income	Reserve Expenses
					Reserve	Funding					
2025	\$172,000	\$1,337,159	12.9 %	High	224.36 %		\$230,000	\$0	\$0	\$3,435	\$119,200
2026	\$286,235	\$1,421,530	20.1 %	High	3.00 %		\$236,900	\$0	\$0	\$6,054	\$7,674
2027	\$521,515	\$1,628,316	32.0 %	Medium	3.00 %		\$244,007	\$0	\$0	\$9,186	\$70,603
2028	\$704,106	\$1,781,649	39.5 %	Medium	3.00 %		\$251,327	\$0	\$0	\$12,497	\$4,699
2029	\$963,231	\$2,012,780	47.9 %	Medium	3.00 %		\$258,867	\$0	\$0	\$16,151	\$46,596
2030	\$1,191,653	\$2,213,166	53.8 %	Medium	3.00 %		\$266,633	\$0	\$0	\$19,062	\$125,781
2031	\$1,351,567	\$2,343,643	57.7 %	Medium	3.00 %		\$274,632	\$0	\$0	\$21,462	\$135,823
2032	\$1,511,837	\$2,473,499	61.1 %	Medium	3.00 %		\$282,871	\$0	\$0	\$24,291	\$89,904
2033	\$1,729,096	\$2,660,532	65.0 %	Medium	3.00 %		\$291,357	\$0	\$0	\$28,255	\$8,107
2034	\$2,040,600	\$2,943,590	69.3 %	Medium	3.00 %		\$300,098	\$0	\$0	\$32,064	\$135,435
2035	\$2,237,326	\$3,110,338	71.9 %	Low	3.00 %		\$309,101	\$0	\$0	\$35,025	\$145,815
2036	\$2,435,637	\$3,277,937	74.3 %	Low	3.00 %		\$318,374	\$0	\$0	\$39,113	\$10,313
2037	\$2,782,811	\$3,596,865	77.4 %	Low	3.00 %		\$327,925	\$0	\$0	\$41,995	\$332,559
2038	\$2,820,173	\$3,600,384	78.3 %	Low	3.00 %		\$337,763	\$0	\$0	\$39,778	\$710,770
2039	\$2,486,943	\$3,221,595	77.2 %	Low	3.00 %		\$347,896	\$0	\$0	\$39,789	\$52,941
2040	\$2,821,687	\$3,516,366	80.2 %	Low	3.00 %		\$358,333	\$0	\$0	\$43,996	\$175,739
2041	\$3,048,277	\$3,701,077	82.4 %	Low	3.00 %		\$369,082	\$0	\$0	\$46,417	\$319,096
2042	\$3,144,681	\$3,751,479	83.8 %	Low	3.00 %		\$380,155	\$0	\$0	\$47,630	\$362,387
2043	\$3,210,080	\$3,766,844	85.2 %	Low	3.00 %		\$391,560	\$0	\$0	\$51,385	\$7,320
2044	\$3,645,704	\$4,156,671	87.7 %	Low	3.00 %		\$403,306	\$0	\$0	\$55,962	\$284,243
2045	\$3,820,729	\$4,281,493	89.2 %	Low	3.00 %		\$415,406	\$0	\$0	\$59,276	\$207,522
2046	\$4,087,889	\$4,497,869	90.9 %	Low	3.00 %		\$427,868	\$0	\$0	\$64,808	\$21,858
2047	\$4,558,706	\$4,921,021	92.6 %	Low	3.00 %		\$440,704	\$0	\$0	\$71,123	\$140,067
2048	\$4,930,466	\$5,244,434	94.0 %	Low	3.00 %		\$453,925	\$0	\$0	\$76,383	\$200,319
2049	\$5,260,454	\$5,525,091	95.2 %	Low	3.00 %		\$467,543	\$0	\$0	\$82,281	\$92,899
2050	\$5,717,379	\$5,934,701	96.3 %	Low	3.00 %		\$481,569	\$0	\$0	\$88,274	\$227,175
2051	\$6,060,047	\$6,228,481	97.3 %	Low	3.00 %		\$496,016	\$0	\$0	\$86,475	\$1,165,098
2052	\$5,477,440	\$5,575,505	98.2 %	Low	3.00 %		\$510,896	\$0	\$0	\$84,551	\$269,553
2053	\$5,803,335	\$5,836,158	99.4 %	Low	3.00 %		\$526,223	\$0	\$0	\$91,514	\$14,643
2054	\$6,406,430	\$6,378,319	100.4 %	Low	3.00 %		\$542,010	\$0	\$0	\$100,230	\$82,480

# 30-Year Income/Expense Detail

Report # 22010-1  
With-Site-Visit

Fiscal Year	2025	2026	2027	2028	2029
Starting Reserve Balance	\$172,000	\$286,235	\$521,515	\$704,106	\$963,231
Annual Reserve Funding	\$230,000	\$236,900	\$244,007	\$251,327	\$258,867
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$3,435	\$6,054	\$9,186	\$12,497	\$16,151
Total Income	\$405,435	\$529,189	\$774,709	\$967,930	\$1,238,249
# Component					
<b>Sites and Grounds</b>					
21050 Driveway Concrete - Repair - 5%	\$0	\$7,674	\$0	\$0	\$0
21090 Concrete Patio/Walkways Repair - 5%	\$7,750	\$0	\$0	\$0	\$0
21190 Asphalt - Seal/Repair	\$6,400	\$0	\$0	\$0	\$7,203
21200 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
<b>Building Exteriors</b>					
23020 Ext. Lights (Decorative) - Replace	\$0	\$0	\$0	\$0	\$0
23180 Trex Decks - Replace	\$0	\$0	\$0	\$0	\$0
23190 Wood Deck - Seal/Repair	\$4,300	\$0	\$0	\$4,699	\$0
23200 Wood Deck - Resurface/Restore	\$0	\$0	\$0	\$0	\$0
23220 Balcony Rails - Paint	\$15,000	\$0	\$0	\$0	\$0
23230 Balcony Rails - Replace	\$0	\$0	\$0	\$0	\$0
23310 Wood Siding - Paint/Repair (Ph 1)	\$0	\$0	\$0	\$0	\$39,393
23310 Wood Siding - Paint/Repair (Ph 2)	\$0	\$0	\$35,646	\$0	\$0
23310 Wood Siding - Paint/Repair (Ph 3)	\$85,750	\$0	\$0	\$0	\$0
23310 Wood Siding - Paint/Repair (Ph 4)	\$0	\$0	\$34,957	\$0	\$0
23320 Wood Siding - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding - Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23410 Metal Siding - Repair/Replace	\$0	\$0	\$0	\$0	\$0
23570 Comp. Shingle Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23570 Metal Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23571 Comp. Shingle Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23571 Metal Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23573 Comp. Shingle Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23573 Metal Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23574 Comp. Shingle Roof - Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23650 Gutters/Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
<b>Mechanicals</b>					
25570 Irrigation Clocks - Replace	\$0	\$0	\$0	\$0	\$0
Total Expenses	\$119,200	\$7,674	\$70,603	\$4,699	\$46,596
Ending Reserve Balance	\$286,235	\$521,515	\$704,106	\$963,231	\$1,191,653

Fiscal Year	2030	2031	2032	2033	2034
Starting Reserve Balance	\$1,191,653	\$1,351,567	\$1,511,837	\$1,729,096	\$2,040,600
Annual Reserve Funding	\$266,633	\$274,632	\$282,871	\$291,357	\$300,098
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$19,062	\$21,462	\$24,291	\$28,255	\$32,064
Total Income	\$1,477,348	\$1,647,661	\$1,819,000	\$2,048,708	\$2,372,762
# Component					
<b>Sites and Grounds</b>					
21050 Driveway Concrete - Repair - 5%	\$0	\$8,896	\$0	\$0	\$0
21090 Concrete Patio/Walkways Repair - 5%	\$8,984	\$0	\$0	\$0	\$0
21190 Asphalt - Seal/Repair	\$0	\$0	\$0	\$8,107	\$0
21200 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
<b>Building Exteriors</b>					
23020 Ext. Lights (Decorative) - Replace	\$0	\$0	\$0	\$0	\$0
23180 Trex Decks - Replace	\$0	\$0	\$0	\$0	\$24,138
23190 Wood Deck - Seal/Repair	\$0	\$5,134	\$0	\$0	\$5,611
23200 Wood Deck - Resurface/Restore	\$0	\$0	\$0	\$0	\$60,020
23220 Balcony Rails - Paint	\$17,389	\$0	\$0	\$0	\$0
23230 Balcony Rails - Replace	\$0	\$0	\$0	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 1)	\$0	\$0	\$0	\$0	\$45,667
23310 Wood Siding – Paint/Repair (Ph 2)	\$0	\$0	\$41,324	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 3)	\$99,408	\$0	\$0	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 4)	\$0	\$0	\$40,524	\$0	\$0
23320 Wood Siding – Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23410 Metal Siding - Repair/Replace	\$0	\$0	\$0	\$0	\$0
23570 Comp. Shingle Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23570 Metal Roof - Replace (Ph 1)	\$0	\$73,434	\$0	\$0	\$0
23571 Comp. Shingle Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23571 Metal Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23573 Comp. Shingle Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23573 Metal Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23574 Comp. Shingle Roof - Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23650 Gutters/Downspouts - Replace	\$0	\$48,359	\$0	\$0	\$0
<b>Mechanicals</b>					
25570 Irrigation Clocks - Replace	\$0	\$0	\$8,056	\$0	\$0
Total Expenses	\$125,781	\$135,823	\$89,904	\$8,107	\$135,435
Ending Reserve Balance	\$1,351,567	\$1,511,837	\$1,729,096	\$2,040,600	\$2,237,326

Fiscal Year	2035	2036	2037	2038	2039
Starting Reserve Balance	\$2,237,326	\$2,435,637	\$2,782,811	\$2,820,173	\$2,486,943
Annual Reserve Funding	\$309,101	\$318,374	\$327,925	\$337,763	\$347,896
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$35,025	\$39,113	\$41,995	\$39,778	\$39,789
Total Income	\$2,581,452	\$2,793,124	\$3,152,732	\$3,197,713	\$2,874,628
# Component					
<b>Sites and Grounds</b>					
21050 Driveway Concrete - Repair - 5%	\$0	\$10,313	\$0	\$0	\$0
21090 Concrete Patio/Walkways Repair - 5%	\$10,415	\$0	\$0	\$0	\$0
21190 Asphalt - Seal/Repair	\$0	\$0	\$9,125	\$0	\$0
21200 Asphalt - Resurface	\$0	\$0	\$156,834	\$0	\$0
<b>Building Exteriors</b>					
23020 Ext. Lights (Decorative) - Replace	\$0	\$0	\$65,585	\$0	\$0
23180 Trex Decks - Replace	\$0	\$0	\$0	\$0	\$0
23190 Wood Deck - Seal/Repair	\$0	\$0	\$6,131	\$0	\$0
23200 Wood Deck - Resurface/Restore	\$0	\$0	\$0	\$0	\$0
23220 Balcony Rails - Paint	\$20,159	\$0	\$0	\$0	\$0
23230 Balcony Rails - Replace	\$0	\$0	\$0	\$0	\$0
23310 Wood Siding - Paint/Repair (Ph 1)	\$0	\$0	\$0	\$0	\$52,941
23310 Wood Siding - Paint/Repair (Ph 2)	\$0	\$0	\$47,906	\$0	\$0
23310 Wood Siding - Paint/Repair (Ph 3)	\$115,241	\$0	\$0	\$0	\$0
23310 Wood Siding - Paint/Repair (Ph 4)	\$0	\$0	\$46,979	\$0	\$0
23320 Wood Siding - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding - Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23410 Metal Siding - Repair/Replace	\$0	\$0	\$0	\$0	\$0
23570 Comp. Shingle Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23570 Metal Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23571 Comp. Shingle Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23571 Metal Roof - Replace (Ph 2)	\$0	\$0	\$0	\$71,958	\$0
23573 Comp. Shingle Roof - Replace (Ph 3)	\$0	\$0	\$0	\$638,812	\$0
23573 Metal Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23574 Comp. Shingle Roof - Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23650 Gutters/Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
<b>Mechanicals</b>					
25570 Irrigation Clocks - Replace	\$0	\$0	\$0	\$0	\$0
Total Expenses	\$145,815	\$10,313	\$332,559	\$710,770	\$52,941
Ending Reserve Balance	\$2,435,637	\$2,782,811	\$2,820,173	\$2,486,943	\$2,821,687

Fiscal Year	2040	2041	2042	2043	2044
Starting Reserve Balance	\$2,821,687	\$3,048,277	\$3,144,681	\$3,210,080	\$3,645,704
Annual Reserve Funding	\$358,333	\$369,082	\$380,155	\$391,560	\$403,306
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$43,996	\$46,417	\$47,630	\$51,385	\$55,962
Total Income	\$3,224,016	\$3,463,777	\$3,572,466	\$3,653,024	\$4,104,973
# Component					
<b>Sites and Grounds</b>					
21050 Driveway Concrete - Repair - 5%	\$0	\$11,955	\$0	\$0	\$0
21090 Concrete Patio/Walkways Repair - 5%	\$12,074	\$0	\$0	\$0	\$0
21190 Asphalt - Seal/Repair	\$0	\$10,270	\$0	\$0	\$0
21200 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
<b>Building Exteriors</b>					
23020 Ext. Lights (Decorative) - Replace	\$0	\$0	\$0	\$0	\$0
23180 Trex Decks - Replace	\$0	\$0	\$0	\$0	\$0
23190 Wood Deck - Seal/Repair	\$6,699	\$0	\$0	\$7,320	\$0
23200 Wood Deck - Resurface/Restore	\$0	\$0	\$0	\$0	\$0
23220 Balcony Rails - Paint	\$23,370	\$0	\$0	\$0	\$0
23230 Balcony Rails - Replace	\$0	\$0	\$0	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 1)	\$0	\$0	\$0	\$0	\$61,373
23310 Wood Siding – Paint/Repair (Ph 2)	\$0	\$0	\$55,536	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 3)	\$133,596	\$0	\$0	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 4)	\$0	\$0	\$54,461	\$0	\$0
23320 Wood Siding – Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23410 Metal Siding - Repair/Replace	\$0	\$0	\$0	\$0	\$0
23570 Comp. Shingle Roof - Replace (Ph 1)	\$0	\$0	\$252,390	\$0	\$0
23570 Metal Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23571 Comp. Shingle Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$222,871
23571 Metal Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23573 Comp. Shingle Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23573 Metal Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23574 Comp. Shingle Roof - Replace (Ph 4)	\$0	\$296,871	\$0	\$0	\$0
23650 Gutters/Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
<b>Mechanicals</b>					
25570 Irrigation Clocks - Replace	\$0	\$0	\$0	\$0	\$0
Total Expenses	\$175,739	\$319,096	\$362,387	\$7,320	\$284,243
Ending Reserve Balance	\$3,048,277	\$3,144,681	\$3,210,080	\$3,645,704	\$3,820,729

Fiscal Year	2045	2046	2047	2048	2049
Starting Reserve Balance	\$3,820,729	\$4,087,889	\$4,558,706	\$4,930,466	\$5,260,454
Annual Reserve Funding	\$415,406	\$427,868	\$440,704	\$453,925	\$467,543
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$59,276	\$64,808	\$71,123	\$76,383	\$82,281
Total Income	\$4,295,411	\$4,580,565	\$5,070,533	\$5,460,774	\$5,810,278
# Component					
<b>Sites and Grounds</b>					
21050 Driveway Concrete - Repair - 5%	\$0	\$13,859	\$0	\$0	\$0
21090 Concrete Patio/Walkways Repair - 5%	\$13,997	\$0	\$0	\$0	\$0
21190 Asphalt - Seal/Repair	\$11,559	\$0	\$0	\$0	\$13,010
21200 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
<b>Building Exteriors</b>					
23020 Ext. Lights (Decorative) - Replace	\$0	\$0	\$0	\$0	\$0
23180 Trex Decks - Replace	\$0	\$0	\$0	\$0	\$0
23190 Wood Deck - Seal/Repair	\$0	\$7,999	\$0	\$0	\$8,741
23200 Wood Deck - Resurface/Restore	\$0	\$0	\$0	\$0	\$0
23220 Balcony Rails - Paint	\$27,092	\$0	\$0	\$0	\$0
23230 Balcony Rails - Replace	\$0	\$0	\$0	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 1)	\$0	\$0	\$0	\$0	\$71,148
23310 Wood Siding – Paint/Repair (Ph 2)	\$0	\$0	\$64,381	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 3)	\$154,874	\$0	\$0	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 4)	\$0	\$0	\$63,136	\$0	\$0
23320 Wood Siding – Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23410 Metal Siding - Repair/Replace	\$0	\$0	\$0	\$0	\$0
23570 Comp. Shingle Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23570 Metal Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23571 Comp. Shingle Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23571 Metal Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23573 Comp. Shingle Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23573 Metal Roof - Replace (Ph 3)	\$0	\$0	\$0	\$200,319	\$0
23574 Comp. Shingle Roof - Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23650 Gutters/Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
<b>Mechanicals</b>					
25570 Irrigation Clocks - Replace	\$0	\$0	\$12,550	\$0	\$0
Total Expenses	\$207,522	\$21,858	\$140,067	\$200,319	\$92,899
Ending Reserve Balance	\$4,087,889	\$4,558,706	\$4,930,466	\$5,260,454	\$5,717,379

Fiscal Year	2050	2051	2052	2053	2054
Starting Reserve Balance	\$5,717,379	\$6,060,047	\$5,477,440	\$5,803,335	\$6,406,430
Annual Reserve Funding	\$481,569	\$496,016	\$510,896	\$526,223	\$542,010
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$88,274	\$86,475	\$84,551	\$91,514	\$100,230
Total Income	\$6,287,222	\$6,642,539	\$6,072,888	\$6,421,072	\$7,048,670
# Component					
<b>Sites and Grounds</b>					
21050 Driveway Concrete - Repair - 5%	\$0	\$16,067	\$0	\$0	\$0
21090 Concrete Patio/Walkways Repair - 5%	\$16,227	\$0	\$0	\$0	\$0
21190 Asphalt - Seal/Repair	\$0	\$0	\$0	\$14,643	\$0
21200 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
<b>Building Exteriors</b>					
23020 Ext. Lights (Decorative) - Replace	\$0	\$0	\$0	\$0	\$0
23180 Trex Decks - Replace	\$0	\$0	\$0	\$0	\$0
23190 Wood Deck - Seal/Repair	\$0	\$0	\$9,552	\$0	\$0
23200 Wood Deck - Resurface/Restore	\$0	\$0	\$0	\$0	\$0
23220 Balcony Rails - Paint	\$31,407	\$0	\$0	\$0	\$0
23230 Balcony Rails - Replace	\$0	\$0	\$112,175	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 1)	\$0	\$0	\$0	\$0	\$82,480
23310 Wood Siding – Paint/Repair (Ph 2)	\$0	\$0	\$74,635	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 3)	\$179,541	\$0	\$0	\$0	\$0
23310 Wood Siding – Paint/Repair (Ph 4)	\$0	\$0	\$73,191	\$0	\$0
23320 Wood Siding – Replace (Ph 1)	\$0	\$1,149,032	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23320 Wood Siding – Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23410 Metal Siding - Repair/Replace	\$0	\$0	\$0	\$0	\$0
23570 Comp. Shingle Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23570 Metal Roof - Replace (Ph 1)	\$0	\$0	\$0	\$0	\$0
23571 Comp. Shingle Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23571 Metal Roof - Replace (Ph 2)	\$0	\$0	\$0	\$0	\$0
23573 Comp. Shingle Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23573 Metal Roof - Replace (Ph 3)	\$0	\$0	\$0	\$0	\$0
23574 Comp. Shingle Roof - Replace (Ph 4)	\$0	\$0	\$0	\$0	\$0
23650 Gutters/Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
<b>Mechanicals</b>					
25570 Irrigation Clocks - Replace	\$0	\$0	\$0	\$0	\$0
Total Expenses	\$227,175	\$1,165,098	\$269,553	\$14,643	\$82,480
Ending Reserve Balance	\$6,060,047	\$5,477,440	\$5,803,335	\$6,406,430	\$6,966,190



## Accuracy, Limitations, and Disclosures

Association Reserves and its employees have no ownership, management, or other business relationships with the client other than this Reserve Study engagement. Bryan Farley, R.S., president of the Colorado LLC, is a credentialed Reserve Specialist (#260). All work done by Association Reserves is performed under his Responsible Charge and is performed in accordance with National Reserve Study Standards (NRSS). There are no material issues to our knowledge that have not been disclosed to the client that would cause a distortion of the client's situation. Per NRSS, information provided by official representative(s) of the client, vendors, and suppliers regarding financial details, component physical details and/or quantities, or historical issues/conditions will be deemed reliable, and is not intended to be used for the purpose of any type of audit, quality/forensic analysis, or background checks of historical records. As such, information provided to us has not been audited or independently verified. Estimates for interest and inflation have been included, because including such estimates are more accurate than ignoring them completely. When we are hired to prepare Update reports, the client is considered to have deemed those previously developed component quantities as accurate and reliable, whether established by our firm or other individuals/firms (unless specifically mentioned in our Site Inspection Notes). During inspections our company standard is to establish measurements within 5% accuracy, and our scope includes visual inspection of accessible areas and components and does not include any destructive or other testing. Our work is done only for budget purposes. Uses or expectations outside our expertise and scope of work include, but are not limited to, project audit, quality inspection, and the identification of construction defects, hazardous materials, or dangerous conditions. Identifying hidden issues such as but not limited to plumbing or electrical problems are also outside our scope of work. Our estimates assume proper original installation & construction, adherence to recommended preventive maintenance, a stable economic environment, and do not consider frequency or severity of natural disasters. Our opinions of component Useful Life, Remaining Useful Life, and current or future cost estimates are not a warranty or guarantee of actual costs or timing. Because the physical and financial status of the property, legislation, the economy, weather, owner expectations, and usage are all in a continual state of change over which we have no control, we do not expect that the events projected in this document will all occur exactly as planned. This Reserve Study is by nature a "one-year" document in need of being updated annually so that more accurate estimates can be incorporated. It is only because a long-term perspective improves the accuracy of near-term planning that this Report projects expenses into the future. We fully expect a number of adjustments will be necessary through the interim years to the cost and timing of expense projections and the funding necessary to prepare for those estimated expenses.



## Terms and Definitions

<b>BTU</b>	British Thermal Unit (a standard unit of energy)
<b>DIA</b>	Diameter
<b>GSF</b>	Gross Square Feet (area). Equivalent to Square Feet
<b>GSY</b>	Gross Square Yards (area). Equivalent to Square Yards
<b>HP</b>	Horsepower
<b>LF</b>	Linear Feet (length)
<b>Effective Age</b>	The difference between Useful Life and Remaining Useful Life. Note that this is not necessarily equivalent to the chronological age of the component.
<b>Fully Funded Balance (FFB)</b>	The value of the deterioration of the Reserve Components. This is the fraction of life "used up" of each component multiplied by its estimated Current Replacement. While calculated for each component, it is summed together for an association total.
<b>Inflation</b>	Cost factors are adjusted for inflation at the rate defined in the Executive Summary and compounded annually. These increasing costs can be seen as you follow the recurring cycles of a component on the "30-yr Income/Expense Detail" table.
<b>Interest</b>	Interest earnings on Reserve Funds are calculated using the average balance for the year (taking into account income and expenses through the year) and compounded monthly using the rate defined in the Executive Summary. Annual interest earning assumption appears in the Executive Summary.
<b>Percent Funded</b>	The ratio, at a particular point in time (the first day of the Fiscal Year), of the actual (or projected) Reserve Balance to the Fully Funded Balance, expressed as a percentage.
<b>Remaining Useful Life (RUL)</b>	The estimated time, in years, that a common area component can be expected to continue to serve its intended function.
<b>Useful Life (UL)</b>	The estimated time, in years, that a common area component can be expected to serve its intended function.



## Component Details

The primary purpose of the photographic appendix is to provide the reader with the basis of our funding assumptions resulting from our physical analysis and subsequent research. The photographs herein represent a wide range of elements that were observed and measured against National Reserve Study Standards to determine if they meet the criteria for reserve funding:

- Client's obligation to maintain/replace existing elements.
- Schedule/need for projects can be reasonably anticipated. A component must have a "reasonably anticipated" limited useful life (this includes a component with an estimated life of greater than 30 years). The useful life limit does not have to be due to physical deterioration but may reach the end of its useful life due to esthetics (out of style), economic obsolescence (no longer energy efficient), or other reasons.
- The total cost for the project is material to the association, can be reasonably estimated, and includes direct/related costs. The next occurrence of the expense must be above a minimum threshold, reasonably estimated, and include all related costs. Material to the association because typically an expense less than ~1%-.5% of the total annual budget is best categorized by expensing the cost to the operating account. Reasonable estimated because unsupported "guesses" are inappropriate (it is random or unknowable), estimating what the expense will be can be valid if the estimate is provided by a qualified outside expert, based on the association's history (i.e., historical frequency or patterns of repairs), manufacture recommendations, etc.

Some components are recommended for reserve funding, while others are not. The components that meet these criteria in our judgment are shown with corresponding maintenance, repair or replacement cycles to the left of the photo (UL = Useful Life or how often the project is expected to occur, RUL = Remaining Useful Life or how many years from our reporting period) and a representative market cost range termed "Best Case" and "Worst Case" below the photo. Many factors can result in a wide variety of potential costs; we are attempting to represent a market average for budget purposes. Where there is no UL, the component is expected to be a one-time expense. Where no pricing, the component is deemed inappropriate for the Reserve Fund.

## Sites and Grounds

**Comp #: 21050 Driveway Concrete - Repair - 5%****Quantity: 5% of ~ 10900 GSF**

Location: Common Areas

Funded?: Yes.

History:

Comments: Concrete driveways determined to be in good condition typically exhibit smooth surfaces with positive slopes. Good consistent aesthetic condition. Driveways are reported to be the maintenance and repair responsibility of the client. Although complete replacement of all areas together should not be required conditions observed merit inclusion of an allowance for ongoing repairs and partial replacements. Exposure to sunlight weather and frequent vehicle traffic can lead to larger more frequent repairs especially for older properties. Inspect all areas periodically to identify trip hazards or other safety issues. Timeline and cost ranges shown here should be re-evaluated during future Reserve Study updates.

Useful Life:

5 years

Remaining Life:

1 years



Best Case: \$ 5,900

Worst Case: \$ 9,000

Cost Source: Allowance

**Comp #: 21090 Concrete Patio/Walkways Repair - 5%**

**Quantity: 5% of ~ 12000 GSF**

Location: Common Areas

Funded?: Yes.

History:

Comments: Walkways include (944 GSF) Buildings 1, 2, (336 GSF) Building 3, (720 GSF) Buildings 6, 7, 8, 9, 10, (482 GSF) Building 11. Patios include (1200 GSF) Front of Buildings 6, 7, 8, 9, 10, (4340 GSF) Rear of Buildings 6, 7, 8, 9, 10, (3712 GSF) Building 11, (256 GSF) Building 3. Concrete sidewalks and patios determined to be in fair condition typically exhibit minor changes in slope and a moderate percentage of cracking and surface wear. Trip hazards may be increasing in frequency and severity and should be closely monitored to prevent further risks. The Rocky Mountain Region is home to expansive soils. One of the causes of concrete damage in this type of soil moisture. Expansive soils tend to swell in size when wet and contract as they dry out. As the soil expands and contracts it can create enough force to cause major damage to sidewalks. Repair any trip and fall hazards immediately to ensure safety. As routine maintenance inspect regularly pressure wash for appearance and repair promptly as needed to prevent water penetrating into the base and causing further damage. In our experience larger repair/replacement expenses emerge as the community ages. Although difficult to predict timing cost and scope we suggest a rotating funding allowance to supplement the operating/maintenance budget for periodic larger repairs. Adjust as conditions actual expense patterns dictate within future reserve study updates.

Useful Life:  
5 years

Remaining Life:  
0 years



Best Case: \$ 6,600

Worst Case: \$ 8,900

Cost Source: Allowance

**Comp #: 21190 Asphalt - Seal/Repair****Quantity: ~ 36400 GSF**

Location: Common Areas

Funded?: Yes.

History:

Comments: Asphalt seal was observed to be in poor condition at the time of the inspection. The seal appeared to be weathered and faded. Exposed aggregate and a gravelly texture was noted. Plan to seal the asphalt soon. Regular cycles of seal coating (along with any needed repair) has proven to be the best program in our opinion for the long term care of lower traffic asphalt areas such as these. The primary reason to seal coat asphalt pavement is to protect the pavement from the deteriorating effects of sun and water. When asphalt pavement is exposed, the asphalt oxidizes, or hardens which causes the pavement to become more brittle. As a result, the pavement will be more likely to crack because it is unable to bend and flex when subjected to traffic and temperature changes. A seal coat combats this situation by providing a waterproof membrane, which not only slows down the oxidation process but also helps the pavement to shed water, preventing it from entering the base material. Seal coat also provides uniform appearance, concealing the inevitable patching and repairs which accumulate over time. Seal coat ultimately extends useful life of asphalt, postponing the asphalt resurfacing, which can be one of the larger cost items in this study (see component #21200 for asphalt resurfacing costs). Repair asphalt before seal coating. Surface preparation and dry weather, during and following application, is key to lasting performance. The ideal conditions are a warm, sunny day with low humidity rain can cause major problems when seal coating and should never be done when showers are threatening. Incorporate any striping and curb repair into this project. Fill cracks and clean oil stains promptly in between cycles as routine maintenance. Prior to a seal coat application, the areas will be cleaned with push blowers and wire brooms. Be aware that sealcoat will not adhere to heavily saturated oil spots. Vendors typically recommend infrared patching on areas with saturated oil spots to ensure adherence of sealcoat.

Useful Life:

4 years

Remaining Life:

0 years



Best Case: \$ 5,600

Worst Case: \$ 7,200

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 21200 Asphalt - Resurface****Quantity: ~ 36400 GSF**

Location: Common Areas

Funded?: Yes.

History:

Comments: Asphalt pavement determined to be in fair condition typically exhibits a mostly uniform surface but with minor to moderate raveling and surface wear. If present crack patterns are normal for the age of the asphalt and not extreme and there are no signs of advanced deterioration such as large block cracking patterns "alligatoring" or potholes. Overall appears to be aging normally and still up to an appropriate aesthetic standard. Useful life below assumes regular seal coating and repairs. The lack of seal coating and repairs can greatly decrease the asphalt's useful life. Resurfacing is typically one of the larger expense items in a reserve study. When need to resurface is apparent within a couple of years consult with geotechnical engineer for recommendations specifications / scope of work and project oversight. As routine maintenance keep surfaces clean and free of debris ensure that drains are free flowing repair cracks and clean oil stains promptly. Assuming proactive maintenance plan to resurface at roughly the time frame below. If regular maintenance and sealing is deferred client may need more extensive repair and replacement projects. Funding below assumes that asphalt has adequate subgrade as well as asphalt fill depth. If fill depth is less than 2" client may need to consider a remove and replacement project which can increase costs by 50% or more. Further resources: Pavement Surface Condition Field Rating Manual for Asphalt Pavement. <http://co-asphalt.com/resources/maintenance-and-preservation/>

Useful Life:  
25 years

Remaining Life:  
12 years



Best Case: \$ 100,000

Worst Case: \$ 120,000

Cost Source: ARI Cost Database: Similar Project Cost History

## Building Exteriors

### Comp #: 23020 Ext. Lights (Decorative) - Replace

Quantity: ~ (170) Lights

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (28) Buildings 1, 2, (12) Building 3, (32) Buildings 4, 5, (85) Buildings 6, 7, 8, 9, 10, (11) Building 11. Exterior lights determined to be in fair condition typically exhibit more moderate signs of wear and age but are generally believed to be aging normally with no unusual conditions noted. Observed during daylight hours but assumed to be in functional operating condition. As routine maintenance clean by wiping down with an appropriate cleaner change bulbs and repair as needed. Best practice is to plan for replacement of all lighting together at roughly the time frame below for cost efficiency and consistent quality/appearance throughout development. Should be coordinated with exterior painting projects whenever possible. Individual replacements should be considered an Operating expense. If available an extra supply of replacement fixtures should be kept on-site to allow for prompt replacement.

Useful Life:  
25 years

Remaining Life:  
12 years



Best Case: \$ 37,000

Worst Case: \$ 55,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23180 Trex Decks - Replace****Quantity: ~ 530 GSF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (532 GSF) Buildings 5, 6. Fair conditions were observed at the time of the inspection. No extensive cracking or weathering noted however the surfaces appeared to be slightly faded. Surface appearance was of that of a composite/plastic/PVC material. Typical warranty period based on a Trex type material is 25 years. However that warranty period is based on proper installation and maintenance. We recommend ongoing evaluations of all elevated decks by a qualified decking or waterproofing contractor to assess overall condition and performance of system components. As part of ongoing maintenance program inspect regularly for any damage/deterioration. Ensure that any rail assemblies are secure. Note project costs can vary significantly professional specifications soliciting several estimates and professional project oversight are recommended. Track actual expenses for inclusion within future Reserve Study updates. If properly installed composite decking systems should experience an extended useful life. Decks should be thoroughly evaluated by a decking or waterproofing contractor prior to re-coating in order to determine scope of any required repairs. If the deck system has a warranty the client should make sure to follow any requirements necessary to maintain said warranty such as re-coating at required intervals and conducting professional inspections. As a general rule potted plants and other items that may trap water should be elevated off the deck or used with a waterproof liner in order to prevent prolonged exposure.

Useful Life:  
25 years

Remaining Life:  
9 years



Best Case: \$ 17,000

Worst Case: \$ 20,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23190 Wood Deck - Seal/Repair**

**Quantity: ~ 1100 GSF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (256) Buildings 1 2 (266) Buildings 4 (360) Buildings 6 7 8 9 10 (241) Building 11. The finish on the deck surfaces appeared in generally poor condition. Evidence of cracking fading and peeling of the paint/stain was observed. Plan to paint the wood surfaces soon. Wood seal coatings lose thickness each year due to wear and exposure to UV light. If more than the topcoat is allowed to wear off the surface may still appear to be in 'good' condition to the untrained eye but waterproof integrity may be compromised. Decks should be thoroughly evaluated by a decking or waterproofing contractor prior to re-coating in order to determine scope of any required repairs. If the deck system has a warranty the client should make sure to follow any requirements necessary to maintain said warranty such as re-coating at required intervals and conducting professional inspections. As a general rule potted plants and other items that may trap water should be elevated off the deck or used with a waterproof liner in order to prevent prolonged exposure.

Useful Life:  
3 years

Remaining Life:  
0 years



Best Case: \$ 3,700

Worst Case: \$ 4,900

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23200 Wood Deck - Resurface/Restore****Quantity: ~ 1100 GSF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (256 GSF) Buildings 1, 2, (266 GSF) Building 4, (360 GSF) Buildings 6, 7, 8, 9, 10, (241 GSF) Building 11. The deck surfaces appeared in fair condition. No broken or missing sections observed. Wood deck surface was painted/stained. No decay of boards was observed. Plan for large scale repair / replacement at roughly the interval below. As routine maintenance inspect deck stairs and railings annually and repair as needed. As part of maintenance apply water repellent stain/preservative at least every other year. Options for a longer lasting deck include such things as using a thick wood boards of suitable species or a composite product. Composite materials are available that require less maintenance and lower life cycle costs typically. Funding for replacing existing wood boards with in-kind material is factored below. Costs can increase greatly if decay of the structural framing is found.

Useful Life:

25 years

Remaining Life:

9 years



Best Case: \$ 43,000

Worst Case: \$ 49,000

Cost Source: ARI Cost Database: Similar Project Cost History

---

**Comp #: 23220 Balcony Rails - Paint****Quantity: ~ 540 LF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (128 LF) Buildings 1, 2, (64 LF) Building 3, (132 LF) Buildings 4, 5, (210 LF) Buildings 6, 7, 8, 9, 10, (9 LF) Building 11. Deck railing finishes determined to be in fair condition typically exhibit minor to moderate wear with faded but consistent color. Coating is generally intact but may be beginning to peel or flake in sections. Railings should be painted/re-coated at the approximate interval shown below in order to restore good appearance and protect the railings from excessive surface wear. If railing is exposed to the elements without adequate coating for an extended period of time useful life may be severely reduced. Best practice is to coordinate with other exterior projects when possible such as deck re-coating or exterior painting.

Useful Life:

5 years

Remaining Life:

0 years



Best Case: \$ 12,000

Worst Case: \$ 18,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23230 Balcony Rails - Replace****Quantity: ~ 540 LF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Deck railings determined to be in fair condition typically exhibit some wear and age but are not showing any advanced structural concerns loose attachments rust etc. Appearance may be declining or outdated at this stage but railings are still performing their intended function. Post attachments and hardware should be inspected periodically for corrosion/rust and any waterproofing issues. As routine maintenance inspect regularly to ensure safety and stability repair promptly as needed using general operating/maintenance funds. We suggest Reserve funding for regular intervals of total replacement as indicated below. Unless otherwise noted costs shown are based on replacement with a similar style of railing. However if the client chooses to upgrade or replace with a different style costs may be substantially different. Any new information about changes in style should be incorporated into future Reserve Study updates.

Useful Life:

40 years

Remaining Life:

27 years



Best Case: \$ 48,000

Worst Case: \$ 53,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23310 Wood Siding – Paint/Repair (Ph 1)****Quantity: ~ 24800 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Painted in 2024 for ~ \$35,440.

Comments: Includes (13440 GSF) Buildings 1, 2, (11340 GSF) Building 4. Painted exterior surfaces determined to be in fair condition typically exhibit some minor to moderate signs of wear and age such as chalking peeling blistering etc. Problems tend to develop in more exposed areas first. Hairline cracks may be present at this stage. Overall appearance is satisfactory. As routine maintenance inspect regularly (including sealants) repair locally and touch-up paint as needed. Typical paint cycles can vary greatly depending upon many factors including type of material painted surface preparations quality of material application methods weather conditions during application moisture beneath paint and exposure to weather conditions. Proper sealant/caulking is critical to preventing water intrusion and resulting damage to the building structure. Incorrect installations of sealant are common and can greatly decrease its useful life. Inspect sealant more frequently as it ages to determine if it is failing. Typical sealant problems include failure of sealant to adhere to adjacent materials and tearing/splitting of the sealant itself. As sealants age and are exposure to ultra-violet sunlight they will dry out harden and lose their elastic ability. Remove and replace sealant as signs of failure begin to appear. Proper cleaning prep work and proper installation are critical for a long lasting sealant/caulking. Do not install sealant in locations that would block water drainage from behind the siding. Repair areas as needed prior to project. For best results the client may want to consult with a building envelope specialist or waterproofing contractor to specify types of materials to be used and define complete scope of work before bidding. Best practice is to coordinate this type of work with other projects whenever practical such as balcony sealing planter waterproofing etc.

Useful Life:  
5 years

Remaining Life:  
4 years



Best Case: \$ 30,000

Worst Case: \$ 40,000

Cost Source: Client Cost History

---

**Comp #: 23310 Wood Siding – Paint/Repair (Ph 2)****Quantity: ~ 22700 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Painted in 2022 for ~ \$33,680.

Comments: Includes (22680 GSF) Buildings 5, 6. Painted exterior surfaces determined to be in fair condition typically exhibit some minor to moderate signs of wear and age such as chalking peeling blistering etc. Problems tend to develop in more exposed areas first. Hairline cracks may be present at this stage. Overall appearance is satisfactory. As routine maintenance inspect regularly (including sealants) repair locally and touch-up paint as needed. Typical paint cycles can vary greatly depending upon many factors including type of material painted surface preparations quality of material application methods weather conditions during application moisture beneath paint and exposure to weather conditions. Proper sealant/caulking is critical to preventing water intrusion and resulting damage to the building structure. Incorrect installations of sealant are common and can greatly decrease its useful life. Inspect sealant more frequently as it ages to determine if it is failing. Typical sealant problems include failure of sealant to adhere to adjacent materials and tearing/splitting of the sealant itself. As sealants age and are exposure to ultra-violet sunlight they will dry out harden and lose their elastic ability. Remove and replace sealant as signs of failure begin to appear. Proper cleaning prep work and proper installation are critical for a long lasting sealant/caulking. Do not install sealant in locations that would block water drainage from behind the siding. Repair areas as needed prior to project. For best results the client may want to consult with a building envelope specialist or waterproofing contractor to specify types of materials to be used and define complete scope of work before bidding. Best practice is to coordinate this type of work with other projects whenever practical such as balcony sealing planter waterproofing etc.

Useful Life:  
5 years

Remaining Life:  
2 years



Best Case: \$ 31,600

Worst Case: \$ 35,600

Cost Source: Client Cost History + Inflation

---

**Comp #: 23310 Wood Siding – Paint/Repair (Ph 3)****Quantity: ~ 64300 GSF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (56700 GSF) Buildings 7, 9, 8, 10, (7598 GSF) Building 11. Painted exterior surfaces determined to be in fair condition typically exhibit some minor to moderate signs of wear and age such as chalking peeling blistering etc. Problems tend to develop in more exposed areas first. Hairline cracks may be present at this stage. Overall appearance is satisfactory. As routine maintenance inspect regularly (including sealants) repair locally and touch-up paint as needed. Typical paint cycles can vary greatly depending upon many factors including type of material painted surface preparations quality of material application methods weather conditions during application moisture beneath paint and exposure to weather conditions. Proper sealant/caulking is critical to preventing water intrusion and resulting damage to the building structure. Incorrect installations of sealant are common and can greatly decrease its useful life. Inspect sealant more frequently as it ages to determine if it is failing. Typical sealant problems include failure of sealant to adhere to adjacent materials and tearing/splitting of the sealant itself. As sealants age and are exposure to ultra-violet sunlight they will dry out harden and lose their elastic ability. Remove and replace sealant as signs of failure begin to appear. Proper cleaning prep work and proper installation are critical for a long lasting sealant/caulking. Do not install sealant in locations that would block water drainage from behind the siding. Repair areas as needed prior to project. For best results the client may want to consult with a building envelope specialist or waterproofing contractor to specify types of materials to be used and define complete scope of work before bidding. Best practice is to coordinate this type of work with other projects whenever practical such as balcony sealing planter waterproofing etc.

Useful Life:  
5 years

Remaining Life:  
0 years



Best Case: \$ 155,000

Worst Case: \$ 16,500

Cost Source: Client Cost History

---

**Comp #: 23310 Wood Siding – Paint/Repair (Ph 4)**

**Quantity: ~ 13700 GSF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (13716 GSF) Building 3. Painted exterior surfaces determined to be in fair condition typically exhibit some minor to moderate signs of wear and age such as chalking peeling blistering etc. Problems tend to develop in more exposed areas first. Hairline cracks may be present at this stage. Overall appearance is satisfactory. As routine maintenance inspect regularly (including sealants) repair locally and touch-up paint as needed. Typical paint cycles can vary greatly depending upon many factors including type of material painted surface preparations quality of material application methods weather conditions during application moisture beneath paint and exposure to weather conditions. Proper sealant/caulking is critical to preventing water intrusion and resulting damage to the building structure. Incorrect installations of sealant are common and can greatly decrease its useful life. Inspect sealant more frequently as it ages to determine if it is failing. Typical sealant problems include failure of sealant to adhere to adjacent materials and tearing/splitting of the sealant itself. As sealants age and are exposure to ultra-violet sunlight they will dry out harden and lose their elastic ability. Remove and replace sealant as signs of failure begin to appear. Proper cleaning prep work and proper installation are critical for a long lasting sealant/caulking. Do not install sealant in locations that would block water drainage from behind the siding. Repair areas as needed prior to project. For best results the client may want to consult with a building envelope specialist or waterproofing contractor to specify types of materials to be used and define complete scope of work before bidding. Best practice is to coordinate this type of work with other projects whenever practical such as balcony sealing planter waterproofing etc.

Useful Life:  
5 years

Remaining Life:  
2 years



Best Case: \$ 31,500

Worst Case: \$ 34,400

Cost Source: Client Cost History

---

**Comp #: 23320 Wood Siding – Replace (Ph 1)****Quantity: ~ 24800 GSF**

Location: Buildings 1, 2, 4.

Funded?: Yes.

History:

Comments: Includes (13440 GSF) Buildings 1, 2, (11340 GSF) Building 4. Wood siding determined to be in fair condition typically exhibits some color fading and inconsistency, with minor, isolated locations showing more advanced surface wear, cracking, splintering, etc. Project costs can vary depending upon materials chosen and the condition of the underlying structural framing when exposed. We recommend the Board conduct research well in advance in order to define scope, timing and costs, including plan for some margin of contingency. Siding is horizontal clapboard and shingle and board and batten. Surface was painted. No view of the critical underlying waterproofing was available as part of our limited visual review. Replacement may ultimately be needed due to the failure of the underlying waterproofing degrading over the decades, and/or the end of the useful life of the siding materials from general aging. Many factors influence the useful life, including exposure to (or protection from) wind driven rain, and the quality of the waterproofing and flashing beneath the siding. Evaluate the siding and the critical underlying waterproofing (typically building paper or house-wrap) more frequently as the remaining useful life approaches zero years. Adjust remaining useful life as dictated by the evaluation. Align with window replacement for cost efficiencies and building envelope integrity when practical. Inspect annually and repair locally as needed using general maintenance funds. Keep the wood siding painted to protect the wood from decay caused by water. Another item that greatly influences useful life is the thoroughness of the original painting. Wood siding will last longer if each piece was painted on all six sides. Typically, wood siding is painted on the two sides that are exposed and not on the back, ends, or top. Since we perform only a visual review, we were unable to confirm the extents of the painting. It is reasonable to presume that not all six sides are painted. If the siding is not painted on all sides, water can infiltrate and be absorbed into the wood on the unpainted sides, which over time will lead to cupping, warping and decay, limiting its useful life.

Useful Life:

50 years

Remaining Life:

26 years



Best Case: \$ 446,100

Worst Case: \$ 619,500

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23320 Wood Siding – Replace (Ph 2)****Quantity: ~ 22700 GSF**

Location: Buildings 5, 6.

Funded?: Yes.

History:

Comments: Includes (22680 GSF) Buildings 5, 6. Wood siding determined to be in fair condition typically exhibits some color fading and inconsistency, with minor, isolated locations showing more advanced surface wear, cracking, splintering, etc. Project costs can vary depending upon materials chosen and the condition of the underlying structural framing when exposed. We recommend the Board conduct research well in advance in order to define scope, timing and costs, including plan for some margin of contingency. Siding is horizontal clapboard and shingle and board and batten. Surface was painted. No view of the critical underlying waterproofing was available as part of our limited visual review. Replacement may ultimately be needed due to the failure of the underlying waterproofing degrading over the decades, and/or the end of the useful life of the siding materials from general aging. Many factors influence the useful life, including exposure to (or protection from) wind driven rain, and the quality of the waterproofing and flashing beneath the siding. Evaluate the siding and the critical underlying waterproofing (typically building paper or house-wrap) more frequently as the remaining useful life approaches zero years. Adjust remaining useful life as dictated by the evaluation. Align with window replacement for cost efficiencies and building envelope integrity when practical. Inspect annually and repair locally as needed using general maintenance funds. Keep the wood siding painted to protect the wood from decay caused by water. Another item that greatly influences useful life is the thoroughness of the original painting. Wood siding will last longer if each piece was painted on all six sides. Typically, wood siding is painted on the two sides that are exposed and not on the back, ends, or top. Since we perform only a visual review, we were unable to confirm the extents of the painting. It is reasonable to presume that not all six sides are painted. If the siding is not painted on all sides, water can infiltrate and be absorbed into the wood on the unpainted sides, which over time will lead to cupping, warping and decay, limiting its useful life.

Useful Life:

50 years

Remaining Life:

33 years



Best Case: \$ 408,200

Worst Case: \$ 567,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23320 Wood Siding – Replace (Ph 3)****Quantity: ~ 64300 GSF**

Location: Buildings 7, 8, 9, 10, 11.

Funded?: Yes.

History:

Comments: Includes (56700 GSF) Buildings 7, 9, 8, 10, (7598 GSF) Building 11. Wood siding determined to be in fair condition typically exhibits some color fading and inconsistency, with minor, isolated locations showing more advanced surface wear, cracking, splintering, etc. Project costs can vary depending upon materials chosen and the condition of the underlying structural framing when exposed. We recommend the Board conduct research well in advance in order to define scope, timing and costs, including plan for some margin of contingency. Siding is horizontal clapboard and/or shingle. Surface was painted. No view of the critical underlying waterproofing was available as part of our limited visual review. Replacement may ultimately be needed due to the failure of the underlying waterproofing degrading over the decades, and/or the end of the useful life of the siding materials from general aging. Many factors influence the useful life, including exposure to (or protection from) wind driven rain, and the quality of the waterproofing and flashing beneath the siding. Evaluate the siding and the critical underlying waterproofing (typically building paper or house-wrap) more frequently as the remaining useful life approaches zero years. Adjust remaining useful life as dictated by the evaluation. Align with window replacement for cost efficiencies and building envelope integrity when practical. Inspect annually and repair locally as needed using general maintenance funds. Keep the wood siding painted to protect the wood from decay caused by water. Another item that greatly influences useful life is the thoroughness of the original painting. Wood siding will last longer if each piece was painted on all six sides. Typically, wood siding is painted on the two sides that are exposed and not on the back, ends, or top. Since we perform only a visual review, we were unable to confirm the extents of the painting. It is reasonable to presume that not all six sides are painted. If the siding is not painted on all sides, water can infiltrate and be absorbed into the wood on the unpainted sides, which over time will lead to cupping, warping and decay, limiting its useful life.

Useful Life:

50 years

Remaining Life:

43 years



Best Case: \$ 952,600

Worst Case: \$ 1,323,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23320 Wood Siding – Replace (Ph 4)****Quantity: ~ 13700 GSF**

Location: Building 3

Funded?: Yes.

History:

Comments: Includes (13716 GSF) Building 3. Wood siding determined to be in fair condition typically exhibits some color fading and inconsistency, with minor, isolated locations showing more advanced surface wear, cracking, splintering, etc. Project costs can vary depending upon materials chosen and the condition of the underlying structural framing when exposed. We recommend the Board conduct research well in advance in order to define scope, timing and costs, including plan for some margin of contingency. Siding is horizontal clapboard and/or shingle. Surface was painted. No view of the critical underlying waterproofing was available as part of our limited visual review. Replacement may ultimately be needed due to the failure of the underlying waterproofing degrading over the decades, and/or the end of the useful life of the siding materials from general aging. Many factors influence the useful life, including exposure to (or protection from) wind driven rain, and the quality of the waterproofing and flashing beneath the siding. Evaluate the siding and the critical underlying waterproofing (typically building paper or house-wrap) more frequently as the remaining useful life approaches zero years. Adjust remaining useful life as dictated by the evaluation. Align with window replacement for cost efficiencies and building envelope integrity when practical. Inspect annually and repair locally as needed using general maintenance funds. Keep the wood siding painted to protect the wood from decay caused by water. Another item that greatly influences useful life is the thoroughness of the original painting. Wood siding will last longer if each piece was painted on all six sides. Typically, wood siding is painted on the two sides that are exposed and not on the back, ends, or top. Since we perform only a visual review, we were unable to confirm the extents of the painting. It is reasonable to presume that not all six sides are painted. If the siding is not painted on all sides, water can infiltrate and be absorbed into the wood on the unpainted sides, which over time will lead to cupping, warping and decay, limiting its useful life.

Useful Life:

50 years

Remaining Life:

47 years



Best Case: \$ 228,600

Worst Case: \$ 317,500

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23410 Metal Siding - Repair/Replace****Quantity: ~ 5300 GSF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (2052 GSF) Buildings 10, 9, 8, 7, (1375 GSF) Building 11, (1840 GSF) Building 3.

Metal surfaces were observed to be in fair condition. No broken or missing sections observed. Rust observed on multiple sections. Replacement may ultimately be needed due to the failure of the underlying waterproofing degrading over the decades and/or the end of the useful life of the siding materials from general aging. Many factors influence the useful life including exposure to (or protection from) wind driven rain and the quality of the waterproofing and flashing beneath the siding. Evaluate the siding and the critical underlying waterproofing (typically building paper or house-wrap) more frequently as the remaining useful life approaches zero years. Adjust remaining useful life as dictated by the evaluation. Align with other exterior replacements for cost efficiencies and building envelope integrity when practical. Inspect annually and repair locally as needed using general maintenance funds. Metal panel can have a finish that is either field applied or factory applied. Most have factory applied finish which can last much longer than a field-applied finish. We assume that it is long lasting factory finish. Many factors influence the useful life including exposure to (or protection from) wind driven rain quality of the siding material and quality of the waterproofing and flashing beneath the siding. Almost all waterproofing systems will degrade over time (years or decades) as it ages. Project costs can vary depending upon materials chosen and the condition of the underlying structural framing when exposed. We recommend the Board conduct research well in advance in order to define scope timing and costs including plan for some margin of contingency.

Useful Life:  
60 years

Remaining Life:  
36 years



Best Case: \$ 170,000

Worst Case: \$ 200,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23570 Comp. Shingle Roof - Replace (Ph 1)****Quantity: ~ 15300 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Replaced in 2022 for ~\$155,488.

Comments: Includes (10306 GSF) Buildings 1, 2, (5002 GSF) Building 4. Ventilation (the lack of which can greatly reduce the roof's useful life) was observed at the eave and ridge. Eave venting consisted of soffit vents. Ridge venting appeared to be provided by gable end louvers. Asphalt shingle roofs determined to be in fair condition and typically exhibit normal signs of wear and deterioration, including some loss of granule cover, and light to moderate curling/lifting, especially in most exposed areas. Overall believed to be aging normally. A reserve study conducts only a limited visual review, and many of the critical waterproofing and ventilation items of the roof are not readily viewable. For a full evaluation have a professional roof consultant/contractor perform a thorough up-close survey of your entire roof system, including attic inspection (if any). Costs below factors replacement with an architectural grade laminated shingle. As routine maintenance, many manufacturers recommend inspections at least twice annually (once in the fall before the snow season and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or any other repair needed to ensure waterproof integrity of roof. Keep roof surface, gutters, and downspouts clear and free of debris. At the time of re-roofing, we recommend that you hire a professional consultant to evaluate the existing roof and specify the new roof materials/design, provide installation oversight. We recommend that all clients hire qualified consultants whenever they are considering having work performed on any building envelope (waterproofing) components including: roof, walls, windows, decks, exterior painting, and caulking/sealant. There is a wealth of information available through Roofing Organizations such as: National Roofing Contractors client (NRCA) <http://www.nrca.net>. Asphalt Roofing Manufacturers client (ARMA) <http://www.asphaltroofing.org/> Roof Consultant Institute (RCI) <http://www.rci-online.org>

Useful Life:  
20 years

Remaining Life:  
17 years



Best Case: \$ 130,100

Worst Case: \$ 175,300

Cost Source: Client Cost History + Inflation

---

**Comp #: 23570 Metal Roof - Replace (Ph 1)****Quantity: ~ 5700 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Phase 1 Built in 2001.

Comments: Includes (3568 GSF) Buildings 1, 2, (2085 Pro Panel) Building 4.

Metal roofing consists of pro-panel metal roof. Typically metal roofs are either Pro-Panel seamed roofs or Standing Seam roofs. Pro Panel roofs are installed with exposed metal screws and fasteners, while Standing Seam will snap lock panels over the mechanical seam, with no penetrations to the underlayment. Advantages of metal roofs include long life expectancies with relatively low need to repair. Metal roofing is typically a long-lived component assuming it was properly installed and is properly maintained. As routine maintenance, many manufacturers recommend inspections at least twice annually (once in the fall, before the rainy season, and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or conduct any other repair needed to ensure waterproof integrity of roof. We recommend having roof inspected in greater detail (including conditions of sub-surface materials) by an independent roofing consultant prior to replacement. There is a wealth of information available through organizations such as the Roof Consultant Institute <http://www.rci-online.org> and the National Roofing Contractors client (NRCA) <http://www.nrca.net/>. If the roof has a warranty, be sure to review terms and conduct proper inspections/repairs as needed to keep warranty in force.

Useful Life:  
30 years

Remaining Life:  
6 years



Best Case: \$ 49,000

Worst Case: \$ 74,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23571 Comp. Shingle Roof - Replace (Ph 2)****Quantity: ~ 12200 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Phase 2 replaced in 2024 for ~ \$125,798.

Comments: Includes (5002 GSF ) Building 5, (7229 GSF) Building 6. Ventilation (the lack of which can greatly reduce the roof's useful life) was observed at the eave and ridge. Eave venting consisted of soffit vents. Ridge venting appeared to be provided by gable end louvers. Asphalt shingle roofs determined to be in fair condition and typically exhibit normal signs of wear and deterioration, including some loss of granule cover, and light to moderate curling/lifting, especially in most exposed areas. Overall believed to be aging normally. A reserve study conducts only a limited visual review, and many of the critical waterproofing and ventilation items of the roof are not readily viewable. For a full evaluation have a professional roof consultant/contractor perform a thorough up-close survey of your entire roof system, including attic inspection (if any). Costs below factors replacement with an architectural grade laminated shingle. As routine maintenance, many manufacturers recommend inspections at least twice annually (once in the fall before the snow season and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or any other repair needed to ensure waterproof integrity of roof. Keep roof surface, gutters, and downspouts clear and free of debris. At the time of re-roofing, we recommend that you hire a professional consultant to evaluate the existing roof and specify the new roof materials/design, provide installation oversight. We recommend that all clients hire qualified consultants whenever they are considering having work performed on any building envelope (waterproofing) components including: roof, walls, windows, decks, exterior painting, and caulking/sealant. There is a wealth of information available through Roofing Organizations such as: National Roofing Contractors client (NRCA) <http://www.nrca.net>. Asphalt Roofing Manufacturers client (ARMA) <http://www.asphaltroofing.org/> Roof Consultant Institute (RCI) <http://www.rci-online.org>

Useful Life:  
20 years

Remaining Life:  
19 years



Best Case: \$ 120,100

Worst Case: \$ 134,100

Cost Source: Research with Local Vendor/Contractor

**Comp #: 23571 Metal Roof - Replace (Ph 2)****Quantity: ~ 4500 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Phase 2 built in 2008.

Comments: Includes (2085 GSF) Building 5, (2407 GSF) Building 6.

Metal roofing consists of pro-panel metal roof. Typically metal roofs are either Pro-Panel seamed roofs or Standing Seam roofs. Pro Panel roofs are installed with exposed metal screws and fasteners, while Standing Seam will snap lock panels over the mechanical seam, with no penetrations to the underlayment. Advantages of metal roofs include long life expectancies with relatively low need to repair. Metal roofing is typically a long-lived component assuming it was properly installed and is properly maintained. As routine maintenance, many manufacturers recommend inspections at least twice annually (once in the fall, before the rainy season, and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or conduct any other repair needed to ensure waterproof integrity of roof. We recommend having roof inspected in greater detail (including conditions of sub-surface materials) by an independent roofing consultant prior to replacement. There is a wealth of information available through organizations such as the Roof Consultant Institute <http://www.rci-online.org> and the National Roofing Contractors client (NRCA) <http://www.nrca.net/>. If the roof has a warranty, be sure to review terms and conduct proper inspections/repairs as needed to keep warranty in force.

Useful Life:  
30 years

Remaining Life:  
13 years



Best Case: \$ 39,000

Worst Case: \$ 59,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23573 Comp. Shingle Roof - Replace (Ph 3)****Quantity: ~ 28600 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Phase 3 built in 2018.

Comments: Includes (23374 GSF) Buildings 7, 9, 10, (5220 GSF) Building 11.

Closed valleys were observed. Ventilation (the lack of which can greatly reduce the roof's useful life) was observed at the ridge. Ridge venting appeared to be provided by gable end louvers and roof jacks. Debris was not observed on the roof surface. Asphalt shingle roofs determined to be in fair condition and typically exhibit normal signs of wear and deterioration including some loss of granule cover and light to moderate curling/lifting especially in most exposed areas. Overall believed to be aging normally. A reserve study conducts only a limited visual review and many of the critical waterproofing and ventilation items of the roof are not readily viewable. For a full evaluation have a professional roof consultant/contractor perform a thorough up-close survey of your entire roof system including attic inspection (if any). Costs below factors replacement with an architectural grade laminated shingle. As routine maintenance many manufacturers recommend inspections at least twice annually (once in the fall before the snow season and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or any other repair needed to ensure waterproof integrity of roof. Keep roof surface gutters and downspouts clear and free of debris. At the time of re-roofing we recommend that you hire a professional consultant to evaluate the existing roof and specify the new roof materials/design provide installation oversight. We recommend that all clients hire qualified consultants whenever they are considering having work performed on any building envelope (waterproofing) components including: roof walls windows decks exterior painting and caulking/sealant. There is a wealth of information available through Roofing Organizations such as: National Roofing Contractors client (NRCA) <http://www.nrca.net>. Asphalt Roofing Manufacturers client (ARMA) <http://www.asphaltroofing.org/> Roof Consultant Institute (RCI) <http://www.rci-online.org>.

Useful Life:

20 years

Remaining Life:

13 years



Best Case: \$ 370,000

Worst Case: \$ 500,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23573 Metal Roof - Replace (Ph 3)****Quantity: ~ 9500 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Phase 3 built in 2018.

Comments: Includes (7781 GSF) Buildings 7, 9, 10, (1738 GSF) Building 11.

Metal roofing consists of pro-panel metal roof. Typically metal roofs are either Pro-Panel seamed roofs or Standing Seam roofs. Pro Panel roofs are installed with exposed metal screws and fasteners, while Standing Seam will snap lock panels over the mechanical seam, with no penetrations to the underlayment. Advantages of metal roofs include long life expectancies with relatively low need to repair. Metal roofing is typically a long-lived component assuming it was properly installed and is properly maintained. As routine maintenance, many manufacturers recommend inspections at least twice annually (once in the fall, before the rainy season, and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or conduct any other repair needed to ensure waterproof integrity of roof. We recommend having roof inspected in greater detail (including conditions of sub-surface materials) by an independent roofing consultant prior to replacement. There is a wealth of information available through organizations such as the Roof Consultant Institute <http://www.rci-online.org> and the National Roofing Contractors client (NRCA) <http://www.nrca.net/>. If the roof has a warranty, be sure to review terms and conduct proper inspections/repairs as needed to keep warranty in force.

Useful Life:  
30 years

Remaining Life:  
23 years



Best Case: \$ 83,000

Worst Case: \$ 120,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23574 Comp. Shingle Roof - Replace (Ph 4)****Quantity: ~ 12000 GSF**

Location: Building Exteriors

Funded?: Yes.

History: Phase 4 built in 2021.

Comments: Includes (11960 GSF) Building 3 which is actually 2 buildings, but takes up lot 3.

Closed valleys were observed. Ventilation (the lack of which can greatly reduce the roof's useful life) was observed at the ridge. Ridge venting appeared to be provided by roof jacks. Debris was not observed on the roof surface. Asphalt shingle roofs determined to be in fair condition and typically exhibit normal signs of wear and deterioration including some loss of granule cover and light to moderate curling/lifting especially in most exposed areas. Overall believed to be aging normally. A reserve study conducts only a limited visual review and many of the critical waterproofing and ventilation items of the roof are not readily viewable. For a full evaluation have a professional roof consultant/contractor perform a thorough up-close survey of your entire roof system including attic inspection (if any). Costs below factors replacement with an architectural grade laminated shingle. As routine maintenance many manufacturers recommend inspections at least twice annually (once in the fall before the snow season and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or any other repair needed to ensure waterproof integrity of roof. Keep roof surface gutters and downspouts clear and free of debris. At the time of re-roofing we recommend that you hire a professional consultant to evaluate the existing roof and specify the new roof materials/design provide installation oversight. We recommend that all clients hire qualified consultants whenever they are considering having work performed on any building envelope (waterproofing) components including: roof walls windows decks exterior painting and caulking/sealant. There is a wealth of information available through Roofing Organizations such as: National Roofing Contractors client (NRCA) <http://www.nrca.net>. Asphalt Roofing Manufacturers client (ARMA) <http://www.asphaltroofing.org/> Roof Consultant Institute (RCI) <http://www.rci-online.org>.

Metal roofing consists of pro-panel metal roof. Typically metal roofs are either Pro-Panel seamed roofs or Standing Seam roofs. Pro Panel roofs are installed with exposed metal screws and fasteners, while Standing Seam will snap lock panels over the mechanical seam, with no penetrations to the underlayment. Advantages of metal roofs include long life expectancies with relatively low need to repair. Metal roofing is typically a long-lived component assuming it was properly installed and is properly maintained. As routine maintenance, many manufacturers recommend inspections at least twice annually (once in the fall, before the rainy season, and again in the spring) and after large storm events. Promptly replace any damaged/missing sections or conduct any other repair needed to ensure waterproof integrity of roof. We recommend having roof inspected in greater detail (including conditions of sub-surface materials) by an independent roofing consultant prior to replacement. There is a wealth of information available through organizations such as the Roof Consultant Institute <http://www.rci-online.org> and the National Roofing Contractors client (NRCA) <http://www.nrca.net/>. If the roof has a warranty, be sure to review terms and conduct proper inspections/repairs as needed to keep warranty in force.

Useful Life:  
20 years

Remaining Life:  
16 years



Best Case: \$ 160,000

Worst Case: \$ 210,000

Cost Source: ARI Cost Database: Similar Project Cost History

**Comp #: 23650 Gutters/Downspouts - Replace****Quantity: ~ 2000 LF**

Location: Building Exteriors

Funded?: Yes.

History:

Comments: Includes (88 LF) Buildings 1, 2, (388 LF) Building 3, (208 LF Aluminum) Buildings 4, 5, (168 LF Copper) Buildings 4, 5, (1050 LF) Buildings 6, 7, 8, 9, 10, (93 LF) Building 11. Gutters and downspouts determined to be in fair condition typically exhibit some normal wear and tear but drainage away from the roof and building appears to be adequate. Generally believed to be aging normally. Gutters and downspouts are assumed to be functioning properly unless otherwise noted. As routine maintenance inspect regularly keep gutters and downspouts free of debris. If buildings are located near trees keep trees trimmed back to avoid accumulation of leaves on the roof surface which will accumulate in the gutters and increase maintenance requirements while reducing life expectancy. Repair or replace individual sections as needed as an Operating expense. We generally recommend that the gutters and downspouts be replaced when the roof is being resurfaced/replaced. National Roofing Contractor client (NRCA) roofing standard includes installing eave flashings at the gutters. We suggest to plan for total replacement of gutter and downspouts at the same intervals as roof replacement for cost efficiency. Unless otherwise noted costs shown here assume replacement with similar type as are currently in place.

Useful Life:  
30 yearsRemaining Life:  
6 years

Best Case: \$ 36,000

Worst Case: \$ 45,000

Cost Source: ARI Cost Database: Similar Project Cost History

---

**Comp #: 23660 Heat Tape - Replace****Quantity: ~ 71500 LF**

Location: Building Exteriors

Funded?: No. Heat tape is the responsibility of the individual owners.

History:

Comments: Client reported that any heat tape observed was the responsibility of the individual unit owners.

Useful Life:

Remaining Life:



Best Case:

Worst Case:

Cost Source:

## Mechanicals

### Comp #: 25570 Irrigation Clocks - Replace

Quantity: ~ (10) Controllers

Location: Common Areas

Funded?: Yes.

History:

Comments: Includes (10) Rainbird ESP-ME3 Controllers. Minimal or no subjective/aesthetic value for this component. Useful life is based primarily on normal expectations for service/performance life in this location. Unless otherwise noted remaining useful life expectancy is based primarily on original installation or last replacement/purchase date our experience with similar systems/components and assuming normal amount of usage and good preventive maintenance. Irrigation controllers should have a relatively long life expectancy under normal circumstances. Replacement is often required due to lack of available replacement parts lightning strikes etc. as opposed to complete failure of existing equipment. Exposure to the elements can affect overall life expectancy and controllers should be located in protected areas or within protective enclosures whenever possible. When evaluating replacement options the client should consider replacement with smart" models (i.e. respond to projected weather data) to minimize unnecessary water usage. Payback period for efficient controllers that minimize water use is typically very short

Useful Life:  
15 years

Remaining Life:  
7 years



Best Case: \$ 6,000

Worst Case: \$ 7,100

Cost Source: Research with Local Vendor/Contractor