

# Alamo Cenotaph

## Investigation & Restoration



**Texas Historical Commission Update**  
**SAL Permit #HS 1120**

July 26, 2024



# Agenda

- Previous Investigation Summary
- Additional Investigation Results
- Restoration Recommendations
- Cleaning and Restoration Mockups
- Schedule






# Previous Investigation

## Findings:

- Low concrete cover depth, exposed reinforcement
- Concrete carbonation
  - Concrete pH = 5 (12 is typical)
  - Carbonation depth of 1.5" from both sides at south wall
- Interior atmospheric conditions
  - Visible water infiltration
  - Insufficient air flow




*Initial investigation area*



# Previous Investigation

- Stone anchors
  - Missing and improperly attached stone anchors
- Exterior marble condition
  - Displacement
  - Spalling, cracking, joint damage
  - Soiling



*Stone anchors*




*Marble damage at joints*



# Additional Investigation

## Scope:


- Access to interior of boot area
- Partial visual access into toe area
- Interior test pit
- Installation of temperature, relative humidity, and CO<sub>2</sub> sensors at tower
- Installation of concrete moisture sensors at boot



*Red = initial investigation, blue = additional investigation*




# Additional Investigation Stone Removal






# Additional Investigation



3D scanning




West interior wall



# Additional Investigation – Concrete Carbonation

## On-site and laboratory testing:


- Depth of carbonation ranges from 1" – 2.5"
- Concrete pH = 8-10 (12 is typical)
- Concrete below grade has negligible carbonation



*Above grade concrete core at south boot wall*




*On-site carbonation testing*





# Additional Investigation – Concrete Cover

- Cover thickness varies between and within elevations
- North wall has thickest cover
- East beam has lowest cover
- Cover thickness is less than the depth of carbonation in many areas




*Ground penetrating radar scan*



# Additional Investigation – Interior Atmosphere

## Sensor Data:



- Temperature and RH fluctuates daily (more fluctuation on top and bottom of tower)
- Higher average temperature at top of tower
- Higher relative humidity at bottom of tower
- Interior CO<sub>2</sub> level higher than average exterior level



*Approximate sensor locations*



# Additional Investigation – Interior Atmosphere



Carbonation rate model


Height from ground (ft)	Sensor ID	Temperature, mean (F)	Temperature, Stdv. (F)	RH, mean (%)	RH, Stdv. (%)
52	G4	90.3	2.3	64.1	8.1
42	W1	89.7	2.4	65.9	9.0
32	G3	89.2	2.2	67.8	9.2
12	G2	88.3	2.6	69.3	10.8
2	G1	87.0	2.1	70.0	8.9

Sensor data



# Additional Investigation - Other Laboratory Testing

- Aluminum stone anchors
  - 95% aluminum
  - 4% copper
  - .5% iron
  - .5% magnesium
  - Alloy is safe to remain embedded in concrete
- Brick and mortar: sulfate contamination
  - In bricks: 0.3% - 0.7%
  - In mortar (20% Portland Cement): 0.8% -1.4%



*Historic anchor drawing*




*Bricks from Cenotaph interior*



# Restoration Recommendations

- Removal and replacement of brick infill
- Realkalization treatment of carbonated concrete
  - All beams require realkalization
  - North and south walls to be considered for realkalization
  - Realkalization area will depend on how much marble cladding is removed
  - Expose 1 foot of concrete structure below grade for treatment
- Apply protective anti-carbonation coating to all accessible concrete surfaces




*East-west section detail at beams*



# Restoration Recommendations

- Environmental control measures
  - Increase interior ventilation
  - Long-term monitoring
- Restoration of marble
  - Complete cleaning
  - Complete marble restoration
  - Reinstall marble with correct anchoring
  - Existing aluminum anchors can be cut and left embedded in concrete as required



*Restoration construction drawing*



# Marble Cleaning

## Chemical Cleaning

- Three products tested March 7



*Before chemical cleaning*



*After chemical cleaning*



# Marble Cleaning

## Laser Cleaning

- Mockup completed June 24



*Before laser cleaning*




*After laser cleaning*



# Marble Restoration

- Marble slab procured from quarry in Georgia that sourced original stone
- Mockup slab will be deliberately damaged and then repaired per restoration recommendations



Repair mockup construction drawing



# Schedule

- Summer 2024: Restoration Construction Documents in progress
- Fall 2024
  - Bidding
  - Stone repair mockup
- Late Fall 2024: Construction mobilization
- June 2025: Restoration complete





# Questions?



1939



2021