

Opportunities for Improvement Green River Panels August 2008



Opportunities

- The company has a world class forming and pressing line
- Access to the most dynamic markets in the world
- The company can differentiate itself by producing a quality product that is cost competitive
- 50% of wood furnish comes from within the company from adjacent sawmill

Opportunities

- A number of issues have to be addressed
- This is not unusual for a new operation
- I have significant experience in the improvement of particleboard operations throughout Australia and in North America
- The following are opportunities for improvement that I have identified from the week visit
 - These are divided into immediate and longer term opportunities

Significant issues

- Dirty raw material
 - Too much dirt is getting into process and causing excessive wear on flaker mill knives & wear plates



Grit in particleboard causes machinability problems once laminated.

It also results in poor quality flake (see over)

It must be eliminated

Significant issues

- Flaker and PAL screen configurations:
 - There is an imbalance between core and surface flake
 - This is due to incorrect configuration of PAL screen sizes & an inability to optimise the outfeed of the dry refiner due to blockages resulting in an inability to generate enough high quality surface material.
 - The correct core to surface ratio needs to be generated from the PAL screens for the thickest board produced.
 - As board sizes get thinner more surface material is required which is generated by the dry refiner from core “accept” chips
- The fines and larger material generated after the chipper need to be redirected to furnish. The chip screen is sub-optimal.


Significant issues

- Flake quality at the blenders:
 - Ex flakers >4mm fraction can vary between 5% - 68% within 12 hrs.
 - Ex screens dust in surface can vary between 0 - 5%
 - Amount of surface flake in core fraction varies between 0-20%
 - This leads to excessive fines in core leading to excessive resin usage and low bending strength and lack of surface material.
 - This can also result in excessive dust in surface which causes dust and glue spots.





Poor flake geometry is having a negative effect on MOR property.

Difficult to maintain consistent core to surface flake ratio



Core fines







Significant issues

- Blending inefficiencies:
 - Insufficient chiller water capacity means blenders are running too hot and resins are being partially cured prior to forming/pressing.
 - This causes an overuse of resin and reduces board physical properties.
 - Blender needs to be set up correctly
 - Resins are being cured in the blender causing downtime due to blender cleaning conducted on a daily basis
 - This stops the blender from being correctly set-up i.e. horn to shell distance resulting in poor blending and resin overuse.
 - Outfeed flaps need to be directly controlled to optimise blending.

Significant issues

- Board properties exhibit too much variability:
 - IB's are generally acceptable, even too high
 - MOR's are generally borderline.
 - This is due to poor flake geometry



Significant issues

- Sanding/sawing productivity:
 - Master boards express should be to the maximum size that the saw can handle i.e. 6m.
 - Boards going through the calibrating sander should be but to but, a solid ribbon of board being sanded.
 - There is a lot of opportunities to increase productivity through the saws
 - Don't stop line when unloading packs.
 - Saw infeed conveyor needs to return in upper position enabling next board to be immediately ready.
 - Need to use plastic staples on WIP board to minimise thumbtacks destroying sander belts.
 - Need to set up testing protocols i.e. board dimensions & sanding quality

Immediate improvements


- The logyard should be kept cleaner to minimise dirt coming into process
- Chip disc screens are under capacity and a lot of good quality furnish is being wasted
- Flaker mills;
 - New wear plates & increase knife projections to 1.0mm
 - Collect data time knife change +0, +3, +6 & +9hrs for me to do an analysis on correct knife changing protocols and PAL flake screen configuration
- Reconfigure PAL flake screens to correctly balance core: surface and remove dust & grit on basis of above I will provide advice on screen sizes

Immediate improvements

- Implement correct blender setups:
 - Install new chillers
 - Correctly set paddle and horn angles
 - Set correct distance between horn and blender shell
 - Correctly set outfeed flap pressures
- Forming station
 - At each stop over 15min, check and clean screens. This will reduce dust spots dropping off the screens causing glue spots.
- Increase master panel size to 6m to improve sanding/sawing productivity

Immediate improvements

- Operating conditions and delegations of authority.
 - There needs to be consistent operating conditions i.e:
 - line speeds, resin loadings, temperatures etc.



Immediate improvements

- Rebalance calibrating sander to achieve even surface spreads at formers (saving of 7% surface flake) using the router test method to measure depth of sander cut
- Increase master panel size
- Butt to butt sanding of board
- Modifications of saw loading conveyor required
- Outfeed bins at saw when unloading stops sanding line.
There is a huge potential to improve sanding/sawing productivity and this will be needed if line is to perform at 200,000 cubic metres per year
- Use plastic staples instead of thumbtacks as the latter will destroy sander belts and the former wont.

Immediate improvements

- Laboratory:
 - Flake data ex knife mill collected by lab staff should be fed back to production in order to optimise knife changes
 - This can be done ex drier and drier m.c. measured at same time
 - Resin C of A data should be plotted:
 - Viscosity, gel times, solids content, temperature at despatch (must be lower than 20°C)
 - When making a product only need to collect samples every 6hrs. Currently over-sampling, very expensive.
 - Data should be plotted and made available to production
 - Flake data ex screens should be collected twice per shift
 - Need to do gel times on resin mix at blender to determine adequacy of hardener addition. This is more important than carrying out tests on raw resin in the lab

Longer term improvements

- Explosion vents need to be placed on all dry cyclones, bag houses and dry flake bunkers, especially after dry refiner.
- In longer term should investigate Firefly/Halon system given the amount of drag chains in use in the process.
- Need to measure density profile of the board so as to optimise resin recipes and press profiles
- Need to undertake a suction system audit plant wide. Improved suction will improve performance of dry refiner.

Longer term improvements

- Introduction of a moisture resistant board using melamine fortified UF resins.
- To consume all sander dust and fine material at furnace may have to put water load into drier.
- Need to institute formaldehyde analysis for board or regularly get board tested for formaldehyde
- Need to test for surface grit levels especially if board is to be laminated
- Make board to E1 and super E1 formaldehyde standards

Opportunities; how I can add value

- At 200,000m resin spend is US\$11.5m. With my technology on wetting physics and ability to increase blending efficiencies I can save the company US\$2m per year on resin expenditure alone.
- Set up technical systems to ensure plant is run to full potential
- Train key personnel in technology of particleboard and how to run process
- Optimise machine settings.
- Suggest improvements to operation
- Set up meaningful process measuring and control systems
- Ensure suppliers of resins have processes in control
- I have access to technology that is unique in world to enhance the efficiency of the process
- With my knowledge of paper impregnation and laminating I will be able to assist the company in this direction.