LOUISIANA STATE POLICE

Louisiana Uniform Crash Report

20120042760

Traffic Fatality



Ascension Parish December 7, 2012 Interstate 10 eastbound Mile Post 169.11

Prepared by Tpr. Steven Bunch #2421
TROOP A
17801 HIGHLAND ROAD
BATON ROUGE, LA 70810
225.754.8500

-		the Street	201200	142/60
TOTAL NUMBER OF		STATE OF LOUISIANA OR VEHICLE TRAFFIC CRA	SU DEDOOT	
ER CLES INVOLVED	UNIFORM MOT	OR VEHICLE TRAFFIC CHA	on neront	
(Internal Control	TIME (DOOD) DISTRICT	TROOP		PAGE #
ATE OF CRASH	1 1 1 1 1		0.32291	01
1 2 0 7 2 0 1 2	TPT0	A LAT.	A L	
ARISH		PARISH CODE LONG.	1 . 0 0 6 7 8	
Ascensio	n	03 LONG.	rant Service Road	
ONTY OR TOWN		CITY CODE NW	SW N E	
		NE	86 L \$ L W L	TWONK THE A
CRASH HIGHWAY #		OADWAY NAME		ZOME SLOS
OCCURRED ON A DITERSTATE	0 169.11	Interstat	e 10	PUBLIC PHOTOS
S.U.S. HWY C.STATE HWY DISTANCE	8	TREETA-BOHWAY CAT INTERSE	CTION X NOT AT INTERSECTIO	
E. CITY STREET	2 1 MILES E NE	LA-928 B	luff Rd	RENOLVED X FAUNCITY
F. OFF HOAD! PROWITE PROPERTY ON TOLL ROAD ONSTANCE	FUET WE SWE	TRESTANGHWAY CLAY INTERSE	CTION DINOT AT INTERSECTIO	
A	MILES			
	FEET SW			
WRITE APPROPRIATE LETTER IN I	LOCK CONTR	BUTING FACTORS AND COND		
ROAD SURFACE	DOADWAY	TYPE OF ROADWAY	ALIGNMENT	PRIMARY FACTOR
ONE PER COLUMN)	CONDITIONS	A. ONE-WAY HOAD	A. STRAIGHT-LEVEL	SECONDARY FACTOR B
A A	B. SHOULDER ABNORMALITY	B. TWO-WAY ROAD WITH NO PHYSICAL SEPARATION	B. STRANGHT-LEVEL ELEVATED G. CURVE-LEVEL	lane of the lane o
	D. DEEP RUTS	G. TWO-WAY ROAD WITH A PHYSICAL SEPARATION	D. CURVE-LEVEL ELEVATED E. ON GRADE-STRAIGHT	A. WOLATIONS B. MOVEMENT PRIOR TO CRASH
B. WET B. BLACK TON C. DNOWNSLAISH C. BRICK	F. LOOSE SURFACE MATERIAL	D. TWO-WAY ROAD WITH A	6. HILLCREST-STRAIGHT	C. VISION ORSCUREMENTS D. CONDITION OF DRIVER
E CONTAMINANT E, DIRT	G. CONSTRUCTION, REPAR H, DVERHEAD GLEARANCE LEMITED	PHYSICAL BARRIER Y, UNKNOWN	H. HILLCREST-CUTIVE L. DIR HUMP-STRAIGHT	E. ROAD SURVACE
(SAVID, MUD, Y. CHRONOWN CHRICOLL, ETC.) Z. OTHER	J. PREMOUS CRASH	Z. OTHER	J. DIP. HUMP-CURVE Y. UNKNOWN	6. ROADWAY CONDITION II. LIGHTING
Y. UNIQUOWIN	L ANIMAL IN ROADWAY		Z OTHER	J. TRAPPIC CONTROL
	M. OQUECT IN HOADWAY Z. OTHICK	RELATION TO	ACCESS CONTROL	K. KIND OF LOCATION L. CONDITION OF PEDESTRIAN M. PEDESTRIAN ACTIONS
WEATHER	KIND OF LOCATION	ROADWAY	C	LIGHTING
A CLEAR	B	A. ON HOADWAY B. SHOULDEN	A. NO CONTROL QUALIMITED ACCESS TO	A. DAYUGHT
B. CLOUDY C. AAIN D. FOG/SMOKE		D. SEYOND SHOURDER - LEFT	BOACHINY) B. PARTIN, CONTROL	D. DARK - NO STREET UGHTS C. DARK - CONTINUOUS STREET
E. SLEET/MAIL E. SHOW	A. MANUFACTURING OR INDUSTRIAL PL BUSINESS CONTINUOUS	E. BEYOND SHOULDER - RIGHT F. BEYOND RIGHT OF WAY	C. FULL CONTROL	D. DANK - STREET LIGHT AT
G. SEVERE CROSSWIND	O. BUSINESS, MOXED RESIDENTIAL D. RESIDENTIAL DISTRICT	G. GORE Y. UNKNOWN	(ONLY RAMP ENTRANCE & EXIT) T. UNKNOWN	INTERSECTION CHLY
H. SLOVING SAND, SOIL, DAT, SNOW	E. RESIDENTIAL SCATTERED F. SCHOOL OR PLAYDROUND	Z. OTHER	Z. OTHER	E DAWN Y. UNKNOWN
Y, UNKNOWN Z, OTHER	G. OPEN COUNTRY Z. OTHER			Z. OTHER
		NAME OF TAXABLE PARTY OF TAXABLE PARTY.	CARGO	BODY TYPE
	VEHICLE CONFIGURATION	The state of the s	TOTAL STREET,	TI GEZETA J WOR
A D	G 💏 J 🚑 M	LE UNIT TRACTOR FARM	A late attended -	
PASSENGER A B C, DR S	FOR 9-15 TRU	CK W/ 3: SEMI-TRAILER COUPM		TRANSPORTER
A STATE OF THE STA	U AND V CON N S	BE RIPEV	B BEE	Ham K
B color E che	EMERGENCY BUS WISEATS	KON7 TRUCK MOTO	IR VANVENCLOSED DUMP THE	UCKU LOG TRUCKU POLE TRAILER
(RU, ETC.) MOTORCYCLE		LER DOUBLE HOM	E BOK TRAILE	TRAILER X Z
C F	(COUNTY COST P (S 🗪 Z	C design	100 mg
VAN PEDALCYCLE		AUCAU SUV OTHE	CARGO TANK CONCIN	
Tel Personati	AXLES	ACTOR		
	TIME CALLED ARRIVED SCEN	E DEPARTED SCENE ARE	SAFD HOSININT	
EMERGENCY V	1522 152	9 1613	RESCUE	1511 1519
SERVICES AMBIRANCE		D FIRE	PRAIRIEV	ILLE FD
SERVICE ACAD	IAN AMBULANC	DEPART	TMENT	
			ICATION TIME OF ARRIVAL	TIME ALL LANES OPENED
	NAME OF AGENCY	TIME OF NOTIF		1841
AGENCY LADP	S	151	3 [1 5 2 2]	五이루丁
	INVESTIGATING		112	232012
COMPLETE Y/N	AGENCY A	A STREE C. MUNISH D	ATE REPORT COMPLETED	
China no education		0	2.4	21 \ \\
D C C 0 C 11	unch	2 Brunn	BADGE	BUYET WEOR'S INTERES ON BADO
INVESTIGATING OFFICER'S NAW	E (PRUNT)	DIMMIN		

TE APPROPRIATE LETTER IN BLOC		TING FACTORS AND CO		
VISION BSCUREMENTS RAIK, SHOW, ETC. ON WENDSHIELD WOODSHIELD OTHERWISE DESCURED	CONDITION OF DRIVERUPED A. NORMAL R. NATEPIENTS C. DESTRACTED D. BLANGS D. BLANGS L. PRODUCT L. PRODUCT C. PRO		JENCE OF EVENTS/HARMFUL EN S. MOTION VENCLE IN TRANSPORT T. PARKED MOTION VENCLE U. STRIKEL'S REF PALLEDO, SHOTHING CANADORN ARE FRALEDO, SHOTHING CANADORN ARE FRALEDO, SHOTHING CANADORN ARE FRALEDOR W. WORK ZOMERAMENTENNANCE EOLEPHANE EOLEPHANE COLLISION WITH FIKED, OBJECT X. MENOT ATTENSATIONOPALISH CUSHION Y. BRIDGE OUTSPRAYAGE STRIKETURE Z. BRIDGE PAGE OR ILAPPORT A. BRODGE PAGE OR ILAPPORT A. BRODGE PAGE OR ILAPPORT F. GUARAGRAM, FACE OL. OLIVE OL. OLIVER EDMANSMENT F. GUARAGRAM, FACE OL. OLIVER OLIVERIAL FACE OLIV	L. TRAFFIC SIGN SUPPORT M. TRAFFIC SIGN SUPPORT M. TRAFFIC SIGN SUPPORT M. TRAFFIC SIGN SUPPORT M. ORLER PORT PORT OO. SUPPORT OO. SUPPORT TO MALEON OO. CHIRCH PIECE OBJECT (MALE OUT SUPPORT TO MALEON OO. CHIRCH PIECE OBJECT (MALE OO. CHIRCH PIECE PROM SHOULDER MOOST HARRING FROM SHOULDER M. ENTERING TRAFFIC FROM SHOULDER M. ENTERING TRAFFIC FROM PROMOT LAND OR PROM CHIRCH PIECE NOW AGRANIC A. CHIRCH OR CHIRCH COL MATE OF PROMP Z. GINERIOR CURRONOMN A. CHIRCH OR CHIRCH OF PROMP Z. GINERIOR CURRONOMN A. CHIRCH OR
Z. OTHER	Z. OTHER	E. NO CONTROLS Y. URINGOWN	(OR ENTER BLOOD AL	
	VEHICLE	FRALLOCATION DISTANCE TRAVE OF VEHICLES AFTER IMPACT THOU I CLE 1 5 9 THOU I CLE 1 5 9	T EST. POSTED TO TO	SKIDMARK DATA FEED. FR PL BR

INVESTIGATING OFFICER'S INITIALS

		gents	ENCE OF EVENTS/HARMFUL EV	VENTS	
AM, SAOW, ETC. ON WISCONNELD MINOCHIELD OF HERMING CAGAGURED 1900 OBSCURED BY LOAD HEES, BUSINES, ETC. MILENNOST SIGN SOARIOS ETC. MINOCHIECUS SIGN SOARIOS ELLCHIEST VERMOLES VERMOLES VERMOLES AUGUSTE SIGN SOARIOS VERMOLES AUGUSTE SIGNES DI VIERQUIGHTE DI VIERQUI VIERQUIGHTE DI VIERQUI	CONDITION OF DRIVER/PED A. NORMAN. S. NATTENTIVE C. DISTRACTED D. SLANESS E. APTICUED F. APPRIENTLY ASLEDMILACKOUT G. DENNING ALCOHOL - NOT INFANSED L. DRIVER C. NOT INFANSED L. DRIVER C. NOT INFANSED E. DRIVER C. NOT SAMPLED E. TOTAL USE - NOT SAMPLED E. STEED C. LIMIO E. TOTAL USE - NOT SAMPLED E. STEED C. LIMIO DRIVER DISTRACTION A. COLL PROVISE S. OTHER ELECTRONIC DRIVES GREGAR, PALLE PILOT, NAVIGATION DRIVES ETC.	NON COLLISION A. OVERTURENEOLICUTE E. PRECOCCIONO C. BAMERSON E. CARROSSON D. JACKSON E. CARROSSON E. CARROSS COLLISION CARROSSON C. PLESSINAN C.	ENGLE OF EVERT IN TRANSPORT T. MARKED MOTOR VERGLE U. GTRUKK OF SALLERS, SHETNOS CARDO OR ANTTHING SET OR NOTION DE MOTOR VERGLE U. WORK ZONEMAINTENANCE COLCEMENT W. GREEN RON-TIXED OBJECT Z. SIMMET ATTERMATORYCHASH OURHOR V. BREDGE PAUL Z. GREDGE PAUL Z. GRE	LL TRAFFIC SIGNS SUPPORT HIM. TRAFFIC SIGNS, SUPPORT NI. OTHER POST, POLE. OR SUPPORT OP. FENCE P. MALLEDX OR. OTHER POST OR SIGN OF THE POST OR SIGN OF THE BULDING, TURNEL, EPC) TV. LINSTOWNS	
EXCESOING STATED SPEED LIMIT EXCEEDING SAFE SPEED LIMIT FALLIER TO YIELD	C, OTHER INSIDE THE VEHICLE D, OTHER OUTSIDE THE VEHICLE E, NOT DISTRACTED	MOVEMENT PRIOR	TO CRASH	S	
FOLLOWING TOO CLOSELY ON-HONE OF CENTER OF CENTER OF CHINTER OF CH	REASON FOR MOVEMENT A TO AVOID OTHER VEHICLE B. TO AVOID PEDESTRIAN C. TO AVOID SHEET VEHICLE B. TO AVOID SHEET VEHICLE B. TO AVOID OTHER OBJECT F. YENGLE OUT OF CONTROL, NOT RESERVE A. YENGLE OUT OF CONTROL, WE HAVE BUT OF CONTROL B. FOR THAPPIC CONTROL B. DUE TO	A STOPPED A PROCESSION STRAIGHT ANEAD C. PROCESSION STRAIGHT ANEAD C. TRUGELING WESTING WAY OF THE CONTROL AND	K. STOPPED PREPARAIN TO, OR MANING E-TURNS ON MANING E-TURNS ON MANING E-TURN OF MANING TO TOPPE E-TURN E-T	T. ENTORNA'T TRAFFIC FROM SHOULDER. U. ENTERHING TRAFFIC FROM METERNA TRAFFIC FROM PROVIDED AND TRAFFIC FROM PROVIDED AND TRAFFIC FROM PRIORE LAND TRAFFIC FROM TRAFFIC FROM TRAFFIC FROM TRAFFIC FROM THE TRAFFI	
CARDLESS OPENATION IMPROVED SECURIOR IND WOLKHOME UNINSWOME UNINSWED IN UNINSWOME UNINSWED IN UNINSWED	J. DUE TO PRIOR CRUSHIS COLLEGES. K. DUE TO DEVICE VOICE TO THE VICTOR TO DEVICE VOICE TO DEVICE VOICE TO THE VICTOR TO THE VICTOR TO PRIVED VOICE VO	VEHICLE CONDITION	ALCOHOL/DRUG NNOCLYEMENT ALCOHOL/DRUG NNOCLYEMENT ALCOHOL/DRUG NNOCLYEMENT ALCOHOL ALCOHOL C. YES-ALCOHOL C. YES-ALCOHOL C. YES-ALCOHOL C. YES-ALCOHOL A TEST REPUSED B. NO TEST GOVEN, RESULTS PENDING C. TEST		
HEADED ON HIGH	MAY STREET OR DRIVE A T B 1 0 O	OF VEHICLES AFTER IMPACT F F 4 3 0 O A D	gar. rosten	0 ' 0 ' 0 ' 0	
		UAU I	CITATIONS		
AREA DAMAGE TO AREA DAMAGED A TO ST TO S	The second second second	NONE:			
Y- UNKCOOKIN					



		,	0	PU					6	0		07
2	0	1	2	U	0	4	4	1	0	U	-	01

OFFICER'S NARRATIVE: DESCRIBE ANY UNUSUAL CIRCUMSTANCES ASSOCIATED WITH CRASH, INCLUDING OFFICER'S OBSERVATIONS AND OPINIONS.
INCLUDED WITNESS NAMES, ADDRESSES, PHONE NUMBERS, ETC.
IF NECESSARY, INDICATE DAMAGE TO PRIVATE PROPERTY (WITH OWNER'S NAME AND ADDRESS) AT THE END OF THE NARRATIVE REFER TO EACH VEHICLE BY VEHICLE NUMBER.

On Friday, December 7, 2012, at 1513 hours, I, Trooper S. Bunch #2421 of the Louisiana State Police - Troop A, responded to a call of a motor vehicle crash, with injuries, on Interstate 10. The crash occurred on Interstate 10 at Mile Post 169.11, east of Louisiana Highway 928 (Bluff Road overpass) in Ascension Parish. Upon my arrival, at 1522 hours, I observed numerous civilians, Prairieville Fire Fighters and Department of Public Safety Police Officer S. Cotten #6368 on the scene. The inside westbound lane and both eastbound lanes of Interstate 10 were closed by emergency vehicles.

Prior to my arrival, Officer S. Cotten arrived on the scene at 1515 hours and began assessing the scene. When I spoke with Officer Cotten, I learned at least two vehicles were involved in the crash. The driver of a Ford F-350 had identified himself to Officer Cotten as the person pulling a trailer, which had become detached from his vehicle and was involved in the crash. Officer Cotten also informed me the driver of a Ford Ranger had sustained serious injuries and was unresponsive. At this time, fire fighters were giving aid to the driver of the Ford Ranger. Officer Cotten pointed out the driver of the F-350 to me and I walked over to speak with him. I spoke with the driver of the F-350, got his driver's license, and told him not to leave the scene until I spoke with him further. I spoke with the fire fighters that were giving aid to the driver of Ford Ranger and they said he was probably not going to survive his injuries. Fire fighters gave me a wallet that belonged to the driver of the Ford Ranger. I found a Texas driver's license, number 28744552, inside the wallet and identified the driver of the Ford Ranger as David L. Hammer of League City, TX.

Senior Trooper PB Rivera #2033 arrived on the scene at 1522 hours and Master Trooper S. Latimer #1708 arrived on the scene at 1530 hours. M/T Latimer, S/T Rivera and I began identifying and speaking with witnesses. Each of the witnesses gave a brief synopsis of the crash. Collectively, all of the witnesses confirmed the trailer detached from the F-350, crossed the center median and struck the Ford Ranger. Some of the witnesses said they immediately ran to Mr. Hammer's aid, but he was unresponsive when they got to him. Written statements were eventually collected from the witnesses (see attached).

Interstate 10 is a four-lane highway divided by an un-raised grassy median. Eastbound and westbound Interstate 10 has inside and outside lanes on each side of the highway. The inner edges of the inside lanes are marked with a yellow no passing line, boarded by a narrow shoulder. White dashed lines and white reflectors separate the inside and outside lanes. The outside lanes are marked with solid white fog lines and boarded by a wide concrete shoulder. In this section, retaining wires and metal guardrails divide the grassy median. There is a gap between the retaining wires and the metal guardrails, 25.6 feet in length. All lane markings are in good condition and were clearly visible. The edges of the roadway had no effect on this crash and there are no roadway edge drop-offs on either side.

At 1548 hours, Sgt. J. Martin #2031 arrived on the scene. M/T Latimer, Sgt. Martin and I inspected the area and found numerous tire marks in the center median, eastbound lanes and beyond the outside eastbound shoulder. The two tire marks found in the center median extended in a southeastern direction, towards the eastbound lanes. The first tire mark in the center median began on the inside roadway edge of the westbound lanes, 46.6 feet east of the end of the retaining wires. This tire mark extended into and through the gap between the retaining wires and the guardrail. This tire mark was 98.8 feet in length. The second tire mark in the center median began 28.3 feet south of the inside roadway edge of the westbound lanes and 5.3 feet east of the end of the retaining wires. This tire mark extended into and through the gap between the retaining wires and the guardrail. This tire mark was 22.2 feet in length. In the inside eastbound lane, multiple tire marks made up three large circular patterns,

INVESTIGATING OFFICER'S INITIALS SPO



COMPUTER NUMBER										P	AG	E#	
2	0	1	2	0	0	4	2	7	6	0	-	0	8

OFFICER'S NARRATIVE: DESCRIBE ANY UNUSUAL CIRCUMSTANCES ASSOCIATED WITH CRASH, INCLUDING OFFICER'S OBSERVATIONS AND OPINIONS.
INCLUDED WITNESS NAMES, ADDRESSES, PHONE NUMBERS, ETC.
IF NECESSARY, INDICATE DAMAGE TO PRIVATE PROPERTY (WITH OWNER'S NAME AND ADDRESS) AT THE END OF THE NARRATIVE IF NECESSARY, INDICATE DAMAGE TO PRIVATE PROPERTY WITH OWNER'S NAME AND ADDRESS) AT THE END OF THE NARRATIVE REFER TO EACH VEHICLE BY VEHICLE NUMBER

which began 55.9 feet west of the end of the retaining wires and ended 30.8 feet west of the end of the retaining wires. The circular tire marks stretched from the inner edge and fog line of the inside lane to approximately the center of the lane. 4.4 feet northwest of the beginning of the circular tire marks was a scrub mark between the inside roadway edge and the inside fog line. 7.1 feet southwest of this scrub mark was the ending of a 2.8 feet in length scrub mark that extended in a northeastern direction, from the center of the inside eastbound lane towards the inside fog line. 8.7 Feet west of the ending of this scrub mark was a third scrub mark, near the inside fog line. 6.1 feet southwest of this scrub mark was the beginning of a tire mark that extended 9.6 feet in a southeastern direction. 5.5 feet south of this tire mark was a parallel tire mark that was 10.9 feet in length. 24.4 east of this tire mark, on the outside fog line, were two scrub marks. 8.3 feet north of these scrub marks was a tire mark that extended east 4.4 feet in length in the center of the outside eastbound lane. 15.7 feet southeast of the end of this tire mark was the beginning of another tire mark, which started near the outside fog line. This tire mark was 37.9 feet in length and extended towards the outside edge of the eastbound lanes. 35.5 feet southeast of the end of this tire mark, in the grassy area beyond the outer edge of the eastbound lanes, was the beginning of three tire marks. These tire marks arched in a northwestern direction, extending into and through a shallow ditch and back towards the eastbound lanes. These tire marks were 220 feet in length and ended near the outside roadway edge of the eastbound lanes. On the outside edge of the roadway, at the ending of these tire marks, a fluid trail began and continued the northwestern arch of the tire marks. The fluid trail extended 60.8 across the eastbound lanes and shoulders and ended near the inside roadway edge. The end of the fluid trail was 12.1 feet south of the left rear tire of the Ford Ranger.

Vehicle 1, a 2001 blue/tan Ford F-350 dually, bearing Louisiana license plate number B754865, was facing west, stopped on the westbound outside shoulder. An inspection of Vehicle 1 showed it sustained no damage. A trailer hitch, with three trailer balls, was attached to the frame, secured with a safety pin. A two-damage in the up position. On the frame, on both side of the trailer hitch were eyelets designed to attach safety chains to secure a towed vehicle or trailer. I inspected the eyelets and found no signs of any hooks or other safety mechanisms attached to them. A close inspection of the eyelets showed no markings or damage on them. While inspecting Vehicle 1, I checked the tire pressure and tread depth. Vehicle 1 had the following tread depth/tire pressure: driver side front (4/32 and 46 psi), passenger side front (5/32 and 51 psi), and passenger side rear (right 3/32 unknown psi, left 5/32 unknown psi), and driver side rear (right 4/32 unknown psi, left 2/32 unknown psi). The psi on the four rear tires is unknown because I was not able to reach the air valves on the tires. The rear tires did not appear to be over or under inflated and did not appear to be a factor in the crash.

Vehicle 1's trailer, a 2009 black RDT utility trailer, bearing Louisiana license plate L138489, was facing southeast, stopped in the center median on the southern side of the metal guardrails. The trailer sustained moderate damage in the crash to its tongue, right front side and minor damage to its right rear side. The right side of the tongue was bent inward, and had a small amount of blood and flesh on it. Attached to the tongue were two safety chains. An inspection of the chains showed there were no hooks on the ends of them or on any of the links. The inspection also showed there were no markings or damage to the end links. While inspecting the trailer, I checked the tire pressure and tread depth. The trailer had the following tread depth/tire pressure: left front (6/32 and 34 psi), left rear (6/32 and 34 psi), right front (5/32 and 19 psi), and right rear (6/32 and 35 psi).

Vehicle 2, a 1998 green Ford Ranger, bearing Texas license plate number 9628AK, was facing north, stopped in the center median with its front end against the retaining wires. The Ranger had severe damage to the front and driver's side, which protruded into the engine and passenger compartments. The Ranger also INVESTIGATING OFFICER'S INITIALS.



		C	OM	PU	TER	NU	MB	EK		_	, ,	MG	CR
2	0	1	2	0	0	4	2	7	6	0	-	0	9
		_											
-	2	2 0	2 0 1	2 0 1 2	2 0 1 2 0	2 0 1 2 0 0	2 0 1 2 0 0 4	2 0 1 2 0 0 4 2	2 0 1 2 0 0 4 2 7	2 0 1 2 0 0 4 2 7 6	2 0 1 2 0 0 4 2 7 6 0	2 0 1 2 0 0 4 2 7 6 0 -	2 0 1 2 0 0 4 2 7 6 0 - 0

OFFICER'S NARRATIVE: DESCRIBE ANY UNUSUAL CIRCUMSTANCES ASSOCIATED WITH CRASH, INCLUDING OFFICER'S OBSERVATIONS AND OPINIONS. DESCRIBE ANY UNUSUAL CREDMET AND EXPOSED THE NAMES, ADDRESSES, PHONE NUMBERS, ETC.
INCLUDED WITNESS NAMES, ADDRESSES, PHONE NUMBERS, ETC.
IF NECESSARY, INDICATE DAMAGE TO PRIVATE PROPERTY (WITH OWNER'S NAME AND ADDRESS) AT THE END OF THE NARRATIVE
IF NECESSARY, INDICATE DAMAGE TO PRIVATE PROPERTY (WITH OWNER'S NAME AND ADDRESS) AT THE END OF THE NARRATIVE
REFER TO EACH VEHICLE BY VEHICLE NUMBER

sustained minor damage to its rear driver's side. While inspecting Vehicle 2, I checked the tire pressure and tread depth. Vehicle 2 had the following tread depth/tire pressure: driver side front (7/32 and 0 psi), driver side rear (7/32 and 41 psi), passenger side front (7/32 and 38 psi), and passenger side rear (7/32 and 40 psi).

Near Vehicle 2, I observed tire marks and a liquid debris trail that led up to its rear end. The tire marks and liquid debris trail began in the center of the eastbound lanes, near the circular tire marks, and pointed in the

direction of the path Vehicle 2 took after impact.

The driver of Vehicle 1 was identified at the scene as Michael B. Munson, with Louisiana driver's license number 6365122. I advised Mr. Munson of his Miranda rights and said he understood them. Mr. Munson gave verbal and written statements on the scene. Mr. Munson verbally stated he was traveling westbound on Interstate 10 in the outside lane at about 70 mph when his trailer began to sway side to side. Mr. Munson said he hit his brakes and began merging onto the outside shoulder. Mr. Munson said as he moved onto the shoulder, his trailer became detached and shot across both westbound lanes. Mr. Munson said his trailer went through an opening in the median and struck another vehicle traveling in the eastbound lanes. In his written statement, Mr. Munson stated:

"I was driving I-10 west when the trailer came off my truck in the right lane. The trailer took off into the middle of the Interstate into eastbound side near Bluff Road. I was driving 70 mph whenever thing happen."

Mr. Munson sustained no injuries in the crash. Mr. Munson was taken from the scene to Troop A at 1644 hours by S/T Rivera for chemical testing. Mr. Munson voluntarily submitted to the Intoxilyzer 5000 test at 1714 hours, and the results indicated a blood alcohol concentration of .000g%. Mr. Munson showed no signs of impairment. Mr. Munson voluntarily submitted a urine sample. Mr. Munson's urine sample was later logged in at Troop A as evidence to be forwarded to State Police Crime Lab for testing. Results are pending at this time. A written consent to search Vehicle 1 was signed by Mr. Munson. M/T Latimer and I searched Vehicle 1. The search was an attempt to locate any other trailer hitches and/or trailer ball assemblies, other than the one observed on the rear of Vehicle 1. The search had negative results.

While on scene, S/T Rivera and I spoke with five witnesses and the passenger of Vehicle 1. The

following written statements were collected:

Vehicle 1's passenger Jerry Chatman stated,

"I look back and the trail was good."

Witness William Bayhi Jr stated,

"Was heading east on I-10. Noticed trailer coming across the median from westbound I-10. The green truck in trailer and the truck that was hit by the front of me was struck on driver front side by trailer. I swerved to avoid the trailer. Came to a stop and noticed the truck that was hit by the trailer was sitting in the center guard wires. Me and several others ran to vehicle and noticed he was not moving. Dialed 911."

Witness Theodise M. Collins stated,

INVESTIGATING OFFICER'S INITIALS	SPA
INVESTIGATING OFFICER'S INITIALS	110

STATE OF LOUISIANA UNIFORM MOTOR VEHICLE TRAFFIC CRASH REPORT NARRATIVE SUPPLEMENT
--

-	_	EK	MB	NU	TER	PU	OM	C		
0	6	7	2	4	0	0	2	1	0	2

OFFICER'S NARRATIVE: DESCRIBE ANY UNUSUAL CIRCUMSTANCES ASSOCIATED WITH CRASH, INCLUDING OFFICER'S OBSERVATIONS AND OPINIONS.
INCLUDED WITNESS NAMES, ADDRESSES, PHONE NUMBERS, ETC.
IF NECESSARY, INDICATE DAMAGE TO PRIVATE PROPERTY (WITH OWNER'S NAME AND ADDRESS) AT THE END OF THE NARRATIVE REFER TO EACH VEHICLE BY VEHICLE NUMBER

At approximately 1841 hours, Vehicle 1's trailer and Vehicle 2 was removed from the scene by Gonzales Towing, and all lanes were cleared of debris and reopened. S/T Rivera and M/T Latimer took photos of the scene and both vehicles. The photos were later uploaded to the Louisiana State Police crash photo

At approximately 1730 hours, notification was made to David L. Hammer's next of kin. Andy Hammer, 4024 Ioda Street, Metairie, LA (504) 430-7603, David Hammer's son, called Troop A and spoke with Sgt. M. Stupka #1890. Andy said he was trying to locate his father, who he had not heard from since about 1400 hours. Andy said his father was on his way to visit him in Metairie, LA and he had not arrived. Sgt. Stupka informed Andy his father was involved in a motor vehicle crash and he did not survive his injuries.

On December 8, 2012, at approximately 0900 hours, M/T Latimer and I returned to the scene. We canvassed the area trying to locate any evidence that would suggest Vehicle 1's trailer had safety chains attached when it disconnected. No evidence was found. While on scene, Master Trooper S. Latimer and I measured the scene with the Total Station Survey Equipment. M/T Latimer later used the data collected from the measurements to draw the diagrams of the crash scene.


On December 8, 2012 at approximately 1330 hours, M/T Latimer and I arrived Gonzales Towing storage yard. Andy Hammer and other family members met us at this location. Andy was allowed to retrieve David L. Hammer's personal belongings from Vehicle 2. M/T Latimer and I further inspected Vehicle 1's trailer and Vehicle 2. While inspecting the trailer, we noticed the trailer ball latch was missing. The latch was found in the cab of Vehicle 2, on the passenger side floorboard. We searched the interior of Vehicle 2 for other parts that may have been transferred between vehicles during impact. No other items, specifically safety chain hooks, were found in or on Vehicle 2.

The on-scene evidence, vehicle damage, witness and driver statements suggest that on December 7, 2012 at approximately 1510 hours, Vehicle 1 was traveling westbound in the outside lane on Interstate 10 as Vehicle 2 was traveling eastbound in the inside lane Interstate 10. As both vehicles approached each other from opposite directions, Vehicle 1's trailer began to sway side to side. As Vehicle 1 began moving onto the westbound outside shoulder, the trailer detached from Vehicle 1 and crossed both westbound lanes. Vehicle 1 came to a controlled stop on the westbound outside shoulder as the trailer left the roadway to its left. The trailer entered and crossed the median through an opening between the retaining wires and metal guardrails. The trailer entered the inside eastbound lanes and struck Vehicle 2. The tongue and right corner of the trailer pierced the driver's side engine and passenger compartments of Vehicle 2, striking David L. Hammer. After the impact, the trailer spun around, traveling 59 feet, and came to rest in the center median. Vehicle 2 crossed over the outside eastbound lane and shoulder, leaving to roadway to its right. Vehicle 2 traveled 255.5 feet in the grass, as it rolled through a shallow ditch and up a small hill. The hill redirected Vehicle 2's path and it crossed back through the shallow ditch and then back into the eastbound lanes. Vehicle 2 crossed over the eastbound lanes and entered the center median. Vehicle 2 came to rest when its front end struck the retaining wires.


Mr. Munson has been charged with L.R.S. 32:384 Trailers and Towed Vehicles and L.R.S. 14:32 Negligent Homicide. For further information on Mr. Munson's arrest, see Louisiana State Police Criminal Arrest Report under Incident Number 12-9919.

INVESTIGATING OFFICER'S INITIALS _	SPB


MAUC IL




PHUE 13



THUIL 1



rHu- 1



REPORT # 20120042760

Louisiana State Police

Measurement Data Log

M/T S. Latimer Scene Measured By 20120042760 File Number ID Number (measured by) 1708 Incident Date/Time 7-Dec-2012 03:10 PM TFC S. Bunch Scene Assisted By Incident Location I-10 at La 928 Overpass ID Number (assisted by) 2421 8-Dec-2012 Date Measured On 61.2' East from Point 2 Reference Point Description Weather Description Clear Secondary Reference Point 67.6' West from Point 5 Concrete - Dry Visibility Description Unlimited

Description Point North South East West Inst Point 0.0000 0.0000 Bridge Support La 928 11.1400 2 60.1600 Guard Rail 2.5200 3 60.4200 Guard Rail End 4.3600 14,5600 4 Retaining Wire 10.4600 66.7400 5 End Guard Rall End 45.6800 4.1200 6 Guard Rall 30.9600 8.3800 7 Guard Rail 13,5200 1.4800 8 Guard Rail 15.3800 16.0000 9 Tire Mark 22.6600 10 117,0000 Tire Mark 15.2000 95,1200 11 Tire Mark 9.2400 12 79.9000 Tire Mark 61.0800 1.4600 13 Tire Mark End 33,4000 10.0800 14 10,1600 Tire Mark 52,4600 15 Tire Mark 1,6600 72,9200 16 Left Tire Vehicle 9.7800 41.5200 17 Right Tire 5.2400 35.1000 18 Vehicle 1 Right Tire 7.4000 33.4200 19 Vehicle 1 18,1800 Trailer Hitch 20 30.1200 Edge of Road 21.0200 16.8000 21 Fog Line 25,6800 22 16.5800 Tire Scrub 28.2400 6.6200 23

Printed from Fx3

SPA

REPORT# 20120042760

6.6200 9.7200 0.5400 0.2400	1.8000 7.5400 9.0400 20.6400 25.9400 14.7400		28.2400 33.4400 36.2000 32.1400 30.2800 26.0400 30.2000 31.9600	Tire Scrub Start of Tire Mark End of Tire Mark Start of Tire Scrub End of Tire Scrub Tire Scrub Start of Tire Mark Milpoint of Tire Mark
0.5400	7.5400 9.0400 20.6400 25.9400 14.7400		36.2000 32.1400 30.2800 26.0400 30.2000 31.9600	Mark End of Tire Mark Start of Tire Scrub End of Tire Scurb Tire Scurb Tire Scrub Start of Tire Mark Midpoint of Tire
	7.5400 9.0400 20.6400 25.9400 14.7400		32.1400 30.2800 26.0400 30.2000 31.9600	Start of Tire Scrub End of Tire Scurb Tire Scrub Start of Tire Mark Midpoint of Tire
0.2400	7.5400 9.0400 20.6400 25.9400 14.7400		30.2800 26.0400 30.2000 31.9600	Scrub End of Tire Scurb Tire Scrub Start of Tire Mark Midpoint of Tire
	7.5400 9.0400 20.6400 25.9400 14.7400		26.0400 30.2000 31.9600	Scurb Tire Scrub Start of Tire Mark Midpoint of Tire
	9.0400 20.6400 25.9400 14.7400		30.2000 31.9600	Start of Tire Mark Midpoint of Tire
	20.6400 25.9400 14.7400		31.9600	Mark Midpoint of Tire
	25.9400 14.7400			
	14.7400			11100111
			28.0400	End of Tire Mark
	22 4000		24.8000	Start of Tire Mark
	23.4600		32.4800	Midpoint of Tire Mark
	29.9800		29,0200	End of Tire Mark
	29.4000		25.1800	End of Tire Mark
	21.1800		25.0200	Start of Tire Mark
	26.4600		31.9600	Midpoint of Tire Mark
	34.1600		26.1400	End of Tire Mark
	32.2600		25.8600	Edge of Road
11.6800			38.5600	Start of Tire Mark
1.7400			43.0800	End of Tire Mark
2.1600			38.1600	Centerline
	21.6000		43.6800	Start of Tire Mark
	25.8200		44.9400	End of Tire Mark
	18.5200		52.5000	Tire Scrub
	22.9800		52.5400	Tire Scrub
	39.3600		52.9000	Start of Tire Mark
	74.1000		68.1000	End of Tire Mark
	74.3200		57.4400	Fog Line
	76,7000		45.9000	Centerline
	33,3000		53.3800	Fog Line
	30.2800		63.8200	Edge of Road
	34.3600		30.6600	Fog Line
	33.7200		25.8400	Edge of Road
			38.3600	Retaining Wire
	_		38.2600	Front Left Tire
			39.8000	Front Right Tire
				Rear Left Tire
				Fluid Trail
			72,4200	Fluid Trail
	303.0000			rulu Itali
		2.1600 21.6000 25.8200 18.5200 22.9800 39.3600 74.1000 74.3200 76.7000 33.3000 30.2800 34.3600 33.7200 361.4800 371.6400 376.8400 376.8400 365.7600	2.1600 21.6000 25.8200 18.5200 22.9800 39.3600 74.1000 74.3200 76.7000 33.3000 30.2800 34.3600	2.1600 38.1600 21.6000 43.6800 25.8200 44.9400 18.5200 52.5000 22.9800 52.5400 39.3600 52.9000 74.1000 68.1000 74.3200 57.4400 76.7000 45.9000 33.3000 53.3800 30.2800 63.8200 34.3600 30.6600 33.7200 25.8400 361.4800 38.3600 371.6400 38.2600 376.8400 39.8000 367.9400 46.9400 365.7600 58.8800

Printed from Fx3

510

REPORT# 20120042760

Point	North	South	East	West	Description
61		337.8800		82.8400	Fluid Trail
62		322.7800		91.9200	Tire Mark on Road
63		288.3800		102.3200	Tire Mark Midpoint
64		216.1800		107.2200	Tire Mark Midpoint
65		163.6200		102.3000	Tire Mark Midpoint
66		109.1000		85.4800	Tire Mark Start
67		107.7800		79.8600	Start of Tire Mark
68		151.6200		94.2800	Tire Mark Midpoint
69		215.8000		102.2400	Tire Mark MidpoInt
70		278.6000		98.1800	Tire Mark Midpoint
71		278.5400		98.1600	Duplicate Poin
72		312.3000		90.8200	End of Tire Ma
73		320.0400		91.5600	End of Tire Ma
74		263.5200		104.6600	Tire Mark Midpoint
75		194.7200		107.8400	Tire Mark Midpoint
76		166.4200		105.3800	Tire Mark Midpoint
77		105.0600		84.8600	Start of Tire Mark
78		10.2800	37.0600		Fog Line Westbound
79		65.8400	31.8600		Fog Line Westbound

Printed from Fx3

SPL

0 10 00
STATE OF LOUISIANA
UNIFORM MOTOR VEHICLE TRAFFIC CRASH REPORT
DRIVER/WITNESS VOLUNTARY STATEMENT

COMPUTER NUMBER							P	AG	E#				
Z	0	l	2	O	0	4	2	7	6	0	-	1	8

DATE 12/7/17 TIME 3:00 DAN PLACE THE SLATE I-10 West
Michael Munsed AM 35 YEARS OF AGE,
MY ADDRESS IS 219 35 St Donaldsonville LA 70346
AND MY TELEPHONE NUMBER IS (215) 279 - 9287 CELL
TIN I I I I I I I I I A COME DOES NOT MAN
I was driving I-10 west when the trailer came tose Off My
Truck IN the right Lane, The Fig. 12 Bit IN THE
Mille Of the INSENSIGN IN to East Bound The Print
Must Road Over WASS. I (IN CHISANG TO MEN DREW THE
trapper.
·
THE ABOVE STATEMENT, TO THE BEST OF MY KNOWLEDGE, IS A TRUE AND CORRECT ACCOUNT OF MY RECOLLECTION IN THE ABOVE DESCRIBED MOTOR VEHICLE CRASH
SIGNED: Nuchal Naya
OFFICER TAKING STATEMENT: S/T PB Rivera #2033
SIGNATURE: 5 /75 C STORES
DPSSP 3111 (REV. JAN, 2005)

15.	UNIFORM MOTOR VEHICL	OF TOUISIANA E TRAFFIC CRASH REPORT DEUNTARY STATEMENT	Z0120042760 - 19
DATE 12 7 - 2 I. 201 WA MY ADDRESS IS AND MY TELEPHON	DOLCSVISI NENUMBERIS (7	2 As 47 48 0	2-9-58 WEARS OF AGE,
	100d.	CK WITC	
THE ABOVE STA	MY RECOLLECTION IN	ST OF MY KNOWLEI THE ABOVE DESCR	OGE, IS A TRUE AND CORRECT IBED MOTOR VEHICLE CRASH
	OFFICER TAK	ING STATEMENT: _	S/T PB Rivera #2033
		SIGNATURE: _	BIVESTIGATING OFFICER'S INITIALS PER SM

	STATE OF LOUISIANA UNIFORM MOTOR VEHICLE TRAFFIC CRASH RE DRIVER/WITNESS VOLUNTARY STATEMEN	COMPUTER NUMBER PAGE # EPORT Z01200 42760
DATE 12/7/12	TIME 3:35 PLACE 1-10	M168
1. William Bay	1205 49th St Metail	YEARS OF AGE,
MY ADDRESS IS	3205 49th S+ Metail	rie La, 70001
AND MY TELEPHON	E NUMBER IS (<u>504</u>) <u>453</u> – 099	99
Was heading	East on I-10. Noticed.	trailer comingacross
the mediane	From West bound I-10.	The green truckin
frant of w	e was struck and div	er front side by
trailor . I	sperved to avoid the	trailer and the truck
11.4.20= 5	+ h. Mr trailer. (am	ie to a stop and
11 -11	do a billet in a hit Di	. The trailer was
c 11 1	a newler alland w.	NS.
ITTE GIVA	Send of the State of	OCICIO ST
Noticed he	was not moving. Dial	led 911.
	~	
		-
THE ABOVE STAT	TEMENT, TO THE BEST OF MY KNOWLE Y RECOLLECTION IN THE ABOVE DESC	EDGE, IS A TRUE AND CORRECT CRIBED MOTOR VEHICLE CRASH
SIGNED: William	: Prushig	
(OFFICER TAKING STATEMENT:	R S BWCH
	SIGNATURE:	M Xximm
	SIGNAL OIL	INVESTIGATING OFFICER'S INITIALS SP
DPSSP 3111 (REV. JAN. 2006)		INVESTIGATING OFFICER & MILIAUD

STATE OF LOUISIANA UNIFORM MOTOR VEHICLE TRAFFIC CRASH REPORT DRIVER/WITNESS VOLUNTARY STATEMENT 201200 42760	
DATE 12-07-12 TIME 3 pm PLACE T-10 (East) I, Theodise M. Collins AM. 46 YEARS OF AGE	,
MY ADDRESS IS 1808 Wagner St New Orleans LA 70114 AND MY TELEPHONE NUMBER IS (504) a20 - 5303 Twos traveling East on I-10 - with when I noted a trailer cross the median. The trailer hit a green truck traveling East on I-10 in front of me (app. 3 cars in front of me). I immediately pulled over to the left side of the interstate and	-
checked for vital signs - none noted.	
	_
THE ABOVE STATEMENT, TO THE BEST OF MY KNOWLEDGE, IS A TRUE AND CORRECT ACCOUNT OF MY RECOLLECTION IN THE ABOVE DESCRIBED MOTOR VEHICLE CRASH	
SIGNED:	
DPSSP 3111 (REV. JAN. 2005)	

STATE OF LOUISIANA
INIFORM MOTOR VEHICLE TRAFFIC CRASH REPORT
DRIVER/WITNESS VOLUNTARY STATEMENT

COMPUTER NUMBER		PAG	E #
	-	2	7
20120042760			

DATE DEREMBER 7, 2012 TIME 3:5/p	PLACE	73	
		45	YEARS OF AGE,
MY ADDRESS IS 8020 PLACIS	ST., N. 0	LA.	78128
AND MY TELEPHONE NUMBER IS (504) 628 -	7773	ELL.

PAROX. 3:30 P., I WAS PARKED ON THE ESHOULDER TRAFFIC TO ENTER OOKED INST AHEAD TRAILER WENT VA CANTINUED THE EAST SIDE OF I'IO DRIVING EAST BOWN D THE LEFT SINE OF THE TRUCK, LAUSING AND SWARVE F RO M ON TO THE RIGHT LANE BNA BACK WIRE GHARD RAIL HEAD OF THE I. 10 TO ASSIST THE MOVED ClastR. , AS I CRUSHE THE DRIVER WAS To RESPONSIVE, ASKED OTHER DRIVERS

THE ABOVE STATEMENT, TO THE BEST OF MY KNOWLEDGE, IS A TRUE AND CORRECT ACCOUNT OF MY RECOLLECTION IN THE ABOVE DESCRIBED MOTOR VEHICLE CRASH

OFFICER TAKING STATEMENT: TM S.BWCH

SIGNATURE: TM S.BWCH

SIGNATURE: TM S.BWCH


SIGNATURE: TM S.BWCH

DPSSP 3111 (REV. JAN. 2006)

[4]	STATE OF LOUIS UNIFORM MOTOR VEHICLE TRAFF DRIVERWITNESS VOLUNTAR	TIC CRASH REPORT	COMPUTER NUMBE 201200427	
DATE 12/7/12 I, Francisco Zoo MY ADDRESS IS 835 AND MY TELEPHONE NI	TIME 3:50 Her 5 Shodyglon aus UMBERIS (225)	AM	29 YEARS	F Road S OF AGE, 70816
while travelie as 10 feet as a trailer. The mergers into Trailer become in front of a truck hea	3:08 pm who, I, Francisco invaluing a ing on left way from the re priver of end suddenly it that man the shoulder es detached from me hitteng don from as about 70 gaing approx	trader the Drive the Veh made of the M one the pposite mah, the	the trailed and such a rail and traffic. Me	close close close whipped become he prider darly the crosses striking speed of
THE ABOVE STATES ACCOUNT OF MY R	MENT, TO THE BEST OF ECOLLECTION IN THE	7/12	DGE, IS A TRUE AND RIBED MOTOR VEHIC S/T. PB Rivers	JEE GIVOIT
DPSSP 3111 (REV. JAN, 2005)			INVESTIGATING OFFICER'S INITIALS	= PBR -SM

UITMOSS

STATE OF LOUISIANA UNIFORM MOTOR VEHICLE TRAFFIC CRASH REPORT DRIVERWITNESS VOLUNTARY STATEMENT



DATE 12 7 12 TIME 1550 PLACE 10 W Brush Pal Overphil
HEATH M VELLEMAN AM 3! YEARS OF AGE,
MY ADDRESS IS P.O. BOX 7758 Pineville LA 71361
AND MY TELEPHONE NUMBER IS (3.8) 447 - 1598
Headed WEST IN I'M TO Before Bluff RD OVERPASS.
Million in Might LANE: TAKVELING KBOW 60-65NPOS.
THE TRUCK IN FRINT OF ME, AMOUNT (500 HT, HAT) A TRATICER WAS
STANTED WEEKING SIDE TO SIDE. THE MATCHE MINORED FROM THE
Truck kno oniday crosses The LEFT LANE TUST IN FRONT
or Amorten voltient The THAILER CRISSED THE MEDIAN BEFORE
THE OFFIRES IN THE ONLY ANDE WITHOUT CADIE. IT IMMEDITIEN
I'M THE DRIVER'S SIDE OF HE ON COMING TRUCK IN THE
IF 110 EAST LANET. THE TRULE SWETWEN TO THE DIGHT OF THE
DAD THEN SHEWED BACK ACROSS THE LAND SHOTH MEDIAN
AND HIT THE PAUL. I PULLED DUEN AND RAW TO THE TRULE
Tried To cottel A Print But The Driver ULAS BADON (MULLEY)
KIND DECEMBED. HTS LEG WIR DEGLOVED AND THE BODY WAS CONTONIED.
WAS project to for to simulate the Oriver of MAGNEY.
PIEGAN TO PULL OUGH AND CHECK ON THE VALVETLAS VOCAL.
TO A TRUE AND CORRECT
THE ABOVE STATEMENT, TO THE BEST OF MY KNOWLEDGE, IS A TRUE AND CORRECT ACCOUNT OF MY RECOLLECTION IN THE ABOVE DESCRIBED MOTOR VEHICLE CRASH
ACCOUNT OF MY RECOLLECTION IN THE ABOVE DECOME
SIGNED:
OFFICER TAKING STATEMENT: S/T PB Rivera #2033
SIGNATURE: 5/400 033
INVESTIGATING OFFICER'S INITIALS PER SPS
DPSSP 3111 (REV. JAN, 2005)

SDC10100.JPG; SDC10101.JPG; SDC10102.JPG; SDC10103.JPG; SDC10104.JPG; SDC10105.JPG; SDC10106.JPG; SDC10107.JPG; SDC10108.JPG; SDC10109.JPG; SDC10110.JPG; SDC10111.JPG; SDC10112.JPG; SDC10113.JPG; SDC10114.JPG; SDC10115.JPG; SDC10116.JPG; SDC10117.JPG; SDC10118.JPG; SDC10119.JPG; ATTZR8TV.JPG; ATTKARWS.JPG; ATTCTDER.JPG; ATT1XFV3.JPG; ATTAZW0U.JPG; ATTUOW2H.JPG; ATT5Q1DO.JPG; ATT6YGQN.JPG; ATTAT2ZF.JPG; ATTS4R26.JPG; ATT8302A.JPG; ATTQBTPI.JPG; ATTCCTUQ.JPG; ATT3DBT0.JPG; ATTSHZK8.JPG; ATTQFD50.JPG; ATT9XR7Y.JPG; ATT1QPGY.JPG; ATTXX48T.JPG; ATTUHHW9.JPG; ATTS057E.JPG; ATTPP8DO.JPG; ATTA9B37.JPG; ATT4J1DD.JPG; ATTUPDBL.JPG; ATT4QD8A.JPG; ATTZU61W.JPG; ATT7QNTJ.JPG; ATT91C8W.JPG; ATTTT0PA.JPG; ATTUAD4C.JPG; ATTQ11R2.JPG; ATTDQKNC.JPG; ATTF98IQ.JPG; ATTTLAXA.JPG; ATTE8EV5.JPG; ATTUBEPH.JPG; ATTMQCUQ.JPG; ATT0ZPQZ.JPG; ATT1U5PE.JPG; ATTZ4KH6.JPG; ATTKHVEV.JPG; ATTZXVG7.JPG; ATTKTX70.JPG; ATT9H9ZW.JPG; ATTV6QLA.JPG; ATTA4CK2.JPG; ATTFSWTV.JPG; ATTJ8DP6.JPG; ATTO70MF.JPG; ATTI9XUV.JPG; ATTPDTNT.JPG; ATTTVYLJ.JPG; ATTXYHK7.JPG; ATTFYYLI.JPG; ATTTRFSQ.JPG; ATTB8WAS.JPG; ATTWN4GL.JPG; ATT71QM6.JPG; ATTQDD93.JPG; ATTHV093.JPG; ATTHVCNX.JPG; ATTPURTG.JPG; ATTNVBA5.JPG; ATT4IJNU.JPG; ATT0IL59.JPG; ATTKQLBE.JPG; ATTASD7W.JPG; ATT8LFQU.JPG; ATTLDWN6.JPG; ATT7FO09.JPG; ATTCJH3W.JPG; ATT04T8P.JPG; ATTZB3MK.JPG

Edit This Report

Print Confirmation

Steven P Bunch | Log Out

SDC10100.JPG; SDC10101.JPG; SDC10102.JPG; SDC10103.JPG; SDC10104.JPG; SDC10105.JPG; SDC10106.JPG; SDC10106.JPG; SDC10106.JPG; SDC10109.JPG; SDC10110.JPG; SDC10111.JPG; SDC10112.JPG; SDC10112.JPG; SDC10113.JPG; SDC10114.JPG; SDC10115.JPG; SDC10115.JPG; SDC10116.JPG; SDC10117.JPG; SDC10118.JPG; SDC10119.JPG; ATTZR8TV.JPG; ATTKARWS.JPG; ATTCTDER.JPG; ATTTXFV3.JPG; ATTAZWOU.JPG; ATTOW2H.JPG; ATTSQ1DO.JPG; ATT6YGQN.JPG; ATTAT2ZF.JPG; ATTS4R26.JPG; ATT8302A.JPG; ATTGBTPI.JPG; ATTCCTUQ.JPG; ATT3DBT0.JPG; ATTSHZK8.JPG; ATTQFD50.JPG; ATTOPPZV.JPG; ATTSQ2D.JPG; ATTSYPZV.JPG; ATT10PGV.JPG; ATTXX48T.JPG;

LOUISIANA STATE POLICE

Crash Photo Upload - Duplicate Report

Home | Edit Profile | Create Crash | Create Incident | Draft Reports | FAQ | Instructions



Report # 20120042760 is an existing Crash report.

Status: Complete

Troop - Author: A - Phillip Rivera

Crash Date: 12/07/2012

Parish: Ascension

Vehicle 1 Driver: MICHAEL B MUNSON

Additional Driver(s): DAVID L HAMMER

Digital Photo Count: 193

SDC10001.JPG; SDC10002.JPG; SDC10003.JPG; SDC10004.JPG; SDC10005.JPG; SDC10006.JPG; SDC10007.JPG; SDC10008.JPG; SDC10009.JPG; SDC10010.JPG; SDC10011.JPG; SDC10012.JPG; SDC10013.JPG; SDC10014.JPG; SDC10015.JPG; SDC10016.JPG; SDC10017.JPG; SDC10018.JPG; SDC10019.JPG; SDC10020.JPG; SDC10021.JPG; SDC10022.JPG; SDC10023.JPG; SDC10024.JPG; SDC10025.JPG; SDC10026.JPG; SDC10027.JPG; SDC10028.JPG; SDC10029.JPG; SDC10030.JPG; SDC10031.JPG; SDC10032.JPG; SDC10033.JPG; SDC10034.JPG; SDC10035.JPG; SDC10036.JPG; SDC10037.JPG; SDC10038.JPG; SDC10039.JPG; SDC10040.JPG; SDC10041.JPG; SDC10042.JPG; SDC10043.JPG; SDC10044.JPG; SDC10045.JPG; SDC10046.JPG; SDC10047.JPG; SDC10048.JPG; SDC10049.JPG; SDC10050.JPG; SDC10051.JPG; SDC10052.JPG; SDC10053.JPG; SDC10054.JPG; SDC10055.JPG; SDC10056.JPG; SDC10057.JPG; SDC10058.JPG; SDC10059.JPG; SDC10060.JPG; SDC10061.JPG; SDC10062.JPG; SDC10063.JPG; SDC10064.JPG; SDC10065.JPG; SDC10066.JPG; SDC10067.JPG; SDC10068.JPG; SDC10069.JPG; SDC10070.JPG; SDC10071.JPG; SDC10072.JPG; SDC10073.JPG; SDC10074.JPG; SDC10075.JPG; SDC10076.JPG; SDC10077.JPG; SDC10078.JPG; SDC10079.JPG; SDC10080.JPG; SDC10081.JPG; SDC10082.JPG; SDC10083.JPG; SDC10084.JPG; SDC10085.JPG; SDC10086.JPG; SDC10087.JPG; SDC10088.JPG; SDC10089.JPG; SDC10090.JPG; SDC10091.JPG; SDC10092.JPG; SDC10093.JPG; SDC10094.JPG; SDC10095.JPG; SDC10096.JPG; SDC10097.JPG; SDC10098.JPG; SDC10099.JPG;