

Company Information

We Inspect NJ

732-359-2132

weinspectnj@gmail.com

<http://www.weinspectnj.com>

Inspector: Brian Duggan: NJ State License #21GI00228700

[Published Report](#)



The Scope and Purpose of a Home Inspection

Purchasing property involves risk

The purpose of a home inspection is to help reduce the risk associated with the purchase of a structure by providing a professional opinion about the overall condition of the structure. A home inspection is a limited visual inspection and it cannot eliminate this risk. Some homes present more risks than others. We cannot control this, but we try to help educate you about what we don't know during the inspection process. This is more difficult to convey in a report and one of many reasons why we recommend that you attend the inspection.

A home inspection is not an insurance policy

This report does not substitute for or serve as a warranty or guarantee of any kind. Home warranties can be purchased separately from insuring firms that provide this service.

A home inspection is visual and not destructive

The descriptions and observations in this report are based on a visual inspection of the structure. We inspect the aspects of the structure that can be viewed without dismantling, damaging or disfiguring the structure and without moving furniture and interior furnishings. Areas that are concealed, hidden or inaccessible to view are not covered by this inspection. Some systems cannot be tested during this inspection as testing risks damaging the building. For example, overflow drains on bathtubs are generally not tested because if they were found to be leaking they could damage the finishes below. Our procedures involve non-invasive investigation and non-destructive testing which will limit the scope of the inspection.

This is not an inspection for code compliance

This inspection and report are not intended for city / local code compliance. During the construction process structures are inspected for code compliance by municipal inspectors. Framing is open at this time and conditions can be fully viewed. Framing is not open during inspections of finished homes, and this limits the inspection. All houses fall out of code compliance shortly after they are built, as the codes continually change. National codes are augmented at least every three years for all of the varying disciplines. Municipalities can choose to adopt and phase in sections of the codes on their own timetables. There are generally no requirements to bring older homes into compliance unless substantial renovation is being done.

This is just our opinion

Construction techniques and standards vary. There is no one way to build a house or install a system in a house. The observations in this report are the opinions of the home inspector. Other inspectors and contractors are likely to have some differing opinions. You are welcome to seek opinions from other professionals.

The scope of this inspection

This inspection will include the following systems: exterior, roof, structure, drainage, foundation, attic, interior, plumbing, electrical and heating. The evaluation will be based on limited observations that are primarily visual and non-invasive. This inspection and report are not intended to be technically exhaustive.

Your expectations

The overall goal of a home inspection is to help ensure that your expectations are appropriate with the house you are proposing to buy. To this end we assist with discovery by showing and documenting observations during the home inspection. This should not be mistaken for a technically exhaustive inspection designed to uncover every defect with a building. Such inspections are available but they are generally cost-prohibitive to most homebuyers.

Your participation is requested

Your presence is requested during this inspection. A written report will not substitute for all the possible information that can be conveyed verbally by a shared visual observation of the conditions of the property.

How to Read This Report

Getting the Information to You

This report is designed to deliver important and technical information in a way that is easy for anyone to access and understand. If you are in a hurry, you can take a quick look at our ["Summary Page"](#) and quickly get critical information for important decision making. However, we strongly recommend that you take the time to read the full [Report](#), which includes digital photographs, captions, diagrams, descriptions, videos and hot links to additional information.

The best way to get the layers of information that are presented in this report is to read your report online, which will allow you to expand your learning about your house. You will notice some words or series of words highlighted in blue and underlined – clicking on these will provide you with a link to additional information.

This report can also be [printed on paper or to a PDF document](#).

Chapters and Sections


This report is divided into chapters that parcel the home into logical inspection components. Each chapter is broken into sections that relate to a specific system or component of the home. You can navigate between chapters with the click of a button on the left side margin.


Most sections will contain some descriptive information done in black font. Observation narrative, done in colored boxes, will be included if a system or component is found to be significantly deficient


in some way or if we wish to provide helpful additional information about the system or the scope of our inspection. If a system or component of the home was deemed to be in satisfactory or serviceable condition, there may be no narrative observation comments in that section and it may simply say "tested," or "inspected."


Observation Labels


All narrative observations are colored, numbered and labeled to help you find, refer to, and understand the severity of the observation. Observation colors and labels used in this report are:


 **Major Concern:** Repair items that may cost significant money to correct now or in the near future, or items that require immediate attention to prevent additional damage or eliminate safety hazards.


 **Repair:** Repair and maintenance items noted during inspection. Please note that some repair items can be expensive to correct such as re-finishing hardwood floors, but are considered simply repair items due to their cosmetic nature.

 **Recommended Maintenance:** These are repair items that should be considered "routine home ownership items," such as servicing the furnace, cleaning the gutters or changing the air filters in the furnace.


 **Improve:** Observations that are not necessarily defects, but which could be improved for safety, efficiency, or reliability reasons.

 **Monitor:** Items that should be watched to see if correction may be needed in the future.

 **Due Diligence:** Observation such as a buried oil tank that may require further investigation to determine the severity and / or urgency of repair.

 **Future Project:** A repair that may be deferred for some time but should be on the radar for repair or replacement in the near future.

Completed: Items that were initially an issue but have since been completed.

 **Note:** Refers to aside information and /or any comments elaborating on descriptions of systems in the home or limitations to the home inspection.

Description: *Detailed description of various aspects of the property noted during the inspection.*

Summary Page

The Summary Page is designed as a bulleted overview of all the observations noted during inspection. This helpful overview is not a substitution for reading the entire inspection report. The entire report must be read to get a complete understanding of this inspection report as the Summary Page does not include photographs or photo captions.

Summary

Major Concerns

⚠️ **G-3 Garage:** The safety laser eye is not functioning properly and did not reverse the door closing at the time of inspection. This occurred at the far right garage door (looking at the house from the front). This is a safety issue as the garage door will not stop closing if there is an obstruction underneath and can cause injury. Recommend further evaluation from a qualified professional. Please view video for example.

⚠️ **EDFW-2 Electric Distribution and Finish Wiring:** Aluminum single strand or solid conductor wiring was noted in the main electrical panel for some of the 15 and 20 amp circuits in this building. Solid strand aluminum wiring that was used for 15 and 20 amp circuits during the Vietnam war era has proven a problematic fire hazard. I recommend hiring a **licensed electrical contractor who specializes in aluminum wiring** to further evaluate these circuits and all termination points and make repairs as recommended. Recommended repair options include using a CPSC approved crimping system or fully replacing the circuits.

- The aluminum alloys used prior to 1972 (AA-1350) are generally more problematic and this wiring should be replaced.
- Post 1972 single strand aluminum should employ an improved alloy (AA-8000) that can be safely kept in service when properly installed at termination points. For more information on solid strand aluminum wiring see:
- <https://dylanchalk.com/single-strand-aluminum-wiring-safe/>
- <http://structuretech1.com/aluminum-wiring/>
- <https://www.cpsc.gov/s3fs-public/516.pdf>
- <https://inspectapedia.com/electric/Old-Fabric-Insulated-Electrical-Wire-ID.php>
- <https://www.alwirerepair.com/photo-gallery/burned-purples>

Examples of specific observations noted during inspection today include:

Repairs

🔧 **G1-2 Grounds:** Downspouts are discharging adjacent to the foundation. This can cause foundation settlement or concrete slab moisture problems. Make sure all downspouts discharge into a proper tight-line system that diverts water at least 5 feet away from the foundation.

🔧 **G1-3 Grounds:** The asphalt driveway flatwork needs to be re-surfaced - see cracking and surface deterioration. Have the driveway and parking surface further investigated and repaired as recommended by a qualified contractor.

🔧 **G1-4 Grounds:** The soils have subsided below the concrete patio step. Repair as needed. This typically involves removal of concrete in these locations and addition of sand or other

bedding material to level the surface and eliminate the step from continuing to fall away from the patio.

🔧 **G1-5 Grounds:** The door jamb and trim material to the basement door well is rotted and requires repair. Repair all damaged wood and try and ensure reliable drainage in this well to reduce risks from wood decay and water entry.

🔧 **G1-7 Grounds:** Trees and shrubbery should be pruned back away from the electric service drop to prevent damage to the electric service conductors. Contact the utility or a professional arborist to implement this repair as working around live electric wires is hazardous.

🔧 **G-1 Garage:** Evidence of rodent entry was noted in the garage. All openings into the garage should be sealed to prevent rodent entry. All feces and contamination should be cleaned and a trapping program implemented to monitor sealing progress. See other sections of the report for more information on rodents.

🔧 **RCG-1 Roof, Chimney and Gutters:** Moss and lichen growth was noted on the roof. The presence of moss will accelerate the deterioration of a roofing material. Moss grows under the successive course lines of the roofing, lifting and spreading the material. When it rains, this moss acts like a sponge to retain the moisture on the roof and allows it to seep into and under the roofing and moisten the vapor barrier and even the sheathing. Under these conditions the roof is much slower to dry and retains a more substantial amount of moisture which aids aging. I would recommend this roof be cleaned and treated with a moss inhibitor. Zinc or galvanized strips at the peak and ridge lines can also be effective to prevent additional build-up of moss afterwards. The minerals in these materials leach onto the roof and prevent moss from growing. Regular treatment with baking soda can also help slow moss growth and prevent damaging moss build-up.

- *Note: Pressure washing a composition roof can damage the roofing material by removing the protective granular surface and should never be done.*

🔧 **RCG-3 Roof, Chimney and Gutters:** Metal flashing has deteriorated and lifted in areas near the roof surface. Recommend further evaluation and repair by a qualified roofer.

🔧 **RCG-4 Roof, Chimney and Gutters:** End of roof ridge above the garage has a last set of shingles nailed without proper tar/sealant. This can allow for moisture to penetrate into this area. Recommend a qualified contractor to repair.

🔧 **RCG-5 Roof, Chimney and Gutters:** Repairs are needed to the masonry chimneys. The conditions noted here could increase the risk of moisture control problems related to the chimney. Neglecting maintenance on masonry chimneys can also lead to loose or damaged bricks and eventually a failing masonry system. Hire a licensed masonry contractor to further evaluate and repair the masonry chimney as recommended. Examples of observations noted during inspection include:

Chimney Caps

- *The chimney cap is just done in a cement wash* and the system is lacking a proper concrete cap. This can lead to moisture control problems.

Chimney Masonry

- *Failing mortar was noted* - this can lead to moisture control and structural problems with the chimney

🔧 **ES1-3 Electric Service:** Abandon wire was found in the electrical box. This is an electrical safety concern and it is recommended to be removed by a licensed electrician.

🔧 **HCFV-2 Heating, Cooling, Fireplaces and Ventilation:** This gas forced air furnace is close to the end of its useful design life. The average service life of natural gas and propane forced air furnaces is 15-20 years. Funds should be reserved to replace this furnace at any time. The risk of running a gas forced air furnace past its useful design life is that the furnace could continue to operate with a cracked heat exchanger. This is a safety hazard that can allow products of combustion enter the supply air to the home. Furnace heat exchangers are not visible to inspection without expensive diagnostics, so is it difficult to know when the furnace could be posing a safety hazard to the occupants. Older furnaces like this are also less reliable and subject to the need for constant repairs. It can be more cost-effective to simply replace these furnaces on a 20 years schedule. Examples of specific observations noted and testing procedures done during inspection include:

I recommend having this furnace serviced and the heat exchanger inspected by a qualified heating contractor. If this furnace is kept in service, keep it on a regular service schedule and budget to update at any time and install carbon monoxide alarms in the home. Standards for CO alarms are 1 / floor and 1 outside all sleeping areas.

🔧 **HCFV-3 Heating, Cooling, Fireplaces and Ventilation:** This AC unit is close to the end of its useful design life (23 years old). Average AC condensing unit typically last 15-20 in New Jersey. Recommend budgeting for the possible failure of this unit and having a licensed HVAC professional further evaluate the performance and life span of the unit.

🔧 **HCFV-4 Heating, Cooling, Fireplaces and Ventilation:** The exhaust ductwork for the bathroom fans are disconnected in the attic and requires repair to ensure fan exhaust is properly venting to the exterior. Having exhaust fans venting into the attic can cause lead to seasonal condensation and moisture controls problems and could damage the attic building materials. Repair to ensure proper discharge of air to the exterior and be sure exhaust ductwork is insulated to R-8 or better to reduce risks of seasonal condensation.

🔧 **P2-5 Plumbing:** No drain pan has been installed below the water heater here. A drain pan is recommended under water heaters that are located in finished spaces or where a leak could damage finishes. Where a pan does not already exist, the tricky part is providing a drain to the outside. A pan without a drain is often of limited benefit / protection. For improved protection from accidental water heater leaks, and where a drain is difficult to install, consider a pan with a moisture alarm and a flood-safe device such as this: [Watts Water Heater Leak Prevention](#).

🔧 **I-2 Interior:** Mold-like substances were noted around some of the windows. This is likely the result of condensation. Some types of windows are prone to condensation, especially single pane windows and older windows with metal frames. Mold testing is beyond the scope of this inspection. If you are concerned about indoor air quality, I recommend consulting with a specialist. To help eliminate molds on windows: keep blinds open to allow good air flow over windows, keep the home heated evenly, use bath and kitchen fans to get moist air to the

exterior. As a general rule in cold seasons, try and keep indoor relative humidity below 50%. Use bath fans as needed to control indoor relative humidity. I recommend cleaning and monitoring.

🔧 **B5-1 Bedrooms:** The back front bedroom door does not close. The door also has signs of damage. It is recommended to replace this door and hinges by a qualified contractor.

🔧 **K-5 Kitchen:** The thermal imaging scan during the inspection uncovered missing insulation above the newly renovated kitchen. These areas of missing insulation will result in energy loss to the house. Please view pictures for visual example. Recommend a qualified contractor to further evaluate and insulate areas in need.

🔧 **FB5-1 Family Bathroom:** The waste plumbing below the new master bathroom sink is leaking and requires immediate repair. Hire a licensed plumber to further evaluate and repair.

🔧 **FB5-2 Family Bathroom:** Mold-like substances were noted in the family bathroom walls around the shower. Clean and seal all mold-like substances with cleaners and stain-killing paints as needed. Please note that mold and mold testing is beyond the scope of this inspection. Localized mold growth is common in bathrooms where building materials stay damp. Shellac-based stain-killing paints can be effective sealers. Finish paints should be glossy to low-sheen paint to better shed water and allow for cleaning. Using bath fans to exhaust moist air is important to prevent mold growth and fans can be places on timers so they run . Mold specialists can be hired as desired to further investigate these stains and remediate. Mold remediation companies are often expensive and it can be more cost-effective to exhaust simple painting, sealing, cleaning and ventilation repairs prior to retaining specialists for such a localized water problem.

🔧 **A-2 Attic:** The exhaust ductwork for the bathroom fans are disconnected in the attic and requires repair to ensure fan exhaust is properly venting to the exterior. Having exhaust fans venting into the attic can cause lead to seasonal condensation and moisture controls problems and could damage the attic building materials. Repair to ensure proper discharge of air to the exterior and be sure exhaust ductwork is insulated to R-8 or better to reduce risks of seasonal condensation.


🔧 **CS1-1 Crawl Space:** No sub-floor insulation was noted in the crawl space. Sub-floors should be insulated to R-30 or better to conserve energy. Given the vulnerability to rodent intrusion in the space I do not recommend insulating with fiberglass as this is conducive to rodent nesting. Either leave uninsulated or insulate with spray or rigid foam.


Recommended Maintenance Items

🔧 **HCFV-1 Heating, Cooling, Fireplaces and Ventilation:** Annual servicing of gas forced air furnaces is recommended for safe and reliable heat. I could not find recent service records on the furnace. A servicing is recommended if one has not been done in the last year. The furnace was tested during inspection and was operational.


Examples of observations noted during inspection include:


- No recent service records were noted


 **LF-3 Laundry Facilities:** The dryer exhaust ductwork is dirty and needs to be cleaned for improved safety. This is important regular maintenance to eliminate a potential fire hazard.

 **LF-5 Laundry Facilities:** A slow drain was noted at the laundry sink indicating that the drain may be obstructed. Repair as needed so the drain keeps up with the fixture supply. This typically involves cleaning out the trap.


Improves


 **DPB-1 Decks, Porches and Balconies:** The concrete pad that is the back patio has settled and requires repair. Sometimes these can be lifted back into place by slab jacking. If the concrete is too old often this will not work and proper repair can necessitate removal. Hire a slab jacking company to further investigate and repair.

 **LF-2 Laundry Facilities:** A moisture alarm with water shut-off features is recommended under the washing machine to protect against accidental leaks in the supply hoses. Pans can be effective when there is a drain, but even these will not protect against a burst supply connector. A moisture alarm with automatic shut-off will. Watts is a brand I have seen installed: [Link](#).

 **A-3 Attic:** The attic and roof cavity ventilation look to be inadequate by today's standards which recommend open ventilation levels in a ratio of 1 to 150 of the attic area. Proper attic ventilation is important for the roofing materials to perform as intended and to reduce chances for condensation problems and heat build-up in the attic. This is a common condition on older buildings that did not originally have composition roofs. As this building is made tighter and better insulated and air-sealed for energy efficiency it is important to improve roof cavity ventilation as well. Consult with a qualified general contractor about adding soffit or core vents for lower "intake" roof ventilation. Generally, you want at least 60% of the air to be from lower soffit or intake vents.

Monitors

 **G1-6 Grounds:** The well structure it's self is starting to deteriorate. Most likely due to freeze and thaw cycle causing the cinderblock's capping to crack. Recommend monitoring at the moment but plan for budging repairs by a qualified contractor.

 **P2-4 Plumbing:** This water heater is likely close to the end of its useful service life. The average life of a water heater is statistically 8-12 years though in practice, they can vary widely between 8-20 years depending on water quality and maintenance schedule such as frequency of flushing the tank and replacing sacrificial anodes. Budget to replace this water heater at any time. Water was hot at the time of inspection.

Due Diligences

 **P2-3 Plumbing:** *A video camera sewer scope is recommended.* An evaluation of the sewer

line below the ground is beyond the scope of this inspection. Due to the age and location of the building, a sewer scope is recommended to further evaluate the sewer line and the below ground connections between the house and the municipal sewer line. Sewer scopes are done using video cameras and can reveal the materials, condition and reliability of the sewer line. If that has been done recently, I recommend having a sewer scope performed.



- *It was reported that there have been back-up issues in the past.*

🔍 **AP-1 Additional Plumbing:** A sump pump system was noted for this building but no sump pump was added. Inquire with the seller for more information about this pump system; is it needed to keep the building dry? Some sump pumps are installed as a prophylactic measure, other systems are critical for keeping a building dry. The importance of this system is impossible to determine during a one-time inspection. Sump pumps always require maintenance. If it is determined that the pump is critical to maintain a dry basement or crawl space, I recommend installing

- Back up power systems so the pump will work in a power outage
- Have a back-up pump and an alarm to alert the occupants in case of a pump failure.

🔍 **AP-2 Additional Plumbing:** Swimming pools are not within the scope of a residential home inspection and they are beyond the scope of this inspection. Still, there are general minimal rules that should be followed to provide safe conditions at these areas since these areas can be dangerous for children and adults.


Pools should be completely surrounded by fencing material at least 4 feet in height. A slatted fence should have gaps no wider than 4 inches so kids can't squeeze through. The gap at the bottom should be less than 2 inches, unless over concrete where it should be less than 4 inches. Gates should be of the self-closing and self-latching type. The latch should be out of a child's reach.

It is also recommended to install alarms. If the house serves as one of the walls of the pool enclosure, any door leading to the pool area should be protected with an alarm. In addition, consideration of an underwater pool alarm that sounds when something hits the water and is audible at the house interior is recommended. Pools covers may be permitted by some jurisdictions, but they don't provide the passive protection that other alarm features may provide.

It is recommended that this pool and related equipment be inspected for operation and safety by a pool specialist.

🔍 **A-1 Attic:** [Mold-like substances](#) were noted on several sheets of OSB in the attic. It appeared that adjacent sheets of OSB were clear. This could indicate that this is not a chronic attic condensation problem, but rather is the result of some sheets of OSB getting wet during the construction process. If you are concerned about molds, a mold remediation specialist should be hired to further evaluate this condition and treat or seal the substances as recommended. Please note that mold and mold testing is beyond the scope of this inspection. Given visible conditions at the time of inspection, and the fact that this is a new build, it seems likely this is just from the construction process. While this may not present any issues to the occupant, it could pose a re-sale issue. I recommend consulting with the builder about options for documenting and / or sealing as recommended.

Future Projects

 **P2-2 Plumbing:** Some of the waste plumbing used in this building is old metal piping. While no leaks were noted at the time of inspection, updating and on-going repairs should be expected. Old metal pipes are subject to internal corrosion which can cause problems at any time. During any renovations to the home be sure to have this old piping evaluated and updated as recommended by a licensed plumber. It is difficult to predict the useful life of metal pipe. Vertical pipe can last much longer than horizontal runs and where occupants use drain cleaning products or other substances that can damage metal pipes, the useful life of the pipe can be shortened. As a general rule the old cast iron pipe often lasts a very long time - even as much as 100 years, galvanized and copper waste pipe can have a shorter useful service life - sometime 50 years.

Completed Items

EDFW-5 Electric Distribution and Finish Wiring: This house has a smart doorbell installed. These are often tied into an internet connection and may include a camera and other features. I recommend disclosing any needed information about using this system and changing access and passwords that may be needed to control this house feature.

Notes

✦ **G-2 Garage:** Correct fire rated door between garage and house.

✦ **G-4 Garage:** Typical cracks were noted in the concrete garage slab. No control joints were used in the pour here so the concrete will crack. You can fill the cracks with a masonry rated caulking, but no repair is needed at this time; this is a cosmetic defect.

✦ **RCG-6 Roof, Chimney and Gutters:** Gutters were noted to be clean at the time of inspection. Be sure to clean gutters quarterly to ensure they are performing as intended.

✦ **EDFW-1 Electric Distribution and Finish Wiring:** This building has wiring that predates the late 1980's. Branch circuit wiring installed in buildings built prior to the late 1980s is typically rated for a maximum temperature of only 60 degrees Celsius. This includes non-metallic sheathed (Romex) wiring, and both BX and AC metal-clad flexible wiring. Knob and tube wiring, typically installed in homes built prior to 1950, may be rated for even lower maximum temperatures. ***Newer electric fixtures including lighting and fans typically require wiring rated for 90 degrees Celsius.*** Connecting newer fixtures to older, 60-degree-rated wiring is a potential fire hazard. Repairs for such conditions may involve replacing the last few feet of wiring to newer fixtures with new 90-degree-rated wire, and installing a junction box to join the old and new wiring. It is beyond the scope of this inspection to determine if any such incompatible components are installed. Based on the age of this building, be aware that such components may be present.

✦ **EDFW-4 Electric Distribution and Finish Wiring:** Carbon monoxide alarms were found and noted during inspection. Be sure to check these regularly. The standard is 1/ floor and 1 outside all sleeping areas.

- ✧ **P2-1 Plumbing:** This shows the location of the water meter in the basement on the north side of the house.
- ✧ **K-2 Kitchen:** Kitchen sink performed as expected at the time of inspection.
- ✧ **K-3 Kitchen:** Garbage disposer performed as expected at the time of inspection.
- ✧ **K-4 Kitchen:** Range performed as expected at the time of inspection.
- ✧ **LF-4 Laundry Facilities:** The electric receptacle to the dryer is three-prong or three -wire system. This is an older configuration. Modern electric dryers circuits require a four-wire system. These older three-wire circuits are still allowed, but be sure to tell your appliance installer that you have a three prong outlet so the cord can be swapped out and the appliance appropriately bonded.
- ✧ **SB-1 Structure and Basement:** Dehumidifier operating in the basement at the time of the inspection. Although evidence of moisture was not present, it is worth noting the operation of the dehumidifier.



The Complete Inspection Report

General Comments

Building Characteristics, Conditions and Limitations

Style of Home: Ranch

Type of Building : Single Family (1 story with Basement)

Approximate Square Footage: 2100

The approximate square footage listed here is listed as a courtesy and is based off of public records and disclosure. An evaluation of square footage of the buildings and property lines is beyond the scope of this inspection.

Approximate Year of Original Construction: 1970

Unless the wiring in the building has been fully updated, this building likely has wiring that predates the late 1980's. Branch circuit wiring installed in buildings built prior to the late 1980s is typically rated for a maximum temperature of only 60 degrees Celsius. This includes non-metallic sheathed (Romex) wiring, and

*both BX and AC metal-clad flexible wiring. Knob and tube wiring, typically installed in homes built prior to 1950, may be rated for even lower maximum temperatures. **Newer electric fixtures including lighting and fans typically require wiring rated for 90 degrees Celsius.** Connecting newer fixtures to older, 60-degree-rated wiring is a potential fire hazard. Repairs for such conditions may involve replacing the last few feet of wiring to newer fixtures with new 90-degree-rated wire, and installing a junction box to join the old and new wiring. It is beyond the scope of this inspection to determine if any such incompatible components are installed. Based on the age of this building, be aware that such components may be present.*

In 1978, federal laws were passed to prohibit use of lead and asbestos in building materials. Manufacturers of building materials were allowed to sell existing stocks of materials that were manufactured with lead and asbestos, so even buildings constructed as late as the mid-1980's could possibly contain lead or asbestos. Identification and testing for lead and asbestos and other environmental testing is beyond the scope of this home inspection. If you wish to seek additional information, I recommend contacting an environmental lab or industrial hygienist.

Attending the Inspection: Buyer and Buyer's Agent

Occupancy: Occupied

Animals Present: No

Weather during the inspection: Clear

Approximate temperature during the inspection: Over 75[F]

Ground/Soil surface conditions: Dry


For the Purposes of This Report, the Front Door Faces: West

This home was occupied at the time of the inspection. Inspection of occupied homes presents some challenges as occupant belongings can obstruct visual inspection of and access to parts of the building. We do our best during inspection to work around belongings to discover as much as possible about the house without moving or damaging personal property, however, the presence of personal items does limit the inspection.

Grounds

General Grounds Photos

Full property picture at the client's request.



Drainage and Site

Clearance to Grade: Standard

Downspout Discharge: Above and below grade

Site Description: Moderate slope

🔧 **(G1-2) Repair:** Downspouts are discharging adjacent to the foundation. This can cause foundation settlement or concrete slab moisture problems. Make sure all downspouts discharge into a proper tight-line system that diverts water at least 5 feet away from the foundation.



Driveways/Walkways/Flatwork

Driveway: Asphalt

Walkways: Concrete, Pavers

Patios: Concrete

🔧 (G1-3) Repair: The asphalt driveway flatwork needs to be re-surfaced - see cracking and surface deterioration. Have the driveway and parking surface further investigated and repaired as recommended by a qualified contractor.



*Cracks were noted in driveway flatwork.
Repair as needed.*

🔧 (G1-4) Repair: The soils have subsided below the concrete patio step. Repair as needed. This typically involves removal of concrete in these locations and addition of sand or other bedding material to level the surface and eliminate the step from continuing to fall away from the patio.



Window and Stairwells

Present, Basement Well

🔧 (G1-5) Repair: The door jamb and trim material to the basement door well is rotted and requires repair. Repair all damaged wood and try and ensure reliable drainage in this well to reduce risks from wood decay and water entry.



👁️ (G1-6) Monitor: The well structure it's self is starting to deteriorate. Most likely due to freeze and thaw cycle causing the cinderblock's capping to crack. Recommend monitoring at the moment but plan for budging repairs by a qualified contractor.



Grounds, Trees and Vegetation

Trees/Vegetation too near building: No

🔧 (G1-7) Repair: Trees and shrubbery should be pruned back away from the electric service drop to prevent damage to the electric service conductors. Contact the utility or a professional arborist to implement this repair as working around live electric wires is hazardous.



The red arrow is pointing at the tree branches that are hanging on top of the electrical drop. These branches could break causing tension on the electrical wire that can lead to larger electrical/safety issues.

Retaining Walls

Retaining Wall Material: None Noted

Exterior Stairs

Exterior Stairs: Standard

Fences

Exterior Fencing: Present

The property has a fencing system in place. Inspection and evaluation of fencing is beyond the scope of a home inspection. If the fencing system is important for your use of this property, I recommended a self-

Exterior Siding, Doors and Windows

Siding and Trim

Trim Material: Vinyl

Siding Material: Vinyl

Exterior Vent and Exhaust Terminations

Present

Eaves

Vinyl

Exterior Doors

Exterior Door Styles: Solid core, Sliding glass

Exterior Window Frames

Window Frames: Vinyl

Decks, Porches and Balconies

Wood Decks Porches and Balconies

None noted

Concrete Decks, Stoops, Landings and Porches

Concrete Structure: Settlement and/or Cracking Noted



(DPB-1) Improve:

The concrete pad that is the back patio has settled and requires repair. Sometimes these can be lifted back into place by slab jacking. If the concrete is too old often this will not work and proper repair can necessitate removal. Hire a slab jacking company to further investigate and repair.



Arrows are pointing at the large crack through the concrete slab.

Garage

Garage General

Garage Type: Attached

🔧 (G-1) Repair: Evidence of rodent entry was noted in the garage. All openings into the garage should be sealed to prevent rodent entry. All feces and contamination should be cleaned and a trapping program implemented to monitor sealing progress. See other sections of the report for more information on rodents.



Rodent trap located next to the garage door opening. Looks to have been placed a long time ago and no evidence of rodent entry was present at the time of the inspection.

✧ **(G-2) Note:** Correct fire rated door between garage and house.



20 minute fire rated door tag

Garage Doors and Automatic Openers

Overhead Garage Door Type: Metal

Automatic Garage Opener: Present, Laser Eyes

Garage Occupant Door: Fire Rated

⚠️ **(G-3) Major Concern:** The safety laser eye is not functioning properly and did not reverse the door closing at the time of inspection. This occurred at the far right garage door (looking at the house from the front). This is a safety issue as the garage door will not stop closing if there is an obstruction underneath and can cause injury. Recommend further evaluation from a qualified professional. Please view video for example.

(This video is only viewable online.)

Garage Floor

Garage Slab: Concrete, Typical Cracks Noted

✦ **(G-4) Note:** Typical cracks were noted in the concrete garage slab. No control joints were used in the pour here so the concrete will crack. You can fill the cracks with a masonry rated caulking, but no repair is needed at this time; this is a cosmetic defect.



Garage Stairs

Garage Stairs: Standard

Roof, Chimney and Gutters

Roof Materials

Method of Roof Inspection: Walked on roof, Viewed with a drone

Drone use was also asked for by client for picture purposes. Roof was inspected by walking.

Roof Style: Hip

Flashings, Valleys and Penetrations: California Cut Valley

This building has a [cut valley detail](#) for the roofing valleys. These generally perform adequately, though some roofers and some shingle manufacturers do not recommend this type of valley detail. They are so common here, I do not consider them defective or in need of repair unless there is visible evidence that a repair is needed at the time or they are showing excessive wear. Generally, valleys done with metal flashing systems are more reliable.

Roof Covering Materials: Three-tab composition shingle

Approximate Age of Roof Covering: 12-14 Years

Overlay Roof: No

Shingle Fastening Accessible For Inspection : No

Please note that when inspecting composition roof installations, I try and look under shingles to see how the shingles have been fastened. Proper fastening is critical for successful roof performance. Often the shingles are bonding so well, they cannot be lifted to inspect the fastening. In this case, I was unable to lift the shingles and see the fastening pattern - they are bonded well and I do not use a flat bar to pry them apart as part of a visual inspection unless there is a reason to start chasing visible leaks. While this limits my visual inspection, this is a good sign, as loose, un-bonded shingles can lead to wind damage and would be written up as a defect.

🔧 (RCG-1) Repair: Moss and lichen growth was noted on the roof. The presence of moss will accelerate the deterioration of a roofing material. Moss grows under the successive course lines of the roofing, lifting and spreading the material. When it rains, this moss acts like a sponge to retain the moisture on the roof and allows it to seep into and under the roofing and moisten the vapor barrier and even the sheathing. Under these conditions the roof is much slower to dry and retains a more substantial amount of moisture which aids aging. I would recommend this roof be cleaned and treated with a moss inhibitor. Zinc or galvanized strips at the peak and ridge lines can also be effective to prevent additional build-up of moss

afterwards. The minerals in these materials leach onto the roof and prevent moss from growing. Regular treatment with baking soda can also help slow moss growth and prevent damaging moss build-up.

- *Note: Pressure washing a composition roof can damage the roofing material by removing the protective granular surface and should never be done.*



🔧 (RCG-3) Repair: Metal flashing has deteriorated and lifted in areas near the roof surface. Recommend further evaluation and repair by a qualified roofer.



The flashing has lost its exterior paint and is susceptible to an increased rate of deterioration.



Minor lifting of this flashing where the garage roof and house roof meet.



Flashing pulling away at the ridge of the roof.

🔧 (RCG-4) Repair: End of roof ridge above the garage has a last set of shingles nailed without proper tar/sealant. This can allow for moisture to penetrate into this area. Recommend a qualified contractor to repair.



Arrows indicating the nails that are unsealed which can allow for water intrusion.

Roof pictures





Chimneys

Present

Chimney Material: Masonry

🔧 (RCG-5) Repair: Repairs are needed to the masonry chimneys. The conditions noted here could increase the risk of moisture control problems related to the chimney. Neglecting maintenance on masonry chimneys can also lead to loose or damaged bricks and eventually a failing masonry system. Hire a licensed masonry contractor to further evaluate and repair the masonry chimney as recommended. Examples of observations noted during inspection include:

Chimney Caps

- *The chimney cap is just done in a cement wash* and the system is lacking a proper concrete cap. This can lead to moisture control problems.

Chimney Masonry


- *Failing mortar was noted* - this can lead to moisture control and structural problems with the chimney



Arrow indicating the cement wash chimney crown. It is recommended for the chimney crown to overhang the chimney stack by two inches to prevent deteriorating of the chimney stack.



Around the chimney mortar, sealant was used. This is not a proper way to seal the chimney and it is recommended for a qualified mason to further evaluate and make repairs.



This illustration demonstrates the proper installation of a chimney crown

Skylights

None noted

Gutters and Downspouts

Gutter and Downspout Materials: Seamless Aluminum

✦ **(RCG-6) Note:** Gutters were noted to be clean at the time of inspection. Be sure to clean gutters quarterly to ensure they are performing as intended.



Fuel Storage and Distribution

Oil Storage

None noted

Propane Storage

None noted

Gas Meter

Present

Gas Shutoff Location: North side of structure

Gas Pipe Materials: Steel and flex pipe

Gas meter location is on the north side of the house.



Gas, Propane and Oil Piping

Gas Piping Materials Noted: Steel

Electric Service

Electric Service Permits Found

These images show electric permits found during inspection.



Electric Service Voltage Tested

Service Voltage: 120/240

Electric Service

Service Entrance: Above Ground

Meter Base Amperage: 150

Electric Service Equipment

Service Entrance (SE) conductor Size: Aluminum, 2/0, 150 amps


Main Panel Amperage: 150 amps

Electric Service Amperage: 150 amps

Main Electric Panel Location: Garage

Panel Manufacturer: Square D


⚠️ (ES1-3) Repair: Abandon wire was found in the electrical box. This is an electrical safety concern and it is recommended to be removed by a licensed electrician.



Arrow pointing at the abandon wire

Electrical Panel





Sub Panel

Sub Panel: None Noted

Electrical Grounding System

Grounding Rod Noted

Ground rod connections were noted at the exterior. The ground rods looked to be fully driven and connections looked standard,



Electrical Bonding System

Bonding Noted on Water Pipes

Bonding connections were noted on the water pipes.



Electric Distribution and Finish Wiring

Branch Wiring

Wire Material: Copper, Solid Conductor Aluminum


For more information about solid conductor aluminum, [see this link](#).

Wiring Method: Non-metallic sheathed cable

⚠️ **(EDFW-2) Major Concern:** Aluminum single strand or solid conductor wiring was noted in the main electrical panel for some of the 15 and 20 amp circuits in this building. Solid strand aluminum wiring that was used for 15 and 20 amp circuits during the Vietnam war era has proven a problematic fire hazard. I recommend hiring a **licensed electrical contractor who specializes in aluminum wiring** to further evaluate these circuits and all termination points and make repairs as recommended. Recommended repair options include using a CPSC approved crimping system or fully replacing the circuits.

- The aluminum alloys used prior to 1972 (AA-1350) are generally more problematic and this wiring should be replaced.
- Post 1972 single strand aluminum should employ an improved alloy (AA-8000) that can be safely kept in service when properly installed at termination points. For more information on solid strand aluminum wiring see:
- <https://dylanchalk.com/single-strand-aluminum-wiring-safe/>
- <http://structuretech1.com/aluminum-wiring/>
- <https://www.cpsc.gov/s3fs-public/516.pdf>
- <https://inspectapedia.com/electric/Old-Fabric-Insulated-Electrical-Wire-ID.php>
- <https://www.alwirerepair.com/photo-gallery/burned-purples>

Examples of specific observations noted during inspection today include:



✧ **(EDFW-1) Note:** This building has wiring that predates the late 1980's. Branch circuit wiring installed in buildings built prior to the late 1980s is typically rated for a maximum temperature of only 60 degrees Celsius. This includes non-metallic sheathed (Romex) wiring, and both BX and AC metal-clad flexible wiring. Knob and tube wiring, typically installed in homes built prior to 1950, may be rated for even lower maximum temperatures. **Newer electric fixtures including lighting and fans typically require wiring rated for 90 degrees Celsius.** Connecting newer fixtures to older, 60-degree-rated wiring is a potential fire hazard. Repairs for such conditions may involve replacing the last few feet of wiring to newer fixtures with new 90-degree-rated wire, and installing a junction box to join the old and new wiring. It is beyond the scope of this inspection to determine if any such incompatible components are installed. Based on the age of this building, be aware that such components may be present.

Receptacles and Fixtures

Inspection Method: Tested All Accessible

During inspection I make an effort to test and inspect all accessible electric receptacles and switches. In general, the scope of testing is directly related to access; where personal belonging and furniture obstruct access to receptacles and fixtures, fewer of them can be reasonably tested during inspection. All defects found during inspection today will be listed in this report.

Electric Receptacles: Three wire receptacles

Ceiling Fans

Ceiling Fans: Present and Tested

The ceiling fans were tested and operating during inspection.

Smoke and Carbon Monoxide Alarm Systems

CO Alarms: Present

The installation of [carbon monoxide](#) alarms is recommended for all homes that have fuel burning appliances such as gas or oil furnaces, gas water heaters, gas ovens and cook-tops, gas fireplaces and wood stoves. In addition, Washington State law ([WAC 51-51-0315](#)) now requires UL 2034 approved carbon monoxide alarms in **ALL** homes and condominiums being sold in Washington State. The location should be: **at least one alarm outside of all sleeping areas and one on each floor of the house**. Best practices are to have these alarms hardwired with a battery back-up - though requirements are for the installation to meet manufacturer's specifications. Carbon monoxide is a colorless, odorless gas that can cause sickness, nausea and even death. Alarms have a useful service life of roughly 6 years, so changing them more frequently than smoke alarms is recommended.



Smoke Alarms Noted: ☒ On Main Floor ☒ In Basement

Smoke Alarms: Present

During the home inspection, I try and test a representative sample of the smoke alarms by using the test button on the alarms. This is NOT an accurate test of the sensor just a test to see if the unit is powered. For reliability, fire marshals recommended updating smoke alarms every 10 years and changing batteries bi-

annually. The latest data indicate that we should be using photoelectric technology in our smoke alarms for improved fire detection and to reduce problems with false alarms which can lead to disabling of this important safety system. Unfortunately, the alarms have to be removed to determine if they are photoelectric or ionization types. It is surprisingly complex to accurately test a smoke alarm system and determine the reliability, age, and type of sensor technology used, especially as many homes can have half a dozen or more alarms throughout the house. A complete evaluation of smoke alarms is beyond the scope of this inspection. For optimal fire safety, I recommend taking control of these important safety devices and learning about how to service and maintain your smoke alarm system to keep the building occupants safe. For more information, please read this link. [For more information, please read this link.](#)

✦ **(EDFW-4) Note:** Carbon monoxide alarms were found and noted during inspection. Be sure to check these regularly. The standard is 1/ floor and 1 outside all sleeping areas.

Low Voltage Wiring

(EDFW-5) Completed: This house has a smart doorbell installed. These are often tied into an internet connection and may include a camera and other features. I recommend disclosing any needed information about using this system and changing access and passwords that may be needed to control this house feature.



Heating, Cooling, Fireplaces and Ventilation

Heating System

Energy Source: Natural gas

Heating Method: Gas forced air furnace

This house has a gas forced air furnace. A critical component to all combustion heating equipment is the heat exchanger. This is the welded metal assembly inside the furnace that contains the products of combustion so that moisture, carbon monoxide and other products of combustion do not mix with interior air and get safely vented to the exterior. Heat exchangers on modern furnaces have an average life expectancy of 15-20 years. Unfortunately, heat exchangers are concealed inside the heating equipment; they are not visible and specifically excluded from a home inspection. Cracks in heat exchangers may be concealed and can pose a potential safety hazard.



This shows an image of a heat exchanger.

Manufacturer: American Standard

Data Plate: Shown Here

This shows the data plate from the air handler. 📷



Capacity: 100,000 btu's

Age: 2002

Last Service Record: None

🔧 (HCFV-2) Repair: This gas forced air furnace is close to the end of its useful design life. The average service life of natural gas and propane forced air furnaces is 15-20 years. Funds should be reserved to replace this furnace at any time. The risk of running a gas forced air furnace past its useful design life is that the furnace could continue to operate with a cracked heat exchanger. This is a safety hazard that can allow products of combustion enter the supply air to the home. Furnace heat exchangers are not visible to inspection without expensive diagnostics, so is it difficult to know when the furnace could be posing a safety hazard to the occupants. Older furnaces like this are also less reliable and subject to the need for constant repairs. It can be more cost-effective to simply replace these furnaces on a 20 years schedule. Examples of specific observations noted and testing procedures done during inspection include:

I recommend having this furnace serviced and the heat exchanger inspected by a qualified heating contractor. If this furnace is kept in service, keep it on a regular service schedule and budget to update at any time and install carbon monoxide alarms in the home. Standards for CO alarms are 1 / floor and 1 outside all sleeping areas.

🔧 (HCFV-1) Recommended Maintenance: Annual servicing of gas forced air furnaces is recommended for safe and reliable heat. I could not find recent service records on the furnace. A servicing is recommended if one has not been done in the last year. The furnace was tested during inspection and was operational.

Examples of observations noted during inspection include:

- No recent service records were noted

Air Filters

Filtration Systems: Disposable

The heating and cooling system has disposable air filters installed. These should be changed quarterly or more to ensure proper air flow at the furnace. Be sure to install the filters with the arrows pointing in the same direction as the air flow in the furnace.

Cooling Systems and Heat Pumps

Air Conditioning Present

The following list is a minimum set of requirements to be expected of heat pump or air conditioning servicing. I provide these as a courtesy to show they types of check-ups that should be expected from a professional servicing.

- *Check compressor efficiency*
- *Check refrigerant level*
- *Clean the condenser coil*
- *Change or clean air filters*
- *Inspect contactors and wiring*
- *Inspect drive-sheaves, pulleys and belts*
- *Check and adjust for proper air flow*
- *Clean the blower motor as needed*
- *Lubricate all motors and shaft bearings*
- *Check, calibrate and program the thermostats and be sure the thermostat has adequate batteries as needed*
- *Check unit smoke detector, clean filter if applicable*
- *Check safety disconnect, laser-temp -- check across contacts*

Manufacturer: Lennox

Data Plate: Shown here

This shows the data plate from the exterior compressor. 📷



System Type: Air Source

Listed Nominal Capacity: 4 Tons

Energy Source: Electric

Age: 1999

🔧 **(HCFV-3) Repair:** This AC unit is close to the end of its useful design life (23 years old). Average AC condensing unit typically last 15-20 in New Jersey. Recommend budgeting for the possible failure of this unit and having a licensed HVAC professional further evaluate the performance and life span of the unit.

Heating and Cooling Distribution Systems

Heat Source in Each Room: Present

Distribution Method: Forced Air / Ducts

Mechanical Ventilation Systems

Bath Fan Ducting: Disconnected in Attic

Kitchen Fan Ducting: Ducted to exterior

Whole House Fans, Ventilation and HRVs: No Mechanical Ventilation Found

🔧 **(HCFV-4) Repair:** The exhaust ductwork for the bathroom fans are disconnected in the attic and requires repair to ensure fan exhaust is properly venting to the exterior. Having

exhaust fans venting into the attic can cause lead to seasonal condensation and moisture controls problems and could damage the attic building materials. Repair to ensure proper discharge of air to the exterior and be sure exhaust ductwork is insulated to R-8 or better to reduce risks of seasonal condensation.



Bathroom fan is not venting out to the exterior.



Bathroom fan is not venting out to the exterior.

Gas Fireplaces

Fireplace Types: No gas fireplaces or woodstoves noted

Solid Fuel Fireplaces

Fireplace Types: No wood burning fireplaces or appliances noted

Plumbing

Water Meter

Location of Water Meter Note

✦ **(P2-1) Note:** This shows the location of the water meter in the basement on the north side of the house.



Water Service Supply

Pipe Material: Copper

Water Supply: Public water

Pressure Reducing Valve: None noted

Main Water Shut-off Location: Water Shut Off Location Noted

This shows the location of the main water shut off located in the basement.



Distribution Pipe

Pipe Insulation: Present

The visible portions of the supply piping appear to be insulated. However, prior to freezing weather it is always a good idea to check pipes and hose bibs for adequate insulation and freeze protection to protect pipes from cold weather and freezing conditions. Hose bibs can often be winterized prior to cold weather.

Supply Pipe Materials: Copper

Copper water supply pipes were installed. Copper pipes installed prior to the late 1980's may be joined with solder that contains lead, which is a known health hazard especially for children. Laws were passed in 1985 prohibiting the use of lead in solder, but prior to that solder normally contained approximately 50% lead. Note that testing for toxic materials such as lead, is beyond the scope of this inspection. Consider having a qualified lab test for lead, and if necessary take steps to reduce or remove lead from the water supply. Various solutions include:

- Flush water taps or faucets. Do not drink water that has been sitting in the plumbing lines for more than 6 hours*
- Install appropriate filters at points of use*
- Use only cold water for cooking and drinking, as hot water dissolves lead more quickly than cold water*
- Treat well water to make it less corrosive*
- Have a qualified plumber replace supply pipes and/or plumbing components as necessary*

Functional Flow: Average

Circulation Pump: None Noted

Waste Pipe and Discharge

Discharge Type: Public Sewer - Buyer

Waste and Vent Pipe Materials: PVC, Galvanized steel

Location of Sewer Cleanout: Basement

This shows the location of the sewer cleanout found during inspection - basement.

🔍 (P2-3) Due Diligence: A video camera sewer scope is recommended. An evaluation of the sewer line below the ground is beyond the scope of this inspection. Due to the age and location of the building, a sewer scope is recommended to further evaluate the sewer line and the below ground connections between the house and the municipal sewer line. Sewer scopes are done using video cameras and can reveal the materials, condition and reliability of the sewer line. If that has been done recently, I recommend having a sewer scope performed.



- *It was reported that there have been back-up issues in the past.*

📁 (P2-2) Future Project: Some of the waste plumbing used in this building is old metal piping. While no leaks were noted at the time of inspection, updating and on-going repairs should be expected. Old metal pipes are subject to internal corrosion which can cause problems at any time. During any renovations to the home be sure to have this old piping evaluated and updated as recommended by a licensed plumber. It is difficult to predict the useful life of metal pipe. Vertical pipe can last much longer than horizontal runs and where occupants use drain cleaning products or other substances that can damage metal pipes, the useful life of the pipe can be shortened. As a general rule the old cast iron pipe often lasts a very long time - even as much as 100 years, galvanized and copper waste pipe can have a shorter useful service life - sometime 50 years.

Water Heater

System Type: Tank

Manufacturer: A.O. Smith

Data Plate: Shown Here

This shows the data plate for this water heater.



Size: 50 gal

Age: 2002

Energy Source: Gas

Straps : None Found

Pad: None Noted - Required


Drain Pan: None Noted - Recommended

Relief Valve: Present - Not Tested

A temperature and pressure relief valve (TPRV) is required on all water heaters to discharge any excessive pressure within the tank. A discharge pipe should be attached to the valve and directed to a safe location away from body contact. Newer installations must be directed to the building exterior or to an approved indoor drain receptor. Most manufacturers suggest that homeowners test these valves at least once a year by lifting the lever to ensure the valve discharges properly and also recommend inspection of these safety devices every three years. The picture here shows a typical TPRV. They may also be found on the side of the heater on some models. I do not test these valves due to the possibility that they may leak after testing. A leaking or inoperative TPRV should be replaced immediately by a licensed plumber.

Due to inconsistencies between both UPC and IPC Plumbing codes, and water heater manufacturer's instructions, and TPRV manufacturer instructions, it is not actually possible to install the drain from the Water Heater TPRV "properly." There are conflicts with distance of termination to the floor/ground, types of pipes approved, and diameters of pipes approved. Additional confusion is added when jurisdictional inspectors approve installations/materials specifically not allowed by both codes and manufacturers. My recommendations will vary depending on the installation and will be included in the applicable narratives below.

Most codes defer to manufacturer instructions and I favor those recommendations. The yellow tag on the valve states clearly the termination should be 6" above the floor which is more consistent with the UPC code requirements.



The arrow shows how a TPRV can be tested

Bollard: None Required

🔧 (P2-5) Repair: No drain pan has been installed below the water heater here. A drain pan is recommended under water heaters that are located in finished spaces or where a leak could damage finishes. Where a pan does not already exist, the tricky part is providing a drain to the

outside. A pan without a drain is often of limited benefit / protection. For improved protection from accidental water heater leaks, and where a drain is difficult to install, consider a pan with a moisture alarm and a flood-safe device such as this: [Watts Water Heater Leak Prevention](#).



👁 (P2-4) **Monitor:** This water heater is likely close to the end of its useful service life. The average life of a water heater is statistically 8-12 years though in practice, they can vary widely between 8-20 years depending on water quality and maintenance schedule such as frequency of flushing the tank and replacing sacrificial anodes. Budget to replace this water heater at any time. Water was hot at the time of inspection.

Water Temperature

Water Temperature Measured During Inspection: 120 Degrees F

Exterior Hose Bibs

Operating

Additional Plumbing

Sump Pumps and Drains

Floor Drain: None noted

🔍 **(AP-1) Due Diligence:** A sump pump system was noted for this building but no sump pump was added. Inquire with the seller for more information about this pump system; is it needed to keep the building dry? Some sump pumps are installed as a prophylactic measure, other systems are critical for keeping a building dry. The importance of this system is impossible to determine during a one-time inspection. Sump pumps always require maintenance. If it is determined that the pump is critical to maintain a dry basement or crawl space, I recommend installing

- Back up power systems so the pump will work in a power outage
- Have a back-up pump and an alarm to alert the occupants in case of a pump failure.

Swimming Pools

🔍 **(AP-2) Due Diligence:** Swimming pools are not within the scope of a residential home inspection and they are beyond the scope of this inspection. Still, there are general minimal rules that should be followed to provide safe conditions at these areas since these areas can be dangerous for children and adults.

Pools should be completely surrounded by fencing material at least 4 feet in height. A slatted fence should have gaps no wider than 4 inches so kids can't squeeze through. The gap at the bottom should be less than 2 inches, unless over concrete where it should be less than 4 inches. Gates should be of the self-closing and self-latching type. The latch should be out of a child's reach.

It is also recommended to install alarms. If the house serves as one of the walls of the pool enclosure, any door leading to the pool area should be protected with an alarm. In addition, consideration of an underwater pool alarm that sounds when something hits the water and is audible at the house interior is recommended. Pools covers may be permitted by some jurisdictions, but they don't provide the passive protection that other alarm features may provide.


It is recommended that this pool and related equipment be inspected for operation and safety by a pool specialist.

Interior

General Interior Photos



Old master room



Hallway



New master (added in 2000)

Floors and Floor Materials

Floor Materials: Hardwood

Floor Settlement: None noted

Walls, Ceilings, Trim, Hallways and Closets

Wall and Ceiling Materials: Drywall

Wall Insulation and Air Bypass

Wall Insulation: Not Visible

Stairs and Railings

Standard

Interior Doors

Interior Doors: Hollow Core


Windows

Window Glazing: Double pane

Interior Window Frame: Wood

Window Styles: Double hung

Window Brands Noted: Anderson

 **(I-2) Repair:** Mold-like substances were noted around some of the windows. This is likely the result of condensation. Some types of windows are prone to condensation, especially single pane windows and older windows with metal frames. Mold testing is beyond the scope of this inspection. If you are concerned about indoor air quality, I recommend consulting with a specialist. To help eliminate molds on windows: keep blinds open to allow good air flow over windows, keep the home heated evenly, use bath and kitchen fans to get moist air to the exterior. As a general rule in cold seasons, try and keep indoor relative humidity below 50%. Use bath fans as needed to control indoor relative humidity. I recommend cleaning and monitoring.



Mold-like growth found on south facing windows of new master bedroom



Mold-like growth found on south facing windows of new master bedroom

Bedrooms

Main Bedroom

Windows: All windows operated correctly

Doors: Back bedroom door is damaged

Electric Switches and Receptacles: All performed at the time of inspection

Walls and Ceilings: Standard

Floors: Standard

Closets: Standard

🔧 (B5-1) Repair: The back front bedroom door does not close. The door also has signs of damage. It is recommended to replace this door and hinges by a qualified contractor.

Kitchen

General Kitchen Photos



Sinks and Faucets

Tested

✦ **(K-2) Note:** Kitchen sink performed as expected at the time of inspection.



Cabinets and Countertops

Countertop Material: Quartz

Cabinet Material: Wood

Disposers

Disposer: Operated

✦ **(K-3) Note:** Garbage disposer performed as expected at the time of inspection.



Dishwasher

Dishwasher: Operated

Ventilation Method

Fan Ducted to Exterior

Ranges, Ovens and Cooktops

Range/ Oven /Cook-tops: Gas

✦ **(K-4) Note:** Range performed as expected at the time of inspection.



Refrigerators


Refrigerator: Operating

General Kitchen Condition


Standard

🔧 (K-5) Repair: The thermal imaging scan during the inspection uncovered missing insulation

above the newly renovated kitchen. These areas of missing insulation will result in energy loss to the house. Please view pictures for visual example. Recommend a qualified contractor to further evaluate and insulate areas in need.



The arrows in the picture are showing the large areas of missing insulation. Most of the ceiling areas were about 76 degrees; the missing insulation areas were about 92 degrees.



Same picture but not using the thermal image; for reference to the first picture.

Laundry Facilities

Laundry Photos



Washer

Tested

During inspection I try and run the clothes washing machine. This is mostly so that I can push water down the drain to test the waste piping system. Running the clothes washer during an inspection is not a reliable test of the appliance. I am not actually doing a load of laundry, so please note the limitations of this test.




(LF-2) Improve: A moisture alarm with water shut-off features is recommended under the washing machine to protect against accidental leaks in the supply hoses. Pans can be effective when there is a drain, but even these will not protect against a burst supply connector. A moisture alarm with automatic shut-off will. Watts is a brand I have seen installed: [Link](#).



Dryer

Tested

Proper dryer exhaust venting is critical for safe and reliable performance from the dryer. Here are some basic rules of thumb for dryer [exhaust duct installation](#): Unless a vent-free appliance is being used, the dryer exhaust vent must terminate outdoors. It should be no more than 25 feet long and for every 90 degree turn subtract 5 feet and for every 45 degree bend subtract 2.5 feet. Use only smooth-wall metal vent pipe @ 4 inch pipe diameter. Do not use plastic pipe and plastic flex pipe. If a flexible connector is needed behind the dryer use a short amount of corrugated metal pipe. If the exhaust duct is getting pinched behind dryer, consider use of a dryer vent box, pictured here. Flex and corrugated pipes should never be used in concealed spaces such as through walls or in attic or crawl spaces. Insulate dryer exhaust duct where it passes through unconditioned spaces to prevent condensation that could hasten lint build-up inside the pipe. Do not use screws to connect pipe as these can trap lint. Secure duct with foil tape as needed. Be sure duct is sleeved properly so that it will not trap lint and clean the vent regularly, especially if it is a long exhaust run.



This shows an example of a dryer vent box

Power Source: Electric

Exhaust Duct: Ducted to Exterior

🔧 **(LF-3) Recommended Maintenance:** The dryer exhaust ductwork is dirty and needs to be cleaned for improved safety. This is important regular maintenance to eliminate a potential fire hazard.

📌 **(LF-4) Note:** The electric receptacle to the dryer is three-prong or three -wire system. This is an older configuration. Modern electric dryers circuits require a four-wire system. These older three-wire circuits are still allowed, but be sure to tell your appliance installer that you have a three prong outlet so the cord can be swapped out and the appliance appropriately bonded.

Laundry Sinks

🔧 **(LF-5) Recommended Maintenance:** A slow drain was noted at the laundry sink indicating that the drain may be obstructed. Repair as needed so the drain keeps up with the fixture supply. This typically involves cleaning out the trap.



Laundry Ventilation

Type: None noted

Family Bathroom

Sinks and Cabinets

Tested

🔧 (FB5-1) Repair: The waste plumbing below the new master bathroom sink is leaking and requires immediate repair. Hire a licensed plumber to further evaluate and repair.



Sink performing



Leak causing water damage to the interior base of the vanity.



Location of the leak is coming the the sink stopper mechanism.

Toilet

Tested

Bathtub / Shower

Tested

Bathroom Ventilation

Type: Bath fan

General Bath Condition

Non-standard

🔧 (FB5-2) Repair: Mold-like substances were noted in the family bathroom walls around the shower. Clean and seal all mold-like substances with cleaners and stain-killing paints as needed. Please note that mold and mold testing is beyond the scope of this inspection. Localized mold growth is common in bathrooms where building materials stay damp. Shellac-based stain-killing paints can be effective sealers. Finish paints should be glossy to low-sheen paint to better shed water and allow for cleaning. Using bath fans to exhaust moist air is important to prevent mold growth and fans can be placed on timers so they run. Mold specialists can be hired as desired to further investigate these stains and remediate. Mold remediation companies are often expensive and it can be more cost-effective to exhaust simple painting, sealing, cleaning and ventilation repairs prior to retaining specialists for such a localized water problem.



Main Bathroom

Sinks and Cabinets

Tested

Toilet

Tested

Bathtub / Shower

Tested

Bathroom Ventilation

Type: Bath fan

General Bath Condition

Standard

Attic

Attic Access

Crawled partial

Roof Framing and Sheathing

Rafters: 2x6

Sheathing: Plywood

🔍 **(A-1) Due Diligence:** [Mold-like substances](#) were noted on several sheets of OSB in the attic. It appeared that adjacent sheets of OSB were clear. This could indicate that this is not a chronic attic condensation problem, but rather is the result of some sheets of OSB getting wet during the construction process. If you are concerned about molds, a mold remediation specialist should be hired to further evaluate this condition and treat or seal the substances as recommended. Please note that mold and mold testing is beyond the scope of this inspection. Given visible conditions at the time of inspection, and the fact that this is a new build, it seems likely this is just from the construction process. While this may not present any issues to the occupant, it could pose a re-sale issue. I recommend consulting with the builder about options for documenting and / or sealing as recommended.



Attic Insulation

Insulation Type: Fiberglass

Approximate Insulation R-Value on Attic Floor: 20


Attic Fan Exhaust Vents

🔧 (A-2) Repair: The exhaust ductwork for the bathroom fans are disconnected in the attic and requires repair to ensure fan exhaust is properly venting to the exterior. Having exhaust fans venting into the attic can cause lead to seasonal condensation and moisture controls problems and could damage the attic building materials. Repair to ensure proper discharge of air to the exterior and be sure exhaust ductwork is insulated to R-8 or better to reduce risks of seasonal condensation.



Attic and Roof Cavity Ventilation

Attic Ventilation Method: Ridge vents

 **(A-3) Improve:** The attic and roof cavity ventilation look to be inadequate by today's standards which recommend open ventilation levels in a ratio of 1 to 150 of the attic area. Proper attic ventilation is important for the roofing materials to perform as intended and to reduce chances for condensation problems and heat build-up in the attic. This is a common condition on older buildings that did not originally have composition roofs. As this building is made tighter and better insulated and air-sealed for energy efficiency it is important to improve roof cavity ventilation as well. Consult with a qualified general contractor about adding soffit or core vents for lower "intake" roof ventilation. Generally, you want at least 60% of the air to be from lower soffit or intake vents.

Crawl Space

General Crawl Space

Crawl Space: Present

Crawl Space Access

Method of Inspection: Crawled

During inspection of the crawl space, every effort is made to inspect the entire space. Visual inspection of crawl spaces is difficult and limited as access is often restricted by pipes, ducts and sub-floor insulation as well as limited clearances.

Vapor Barrier

Vapor Barrier Material: Concrete

Crawl Space Ventilation

Ventilation Method: Vents to basement

Posts and Footings

Not visible

Insulation

Insulation Type: None noted

🔧 (CS1-1) Repair: No sub-floor insulation was noted in the crawl space. Sub-floors should be insulated to R-30 or better to conserve energy. Given the vulnerability to rodent intrusion in the space I do not recommend insulating with fiberglass as this is conducive to rodent nesting. Either leave uninsulated or insulate with spray or rigid foam.



Insulation is only located where supply ductwork is run.

Moisture Conditions

No water was visible or present at the time of inspection

Structure and Basement

Foundation

% of Foundation Not Visible: 30%

Building Configuration: Basement, Crawl space

Foundation Description: Masonry block

Floor, Wall and Ceiling Framing

Wall Framing: Not visible

Wall Sheathing: Plywood

Floor Framing: Partly visible, 2x6

Sub-Floor Material: Plywood

Ceiling Framing: 2x6

Basement

Rough and incomplete finishes

Basement Moisture

Some signs

As a general rule, older basements are prone to seasonal dampness and moisture issues. This is because there were no industry standards to water proof foundations at the time this home was built. Today's basements will likely be sealed on the outside with concrete sealer over the foundation. On top of this a water-proofing fabric is applied which will divert water into a footing drain system at the base of the foundation; old basements usually have none of these water-proofing systems installed. Some old basements do stay dry - typically the result of a good site and good soil drainage around the building. This is impossible to evaluate or predict during a visual home inspection.

✦ **(SB-1) Note:** Dehumidifier operating in the basement at the time of the inspection. Although evidence of moisture was not present, it is worth noting the operation of the dehumidifier.



Receipt -- The Complete Inspection Report

Report # 220514A

Inspection Date: 2022-05-14

Property inspected for:

John Doe
50 Randolph Road
Freehold, NJ 07728

Home Inspection

\$430.00

\$430.00

PAID

Thank you for your business!

We Inspect NJ
C/O Brian Duggan
50 Randolph Road
Freehold, NJ 07728
732-359-2132



We Inspect NJ

732-359-2132

weinspectnj@gmail.com

www.weinspectnj.com

Inspected by Brian Duggan, NJ State Inspector License No. 21GI00228700



Copyright © 2022 We Inspect NJ. All rights reserved. Software by ScribeWare.