

Serving the Inland Empire
3200 Guasti Road, Suite 100
Ontario, CA 91761

Tel : (909) 906-1025
Fax : (909) 906-1041
www.reservestudy.com



**ASSOCIATION
RESERVES™**

Planning For The Inevitable™

Regional Offices

Arizona
California
Colorado
Florida
Hawaii
Nevada
North Carolina
Texas
Washington



Whispering Palms *Hemet, CA*



Report #: 14073-3
Beginning: July 1, 2021
Expires: June 30, 2022

RESERVE STUDY Update "With-Site-Visit"

June 9, 2021

Welcome to your Reserve Study!

A Reserve Study is a valuable tool to help you budget responsibly for your property. This report contains all the information you need to avoid surprise expenses, make informed decisions, save money, and protect property values.

Regardless of the property type, it's a fact of life that the very moment construction is completed, every major building component begins a predictable process of physical deterioration. The operative word is "predictable" because planning for the inevitable is what a Reserve Study by **Association Reserves** is all about!

In this Report, you will find three key results:

- **Component List**

Unique to each property, the Component List serves as the foundation of the Reserve Study and details the scope and schedule of all necessary repairs & replacements.

- **Reserve Fund Strength**

A calculation that measures how well the Reserve Fund has kept pace with the property's physical deterioration.

- **Reserve Funding Plan**

A multi-year funding plan based on current Reserve Fund strength that allows for component repairs and replacements to be completed in a timely manner, with an emphasis on fairness and avoiding "catch-up" funding.

Questions?

Please contact your Project Manager directly.



Est. 1986

**ASSOCIATION
RESERVES™**

Planning For The Inevitable™

www.reservestudy.com

Table of Contents

Executive Summary	4
Executive Summary (Component List)	5
Introduction, Objectives, and Methodology	7
Which Physical Assets are Funded by Reserves?	8
How do we establish Useful Life and Remaining Useful Life estimates?	8
How do we establish Current Repair/Replacement Cost Estimates?	8
How much Reserves are enough?	9
How much should we contribute?	10
What is our Recommended Funding Goal?	10
Site Inspection Notes	11
Projected Expenses	12
Annual Reserve Expenses Graph	12
Reserve Fund Status & Recommended Funding Plan	13
Annual Reserve Funding Graph	13
30-Yr Cash Flow Graph	14
Percent Funded Graph	14
Table Descriptions	15
Budget Summary	16
Reserve Component List Detail	17
Fully Funded Balance	19
Component Significance	21
Accounting & Tax Summary	23
30-Year Reserve Plan Summary	25
30-Year Income/Expense Detail	26
Accuracy, Limitations, and Disclosures	38
Terms and Definitions	39
Component Details	40
General Common Area	41
Streets	52
Clubhouse Interior	58
Clubhouse Exterior	68
Pool	70

**Whispering Palms**


Hemet, CA

Level of Service: **Update "With-Site-Visit"**Report #: **14073-3**

of Units: 129

July 1, 2021 through June 30, 2022**Findings & Recommendations****as of July 1, 2021**

Projected Starting Reserve Balance	\$340,735
Fully Funded Balance	\$468,655
Average Reserve Deficit (Surplus) Per Unit	\$992
Percent Funded	72.7 %
Recommended 2021 Monthly Reserve Contributions	\$4,300
Most Recent Reserve Contribution Rate	\$4,300

Reserve Fund Strength: 72.7%**Risk of Special Assessment:****Economic Assumptions:**Net Annual "After Tax" Interest Earnings Accruing to Reserves **1.00 %**Annual Inflation Rate **3.00 %**

- This is an Update "With-Site-Visit".
- This Reserve Study was prepared by a credentialed Reserve Specialist (RS).
- Because your Reserve Fund is at 72.7 % Funded, this means the association's special assessment & deferred maintenance risk is currently Low.
- Your multi-year Funding Plan is designed to gradually bring you to the 100% level, or "Fully Funded". This is a low risk position where special assessments and other cash flow problems are extremely rare.
- Based on this starting point, your anticipated future expenses, and your historical Reserve contribution rate, our recommendation is to budget Monthly Reserve contributions of \$4,300. Nominal annual increases are scheduled to help offset inflation (see tables herein for details).
- We recommend that this Reserve Study be updated annually, with an on-site inspection update every three years.

# Component	Useful Life (yrs)	Rem. Useful Life (yrs)	Current Average Cost
General Common Area			
320 Pole Lights - Replace	25	1	\$45,000
403 Mailboxes - Replace	18	14	\$16,500
407 BBQ - Replace	10	6	\$1,250
503 Metal Fence/Gates - Repair	10	6	\$4,500
504 RV Gates - Replace	30	9	\$7,700
504 Vehicle Gates - Replace	30	15	\$13,500
704 Intercom - Replace	15	4	\$3,800
705 Gate Operator - Replace (rear)	12	4	\$3,500
705 Gate Operators - Replace (main)	12	0	\$7,000
1003 Irrigation Controllers - Replace	15	4	\$3,000
1006 Landscaping - Refurbish	10	2	\$17,500
1107 Metal Fence - Repaint	5	1	\$3,400
1401 Monument Signs - Replace	25	6	\$4,500
1403 Street Signs - Replace	25	6	\$14,000
1405 Bulletin Board - Replace	20	2	\$1,650
1809 Sewer Pumps - Replace	10	9	\$3,750
1810 4" Backflow Device - Replace	30	7	\$6,500
1810 8" Backflow Device - Replace	30	19	\$10,500
1900 Common Sewer Lines (partial)	5	1	\$9,000
1900 Common Water Lines (partial)	5	1	\$6,000
Streets			
201 Asphalt - Replace (2010)	35	23	\$21,500
201 Asphalt - Replace (2011)	35	24	\$67,000
201 Asphalt - Replace (2013)	35	26	\$96,000
201 Asphalt - Replace (2015)	35	28	\$46,000
201 Asphalt - Replace (2017)	35	30	\$53,000
201 Asphalt - Replace (2018/2019)	35	31	\$100,000
201 Asphalt - Replace (2027)	35	5	\$67,500
201 Asphalt - Replace (2029)	35	7	\$43,000
202 Asphalt - Seal/Repair	4	2	\$17,500
203 Parking Areas - Seal/Repair	6	2	\$2,900
204 Concrete Swales/Gutters - Repair	15	1	\$15,000
215 Loop Detectors - Replace	15	1	\$7,800
Clubhouse Interior			
303 HVAC Systems - Replace	20	6	\$19,500
411 Drinking Fountain - Replace	20	5	\$1,300
601 Carpet - Replace	12	2	\$1,100

# Component	Useful Life (yrs)	Rem. Useful Life (yrs)	Current Average Cost
602 Vinyl Floor - Replace	18	2	\$2,300
603 Tile Floor - Replace	25	12	\$11,000
604 Laminate Floor - Replace	18	5	\$8,000
901 Appliances - Replace	15	0	\$3,500
901 Refrigerators - Replace	15	5	\$1,900
903 Furniture - Replace (Billiard Room)	15	2	\$2,300
903 Furniture - Replace (Library)	15	2	\$4,300
903 Furniture - Replace (office)	15	2	\$3,750
903 Tables/Chairs - Replace	12	2	\$6,000
904 Kitchen - Remodel	25	2	\$15,000
905 Billiard Table - Replace	15	2	\$2,200
908 Window Treatments - Replace	20	10	\$5,000
910 Bathrooms - Refurbish	25	2	\$9,500
912 Office Equipment - Replace	8	1	\$2,300
913 Sound System - Replace	15	0	\$2,000
1110 Interior Surfaces - Repaint	15	2	\$6,000
Clubhouse Exterior			
411 Drinking Fountain - Replace	15	0	\$1,300
1115 Stucco - Repaint	15	2	\$4,500
1116 Wood Surfaces - Repaint/Repair	5	2	\$2,100
1304 Tile Roof - Replace underlayment	35	3	\$22,000
Pool			
404 Pool Furniture - Replace	8	1	\$9,000
1202 Pool - Resurface	12	2	\$16,000
1207 Pool Filter - Replace	12	6	\$1,400
1208 Pool Heater - Replace	12	11	\$3,700
1210 Pool Pump - Replace	8	0	\$1,250

60 Total Funded Components

Introduction



A Reserve Study is the art and science of anticipating, and preparing for, an association's major common area repair and replacement expenses. Partially art, because in this field we are making projections about the future. Partially science, because our work is a combination of research and well-defined computations, following consistent National Reserve Study Standard principles.

The foundation of this and every Reserve Study is your Reserve Component List (what you are reserving for). This is because the Reserve Component List defines the *scope and schedule* of all your anticipated upcoming Reserve projects. Based on that List and your starting balance, we calculate the association's Reserve Fund Strength (reported in terms of "Percent Funded"). Then we compute a Reserve Funding Plan to provide for the Reserve needs of the association. These form the three results of your Reserve Study.



Reserve contributions are not “for the future”. Reserve contributions are designed to offset the ongoing, daily deterioration of your Reserve assets. Done well, a stable, budgeted Reserve Funding Plan will collect sufficient funds from the owners who enjoyed the use of those assets, so the association is financially prepared for the irregular expenditures scattered through future years when those projects eventually require replacement.

Methodology



For this [Update With-Site-Visit Reserve Study](#), we started with a review of your prior Reserve Study, then looked into recent Reserve expenditures, evaluated how expenditures are handled (ongoing maintenance vs Reserves), and researched any well-established association

precedents. We performed an on-site inspection to evaluate your common areas, updating and adjusting your Reserve Component List as appropriate.

Which Physical Assets are Funded by Reserves?

There is a national-standard four-part test to determine which expenses should appear in your Reserve Component List. First, it must be a common area maintenance responsibility. Second, the component must have a limited life. Third, the remaining life must be predictable (or it by definition is a *surprise* which cannot be accurately anticipated). Fourth, the component must be above a minimum threshold cost (often between .5% and 1% of an association's total budget). This limits Reserve



RESERVE COMPONENT "FOUR-PART TEST"

Components to major, predictable expenses. Within this framework, it is inappropriate to include *lifetime* components, unpredictable expenses (such as damage due to fire, flood, or earthquake), and expenses more appropriately handled from the Operational Budget or as an insured loss.

How do we establish Useful Life and Remaining Useful Life estimates?

- 1) Visual Inspection (observed wear and age)
- 2) Association Reserves database of experience
- 3) Client History (install dates & previous life cycle information)
- 4) Vendor Evaluation and Recommendation

How do we establish Current Repair/Replacement Cost Estimates?

In this order...

- 1) Actual client cost history, or current proposals
- 2) Comparison to Association Reserves database of work done at similar associations
- 3) Vendor Recommendations
- 4) Reliable National Industry cost estimating guidebooks

How much Reserves are enough?

Reserve adequacy is not measured in cash terms. Reserve adequacy is found when the *amount* of current Reserve cash is compared to Reserve component deterioration (the *needs of the association*). Having *enough* means the association can execute its projects in a timely manner with existing Reserve funds. Not having *enough* typically creates deferred maintenance or special assessments.

Adequacy is measured in a two-step process:

- 1) Calculate the *value of deterioration* at the association (called Fully Funded Balance, or FFB).
- 2) Compare that to the Reserve Fund Balance, and express as a percentage.



Each year, the *value of deterioration* at the association changes. When there is more deterioration (as components approach the time they need to be replaced), there should be more cash to offset that deterioration and prepare for the expenditure. Conversely, the *value of deterioration* shrinks after projects are accomplished. The *value of deterioration* (the FFB) changes each year, and is a moving but predictable target.

There is a high risk of special assessments and deferred maintenance when the Percent Funded is *weak*, below 30%. Approximately 30% of all associations are in this high risk range. While the 100% point is Ideal (indicating Reserve cash is equal to the *value of deterioration*), a Reserve Fund in the 70% - 130% range is considered strong (low risk of special assessment).

Measuring your Reserves by Percent Funded tells how well prepared your association is for upcoming Reserve expenses. New buyers should be very aware of this important disclosure!

How much should we contribute?



According to National Reserve Study Standards, there are four Funding Principles to balance in developing your Reserve Funding Plan. Our first objective is to design a plan that provides you with sufficient cash to perform your Reserve projects on time. Second, a stable contribution is desirable because it keeps these naturally irregular expenses from unsettling the budget.

Reserve contributions that are evenly distributed over current and future owners enable each owner to pay their fair share of the association's Reserve expenses over the years. And finally, we develop a plan that is fiscally responsible and safe for Boardmembers to recommend to their association. Remember, it is the Board's job to provide for the ongoing care of the common areas. Boardmembers invite liability exposure when Reserve contributions are inadequate to offset ongoing common area deterioration.

What is our Recommended Funding Goal?

Maintaining the Reserve Fund at a level equal to the *value* of deterioration is called "Full Funding" (100% Funded). As each asset ages and becomes "used up," the Reserve Fund grows proportionally. **This is simple, responsible, and our recommendation.** Evidence shows that associations in the 70 - 130% range *enjoy a low risk of special assessments or deferred maintenance.*



Allowing the Reserves to fall close to zero, but not below zero, is called Baseline Funding. Doing so allows the Reserve Fund to drop into the 0 - 30% range, where there is a high risk of special assessments & deferred maintenance. Since Baseline Funding still provides for the timely execution of all Reserve projects, and only the "margin of safety" is different, Baseline Funding contributions average only 10% - 15% less than Full Funding contributions. Threshold Funding is the title of all other Cash or Percent Funded objectives *between* Baseline Funding and Full Funding.

Site Inspection Notes

During our site visit on 5/26/2021, we visually inspected all common areas of the association. Our scope includes visual inspection of accessible areas and components and does not include any destructive or other testing.



Projected Expenses

While this Reserve Study looks forward 30 years, we have no expectation that all these expenses will all take place as anticipated. This Reserve Study needs to be updated annually because we expect the timing of these expenses to shift and the size of these expenses to change. We do feel more certain of the timing and cost of near-term expenses than expenses many years away.

The figure below summarizes the projected future expenses at your association as defined by your Reserve Component List. A summary of these components are shown in the Component Details table, while a summary of the expenses themselves are shown in the 30-yr Summary table.




Figure 1

Reserve Fund Status

The starting point for our financial analysis is your Reserve Fund balance, projected to be \$340,735 as-of the start of your Fiscal Year on 7/1/2021. This is based on your actual balance on 4/30/2021 of \$289,135 and anticipated Reserve contributions and expenses projected through the end of your Fiscal Year. As of your Fiscal Year Start, your Fully Funded Balance is computed to be \$468,655. This figure represents the deteriorated value of your common area components. Comparing your Reserve Balance to your Fully Funded Balance indicates your Reserves are 72.7 % Funded.

Recommended Funding Plan

Based on your current Percent Funded and your near-term and long-term Reserve needs, we are recommending budgeted contributions of \$4,300 Monthly this Fiscal Year. The overall 30-yr plan, in perspective, is shown below. This same information is shown numerically in both the 30-yr Summary and the Cash Flow Detail tables.




Figure 2

The following chart shows your Reserve balance under our recommended Full Funding Plan and at your current budgeted contribution rate, compared to your always-changing Fully Funded Balance target.




Figure 3

This figure shows the same information plotted on a Percent Funded scale. It is clear here to see how your Reserve Fund strength approaches the 100% Funded level under our recommended multi-yr Funding Plan.



Figure 4



Table Descriptions

Executive Summary is a summary of your Reserve Components

Budget Summary is a management and accounting tool, summarizing groupings of your Reserve Components.

Reserve Component List Detail discloses key Component information, providing the foundation upon which the financial analysis is performed.

Fully Funded Balance shows the calculation of the Fully Funded Balance for each of your components, and their contributions to the property total. For each component, the Fully Funded Balance is the fraction of life used up multiplied by its estimated Current Replacement Cost.

Component Significance shows the relative significance of each component to Reserve funding needs of the property, helping you see which components have more (or less) influence than others on your total Reserve contribution rate. The deterioration cost/yr of each component is calculated by dividing the estimated Current Replacement Cost by its Useful Life, then that component's percentage of the total is displayed.

Accounting & Tax Summary provides information on each Component's proportionate portion of key totals, valuable to accounting professionals primarily during tax preparation time of year.

30-Yr Reserve Plan Summary provides a one-page 30-year summary of the cash flowing into and out of the Reserve Fund, with a display of the Fully Funded Balance, Percent Funded, and special assessment risk at the beginning of each year.

30-Year Income/Expense Detail shows the detailed income and expenses for each of the next 30 years. This table makes it possible to see which components are projected to require repair or replacement in a particular year, and the size of those individual expenses.




Budget Summary

Report # 14073-3
With-Site-Visit

	Useful Life		2021 Rem. Useful Life		Estimated Replacement Cost in 2021	2021 Expenditures	07/01/2021 Current Fund Balance	07/01/2021 Fully Funded Balance	Remaining Bal. to be Funded	2021 Contributions
	Min	Max	Min	Max						
General Common Area	5	30	0	19	\$182,550	\$7,000	\$109,068	\$129,100	\$73,482	\$14,893
Streets	4	35	1	31	\$537,200	\$0	\$106,174	\$205,535	\$431,026	\$24,376
Clubhouse Interior	8	25	0	12	\$106,950	\$5,500	\$75,760	\$83,980	\$31,190	\$7,008
Clubhouse Exterior	5	35	0	3	\$29,900	\$1,300	\$26,574	\$26,574	\$3,326	\$1,707
Pool	8	12	0	11	\$31,350	\$1,250	\$23,158	\$23,467	\$8,192	\$3,616
					\$887,950	\$15,050	\$340,735	\$468,655	\$547,215	\$51,600

Percent Funded: 72.7%





Reserve Component List Detail

Report # 14073-3
With-Site-Visit

#	Component	Quantity	Useful Life	Rem. Useful Life	Current Cost Estimate
General Common Area					
320	Pole Lights - Replace	(45) Fixtures	25	1	\$45,000
403	Mailboxes - Replace	(9) Kiosks (5) Parcels	18	14	\$16,500
407	BBQ - Replace	(1) BBQ	10	6	\$1,250
503	Metal Fence/Gates - Repair	Approx 395 LF	10	6	\$4,500
504	RV Gates - Replace	(2) Rolling Gates	30	9	\$7,700
504	Vehicle Gates - Replace	(3) Sets of Gates	30	15	\$13,500
704	Intercom - Replace	(1) Elite Intercom	15	4	\$3,800
705	Gate Operator - Replace (rear)	(1) Liftmaster	12	4	\$3,500
705	Gate Operators - Replace (main)	(2) Elite Swing Operators	12	0	\$7,000
1003	Irrigation Controllers - Replace	(2) Controllers	15	4	\$3,000
1006	Landscaping - Refurbish	Approx 0.65 acres	10	2	\$17,500
1107	Metal Fence - Repaint	Approx 395 LF	5	1	\$3,400
1401	Monument Signs - Replace	(2) Tile Signs	25	6	\$4,500
1403	Street Signs - Replace	(28) Signs, (14) Posts	25	6	\$14,000
1405	Bulletin Board - Replace	(1) 5x8 Structure	20	2	\$1,650
1809	Sewer Pumps - Replace	(3) Pumps	10	9	\$3,750
1810	4" Backflow Device - Replace	(1) 4" Backflow	30	7	\$6,500
1810	8" Backflow Device - Replace	(1) 8" backflow	30	19	\$10,500
1900	Common Sewer Lines (partial)	Extensive LF	5	1	\$9,000
1900	Common Water Lines (partial)	Extensive LF	5	1	\$6,000
Streets					
201	Asphalt - Replace (2010)	Approx 5,905 GSF	35	23	\$21,500
201	Asphalt - Replace (2011)	Approx 18,115 GSF	35	24	\$67,000
201	Asphalt - Replace (2013)	Approx 26,505 GSF	35	26	\$96,000
201	Asphalt - Replace (2015)	Approx 11,990 GSF	35	28	\$46,000
201	Asphalt - Replace (2017)	Approx 14,475 GSF	35	30	\$53,000
201	Asphalt - Replace (2018/2019)	Approx 13,260 GSF	35	31	\$100,000
201	Asphalt - Replace (2027)	Approx 18,220 GSF	35	5	\$67,500
201	Asphalt - Replace (2029)	Approx 11,305 GSF	35	7	\$43,000
202	Asphalt - Seal/Repair	Approx 119,870 GSF	4	2	\$17,500
203	Parking Areas - Seal/Repair	Approx 5,200 GSF	6	2	\$2,900
204	Concrete Swales/Gutters - Repair	Extensive area	15	1	\$15,000
215	Loop Detectors - Replace	(6) Loop Detectors	15	1	\$7,800
Clubhouse Interior					
303	HVAC Systems - Replace	(3) Carrier Units	20	6	\$19,500
411	Drinking Fountain - Replace	(1) Fountain	20	5	\$1,300
601	Carpet - Replace	Approx 25 GSY	12	2	\$1,100
602	Vinyl Floor - Replace	Approx 170 GSF	18	2	\$2,300
603	Tile Floor - Replace	Approx 590 GSF	25	12	\$11,000
604	Laminate Floor - Replace	Approx 1,180 GSF	18	5	\$8,000
901	Appliances - Replace	(4) Pieces	15	0	\$3,500
901	Refrigerators - Replace	(2) Refrigerators	15	5	\$1,900
903	Furniture - Replace (Billiard Room)	(10) Assorted Pieces	15	2	\$2,300
903	Furniture - Replace (Library)	(16) Assorted Pieces	15	2	\$4,300

#	Component	Quantity	Useful Life	Rem. Useful Life	Current Cost Estimate
903	Furniture - Replace (office)	(12) Assorted pieces	15	2	\$3,750
903	Tables/Chairs - Replace	(9) Tables (41) Chairs	12	2	\$6,000
904	Kitchen - Remodel	Kitchen Area	25	2	\$15,000
905	Billiard Table - Replace	(1) Standard Table	15	2	\$2,200
908	Window Treatments - Replace	(33) Blinds	20	10	\$5,000
910	Bathrooms - Refurbish	(2) bathrooms, 310 GSF	25	2	\$9,500
912	Office Equipment - Replace	(1) Computer, (1) Printer	8	1	\$2,300
913	Sound System - Replace	(1) System	15	0	\$2,000
1110	Interior Surfaces - Repaint	Approx 6,000 GSF	15	2	\$6,000
Clubhouse Exterior					
411	Drinking Fountain - Replace	(1) St. Steel Fountain	15	0	\$1,300
1115	Stucco - Repaint	Exterior Walls	15	2	\$4,500
1116	Wood Surfaces - Repaint/Repair	Trim & Doors	5	2	\$2,100
1304	Tile Roof - Replace underlayment	Approx 3,500 GSF	35	3	\$22,000
Pool					
404	Pool Furniture - Replace	(47) Assorted Pieces	8	1	\$9,000
1202	Pool - Resurface	(1) 25x45 pool	12	2	\$16,000
1207	Pool Filter - Replace	(1) 60 GSF Filter	12	6	\$1,400
1208	Pool Heater - Replace	(1) Pentair	12	11	\$3,700
1210	Pool Pump - Replace	(1) Pump & Motor	8	0	\$1,250
60	Total Funded Components				



#	Component	Current Cost Estimate	X	Effective Age	/	Useful Life	=	Fully Funded Balance
General Common Area								
320	Pole Lights - Replace	\$45,000	X	24	/	25	=	\$43,200
403	Mailboxes - Replace	\$16,500	X	4	/	18	=	\$3,667
407	BBQ - Replace	\$1,250	X	4	/	10	=	\$500
503	Metal Fence/Gates - Repair	\$4,500	X	4	/	10	=	\$1,800
504	RV Gates - Replace	\$7,700	X	21	/	30	=	\$5,390
504	Vehicle Gates - Replace	\$13,500	X	15	/	30	=	\$6,750
704	Intercom - Replace	\$3,800	X	11	/	15	=	\$2,787
705	Gate Operator - Replace (rear)	\$3,500	X	8	/	12	=	\$2,333
705	Gate Operators - Replace (main)	\$7,000	X	12	/	12	=	\$7,000
1003	Irrigation Controllers - Replace	\$3,000	X	11	/	15	=	\$2,200
1006	Landscaping - Refurbish	\$17,500	X	8	/	10	=	\$14,000
1107	Metal Fence - Repaint	\$3,400	X	4	/	5	=	\$2,720
1401	Monument Signs - Replace	\$4,500	X	19	/	25	=	\$3,420
1403	Street Signs - Replace	\$14,000	X	19	/	25	=	\$10,640
1405	Bulletin Board - Replace	\$1,650	X	18	/	20	=	\$1,485
1809	Sewer Pumps - Replace	\$3,750	X	1	/	10	=	\$375
1810	4" Backflow Device - Replace	\$6,500	X	23	/	30	=	\$4,983
1810	8" Backflow Device - Replace	\$10,500	X	11	/	30	=	\$3,850
1900	Common Sewer Lines (partial)	\$9,000	X	4	/	5	=	\$7,200
1900	Common Water Lines (partial)	\$6,000	X	4	/	5	=	\$4,800
Streets								
201	Asphalt - Replace (2010)	\$21,500	X	12	/	35	=	\$7,371
201	Asphalt - Replace (2011)	\$67,000	X	11	/	35	=	\$21,057
201	Asphalt - Replace (2013)	\$96,000	X	9	/	35	=	\$24,686
201	Asphalt - Replace (2015)	\$46,000	X	7	/	35	=	\$9,200
201	Asphalt - Replace (2017)	\$53,000	X	5	/	35	=	\$7,571
201	Asphalt - Replace (2018/2019)	\$100,000	X	4	/	35	=	\$11,429
201	Asphalt - Replace (2027)	\$67,500	X	30	/	35	=	\$57,857
201	Asphalt - Replace (2029)	\$43,000	X	28	/	35	=	\$34,400
202	Asphalt - Seal/Repair	\$17,500	X	2	/	4	=	\$8,750
203	Parking Areas - Seal/Repair	\$2,900	X	4	/	6	=	\$1,933
204	Concrete Swales/Gutters - Repair	\$15,000	X	14	/	15	=	\$14,000
215	Loop Detectors - Replace	\$7,800	X	14	/	15	=	\$7,280
Clubhouse Interior								
303	HVAC Systems - Replace	\$19,500	X	14	/	20	=	\$13,650
411	Drinking Fountain - Replace	\$1,300	X	15	/	20	=	\$975
601	Carpet - Replace	\$1,100	X	10	/	12	=	\$917
602	Vinyl Floor - Replace	\$2,300	X	16	/	18	=	\$2,044
603	Tile Floor - Replace	\$11,000	X	13	/	25	=	\$5,720
604	Laminate Floor - Replace	\$8,000	X	13	/	18	=	\$5,778
901	Appliances - Replace	\$3,500	X	15	/	15	=	\$3,500
901	Refrigerators - Replace	\$1,900	X	10	/	15	=	\$1,267
903	Furniture - Replace (Billiard Room)	\$2,300	X	13	/	15	=	\$1,993
903	Furniture - Replace (Library)	\$4,300	X	13	/	15	=	\$3,727

#	Component	Current Cost Estimate	X	Effective Age	/	Useful Life	=	Fully Funded Balance
903	Furniture - Replace (office)	\$3,750	X	13	/	15	=	\$3,250
903	Tables/Chairs - Replace	\$6,000	X	10	/	12	=	\$5,000
904	Kitchen - Remodel	\$15,000	X	23	/	25	=	\$13,800
905	Billiard Table - Replace	\$2,200	X	13	/	15	=	\$1,907
908	Window Treatments - Replace	\$5,000	X	10	/	20	=	\$2,500
910	Bathrooms - Refurbish	\$9,500	X	23	/	25	=	\$8,740
912	Office Equipment - Replace	\$2,300	X	7	/	8	=	\$2,013
913	Sound System - Replace	\$2,000	X	15	/	15	=	\$2,000
1110	Interior Surfaces - Repaint	\$6,000	X	13	/	15	=	\$5,200
Clubhouse Exterior								
411	Drinking Fountain - Replace	\$1,300	X	15	/	15	=	\$1,300
1115	Stucco - Repaint	\$4,500	X	13	/	15	=	\$3,900
1116	Wood Surfaces - Repaint/Repair	\$2,100	X	3	/	5	=	\$1,260
1304	Tile Roof - Replace underlayment	\$22,000	X	32	/	35	=	\$20,114
Pool								
404	Pool Furniture - Replace	\$9,000	X	7	/	8	=	\$7,875
1202	Pool - Resurface	\$16,000	X	10	/	12	=	\$13,333
1207	Pool Filter - Replace	\$1,400	X	6	/	12	=	\$700
1208	Pool Heater - Replace	\$3,700	X	1	/	12	=	\$308
1210	Pool Pump - Replace	\$1,250	X	8	/	8	=	\$1,250
								\$468,655



# Component	Useful Life (yrs)	Current Cost Estimate	Deterioration Cost/Yr	Deterioration Significance
General Common Area				
320 Pole Lights - Replace	25	\$45,000	\$1,800	4.15 %
403 Mailboxes - Replace	18	\$16,500	\$917	2.11 %
407 BBQ - Replace	10	\$1,250	\$125	0.29 %
503 Metal Fence/Gates - Repair	10	\$4,500	\$450	1.04 %
504 RV Gates - Replace	30	\$7,700	\$257	0.59 %
504 Vehicle Gates - Replace	30	\$13,500	\$450	1.04 %
704 Intercom - Replace	15	\$3,800	\$253	0.58 %
705 Gate Operator - Replace (rear)	12	\$3,500	\$292	0.67 %
705 Gate Operators - Replace (main)	12	\$7,000	\$583	1.34 %
1003 Irrigation Controllers - Replace	15	\$3,000	\$200	0.46 %
1006 Landscaping - Refurbish	10	\$17,500	\$1,750	4.03 %
1107 Metal Fence - Repaint	5	\$3,400	\$680	1.57 %
1401 Monument Signs - Replace	25	\$4,500	\$180	0.41 %
1403 Street Signs - Replace	25	\$14,000	\$560	1.29 %
1405 Bulletin Board - Replace	20	\$1,650	\$83	0.19 %
1809 Sewer Pumps - Replace	10	\$3,750	\$375	0.86 %
1810 4" Backflow Device - Replace	30	\$6,500	\$217	0.50 %
1810 8" Backflow Device - Replace	30	\$10,500	\$350	0.81 %
1900 Common Sewer Lines (partial)	5	\$9,000	\$1,800	4.15 %
1900 Common Water Lines (partial)	5	\$6,000	\$1,200	2.77 %
Streets				
201 Asphalt - Replace (2010)	35	\$21,500	\$614	1.42 %
201 Asphalt - Replace (2011)	35	\$67,000	\$1,914	4.41 %
201 Asphalt - Replace (2013)	35	\$96,000	\$2,743	6.32 %
201 Asphalt - Replace (2015)	35	\$46,000	\$1,314	3.03 %
201 Asphalt - Replace (2017)	35	\$53,000	\$1,514	3.49 %
201 Asphalt - Replace (2018/2019)	35	\$100,000	\$2,857	6.59 %
201 Asphalt - Replace (2027)	35	\$67,500	\$1,929	4.45 %
201 Asphalt - Replace (2029)	35	\$43,000	\$1,229	2.83 %
202 Asphalt - Seal/Repair	4	\$17,500	\$4,375	10.09 %
203 Parking Areas - Seal/Repair	6	\$2,900	\$483	1.11 %
204 Concrete Swales/Gutters - Repair	15	\$15,000	\$1,000	2.31 %
215 Loop Detectors - Replace	15	\$7,800	\$520	1.20 %
Clubhouse Interior				
303 HVAC Systems - Replace	20	\$19,500	\$975	2.25 %
411 Drinking Fountain - Replace	20	\$1,300	\$65	0.15 %
601 Carpet - Replace	12	\$1,100	\$92	0.21 %
602 Vinyl Floor - Replace	18	\$2,300	\$128	0.29 %
603 Tile Floor - Replace	25	\$11,000	\$440	1.01 %
604 Laminate Floor - Replace	18	\$8,000	\$444	1.02 %
901 Appliances - Replace	15	\$3,500	\$233	0.54 %
901 Refrigerators - Replace	15	\$1,900	\$127	0.29 %
903 Furniture - Replace (Billiard Room)	15	\$2,300	\$153	0.35 %
903 Furniture - Replace (Library)	15	\$4,300	\$287	0.66 %

# Component	Useful Life (yrs)	Current Cost Estimate	Deterioration Cost/Yr	Deterioration Significance
903 Furniture - Replace (office)	15	\$3,750	\$250	0.58 %
903 Tables/Chairs - Replace	12	\$6,000	\$500	1.15 %
904 Kitchen - Remodel	25	\$15,000	\$600	1.38 %
905 Billiard Table - Replace	15	\$2,200	\$147	0.34 %
908 Window Treatments - Replace	20	\$5,000	\$250	0.58 %
910 Bathrooms - Refurbish	25	\$9,500	\$380	0.88 %
912 Office Equipment - Replace	8	\$2,300	\$288	0.66 %
913 Sound System - Replace	15	\$2,000	\$133	0.31 %
1110 Interior Surfaces - Repaint	15	\$6,000	\$400	0.92 %
Clubhouse Exterior				
411 Drinking Fountain - Replace	15	\$1,300	\$87	0.20 %
1115 Stucco - Repaint	15	\$4,500	\$300	0.69 %
1116 Wood Surfaces - Repaint/Repair	5	\$2,100	\$420	0.97 %
1304 Tile Roof - Replace underlayment	35	\$22,000	\$629	1.45 %
Pool				
404 Pool Furniture - Replace	8	\$9,000	\$1,125	2.59 %
1202 Pool - Resurface	12	\$16,000	\$1,333	3.07 %
1207 Pool Filter - Replace	12	\$1,400	\$117	0.27 %
1208 Pool Heater - Replace	12	\$3,700	\$308	0.71 %
1210 Pool Pump - Replace	8	\$1,250	\$156	0.36 %
60 Total Funded Components			\$43,380	100.00 %



# Component	UL	RUL	Current Cost Estimate	Fully Funded Balance	Proportional Reserve Contribs
General Common Area					
320 Pole Lights - Replace	25	1	\$45,000	\$43,200	\$178.42
403 Mailboxes - Replace	18	14	\$16,500	\$3,667	\$90.86
407 BBQ - Replace	10	6	\$1,250	\$500	\$12.39
503 Metal Fence/Gates - Repair	10	6	\$4,500	\$1,800	\$44.61
504 RV Gates - Replace	30	9	\$7,700	\$5,390	\$25.44
504 Vehicle Gates - Replace	30	15	\$13,500	\$6,750	\$44.61
704 Intercom - Replace	15	4	\$3,800	\$2,787	\$25.11
705 Gate Operator - Replace (rear)	12	4	\$3,500	\$2,333	\$28.91
705 Gate Operators - Replace (main)	12	0	\$7,000	\$7,000	\$57.82
1003 Irrigation Controllers - Replace	15	4	\$3,000	\$2,200	\$19.82
1006 Landscaping - Refurbish	10	2	\$17,500	\$14,000	\$173.47
1107 Metal Fence - Repaint	5	1	\$3,400	\$2,720	\$67.40
1401 Monument Signs - Replace	25	6	\$4,500	\$3,420	\$17.84
1403 Street Signs - Replace	25	6	\$14,000	\$10,640	\$55.51
1405 Bulletin Board - Replace	20	2	\$1,650	\$1,485	\$8.18
1809 Sewer Pumps - Replace	10	9	\$3,750	\$375	\$37.17
1810 4" Backflow Device - Replace	30	7	\$6,500	\$4,983	\$21.48
1810 8" Backflow Device - Replace	30	19	\$10,500	\$3,850	\$34.69
1900 Common Sewer Lines (partial)	5	1	\$9,000	\$7,200	\$178.42
1900 Common Water Lines (partial)	5	1	\$6,000	\$4,800	\$118.95
Streets					
201 Asphalt - Replace (2010)	35	23	\$21,500	\$7,371	\$60.89
201 Asphalt - Replace (2011)	35	24	\$67,000	\$21,057	\$189.75
201 Asphalt - Replace (2013)	35	26	\$96,000	\$24,686	\$271.89
201 Asphalt - Replace (2015)	35	28	\$46,000	\$9,200	\$130.28
201 Asphalt - Replace (2017)	35	30	\$53,000	\$7,571	\$150.10
201 Asphalt - Replace (2018/2019)	35	31	\$100,000	\$11,429	\$283.21
201 Asphalt - Replace (2027)	35	5	\$67,500	\$57,857	\$191.17
201 Asphalt - Replace (2029)	35	7	\$43,000	\$34,400	\$121.78
202 Asphalt - Seal/Repair	4	2	\$17,500	\$8,750	\$433.67
203 Parking Areas - Seal/Repair	6	2	\$2,900	\$1,933	\$47.91
204 Concrete Swales/Gutters - Repair	15	1	\$15,000	\$14,000	\$99.12
215 Loop Detectors - Replace	15	1	\$7,800	\$7,280	\$51.54
Clubhouse Interior					
303 HVAC Systems - Replace	20	6	\$19,500	\$13,650	\$96.65
411 Drinking Fountain - Replace	20	5	\$1,300	\$975	\$6.44
601 Carpet - Replace	12	2	\$1,100	\$917	\$9.09
602 Vinyl Floor - Replace	18	2	\$2,300	\$2,044	\$12.67
603 Tile Floor - Replace	25	12	\$11,000	\$5,720	\$43.61
604 Laminate Floor - Replace	18	5	\$8,000	\$5,778	\$44.06
901 Appliances - Replace	15	0	\$3,500	\$3,500	\$23.13
901 Refrigerators - Replace	15	5	\$1,900	\$1,267	\$12.56
903 Furniture - Replace (Billiard Room)	15	2	\$2,300	\$1,993	\$15.20

# Component	UL	RUL	Current Cost Estimate	Fully Funded Balance	Proportional Reserve Contribs
903 Furniture - Replace (Library)	15	2	\$4,300	\$3,727	\$28.42
903 Furniture - Replace (office)	15	2	\$3,750	\$3,250	\$24.78
903 Tables/Chairs - Replace	12	2	\$6,000	\$5,000	\$49.56
904 Kitchen - Remodel	25	2	\$15,000	\$13,800	\$59.47
905 Billiard Table - Replace	15	2	\$2,200	\$1,907	\$14.54
908 Window Treatments - Replace	20	10	\$5,000	\$2,500	\$24.78
910 Bathrooms - Refurbish	25	2	\$9,500	\$8,740	\$37.67
912 Office Equipment - Replace	8	1	\$2,300	\$2,013	\$28.50
913 Sound System - Replace	15	0	\$2,000	\$2,000	\$13.22
1110 Interior Surfaces - Repaint	15	2	\$6,000	\$5,200	\$39.65
Clubhouse Exterior					
411 Drinking Fountain - Replace	15	0	\$1,300	\$1,300	\$8.59
1115 Stucco - Repaint	15	2	\$4,500	\$3,900	\$29.74
1116 Wood Surfaces - Repaint/Repair	5	2	\$2,100	\$1,260	\$41.63
1304 Tile Roof - Replace underlayment	35	3	\$22,000	\$20,114	\$62.31
Pool					
404 Pool Furniture - Replace	8	1	\$9,000	\$7,875	\$111.52
1202 Pool - Resurface	12	2	\$16,000	\$13,333	\$132.17
1207 Pool Filter - Replace	12	6	\$1,400	\$700	\$11.56
1208 Pool Heater - Replace	12	11	\$3,700	\$308	\$30.56
1210 Pool Pump - Replace	8	0	\$1,250	\$1,250	\$15.49
60 Total Funded Components				\$468,655	\$4,300



30-Year Reserve Plan Summary

Report # 14073-3
With-Site-Visit

Fiscal Year Start: 2021

Interest: 1.00 %

Inflation: 3.00 %

Reserve Fund Strength: as-of Fiscal Year Start Date					Projected Reserve Balance Changes			
Year	Starting Reserve Balance	Fully Funded Balance	Percent Funded	Special Assmt Risk	Reserve Contribs.	Loan or Special Assmts	Interest Income	Reserve Expenses
2021	\$340,735	\$468,655	72.7 %	Low	\$51,600	\$0	\$3,607	\$15,050
2022	\$380,891	\$511,895	74.4 %	Low	\$53,509	\$0	\$3,591	\$100,425
2023	\$337,566	\$469,835	71.8 %	Low	\$55,489	\$0	\$3,059	\$121,579
2024	\$274,535	\$406,106	67.6 %	Medium	\$57,542	\$0	\$2,926	\$24,040
2025	\$310,964	\$442,352	70.3 %	Low	\$59,671	\$0	\$3,365	\$11,593
2026	\$362,407	\$493,971	73.4 %	Low	\$61,879	\$0	\$3,493	\$91,235
2027	\$336,545	\$466,616	72.1 %	Low	\$64,169	\$0	\$3,217	\$96,778
2028	\$307,153	\$434,285	70.7 %	Low	\$66,543	\$0	\$3,101	\$63,461
2029	\$313,335	\$436,900	71.7 %	Low	\$69,005	\$0	\$3,468	\$5,257
2030	\$380,551	\$501,193	75.9 %	Low	\$71,558	\$0	\$4,033	\$29,684
2031	\$426,459	\$543,953	78.4 %	Low	\$74,206	\$0	\$4,505	\$30,238
2032	\$474,931	\$589,174	80.6 %	Low	\$76,951	\$0	\$5,004	\$30,592
2033	\$526,295	\$637,189	82.6 %	Low	\$79,799	\$0	\$5,419	\$53,609
2034	\$557,904	\$664,792	83.9 %	Low	\$82,751	\$0	\$6,020	\$0
2035	\$646,675	\$750,351	86.2 %	Low	\$85,813	\$0	\$6,472	\$90,755
2036	\$648,204	\$746,968	86.8 %	Low	\$88,988	\$0	\$6,800	\$31,627
2037	\$712,365	\$806,413	88.3 %	Low	\$92,280	\$0	\$7,203	\$82,963
2038	\$728,885	\$816,853	89.2 %	Low	\$95,695	\$0	\$7,500	\$60,246
2039	\$771,834	\$853,156	90.5 %	Low	\$99,236	\$0	\$8,091	\$32,176
2040	\$846,985	\$921,676	91.9 %	Low	\$102,907	\$0	\$8,840	\$36,911
2041	\$921,821	\$989,656	93.1 %	Low	\$106,715	\$0	\$9,732	\$12,823
2042	\$1,025,445	\$1,086,837	94.4 %	Low	\$110,663	\$0	\$10,686	\$34,229
2043	\$1,112,564	\$1,167,306	95.3 %	Low	\$114,758	\$0	\$11,380	\$74,249
2044	\$1,164,453	\$1,211,462	96.1 %	Low	\$119,004	\$0	\$11,967	\$65,523
2045	\$1,229,901	\$1,268,499	97.0 %	Low	\$123,407	\$0	\$12,207	\$152,968
2046	\$1,212,547	\$1,239,824	97.8 %	Low	\$127,973	\$0	\$12,691	\$26,382
2047	\$1,326,830	\$1,343,398	98.8 %	Low	\$132,708	\$0	\$11,524	\$492,026
2048	\$979,036	\$973,272	100.6 %	Low	\$137,618	\$0	\$10,230	\$59,086
2049	\$1,067,798	\$1,040,861	102.6 %	Low	\$142,710	\$0	\$10,875	\$113,252
2050	\$1,108,131	\$1,057,663	104.8 %	Low	\$147,990	\$0	\$11,831	\$8,837

30-Year Income/Expense Detail

Report # 14073-3
With-Site-Visit

Fiscal Year	2021	2022	2023	2024	2025
Starting Reserve Balance	\$340,735	\$380,891	\$337,566	\$274,535	\$310,964
Annual Reserve Contribution	\$51,600	\$53,509	\$55,489	\$57,542	\$59,671
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$3,607	\$3,591	\$3,059	\$2,926	\$3,365
Total Income	\$395,941	\$437,991	\$396,114	\$335,004	\$374,000
# Component					
General Common Area					
320 Pole Lights - Replace	\$0	\$46,350	\$0	\$0	\$0
403 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
407 BBQ - Replace	\$0	\$0	\$0	\$0	\$0
503 Metal Fence/Gates - Repair	\$0	\$0	\$0	\$0	\$0
504 RV Gates - Replace	\$0	\$0	\$0	\$0	\$0
504 Vehicle Gates - Replace	\$0	\$0	\$0	\$0	\$0
704 Intercom - Replace	\$0	\$0	\$0	\$0	\$4,277
705 Gate Operator - Replace (rear)	\$0	\$0	\$0	\$0	\$3,939
705 Gate Operators - Replace (main)	\$7,000	\$0	\$0	\$0	\$0
1003 Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$3,377
1006 Landscaping - Refurbish	\$0	\$0	\$18,566	\$0	\$0
1107 Metal Fence - Repaint	\$0	\$3,502	\$0	\$0	\$0
1401 Monument Signs - Replace	\$0	\$0	\$0	\$0	\$0
1403 Street Signs - Replace	\$0	\$0	\$0	\$0	\$0
1405 Bulletin Board - Replace	\$0	\$0	\$1,750	\$0	\$0
1809 Sewer Pumps - Replace	\$0	\$0	\$0	\$0	\$0
1810 4" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1810 8" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1900 Common Sewer Lines (partial)	\$0	\$9,270	\$0	\$0	\$0
1900 Common Water Lines (partial)	\$0	\$6,180	\$0	\$0	\$0
Streets					
201 Asphalt - Replace (2010)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2011)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2013)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2015)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2017)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2018/2019)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2027)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2029)	\$0	\$0	\$0	\$0	\$0
202 Asphalt - Seal/Repair	\$0	\$0	\$18,566	\$0	\$0
203 Parking Areas - Seal/Repair	\$0	\$0	\$3,077	\$0	\$0
204 Concrete Swales/Gutters - Repair	\$0	\$15,450	\$0	\$0	\$0
215 Loop Detectors - Replace	\$0	\$8,034	\$0	\$0	\$0
Clubhouse Interior					
303 HVAC Systems - Replace	\$0	\$0	\$0	\$0	\$0
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
601 Carpet - Replace	\$0	\$0	\$1,167	\$0	\$0
602 Vinyl Floor - Replace	\$0	\$0	\$2,440	\$0	\$0
603 Tile Floor - Replace	\$0	\$0	\$0	\$0	\$0
604 Laminate Floor - Replace	\$0	\$0	\$0	\$0	\$0
901 Appliances - Replace	\$3,500	\$0	\$0	\$0	\$0
901 Refrigerators - Replace	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Billiard Room)	\$0	\$0	\$2,440	\$0	\$0
903 Furniture - Replace (Library)	\$0	\$0	\$4,562	\$0	\$0
903 Furniture - Replace (office)	\$0	\$0	\$3,978	\$0	\$0
903 Tables/Chairs - Replace	\$0	\$0	\$6,365	\$0	\$0
904 Kitchen - Remodel	\$0	\$0	\$15,914	\$0	\$0
905 Billiard Table - Replace	\$0	\$0	\$2,334	\$0	\$0
908 Window Treatments - Replace	\$0	\$0	\$0	\$0	\$0
910 Bathrooms - Refurbish	\$0	\$0	\$10,079	\$0	\$0
912 Office Equipment - Replace	\$0	\$2,369	\$0	\$0	\$0
913 Sound System - Replace	\$2,000	\$0	\$0	\$0	\$0
1110 Interior Surfaces - Repaint	\$0	\$0	\$6,365	\$0	\$0
Clubhouse Exterior					

Fiscal Year	2021	2022	2023	2024	2025
411 Drinking Fountain - Replace	\$1,300	\$0	\$0	\$0	\$0
1115 Stucco - Repaint	\$0	\$0	\$4,774	\$0	\$0
1116 Wood Surfaces - Repaint/Repair	\$0	\$0	\$2,228	\$0	\$0
1304 Tile Roof - Replace underlayment	\$0	\$0	\$0	\$24,040	\$0
Pool					
404 Pool Furniture - Replace	\$0	\$9,270	\$0	\$0	\$0
1202 Pool - Resurface	\$0	\$0	\$16,974	\$0	\$0
1207 Pool Filter - Replace	\$0	\$0	\$0	\$0	\$0
1208 Pool Heater - Replace	\$0	\$0	\$0	\$0	\$0
1210 Pool Pump - Replace	\$1,250	\$0	\$0	\$0	\$0
Total Expenses	\$15,050	\$100,425	\$121,579	\$24,040	\$11,593
Ending Reserve Balance	\$380,891	\$337,566	\$274,535	\$310,964	\$362,407

Fiscal Year	2026	2027	2028	2029	2030
Starting Reserve Balance	\$362,407	\$336,545	\$307,153	\$313,335	\$380,551
Annual Reserve Contribution	\$61,879	\$64,169	\$66,543	\$69,005	\$71,558
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$3,493	\$3,217	\$3,101	\$3,468	\$4,033
Total Income	\$427,780	\$403,931	\$376,797	\$385,808	\$456,142
# Component					
General Common Area					
320 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
403 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
407 BBQ - Replace	\$0	\$1,493	\$0	\$0	\$0
503 Metal Fence/Gates - Repair	\$0	\$5,373	\$0	\$0	\$0
504 RV Gates - Replace	\$0	\$0	\$0	\$0	\$10,047
504 Vehicle Gates - Replace	\$0	\$0	\$0	\$0	\$0
704 Intercom - Replace	\$0	\$0	\$0	\$0	\$0
705 Gate Operator - Replace (rear)	\$0	\$0	\$0	\$0	\$0
705 Gate Operators - Replace (main)	\$0	\$0	\$0	\$0	\$0
1003 Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$0
1006 Landscaping - Refurbish	\$0	\$0	\$0	\$0	\$0
1107 Metal Fence - Repaint	\$0	\$4,060	\$0	\$0	\$0
1401 Monument Signs - Replace	\$0	\$5,373	\$0	\$0	\$0
1403 Street Signs - Replace	\$0	\$16,717	\$0	\$0	\$0
1405 Bulletin Board - Replace	\$0	\$0	\$0	\$0	\$0
1809 Sewer Pumps - Replace	\$0	\$0	\$0	\$0	\$4,893
1810 4" Backflow Device - Replace	\$0	\$0	\$7,994	\$0	\$0
1810 8" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1900 Common Sewer Lines (partial)	\$0	\$10,746	\$0	\$0	\$0
1900 Common Water Lines (partial)	\$0	\$7,164	\$0	\$0	\$0
Streets					
201 Asphalt - Replace (2010)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2011)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2013)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2015)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2017)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2018/2019)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2027)	\$78,251	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2029)	\$0	\$0	\$52,885	\$0	\$0
202 Asphalt - Seal/Repair	\$0	\$20,896	\$0	\$0	\$0
203 Parking Areas - Seal/Repair	\$0	\$0	\$0	\$3,674	\$0
204 Concrete Swales/Gutters - Repair	\$0	\$0	\$0	\$0	\$0
215 Loop Detectors - Replace	\$0	\$0	\$0	\$0	\$0
Clubhouse Interior					
303 HVAC Systems - Replace	\$0	\$23,284	\$0	\$0	\$0
411 Drinking Fountain - Replace	\$1,507	\$0	\$0	\$0	\$0
601 Carpet - Replace	\$0	\$0	\$0	\$0	\$0
602 Vinyl Floor - Replace	\$0	\$0	\$0	\$0	\$0
603 Tile Floor - Replace	\$0	\$0	\$0	\$0	\$0
604 Laminate Floor - Replace	\$9,274	\$0	\$0	\$0	\$0
901 Appliances - Replace	\$0	\$0	\$0	\$0	\$0
901 Refrigerators - Replace	\$2,203	\$0	\$0	\$0	\$0
903 Furniture - Replace (Billiard Room)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Library)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (office)	\$0	\$0	\$0	\$0	\$0
903 Tables/Chairs - Replace	\$0	\$0	\$0	\$0	\$0
904 Kitchen - Remodel	\$0	\$0	\$0	\$0	\$0
905 Billiard Table - Replace	\$0	\$0	\$0	\$0	\$0
908 Window Treatments - Replace	\$0	\$0	\$0	\$0	\$0
910 Bathrooms - Refurbish	\$0	\$0	\$0	\$0	\$0
912 Office Equipment - Replace	\$0	\$0	\$0	\$0	\$3,001
913 Sound System - Replace	\$0	\$0	\$0	\$0	\$0
1110 Interior Surfaces - Repaint	\$0	\$0	\$0	\$0	\$0
Clubhouse Exterior					
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
1115 Stucco - Repaint	\$0	\$0	\$0	\$0	\$0
1116 Wood Surfaces - Repaint/Repair	\$0	\$0	\$2,583	\$0	\$0
1304 Tile Roof - Replace underlayment	\$0	\$0	\$0	\$0	\$0
Pool					
404 Pool Furniture - Replace	\$0	\$0	\$0	\$0	\$11,743

Fiscal Year	2026	2027	2028	2029	2030
1202 Pool - Resurface	\$0	\$0	\$0	\$0	\$0
1207 Pool Filter - Replace	\$0	\$1,672	\$0	\$0	\$0
1208 Pool Heater - Replace	\$0	\$0	\$0	\$0	\$0
1210 Pool Pump - Replace	\$0	\$0	\$0	\$1,583	\$0
Total Expenses	\$91,235	\$96,778	\$63,461	\$5,257	\$29,684
Ending Reserve Balance	\$336,545	\$307,153	\$313,335	\$380,551	\$426,459

Fiscal Year	2031	2032	2033	2034	2035
Starting Reserve Balance	\$426,459	\$474,931	\$526,295	\$557,904	\$646,675
Annual Reserve Contribution	\$74,206	\$76,951	\$79,799	\$82,751	\$85,813
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$4,505	\$5,004	\$5,419	\$6,020	\$6,472
Total Income	\$505,169	\$556,886	\$611,512	\$646,675	\$738,959
# Component					
General Common Area					
320 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
403 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$24,958
407 BBQ - Replace	\$0	\$0	\$0	\$0	\$0
503 Metal Fence/Gates - Repair	\$0	\$0	\$0	\$0	\$0
504 RV Gates - Replace	\$0	\$0	\$0	\$0	\$0
504 Vehicle Gates - Replace	\$0	\$0	\$0	\$0	\$0
704 Intercom - Replace	\$0	\$0	\$0	\$0	\$0
705 Gate Operator - Replace (rear)	\$0	\$0	\$0	\$0	\$0
705 Gate Operators - Replace (main)	\$0	\$0	\$9,980	\$0	\$0
1003 Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$0
1006 Landscaping - Refurbish	\$0	\$0	\$24,951	\$0	\$0
1107 Metal Fence - Repaint	\$0	\$4,706	\$0	\$0	\$0
1401 Monument Signs - Replace	\$0	\$0	\$0	\$0	\$0
1403 Street Signs - Replace	\$0	\$0	\$0	\$0	\$0
1405 Bulletin Board - Replace	\$0	\$0	\$0	\$0	\$0
1809 Sewer Pumps - Replace	\$0	\$0	\$0	\$0	\$0
1810 4" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1810 8" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1900 Common Sewer Lines (partial)	\$0	\$12,458	\$0	\$0	\$0
1900 Common Water Lines (partial)	\$0	\$8,305	\$0	\$0	\$0
Streets					
201 Asphalt - Replace (2010)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2011)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2013)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2015)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2017)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2018/2019)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2027)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2029)	\$0	\$0	\$0	\$0	\$0
202 Asphalt - Seal/Repair	\$23,519	\$0	\$0	\$0	\$26,470
203 Parking Areas - Seal/Repair	\$0	\$0	\$0	\$0	\$4,387
204 Concrete Swales/Gutters - Repair	\$0	\$0	\$0	\$0	\$0
215 Loop Detectors - Replace	\$0	\$0	\$0	\$0	\$0
Clubhouse Interior					
303 HVAC Systems - Replace	\$0	\$0	\$0	\$0	\$0
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
601 Carpet - Replace	\$0	\$0	\$0	\$0	\$1,664
602 Vinyl Floor - Replace	\$0	\$0	\$0	\$0	\$0
603 Tile Floor - Replace	\$0	\$0	\$15,683	\$0	\$0
604 Laminate Floor - Replace	\$0	\$0	\$0	\$0	\$0
901 Appliances - Replace	\$0	\$0	\$0	\$0	\$0
901 Refrigerators - Replace	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Billiard Room)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Library)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (office)	\$0	\$0	\$0	\$0	\$0
903 Tables/Chairs - Replace	\$0	\$0	\$0	\$0	\$9,076
904 Kitchen - Remodel	\$0	\$0	\$0	\$0	\$0
905 Billiard Table - Replace	\$0	\$0	\$0	\$0	\$0
908 Window Treatments - Replace	\$6,720	\$0	\$0	\$0	\$0
910 Bathrooms - Refurbish	\$0	\$0	\$0	\$0	\$0
912 Office Equipment - Replace	\$0	\$0	\$0	\$0	\$0
913 Sound System - Replace	\$0	\$0	\$0	\$0	\$0
1110 Interior Surfaces - Repaint	\$0	\$0	\$0	\$0	\$0
Clubhouse Exterior					
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
1115 Stucco - Repaint	\$0	\$0	\$0	\$0	\$0
1116 Wood Surfaces - Repaint/Repair	\$0	\$0	\$2,994	\$0	\$0
1304 Tile Roof - Replace underlayment	\$0	\$0	\$0	\$0	\$0
Pool					
404 Pool Furniture - Replace	\$0	\$0	\$0	\$0	\$0

Fiscal Year		2031	2032	2033	2034	2035
1202	Pool - Resurface	\$0	\$0	\$0	\$0	\$24,201
1207	Pool Filter - Replace	\$0	\$0	\$0	\$0	\$0
1208	Pool Heater - Replace	\$0	\$5,122	\$0	\$0	\$0
1210	Pool Pump - Replace	\$0	\$0	\$0	\$0	\$0
Total Expenses		\$30,238	\$30,592	\$53,609	\$0	\$90,755
Ending Reserve Balance		\$474,931	\$526,295	\$557,904	\$646,675	\$648,204

Fiscal Year	2036	2037	2038	2039	2040
Starting Reserve Balance	\$648,204	\$712,365	\$728,885	\$771,834	\$846,985
Annual Reserve Contribution	\$88,988	\$92,280	\$95,695	\$99,236	\$102,907
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$6,800	\$7,203	\$7,500	\$8,091	\$8,840
Total Income	\$743,992	\$811,849	\$832,081	\$879,161	\$958,732
# Component					
General Common Area					
320 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
403 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
407 BBQ - Replace	\$0	\$2,006	\$0	\$0	\$0
503 Metal Fence/Gates - Repair	\$0	\$7,221	\$0	\$0	\$0
504 RV Gates - Replace	\$0	\$0	\$0	\$0	\$0
504 Vehicle Gates - Replace	\$21,033	\$0	\$0	\$0	\$0
704 Intercom - Replace	\$0	\$0	\$0	\$0	\$6,663
705 Gate Operator - Replace (rear)	\$0	\$5,616	\$0	\$0	\$0
705 Gate Operators - Replace (main)	\$0	\$0	\$0	\$0	\$0
1003 Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$5,261
1006 Landscaping - Refurbish	\$0	\$0	\$0	\$0	\$0
1107 Metal Fence - Repaint	\$0	\$5,456	\$0	\$0	\$0
1401 Monument Signs - Replace	\$0	\$0	\$0	\$0	\$0
1403 Street Signs - Replace	\$0	\$0	\$0	\$0	\$0
1405 Bulletin Board - Replace	\$0	\$0	\$0	\$0	\$0
1809 Sewer Pumps - Replace	\$0	\$0	\$0	\$0	\$6,576
1810 4" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1810 8" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$18,412
1900 Common Sewer Lines (partial)	\$0	\$14,442	\$0	\$0	\$0
1900 Common Water Lines (partial)	\$0	\$9,628	\$0	\$0	\$0
Streets					
201 Asphalt - Replace (2010)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2011)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2013)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2015)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2017)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2018/2019)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2027)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2029)	\$0	\$0	\$0	\$0	\$0
202 Asphalt - Seal/Repair	\$0	\$0	\$0	\$29,793	\$0
203 Parking Areas - Seal/Repair	\$0	\$0	\$0	\$0	\$0
204 Concrete Swales/Gutters - Repair	\$0	\$24,071	\$0	\$0	\$0
215 Loop Detectors - Replace	\$0	\$12,517	\$0	\$0	\$0
Clubhouse Interior					
303 HVAC Systems - Replace	\$0	\$0	\$0	\$0	\$0
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
601 Carpet - Replace	\$0	\$0	\$0	\$0	\$0
602 Vinyl Floor - Replace	\$0	\$0	\$0	\$0	\$0
603 Tile Floor - Replace	\$0	\$0	\$0	\$0	\$0
604 Laminate Floor - Replace	\$0	\$0	\$0	\$0	\$0
901 Appliances - Replace	\$5,453	\$0	\$0	\$0	\$0
901 Refrigerators - Replace	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Billiard Room)	\$0	\$0	\$3,802	\$0	\$0
903 Furniture - Replace (Library)	\$0	\$0	\$7,107	\$0	\$0
903 Furniture - Replace (office)	\$0	\$0	\$6,198	\$0	\$0
903 Tables/Chairs - Replace	\$0	\$0	\$0	\$0	\$0
904 Kitchen - Remodel	\$0	\$0	\$0	\$0	\$0
905 Billiard Table - Replace	\$0	\$0	\$3,636	\$0	\$0
908 Window Treatments - Replace	\$0	\$0	\$0	\$0	\$0
910 Bathrooms - Refurbish	\$0	\$0	\$0	\$0	\$0
912 Office Equipment - Replace	\$0	\$0	\$3,802	\$0	\$0
913 Sound System - Replace	\$3,116	\$0	\$0	\$0	\$0
1110 Interior Surfaces - Repaint	\$0	\$0	\$9,917	\$0	\$0
Clubhouse Exterior					
411 Drinking Fountain - Replace	\$2,025	\$0	\$0	\$0	\$0
1115 Stucco - Repaint	\$0	\$0	\$7,438	\$0	\$0
1116 Wood Surfaces - Repaint/Repair	\$0	\$0	\$3,471	\$0	\$0
1304 Tile Roof - Replace underlayment	\$0	\$0	\$0	\$0	\$0
Pool					
404 Pool Furniture - Replace	\$0	\$0	\$14,876	\$0	\$0

Fiscal Year		2036	2037	2038	2039	2040
1202	Pool - Resurface	\$0	\$0	\$0	\$0	\$0
1207	Pool Filter - Replace	\$0	\$0	\$0	\$2,383	\$0
1208	Pool Heater - Replace	\$0	\$0	\$0	\$0	\$0
1210	Pool Pump - Replace	\$0	\$2,006	\$0	\$0	\$0
Total Expenses		\$31,627	\$82,963	\$60,246	\$32,176	\$36,911
Ending Reserve Balance		\$712,365	\$728,885	\$771,834	\$846,985	\$921,821

Fiscal Year	2041	2042	2043	2044	2045
Starting Reserve Balance	\$921,821	\$1,025,445	\$1,112,564	\$1,164,453	\$1,229,901
Annual Reserve Contribution	\$106,715	\$110,663	\$114,758	\$119,004	\$123,407
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$9,732	\$10,686	\$11,380	\$11,967	\$12,207
Total Income	\$1,038,268	\$1,146,793	\$1,238,702	\$1,295,424	\$1,365,515
# Component					
General Common Area					
320 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
403 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
407 BBQ - Replace	\$0	\$0	\$0	\$0	\$0
503 Metal Fence/Gates - Repair	\$0	\$0	\$0	\$0	\$0
504 RV Gates - Replace	\$0	\$0	\$0	\$0	\$0
504 Vehicle Gates - Replace	\$0	\$0	\$0	\$0	\$0
704 Intercom - Replace	\$0	\$0	\$0	\$0	\$0
705 Gate Operator - Replace (rear)	\$0	\$0	\$0	\$0	\$0
705 Gate Operators - Replace (main)	\$0	\$0	\$0	\$0	\$14,230
1003 Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$0
1006 Landscaping - Refurbish	\$0	\$0	\$33,532	\$0	\$0
1107 Metal Fence - Repaint	\$0	\$6,325	\$0	\$0	\$0
1401 Monument Signs - Replace	\$0	\$0	\$0	\$0	\$0
1403 Street Signs - Replace	\$0	\$0	\$0	\$0	\$0
1405 Bulletin Board - Replace	\$0	\$0	\$3,162	\$0	\$0
1809 Sewer Pumps - Replace	\$0	\$0	\$0	\$0	\$0
1810 4" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1810 8" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1900 Common Sewer Lines (partial)	\$0	\$16,743	\$0	\$0	\$0
1900 Common Water Lines (partial)	\$0	\$11,162	\$0	\$0	\$0
Streets					
201 Asphalt - Replace (2010)	\$0	\$0	\$0	\$42,432	\$0
201 Asphalt - Replace (2011)	\$0	\$0	\$0	\$0	\$136,197
201 Asphalt - Replace (2013)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2015)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2017)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2018/2019)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2027)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2029)	\$0	\$0	\$0	\$0	\$0
202 Asphalt - Seal/Repair	\$0	\$0	\$33,532	\$0	\$0
203 Parking Areas - Seal/Repair	\$5,238	\$0	\$0	\$0	\$0
204 Concrete Swales/Gutters - Repair	\$0	\$0	\$0	\$0	\$0
215 Loop Detectors - Replace	\$0	\$0	\$0	\$0	\$0
Clubhouse Interior					
303 HVAC Systems - Replace	\$0	\$0	\$0	\$0	\$0
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
601 Carpet - Replace	\$0	\$0	\$0	\$0	\$0
602 Vinyl Floor - Replace	\$4,154	\$0	\$0	\$0	\$0
603 Tile Floor - Replace	\$0	\$0	\$0	\$0	\$0
604 Laminate Floor - Replace	\$0	\$0	\$0	\$15,789	\$0
901 Appliances - Replace	\$0	\$0	\$0	\$0	\$0
901 Refrigerators - Replace	\$3,432	\$0	\$0	\$0	\$0
903 Furniture - Replace (Billiard Room)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Library)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (office)	\$0	\$0	\$0	\$0	\$0
903 Tables/Chairs - Replace	\$0	\$0	\$0	\$0	\$0
904 Kitchen - Remodel	\$0	\$0	\$0	\$0	\$0
905 Billiard Table - Replace	\$0	\$0	\$0	\$0	\$0
908 Window Treatments - Replace	\$0	\$0	\$0	\$0	\$0
910 Bathrooms - Refurbish	\$0	\$0	\$0	\$0	\$0
912 Office Equipment - Replace	\$0	\$0	\$0	\$0	\$0
913 Sound System - Replace	\$0	\$0	\$0	\$0	\$0
1110 Interior Surfaces - Repaint	\$0	\$0	\$0	\$0	\$0
Clubhouse Exterior					
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
1115 Stucco - Repaint	\$0	\$0	\$0	\$0	\$0
1116 Wood Surfaces - Repaint/Repair	\$0	\$0	\$4,024	\$0	\$0
1304 Tile Roof - Replace underlayment	\$0	\$0	\$0	\$0	\$0
Pool					
404 Pool Furniture - Replace	\$0	\$0	\$0	\$0	\$0

Fiscal Year		2041	2042	2043	2044	2045
1202	Pool - Resurface	\$0	\$0	\$0	\$0	\$0
1207	Pool Filter - Replace	\$0	\$0	\$0	\$0	\$0
1208	Pool Heater - Replace	\$0	\$0	\$0	\$7,302	\$0
1210	Pool Pump - Replace	\$0	\$0	\$0	\$0	\$2,541
Total Expenses		\$12,823	\$34,229	\$74,249	\$65,523	\$152,968
Ending Reserve Balance		\$1,025,445	\$1,112,564	\$1,164,453	\$1,229,901	\$1,212,547

Fiscal Year	2046	2047	2048	2049	2050
Starting Reserve Balance	\$1,212,547	\$1,326,830	\$979,036	\$1,067,798	\$1,108,131
Annual Reserve Contribution	\$127,973	\$132,708	\$137,618	\$142,710	\$147,990
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$12,691	\$11,524	\$10,230	\$10,875	\$11,831
Total Income	\$1,353,211	\$1,471,062	\$1,126,884	\$1,221,383	\$1,267,952
# Component					
General Common Area					
320 Pole Lights - Replace	\$0	\$97,047	\$0	\$0	\$0
403 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
407 BBQ - Replace	\$0	\$2,696	\$0	\$0	\$0
503 Metal Fence/Gates - Repair	\$0	\$9,705	\$0	\$0	\$0
504 RV Gates - Replace	\$0	\$0	\$0	\$0	\$0
504 Vehicle Gates - Replace	\$0	\$0	\$0	\$0	\$0
704 Intercom - Replace	\$0	\$0	\$0	\$0	\$0
705 Gate Operator - Replace (rear)	\$0	\$0	\$0	\$8,008	\$0
705 Gate Operators - Replace (main)	\$0	\$0	\$0	\$0	\$0
1003 Irrigation Controllers - Replace	\$0	\$0	\$0	\$0	\$0
1006 Landscaping - Refurbish	\$0	\$0	\$0	\$0	\$0
1107 Metal Fence - Repaint	\$0	\$7,332	\$0	\$0	\$0
1401 Monument Signs - Replace	\$0	\$0	\$0	\$0	\$0
1403 Street Signs - Replace	\$0	\$0	\$0	\$0	\$0
1405 Bulletin Board - Replace	\$0	\$0	\$0	\$0	\$0
1809 Sewer Pumps - Replace	\$0	\$0	\$0	\$0	\$8,837
1810 4" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1810 8" Backflow Device - Replace	\$0	\$0	\$0	\$0	\$0
1900 Common Sewer Lines (partial)	\$0	\$19,409	\$0	\$0	\$0
1900 Common Water Lines (partial)	\$0	\$12,940	\$0	\$0	\$0
Streets					
201 Asphalt - Replace (2010)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2011)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2013)	\$0	\$207,033	\$0	\$0	\$0
201 Asphalt - Replace (2015)	\$0	\$0	\$0	\$105,245	\$0
201 Asphalt - Replace (2017)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2018/2019)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2027)	\$0	\$0	\$0	\$0	\$0
201 Asphalt - Replace (2029)	\$0	\$0	\$0	\$0	\$0
202 Asphalt - Seal/Repair	\$0	\$37,740	\$0	\$0	\$0
203 Parking Areas - Seal/Repair	\$0	\$6,254	\$0	\$0	\$0
204 Concrete Swales/Gutters - Repair	\$0	\$0	\$0	\$0	\$0
215 Loop Detectors - Replace	\$0	\$0	\$0	\$0	\$0
Clubhouse Interior					
303 HVAC Systems - Replace	\$0	\$42,054	\$0	\$0	\$0
411 Drinking Fountain - Replace	\$2,722	\$0	\$0	\$0	\$0
601 Carpet - Replace	\$0	\$2,372	\$0	\$0	\$0
602 Vinyl Floor - Replace	\$0	\$0	\$0	\$0	\$0
603 Tile Floor - Replace	\$0	\$0	\$0	\$0	\$0
604 Laminate Floor - Replace	\$0	\$0	\$0	\$0	\$0
901 Appliances - Replace	\$0	\$0	\$0	\$0	\$0
901 Refrigerators - Replace	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Billiard Room)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (Library)	\$0	\$0	\$0	\$0	\$0
903 Furniture - Replace (office)	\$0	\$0	\$0	\$0	\$0
903 Tables/Chairs - Replace	\$0	\$12,940	\$0	\$0	\$0
904 Kitchen - Remodel	\$0	\$0	\$33,319	\$0	\$0
905 Billiard Table - Replace	\$0	\$0	\$0	\$0	\$0
908 Window Treatments - Replace	\$0	\$0	\$0	\$0	\$0
910 Bathrooms - Refurbish	\$0	\$0	\$21,102	\$0	\$0
912 Office Equipment - Replace	\$4,816	\$0	\$0	\$0	\$0
913 Sound System - Replace	\$0	\$0	\$0	\$0	\$0
1110 Interior Surfaces - Repaint	\$0	\$0	\$0	\$0	\$0
Clubhouse Exterior					
411 Drinking Fountain - Replace	\$0	\$0	\$0	\$0	\$0
1115 Stucco - Repaint	\$0	\$0	\$0	\$0	\$0
1116 Wood Surfaces - Repaint/Repair	\$0	\$0	\$4,665	\$0	\$0
1304 Tile Roof - Replace underlayment	\$0	\$0	\$0	\$0	\$0
Pool					
404 Pool Furniture - Replace	\$18,844	\$0	\$0	\$0	\$0

Fiscal Year		2046	2047	2048	2049	2050
1202	Pool - Resurface	\$0	\$34,505	\$0	\$0	\$0
1207	Pool Filter - Replace	\$0	\$0	\$0	\$0	\$0
1208	Pool Heater - Replace	\$0	\$0	\$0	\$0	\$0
1210	Pool Pump - Replace	\$0	\$0	\$0	\$0	\$0
Total Expenses		\$26,382	\$492,026	\$59,086	\$113,252	\$8,837
Ending Reserve Balance		\$1,326,830	\$979,036	\$1,067,798	\$1,108,131	\$1,259,115



Accuracy, Limitations, and Disclosures

Association Reserves and its employees have no ownership, management, or other business relationships with the client other than this Reserve Study engagement. Kevin Leonard, R.S., president, is a credentialed Reserve Specialist (#294). All work done by Association Reserves is performed under his Responsible Charge and is performed in accordance with National Reserve Study Standards (NRSS). There are no material issues to our knowledge that have not been disclosed to the client that would cause a distortion of the client's situation.

Per NRSS, information provided by official representative(s) of the client, vendors, and suppliers regarding financial details, component physical details and/or quantities, or historical issues/conditions will be deemed reliable, and is not intended to be used for the purpose of any type of audit, quality/forensic analysis, or background checks of historical records. As such, information provided to us has not been audited or independently verified.

Estimates for interest and inflation have been included, because including such estimates are more accurate than ignoring them completely. When we are hired to prepare Update reports, the client is considered to have deemed those previously developed component quantities as accurate and reliable, whether established by our firm or other individuals/firms (unless specifically mentioned in our Site Inspection Notes). During inspections our company standard is to establish measurements within 5% accuracy, and our scope includes visual inspection of accessible areas and components and does not include any destructive or other testing. Our work is done only for budget purposes. Uses or expectations outside our expertise and scope of work include, but are not limited to, project audit, quality inspection, and the identification of construction defects, hazardous materials, or dangerous conditions. Identifying hidden issues such as but not limited to plumbing or electrical problems are also outside our scope of work. Our estimates assume proper original installation & construction, adherence to recommended preventive maintenance, a stable economic environment, and do not consider frequency or severity of natural disasters. Our opinions of component Useful Life, Remaining Useful Life, and current or future cost estimates are not a warranty or guarantee of actual costs or timing.

Because the physical and financial status of the property, legislation, the economy, weather, owner expectations, and usage are all in a continual state of change over which we have no control, we do not expect that the events projected in this document will all occur exactly as planned. This Reserve Study is by nature a "one-year" document in need of being updated annually so that more accurate estimates can be incorporated. It is only because a long-term perspective improves the accuracy of near-term planning that this Report projects expenses into the future. We fully expect a number of adjustments will be necessary through the interim years to the cost and timing of expense projections and the funding necessary to prepare for those estimated expenses.

In this engagement our compensation is not contingent upon our conclusions, and our liability in any matter involving this Reserve Study is limited to our fee for services rendered.



Terms and Definitions

BTU	British Thermal Unit (a standard unit of energy)
DIA	Diameter
GSF	Gross Square Feet (area). Equivalent to Square Feet
GSY	Gross Square Yards (area). Equivalent to Square Yards
HP	Horsepower
LF	Linear Feet (length)
Effective Age	The difference between Useful Life and Remaining Useful Life. Note that this is not necessarily equivalent to the chronological age of the component.
Fully Funded Balance (FFB)	The value of the deterioration of the Reserve Components. This is the fraction of life "used up" of each component multiplied by its estimated Current Replacement. While calculated for each component, it is summed together for an association total.
Inflation	Cost factors are adjusted for inflation at the rate defined in the Executive Summary and compounded annually. These increasing costs can be seen as you follow the recurring cycles of a component on the "30-yr Income/Expense Detail" table.
Interest	Interest earnings on Reserve Funds are calculated using the average balance for the year (taking into account income and expenses through the year) and compounded monthly using the rate defined in the Executive Summary. Annual interest earning assumption appears in the Executive Summary.
Percent Funded	The ratio, at a particular point in time (the first day of the Fiscal Year), of the actual (or projected) Reserve Balance to the Fully Funded Balance, expressed as a percentage.
Remaining Useful Life (RUL)	The estimated time, in years, that a common area component can be expected to continue to serve its intended function.
Useful Life (UL)	The estimated time, in years, that a common area component can be expected to serve its intended function.



Component Details

The primary purpose of the Component Details appendix is to provide the reader with the basis of our funding assumptions resulting from our physical analysis and subsequent research. The information presented here represents a wide range of components that were observed and measured against National Reserve Study Standards to determine if they meet the criteria for reserve funding.

- 1) Common area repair & replacement responsibility
- 2) Component must have a limited useful life
- 3) Life limit must be predictable
- 4) Above a minimum threshold cost (board's discretion – typically ½ to 1% of Annual operating expenses).

Not all your components may have been found appropriate for reserve funding. In our judgment, the components meeting the above four criteria are shown with the Useful Life (how often the project is expected to occur), Remaining Useful Life (when the next instance of the expense will be) and representative market cost range termed “Best Cost” and “Worst Cost”. There are many factors that can result in a wide variety of potential costs, and we have attempted to present the cost range in which your actual expense will occur.

Where no Useful Life, Remaining Useful Life, or pricing exists, the component was deemed inappropriate for Reserve Funding.

General Common Area

Comp #: 320 Pole Lights - Replace**Quantity: (45) Fixtures**

Location: Throughout property

Funded?: Yes.

History:

Comments: Inspected during daylight hours but assumed functional. Expect a full service life. Best to replace all at once to maintain a uniform appearance.

Useful Life:
25 years

Remaining Life:
1 years



Best Case: \$ 40,000

Worst Case: \$ 50,000

Cost Source: Allowance Estimate

Comp #: 403 Mailboxes - Replace**Quantity: (9) Kiosks (5) Parcels**

Location: Each side of the clubhouse area

Funded?: Yes.

History: Manufactured date: 2018.

Comments: Inspect regularly and clean by wiping down exterior surfaces. If necessary, change lock cylinders, lubricate hinges and repair as an Operating expense. Best to plan for total replacement at roughly the time frame below due to constant exposure, usage and wear over time.

Useful Life:
18 years

Remaining Life:
14 years



Best Case: \$ 13,000

Worst Case: \$ 20,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 407 BBQ - Replace

Quantity: (1) BBQ

Location: Pool area

Funded?: Yes.

History: Approximately 2017

Comments: No issues reported. Expect a full useful life.

Useful Life:

10 years

Remaining Life:

6 years



Best Case: \$ 1,000

Worst Case: \$ 1,500

Cost Source: ARI Cost Database

Comp #: 503 Metal Fence/Gates - Repair

Quantity: Approx 395 LF

Location: Throughout common area

Funded?: Yes.

History:

Comments: An allowance has been provided to make repairs ever other painting project. Continue to monitor and adjust as needed in future Reserve Study updates.

Useful Life:

10 years

Remaining Life:

6 years



Best Case: \$ 3,000

Worst Case: \$ 6,000

Lower allowance

Higher allowance

Cost Source: Allowance Estimate

Comp #: 504 RV Gates - Replace**Quantity: (2) Rolling Gates**

Location: RV area

Funded?: Yes.

History:

Comments: Expect a long useful life if painted regularly.

Useful Life:

30 years

Remaining Life:

9 years



Best Case: \$ 7,000

Worst Case: \$ 8,400

Cost Source: ARI Cost Database

Comp #: 504 Vehicle Gates - Replace**Quantity: (3) Sets of Gates**

Location: (1) Front Entrance area and (2) at the rear of the property

Funded?: Yes.

History:

Comments: We strongly recommend regular inspections, maintenance and repairs to help extend useful life cycles. Clean for appearance and paint/touch-up as needed within general maintenance/Operating funds. Although metal gates are typically durable, we recommend setting aside funding for regular intervals of replacement due to constant wear/usage, exposure and vehicle damage. Replacement can also be warranted for aesthetic changes over time. Plan to replace at roughly the time frame shown below.

Useful Life:

30 years

Remaining Life:

15 years



Best Case: \$ 12,000

Worst Case: \$ 15,000

Cost Source: ARI Cost Database

Comp #: 704 Intercom - Replace**Quantity: (1) Elite Intercom**

Location: Entrance

Funded?: Yes.

History:

Comments: Access/intercom system was not inspected internally during site inspection. Should be checked and repaired as needed by servicing vendor as routine maintenance. Individual components can often be replaced for relatively low cost as an Operating expense. Plan for complete replacement at the approximate interval shown here for functional and aesthetic considerations.

Useful Life:
15 years

Remaining Life:
4 years



Best Case: \$ 3,200

Worst Case: \$ 4,400

Cost Source: ARI Cost Database

Comp #: 705 Gate Operator - Replace (rear)**Quantity: (1) Liftmaster**

Location: Rear gate

Funded?: Yes.

History: 2013

Comments: Installed in 2013. Expect a full service life. We recommend regular inspections (including service and repair as needed) be paid through the Operating budget. Even with ongoing maintenance, plan for replacement at typical life expectancy indicated below. Useful life can vary greatly depending on level of use, exposure to the elements, etc. Monitor actual expenses closely for future Reserve Study updates. Unless otherwise noted, funding to replace with similar units.

Useful Life:
12 years

Remaining Life:
4 years



Best Case: \$ 3,000

Worst Case: \$ 4,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 705 Gate Operators - Replace (main)

Quantity: (2) Elite Swing Operators

Location: Main entry/exit

Funded?: Yes.

History: 2003

Comments: Installed in 2003. Expect to replace in the near future based on age.

Useful Life:

12 years

Remaining Life:

0 years



Best Case: \$ 6,000

Worst Case: \$ 8,000

Cost Source: ARI Cost Database

Comp #: 1003 Irrigation Controllers - Replace

Quantity: (2) Controllers

Location: Utility closets

Funded?: Yes.

History:

Comments: Controllers are assumed to be functional. Expect a full useful life.

Useful Life:

15 years

Remaining Life:

4 years



Best Case: \$ 2,000

Worst Case: \$ 4,000

Cost Source: ARI Cost Database

Comp #: 1006 Landscaping - Refurbish**Quantity: Approx 0.65 acres**

Location: Throughout the association

Funded?: Yes.

History:

Comments: The association has periodically refurbished the landscaping throughout the community. An allowance has been provided on roughly the schedule below.

Useful Life:
10 yearsRemaining Life:
2 years

Best Case: \$ 15,000

Worst Case: \$ 20,000

Lower estimate to refurbish

Higher allowance

Cost Source: Allowance Estimate


Comp #: 1107 Metal Fence - Repaint**Quantity: Approx 395 LF**

Location: Throughout common area. Pool.

Funded?: Yes.

History:

Comments: No major signs of chipping, peeling, or rust. Good overall condition. Regular painting projects will protect the metal from premature deterioration.

Useful Life:
5 yearsRemaining Life:
1 years

Best Case: \$ 2,600

Worst Case: \$ 4,200

Lower estimate to repaint

Higher estimate

Cost Source: Client Cost History, Plus Inflation

Comp #: 1401 Monument Signs - Replace

Quantity: (2) Tile Signs

Location: Entrance to complex

Funded?: Yes.

History:

Comments: Best to clean regularly to maintain a good appearance. Expect replacement to only be necessary on a long term schedule.

Useful Life:

25 years

Remaining Life:

6 years



Best Case: \$ 3,000

Worst Case: \$ 6,000

Cost Source: Allowance Estimate

Comp #: 1403 Street Signs - Replace

Quantity: (28) Signs, (14) Posts

Location: Throughout the association

Funded?: Yes.

History:

Comments: Signs are intact and upright. Expect replacement to only be needed on a long term schedule.

Useful Life:

25 years

Remaining Life:

6 years



Best Case: \$ 10,000

Worst Case: \$ 18,000

Lower estimate to completely replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1405 Bulletin Board - Replace

Quantity: (1) 5x8 Structure

Location: Front of clubhouse

Funded?: Yes.

History:

Comments: Continue to monitor and adjust as needed in future Reserve Study updates.

Useful Life:

20 years

Remaining Life:

2 years



Best Case: \$ 1,300

Worst Case: \$ 2,000

Cost Source: ARI Cost Database

Comp #: 1808 Catch Basin/Well - Rebuild

Quantity: (1) System

Location: RV Lot

Funded?: No. This project was deemed unnecessary by the board due to the efficiency of the new pumps.

History:

Comments:

Useful Life:

Remaining Life:



Best Case:

Worst Case:

Cost Source:

Comp #: 1809 Sewer Pumps - Replace

Quantity: (3) Pumps

Location: RV Lot

Funded?: Yes.

History: 2015. 11/2020.

Comments: (3) sewer pumps replaced (2) sump pumps in 2020. Expect a full service life before replacement is necessary.

Useful Life:

10 years

Remaining Life:

9 years



Best Case: \$ 3,000

Worst Case: \$ 4,500

Cost Source: Allowance Estimate

Comp #: 1810 4" Backflow Device - Replace

Quantity: (1) 4" Backflow

Location: Center of property

Funded?: Yes.

History:

Comments: Expect to replace on roughly the schedule below.

Useful Life:

30 years

Remaining Life:

7 years



Best Case: \$ 5,500

Worst Case: \$ 7,500

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1810 8" Backflow Device - Replace

Quantity: (1) 8" backflow

Location: Near entrance to property

Funded?: Yes.

History: Installed 2010

Comments: Backflow is new as of 2010. No signs of any leaks or damage. Expect full service life.

Useful Life:

30 years

Remaining Life:

19 years



Best Case: \$ 9,000

Worst Case: \$ 12,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1900 Common Sewer Lines (partial)

Quantity: Extensive LF

Location: Throughout association

Funded?: Yes.

History:

Comments: The association has a history of making repairs. Therefore an allowance has been provided on the schedule below.

No reports of any planned projects in the near future.

Useful Life:

5 years

Remaining Life:

1 years



Best Case: \$ 6,000

Worst Case: \$ 12,000

Lower allowance for repairs

Higher allowance

Cost Source: Allowance Estimate

Comp #: 1900 Common Water Lines (partial)

Quantity: Extensive LF

Location: Throughout the association

Funded?: Yes.

History:

Comments: The association has a history of making repairs. Therefore an allowance has been provided on the schedule below. No reports of any planned projects in the near future.

Useful Life:
5 years

Remaining Life:
1 years



Best Case: \$ 4,000

Worst Case: \$ 8,000

Lower allowance for repairs

Higher allowance

Cost Source: Allowance Estimate

Streets

Comp #: 201 Asphalt - Replace (2010)**Quantity: Approx 5,905 GSF**

Location: Bahama (partially)

Funded?: Yes.

History: 2010

Comments: The association replaces sections of their asphalt separately. This component represents the project completed in 2010. With regular seal/repair projects, expect a full useful life.

Useful Life:
35 years

Remaining Life:
23 years



Best Case: \$ 20,000

Worst Case: \$ 23,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 201 Asphalt - Replace (2011)**Quantity: Approx 18,115 GSF**

Location: Bahama (partially), Tobago, Bermuda (partially)

Funded?: Yes.

History: 2011

Comments: The association replaces sections of their asphalt separately. This component represents the project completed in 2011. With regular seal/repair projects, expect a full useful life.

Useful Life:
35 years

Remaining Life:
24 years



Best Case: \$ 60,000

Worst Case: \$ 74,000

Lower estimate for replacement

Higher estimate

Cost Source: ARI Cost Database

Comp #: 201 Asphalt - Replace (2013)**Quantity: Approx 26,505 GSF**

Location: Bahama Entry, Bermuda (partially), St Barthelemy Dr

Funded?: Yes.

History: 2013

Comments: The association replaces sections of their asphalt separately. This component represents the project completed in 2013. With regular seal/repair projects, expect a full useful life.

Useful Life:

35 years

Remaining Life:

26 years



Best Case: \$ 87,000

Worst Case: \$ 105,000

Lower estimate for replacement

Higher estimate

Cost Source: ARI Cost Database

Comp #: 201 Asphalt - Replace (2015)**Quantity: Approx 11,990 GSF**

Location: West Bahama (Partially)

Funded?: Yes.

History: 2015

Comments: The association replaces sections of their asphalt separately. This component represents the project completed in 2015. With regular seal/repair projects, expect a full useful life.

Useful Life:

35 years

Remaining Life:

28 years



Best Case: \$ 39,000

Worst Case: \$ 53,000

Lower estimate for replacement

Higher estimate

Cost Source: ARI Cost Database

Comp #: 201 Asphalt - Replace (2017)**Quantity: Approx 14,475 GSF**

Location: Martinique Dr and East Bermuda

Funded?: Yes.

History: 2017

Comments: The association replaces sections of their asphalt separately. This component represents the project completed in 2017. With regular seal/repair projects, expect a full useful life.

Useful Life:
35 years

Remaining Life:
30 years



Best Case: \$ 48,000

Worst Case: \$ 58,000

Lower estimate for replacement

Higher estimate

Cost Source: ARI Cost Database

Comp #: 201 Asphalt - Replace (2018/2019)**Quantity: Approx 13,260 GSF**

Location: West Bermuda from Cayman to Trinidad. St. Croix.

Funded?: Yes.

History: 2018: \$68,472 (included concrete repairs). 2019: \$30,444

Comments: The association replaces sections of their asphalt separately. This component represents the project completed in 2018. With regular seal/repair projects, expect a full useful life.

Useful Life:
35 years

Remaining Life:
31 years



Best Case: \$ 90,000

Worst Case: \$ 110,000

Lower estimate for replacement

Higher estimate

Cost Source: Client Cost History

Comp #: 201 Asphalt - Replace (2027)**Quantity: Approx 18,220 GSF**

Location: Trinidad and Barbados

Funded?: Yes.

History:

Comments: The association replaces sections of their asphalt separately. This component represents the project planned to be completed in 2027. With regular seal/repair projects, expect a full useful life.

Useful Life:
35 years

Remaining Life:
5 years



Best Case: \$ 60,000

Worst Case: \$ 75,000

Lower estimate for replacement

Higher estimate

Cost Source: ARI Cost Database

Comp #: 201 Asphalt - Replace (2029)**Quantity: Approx 11,305 GSF**

Location: Cayman

Funded?: Yes.

History:

Comments: The association replaces sections of their asphalt separately. This component represents the project planned to be completed in 2027. With regular seal/repair projects, expect a full useful life.

Useful Life:
35 years

Remaining Life:
7 years



Best Case: \$ 37,000

Worst Case: \$ 49,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 202 Asphalt - Seal/Repair**Quantity: Approx 119,870 GSF**

Location: Streets throughout the association

Funded?: Yes.

History: 2018/2019

Comments: Regular seal projects are necessary preventative maintenance projects for asphalt surfaces. Conditions vary throughout the property. Areas of cracking observed throughout.

Useful Life:
4 yearsRemaining Life:
2 years

Best Case: \$ 14,500

Worst Case: \$ 20,500

Cost Source: ARI Cost Database

Comp #: 203 Parking Areas - Seal/Repair**Quantity: Approx 5,200 GSF**

Location: Parking areas

Funded?: Yes.

History:

Comments: Regular seal projects are necessary preventative maintenance projects for asphalt surfaces. Fair condition. Plan to seal along with the main sealing project for efficiency.

Useful Life:
6 yearsRemaining Life:
2 years

Best Case: \$ 2,600

Worst Case: \$ 3,200

Lower estimate to seal/repair

Higher estimate

Cost Source: ARI Cost Database

Comp #: 204 Concrete Swales/Gutters - Repair**Quantity: Extensive area**

Location: Throughout streets and drives

Funded?: Yes.

History:

Comments: Mostly in fair condition. No expectation to ever completely replace. An allowance has been provided to make repairs as necessary. Complete along with asphalt projects when possible for efficiency.

Useful Life:
15 years

Remaining Life:
1 years



Best Case: \$ 10,000

Worst Case: \$ 20,000

Cost Source: Allowance Estimate

Comp #: 215 Loop Detectors - Replace**Quantity: (6) Loop Detectors**

Location: Exit areas

Funded?: Yes.

History:

Comments: No access to directly inspect. Assumed to be functional. Based on age expect the need for replacement in the near future.

Useful Life:
15 years

Remaining Life:
1 years



Best Case: \$ 6,600

Worst Case: \$ 9,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Clubhouse Interior

Comp #: 303 HVAC Systems - Replace

Quantity: (3) Carrier Units

Location: Exterior of clubhouse

Funded?: Yes.

History:

Comments: Life expectancy of HVAC systems can vary greatly depending on many factors including location of the property, level of preventive maintenance, manufacturer, technology/efficiency improvements, etc. We recommend that routine repairs and maintenance such as filter replacements, system flushing, etc. be budgeted as an Operating expense. Useful life can often be extended with proactive service and maintenance. Unless otherwise noted, funding for system with same size/capacity as the current system. For split systems, we recommend budgeting to replace the entire system (condensing unit and air handler) together in order to obtain better unit pricing and ensure maximum efficiency, refrigerant compatibility, etc. If additional costs are expected during replacement, such as for system reconfiguration or expansion, ductwork repairs, electrical work, etc. costs should be re-evaluated and adjusted as needed during future Reserve Study updates.

Useful Life:
20 years

Remaining Life:
6 years



Best Case: \$ 15,000

Worst Case: \$ 24,000

Cost Source: ARI Cost Database

Comp #: 411 Drinking Fountain - Replace

Quantity: (1) Fountain

Location: Interior hallway

Funded?: Yes.

History:

Comments: Replace at the board's discretion.

Useful Life:
20 years

Remaining Life:
5 years



Best Case: \$ 1,100

Worst Case: \$ 1,500

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 601 Carpet - Replace**Quantity: Approx 25 GSY**

Location: Office

Funded?: Yes.

History:

Comments: As part of ongoing maintenance program, vacuum regularly and professionally clean as needed. Best practice is to coordinate at same time as other interior projects whenever possible to minimize downtime and maintain consistent quality standard. Timing of replacements is ultimately subjective. Estimates shown here are based on our experience with similar properties and general aesthetic qualities. Schedule can be updated/adjusted at the discretion of the Association for planning purposes.

Useful Life:
12 years

Remaining Life:
2 years



Best Case: \$ 900

Worst Case: \$ 1,300

Cost Source: ARI Cost Database

Comp #: 602 Vinyl Floor - Replace**Quantity: Approx 170 GSF**

Location: Kitchen

Funded?: Yes.

History:

Comments: Good condition with no major damage or abuse noted.

Useful Life:
18 years

Remaining Life:
2 years



Best Case: \$ 1,800

Worst Case: \$ 2,800

Cost Source: ARI Cost Database

Comp #: 603 Tile Floor - Replace**Quantity: Approx 590 GSF**

Location: Clubhouse interior

Funded?: Yes.

History:

Comments: Flooring will have a long useful life. Best to plan for eventual replacement on the schedule below.

Useful Life:

25 years

Remaining Life:

12 years



Best Case: \$ 8,000

Worst Case: \$ 14,000

Cost Source: ARI Cost Database

Comp #: 604 Laminate Floor - Replace**Quantity: Approx 1,180 GSF**

Location: Clubhouse interior

Funded?: Yes.

History:

Comments: No reports of any planned replacements. Expect a full useful life.

Useful Life:

18 years

Remaining Life:

5 years



Best Case: \$ 6,000

Worst Case: \$ 10,000

Cost Source: ARI Cost Database

Comp #: 901 Appliances - Replace

Quantity: (4) Pieces

Location: Kitchen area

Funded?: Yes.

History:

Comments: Funding has been provided for comprehensive replacement.

Useful Life:
15 years

Remaining Life:
0 years



Best Case: \$ 3,000

Worst Case: \$ 4,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 901 Refrigerators - Replace

Quantity: (2) Refrigerators

Location: Clubhouse

Funded?: Yes.

History:

Comments: Expect a full useful life. Plan to replace at once to maintain uniformity.

Useful Life:
15 years

Remaining Life:
5 years



Best Case: \$ 1,400

Worst Case: \$ 2,400

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 903 Furniture - Replace (Billiard Room)**Quantity: (10) Assorted Pieces**

Location: Billiard Room

Funded?: Yes.

History:

Comments: Reportedly, no plans to replace in the near future.

Useful Life:

15 years

Remaining Life:

2 years



Best Case: \$ 2,000

Worst Case: \$ 2,600

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 903 Furniture - Replace (Library)**Quantity: (16) Assorted Pieces**

Location: Library

Funded?: Yes.

History:


Comments: Area was observed to be used as a storage room during the site visit. Continue to monitor and adjust as needed in future Reserve Study updates.

Useful Life:

15 years

Remaining Life:

2 years



Best Case: \$ 3,800

Worst Case: \$ 4,800

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 903 Furniture - Replace (office)

Quantity: (12) Assorted pieces

Location: Office

Funded?: Yes.

History:

Comments: Expect a full useful life.

Useful Life:

15 years

Remaining Life:

2 years



Best Case: \$ 3,500

Worst Case: \$ 4,000

Cost Source: ARI Cost Database

Comp #: 903 Tables/Chairs - Replace

Quantity: (9) Tables (41) Chairs

Location: Clubhouse

Funded?: Yes.

History:

Comments: Expect to replace on roughly the schedule below.

Useful Life:

12 years

Remaining Life:

2 years



Best Case: \$ 4,000

Worst Case: \$ 8,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 904 Kitchen - Remodel**Quantity: Kitchen Area**

Location: Kitchen

Funded?: Yes.

History: Unknown

Comments: Kitchen materials typically have an extended useful life. However, many Associations choose to refurbish the kitchen periodically for aesthetic updating. This may include refurbishment/refinishing of kitchen cabinets and countertops, replacement of sinks, installation/replacement of under-cabinet lighting, etc. Should ideally be coordinated with replacement of the kitchen appliances. Best practice is to coordinate this project with other amenity areas, such as bathrooms or other amenity rooms.

Useful Life:

25 years

Remaining Life:

2 years



Best Case: \$ 10,000

Worst Case: \$ 20,000

Cost Source: Allowance Estimate

Comp #: 905 Billiard Table - Replace**Quantity: (1) Standard Table**

Location: Billiard room

Funded?: Yes.

History:

Comments: Table may last beyond its typical useful life. Continue to monitor and adjust as needed in future Reserve Study updates.

Useful Life:

15 years

Remaining Life:

2 years



Best Case: \$ 2,000

Worst Case: \$ 2,400

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 908 Window Treatments - Replace**Quantity: (33) Blinds**

Location: Clubhouse

Funded?: Yes.

History: 2011

Comments: Expect a full useful life.

Useful Life:

20 years

Remaining Life:

10 years



Best Case: \$ 4,500

Worst Case: \$ 5,500

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 910 Bathrooms - Refurbish**Quantity: (2) bathrooms, 310 GSF**

Location: Clubhouse

Funded?: Yes.

History:

Comments: As routine maintenance, inspect regularly and perform any needed repairs promptly utilizing general Operating funds. Typical remodeling project can include some or all of the following: replacement of plumbing fixtures, partitions, countertops, lighting, flooring, ventilation fans, accessories, décor, etc. Costs can vary greatly depending on scope of work involved. In general, estimates shown are based primarily on cosmetic remodeling, not necessarily total "gut" remodel projects unless otherwise noted.

Useful Life:

25 years

Remaining Life:

2 years



Best Case: \$ 7,000

Worst Case: \$ 12,000

Lower estimate to replace

Higher estimate

Cost Source: Allowance Estimate

Comp #: 912 Office Equipment - Replace

Quantity: (1) Computer, (1) Printer

Location: Office

Funded?: Yes.

History:

Comments: Plan to periodically replace the equipment as needed.

Useful Life:

8 years

Remaining Life:

1 years



Best Case: \$ 2,100

Worst Case: \$ 2,500

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 913 Sound System - Replace

Quantity: (1) System

Location: Clubhouse

Funded?: Yes.

History:

Comments: An allowance has been provided to upgrade the system on roughly the schedule below.

Useful Life:

15 years

Remaining Life:

0 years



Best Case: \$ 1,500

Worst Case: \$ 2,500

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1110 Interior Surfaces - Repaint

Quantity: Approx 6,000 GSF

Location: Clubhouse

Funded?: Yes.

History:

Comments: Expect to periodically repaint to maintain an attractive appearance.

Useful Life:
15 years

Remaining Life:
2 years



Best Case: \$ 4,000

Worst Case: \$ 8,000

Lower estimate to repaint

Higher estimate

Cost Source: ARI Cost Database

Clubhouse Exterior

Comp #: 411 Drinking Fountain - Replace**Quantity: (1) St. Steel Fountain**

Location: Pool area

Funded?: Yes.

History:

Comments: Replace at the board's discretion.

Useful Life:
15 yearsRemaining Life:
0 years

Best Case: \$ 1,100

Worst Case: \$ 1,500

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1115 Stucco - Repaint**Quantity: Exterior Walls**

Location: Exterior Walls

Funded?: Yes.

History:

Comments: Plan to periodically repaint in order to maintain an attractive appearance.

Useful Life:
15 yearsRemaining Life:
2 years

Best Case: \$ 3,800

Worst Case: \$ 5,200

Lower estimate to repaint

Higher estimate

Cost Source: Estimate Provided by Client

Comp #: 1116 Wood Surfaces - Repaint/Repair

Quantity: Trim & Doors

Location: Trim & Doors

Funded?: Yes.

History:

Comments: Plan to periodically repaint in order to maintain an attractive appearance.

Useful Life:

5 years

Remaining Life:

2 years



Best Case: \$ 1,800

Worst Case: \$ 2,400

Lower estimate to repaint & repair

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1304 Tile Roof - Replace underlayment

Quantity: Approx 3,500 GSF

Location: Clubhouse roof

Funded?: Yes.

History:

Comments: It was noted that minor repairs will be made in the near future. Funding has been provided for complete replacement of the underlayment. This project only needs to be completed on a long term cycle.

Useful Life:

35 years

Remaining Life:

3 years



Best Case: \$ 20,000

Worst Case: \$ 24,000

Cost Source: ARI Cost Database

Pool

Comp #: 404 Pool Furniture - Replace**Quantity: (47) Assorted Pieces**

Location: Pool area

Funded?: Yes.

History:

Comments: Expect to replace on roughly the schedule below.

Useful Life:
8 yearsRemaining Life:
1 years

Best Case: \$ 6,000

Worst Case: \$ 12,000

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1202 Pool - Resurface**Quantity: (1) 25x45 pool**

Location: Pool area

Funded?: Yes.

History:

Comments: Pool resurfacing will restore the aesthetic quality of the pool while protecting the actual concrete shell of the pool from deterioration. While drained for resurfacing any other repairs to lighting handrails stairs ladders etc. should be conducted as needed. This type of project is best suited for slow/offseason to minimize downtime during periods when pool is used heavily. Should be expected at the approximate interval shown below; in some cases schedule may need to be accelerated due to improper chemical balances or aesthetic preferences of the Association.

Useful Life:
12 yearsRemaining Life:
2 years

Best Case: \$ 12,000

Worst Case: \$ 20,000

Lower estimate to resurface

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1207 Pool Filter - Replace**Quantity: (1) 60 GSF Filter**

Location: Pool equipment area

Funded?: Yes.

History:

Comments: Pool vendor should inspect regularly for optimal performance and address any repairs or preventive maintenance as needed. Life can vary depending on location as well as level of use and preventive maintenance. Plan to replace at the approximate interval shown below.

Useful Life:

12 years

Remaining Life:

6 years



Best Case: \$ 1,000

Worst Case: \$ 1,800

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database

Comp #: 1208 Pool Heater - Replace**Quantity: (1) Pentair**

Location: Pool equipment area

Funded?: Yes.

History: 2021: \$3,679

Comments: Pool vendor should inspect heater regularly to ensure proper function identify any required repairs etc. Internal components were not analyzed during our site inspection. Many Associations choose not to heat their pools year-round which can prolong the life of the heater while reducing energy costs. When replacement models are being evaluated we recommend considering high efficiency models which may have a higher initial cost but will ultimately be less expensive due to reduced energy usage.

Useful Life:

12 years

Remaining Life:

11 years



Best Case: \$ 3,500

Worst Case: \$ 3,900

Lower estimate to replace

Higher estimate

Cost Source: Client Cost History

Comp #: 1210 Pool Pump - Replace

Quantity: (1) Pump & Motor

Location: Pool equipment area

Funded?: Yes.

History:

Comments: Pool vendor should inspect regularly for optimal performance and address any repairs or preventive maintenance as needed. Life can vary depending on location as well as level of use and preventive maintenance. Plan to replace at the approximate interval shown below.

Useful Life:
8 years

Remaining Life:
0 years



Best Case: \$ 1,000

Worst Case: \$ 1,500

Lower estimate to replace

Higher estimate

Cost Source: ARI Cost Database
