

Serving the Pacific Northwest
10900 NE 4th St, Suite 2300
Bellevue, WA 98004

Tel: (253) 661-5437
www.reservestudy.com



ASSOCIATION
RESERVES®

Planning For The Inevitable

Regional Offices

Arizona	Nevada
California	New Jersey
Colorado	New Mexico
Florida	North Carolina
Hawaii	Ohio
Mid-Atlantic	Texas
Midwest	Washington



Garden Grove Condominium Owners Association *Everett, WA*



Report #: 13381-3
Beginning: January 1, 2026
Expires: December 31, 2026

RESERVE STUDY

Update "With-Site-Visit"

Welcome to your Reserve Study!

A Reserve Study is a valuable tool to help you budget responsibly for your property. This report contains all the information you need to avoid surprise expenses, make informed decisions, save money, and protect property values.

Regardless of the property type, it's a fact of life that the very moment construction is completed, every major building component begins a predictable process of physical deterioration. The operative word is "predictable" because planning for the inevitable is what a Reserve Study by **Association Reserves** is all about!

In this Report, you will find three key results:

- **Component List**

Unique to each property, the Component List serves as the foundation of the Reserve Study and details the scope and schedule of all necessary repairs & replacements.

- **Reserve Fund Strength**

A calculation that measures how well the Reserve Fund has kept pace with the property's physical deterioration.

- **Reserve Funding Plan**

A multi-year funding plan based on current Reserve Fund strength that allows for component repairs and replacements to be completed in a timely manner, with an emphasis on fairness and avoiding "catch-up" funding.

Questions?

Please contact your Project Manager directly.



www.reservestudy.com

The logo used within this report is the registered trademark of Association Reserves, Inc., All rights reserved.

Table of Contents

Executive Summary	5
Executive Summary (Component List)	7
Introduction, Objectives, and Methodology	9
Which Physical Assets are Funded by Reserves?	10
How do we establish Useful Life and Remaining Useful Life estimates?	10
How do we establish Current Repair/Replacement Cost Estimates?	10
How much Reserves are enough?	11
How much should we transfer to Reserves?	12
What is our Recommended Funding Goal?	12
Site Inspection Notes	13
Projected Expenses	14
Annual Reserve Expenses Graph	14
Reserve Fund Status & Recommended Funding Plan	15
Annual Reserve Funding Graph	15
30-Yr Cash Flow Graph	16
Percent Funded Graph	16
Table Descriptions	17
Reserve Component List Detail	18
Fully Funded Balance	19
Component Significance	20
30-Year Reserve Plan Summary	21
30-Year Reserve Plan Summary (Alternate Funding Plan)	22
30-Year Income/Expense Detail	23
Accuracy, Limitations, and Disclosures	29
Terms and Definitions	30
Component Details	31
Site & Grounds	32
Building Exteriors	54
Systems & Evaluations	71



Garden Grove Condominium - Owners Association

Report #: 13381-3

Everett, WA

of Units: 134

Level of Service: Update "With-Site-Visit"


January 1, 2026 through December 31, 2026

Findings & Recommendations

as of January 1, 2026

Starting Reserve Balance	\$364,732
Current Fully Funded Reserve Balance	\$3,886,059
Percent Funded	9.4 %
Average Reserve (Deficit) or Surplus Per Unit	(\$26,279)
Recommended 2026 100% Monthly "Full Funding" Reserve Transfers	\$38,700
2026 "Baseline Funding" minimum to keep Reserves above \$0	\$36,000
Recommended 2026 Special Assessment	\$0
Most Recent Budgeted Reserve Transfer Rate	\$15,245

Reserve Fund Strength: 9.4%



Risk of Special Assessment:

Economic Assumptions:

Net Annual "After Tax" Interest Earnings Accruing to Reserves	1.00 %
Annual Inflation Rate	3.00 %

• This is a Update "With-Site-Visit", meeting all requirements of the Revised Code of Washington (RCW). This study was prepared under the supervision of a credentialed Reserve Specialist (RS™).

• Your Reserve Fund is currently 9.4 % Funded. This means the association's special assessment & deferred maintenance risk is currently High. The objective of your multi-year Funding Plan is to fund your Reserves to a level where you will enjoy a low risk of such Reserve cash flow problems. The current annual deterioration of your reserve components is \$285,996 - see Component Significance table.

• Based on this starting point and your anticipated future expenses, our recommendation is to budget Reserve Contributions to the 100% level as noted above and levy Special Assessment of \$0 in 2026 for upcoming projects. This Special Assessment is preliminary and should be adjusted based on evaluation, scope of work, competitive bidding for projects, contractor selection, etc. The 100% "Full" transfer rate is designed to gradually achieve this funding objective by the end of our 30-year report scope. The Special Assessment is intended to cover the projected expenses for 2026. In the year 2042, we are recommending a significant drop in recommended funding due to adequate funding following a large building renovation project.

• Baseline funding cannot be achieved without a special assessment within the 30-year period.

• No assets appropriate for Reserve designation known to be excluded. See appendix for component information and the basis of our assumptions. "Baseline Funding" in this report is as defined within the RCW, "to maintain the reserve account balance above zero throughout the thirty-year study period, without special assessments." Funding plan contribution rates, and reserves deficit or (surplus) are presented as an aggregate total, assuming average percentage of ownership. The actual ownership allocation may vary - refer to your governing documents, and assessment computational tools to adjust for any variation.

Regulatory Compliance: Rehabilitative construction projects exceeding 5% of the assessed value of the building must meet RCW 64.55 requirements, including building enclosure design & waterproofing details by a licensed architect/engineer and independent construction oversight. The RCW does not preclude Reserve

Study contents including components with > 30 years Useful Life that otherwise meet CAI's National Reserve Study Standards.

# Component	Useful Life (yrs)	Rem. Useful Life (yrs)	Current Average Cost
Site & Grounds			
100 Concrete - Maintain/Repair	10	0	\$7,000
120 Shared Asphalt - Resurface	35	8	\$12,100
121 Shared Asphalt - Repair & Seal	5	0	\$2,000
122 1999 Asphalt - Resurface	35	8	\$401,000
123 2019 Parking Area - Resurface	35	28	\$9,500
125 Asphalt - Repair & Seal	5	4	\$59,400
140 Perimeter Fences - Replace	20	10	\$64,600
142 Yard Fencing - Replace	5	4	\$54,600
143 Storm Pond Fence - Replace	20	0	\$31,600
145 Vinyl Fence – Replace	35	8	\$99,500
147 Garbage Enclosures - Repair/Replace	25	23	\$26,900
160 Pole Lights - Replace	40	13	\$13,200
183 Drainage & Stormwater - CB Cleaning	3	0	\$4,000
205 Mailboxes - Replace	30	21	\$21,700
220 Sport Court - Resurface	45	18	\$27,900
Building Exteriors			
500 Bldgs BB & DD Roofs - Replace	25	18	\$205,897
501 Bldg Y Roof - Replace	25	20	\$62,418
502 Bldgs O & AA Roofs - Replace	25	21	\$152,028
503 Bldgs B & D Roof - Replace	25	22	\$101,000
504 Roofs (23) - Replace	25	23	\$1,327,670
507 Garage Roofs - Replace	20	0	\$78,100
513 Skylights - Replace	25	23	\$33,180
517 Gutters & Downspouts - Replace	40	13	\$175,200
520 Vinyl Siding - Exterior Renovation	40	13	\$3,524,000
521 Vinyl Siding - Clean & Inspect	4	3	\$61,000
533 Exterior Surfaces - Caulk & Paint	8	0	\$110,000
541 Traffic Coated Decks - Resurface	30	3	\$172,000
542 Traffic Coated Decks - Recoat	5	3	\$72,400
543 Elevated Walkway - Recoat	5	3	\$10,900
545 Wood Decks - Replace	20	5	\$81,700
555 Building Wood Rails - Replace	20	4	\$144,200
560 Exterior Lights - Replace	40	13	\$44,000
Systems & Evaluations			
900 Plumbing - Systems Evaluation	20	0	\$12,500
965 Fire Alarm Panels - Replace	20	0	\$20,000
995 Building Envelope & Structure	10	0	\$12,000

35 Total Funded Components

Note 1: Yellow highlighted line items are expected to require attention in this initial year, light blue highlighted items are expected to occur within the first-five years.

Introduction



A Reserve Study is the art and science of anticipating, and preparing for, an association's major common area repair and replacement expenses. Partially art, because in this field we are making projections about the future. Partially science, because our work is a combination of research and well-defined computations, following consistent National Reserve Study Standard principles.

The foundation of this and every Reserve Study is your Reserve Component List (what you are reserving for). This is because the Reserve Component List defines the *scope and schedule* of all your anticipated upcoming Reserve projects. Based on that List and your starting balance, we calculate the association's Reserve Fund Strength (reported in terms of "Percent Funded"). Then we compute a Reserve Funding Plan to provide for the Reserve needs of the association. These form the three results of your Reserve Study.



Reserve funding is not "for the future". Ongoing Reserve transfers are intended to offset the ongoing, daily deterioration of your Reserve assets. Done well, a stable, budgeted Reserve Funding Plan will collect sufficient funds from the owners who enjoyed the use of those assets, so the association is financially prepared for the irregular expenditures scattered through future years when those projects eventually require replacement.

Methodology




For this [Update With-Site-Visit Reserve Study](#), we started with a review of your prior Reserve Study, then looked into recent Reserve expenditures, evaluated how expenditures are handled (ongoing maintenance vs Reserves), and researched any well-established association

precedents. We performed an on-site inspection to evaluate your common areas, updating and adjusting your Reserve Component List as appropriate.

Which Physical Assets are Funded by Reserves?

There is a national-standard three-part test to determine which projects should appear in a Reserve Component List. First, it must be a common area maintenance obligation. Second, both the need and schedule of a component's project can be reasonably anticipated. Third, the project's total cost is material to the client, can be reasonably anticipated, and includes all direct and related costs. A project cost is commonly considered *material* if it is more than 0.5% to 1% of the total annual budget. This limits Reserve components to major, predictable expenses. Within this framework, it is inappropriate to include *lifetime* components, unpredictable expenses (such as damage due to natural disasters and/or insurable events), and expenses more appropriately handled from the Operational budget.



How do we establish Useful Life and Remaining Useful Life estimates?

- 1) Visual Inspection (observed wear and age)
- 2) Association Reserves database of experience
- 3) Client History (install dates & previous life cycle information)
- 4) Vendor Evaluation and Recommendation

How do we establish Current Repair/Replacement Cost Estimates?

In this order...

- 1) Actual client cost history, or current proposals
- 2) Comparison to Association Reserves database of work done at similar associations
- 3) Vendor Recommendations
- 4) Reliable National Industry cost estimating guidebooks

How much Reserves are enough?

Reserve adequacy is not measured in cash terms. Reserve adequacy is found when the *amount* of current Reserve cash is compared to Reserve component deterioration (the *needs of the association*). Having *enough* means the association can execute its projects in a timely manner with existing Reserve funds. Not having *enough* typically creates deferred maintenance or special assessments.

Adequacy is measured in a two-step process:

- 1) Calculate the *value of deterioration* at the association (called Fully Funded Balance, or FFB).
- 2) Compare that to the Reserve Fund Balance, and express as a percentage.



Each year, the *value of deterioration* at the association changes. When there is more deterioration (as components approach the time they need to be replaced), there should be more cash to offset that deterioration and prepare for the expenditure. Conversely, the *value of deterioration* shrinks after projects are accomplished. The *value of deterioration* (the FFB) changes each year, and is a moving but predictable target.

There is a high risk of special assessments and deferred maintenance when the Percent Funded is *weak*, below 30%. Approximately 30% of all associations are in this high risk range. While the 100% point is Ideal (indicating Reserve cash is equal to the *value of deterioration*), a Reserve Fund in the 70% - 130% range is considered strong (low risk of special assessment).

Measuring your Reserves by Percent Funded tells how well prepared your association is for upcoming Reserve expenses. New buyers should be very aware of this important disclosure!

How much should we transfer to Reserves?



According to National Reserve Study Standards, there are four Funding Principles to balance in developing your Reserve Funding Plan. Our first objective is to design a plan that provides you with sufficient cash to perform your Reserve projects on time. Second, a stable rate of ongoing Reserve transfers is desirable because it keeps these naturally irregular expenses from unsettling the budget.

Reserve transfers that are evenly distributed over current and future owners enable each owner to pay their fair share of the association's Reserve expenses over the years. And finally, we develop a plan that is fiscally responsible and safe for Board members to recommend to their association. Remember, it is the Board's job to provide for the ongoing care of the common areas. Board members invite liability exposure when Reserve transfers are inadequate to offset ongoing common area deterioration.

What is our Recommended Funding Goal?

Maintaining the Reserve Fund at a level equal to the *value* of deterioration is called "Full Funding" (100% Funded). As each asset ages and becomes "used up," the Reserve Fund grows proportionally. **This is simple, responsible, and our recommendation.** Evidence shows that associations in the 70 - 130% range *enjoy a low risk of special assessments or deferred maintenance.*



Allowing the Reserves to fall close to zero, but not below zero, is called Baseline Funding. Doing so allows the Reserve Fund to drop into the 0 - 30% range, where there is a high risk of special assessments & deferred maintenance. Since Baseline Funding still provides for the timely execution of all Reserve projects, and only the "margin of safety" is different, recommended Reserve transfers for Baseline Funding average only 10% to 15% less than Full Funding recommendations. Threshold Funding is the title of all other Cash or Percent Funded objectives *between* Baseline Funding and Full Funding.

Site Inspection Notes

During our site visit on 9/23/2025, we visually inspected all visible common areas, while compiling a photographic inventory, noting: general exterior observations, make & model information where appropriate, apparent levels of care and maintenance, exposure to weather elements and other factors that may affect the components useful life.

Projected Expenses

While this Reserve Study looks forward 30 years, we have no expectation that all these expenses will all take place as anticipated. This Reserve Study needs to be updated annually because we expect the timing of these expenses to shift and the size of these expenses to change. We do feel more certain of the timing and cost of near-term expenses than expenses many years away. The figure below summarizes the projected future expenses at your association as defined by your Reserve Component List. A summary of these expenses are shown in the 30-yr Summary Table, while details of the projects that make up these expenses are shown in the Cash Flow Detail Table.




Figure 1

Reserve Fund Status

The starting point for our financial analysis is your Reserve Fund balance, projected to be \$364,732 as-of the start of your Fiscal Year on 1/1/2026. As of that date, your Fully Funded Balance is computed to be \$3,886,059 (see Fully Funded Balance Table). This figure represents the deteriorated value of your common area components.

Recommended Funding Plan

Based on your current Percent Funded and your near-term and long-term Reserve needs, we are recommending budgeted contributions of \$38,700 per month and Special Assessment of {SpecAssessment} this Fiscal Year. The overall 30-yr plan, in perspective, is shown below. This same information is shown numerically in both the 30-yr Summary Table and the Cash Flow Detail Table.




Figure 2

The following chart shows your Reserve balance under our recommended Full Funding Plan, an alternate Baseline Funding Plan, and at your current budgeted transfer rate (assumes future increases), compared to your always-changing Fully Funded Balance target.




Figure 3

This figure shows the same information plotted on a Percent Funded scale. It is clear here to see how your Reserve Fund strength approaches the 100% Funded level under our recommended multi-yr Funding Plan.




Figure 4



Table Descriptions

Executive Summary is a summary of your Reserve Components

Reserve Component List Detail discloses key Component information, providing the foundation upon which the financial analysis is performed.

Fully Funded Balance shows the calculation of the Fully Funded Balance for each of your components, and their specific proportion related to the property total. For each component, the Fully Funded Balance is the fraction of life used up multiplied by its estimated Current Replacement Cost.

Component Significance shows the relative significance of each component to Reserve funding needs of the property, helping you see which components have more (or less) influence than others on your total Reserve funding requirements. The deterioration cost/yr of each component is calculated by dividing the estimated Current Replacement Cost by its Useful Life, then that component's percentage of the total is displayed.

30-Yr Reserve Plan Summary provides a one-page 30-year summary of the cash flowing into and out of the Reserve Fund, with a display of the Fully Funded Balance, Percent Funded, and special assessment risk at the beginning of each year.

30-Year Income/Expense Detail shows the detailed income and expenses for each of the next 30 years. This table makes it possible to see which components are projected to require repair or replacement in a particular year, and the size of those individual expenses.



#	Component	Approx	Quantity	Useful Life	Rem. Useful Life	Current Cost Estimate	
						Lower Estimate	Higher Estimate
Site & Grounds							
100	Concrete - Maintain/Repair	1	Unfunded	10	0	\$6,300	\$7,700
120	Shared Asphalt - Resurface	4,500	GSF, Asphalt	35	8	\$10,900	\$13,300
121	Shared Asphalt - Repair & Seal	4,500	GSF, Asphalt	5	0	\$1,800	\$2,200
122	1999 Asphalt - Resurface	104,170	GSF, Asphalt	35	8	\$361,000	\$441,000
123	2019 Parking Area - Resurface	2,450	GSF, Asphalt	35	28	\$8,550	\$10,400
125	Asphalt - Repair & Seal	106,620	GSF, Asphalt	5	4	\$53,500	\$65,300
140	Perimeter Fences - Replace	965	LF, Wood	20	10	\$58,100	\$71,100
142	Yard Fencing - Replace	1	Allowance	5	4	\$49,100	\$60,100
143	Storm Pond Fence - Replace	445	LF, Wood	20	0	\$28,400	\$34,800
145	Vinyl Fence – Replace	1,930	LF	35	8	\$89,600	\$109,000
147	Garbage Enclosures - Repair/Replace	4	LF, Wood	25	23	\$24,200	\$29,600
160	Pole Lights - Replace	10	Assemblies, Metal	40	13	\$11,900	\$14,500
183	Drainage & Stormwater - CB Cleaning	14	Catch Basins	3	0	\$3,600	\$4,400
205	Mailboxes - Replace	7	Clusters	30	21	\$19,500	\$23,900
220	Sport Court - Resurface	1,125	GSF / Concrete	45	18	\$25,100	\$30,700
Building Exteriors							
500	Bldgs BB & DD Roofs - Replace	19,990	GSF / Comp Shingle	25	18	\$185,000	\$226,000
501	Bldg Y Roof - Replace	6,060	GSF / Comp Shingle	25	20	\$56,200	\$68,700
502	Bldgs O & AA Roofs - Replace	14,760	GSF / Comp Shingle	25	21	\$137,000	\$167,000
503	Bldgs B & D Roof - Replace	7,630	GSF / Comp Shingle	25	22	\$90,900	\$111,000
504	Roofs (23) - Replace	128,900	GSF / Comp Shingle	25	23	\$1,190,000	\$1,460,000
507	Garage Roofs - Replace	7,580	GSF / Comp Shingle	20	0	\$70,300	\$85,900
513	Skylights - Replace	35	Fixtures	25	23	\$29,900	\$36,500
517	Gutters & Downspouts - Replace	11,300	LF, Metal	40	13	\$158,000	\$193,000
520	Vinyl Siding - Exterior Renovation	124,000	GSF	40	13	\$3,170,000	\$3,880,000
521	Vinyl Siding - Clean & Inspect	124,000	GSF	4	3	\$54,900	\$67,100
533	Exterior Surfaces - Caulk & Paint	1	Allowance	8	0	\$99,000	\$121,000
541	Traffic Coated Decks - Resurface	5,405	GSF, Elastomeric	30	3	\$155,000	\$189,000
542	Traffic Coated Decks - Recoat	5,405	GSF, Elastomeric	5	3	\$65,200	\$79,600
543	Elevated Walkway - Recoat	805	GSF, Elastomeric	5	3	\$9,810	\$12,000
545	Wood Decks - Replace	2,560	GSF, Wood	20	5	\$73,500	\$89,900
555	Building Wood Rails - Replace	2,000	LF	20	4	\$130,000	\$159,000
560	Exterior Lights - Replace	400	Fixtures, Assorted	40	13	\$39,600	\$48,400
Systems & Evaluations							
900	Plumbing - Systems Evaluation	1	Inspection & Report	20	0	\$11,200	\$13,800
965	Fire Alarm Panels - Replace	3	Panels	20	0	\$18,000	\$22,000
995	Building Envelope & Structure	1	Inspection & Report	10	0	\$10,800	\$13,200
35	Total Funded Components						



#	Component	Current Cost Estimate	X	Effective Age	/	Useful Life	=	Fully Funded Balance
Site & Grounds								
100	Concrete - Maintain/Repair	\$7,000	X	10	/	10	=	\$7,000
120	Shared Asphalt - Resurface	\$12,100	X	27	/	35	=	\$9,334
121	Shared Asphalt - Repair & Seal	\$2,000	X	5	/	5	=	\$2,000
122	1999 Asphalt - Resurface	\$401,000	X	27	/	35	=	\$309,343
123	2019 Parking Area - Resurface	\$9,500	X	7	/	35	=	\$1,900
125	Asphalt - Repair & Seal	\$59,400	X	1	/	5	=	\$11,880
140	Perimeter Fences - Replace	\$64,600	X	10	/	20	=	\$32,300
142	Yard Fencing - Replace	\$54,600	X	1	/	5	=	\$10,920
143	Storm Pond Fence - Replace	\$31,600	X	20	/	20	=	\$31,600
145	Vinyl Fence - Replace	\$99,500	X	27	/	35	=	\$76,757
147	Garbage Enclosures - Repair/Replace	\$26,900	X	2	/	25	=	\$2,152
160	Pole Lights - Replace	\$13,200	X	27	/	40	=	\$8,910
183	Drainage & Stormwater - CB Cleaning	\$4,000	X	3	/	3	=	\$4,000
205	Mailboxes - Replace	\$21,700	X	9	/	30	=	\$6,510
220	Sport Court - Resurface	\$27,900	X	27	/	45	=	\$16,740
Building Exteriors								
500	Bldgs BB & DD Roofs - Replace	\$205,897	X	7	/	25	=	\$57,651
501	Bldg Y Roof - Replace	\$62,418	X	5	/	25	=	\$12,484
502	Bldgs O & AA Roofs - Replace	\$152,028	X	4	/	25	=	\$24,324
503	Bldgs B & D Roof - Replace	\$101,000	X	3	/	25	=	\$12,120
504	Roofs (23) - Replace	\$1,327,670	X	2	/	25	=	\$106,214
507	Garage Roofs - Replace	\$78,100	X	20	/	20	=	\$78,100
513	Skylights - Replace	\$33,180	X	2	/	25	=	\$2,654
517	Gutters & Downspouts - Replace	\$175,200	X	27	/	40	=	\$118,260
520	Vinyl Siding - Exterior Renovation	\$3,524,000	X	27	/	40	=	\$2,378,700
521	Vinyl Siding - Clean & Inspect	\$61,000	X	1	/	4	=	\$15,250
533	Exterior Surfaces - Caulk & Paint	\$110,000	X	8	/	8	=	\$110,000
541	Traffic Coated Decks - Resurface	\$172,000	X	27	/	30	=	\$154,800
542	Traffic Coated Decks - Recoat	\$72,400	X	2	/	5	=	\$28,960
543	Elevated Walkway - Recoat	\$10,900	X	2	/	5	=	\$4,360
545	Wood Decks - Replace	\$81,700	X	15	/	20	=	\$61,275
555	Building Wood Rails - Replace	\$144,200	X	16	/	20	=	\$115,360
560	Exterior Lights - Replace	\$44,000	X	27	/	40	=	\$29,700
Systems & Evaluations								
900	Plumbing - Systems Evaluation	\$12,500	X	20	/	20	=	\$12,500
965	Fire Alarm Panels - Replace	\$20,000	X	20	/	20	=	\$20,000
995	Building Envelope & Structure	\$12,000	X	10	/	10	=	\$12,000
								\$3,886,059



Component Significance

Report # 13381-3
With-Site-Visit

# Component	Useful Life (yrs)	Current Cost Estimate	Deterioration Cost/Yr	Deterioration Significance
Site & Grounds				
100 Concrete - Maintain/Repair	10	\$7,000	\$700	0.24 %
120 Shared Asphalt - Resurface	35	\$12,100	\$346	0.12 %
121 Shared Asphalt - Repair & Seal	5	\$2,000	\$400	0.14 %
122 1999 Asphalt - Resurface	35	\$401,000	\$11,457	4.01 %
123 2019 Parking Area - Resurface	35	\$9,500	\$271	0.09 %
125 Asphalt - Repair & Seal	5	\$59,400	\$11,880	4.15 %
140 Perimeter Fences - Replace	20	\$64,600	\$3,230	1.13 %
142 Yard Fencing - Replace	5	\$54,600	\$10,920	3.82 %
143 Storm Pond Fence - Replace	20	\$31,600	\$1,580	0.55 %
145 Vinyl Fence – Replace	35	\$99,500	\$2,843	0.99 %
147 Garbage Enclosures - Repair/Replace	25	\$26,900	\$1,076	0.38 %
160 Pole Lights - Replace	40	\$13,200	\$330	0.12 %
183 Drainage & Stormwater - CB Cleaning	3	\$4,000	\$1,333	0.47 %
205 Mailboxes - Replace	30	\$21,700	\$723	0.25 %
220 Sport Court - Resurface	45	\$27,900	\$620	0.22 %
Building Exteriors				
500 Bldgs BB & DD Roofs - Replace	25	\$205,897	\$8,236	2.88 %
501 Bldg Y Roof - Replace	25	\$62,418	\$2,497	0.87 %
502 Bldgs O & AA Roofs - Replace	25	\$152,028	\$6,081	2.13 %
503 Bldgs B & D Roof - Replace	25	\$101,000	\$4,040	1.41 %
504 Roofs (23) - Replace	25	\$1,327,670	\$53,107	18.57 %
507 Garage Roofs - Replace	20	\$78,100	\$3,905	1.37 %
513 Skylights - Replace	25	\$33,180	\$1,327	0.46 %
517 Gutters & Downspouts - Replace	40	\$175,200	\$4,380	1.53 %
520 Vinyl Siding - Exterior Renovation	40	\$3,524,000	\$88,100	30.80 %
521 Vinyl Siding - Clean & Inspect	4	\$61,000	\$15,250	5.33 %
533 Exterior Surfaces - Caulk & Paint	8	\$110,000	\$13,750	4.81 %
541 Traffic Coated Decks - Resurface	30	\$172,000	\$5,733	2.00 %
542 Traffic Coated Decks - Recoat	5	\$72,400	\$14,480	5.06 %
543 Elevated Walkway - Recoat	5	\$10,900	\$2,180	0.76 %
545 Wood Decks - Replace	20	\$81,700	\$4,085	1.43 %
555 Building Wood Rails - Replace	20	\$144,200	\$7,210	2.52 %
560 Exterior Lights - Replace	40	\$44,000	\$1,100	0.38 %
Systems & Evaluations				
900 Plumbing - Systems Evaluation	20	\$12,500	\$625	0.22 %
965 Fire Alarm Panels - Replace	20	\$20,000	\$1,000	0.35 %
995 Building Envelope & Structure	10	\$12,000	\$1,200	0.42 %
35 Total Funded Components			\$285,996	100.00 %



30-Year Reserve Plan Summary

Report # 13381-3
With-Site-Visit

Fiscal Year Start: 2026

Net After Tax Interest:

1.00 %

Avg 30-Yr Inflation: 3.00 %

Reserve Fund Strength (as-of Fiscal Year Start)					Projected Reserve Balance Changes				
Year	Starting Reserve Balance	Fully Funded Balance	Percent Funded	Special Assmt Risk	% Increase In Annual Reserve Funding	Reserve Funding	Loan or Special Assmts	Interest Income	Reserve Expenses
2026	\$364,732	\$3,886,059	9.4 %	High	153.85 %	\$464,400	\$0	\$4,604	\$277,200
2027	\$556,536	\$4,011,700	13.9 %	High	3.00 %	\$478,332	\$0	\$7,994	\$0
2028	\$1,042,862	\$4,435,464	23.5 %	High	3.00 %	\$492,682	\$0	\$12,951	\$0
2029	\$1,548,495	\$4,881,043	31.7 %	Medium	3.00 %	\$507,462	\$0	\$16,347	\$350,000
2030	\$1,722,304	\$4,988,865	34.5 %	Medium	3.00 %	\$522,686	\$0	\$18,468	\$290,606
2031	\$1,972,852	\$5,170,754	38.2 %	Medium	3.00 %	\$538,367	\$0	\$22,036	\$97,031
2032	\$2,436,224	\$5,567,428	43.8 %	Medium	3.00 %	\$554,518	\$0	\$27,236	\$4,776
2033	\$3,013,201	\$6,081,271	49.5 %	Medium	3.00 %	\$571,153	\$0	\$32,763	\$75,022
2034	\$3,542,095	\$6,548,727	54.1 %	Medium	3.00 %	\$588,288	\$0	\$34,047	\$894,213
2035	\$3,270,217	\$6,197,309	52.8 %	Medium	3.00 %	\$605,937	\$0	\$35,123	\$153,963
2036	\$3,757,313	\$6,609,001	56.9 %	Medium	3.00 %	\$624,115	\$0	\$40,303	\$115,039
2037	\$4,306,691	\$7,084,665	60.8 %	Medium	3.00 %	\$642,838	\$0	\$46,070	\$84,438
2038	\$4,911,161	\$7,617,996	64.5 %	Medium	3.00 %	\$662,123	\$0	\$52,635	\$5,703
2039	\$5,620,216	\$8,260,656	68.0 %	Medium	3.00 %	\$681,987	\$0	\$31,563	\$5,638,729
2040	\$695,037	\$3,133,179	22.2 %	High	1.00 %	\$688,807	\$0	\$9,576	\$172,435
2041	\$1,220,985	\$3,495,139	34.9 %	Medium	1.00 %	\$695,695	\$0	\$15,236	\$104,384
2042	\$1,827,532	\$3,951,417	46.3 %	Medium	12.12 %	\$780,000	\$0	\$21,391	\$176,518
2043	\$2,452,405	\$4,360,854	56.2 %	Medium	1.00 %	\$787,800	\$0	\$28,594	\$0
2044	\$3,268,799	\$4,978,568	65.7 %	Medium	1.00 %	\$795,678	\$0	\$34,089	\$546,646
2045	\$3,551,920	\$5,066,375	70.1 %	Low	1.00 %	\$803,635	\$0	\$38,178	\$306,864
2046	\$4,086,868	\$5,418,837	75.4 %	Low	1.00 %	\$811,671	\$0	\$43,087	\$407,491
2047	\$4,534,135	\$5,693,723	79.6 %	Low	1.00 %	\$819,788	\$0	\$48,007	\$330,626
2048	\$5,071,303	\$6,071,987	83.5 %	Low	1.00 %	\$827,986	\$0	\$54,133	\$193,526
2049	\$5,759,896	\$6,619,252	87.0 %	Low	1.00 %	\$836,266	\$0	\$46,877	\$3,023,633
2050	\$3,619,404	\$4,284,858	84.5 %	Low	1.00 %	\$844,628	\$0	\$36,803	\$756,606
2051	\$3,744,229	\$4,232,911	88.5 %	Low	1.00 %	\$853,075	\$0	\$41,019	\$175,249
2052	\$4,463,074	\$4,796,168	93.1 %	Low	1.00 %	\$861,605	\$0	\$49,164	\$0
2053	\$5,373,843	\$5,575,333	96.4 %	Low	1.00 %	\$870,221	\$0	\$57,631	\$144,384
2054	\$6,157,311	\$6,248,215	98.5 %	Low	1.00 %	\$878,924	\$0	\$65,204	\$212,320
2055	\$6,889,120	\$6,890,941	100.0 %	Low	1.00 %	\$887,713	\$0	\$72,317	\$268,648



30-Year Reserve Plan Summary (Alternate Funding Plan)

Report # 13381-3
With-Site-Visit

Fiscal Year Start: 2026

Net After Tax Interest:

1.00 %

Avg 30-Yr Inflation: 3.00 %

Reserve Fund Strength (as-of Fiscal Year Start)					Projected Reserve Balance Changes				
Year	Starting Reserve Balance	Fully Funded Balance	Percent Funded	Special Assmt Risk	% Increase In Annual Reserve Funding	Reserve Funding	Loan or Special Assmts	Interest Income	Reserve Expenses
2026	\$364,732	\$3,886,059	9.4 %	High	136.14 %	\$432,000	\$0	\$4,442	\$277,200
2027	\$523,974	\$4,011,700	13.1 %	High	3.00 %	\$444,960	\$0	\$7,499	\$0
2028	\$976,432	\$4,435,464	22.0 %	High	3.00 %	\$458,309	\$0	\$12,111	\$0
2029	\$1,446,853	\$4,881,043	29.6 %	High	3.00 %	\$472,058	\$0	\$15,148	\$350,000
2030	\$1,584,058	\$4,988,865	31.8 %	Medium	3.00 %	\$486,220	\$0	\$16,896	\$290,606
2031	\$1,796,568	\$5,170,754	34.7 %	Medium	3.00 %	\$500,806	\$0	\$20,076	\$97,031
2032	\$2,220,419	\$5,567,428	39.9 %	Medium	3.00 %	\$515,831	\$0	\$24,873	\$4,776
2033	\$2,756,347	\$6,081,271	45.3 %	Medium	3.00 %	\$531,306	\$0	\$29,982	\$75,022
2034	\$3,242,612	\$6,548,727	49.5 %	Medium	3.00 %	\$547,245	\$0	\$30,832	\$894,213
2035	\$2,926,476	\$6,197,309	47.2 %	Medium	3.00 %	\$563,662	\$0	\$31,457	\$153,963
2036	\$3,367,632	\$6,609,001	51.0 %	Medium	3.00 %	\$580,572	\$0	\$36,169	\$115,039
2037	\$3,869,334	\$7,084,665	54.6 %	Medium	3.00 %	\$597,989	\$0	\$41,451	\$84,438
2038	\$4,424,336	\$7,617,996	58.1 %	Medium	3.00 %	\$615,929	\$0	\$47,512	\$5,703
2039	\$5,082,073	\$8,260,656	61.5 %	Medium	3.00 %	\$634,407	\$0	\$25,918	\$5,638,729
2040	\$103,669	\$3,133,179	3.3 %	High	1.00 %	\$640,751	\$0	\$3,394	\$172,435
2041	\$575,378	\$3,495,139	16.5 %	High	1.00 %	\$647,158	\$0	\$8,507	\$104,384
2042	\$1,126,659	\$3,951,417	28.5 %	High	13.44 %	\$734,118	\$0	\$14,119	\$176,518
2043	\$1,698,378	\$4,360,854	38.9 %	Medium	1.00 %	\$741,459	\$0	\$20,786	\$0
2044	\$2,460,623	\$4,978,568	49.4 %	Medium	1.00 %	\$748,874	\$0	\$25,735	\$546,646
2045	\$2,688,586	\$5,066,375	53.1 %	Medium	1.00 %	\$756,363	\$0	\$29,267	\$306,864
2046	\$3,167,352	\$5,418,837	58.5 %	Medium	1.00 %	\$763,926	\$0	\$33,609	\$407,491
2047	\$3,557,397	\$5,693,723	62.5 %	Medium	1.00 %	\$771,565	\$0	\$37,952	\$330,626
2048	\$4,036,288	\$6,071,987	66.5 %	Medium	1.00 %	\$779,281	\$0	\$43,491	\$193,526
2049	\$4,665,533	\$6,619,252	70.5 %	Low	1.00 %	\$787,074	\$0	\$35,636	\$3,023,633
2050	\$2,464,610	\$4,284,858	57.5 %	Medium	1.00 %	\$794,945	\$0	\$24,952	\$756,606
2051	\$2,527,900	\$4,232,911	59.7 %	Medium	1.00 %	\$802,894	\$0	\$28,548	\$175,249
2052	\$3,184,093	\$4,796,168	66.4 %	Medium	1.00 %	\$810,923	\$0	\$36,061	\$0
2053	\$4,031,076	\$5,575,333	72.3 %	Low	1.00 %	\$819,032	\$0	\$43,885	\$144,384
2054	\$4,749,609	\$6,248,215	76.0 %	Low	1.00 %	\$827,223	\$0	\$50,803	\$212,320
2055	\$5,415,315	\$6,890,941	78.6 %	Low	1.00 %	\$835,495	\$0	\$57,249	\$268,648

30-Year Income/Expense Detail

Report # 13381-3
With-Site-Visit

Fiscal Year	2026	2027	2028	2029	2030
Starting Reserve Balance	\$364,732	\$556,536	\$1,042,862	\$1,548,495	\$1,722,304
Annual Reserve Funding	\$464,400	\$478,332	\$492,682	\$507,462	\$522,686
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$4,604	\$7,994	\$12,951	\$16,347	\$18,468
Total Income	\$833,736	\$1,042,862	\$1,548,495	\$2,072,305	\$2,263,458
# Component					
Site & Grounds					
100 Concrete - Maintain/Repair	\$7,000	\$0	\$0	\$0	\$0
120 Shared Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
121 Shared Asphalt - Repair & Seal	\$2,000	\$0	\$0	\$0	\$0
122 1999 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
123 2019 Parking Area - Resurface	\$0	\$0	\$0	\$0	\$0
125 Asphalt - Repair & Seal	\$0	\$0	\$0	\$0	\$66,855
140 Perimeter Fences - Replace	\$0	\$0	\$0	\$0	\$0
142 Yard Fencing - Replace	\$0	\$0	\$0	\$0	\$61,453
143 Storm Pond Fence - Replace	\$31,600	\$0	\$0	\$0	\$0
145 Vinyl Fence - Replace	\$0	\$0	\$0	\$0	\$0
147 Garbage Enclosures - Repair/Replace	\$0	\$0	\$0	\$0	\$0
160 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
183 Drainage & Stormwater - CB Cleaning	\$4,000	\$0	\$0	\$4,371	\$0
205 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
220 Sport Court - Resurface	\$0	\$0	\$0	\$0	\$0
Building Exteriors					
500 Bldgs BB & DD Roofs - Replace	\$0	\$0	\$0	\$0	\$0
501 Bldg Y Roof - Replace	\$0	\$0	\$0	\$0	\$0
502 Bldgs O & AA Roofs - Replace	\$0	\$0	\$0	\$0	\$0
503 Bldgs B & D Roof - Replace	\$0	\$0	\$0	\$0	\$0
504 Roofs (23) - Replace	\$0	\$0	\$0	\$0	\$0
507 Garage Roofs - Replace	\$78,100	\$0	\$0	\$0	\$0
513 Skylights - Replace	\$0	\$0	\$0	\$0	\$0
517 Gutters & Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
520 Vinyl Siding - Exterior Renovation	\$0	\$0	\$0	\$0	\$0
521 Vinyl Siding - Clean & Inspect	\$0	\$0	\$0	\$66,656	\$0
533 Exterior Surfaces - Caulk & Paint	\$110,000	\$0	\$0	\$0	\$0
541 Traffic Coated Decks - Resurface	\$0	\$0	\$0	\$187,949	\$0
542 Traffic Coated Decks - Recoat	\$0	\$0	\$0	\$79,113	\$0
543 Elevated Walkway - Recoat	\$0	\$0	\$0	\$11,911	\$0
545 Wood Decks - Replace	\$0	\$0	\$0	\$0	\$0
555 Building Wood Rails - Replace	\$0	\$0	\$0	\$0	\$162,298
560 Exterior Lights - Replace	\$0	\$0	\$0	\$0	\$0
Systems & Evaluations					
900 Plumbing - Systems Evaluation	\$12,500	\$0	\$0	\$0	\$0
965 Fire Alarm Panels - Replace	\$20,000	\$0	\$0	\$0	\$0
995 Building Envelope & Structure	\$12,000	\$0	\$0	\$0	\$0
Total Expenses	\$277,200	\$0	\$0	\$350,000	\$290,606
Ending Reserve Balance	\$556,536	\$1,042,862	\$1,548,495	\$1,722,304	\$1,972,852

Fiscal Year	2031	2032	2033	2034	2035
Starting Reserve Balance	\$1,972,852	\$2,436,224	\$3,013,201	\$3,542,095	\$3,270,217
Annual Reserve Funding	\$538,367	\$554,518	\$571,153	\$588,288	\$605,937
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$22,036	\$27,236	\$32,763	\$34,047	\$35,123
Total Income	\$2,533,255	\$3,017,977	\$3,617,117	\$4,164,430	\$3,911,276
# Component					
Site & Grounds					
100 Concrete - Maintain/Repair	\$0	\$0	\$0	\$0	\$0
120 Shared Asphalt - Resurface	\$0	\$0	\$0	\$15,328	\$0
121 Shared Asphalt - Repair & Seal	\$2,319	\$0	\$0	\$0	\$0
122 1999 Asphalt - Resurface	\$0	\$0	\$0	\$507,975	\$0
123 2019 Parking Area - Resurface	\$0	\$0	\$0	\$0	\$0
125 Asphalt - Repair & Seal	\$0	\$0	\$0	\$0	\$77,504
140 Perimeter Fences - Replace	\$0	\$0	\$0	\$0	\$0
142 Yard Fencing - Replace	\$0	\$0	\$0	\$0	\$71,241
143 Storm Pond Fence - Replace	\$0	\$0	\$0	\$0	\$0
145 Vinyl Fence - Replace	\$0	\$0	\$0	\$126,044	\$0
147 Garbage Enclosures - Repair/Replace	\$0	\$0	\$0	\$0	\$0
160 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
183 Drainage & Stormwater - CB Cleaning	\$0	\$4,776	\$0	\$0	\$5,219
205 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
220 Sport Court - Resurface	\$0	\$0	\$0	\$0	\$0
Building Exteriors					
500 Bldgs BB & DD Roofs - Replace	\$0	\$0	\$0	\$0	\$0
501 Bldg Y Roof - Replace	\$0	\$0	\$0	\$0	\$0
502 Bldgs O & AA Roofs - Replace	\$0	\$0	\$0	\$0	\$0
503 Bldgs B & D Roof - Replace	\$0	\$0	\$0	\$0	\$0
504 Roofs (23) - Replace	\$0	\$0	\$0	\$0	\$0
507 Garage Roofs - Replace	\$0	\$0	\$0	\$0	\$0
513 Skylights - Replace	\$0	\$0	\$0	\$0	\$0
517 Gutters & Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
520 Vinyl Siding - Exterior Renovation	\$0	\$0	\$0	\$0	\$0
521 Vinyl Siding - Clean & Inspect	\$0	\$0	\$75,022	\$0	\$0
533 Exterior Surfaces - Caulk & Paint	\$0	\$0	\$0	\$139,345	\$0
541 Traffic Coated Decks - Resurface	\$0	\$0	\$0	\$0	\$0
542 Traffic Coated Decks - Recoat	\$0	\$0	\$0	\$91,714	\$0
543 Elevated Walkway - Recoat	\$0	\$0	\$0	\$13,808	\$0
545 Wood Decks - Replace	\$94,713	\$0	\$0	\$0	\$0
555 Building Wood Rails - Replace	\$0	\$0	\$0	\$0	\$0
560 Exterior Lights - Replace	\$0	\$0	\$0	\$0	\$0
Systems & Evaluations					
900 Plumbing - Systems Evaluation	\$0	\$0	\$0	\$0	\$0
965 Fire Alarm Panels - Replace	\$0	\$0	\$0	\$0	\$0
995 Building Envelope & Structure	\$0	\$0	\$0	\$0	\$0
Total Expenses	\$97,031	\$4,776	\$75,022	\$894,213	\$153,963
Ending Reserve Balance	\$2,436,224	\$3,013,201	\$3,542,095	\$3,270,217	\$3,757,313

Fiscal Year	2036	2037	2038	2039	2040
Starting Reserve Balance	\$3,757,313	\$4,306,691	\$4,911,161	\$5,620,216	\$695,037
Annual Reserve Funding	\$624,115	\$642,838	\$662,123	\$681,987	\$688,807
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$40,303	\$46,070	\$52,635	\$31,563	\$9,576
Total Income	\$4,421,731	\$4,995,599	\$5,625,919	\$6,333,766	\$1,393,420
# Component					
Site & Grounds					
100 Concrete - Maintain/Repair	\$9,407	\$0	\$0	\$0	\$0
120 Shared Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
121 Shared Asphalt - Repair & Seal	\$2,688	\$0	\$0	\$0	\$0
122 1999 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
123 2019 Parking Area - Resurface	\$0	\$0	\$0	\$0	\$0
125 Asphalt - Repair & Seal	\$0	\$0	\$0	\$0	\$89,848
140 Perimeter Fences - Replace	\$86,817	\$0	\$0	\$0	\$0
142 Yard Fencing - Replace	\$0	\$0	\$0	\$0	\$82,587
143 Storm Pond Fence - Replace	\$0	\$0	\$0	\$0	\$0
145 Vinyl Fence - Replace	\$0	\$0	\$0	\$0	\$0
147 Garbage Enclosures - Repair/Replace	\$0	\$0	\$0	\$0	\$0
160 Pole Lights - Replace	\$0	\$0	\$0	\$19,385	\$0
183 Drainage & Stormwater - CB Cleaning	\$0	\$0	\$5,703	\$0	\$0
205 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
220 Sport Court - Resurface	\$0	\$0	\$0	\$0	\$0
Building Exteriors					
500 Bldgs BB & DD Roofs - Replace	\$0	\$0	\$0	\$0	\$0
501 Bldg Y Roof - Replace	\$0	\$0	\$0	\$0	\$0
502 Bldgs O & AA Roofs - Replace	\$0	\$0	\$0	\$0	\$0
503 Bldgs B & D Roof - Replace	\$0	\$0	\$0	\$0	\$0
504 Roofs (23) - Replace	\$0	\$0	\$0	\$0	\$0
507 Garage Roofs - Replace	\$0	\$0	\$0	\$0	\$0
513 Skylights - Replace	\$0	\$0	\$0	\$0	\$0
517 Gutters & Downspouts - Replace	\$0	\$0	\$0	\$257,287	\$0
520 Vinyl Siding - Exterior Renovation	\$0	\$0	\$0	\$5,175,113	\$0
521 Vinyl Siding - Clean & Inspect	\$0	\$84,438	\$0	\$0	\$0
533 Exterior Surfaces - Caulk & Paint	\$0	\$0	\$0	\$0	\$0
541 Traffic Coated Decks - Resurface	\$0	\$0	\$0	\$0	\$0
542 Traffic Coated Decks - Recoat	\$0	\$0	\$0	\$106,322	\$0
543 Elevated Walkway - Recoat	\$0	\$0	\$0	\$16,007	\$0
545 Wood Decks - Replace	\$0	\$0	\$0	\$0	\$0
555 Building Wood Rails - Replace	\$0	\$0	\$0	\$0	\$0
560 Exterior Lights - Replace	\$0	\$0	\$0	\$64,615	\$0
Systems & Evaluations					
900 Plumbing - Systems Evaluation	\$0	\$0	\$0	\$0	\$0
965 Fire Alarm Panels - Replace	\$0	\$0	\$0	\$0	\$0
995 Building Envelope & Structure	\$16,127	\$0	\$0	\$0	\$0
Total Expenses	\$115,039	\$84,438	\$5,703	\$5,638,729	\$172,435
Ending Reserve Balance	\$4,306,691	\$4,911,161	\$5,620,216	\$695,037	\$1,220,985

Fiscal Year	2041	2042	2043	2044	2045
Starting Reserve Balance	\$1,220,985	\$1,827,532	\$2,452,405	\$3,268,799	\$3,551,920
Annual Reserve Funding	\$695,695	\$780,000	\$787,800	\$795,678	\$803,635
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$15,236	\$21,391	\$28,594	\$34,089	\$38,178
Total Income	\$1,931,916	\$2,628,922	\$3,268,799	\$4,098,566	\$4,393,732
# Component					
Site & Grounds					
100 Concrete - Maintain/Repair	\$0	\$0	\$0	\$0	\$0
120 Shared Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
121 Shared Asphalt - Repair & Seal	\$3,116	\$0	\$0	\$0	\$0
122 1999 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
123 2019 Parking Area - Resurface	\$0	\$0	\$0	\$0	\$0
125 Asphalt - Repair & Seal	\$0	\$0	\$0	\$0	\$104,158
140 Perimeter Fences - Replace	\$0	\$0	\$0	\$0	\$0
142 Yard Fencing - Replace	\$0	\$0	\$0	\$0	\$95,741
143 Storm Pond Fence - Replace	\$0	\$0	\$0	\$0	\$0
145 Vinyl Fence - Replace	\$0	\$0	\$0	\$0	\$0
147 Garbage Enclosures - Repair/Replace	\$0	\$0	\$0	\$0	\$0
160 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
183 Drainage & Stormwater - CB Cleaning	\$6,232	\$0	\$0	\$6,810	\$0
205 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
220 Sport Court - Resurface	\$0	\$0	\$0	\$47,498	\$0
Building Exteriors					
500 Bldgs BB & DD Roofs - Replace	\$0	\$0	\$0	\$350,526	\$0
501 Bldg Y Roof - Replace	\$0	\$0	\$0	\$0	\$0
502 Bldgs O & AA Roofs - Replace	\$0	\$0	\$0	\$0	\$0
503 Bldgs B & D Roof - Replace	\$0	\$0	\$0	\$0	\$0
504 Roofs (23) - Replace	\$0	\$0	\$0	\$0	\$0
507 Garage Roofs - Replace	\$0	\$0	\$0	\$0	\$0
513 Skylights - Replace	\$0	\$0	\$0	\$0	\$0
517 Gutters & Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
520 Vinyl Siding - Exterior Renovation	\$0	\$0	\$0	\$0	\$0
521 Vinyl Siding - Clean & Inspect	\$95,036	\$0	\$0	\$0	\$106,964
533 Exterior Surfaces - Caulk & Paint	\$0	\$176,518	\$0	\$0	\$0
541 Traffic Coated Decks - Resurface	\$0	\$0	\$0	\$0	\$0
542 Traffic Coated Decks - Recoat	\$0	\$0	\$0	\$123,256	\$0
543 Elevated Walkway - Recoat	\$0	\$0	\$0	\$18,557	\$0
545 Wood Decks - Replace	\$0	\$0	\$0	\$0	\$0
555 Building Wood Rails - Replace	\$0	\$0	\$0	\$0	\$0
560 Exterior Lights - Replace	\$0	\$0	\$0	\$0	\$0
Systems & Evaluations					
900 Plumbing - Systems Evaluation	\$0	\$0	\$0	\$0	\$0
965 Fire Alarm Panels - Replace	\$0	\$0	\$0	\$0	\$0
995 Building Envelope & Structure	\$0	\$0	\$0	\$0	\$0
Total Expenses	\$104,384	\$176,518	\$0	\$546,646	\$306,864
Ending Reserve Balance	\$1,827,532	\$2,452,405	\$3,268,799	\$3,551,920	\$4,086,868

Fiscal Year	2046	2047	2048	2049	2050
Starting Reserve Balance	\$4,086,868	\$4,534,135	\$5,071,303	\$5,759,896	\$3,619,404
Annual Reserve Funding	\$811,671	\$819,788	\$827,986	\$836,266	\$844,628
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$43,087	\$48,007	\$54,133	\$46,877	\$36,803
Total Income	\$4,941,626	\$5,401,930	\$5,953,422	\$6,643,038	\$4,500,835
# Component					
Site & Grounds					
100 Concrete - Maintain/Repair	\$12,643	\$0	\$0	\$0	\$0
120 Shared Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
121 Shared Asphalt - Repair & Seal	\$3,612	\$0	\$0	\$0	\$0
122 1999 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
123 2019 Parking Area - Resurface	\$0	\$0	\$0	\$0	\$0
125 Asphalt - Repair & Seal	\$0	\$0	\$0	\$0	\$120,748
140 Perimeter Fences - Replace	\$0	\$0	\$0	\$0	\$0
142 Yard Fencing - Replace	\$0	\$0	\$0	\$0	\$110,991
143 Storm Pond Fence - Replace	\$57,073	\$0	\$0	\$0	\$0
145 Vinyl Fence - Replace	\$0	\$0	\$0	\$0	\$0
147 Garbage Enclosures - Repair/Replace	\$0	\$0	\$0	\$53,089	\$0
160 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
183 Drainage & Stormwater - CB Cleaning	\$0	\$7,441	\$0	\$0	\$8,131
205 Mailboxes - Replace	\$0	\$40,368	\$0	\$0	\$0
220 Sport Court - Resurface	\$0	\$0	\$0	\$0	\$0
Building Exteriors					
500 Bldgs BB & DD Roofs - Replace	\$0	\$0	\$0	\$0	\$0
501 Bldg Y Roof - Replace	\$112,734	\$0	\$0	\$0	\$0
502 Bldgs O & AA Roofs - Replace	\$0	\$282,817	\$0	\$0	\$0
503 Bldgs B & D Roof - Replace	\$0	\$0	\$193,526	\$0	\$0
504 Roofs (23) - Replace	\$0	\$0	\$0	\$2,620,272	\$0
507 Garage Roofs - Replace	\$141,057	\$0	\$0	\$0	\$0
513 Skylights - Replace	\$0	\$0	\$0	\$65,484	\$0
517 Gutters & Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
520 Vinyl Siding - Exterior Renovation	\$0	\$0	\$0	\$0	\$0
521 Vinyl Siding - Clean & Inspect	\$0	\$0	\$0	\$120,389	\$0
533 Exterior Surfaces - Caulk & Paint	\$0	\$0	\$0	\$0	\$223,607
541 Traffic Coated Decks - Resurface	\$0	\$0	\$0	\$0	\$0
542 Traffic Coated Decks - Recoat	\$0	\$0	\$0	\$142,888	\$0
543 Elevated Walkway - Recoat	\$0	\$0	\$0	\$21,512	\$0
545 Wood Decks - Replace	\$0	\$0	\$0	\$0	\$0
555 Building Wood Rails - Replace	\$0	\$0	\$0	\$0	\$293,129
560 Exterior Lights - Replace	\$0	\$0	\$0	\$0	\$0
Systems & Evaluations					
900 Plumbing - Systems Evaluation	\$22,576	\$0	\$0	\$0	\$0
965 Fire Alarm Panels - Replace	\$36,122	\$0	\$0	\$0	\$0
995 Building Envelope & Structure	\$21,673	\$0	\$0	\$0	\$0
Total Expenses	\$407,491	\$330,626	\$193,526	\$3,023,633	\$756,606
Ending Reserve Balance	\$4,534,135	\$5,071,303	\$5,759,896	\$3,619,404	\$3,744,229

Fiscal Year	2051	2052	2053	2054	2055
Starting Reserve Balance	\$3,744,229	\$4,463,074	\$5,373,843	\$6,157,311	\$6,889,120
Annual Reserve Funding	\$853,075	\$861,605	\$870,221	\$878,924	\$887,713
Recommended Special Assessments	\$0	\$0	\$0	\$0	\$0
Interest Earnings	\$41,019	\$49,164	\$57,631	\$65,204	\$72,317
Total Income	\$4,638,323	\$5,373,843	\$6,301,695	\$7,101,439	\$7,849,150
# Component					
Site & Grounds					
100 Concrete - Maintain/Repair	\$0	\$0	\$0	\$0	\$0
120 Shared Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
121 Shared Asphalt - Repair & Seal	\$4,188	\$0	\$0	\$0	\$0
122 1999 Asphalt - Resurface	\$0	\$0	\$0	\$0	\$0
123 2019 Parking Area - Resurface	\$0	\$0	\$0	\$21,735	\$0
125 Asphalt - Repair & Seal	\$0	\$0	\$0	\$0	\$139,980
140 Perimeter Fences - Replace	\$0	\$0	\$0	\$0	\$0
142 Yard Fencing - Replace	\$0	\$0	\$0	\$0	\$128,668
143 Storm Pond Fence - Replace	\$0	\$0	\$0	\$0	\$0
145 Vinyl Fence - Replace	\$0	\$0	\$0	\$0	\$0
147 Garbage Enclosures - Repair/Replace	\$0	\$0	\$0	\$0	\$0
160 Pole Lights - Replace	\$0	\$0	\$0	\$0	\$0
183 Drainage & Stormwater - CB Cleaning	\$0	\$0	\$8,885	\$0	\$0
205 Mailboxes - Replace	\$0	\$0	\$0	\$0	\$0
220 Sport Court - Resurface	\$0	\$0	\$0	\$0	\$0
Building Exteriors					
500 Bldgs BB & DD Roofs - Replace	\$0	\$0	\$0	\$0	\$0
501 Bldg Y Roof - Replace	\$0	\$0	\$0	\$0	\$0
502 Bldgs O & AA Roofs - Replace	\$0	\$0	\$0	\$0	\$0
503 Bldgs B & D Roof - Replace	\$0	\$0	\$0	\$0	\$0
504 Roofs (23) - Replace	\$0	\$0	\$0	\$0	\$0
507 Garage Roofs - Replace	\$0	\$0	\$0	\$0	\$0
513 Skylights - Replace	\$0	\$0	\$0	\$0	\$0
517 Gutters & Downspouts - Replace	\$0	\$0	\$0	\$0	\$0
520 Vinyl Siding - Exterior Renovation	\$0	\$0	\$0	\$0	\$0
521 Vinyl Siding - Clean & Inspect	\$0	\$0	\$135,499	\$0	\$0
533 Exterior Surfaces - Caulk & Paint	\$0	\$0	\$0	\$0	\$0
541 Traffic Coated Decks - Resurface	\$0	\$0	\$0	\$0	\$0
542 Traffic Coated Decks - Recoat	\$0	\$0	\$0	\$165,646	\$0
543 Elevated Walkway - Recoat	\$0	\$0	\$0	\$24,938	\$0
545 Wood Decks - Replace	\$171,062	\$0	\$0	\$0	\$0
555 Building Wood Rails - Replace	\$0	\$0	\$0	\$0	\$0
560 Exterior Lights - Replace	\$0	\$0	\$0	\$0	\$0
Systems & Evaluations					
900 Plumbing - Systems Evaluation	\$0	\$0	\$0	\$0	\$0
965 Fire Alarm Panels - Replace	\$0	\$0	\$0	\$0	\$0
995 Building Envelope & Structure	\$0	\$0	\$0	\$0	\$0
Total Expenses	\$175,249	\$0	\$144,384	\$212,320	\$268,648
Ending Reserve Balance	\$4,463,074	\$5,373,843	\$6,157,311	\$6,889,120	\$7,580,501



Accuracy, Limitations, and Disclosures

"This reserve study should be reviewed carefully. It may not include all common and limited common element components that will require major maintenance, repair, or replacement in future years, and may not include regular contributions to a reserve account for the cost of such maintenance, repair, or replacement. The failure to include a component in a reserve study, or to provide contributions to a reserve account for a component, may, under some circumstances, require the association to (1) defer major maintenance, repair, or replacement, (2) increase future reserve contributions, (3) borrow funds to pay for major maintenance, repair, or replacement, or (4) impose special assessments for the cost of major maintenance, repair, or replacement." Association Reserves and its employees have no ownership, management, or other business relationships with the client other than this Reserve Study engagement. Jim Talaga, company President, is a credentialed Reserve Specialist (#66). All work done by Association Reserves WA, LLC is performed under his responsible charge and is performed in accordance with National Reserve Study Standards (NRSS). There are no material issues to our knowledge that have not been disclosed to the client that would cause a distortion of the client's situation. Per NRSS, information provided by official representative(s) of the client, vendors, and suppliers regarding financial details, component physical details and/or quantities, or historical issues/conditions will be deemed reliable, and is not intended to be used for the purpose of any type of audit, quality/forensic analysis, or background checks of historical records. As such, information provided to us has not been audited or independently verified. Estimates for interest and inflation have been included, because including such estimates are more accurate than ignoring them completely. When we are hired to prepare Update reports, the client is considered to have deemed those previously developed component quantities as accurate and reliable, whether established by our firm or other individuals/firms (unless specifically mentioned in our Site Inspection Notes). During inspections our company standard is to establish measurements within 5% accuracy, and our scope includes visual inspection of accessible areas and components and does not include any destructive or other testing. Our work is done only for budget purposes. Uses or expectations outside our expertise and scope of work include, but are not limited to: project audit, quality inspection, and the identification of construction defects, hazardous materials, or dangerous conditions. Identifying hidden issues such as but not limited to, plumbing or electrical problems are also outside our scope of work. Our estimates assume proper original installation & construction, adherence to recommended preventive maintenance, a stable economic environment, and do not consider frequency or severity of natural disasters. Our opinions of component Useful Life, Remaining Useful Life, and current or future cost estimates are not a warranty or guarantee of actual costs or timing. Because the physical and financial status of the property, legislation, the economy, weather, owner expectations, and usage are all in a continual state of change over which we have no control, we do not expect that the events projected in this document will all occur exactly as planned. This Reserve Study is by nature a "one-year" document in need of being updated annually so that more accurate estimates can be incorporated. It is only because a long-term perspective improves the accuracy of near-term planning that this Report projects expenses into the future. We fully expect a number of adjustments will be necessary through the interim years to the cost and timing of expense projections and the funding necessary to prepare for those estimated expenses. In this engagement our compensation is not contingent upon our conclusions, and our liability in any matter involving this Reserve Study is limited to our fee for services rendered.



Terms and Definitions

BTU	British Thermal Unit (a standard unit of energy)
DIA	Diameter
GSF	Gross Square Feet (area). Equivalent to Square Feet
GSY	Gross Square Yards (area). Equivalent to Square Yards
HP	Horsepower
LF	Linear Feet (length)
UOM	Unit of Measure
Effective Age	The difference between Useful Life and Remaining Useful Life. Note that this is not necessarily equivalent to the chronological age of the component.
Fully Funded Balance (FFB)	The value of the deterioration of the Reserve Components. This is the fraction of life "used up" of each component multiplied by its estimated Current Replacement. While calculated for each component, it is summed together for an association total.
Inflation	Cost factors are adjusted for inflation at the rate defined in the Executive Summary and compounded annually. These increasing costs can be seen as you follow the recurring cycles of a component on the "30-yr Income/Expense Detail" table.
Interest	Interest earnings on Reserve Funds are calculated using the average balance for the year (taking into account income and expenses through the year) and compounded monthly using the rate defined in the Executive Summary. Annual interest earning assumption appears in the Executive Summary.
Percent Funded	The ratio, at a particular point in time (the first day of the Fiscal Year), of the actual (or projected) Reserve Balance to the Fully Funded Balance, expressed as a percentage.
Remaining Useful Life (RUL)	The estimated time, in years, that a common area component can be expected to continue to serve its intended function.
Useful Life (UL)	The estimated time, in years, that a common area component can be expected to serve its intended function.



Component Details

The primary purpose of the Component Details appendix is to provide the reader with the basis of our funding assumptions resulting from our research and analysis. The information presented here represents a wide range of components that were observed and measured against National Reserve Study Standards to determine if they meet the criteria for reserve funding: 1) The project is the Association's present obligation. 2) The need and schedule of a project can be reasonably anticipated. 3) The total cost of the project is material, can be estimated and includes all direct & related costs. Not all your components may have been found appropriate for reserve funding. In our judgment, the components meeting the above three criteria are shown with the Useful Life (how often the project is expected to occur), Remaining Useful Life (when the next instance of the expense will be) and representative market cost range termed "Best Cost" and "Worst Cost". There are many factors that can result in a wide variety of potential costs, and we have attempted to present the cost range in which your actual expense will occur. Where no Useful Life, Remaining Useful Life, or pricing exists, the component was deemed inappropriate for Reserve Funding.

Site & Grounds

Comp #: 100 Concrete - Maintain/Repair**Approx Quantity: 1 Unfunded****Location:** The community sidewalks, walkways, patios, and curbs.**Funded?:** Yes.**History:** None known.**Comments:** The concrete appeared with several areas of significant damage including cracking, shifting, and trip hazards. Some curbing was noted to be cracked and deteriorating.

Due to the general age and eventual wear, we suggest a periodic funding allowance to supplement the operating budget for periodic large-scale repair/replacements as reflected below.

As routine maintenance utilizing operating funds, inspect regularly, and pressure wash for appearance. Repair promptly as needed to prevent water penetrating into the base, which can cause further damage. Factors affecting the quality of the concrete include the preparation of the underlying soil and drainage, thickness and strength of the concrete used, steel reinforcement (none likely), and the amount and weight of vehicle traffic.

Resources:<https://mrsc.org/explore-topics/public-works/streets,-road-and-sidewalks/sidewalk-construction-maintenance-and-repair><https://www.sakrete.com/blog/post/5-key-considerations-for-small-concrete-repairs/><http://www.concretenetwork.com/cold-weather-concrete/weather.html>**Useful Life:**
10 years**Remaining Life:**
0 years**Lower Estimate:**

\$ 6,300

Higher Estimate:

\$ 7,700

Cost Source: Budget Allowance

Comp #: 106 Gravel Paths - Refurbish

Approx Quantity: 1 Unfunded

Location: Scattered throughout the community.

Funded?: No. Costs are best handled with operating funds.

History: None known.

Comments: The gravel areas observed were noted with a fair coverage but appear to have significant vegetation growth. No major depressions observed. Profile and drainage appear adequate. We recommend replenishing the gravel utilizing operating funds. Track the actual history and costs, and if warranted, funding can be added to this component in future reserve studies.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 120 Shared Asphalt - Resurface**Approx Quantity: 4,500 GSF, Asphalt****Location:** The community entrances of Garden Grove and Kiley Court.**Funded?:** Yes. Garden Grove is reported to be responsible for 69.8% of the total costs.**History:** Installed 1999.**Comments:** This component represents the shared asphalt with Kiley Court at the community entrance. It was reported Garden Grove is responsible for 69.8% of the total costs for maintaining, repairing, and replacing this asphalt.

The asphalt did not show evidence of significant damage, instability, or failure such as cracking, excessive wear, alligator cracking, etc.

The useful life below assumes regular repairs and seal coating (see component #121). The lack of repairs and seal coating can greatly decrease the asphalt's useful life. Resurfacing is typically one of the larger expense items in a reserve study. When the need to resurface is becoming apparent, consult with a geotechnical engineer for recommendations, specifications/scope of work, and project oversight.

As routine maintenance, keep surfaces clean and free of debris, ensure that drains are free flowing, repair cracks, and clean oil stains promptly. Assuming proactive maintenance, plan to resurface at roughly the time frame below.

Note: The photograph may not be representative of the actual component.

Resources:

Pavement Surface Condition Field Rating Manual for Asphalt Pavement:

<https://www.wsdot.wa.gov/publications/manuals/fulltext/m0000/AsphaltPavements.pdf>

Washington Asphalt Pavement Association: <http://www.asphaltwa.com/>

Useful Life:

35 years

Remaining Life:

8 years

**Lower Estimate:**

\$ 10,900

Higher Estimate:

\$ 13,300

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 121 Shared Asphalt - Repair & Seal**Approx Quantity: 4,500 GSF, Asphalt****Location:** The community entrances of Garden Grove and Kiley Court.**Funded?:** Yes. Costs are best handled with operating funds.**History:** Stripped 2019; sealed 2016; sealed 2010; sealed 2005.**Comments:** This component represents the shared asphalt with Kiley Court at the community entrance. It was reported Garden Grove is responsible for 69.8% of the total costs for maintaining, repairing, and replacing this asphalt. The costs for resealing this area of asphalt are projected to be below the minimal requirement for reserves funding (1% of the annual operating budget). We recommend the Association complete the project utilizing operating funds.

The State of Washington Department of Transportation (WSDOT) recommends regular cycles of seal coating, along with needed repairs, for the long-term care of asphalt paving with low traffic and low speed to extend the useful life. The primary reason to seal coat asphalt pavement is to protect the pavement from the deteriorating effects of sun and water. When asphalt pavement is exposed, the asphalt oxidizes or hardens, and this causes the pavement to become increasingly brittle. As a result, the pavement will become more likely to crack, as it is unable to bend and flex when subjected to traffic (weight) and temperature changes (thermal expansion and contraction). A seal coat combats this situation by providing a waterproof membrane, which not only slows down the oxidation process, but also helps the pavement shed water. Seal coating also provides uniform appearance, and conceals the inevitable patching and repairs which accumulate over time, ultimately extending the useful life of asphalt before more costly resurfacing is needed (see component #120).

Repairing asphalt before seal coating is imperative. Surface preparation and dry weather during and following application is key to lasting performance.


Note: The photograph may not be representative of the actual component.

Resources:Asphalt Pavement Maintenance Best Practices Handbook: <http://www.cee.mtu.edu/~balkire/CE5403/AsphaltPaveMaint.pdf>Asphalt Seal Coat Treatments General Overview: <https://www.wsdot.wa.gov/research/reports/fullreports/136.1.pdf>Other: <http://www.pavementinteractive.org/article/bituminous-surface-treatments/>**Useful Life:**

5 years

Remaining Life:

0 years

**Lower Estimate:**

\$ 1,800

Higher Estimate:

\$ 2,200

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 122 1999 Asphalt - Resurface**Approx Quantity: 104,170 GSF, Asphalt****Location:** The community roadways and parking areas.**Funded?:** Yes.**History:** Installed 1999.**Comments:** This component represents resurfacing the community asphalt roadways and parking areas.

The original asphalt roadway was observed with many areas of cracking and previous repairs. Some of the patches and repairs were observed with failing crack fill.

Useful Life:

35 years

Remaining Life:

8 years

**Lower Estimate:**

\$ 361,000

Higher Estimate:

\$ 441,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 123 2019 Parking Area - Resurface**Approx Quantity: 2,450 GSF, Asphalt****Location:** The southeast area of the community behind the garages.**Funded?:** Yes.**History:** Installed 2019.**Comments:** This component represents resurfacing the parking areas that were installed in 2019.

This asphalt area did not show evidence of significant damage, instability, or failure.

Useful Life:

35 years

Remaining Life:

28 years

**Lower Estimate:**

\$ 8,550

Higher Estimate:

\$ 10,500

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 125 Asphalt - Repair & Seal**Approx Quantity: 106,620 GSF, Asphalt****Location:** The community roadways and parking areas, including the southeast area behind the garages.**Funded?:** Yes.**History:** Crack fill & seal coating in 2025 Northwest Infrastructure - \$14,028 & \$35,966; Repairs in 2024 Northwest Infrastructure - \$9,387; Speedbumps added & striped 2019; sealed 2016; sealed 2010; sealed 2005; installed 1999.**Comments:** This component represents maintaining, repairing, and sealing the community asphalt roadways and parking areas.

It was reported that there was a project in 2024 and then 2 projects in 2025, the surface of the asphalt varied throughout the community. The cost of incomplete projects typically is greater than planning for a total replacement.

Useful Life:

5 years

Remaining Life:

4 years

**Lower Estimate:**

\$ 53,500


Higher Estimate:

\$ 65,300

Cost Source: Inflated Client Cost History - Northwest Infrastructure

Comp #: 135 Metal Gate - Repair/Replace**Approx Quantity: 1 Assembly****Location:** Adjacent to the storm pond on the south community perimeter.**Funded?:** No. The useful life is not predictable.**History:** None known.**Comments:** The metal gate appeared to be functional during our site review. No damage or corrosion was observed.

As routine maintenance, inspect the gate regularly for any damage, and repair as needed. Apply a rust inhibitor if corrosion is found. Clean by wiping down for appearance, change lock cylinders, and lubricate the hinges.

Useful Life:**Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 137 Emergency Access Gate - Replace**Approx Quantity: 30 LF****Location:** The southwest area of the community.**Funded?:** No. The useful life is not predictable.**History:** Replaced 2022; installed 1999.**Comments:** This component represents the emergency access gate in the southwest area of the community adjacent to the stormwater pond. Although it was reported to have been replaced in 2022, due to its minimal use we are unable to predict an estimated remaining useful life. Track the actual history and adjust future reserve studies accordingly.**Useful Life:****Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 140 Perimeter Fences - Replace**Approx Quantity: 965 LF, Wood****Location:** The west and south community perimeters.**Funded?:** Yes.**History:** Repairs complete in 2025 by Northwest Infrastructure - \$7,573**Comments:** The wood fence did not show evidence of significant damage, instability, or failure. Wood board fence is approximately 6-foot tall and painted, so we were unable to confirm if the posts and rails are a pressure treated material.

Plan to replace the fence at roughly the time frame below. Typical failures occur from deterioration through the end grains and contact with the ground and surrounding landscape.

As routine maintenance, inspect regularly for any damage, and repair as needed. Avoid unnecessary contact with the ground, sprinkler patterns, and surrounding vegetation. Regular cycles of stain/paint will help to maintain appearance. Painting or staining the fence has a higher overall life cycle cost but may extend life in addition to an aesthetic benefit.

Useful Life:

20 years

Remaining Life:

10 years

**Lower Estimate:**

\$ 58,100

Higher Estimate:

\$ 71,100

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 141 East Fence - Repair/Replace

Approx Quantity: 310 LF, Wood

Location: The shared east perimeter with Kiley Court.

Funded?: No. Reported to be the responsibility of Kiley Court.

History: None known.

Comments: This component represents the wood fence along the shared east perimeter with Kiley Court. It was reported Kiley Court is responsible for maintaining, repairing, and replacing this fence.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 142 Yard Fencing - Replace

Approx Quantity: 1 Allowance

Location: The perimeters of individual yards/lots.

Funded?: Yes.

History: Repairs in 2025 by Northwest Infrastructure - \$8,961

Comments: This component represents the wood fencing along the perimeters of individual lots/yards. We have provided a cyclical allowance below for localized replacement of this fencing as it is unlikely simultaneous replacement will be required. It was reported that several of these structures were repaired and painted in 2025

Track the actual history and costs and adjust future reserve studies accordingly.

Useful Life:

5 years

Remaining Life:

4 years



Lower Estimate:

\$ 49,100

Higher Estimate:

\$ 60,100

Cost Source: Budget Allowance

Comp #: 143 Storm Pond Fence - Replace**Approx Quantity: 445 LF, Wood****Location:** The stormwater pond perimeters.**Funded?:** Yes.**History:** None known.

Comments: This component represents repair/replacement of the wood stormwater pond fence. Some damage was observed of the storm pond fence. Loose nails and some warped boards were observed. The fencing had some moss growth. The upper and lower ends in several areas of the fencing were noted with decay.

Useful Life:

20 years

Remaining Life:

0 years

**Lower Estimate:**

\$ 28,400

Higher Estimate:

\$ 34,800

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 145 Vinyl Fence – Replace**Approx Quantity: 1,930 LF****Location:** The perimeters of the Native Growth Protection Area.**Funded?:** Yes.**History:** Installed 1999.

Comments: The double rail fence did not show evidence of significant damage, instability, or failure. Some aging was apparent.

Plan to replace the fence at roughly the time frame below. As routine maintenance, clean the fence, and inspect it regularly for any damage. Repair as needed with operating funds.

Useful Life:

35 years

Remaining Life:

8 years

**Lower Estimate:**

\$ 89,600

Higher Estimate:

\$ 109,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 147 Garbage Enclosures - Repair/Replace

Approx Quantity: 4 LF, Wood

Location: Scattered throughout the community.

Funded?: Yes.

History: Replace 2024 ~\$25,327

Comments: The garbage enclosures did not show evidence of significant damage, instability, or failure. New enclosures were installed in 2024 with metal gate and 6' cedar fencing.

A general rotating funding allowance is factored below for repairs/replacement. Track history and actual expenses, and adjust accordingly in reserve study updates.

These garbage enclosures are subject to abuse. It is reasonable to expect repairs at relatively small intervals due to misuse, although it is difficult to predict the precise scope and timing of such repairs. We suggest at the next replacement to consider a more durable enclosure material such as steel posts and rails. By utilizing such materials, the enclosure can better withstand regular abuse, reduce repair costs, and increase its useful life. A less expensive option is to install concrete wheel stops (typically used at the front of parking spaces) to prevent the container or vehicles from impacting the enclosure.

Useful Life:
25 years

Remaining Life:
23 years



Lower Estimate:	\$ 24,200	Higher Estimate:	\$ 29,600
------------------------	------------------	-------------------------	------------------

Cost Source: Inflated Client Cost History

Comp #: 160 Pole Lights - Replace**Approx Quantity: 10 Assemblies, Metal****Location:** Scattered throughout the community.**Funded?:** Yes.**History:** None known.**Comments:** The pole lights were observed during daylight hours and are assumed to be functional. No problems were reported.

Our recommendation is to plan for a large-scale replacement at roughly the time frame below, for both cost efficiency and consistent quality/appearance throughout the association. There are a variety of materials and styles available and a general mid-range funding allowance is projected below. Cost can vary significantly depending on the quality of the light pole chosen.


As routine maintenance, inspect, repair, and change bulbs as needed. Where possible, take precautions to limit damage from landscaping equipment.

Useful Life:

40 years

Remaining Life:

13 years

**Lower Estimate:**

\$ 11,900

Higher Estimate:

\$ 14,500

Cost Source: Budget Allowance

Comp #: 165 Grounds Lighting - Replace**Approx Quantity: 5 Fixtures, Assorted****Location:** Along the front sidewalk.**Funded?:** No. Costs are best handled with operating funds.**History:** None known.**Comments:** We did not view the ground lighting during our inspection. The ground lights were observed during daylight hours and are assumed to be functional. No problems were reported.

As routine maintenance, inspect, and repair/change bulbs, as needed. Some local replacement may be needed from time to time - use general operating funds.

Useful Life:**Remaining Life:**

No Photo Available

Lower Estimate:**Higher Estimate:****Cost Source:**

Comp #: 170 Landscape - Refurbish

Approx Quantity: 1 Unfunded

Location: Turf, shrubs, etc. throughout the community.

Funded?: No. Annual costs best handled through operating budget

History: None known.

Comments: The landscape is generally healthy and mature. Some plantings near the building appear to be encroaching on building clearance and should be trimmed away.

Landscape maintenance is currently funded through the operating budget. As associations age, many find the need or desire for large-scale refurbishment projects not covered within the maintenance contract, and they allocate funds within reserves. These types of projects can include bed renovations, major replanting, large-scale bark or mulch replacements, turf renovations, drainage improvements, irrigation system extensions/replacement, etc.

Walk the landscaped areas each year with the community's landscape contractor, and perhaps a landscape architect, to assess the overall health, function, and future needs of maintenance and refurbish to determine if supplemental reserve funding should be planned.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 172 Native Growth Area - Maintain

Approx Quantity: 1 Unfunded

Location: The northwest and east areas of the community.

Funded?: No. No basis for reserve funding

History: None known.

Comments: Native growth areas are typically a low maintenance item, as they are designed to be left permanently undisturbed in a substantially natural state.

There is no basis for reserve funding at this time, but can be incorporated into future reserve study updates if funding basis emerges.

Comply with any and all governmental regulations regarding these areas. Activities that are allowed in a native growth area are very limited, but may include maintenance of the drainage basin, and removal of trees deemed hazardous by the local jurisdiction.

Washington State's Growth Management Act (GMA) was established by the state legislature in 1990. The GMA requires the State and local governments to identify and protect critical areas and natural resource lands. Native growth areas are typically either recorded as an easement, or as a separate tract/parcel of land.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 173 Trees - Trim/Remove & Replace

Approx Quantity: 1 Unfunded


Location: Throughout the community.

Funded?: No. Costs are best handled with operating funds.

History: Tree pruning and selective removal in 2025 by Hovey Tree Services - \$27,552

Comments: There were no specific problems with the trees observed or reported at this time.

This component may be utilized for larger tree removal/trimming projects which do not occur on an annual basis. If the community has not already done so, consult with a qualified arborist to assess the current plantings and to prepare a long term plan for the care and management of the community's trees, balancing aesthetics with the protection of the association's assets. Tree roots can be damaging to walkways, irrigation, underground utilities, and building structures. Track actual expenses, and adjust accordingly in reserve study updates.



Useful Life:

Remaining Life:

Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 175 Irrigation System - Repair/Replace

Approx Quantity: 1 Hidden System

Location: Heads, lines, timers, etc throughout the community.

Funded?: No. No basis for reserve funding

History: None known.

Comments: Our visual observation of the irrigation system was limited, as the majority of system components are below grade. There were no reports of repairs or problems. At the time of this study, no information (plans and/or specifications) was provided to us regarding the extent of the irrigation system.

There are no predictable large-scale costs at this time. Have your landscaper or irrigation specialist periodically unearth sections to check lines for any damage or deterioration. PVC can eventually become brittle and leak (typically not before the 40 year mark of life).

As routine maintenance, inspect, test, and repair the system, as needed, as part of the operating budget. Follow proper winterization and spring startup procedures. If properly installed and bedded without defect, the lines could last for many years. Controls for the system can vary greatly in number, cost, and life expectancy - typically each controller is less than \$500. Other elements (i.e. sprinkler heads, valves) within this system are generally lower cost, and have a failure rate that is difficult to predict. These elements are better suited to be handled with operating funds, not reserves.



Useful Life:

Remaining Life:

Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 182 Drainage & Stormwater - Maintain

Approx Quantity: 1 Unfunded

Location: Catch basins, drains, etc. throughout the community.

Funded?: No. The useful life is not predictable.

History: None known.

Comments: An analysis of the drainage system is beyond the scope of a reserve study, as the vast majority of the drainage system is located below ground. Our observations were very limited to catch basin areas. No problems were reported to us.

There is no predictable large-scale repair/replacement at this time. Local repairs should be performed as part of general maintenance. If problems become known from a professional evaluation, funding can be included in future reserve studies.

As routine maintenance, inspect regularly, and keep drains/grates free of debris to ensure water drains as intended. Maintenance schedules on stormwater systems depend on the condition of the system itself, and the amount of sediment and debris moving around on site. Stormwater inspections usually consist of inspecting the catch basins and manholes, and ensuring vaults and control structures are properly functioning. Evaluation of the drainage system can include the visual review of the interior drain lines with the use of a miniature remote camera. Clean out the drain lines and basins as often as needed in order to prevent decreased drainage capacity. Repair as needed. The responsibility of keeping the stormwater system in good working order falls on the association.

Resources:

City of Everett Surface & Stormwater: <https://www.everettwa.gov/668/Surface-Stormwater>

Snohomish County Surface Water Management: <https://snohomishcountywa.gov/208/Surface-Water-Management>

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 183 Drainage & Stormwater - CB Cleaning

Approx Quantity: 14 Catch Basins

Location: Catch basins, drains, etc. throughout the community.

Funded?: Yes.

History: None known.

Comments: An analysis of the drainage system is beyond the scope of a reserve study, as the vast majority of the drainage system is located below ground. Our observations were very limited to catch basin areas. No problems were reported to us. We have included funding for cycles of catch basin cleaning. These private systems are the responsibility of the Association to clean and maintain. We have not been provided any information on project history.

Useful Life:
3 years

Remaining Life:
0 years



Lower Estimate:	\$ 3,600	Higher Estimate:	\$ 4,400
------------------------	----------	-------------------------	----------

Cost Source: Budget Allowance



Comp #: 185 Stormwater Ponds - Refurbish

Approx Quantity: 2 Ponds

Location: The community entrance and the southwest corner of the community.

Funded?: No. Costs are best handled with operating funds.

History: None known.

Comments: The large stormwater pond was observed with excessive vegetation. Ongoing maintenance is assumed. We have not been informed if this is a detention pond or retention pond and no information provided on wet and dry cycles of this structure.

The state Department of Ecology and local (i.e. county or city) stormwater resources have standards for maintaining and constructing or reconstructing the pond(s) to the engineer's design parameters. Sediment must be removed when the governing authority has determined a maximum reduction in pond volume. The pond may also be tested for any contaminants, and acceptable turbidity level. Timing is difficult to predict, but in our experience and research, it may be in the 15-year range. Regular maintenance and inspection are keys to extending the useful life. Have the pond periodically assessed by a professional engineer, in addition to the overseeing governmental authority.

Costs for large-scale non-routine maintenance such as sediment removal and structural repairs can vary widely depending upon a number of factors, including but not limited to contractor selection and mobilization fees, engineering and oversight, disposal options for excavated material per pond testing, liner type, etc. A general budget allowance range is provided below - work with the governing authority and local contractor(s) to better define.

Resource:

Municipal Research and Services Center - Washington State Stormwater Manuals: <http://mrsc.org/Home/Explore-Topics/Environment/Water-Topics/Storm-and-Surface-Water-Management/Stormwater-Detention-Facility-Maintenance.aspx>

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 200 Community Monument - Repair/Replace

Approx Quantity: 1 Structure, Wood/Stone

Location: The community entrance.

Funded?: No. Costs are best handled with operating funds.

History: Installed 1999.

Comments: The community monument did not show evidence of significant damage, instability, or failure. This structure is built of stone wall and pillars with a wood framed composite roof and sand blasted sign panel.

Costs to refurbish or replace the wood sign itself are unlikely to reach the minimal requirement for reserves funding. Paint and replace/refurbish the wood sign utilizing operating funds. Stone is a durable material that should require minimal maintenance. Replace the roof with operating funds or simultaneously as the buildings. Replace individual light fixtures with operating funds or as part of a larger project with the buildings.

Inspect periodically, repair, clean, and touch up for appearance, as needed, using operating funds.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 205 Mailboxes - Replace**Approx Quantity: 7 Clusters****Location:** The community entrance.**Funded?:** Yes.**History:** None known.

Comments: The mailboxes did not show evidence of significant damage, instability or failure. We did not observe the function of the individual boxes. The metal clusters are flush inset into a wood framed structure and are protected from the weather elements and vandalism.

In our experience, it is best to plan for total replacement at roughly the time frame below due to constant usage and wear over time.

As routine maintenance, inspect regularly, clean by wiping down for appearance, change lock cylinders, lubricate hinges, and repair as needed with operating funds.

Useful Life:

30 years

Remaining Life:

21 years

**Lower Estimate:**

\$ 19,500

Higher Estimate:

\$ 23,900

Cost Source: Budget Allowance

Comp #: 206 Mailbox Kiosk - Repair/Replace**Approx Quantity: 1 Structures, Stone/Wood****Location:** The community entrance.**Funded?:** No. Costs are best handled with operating funds.**History:** Constructed 1999.

Comments: This component represents maintaining, repairing, and replacing the mailbox kiosk. Complete any necessary repair projects, including siding repairs and painting, with operating funds. Replace the roof with operating funds or simultaneously as the buildings. Track the actual history and costs, and adjust future reserve studies accordingly.

Useful Life:**Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 220 Sport Court - Resurface**Approx Quantity: 1,125 GSF / Concrete****Location:** Behind building CC (#11501).**Funded?:** Yes.**History:** Installed 1999.**Comments:** The sport court surface was observed with some local cracks noted, but not significant or widespread at this time.

Plan for an eventual total resurface. Repair the base as needed at that time to ensure positive drainage. As routine maintenance, inspect regularly, clean as needed, and fill cracks with operating funds.

Useful Life:

45 years

Remaining Life:

18 years

**Lower Estimate:**

\$ 25,100

Higher Estimate:

\$ 30,700

Cost Source: Budget Allowance

Comp #: 222 Basketball Hoops - Replace**Approx Quantity: 2 Assemblies****Location:** The sport court.**Funded?:** No. Costs are best handled with operating funds.**History:** None known.**Comments:** The basketball hoop assemblies did not show evidence of significant damage, instability, or failure. Some general aging apparent. The backboard was noted to be grimy and the net was discolored from aging.

Inspect regularly and complete any necessary repairs or replacement with operating funds. Track history and expenses, and if warranted, funding can be added to this component in future reports.

Useful Life:**Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 223 Volleyball Assembly - Replace

Approx Quantity: 2 Poles

Location: The sport court.

Funded?: No. The useful life is not predictable.

History: None known.

Comments: The volleyball assembly did not show evidence of significant damage, instability, or failure. The net was not in service during our site visit.

Inspect regularly and complete any necessary repairs or replacement with operating funds. Track history and expenses, and if warranted, funding can be added to this component in future reports.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Building Exteriors

Comp #: 500 Bldgs BB & DD Roofs - Replace**Approx Quantity: 19,990 GSF / Comp Shingle****Location:** The rooftops of buildings BB and DD.**Funded?:** Yes.**History:** Replaced 2019 Four Seasons; installed 1999.**Comments:** This component represents repair/replacement of the rooftops of buildings BB and DD which were reported to have been replaced in 2019.

The new roofs have ventilation (the lack of which can greatly reduce the roof's useful life) at the eave and ridge. Eave venting consisted of circular holes in blocking between the rafters. Ridge venting appeared to be provided by continuous ridge vents, gable end louvers, roof jacks. Portions of roof flashing were visible at the rake, headwall, sidewall, and valleys. Diverter (kick-out) flashing was observed. Gutters blocked the view of the eaves, so eave flashing was not confirmed. Debris and moss were not observed on the roof surface. A reserve study conducts a limited visual review for budget purposes, and many of the critical waterproofing and ventilation items of the roof are not readily viewable. For a full evaluation have a professional roof consultant/contractor perform a thorough up-close survey of your entire roof system, including attic inspection (if any).

It is assumed future replaced roofs will have similar features.

As routine maintenance, many manufacturers recommend inspections at least twice annually (once in the fall before the rainy season, and again in the spring), and after large storm events. Promptly replace any damaged/missing sections and complete any other repairs needed to ensure the waterproof integrity of the roof. Keep the roof surface, gutters, and downspouts clear and free of moss and/or debris.

At the time of re-roofing, we recommend that you hire a professional consultant to evaluate the existing roof, specify the new roof materials/design, and provide installation oversight. We recommend that all associations hire qualified consultants whenever they are considering having work performed on any building envelope (waterproofing) components including the roof, walls, windows, decks, exterior painting, and caulking/sealant.


Note: The photograph may not be representative of the actual component.

Resources:National Roofing Contractors Association (NRCA) <http://www.nrca.net/>.Asphalt Roofing Manufacturers Association (ARMA) <http://www.asphaltroofing.org/>Roof Consultant Institute (RCI) <http://www.rci-online.org/>Western States Roofing Contractors Association (WSRCA) <http://www.wsrca.com/>**Useful Life:**

25 years

Remaining Life:

18 years

**Lower Estimate:**

\$ 185,000

Higher Estimate:

\$ 226,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 501 Bldg Y Roof - Replace**Approx Quantity: 6,060 GSF / Comp Shingle****Location:** The rooftop of building Y.**Funded?:** Yes.**History:** Replaced 2021 Four Seasons ~\$31,600; installed 1999.**Comments:** This component represents repair/replacement of the rooftop of building Y. It was reported this rooftop was replaced in 2021.

Note: The photograph may not be representative of the actual component.

Useful Life:

25 years

Remaining Life:

20 years

**Lower Estimate:**

\$ 56,200

Higher Estimate:

\$ 68,700

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 502 Bldgs O & AA Roofs - Replace**Approx Quantity: 14,760 GSF / Comp Shingle****Location:** The rooftops of buildings O, and AA.**Funded?:** Yes.**History:** Replaced 2022 Four Seasons; installed 1999.**Comments:** This component represents repair/replacement of the rooftops of buildings O, and AA. It was reported these rooftops were replaced in 2022.

Note: The photograph may not be representative of the actual component.

Useful Life:

25 years

Remaining Life:

21 years

**Lower Estimate:**

\$ 137,000

Higher Estimate:

\$ 167,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 503 Bldgs B & D Roof - Replace**Approx Quantity: 7,630 GSF / Comp Shingle****Location:** The rooftops of buildings B & D**Funded?:** Yes.**History:** Replaced 2023 Four Seasons ~\$51K**Comments:** This component represents repair/replacement of the rooftops of buildings B and D. It was reported these rooftops were replaced in 2023.

Note: The photograph may not be representative of the actual component.

Useful Life:

25 years

Remaining Life:

22 years

**Lower Estimate:**

\$ 90,900

Higher Estimate:

\$ 111,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 504 Roofs (23) - Replace**Approx Quantity: 128,900 GSF / Comp Shingle****Location:** (23) building rooftops: A,C,E, F, G,J,K,N,M,L,I,H,V,U,T,S,Q,R,P,Z,W,X,CC (excludes BB, DD, Y, O, AA, B & D in separate components)**Funded?:** Yes.**History:** Replaced 2024 ~\$660K**Comments:** This component represents replacement of 1/4 of the remaining residential roofs to be replaced in 2024.

Note: The photograph may not be representative of the actual component.

Useful Life:

25 years

Remaining Life:

23 years

**Lower Estimate:**

\$ 1,190,000

Higher Estimate:

\$ 1,460,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 507 Garage Roofs - Replace

Location: The garage rooftops.

Funded?: Yes.

History: Installed 1999.

Comments: This component represents replacement of the garage roofs. We have set this component for this project to occur in 2027.

Approx Quantity: 7,580 GSF / Comp Shingle

Note: The photograph may not be representative of the actual component.

Useful Life:
20 years

Remaining Life:
0 years



Lower Estimate:	\$ 70,300	Higher Estimate:	\$ 85,900
------------------------	-----------	-------------------------	-----------

Cost Source: Budget Allowance



Comp #: 512 Bldg O Skylights - Replace

Approx Quantity: 4 Fixtures

Location: The rooftop of building O.

Funded?: No. Costs are best handled with operating funds.

History: None known.

Comments: This component represents repair/replacement of the skylights for building O which are assumed to have been replaced during the 2022 roof replacement project.

Observation of the skylights revealed curb mounted skylights with visible portions of flashing. No current water leaks or other problems were reported by the association.

Estimated costs of replacing the skylights does not meet the minimal threshold requirements. Replace the skylights utilizing operating funds or, for best practice and costs efficiencies, simultaneously as the roof.

Inspect the skylights as part of the ongoing roof inspections, and repair as needed to maintain the waterproof integrity. Review the skylight conditions with a consultant or roof contractor while evaluating the roofing project.

Note: The photograph may not be representative of the actual component.

Resource:

<https://www.veluxusa.com/help/installation-help/service-and-maintenance>

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 513 Skylights - Replace**Approx Quantity: 35 Fixtures****Location:** Building rooftops**Funded?:** Yes.**History:** Original**Comments:** This component represents replacement of 1/4 of the remaining skylights which are assumed to have been repaired or replaced during the roof replacements.

Note: The photograph may not be representative of the actual component.

Useful Life:

25 years

Remaining Life:

23 years

**Lower Estimate:**

\$ 29,900

Higher Estimate:

\$ 36,500

Cost Source: Budget Allowance

Comp #: 517 Gutters & Downspouts - Replace**Approx Quantity: 11,300 LF, Metal****Location:** The building and garage perimeters.**Funded?:** Yes.**History:** Installed 1999.**Comments:** Based on our limited visual inspection, the metal gutters and downspouts appeared to be functional.

We recommend planning for a total replacement of the gutters and downspouts at the same intervals as the roof replacement for cost efficiency. Evaluate these components at the time of the project to determine if replacement or re-use is the better value.

As routine maintenance, inspect regularly, and keep gutters and downspouts free of debris.

Useful Life:

40 years

Remaining Life:

13 years

**Lower Estimate:**

\$ 158,000

Higher Estimate:

\$ 193,000

Cost Source: Budget Allowance

Comp #: 520 Vinyl Siding - Exterior Renovation

Approx Quantity: 124,000 GSF

Location: The exterior walls, underlying waterproofing components, and structural components.

Funded?: Yes.

History: Installed 1999.

Comments: The vinyl siding was a horizontal clapboard and shingle style. The siding did not show evidence of significant damage, instability, or failure. No view of the critical underlying waterproofing was available as part of our limited visual review.

Siding replacement may ultimately be needed due to the failure of the underlying waterproofing due to degradation over the decades, and/or the end of the useful life of the siding materials from general aging. Many factors influence the useful life, including exposure to (or protection from) wind driven rain, and the quality of the waterproofing and flashing beneath the siding. Evaluate the siding and the critical underlying waterproofing (typically building paper or house-wrap) more frequently as the remaining useful life approaches zero years. Adjust the remaining useful life as dictated by the evaluation. When practical, align with window replacement for cost efficiencies and building envelope integrity. Inspect annually and repair locally, as needed, using general maintenance funds.

Replacing the underlying waterproofing and flashing is projected to require replacement of the vinyl siding. Vinyl siding will typically fade over the years, and when replacing pieces it may be difficult to match the faded color.

Note: Rehabilitative construction projects with associated costs are equal to or greater than 5% of the assessed value of the units must comply with the requirements of RCW 64.55 <http://app.leg.wa.gov/rcw/default.aspx?cite=64.55>. These requirements include building enclosure design documents with waterproofing details by an architect or engineer, and independent oversight during construction to verify compliance with those details.

Project costs can vary depending upon materials chosen and the condition of the underlying structural framing when exposed. We recommend the Board conduct research well in advance in order to define the scope, timing, and costs; including a plan for some margin of contingency.

Useful Life:
40 years

Remaining Life:
13 years



Lower Estimate:

\$ 3,170,000

Higher Estimate:

\$ 3,880,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 521 Vinyl Siding - Clean & Inspect

Approx Quantity: 124,000 GSF

Location: The building surfaces.

Funded?: Yes.

History: Project completed in 2025 by Sparkle Wash - \$59,172

Comments: The vinyl siding was generally clean and free of damage. It was reported that the buildings were cleaned in July 2025.

It is best practice to clean vinyl siding every few years to remove contaminants that can reduce its service life, and to maintain appearance. This is also a good opportunity to have the exterior sealant inspected. We have projected the higher end of the cost range for cleaning to include sealant inspection at the same time as power washing. When washing, we advise not to use too high of pressure, and ensure spray angles do not allow water beneath the vinyl. Hand washing is also available, but is often more expensive.

Useful Life:
4 years

Remaining Life:
3 years



Lower Estimate:

\$ 54,900

Higher Estimate:

\$ 67,100

Cost Source: Inflated Client Cost History - Sparkle Wash

Comp #: 525 Stone Veneer - Maintain/Repair

Location: The exterior walls, underlying waterproofing components, and structural components.

Funded?: No. The useful life is not predictable.

History: Installed 1999.

Comments: Some stone veneer was used for cladding on small portions of the buildings. No cracked grout or broken stones were observed during our site visit. During our limited visual review, we are not able to view or evaluate the critical underlying waterproofing and flashings.

Approx Quantity: 1 Unfunded

Stone veneer is a relatively low maintenance item. Inspect periodically, and repair as needed using operating funds.

Many factors influence the useful life, including exposure to (or protection from) wind driven rain, the quality of the siding material, and the quality of the waterproofing and flashing beneath the siding. Almost all waterproofing systems will degrade over time (years or decades) as it ages.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 533 Exterior Surfaces - Caulk & Paint

Approx Quantity: 1 Allowance

Location: Trim, doors, etc. of the exterior paintable building surfaces.

Funded?: Yes.

History: Soffit repair and painting in 2025 by Northwest Infrastructure - \$28,289

Comments: The ends of several trim pieces were noted to have faded paint and damage. It was reported that the buildings soffits were repaired and repainted in 2025.

Typical Northwest paint cycles vary greatly depending upon many factors including the type of material painted, surface preparation, quality of the primer/paint/stain, application methods, weather conditions during the application process, moisture beneath the surface, and exposure to weather conditions. Repair areas, as needed, prior to painting/caulking. As routine maintenance, inspect regularly (including sealants), repair locally, and touch-up paint, as needed, using operating funds.

Proper sealant/caulking is critical to keeping water out of the walls, and preventing water damage. Incorrect installation of sealants is very common, and can greatly decrease its useful life. Inspect sealants (more frequently as they age) to determine if failing is occurring. Typical sealant problems include failure of the sealant to adhere to adjacent materials, and tearing/splitting of the sealant itself. As sealants age, and due to exposure to ultraviolet sunlight, they will dry out, harden, and lose their elastic ability. Remove and replace all sealants at the time sealant failure begins to appear. Proper cleaning, prep work, and installation technique (shape, size, tooling of joint) are critical for a long lasting sealant/caulking. Do not install sealant in locations that would block water drainage from behind the siding (e.g. at head flashings).

Resources:

American Coatings Association: <http://www.paint.org/>

Master Paint Institute: <http://www.paintinfo.com/>

Useful Life:
8 years

Remaining Life:
0 years



Lower Estimate:

\$ 99,000

Higher Estimate:

\$ 121,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 535 Windows - Replace**Approx Quantity: 930 Windows, Assorted****Location:** The exterior building walls.**Funded?:** No.**History:** Installed 1999.

Comments: We have previously included funding for windows, sliders, and entry door and have removed funding for the purpose of the 2026 Reserve Study based on a responsibility matrix that was provided to us. This matrix was drafted in 2012 by Condo Law Group and identifies doors and windows as limited common elements under section 4.1.4 of the declaration but also identifies that the owners are responsible for the cost under sections 11.5.1, 11.6.4, & 12.5.

Additional details of the responsibilities can be found within that document.

Useful Life:**Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 536 Sliders - Replace**Approx Quantity: 134 Doors****Location:** The exterior building walls.**Funded?:** No.**History:** Installed 1999.

Comments: We have previously included funding for windows, sliders, and entry door and have removed funding for the purpose of the 2026 Reserve Study based on a responsibility matrix that was provided to us. This matrix was drafted in 2012 by Condo Law Group and identifies doors and windows as limited common elements under section 4.1.4 of the declaration but also identifies that the owners are responsible for the cost under sections 11.5.1, 11.6.4, & 12.5.

Additional details of the responsibilities can be found within that document.

Useful Life:**Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 540 Exterior Doors - Repair/Replace

Approx Quantity: 190 Assemblies

Location: The exterior building walls.

Funded?: No. No predictable large-scale repair or replacement projected

History: None known.

Comments: We have previously included funding for windows, sliders, and entry door and have removed funding for the purpose of the 2026 Reserve Study based on a responsibility matrix that was provided to us. This matrix was drafted in 2012 by Condo Law Group and identifies doors and windows as limited common elements under section 4.1.4 of the declaration but also identifies that the owners are responsible for the cost under sections 11.5.1, 11.6.4, & 12.5.

Additional details of the responsibilities can be found within that document.

Useful Life:

Remaining Life:



Lower Estimate: **Higher Estimate:**
Cost Source:

Comp #: 541 Traffic Coated Decks - Resurface

Approx Quantity: 5,405 GSF, Elastomeric

Location: Select units.

Funded?: Yes. The useful life is not predictable.

History: None known.

Comments: Direct access to a deck was not available during our site visit and viewing was limited from the ground surface. It was previously reported that the surface of the deck appeared to be a urethane/elastomeric coating. The drip edge of the deck was open. A vertical portion of drip edge flashing was observed. We were unable to view if the coating was turned up the wall a few inches beneath the cladding to prevent water from entering behind the siding. We were unable to determine if the threshold of the door was raised slightly above the deck surface to allow proper flashing. Venting on the underside of the deck, at the soffit below, was observed. Venting is a good practice as it can reduce problems from condensation. The railing connections did not attach through the deck surface. The fewer penetrations through the waterproof surface, the fewer opportunities there are for water penetration.

Re-application of the topcoat periodically is required to maintain its waterproof integrity - see component #542 and 543. If decks are not maintained adequately, significant repair/replacement expenses often occur. In addition to re-application of the topcoat periodically (see next component), over time the underlying base layers and aggregate will wear and need to be redone. This component provides funding for that total system resurface which generally includes stripping the existing layers down to structural decking (plywood/concrete) and reinstalling, including primer/base layers, often metal lath or fiberglass mesh, aggregate broadcast coat for non-slip properties, and completed with a topcoat (see next component) which combines with the cost here for total project. The timing can vary depending on a number of factors including location/orientation of deck, such as inset vs. exposed/uncovered, more weather exposed sides of building (S & W) and if routine top coating has been completed. More exposed, weather sides of buildings may last 20-30 years while inset non-weather sides of buildings may last significantly longer.

Most deck coatings come with a warranty. A typical warranty is three to five years if properly maintained. Some warranties can be extended if the re-coating, and any other prescribed maintenance, is performed within a certain time frame. Check your warranty paperwork to determine the necessary timing of recoating and maintenance.

Useful Life:
30 years

Remaining Life:
3 years



Lower Estimate:	\$ 155,000	Higher Estimate:	\$ 189,000
------------------------	-------------------	-------------------------	-------------------

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 542 Traffic Coated Decks - Recoat**Approx Quantity: 5,405 GSF, Elastomeric****Location:** Select units.**Funded?:** Yes.**History:** None known.

Comments: The deck surface appearance was of a urethane/elastomeric coating. Re-application of the topcoat periodically is required to maintain its waterproof integrity. If decks are not maintained adequately, significant repair/replacement expenses often occur. Proactive coating cycles are cost effective. Extending the time between coatings runs the risk of increased costs due to wear on the second coat in addition to the topcoat and potential water penetration, which can damage the underlying components and greatly increase costs. Elastomeric deck surfaces are typically a three-coat system. The top coat loses thickness each year, primarily from exposure to ultraviolet sunlight, and to a lesser extent wear and tear. If more than the topcoat is allowed to wear off, the surface may still appear to be in 'good' condition, but the waterproof integrity may be compromised by nearly imperceptible "pin holes". Evaluate and repair, as needed, before recoating. Check with your specific manufacturer for cleaning instructions to avoid damage to the coating. Many manufacturers allow cleaning with a mild solution, such as soap and water, TSP, etc.

Most deck coatings come with a warranty. A typical warranty is three to five years if properly maintained. Some warranties can be extended if the re-coating is performed within a certain time frame. Check your warranty paperwork to determine the necessary timing of recoating and maintenance.

Resource:<https://deckandfloorcoating.com/how-to-maintain-your-waterproof-deck/>**Useful Life:**

5 years

Remaining Life:

3 years

**Lower Estimate:**

\$ 65,200

Higher Estimate:

\$ 79,600

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 543 Elevated Walkway - Recoat**Approx Quantity: 805 GSF, Elastomeric****Location:** Building CC (#11501).**Funded?:** Yes.**History:** None known.**Comments:** This component represents repairing and recoating the elevated walkway and stair landings of building CC (#11501). Fading of the coating and some evidence of ponding of water were observed.**Useful Life:**

5 years

Remaining Life:

3 years

**Lower Estimate:**

\$ 9,810

Higher Estimate:

\$ 12,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 545 Wood Decks - Replace**Approx Quantity: 2,560 GSF, Wood****Location:** Select units.**Funded?:** Yes.**History:** Spot repairs 2023 ~\$13,250**Comments:** The deck surface has open boards that allow water to drain between them. The wood deck surface appears to be stained. No decay of boards was observed.

Funding factored below is for replacing the existing walking surface materials with like-kind materials. The costs may be greater if the structural framing is found to need repair or replacement.

Inspect the deck, stairs, and railings annually, and repair as needed. As part of maintenance, apply water repellent stain/preservative at least every other year. Painting is included in component #533. Almost all exterior wood exposed to the Puget Sound area weather will decay over time, and require replacement. Current building codes require flashing of the ledger joist (at the exterior building wall) to prevent decay from compromising the structural integrity. Options for a longer lasting deck include using thick wood boards or a composite product (increased costs).

Useful Life:

20 years

Remaining Life:

5 years

**Lower Estimate:**

\$ 73,500

Higher Estimate:

\$ 89,900

Cost Source: Budget Allowance

Comp #: 553 Exterior Stairs - Maintain/Repair**Approx Quantity: 18 Sets****Location:** Select buildings.**Funded?:** No. No predictable large-scale repair or replacement projected**History:** Constructed 1999.**Comments:** The stair stringers are wood. The concrete stair treads are attached to the stair stringer by steel angle and bolts. The railings are wood. No corrosion was observed on the steel angle attachments, and no decay of wood was observed in the few stairs sampled for our visual review. The stairs are mostly protected from the weather by the overhead structure.

There is no predictable large-scale repairs or replacement at this time. Repair, as needed, using general maintenance funds. As stairs age, and repair needs become evident, funding can be added to future reserve studies.

As routine maintenance, inspect regularly to ensure safety and stability. Repair promptly, as needed, with operating funds. Paint as a part of an exterior paint project - see component #533. Treat corroded metal with a rusted inhibitor to extend the useful life.

Useful Life:**Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 555 Building Wood Rails - Replace**Approx Quantity: 2,000 LF****Location:** The decks, walkway, and stairs.**Funded?:** Yes.**History:** Installed 1999.**Comments:** The wood rails did not show evidence of significant damage, instability, or failure. Some localized decay was observed. The rails were not attached through the waterproof surface of the deck.

As routine maintenance, all railings and connections should be inspected at least annually for structural and/or waterproofing issues. Repair promptly, as needed, using operating funds. A general allowance is provided below for larger repair projects.

Useful Life:

20 years

Remaining Life:

4 years

**Lower Estimate:**

\$ 130,000

Higher Estimate:

\$ 159,000

Cost Source: ARI Cost Database: Similar Project Cost History

Comp #: 560 Exterior Lights - Replace
Location: Mounted to the building exteriors.
Funded?: Yes.
History: Varies.
Comments: The exterior lights were observed during daylight hours and are assumed to be functional. No problems were reported.


Approx Quantity: 400 Fixtures, Assorted

Our recommendation is to plan for a large-scale replacement at roughly the time frame below, for both cost efficiency and consistent quality/appearance throughout the association. There are a variety of materials and styles available. Cost can vary significantly depending on the quality and design of fixtures selected. Funding has not been added at this time.

As routine maintenance, inspect, repair, and change bulbs as needed.

Useful Life:
40 years

Remaining Life:
13 years



Lower Estimate:	\$ 39,600	Higher Estimate:	\$ 48,400
------------------------	-----------	-------------------------	-----------

Cost Source: Budget Allowance

Systems & Evaluations

Comp #: 900 Plumbing - Systems Evaluation**Approx Quantity: 1 Inspection & Report****Location:** Supply, drains, etc. throughout the buildings.**Funded?:** Yes.**History:** None known.**Comments:** Plumbing systems are generally considered by the engineering community to be life limited. The costs for replacement can vary widely depending upon the specifications, site conditions, unit repairs after install, hazardous material handling, etc.

The vast majority of the plumbing system is hidden, and not visible for review. A reserve study is limited to visual exterior observations and research for budget purposes.


We highly recommend the association engage a qualified firm to evaluate the plumbing systems, including forensic wall openings, and test sections of piping. Additional testing may be further recommended. Patterns of significant repair expenses, leaks, poor flow, and sediments in the lines, should accelerate the need to address proactively and seek a detailed analysis to identify hidden conditions, project a remaining useful life, and recommendations for any needed repairs, maintenance, etc. The cost can vary depending on the complexity of systems, the number of wall or ceiling openings, etc. Prior to such an evaluation, there is no predictable basis at this time for large-scale plumbing repair or replacement expenses. Results should be included in the subsequent reserve study update.

Useful Life:

20 years

Remaining Life:

0 years

**Lower Estimate:**

\$ 11,300

Higher Estimate:

\$ 13,800

Cost Source: Budget Allowance: Kent Engineering 206-455-5121

Comp #: 901 Plumbing - Repair/Replace

Approx Quantity: 1 Extensive Systems

Location: Supply & drain lines throughout the buildings.

Funded?: No. Useful life not predictable, prior to systems evaluation


History: None known.

Comments: Plumbing systems are generally considered by the engineering community to be life limited. The costs for systems replacement can vary widely depending upon the specifications, site conditions, unit repairs after install, hazardous material handling, etc.

See the previous component for a recommended plumbing evaluation. Until a qualified engineering firm has performed an evaluation of your plumbing systems, and provided specific recommendations, there is no predictable basis for system replacement reserve funding at this time.

Manufacturing defects become apparent from time to time, and certain site conditions (e.g. galvanic corrosion, dissimilar metals in contact with piping, chemical reactions, etc.) can contribute to premature deterioration of the plumbing systems.

Treat minor repairs as an ongoing maintenance expense.



Useful Life:

Remaining Life:

Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 920 Electrical System - Maintain/Repair**Approx Quantity: 1 Extensive Systems****Location:** Main & branch systems throughout the community.**Funded?:** No. The useful life is not predictable.**History:** None known.**Comments:** The majority of the electrical system was not visible for review. Analysis of the electrical system, beyond a limited visual review, is not within the scope of a reserve study. No large issues or problems/defects were reported.

We recommend periodic evaluation by engineer/master electrician to evaluate the system(s) for safety, code-compliance, maintenance, repair & replacement needs. Any predictable expenses identified that meet the criteria for reserve funding can be included in the reserve plan. Some electrical system components are known to be life limited. Manufacturing defects become known from time to time, and certain site conditions can contribute to premature deterioration of electrical components.

Useful Life:**Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 964 Fire System - Inspect/Test/Evaluate**Approx Quantity: 1 Extensive Systems****Location:** Bells, pulls, etc. of select buildings.**Funded?:** No. Costs are best handled with operating funds.**History:** None known.**Comments:** Fire jurisdictions across the region may vary in their local enforcement and recommendations relating to the International Fire Code. Codes evolve over time, and are generally amended every three years - inspections, vendor recommendations, need to replace older technology, etc. are examples of drivers that may require significant upgrades to your current system. It is therefore our recommendation that you engage a fire systems consultant from time to time, funded from the operating budget, to evaluate and provide specific recommendations for your system and locale.

Several tests are required over time per the NFPA 25, Inspections, Testing and Maintenance of Water-Based Fire Protection Systems. These types of expenses are typically most appropriately factored within the annual operating budget, not reserves.

Useful Life:**Remaining Life:**

No Photo Available

Lower Estimate:**Higher Estimate:****Cost Source:**

Comp #: 965 Fire Alarm Panels - Replace

Approx Quantity: 3 Panels

Location: Buildings X (727), Y (723), and 11501 (CC).

Funded?: Yes.

History: None known.

Comments: Fire alarm control rooms were noted in a few buildings. It is assumed only the larger buildings have a fire alarm panel, and the panels are original to construction. We have funded for (3) panels but can adjust accordingly in revisions or future reports. We did not have access to these fire panels during our September 2025 inspection.

Our experience suggests that an approximate useful life for the panel for budget planning purposes is in the 12-20 year range. Discuss this component with your fire panel vendor or consultant to better determine the timing of the panel's repair or replacement needs, and to assess the overall system in relation to the current codes, and parts and technician availability to determine if upgrades or replacement will be required.

Fire alarm panels are required to be inspected annually, and the company performing the inspection is required to log/note it at the panel so that the fire department can view it. Fire departments can issue a fine if inspections are not performed. Fire panels are a critical life safety item that needs to be well maintained, following all requirements of the National Fire Protection Association (N.F.P.A.) and local codes.

The scope of work at the time of repairs can vary greatly based on the amount of work needed to bring the existing fire system to the level required by the fire/building codes in place at that time. Evaluating the entire fire prevention system is beyond the scope of a reserve study. Replace the panel proactively, and perform additional upgrades as required by code. The costs below are for the repair and/or replacement of the panel only.

Useful Life:

20 years

Remaining Life:

0 years

No Photo Available

Lower Estimate:

\$ 18,000

Higher Estimate:

\$ 22,000

Cost Source: Budget Allowance

Comp #: 966 Fire Sprinkler Heads - Test/Replace

Approx Quantity: 1 Extensive Systems

Location: Select buildings.

Funded?: No. Costs are best handled with operating funds.

History: None known.

Comments: There are a variety of heads that may be present as part of wet and/or dry sprinkler systems. Fire sprinkler heads are required to be inspected regularly per NFPA, and pass testing or be replaced at prescribed intervals depending upon the type of head(s) in place, and other factors such as environment. If large scale replacement is deemed necessary and predictable, reserve funding can be appropriate. If testing expense is less than 1% of your operating budget, expense within the operating budget in the year of occurrence.

Fire sprinklers remain idle in most instances making it difficult to identify any problems. The NFPA 25 handbook recommends testing a representative sample of dry sprinkler heads at 10 years then every 10 year thereafter, high-risk or exposure every 5 years, wet system quick response at 20 years and every 10 thereafter, conventional at 50 years and every 10 thereafter. If the representative sample heads fail, all sprinkler heads should be replaced. If testing of heads is a significant expense and/or requires significant carpentry expense to repair surrounding structure, replacement may be the prudent choice.

Useful Life:

Remaining Life:



Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 969 Fire Hydrants - Maintain/Replace**Approx Quantity: 1 Unfunded****Location:** Scattered throughout the community.**Funded?:** No. Reported to be the responsibility of Snohomish County.**History:** None known.**Comments:** The fire hydrants are assumed to be functional. It was reported Snohomish County is responsible for maintaining, repairing, and replacing the fire hydrants.

Our research indicates fire hydrants can last anywhere from 30 to over 100 years. Inspect the hydrants regularly, and report any concerns to the Snohomish County Public Works Department via an option below:

Phone: 425-388-6453

Email: Contact.PWCustomerServiceCenter@snoco.orgWebsite: <https://snohomishcountywa.gov/204/Public-Works>**Useful Life:****Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 971 Vents - Clean & Inspect**Approx Quantity: 1 Unfunded****Location:** The building exteriors.**Funded?:** No. Costs are best handled with operating funds.**History:** None known.**Comments:** The buildings include multiple vents that serve various purposes. We recommend the Association have the vents inspected and cleaned annually with operating funds. Heightened attention should be given to dryer vents to ensure no blockages have occurred. Dirty/blocked dryer vents (and hoses) have the potential to lead to a fire hazard.**Useful Life:****Remaining Life:****Lower Estimate:****Higher Estimate:****Cost Source:**

Comp #: 990 Ancillary Evaluations

Approx Quantity: 1 Specialty Evaluations

Location: To augment reserve planning.

Funded?: No. Costs are best handled with operating funds.

History: None known.

Comments: A reserve study is a budget model, limited to visual exterior observations and research. As there are some key details and factors of buildings and grounds hidden from view, it is prudent to conduct additional ancillary evaluations from time to time. The purpose of these evaluations is to aid planning and assess for any basis of predictable funding that may be incorporated into the reserve study. We recommend that you periodically engage specialty evaluations in the following areas/fields as applicable to your property:

- Civil Engineering review: Soils & drainage, pavement specifications, below grade waterproofing
- Arborist: Trees & landscape - plan of care and life cycle forecast
- Legal Responsibility Matrix: Governing document review for clear expense delineation between the association and unit owners
- Legal Governing Document review periodically to incorporate changes in law over time and best practices
- Investment consultant: Maximize return and cash flow management while protecting principal
- Insurance policy & coverage review: Understand what is and is not covered and by whom (association vs. owner policies)
- Masonry consultant: Assess mortar condition and waterproofing, and provide forecast and recommendations
- Energy Audit: Typically conducted by a utility company, HVAC vendor or consulting engineer to assess efficiency, and cost benefit to retrofit existing equipment. WA Clean Building Performance Standard is a new law in Washington for residential buildings 20,000 GSF and larger - see Dept. of Commerce for more information. Rules and compliance are not yet fully formed.

Note: There are several other important professional evaluations to augment reserve planning that are of heightened importance such as Life-Safety and/or Building Envelope & Structural issues, and Plumbing. Those components are addressed separately within this report.

Useful Life:

Remaining Life:

No Photo Available

Lower Estimate:

Higher Estimate:

Cost Source:

Comp #: 995 Building Envelope & Structure**Approx Quantity: 1 Inspection & Report****Location:** The exterior walls, underlying waterproofing components, and structural components.**Funded?:** Yes.**History:** None known.

Comments: A reserve study is a budget model, limited to visual exterior observations and research. It is outside the scope of our services, and the purpose of a reserve study, to assess the adequacy of the building envelope and structural performance, as many of the key details are hidden from view. Many associations are required to have annual inspections by a qualified engineer or architect to assess the physical condition of the improvements - check your governing documents for any such requirements. Any areas of concern observable from our limited exterior observations, and cycles for repair and replacement, have been stated in the various component field notes throughout this report. We highly recommend regular professional specialty inspections by a qualified engineering, architectural, or building envelope consulting firm to evaluate the performance of the building envelope and structural components.

Many associations are required by their Declaration to have annual inspections by a qualified architect or engineer to assess the physical condition of the building envelope enclosure. The building envelope inspection typically covers at minimum the roofs, decks, siding, windows, doors, sealants/caulking, and flashings. As the building ages, and the waterproofing typically deteriorates, provide more frequent inspections.

Building envelope inspections can be either visual or intrusive. An intrusive investigation (where finished materials are removed to view and better understand the underlying systems, conditions and performance) should be of greater benefit, since a visual review provides only a limited amount of information derived from surface observations.

In addition, we recommend the association annually survey residents to inquire about conditions only visible from the unit interiors that the association may not be aware of. Survey questions may include, but are not limited to, water intrusion/organic growth (particularly at windows and doors, skylights, water heaters, plumbing fixtures, etc), cracking or any other movement of drywall or structural members, and any other general building concerns. Such surveys can be key in identifying potential concerns early, thus increasing the opportunity to conduct repairs before advanced deterioration/damage and, therefore, larger expenses occur.

Useful Life:
10 years

Remaining Life:
0 years

**Lower Estimate:**

\$ 10,800

Higher Estimate:

\$ 13,200

Cost Source: Budget Allowance

Comp #: 997 Unit High-Risk Components**Approx Quantity: 1 Inspection & Report****Location:** Analysis of in-unit high-risk components.**Funded?:** No. Costs are best handled with operating funds.**History:** None known.

Comments: While this component does not meet the criteria for reserve funding, our experience in preparing well over 10,000 reserve studies in the Pacific NW indicates that most communities would benefit from a review of the high-risk components within the individual units. High-risk components are those with a history of failure, often leading to significant damage of unit interiors and surrounding common area structural components. High-risk components include, but are not limited to water heaters, washer and dryer hookups, ice maker lines, plumbing angle stops, electrical panels, window and door waterproofing, etc. The Board of Directors is charged with a duty to set the standard of care in the community. Many governing documents and state law governing Common Interest Communities (RCW 64.90.440) provide guidance for those physical components that pose a heightened risk.

It is our strong recommendation that you factor the cost for a high-risk component review within an upcoming operating budget. Consult with an engineering firm specializing in such inspections and analysis. The cost for such a study may be in the range of \$50 - \$200 per unit, depending upon the complexity and scope of work. High-risk component review is not within the scope of our services.

Useful Life:**Remaining Life:**

No Photo Available

Lower Estimate:**Higher Estimate:****Cost Source:**

Comp #: 999 Reserve Study - Update**Approx Quantity: 1 Annual Update****Location:** The community common and limited common elements.**Funded?:** No. Costs are best handled with operating funds.**History:** WSV: 2026; NSV: 2025, 2024; FULL: 2023

Comments: Per Washington State law (RCW), reserve studies are to be updated annually, with site inspections by an independent reserve study professional to occur no less than every three years to assess changes in condition (i.e., physical, economic, governmental, etc.), and the resulting effect on the community's long-term reserves plan. Reserve Study costs are most appropriately factored within the annual operating budget, not as a reserve's component.

Thank you for choosing Association Reserves!

Useful Life:**Remaining Life:**

**ASSOCIATION
RESERVES™**
Planning For The Inevitable

Lower Estimate:**Higher Estimate:****Cost Source:**

