

# CONEJOS RIVER DIVERSION INFRASTRUCTURE INVENTORY

---

**Structure Name:** GARCIA R D

---

**Reported By:** Daniel Boyes

---

**Date:** April 3, 2019

---

<b>Headgate</b>	<b>Latitude</b>	<b>Longitude</b>
<b>Location:</b>	37.110711	-105.983651

---

**Headgate Type:** Manually operated 4' wide steel slide gate

---

<b>Headgate Condition:</b>	A <input type="checkbox"/>	<b>Diversion and Other Conditions:</b>	A <input type="checkbox"/>	<b>River Miles From North Branch Conejos Terminus (Point Of Diversion):</b>	<b>Structure Submerged:</b> Yes <input type="checkbox"/>
	B <input checked="" type="checkbox"/>		B <input checked="" type="checkbox"/>		No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>	10.74 mi	

---

**Repair(s) or Improvement(s) Completed Since 2006:** None

**Structure Description:** This structure is located on the north branch of Conejos River. A checkboard diversion dam with a combination of steel and wood wingwalls directs water into a short feeder channel and to the headgate, which is located on the south bank of the river. Opposite this headgate is the Garcia Ditch headgate, located on the north bank of the river.

---

**Repair(s) or Improvement(s) Currently Needed:** The SMP Technical Advisory Team (TAT) recommends erosion mitigation and riparian revegetation as well as improving the diversion. A new or improved diversion would improve efficiency and reduce maintenance.

---

**Comments:** This ditch is a priority 4.5

---

**Notes:**

---

**Estimated Range of Cost:** Low

---

Headgate looking downstream



Headgate outlet




Diversion dam looking downstream



Diversion dam looking upstream



Aerial image of structure



Flume looking upstream



CONEJOS RIVER DIVERSION INFRASTRUCTURE INVENTORY

GARCIA R DITCH

PHOTO LOG

Conejos River Stream Management Plan