

**Department of Education**  
**SPTVE**  
**SHIELDED METAL ARC**  
**WELDING (SMAW)10**  
**Multi Layer Fillet Weld in Flat Position**  
**Quarter 2: Week 5 Module**



Albert B. Sierra  
**Writer**

Gerry V. Domalanta  
**Validator**

Dr. Valentina A. Ballesteros  
**Quality Assurance Team Chair**



**Schools Division Office – Muntinlupa City**

Student Center for Life Skills Bldg., Centennial Ave., Brgy. Tunasan, Muntinlupa City  
(02) 8805-9935 / (02) 8805-9940



## EXPECTATIONS

At the end of the lesson, the learner is expected to:

1. Identify the procedures in welding multi layer fillet in flat position,
2. enumerate the procedures in welding multi layer fillet and
3. draw the working drawing of the multi layer fillet weld in flat position,



## PRE-TEST

**Direction:** Encircle the letter of the correct answer.

1. A fillet weld is a weld type in the cross-sectional shape of a \_\_\_\_\_.  
A. Circle  
B. Rectangle  
C. Square  
D. Triangle
2. Travel angle for single pass fillet weld is usually set at an angle of \_\_\_\_\_.  
A. 45 degrees  
B. 60 degrees  
C. 70 degrees  
D. 85 degrees
3. Frequently used in all kinds of work, which may be single fillet lap joint or double fillet.  
A. Butt joint  
B. Corner joint  
C. Lap joint  
D. Tee joint
4. Use \_\_\_\_\_ electrode and tack weld the metal to form a T-joint.  
A. 6010  
B. 6011  
C. 6013  
D. 7018
5. In stringer bead in flat fillet weld of the same thickness plate, the work Angle is always.  
A. 30 degrees  
B. 45 degrees  
C. 60 degrees  
D. 70 degrees
6. Refers to the layers of beads which has been deposited in the base metal.  
A. Arc rays  
B. Pass  
C. Puddle  
D. Ripple
7. What is the recommended amperage setting in welding fillet?  
A. 85  
B. 90  
C. 95  
D. 100
8. What is the specified length of tack welds on fillet welds?  
A. 5 mm  
B. 10 mm  
C. 15 mm  
D. 20 mm
9. Welding fillet, the normal arc length is \_\_\_\_\_.  
A.  $1/16 - 1/8$  inch.  
B.  $1/8 - 3/16$  inch.  
C.  $1/4 - 3/8$  inch.  
D.  $5/16 - 1/2$  inch.
10. Metal to be welded should be tack welded in \_\_\_\_\_.  
A. Both edge of the plate  
B. Both end and the center of the joint  
C. Center and edge of the joint.  
D. Center of the joint



## LOOKING BACK

In the previous lesson, you have learned the procedures in multi pass weld in flat position. Now let us see if you still remember these procedures.

**Directions:** Fill in the missing word/words to complete the sentence.

- A. Wear the appropriate \_\_\_\_\_ before welding. 1
- B. \_\_\_\_\_ the tools, equipment and materials needed. 2
- C. Set up the welding machine and adjust the correct current \_\_\_\_\_ at 95 amps. 3
- D. Use \_\_\_\_\_ electrode and tackweld the metal to form a T-joint. 4
- E. Clamp firmly the workpiece to the \_\_\_\_\_ and clean the joint to be welded. 5
- F. \_\_\_\_\_ the arc at the starting point and hold the rod at \_\_\_\_\_ then shorten the arc at the finishing points and fill the crater with molten metal. 6
- G. Remove the slag with a \_\_\_\_\_ and clean the bead using steel brush. 7
- H. Deposit the \_\_\_\_\_ it should overlap the first bead by half or 2/3. 8
- I. Deposit the \_\_\_\_\_ it should overlap the second bead by half or 2/3. 9
- J. Properly clean the metal for \_\_\_\_\_. 10
- K. Visually check the following:
- Plate alignment and squareness
  - Bead weave pattern
  - Weld defects such as porosity, undercut, overlaps
  - Bead connection



## BRIEF INTRODUCTION

### Multi Layer Fillet Weld in Flat Position

#### Materials:


- 2 pcs. Mild Steel plates 10 mm X 50mm X 200 mm
- 8 pcs. E-6013- 3.25mm/Æ

#### Tools and Equipment:

- AC or DC welding machine with accessories
- Chipping Hammer
- Steel brush
- Welding gloves (leather)
- Welding apron (leather)
- Welding helmet/mask
- Portable grinder

#### Procedures:


1. Wear the appropriate Personal Protective Equipment (PPE) before welding.
2. Prepare the tools, equipment and materials needed.
3. Set up the welding machine and adjust the correct current amperage settings at 95 amps.
  - 85-100 amperes (range of adjustments)
4. Use E6013 electrode and tackweld the metal to form a T-joint.
5. Clamp firmly the workpiece to the welding positioner and clean the joint to be welded.
6. Strike the arc at the starting point and hold the rod at correct angles then shorten the arc at the finishing points and fill the crater with molten metal. As in the illustration below.




7. Remove the slag with a chipping hammer and clean the bead using

steel brush. **Note:** Use clear goggles/face shield when chipping. The direction of chipping should be away from you.

8. Deposit the second pass. It should overlap the first bead by half or  $\frac{2}{3}$ . As in the illustration below.




9. Deposit the third pass. It should overlap the second bead by half or  $\frac{2}{3}$ . As in the illustration below.




10. Properly clean the metal for inspection.
11. Visually check the following:
  - Plate alignment and squareness
  - Bead weave pattern
  - Weld defects such as porosity, undercut, overlaps
  - Bead connection

## WORKING DRAWING



## “V” WELD POSITION



## POSITION OF ELECTRODE

**Figure 15.** Multi layer fillet welds



## ACTIVITIES


### Activity 1

**Directions:** Arrange the welding procedures of multi layer fillet weld in flat position. Write 1 on the blank for the first procedure, 2 for the second procedure and 3 to 11 for the succeeding procedure.

- \_\_\_\_\_ Prepare the tools, equipment and materials needed.
- \_\_\_\_\_ Strike the arc at the starting point and hold the rod at correct angles then shorten the arc at the finishing points and fill the crater with molten metal.
- \_\_\_\_\_ Visually check the following:
  - \_\_\_\_\_ Remove the slag with a chipping hammer and clean the bead using steel brush.
  - \_\_\_\_\_ Use E6013 electrode and tack weld the metal to form a T- joint.
  - \_\_\_\_\_ Properly clean the metal for inspection.
  - \_\_\_\_\_ Clamp firmly the workpiece to the welding positioner and clean the joint to be welded.
- \_\_\_\_\_ Set up the welding machine and adjust the correct current amperage settings at 95 amps.
- \_\_\_\_\_ Wear the appropriate Personal Protective Equipment (PPE) before welding.
- \_\_\_\_\_ Deposit the second pass. It should overlap the first bead by half or 2/3
- \_\_\_\_\_ Deposit the third pass. It should overlap the second bead by half or 2/3.

### Activity 2

**Directions:** Draw the illustration/working drawing of multi layer fillet weld in flat position in separate answer sheet. See figure 15.





### REMEMBER

The welding steps and procedures are very important or required to follow completely because it serves as a guide of a welder for the effective welding in accordance with welding procedure specification, or WPS.



### CHECK YOUR UNDERSTANDING

**Directions:** Enumerate the steps on how to weld multi layer fillet in flat position.

- 1) \_\_\_\_\_
- 2) \_\_\_\_\_
- 3) \_\_\_\_\_
- 4) \_\_\_\_\_
- 5) \_\_\_\_\_
- 6) \_\_\_\_\_
- 7) \_\_\_\_\_
- 8) \_\_\_\_\_
- 9) \_\_\_\_\_
- 10) \_\_\_\_\_
- 11) \_\_\_\_\_





## POST TEST

**Direction:** Encircle the letter of the correct answer.

1. What is the recommended amperage setting in welding multi layer fillet?  
A. 85  
B. 90  
C. 95  
D. 100
2. In stringer bead in flat fillet weld of the same thickness plate, the work angle is always.  
A. 30 degrees  
B. 45 degrees  
C. 60 degrees  
D. 70 degrees
3. Travel angle for single pass fillet weld is usually set at an angle of \_\_\_\_\_.  
A. 45 degrees  
B. 60 degrees  
C. 70 degrees  
D. 85 degrees
4. Use \_\_\_\_\_ electrode and tack weld the metal to form a T-joint.  
A. 6010  
B. 6011  
C. 6013  
D. 7018
5. What is the specified length of tack welds on fillet welds?  
A. 5 mm  
B. 10 mm  
C. 15 mm  
D. 20 mm
6. to be welded should be tack welded in \_\_\_\_\_.  
A. Both edge of the plate  
B. Both end and the center of the joint  
C. Center and edge of the joint.  
D. Center of the joint
7. A fillet weld is a weld type in the cross-sectional shape of a \_\_\_\_\_.  
A. Circle  
B. Rectangle  
C. Square  
D. Triangle
8. Welding fillet, the normal arc length is \_\_\_\_\_.  
A.  $1/16 - 1/8$  inch.  
B.  $1/8 - 3/16$  inch.  
C.  $1/4 - 3/8$  inch.  
D.  $5/16 - 1/2$  inch.
9. Refers to the layers of beads which has been deposited in the base metal.  
A. Arc rays  
B. Pass  
C. Puddle  
D. Ripple
10. Frequently used in all kinds of work, which may be single fillet lap joint or double fillet.  
A. Butt joint  
B. Corner joint  
C. Lap joint  
D. Tee joint

|  |  |  |
|--|--|--|
|  | <p><b>Checking your understanding</b></p> <p>1. Wear the appropriate Personal Protective Equipment (PPE) before welding.</p> <p>2. Prepare the tools, equipment and materials needed.</p> <p>3. Set up the welding machine and adjust the correct current.</p> <p>4. Clamp firmly the workpiece to the welding positioner, and clean the joint to be welded.</p> <p>5. Strike the arc at the starting point and hold the rod at correct angles then shorten the arc at the finishing points and fill the crater with molten metal.</p> <p>6. Remove the slag with a chipping hammer and clean the bead using steel brush.</p> <p>7. Deposit the second pass. It should overlap the first bead by half or 2/3.</p> <p>8. Deposit the third pass. It should overlap the second bead by half or 2/3.</p> <p>9. Properly clean the metal for inspection.</p> <p>10. Visually check the following:</p> <ul style="list-style-type: none"> <li>-plate alignment/squareness</li> <li>-beave weave pattern</li> <li>-weld defects</li> <li>-bead connection</li> </ul> | <p><b>Key to Corrections:</b></p> <p><b>Pre-test</b></p> <ol style="list-style-type: none"> <li>1. B</li> <li>2. C</li> <li>3. B</li> <li>4. A</li> <li>5. B</li> <li>6. D</li> <li>7. C</li> <li>8. D</li> <li>9. C</li> <li>10. B</li> </ol> <p><b>Looking Back</b></p> <ol style="list-style-type: none"> <li>1. Personal protective equipment</li> <li>2. Prepare</li> <li>3. Amperage setting</li> <li>4. E6013</li> <li>5. Welding positioner</li> <li>6. Correct angles</li> <li>7. Chipping hammer</li> <li>8. Second pass</li> <li>9. Third pass</li> <li>10. Inspect</li> </ol> <p><b>Activity</b></p> <p><b>Act. 1</b></p> <ol style="list-style-type: none"> <li>A. 2</li> <li>B. 6</li> <li>C. 11</li> <li>D. 7</li> <li>E. 4</li> <li>F. 10</li> <li>G. 5</li> <li>H. 3</li> <li>I. 1</li> <li>J. 8</li> <li>K. 9</li> </ol> |
|--|--|--|

## References

- *K12 Basic Education Curriculum, Grade 10, SMAW LM Final Check and verified page 70-76.*
- Public Technical Vocational High Schools, Competency-Based Learning material, SMAW NCI, (Department of Education 2008)