## Section 2.2 Troubleshooting Flow Charts

## **Evolution™ Controller e-Codes**

| Displayed<br>Alarm  | Alarm/<br>Warning | e-Code<br>Breakdown | Description   | Action Step  |
|---------------------|-------------------|---------------------|---|--|
| Controller Fault    | ALARM             |                     | No E-code on HSB  | Replace Controller   |
| Overcrank           | ALARM             | 1100                | Condition - Engine Cranks but will not Start (5 crank attempts) Unit turns over but will not start. Controller is receiving signal on Wire 18.  | Problem 17   |
| Overspeed           | ALARM             | 1200                | Prolonged (60 Hz on a 50 Hz unit, 72Hz on 60Hz unit)  Over specified Hz for 3 seconds. Possible cause: Stepper motor/mixer body assembly issue.   | Test 12  |
| Overspeed           | ALARM             | 1205                | Instantaneous (62 Hz on a 50 Hz unit, 75Hz on 60Hz unit)  Over specified Hz for 0.1 second (100 milliseconds). Possible cause: Stepper motor/mixer body assembly issue.   | Test 12  |
| Overspeed           | ALARM             | 1207                | Monitors zero cross timing of the AVR to determine the alternator frequency which is a speed indicator. Set for 150 milliseconds of 4500 rpm or higher. Used if the normal ignition pulse sequence(s) are not being seen by the controller. | Test 64 and Test 60  |
| Low Oil Pressure    | ALARM             | 1300                | Occurred while running The default Extended alarm for low oil pressure. Check oil level and pressure.   | Test 61  |
| High<br>Temperature | ALARM             | 1400                | Condition - Air Flow Impeded / Flow Issue Check the inlet/outlet for debris. Check temperature sensor and wiring.   | Test 62  |
| RPM Sensor          | ALARM             | 1501                | Twin Cylinder+Running Twin Cylinder Running faults to RPM Sensor Loss. Possible Causes: air pocket in fuel line, dirty fuel, missing ignition pulse (loss of one of the primary coils).   | Test 50 and Test 64  |
| RPM Sensor          | ALARM             | 1505                | Twin Cylinder+Cranking Twin Cylinder Cranking faults to RPM sensor loss Possible Cause: starter motor issue, missing ignition pulse (loss of one of the primary coils).   | If engine cranks, Test 64. If engine does not crank, Problem 15.   |
| RPM Sensor          | ALARM             | 1511                | Single Cylinder+Running Single Cylinder Running RPM sensor loss Possible Causes: air pocket in fuel line, dirty fuel. Loss of ignition pulse.   | Test 50 and Test 64  |
| RPM Sensor          | ALARM             | 1515                | Single Cylinder+Cranking Single Cylinder Cranking faults to RPM sensor loss Possible Cause: starter motor and/or engine issue. Loss of ignition pulse.  | If engine cranks, Test 64. If engine does not crank, Problem 15.   |
| Underspeed          | ALARM             | 1600                | Condition - Unit is Overloaded (55 Hz for 60 Hz for 30 sec, 40 Hz for 50 Hz unit Unit is Overloaded slowing engine speed, fuel supply low or throttle control problem.  | Problem 3, or Test 50, or Test 12  |
| Underspeed          | ALARM             | 1603                | Underspeed The engine never comes up to 3600 RPM.   | Check fuel selection and fuel supply   |
| Overvoltage         | ALARM             | 1800                | Prolonged Over-Voltage  | Problem 2  |
| Undervoltage        | ALARM             | 1900                | Prolonged Under-Voltage Undervoltage due to loss of voltage. Below 80% for 10+ seconds)   | *Preliminary Output<br>Voltage Test (firmware<br>v1.12 and above).<br>Note: Update controller to<br>latest firmware. |
| Undervoltage        | ALARM             | 1901                | Instantaneous Undervoltage due to sudden loss of voltage. (Voltage less than 15 sec 2 sec+)   | *Preliminary Output<br>Voltage Test (firmware<br>v1.12 and above).<br>Note: Update controller to<br>latest firmware. |
| Undervoltage        | ALARM             | 1902                | Both Zero Crosses missing Undervoltage due to faulty excitation winding, or zero cross circuit, or circuit in general. Possible cause: loose wiring, field boost hardware failure. (Both zero cross missing greater than 1.5 sec)           | *Preliminary Output<br>Voltage Test (firmware<br>v1.12 and above).<br>Note: Update controller to<br>latest firmware. |

NOTE: If an alarm code is displayed on the controller, use the diagnostic procedure listed in the action step.

Diagnostic Repair Manual 29

## **Evolution™ Controller e-Codes**

| Displayed<br>Alarm       | Alarm/<br>Warning   | e-Code<br>Breakdown | Description   | Action Step  |
|--------------------------|---------------------|---------------------|---|--|
| Undervoltage             | ALARM               | 1906                | Single Zero Cross missing Undervoltage due to faulty excitation winding, zero cross circuit, or circuit in general. Possible cause: field boost hardware failure. (One zero cross missing greater than 1.5 sec) | *Preliminary Output<br>Voltage Test (firmware<br>v1.12 and above).<br>Note: Update controller to<br>latest firmware. |
| Wiring Error             | ALARM               | 2099                | Mis-wired Customer connection low voltage and high voltage wires are crossed.   | Check customer connection in generator   |
| Overload<br>Remove Load  | ALARM               | 2100                | Overloaded - Default (Output Current Method) Unit is overloaded. One or both CT(s) detecting an overload condition. Check transfer switch loadshed functionality. (Change load dynamics or utilize loadshed).   | Remove Load  |
| Undervoltage<br>Overload | ALARM               | 2299                | Unit was overloaded and attempted to start with a large load connected. The unit can not ramp up the generator voltage to its normal target voltage value if it starts with a large load connected              | Remove Load  |
| Stepper<br>Overcurrent   | ALARM               | 2399                | Current flow in stepper coil(s) above specification   | Test 12  |
| Fuse Problem             | ALARM               | 2400*               | Missing / Damaged Fuse The 7.5 amp Controller Fuse is missing or blown (open). *Firmware version 1.11 and older only  | Test 44  |
| Aux Shutdown             | ALARM               | 2800                | External shut down circuit is open.   | Check the continuity of<br>the harness and operation<br>of the switch(es). Repair/<br>replace as needed.             |
| Low Battery              | WARNING             |                     | Condition->Battery less than 12.1 Volts for 60 seconds  | Test 45  |
| Battery Problem          | WARNING             |                     | Condition->More than 16 Volts of battery voltage or 600 milliamperes or more of charge current at the end of an 18 hour charge  | Test 45  |
| Charger Warning          | WARNING             |                     | Less than 12.5 volts of battery voltage at the end of a 18 hour charge  | Problem 22   |
| Charger Missing<br>AC    | WARNING             |                     | AC power is missing from the battery charger input  | Problem 22   |
|                          | Service<br>Schedule |                     | Service Schedule A 200hours 2 years<br>Service Schedule B 400 Hours 4 years   | Perform Maintenance  |

NOTE: If an alarm code is displayed on the controller, use the diagnostic procedure listed in the action step.

## Additional Codes For 8 and 9 kW Units Only

| Displayed<br>Alarm      | Alarm/<br>Warning | e-Code<br>Breakdown | Description   | Action Step  |
|-------------------------|-------------------|---------------------|---|--|
| Overcrank               | ALARM             | 1101                | Engine/Starter Problem Limiting number of cranking cycles to protect the starter motor.                   | If the engine has tried to crank for 10 times unsuccessfully, this will trigger. |
| Overload<br>Remove Load | ALARM             | 2102                | Overloaded Unit re-cranks 5 times when load is applied, engine dies (0 RPM) and has low voltage (< 180V)  | Check for Overloaded condition on unit. Inspect stepper motor operation.         |
| Overload<br>Remove Load | ALARM             | 2103                | Overloaded Unit has run and attempted to accept load 10 times, could not accept due to overload condition | Check for Overloaded condition on unit   |