

SERVICE BULLETIN

DATE 10-23-70

BULLETIN NUMBER 1927

MINITEREST General Manager Sales Manager Service Manager Parts Manager Service Technician

BUBJECT: BODY
BUJET: HOOD HOLD DOWN PIN AND
BEZEL WEAR

BULLETIN NUMBER 1927

MODELS: 1970 "TRANS-AM" AND MODELS: "A, A, R, CUDA"

Hood vibration during continued high speed operation may result in wear of the hood hold down spring pin and bezel.

If this condition is encountered, the pin and bezel should be replaced with the recently introduced repair package, Part No. 3579670, which contains the following parts:

3508508 Spring Pin

3508507 Gasket

3508506 Bezel

H. F. CHISHOLM SERVICE MANAGER

(THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS)
(CE BULLETIN VOUS EST FOURNI À TITRE DE RENSEIGNEMENT TECHNIQUE SEULEMENT; IL N'AUTORISE AUCUNE RÉPARATION)