Your Home Inspection



1010 USA Drive Fort Wayne, IN 01010

NON TRANSFERABLE

Prepared for: Mr. Mrs. John Doe

Prepared by: PTI Home Inspections 407 North Main Street Churubusco, Indiana 46723 License #HI00500182 License #F212917

Mr & Mrs John Doe 1010 USA Drive Page 1 of 13

Major Defect Summary

When work is performed in response to this report, we recommend that all repairs be done by licensed or certified contractors. This report is an integral and binding instrument of the attached "Agreement and Order"

Plumbing

1. Water Softener: Culligan water softener - Re generated at the inspection-service as regular maintenance

The unit started leaking about 45 minutes into the RE generation, PTI contacted the sellers agent to inform of bypassing the unit and unplugging to stop further leaking and or damage, review and repair as needed



Minor Defect Summary


When work is performed in response to this report, we recommend that all repairs be done by licensed or certified contractors. This report is an integral and binding instrument of the attached "Agreement and Order"

Kitchen

 Kitchen Microwave: Tested operational and no microwave leaks was detected - Certain control buttons on the unit will not work such as CANCEL and FAN Review and repair as needed

Roof

2. Flashing: Aluminum flashing and rubber boots - The waste vents rubber boot is dry rotted and cracked from the UV Rays from the sun and is prone to leak, replace the boot



Mr & Mrs John Doe 1010 USA Drive Page 3 of 13

Routine Maintenance Summary

When work is performed in response to this report, we recommend that all repairs be done by licensed or certified contractors. This report is an integral and binding instrument of the attached "Agreement and Order"

Air Conditioning

 AC System Cooling Operations: The AC was not tested due to the temperatures being < than 65 degrees for more than three day and nights and will damage the unit -Compressor motor ran, the unit could not be operated or brought up to temperature due to the outside temperature being below 65 degrees for more than 3 consecutive days and nights, review by a licensed HAVAC technician in the spring



Heating System


 Heating System Furnace Condition: No documentation of regular maintenance was found - Regular service and maintenance is due, Service and maintenance by a licensed HAVAC technician is recommended

of

3. Heating System Filter Size/Type: 16x25x4. Note: filters are directional, VISIT http://www.discountfilters.com for savings on filters - The filter was installed backwards, being newly changed it was turned around, PTI marked the cover with the proper direction of the filter and its size

Mr & Mrs John Doe 1010 USA Drive Page 4 of 13

Heating System (Continued)



4. Heating System Humidifier: Totaline - Humidifiers are beyond the scope of our inspections and needs to be serviced annually with the furnace

Attic

5. Attic Wiring/Lighting: 115v outlets and general lighting circuits -Install a j-box cover in the attic



Exterior Surface

6. Window Screens: Vinyl mesh screens - Missing screens, replace or locate for the buyer

12:06 March 28, 2022

PTI Home Inspections

Table of Contents

Definitions	6
General Information	6
Electrical	7
Air Conditioning	7
Plumbing	8
Heating System	9
Structure	10
Laundry Room/Area	10
Kitchen	10
Living Space	11
Bathroom	11
Attic	12
Roof	12
Garage/Carport	12
Exterior Surface	13
Lots and Grounds	13

Definitions

Satisfactory Major Defect	Satisfactory "Defect" means a condition that would have a significant adverse affect on the value of the property, that would significantly impair the health or safety of future occupants of the property, or that if not repaired, removed, or replaced would significantly shorten or adversely affect the expected normal life of the premises.
Minor Defect	"Defect" means a condition that would have a significant adverse affect on the value of the property, that would significantly impair the health or safety of future occupants of the property, or that if not repaired, removed, or replaced would significantly shorten or adversely affect the expected normal life of the premises.
Routine Maintenance	A list of some items that a homeowner would perform to maintain or up-keep the home properly as time, seasons, or finances permit. See seasonal maintenance checklist provided with the report.
Future Projects	A list of some important items requiring possible repair or replacement in the medium term.

General Information

Property Information

Property Address 1010 USA Drive City Fort Wayne State Indiana Zip 46818 Contact Name Best Realtors Phone Fax

Client Information

Client Name Mr & Mrs John Doe Client Address 2020 Freedom Drive City Fort Wayne State Indiana Zip 46814 Phone xxx-111-2020 Fax E-Mail JohnDoe@comcast.net

Inspection Company

Inspector Name Kevin Nichols Company Name PTI Home Inspections Address 407 North Main Street City Churubusco State Indiana Zip 46723 Phone 260) 693-0599 Fax Home Inspector #H100500182 #F212917 E-Mail kevin@ptihomeinspections.com File Number 032522 Amount Received \$365.00 Paid Check #00000

Conditions

Others Present Buyer's Agent Property Occupied Occupied Estimated Age 05-2007 Entrance Faces East Inspection Date 03-25-2022

General Information (Continued)

Start Time 1:45pm Electric On Yes Gas/Oil On Yes Water On Yes Temperature 55 degrees Weather Cloudy conditions, misting rain Soil Conditions Wet

Electrical

2. Satisfactory	00amp system Volts: 115v - 230v system Service: Underground service
Main Electric Panel	Manufacturen Caimana alastriaal nanal
3. Satisfactory	Manufacturer: Seimens electrical panel
4. Maximum Capacity: 2	200amp rated panel box
5. Satisfactory	Main Breaker Size: 200amp main breaker
6. Satisfactory	Conductor Type: 200amp #3-0 copper conductors
7. Satisfactory	Breakers: 115v and 230v
8. Satisfactory	120 VAC Branch Circuits: Copper Romex wiring, proper wire to breaker size
9. Satisfactory	240 VAC Branch Circuits: Copper Romex wiring, proper wire to breaker size
10. Satisfactory	Ground: Proper grounding of the electrical system
11. Satisfactory	Panel Bonded: Proper bonding of the electrical system
12. Satisfactory	Smoke/CO Detectors: Adequate smoke alarms in the home, Change smoke alarms every 5 years due to the loss of sensitivity, suggest a ABC fire extinguisher for home use

Air Conditioning

AC System -

- 1. Satisfactory Exterior Unit: Pad mounted PVC or concrete
- 2. Manufacturer: Bryant
- 3. Area Served: 1st floor of the home Approximate Age: 03-2007
- 4. Satisfactory Visible Coils: Aluminum coils
- 5. Satisfactory Refrigerant Lines: Insulated line
- 6. Satisfactory Electrical Disconnect: Breaker/blade/fuse disconnect is provided on the exterior of the home
- 7. Supply Temp: The unit was not run up to full temps
- 8. Return Temp: The unit was not run up to full temps
- 9. Differential Temp: The unit was not run up to full temps

Air Conditioning (Continued)

10. Routine Maintenance Cooling Operations: The AC was not tested due to the temperatures being < than 65 degrees for more than three day and nights and will damage the unit - Compressor motor ran, the unit could not be operated or brought up to temperature due to the outside temperature being below 65 degrees for more than 3 consecutive days and nights, review by a licensed HAVAC technician in the spring

Plumbing

- 1. Public Service: Yes
- 2. Private Well: No
- 3. Satisfactory Service Line: Pex water line
- 4. Satisfactory Main Water Shutoff: Located in the garage
- 5. Satisfactory Water Lines: PEX water lines, Manbloc system
- 6. Water PSI High: 59 psi
- 7. Gallons Per Minute: 8-10 gallons per minute
- 8. Satisfactory Functional Flow: Average water flow
- 9. Major Defect
 Water Softener: Culligan water softener Re generated at the inspection-service as regular maintenance
 The unit started leaking about 45 minutes into the RE generation, PTI contacted the sellers agent to inform of bypassing the unit and unplugging to stop further leaking and or damage, review and repair as needed
- 10. Public Waste System: Yes
- 11. Private Waste System: No
- 12. Satisfactory Type of Waste Lines: PVC waste lines
- 13. Satisfactory Waste Line C/O Cap Located at the side of the home in the landscaping
- 14. Satisfactory Gas Supply Lines: Black iron gas lines
- Garage Water Heater -
- 15. Satisfactory Water Heater Operation: Functional at time of inspection and is 18 off the garage floor surface
- 16. Manufacturer: Bradford-White
- 17. Type: Electric Capacity: 50 Gallon capacity
- 18. Approximate Age: 04-2018 Area Served: 1st floor of the home
- 19. Satisfactory TPRV and Drain Tube: TPR valve with 3/4" copper/PVC TPR extension pipe plumbed within 6" of the floor surface

Heating System

Heating System -

- 1. Service the Heating/Air Systems each season
- 2. Manufacturer: Bryant
- 3. Manufactures Date: 02-2007
- 4. Installation Date: 05-2007
- 5. Type Medium: Forced air system, sealed unit Capacity: 80,000 BTUHR
- 6. Fuel Type: Natural gas
- 7. Satisfactory Emergency Shut off Location: Gas and Electric shutoff valve is located at the unit
- 8. Furnace Fired: Yes
- 9. Heat Exchanger Access: Note: The heat exchanger is an intrusive inspection and is not a part of this inspection due to the fact that they are contained within the air handler and are not visible to the inspector.
- 10. Routine Maintenance Furnace Condition: No documentation of regular maintenance was found -

Regular service and maintenance is due, Service and maintenance by a licensed HAVAC technician is recommended

- 11. Satisfactory Thermostats: Digital stat
- 12. Satisfactory Gas/CO Leaks: No gas or carbon monoxide readings were noted at the time of the inspection, test readings were done at the furnace and at the registers in the home
- 13. Clearance from Combustibles: Yes
- 14. Combustable Air Source: Yes
- 15. Routine Maintenance Filter Size/Type: 16x25x4. Note: filters are directional, VISIT http://www.discountfilters.com for savings on filters - The filter was installed backwards, being newly changed it was turned around, PTI marked the
 - cover with the proper direction of the filter and its size
- 16. Satisfactory Distribution: Metal duct and or insulated flex duct
- 17. Suspected Asbestos: No
- 18. Heat supplies each room: Yes
- 19. Satisfactory Flue Pipe: PVC vented to the exterior of the home
- 20. Satisfactory Condensate Removal: PVC drain line to surface drain
- 21. Routine Maintenance Humidifier: Totaline Humidifiers are beyond the scope of our inspections and needs to be serviced annually with the furnace
- 22. Underground Fuel Tanks: No underground fuel tanks was noted

Structure

Please note that PTI Home Inspections looks for proper drainage around the home from gutters and downspouts, swale around the home, and negative slope towards the home. We want to see water draining away from the home. PTI Home Inspections can not determine how a home will react through out all the seasons or with unusual Amounts of water or days of consistent heavy rain saturating the soil. PTI Home Inspections can not determine the condition of HAVAC duct in a slab home or in these conditions.

- 1. Satisfactory Structure Type: Wood frame 2x4 2x6 construction
- 2. Satisfactory Foundation: Poured slab foundation
- 3. Satisfactory Differential Movement: No movement or displacement noted
- 4. Satisfactory Bearing Walls: Studded 2x4 2x6 materials

Laundry Room/Area

Laundry Room/Area -

- 1. Gas Available: No
- 2. 230V Available: Yes
- 3. Units Included: Yes
- 4. Units Tested: Yes
- 5. Satisfactory Washer Hose Bib: Gate valves
- 6. We recommend replacement of the washers water hoses each year to prevent unforeseen water damage.
- 7. Satisfactory Dryer Vent: Aluminum flex
- 8. Satisfactory Adequate Waste: Drains to the main lines

Kitchen

Kitchen -1. Satisfactory Cook Top/Oven: Electric cook top/oven 2. Satisfactory Ventilation: Ductless venting 3. Satisfactory Disposal: In-Sinkerator 4. Satisfactory Dishwasher: Tested-Operational at the time of the inspection 5. Satisfactory Refrigerator: Frost free with ice maker 6. Minor Defect Microwave: Tested operational and no microwave leaks was detected -Certain control buttons on the unit will not work such as CANCEL and FAN Review and repair as needed 7. Satisfactory Sink: PVC/Plastic sink and basin 8. Satisfactory Electrical: GFCI outlets are available, 115v outlets and general lighting circuits Plumbing/Fixtures: PVC drain lines and traps, no leaks was noted 9. Satisfactory 10. Satisfactory Counter Tops: Composit materials counter tops Cabinets: Oak cabinets 11. Satisfactory 12. Satisfactory Floor: Ceramic tile floor coverings

Living Space

Living Space	
1. Satisfactory	Closet: Small walk-in and large walk-in pantry/linen/bedroom closets
2. Satisfactory	Ceiling: Drywall materials with a painted finish
3. Satisfactory	Walls: Drywall materials with a painted finish
4. Satisfactory	Floor: Concrete with no floor coverings, Wood plank flooring
5. Satisfactory	Doors: Hollow wood panel doors
6. Satisfactory	Windows: Vinyl casement and fixed windows
7. Satisfactory	Electrical: 115v outlets and general lighting circuits
Family Room Fireplace	
8. Type: Gas log, sealed	lunit
9. Satisfactory	Fireplace Construction: Brick
10. Satisfactory	Fireplace Insert: Ceramic hearth
11. Satisfactory	Flue: Direct venting
12. Satisfactory	Hearth: Brick outer hearth

Bathroom

Master Bathroom	
1. Satisfactory	Floor: Vinyl floor covering
2. Satisfactory	Electrical: GFCI outlets are available, 115v outlets and general lighting circuits
3. Satisfactory	Sink/Basin: Single basin and base cabinet
4. Satisfactory	Faucets/Traps: PVC lines and trap, no leaking was noted
5. Satisfactory	Shower/Surround: Fiberglass pan and fiberglass surround
6. Satisfactory	Toilets: No leaking was noted and toilet is secured to the floor
7. Satisfactory	Ventilation: Electric ventilation fan
Family Bath Bathroom -	
Tanniy Dath Dath Oom –	
8. Satisfactory	Floor: Vinyl floor covering
5	Floor: Vinyl floor covering Electrical: GFCI outlets are available, 115v outlets and general lighting circuits
8. Satisfactory	Electrical: GFCI outlets are available, 115v outlets and general lighting
 8. Satisfactory 9. Satisfactory 	Electrical: GFCI outlets are available, 115v outlets and general lighting circuits
 8. Satisfactory 9. Satisfactory 10. Satisfactory 	Electrical: GFCI outlets are available, 115v outlets and general lighting circuits Sink/Basin: Single basin and base cabinet
 8. Satisfactory 9. Satisfactory 10. Satisfactory 11. Satisfactory 	Electrical: GFCI outlets are available, 115v outlets and general lighting circuits Sink/Basin: Single basin and base cabinet Faucets/Traps: PVC lines and trap, no leaking was noted
 8. Satisfactory 9. Satisfactory 10. Satisfactory 11. Satisfactory 12. Satisfactory 	Electrical: GFCI outlets are available, 115v outlets and general lighting circuits Sink/Basin: Single basin and base cabinet Faucets/Traps: PVC lines and trap, no leaking was noted Tub/Surround: Fiberglass tub and fiberglass surround

Attic

Αι		
1.	Satisfactory	Method of Inspection: Garage pull down ladder & Ceiling hatch access
2.	Satisfactory	Roof Framing: 2x10 Rafter system
3.	Satisfactory	Sheathing: 16/24 rated 7/16" OSB sheathing
4.	Satisfactory	Ventilation: Ridge and continual soffit vents
5.	Satisfactory	Insulation: Fiberglass batting, Blown in cellulose materials
6.	Satisfactory	Insulation Depth: 11"-12" in depth or R-38-40 in insulation values
7.	Routine Maintenance	Wiring/Lighting: 115v outlets and general lighting circuits - Install a j-box cover in the attic
8.	Satisfactory	Moisture Penetration: No water stains or water issues noted at the time of the inspection
9.	Satisfactory	Bathroom Fan Venting: Bathroom venting vents to the exterior of the home

Roof

Roof Surface -

- 1. Method of Inspection: Drone,, Ground level
- 2. Satisfactory Material: Composite material shingles-three dimentional shingles
- 3. Type: Gable roof system
- 4. Minor Defect
 4. Minor Defect
 5. Satisfactory
 6. Satisfactory
 7. Satisfactory
 Flashing: Aluminum flashing and rubber boots The waste vents rubber boot is dry rotted and cracked from the UV Rays from the sun and is prone to leak, replace the boot
 Valleys: Woven composite three dimensional shingle with a closed cut valley
 Plumbing Vents: PVC vents penetrate the roof line
 Gutters/Downspouts: Aluminum gutter/downspout system

Garage/Carport

Attached Garage 1. Type of Structure: 2x4, 2x6 construction Car Spaces: 3 bay garage 2. Satisfactory Garage Doors: Steel insulated overhead door Door Opener: Electric overhead door opener with I-beam safety reverse 3. Satisfactory devise, we recommend that the learn button be held down for 10 seconds to change the openers frequency from any other hand held openers or any vehicle that it may be programmed to for your protection and security 4. Satisfactory Fire Door: Metal fire rated fire door at the home to garage juncture 5. Satisfactory Electrical: GFCI outlets are available, 115v outlets and general lighting circuits Fire Wall: 5/8 drywall at the garage to home juncture 6. Satisfactory Floor/Foundation: Poured concrete slab 7. Satisfactory

Exterior Surface

Exterior Surface		
1. Satisfactory	Type: Vinyl siding, Brick veneer, Vinyl Shake Impressions	
2. Satisfactory	Trim: Cedar trim, Aluminum, Vinyl trim	
3. Satisfactory	Fascia: Aluminum trim	
4. Satisfactory	Soffits: Vinyl trim	
5. Satisfactory	Door Bell: Hard wired	
6. Satisfactory	Entry Doors: Metal insulated entry doors	
7. Satisfactory	Patio Door: Vinyl sliding patio door	
8. Routine Maintenance	Window Screens: Vinyl mesh screens - Missing screens, replace or locate	
	for the buyer	
9. Satisfactory	Exterior Lighting: Surface mount	
 Satisfactory 	Exterior Electric Outlets: GFCI outlets are available, 115v outlets	
1. Satisfactory	Hose Bibs: Gate valve type hose bibs	
2. Satisfactory	Gas Meter: Located at the side of the home	

Lots and Grounds

- 1. Satisfactory Driveway: Concrete driveway
- 2. Satisfactory Walks: Concrete walkways, public walkways
- 3. Satisfactory Patio: Poured stepping stone, Brick Pavers
- 4. Satisfactory Deck: Treated wood, Treated Wood Pergolas
- 5. Satisfactory Grading: Flat lot, Moderate slope
- 6. Satisfactory Vegetation: Keep all vegetation trimmed away from the home and foundation to prevent from retaining moisture that is conducive to insect infestation and water damage/rot
- 7. Satisfactory Retaining Walls: Block landscaping wall

Final Comments

Thank you for allowing us to perform your home inspection. It was a pleasure working with you. Please call with any questions.