HOME INSPECTION REPORT SUMMARY



157A Cumberland Street

Barrie, Ontario

Prepared by: Lee David Reich, RHI **Date:** August 31, 2023



Contact the selling agent to view the complete inspection report for this home.



HOME INSPECTION REPORT SUMMARY

This Report Summary reflects the key findings of our inspection at 157A Cumberland Street, Barrie.

ABOUT THE HOME

- Roofing: The roof is covered with laminated asphalt shingles.
- Exterior: Overall well maintained, typical maintenance suggested.
- **Structure:** This is a wood frame structure resting on a poured concrete and block foundation. The exterior walls are covered in brick. This is well-built home. There were no structural concerns identified.
- Electrical: There are two(2) 100-amp electrical services which is suitable for a home of this size with two dwellings units. The wiring is cooper, non-metallic sheathed.
- Heating: The high efficiency furnace is 24 years old with a typical life expectancy of 15-20 years. This home also has a gas fireplace on the main floor.
- Cooling: The central air conditioner is 15+ years old with a typical life expectancy of 10-15 years.
- **Plumbing:** The main water service pipe entering the home from the street is copper. The water distribution pipes within the home are copper and plastic. The 189 liter water heater is 5 years old with a typical life expectancy of 10-15 years.
- Interior: The upper level unit is been well maintained, the lower level unit appears to have had deferred maintenance.

ITEMS THAT MAY REQUIRE ATTENTION:

- Heating: The furnace is at the end of its life expectancy. Continue to use, service, and replace when necessary (Cost \$3,500 \$7,000).
- **Cooling:** The air conditioner is at the end of its typical life expectancy. Replace when necessary (Cost \$3,000 \$6,000).

FOR THE BUYER: This report summary is an unbiased overview of the home based on our inspection. Contact us to book an on-site review with the original inspector. This home includes warranty coverage for 30 days after closing, and the right to extend coverage to maintain the Certified Pre-Owned Home designation.

WHAT IS A HOME INSPECTION?

A home inspection is an in-field performance evaluation conducted to provide information about the present condition of the home, based on a visual inspection of the readily accessible features.

HOMEOWNERS ASSOCIATION

All of our clients receive complimentary membership in the Carson Dunlop Homeowners Association, which provides many benefits and exceptional value. In addition to lifelong technical advice and support, we partner with several companies to offer discounts on insurance, moving services, home maintenance / handyman services, junk removal, and more.





Get your exclusive Carson Dunlop discount at sonnet.ca

Get a Quote





Over 150,000 inspections performed since 1978.