

RIO GRANDE DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: ANTLERS PARK D

Reported By: Daniel Boyes

Date: May 7, 2019

Headgate	Latitude	Longitude
Location:	37.804463	-106.985115

Headgate Type: N/A

Headgate Condition:	A <input type="checkbox"/>	Diversion and Other Condition:	A <input type="checkbox"/>	River Miles from New Mexico State Line (Point of Diversion):	Structure Submerged: Yes <input type="checkbox"/>
	B <input type="checkbox"/>		B <input type="checkbox"/>		No <input checked="" type="checkbox"/>
	C <input checked="" type="checkbox"/>		C <input type="checkbox"/>	148.15 mi	
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input checked="" type="checkbox"/>		

Repair(s) or Improvement(s) Completed Since 2006:

Structure Description: This structure is located roughly 1 mile downstream of Marshall Park campground and has no diversion dam. The structure cannot access its full decree due to the ditch's location on the river and the poor condition of the headgate.

Repair(s) or Improvement(s) Currently Needed: Given these issues, the SMP Technical Advisory Team (TAT) recommends installing a new headgate and improving or relocating the diversion dam to effectively divert water at all flows.

Comments: This ditch is a priority 1903-51

Notes:

Estimated Range of Cost: Medium

Rio Grande downstream of diversion dam



RIO GRANDE DIVERSION INFRASTRUCTURE INVENTORY

ANTLERS PARK DITCH

PHOTO LOG

Rio Grande Stream
Management Plan



Antlers Park Ditch point of diversion location