

SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: MOSES GOFF D 1

Reported By: Daniel Boyes

Date: April 11, 2019

Headgate	Latitude	Longitude
Location:	38.100476	-106.228447

Headgate Type: Manually operated 2' screw gate

Headgate Condition:	A <input type="checkbox"/>	Diversion and Other Condition:	A <input type="checkbox"/>	Stream Miles from Saguache Creek Terminus (Point of Diversion):	Structure Submerged: Yes <input type="checkbox"/>
	B <input checked="" type="checkbox"/>		B <input checked="" type="checkbox"/>	23.73 mi	No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>		

Structure Description: The diversion dam is a 2' wide culvert with steel wing walls. The headgate is on the east bank of the stream, and, despite being tilted, it functions effectively.

Repair(s) or Improvement(s) Currently Needed: The headgate may require repair in the future, however no immediate repair needs were noted.

Comments: This ditch is a priority 11.

Notes:

Estimated Range of Cost: Low

Headgate looking downstream



Headgate outlet



Diversion dam looking downstream



Diversion dam looking upstream



Flume looking downstream



Flume looking upstream



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

MOSES GOFF D 1

PHOTO LOG

Saguache Creek Stream Management Plan