

NSX - Inspection (Translation)

Translation from the comments in the report:

Front tire fender right and left are missing. Engine compartment light remains on.

- Ventilation control does not work at all chosen speeds
- Alignment required
- Spare tire fixation to be fixed
- Windshield washer to adjust on the right side & unblock left
- Hood bracket missing
- Tie rod right slightly loose
- Car boot shock absorber do not work
- Tire usage is good but back tire may have rode soft

Signed: Thierry Frappier