

This drawing is to be read in conjunction with other consultants drawings.

2. Check site conditions prior to commencement of work. 3. Discrepancies must be reported directly to the Architect.

Canadian Roof Slates

Spanish Roof Slates

---- Overhead (or Below where noted)

Foul Water Connection Point

Surface Water Connection Point

Rev.

Project Address Buckland Hall, Bwlch, Brecon, LD3 7JJ Project Description | Building Alterations

Drawing Title Proposed First Floor Plan