



#### **ArbTS - Arboricultural Technician Services Ltd**

(Tree Consultancy Services)

Stephen Lucocq BSc (Hons), Tech Cert (ArborA), M.Arbor.A Professional Member of the Arboricultural Association

Web site: <a href="www.ArbTS.co.uk">www.ArbTS.co.uk</a>
Email: <a href="mailto:info@ArbTS.co.uk">info@ArbTS.co.uk</a>
Phone: (01639) 731 139
Mobile: 07789 551 591

# **Arboricultural Report**

Including:

Tree Survey Data &

Tree Constraints Plan,

**Arboricultural Impact Assessment** 

To the British Standard 5837:2012 (Trees in relation to design, demolition and construction. Recommendations)

Date - 26th October 2020

Site - Channel View, Cardiff

Project Reference - ArbTS\_827.1\_ChannelView

## **Table of Contents**

1.0	Introd	uction	1	3
2.0	The Tr	ee Sui	rvey	3
3.0	The Tr	ees		4
4.0	Tree C	onstra	aints Plan Information	4
5.0	Arbori	cultur	al Impact Assessment	5
6.0	Tree P	rotect	tion	7
7.0	Conclu	sion		7
8.0	Qualifi	catior	ns & Further Information	8
9.0	Bibliog	raphy	& Web Information	9
10.0	Appen	dix		
		1a	Tree Survey Data	
		1b	Detailed Tree Survey Data Summary	
	:	2	Tree Constraints Plan	
	:	3	Tree Survey Key	
	•	4	An Introduction to Tree Protection	
	!	5	Tree Photographs	
	(	6	Tree Impact Plan	

#### Copyright © 2020

ArbTS - Arboricultural Technician Services Ltd, 5 Weavers Road, Ystradgynlais, Powys, SA9 1PQ. All rights reserved.

No part of this report may be copied or reproduced by any means without prior written permission from ArbTS.

If you have received this report in error, please destroy all copies in your possession or control.

This report has been prepared for the exclusive use of the commissioning party and unless otherwise agreed in writing by ArbTS, no other party may use, make use of or rely on the contents of this report.

No liability is accepted by ArbTS for any use of this report, other than for the purposes for which it was originally prepared and provided. Opinions and information provided in the report are on the basis of ArbTS using due skill, care and diligence in the preparation of the same and no warranty is provided as to their accuracy.

Surveys are undertaken on the understanding that nothing in the final report will be omitted, amended or misrepresented by the client or any other interested party.

This report and its contents remain the property of ArbTS until payment has been made in full.

It should be noted and it is expressly stated that no independent verification of any of the documents or information supplied to ArbTS has been made.

#### 1.0 Introduction

- 1.1 The purpose of this report is to give an assessment to the quality of the trees at Channel View, Cardiff, and to assess the arboricultural impact of the proposed development design.
- 1.2 This report identifies the quality of the trees on this site as categorised by the *British Standard 5837:2012, Trees in relation to design, demolition and construction Recommendations*. The survey and findings as reported here, represent an unbiased third party opinion offering professional advice as to the value of the trees on this site. To illustrate the constraints identified trees pose to the design of future development a Tree Constraints Plan (TCP) has been drawn as found at Appendix 2.
- 1.3 Arboricultural constraints within the surveyed site relates primarily to the preservation of trees recommended for retention. Identified trees must be protected during the construction phase through the employment of a combination of tree protection methods as introduced in Appendix 4 An introduction to tree protection.
- 1.4 The tree's root system and the associated soil structure is often over looked during the construction process and can be damaged or altered by compaction causing major damage to the health of the tree. Generally the entire root system of the tree is within the top 600mm of soil where it can be easily damaged. A calculated area of ground around the tree should be protected for the duration of the onsite construction phase. In this report it is referred to as the Root Protection Area (RPA).

## 2.0 The Tree Survey

- 2.1 The tree survey was conducted by Stephen Lucocq *BSc (Hons), Tech Cert (ArborA), MArborA* on 20<sup>th</sup> and 21<sup>st</sup> October 2020. At the time of the survey no trees were marked with spray paint. This work was subsequently carried out by another contractor.
- Trees over 75mm were tagged where appropriate with numbered metal identification tags at around 2.0 metres above ground level.
- 2.3 All observations were made from the ground with the aid of an acoustic sounding hammer. No invasive decay detective instruments were used.
- 2.4 The survey was carried out in accordance to *British Standard 5837:2012, Trees in relation to design, demolition and construction Recommendations.* This standard gives a systematic, consistent and transparent evaluation method to tree surveying.
- 2.5 The survey was conducted with the aid of a topographical tree survey.
- 2.6 **Preliminary management recommendations:** The survey has identified preliminary management recommendation for the trees on or adjacent to this site. Details regarding these identified operations are given in this report (See Appendix 1 Tree Survey Data). Where work priority is stated to be H High due to safety reasons these operations should be carried out a soon as practically possible. Where work

- priority is stated to be M/H medium/high or higher these operations should be undertaken before commencement of any works on site.
- 2.7 Limitations of the tree survey: Whilst every effort is made to ensure an accurate assessment of the tree's condition is made during survey, no responsibility can be taken for resultant damage or injury occurred by a failing tree. The survey only gives a snap shot of what is visible and is not obscured on the day of the survey. The survey identifies trees of varying quality and there above ground/below ground constraints. This survey does not constitute to a full tree condition/tree risk assessment of the site and this report is only valid for 12 months from the date of the tree survey.

#### 3.0 The Trees

- 3.1 The full tree survey data can be found in Appendix 1A Tree Survey Data
- 3.2 Tree Survey Summary Table (See Appendix 3 for BS5837 category definitions). (A more detailed Tree Survey Data Summary can be found in Appendix 1B)

BS5837:2012 Quality Category	Total Number of Individual Trees Surveyed	Total Number of Tree Groups Surveyed	Total Number of Tree Areas Surveyed	Total Number of Woodland Areas Surveyed	Total Number of Hedgerows Surveyed	Total
A (High - Most desirable for retention)	2	0	0	0	0	2
B (Moderate - Desirable for retention)	40	6	0	0	0	46
C (Low - Optional for retention)	15	13	1	0	0	29
U (Poor - Unsuitable for retention)	0	0	0	0	0	0
Total A,B,C,U	57	19	1	0	0	77

## 4.0 Tree Constraints Plan (TCP) Information

4.1 A Tree Constraints Plan (TCP) can be found at Appendix 2 of this report. An introduction to TCP can also be found at the start of this Appendix Section. For further information and details regarding TCP please see the *British Standard 5837:2012*, Trees in relation to design, demolition and construction – Recommendations.

## 5.0 Arboricultural Impact Assessment (AIA)

- 5.1 The following Arboricultural Impact Assessment has been made for the proposed development design. A Tree Impact Plan can be found in Appendix 6. This plan illustrates the arboricultural impact of the proposal.
- 5.2.1 <u>Tree Loss -</u> The following table details the trees that are required to be removed to facilitate the construction of the proposed development design.

Tree ID loss (T – Individual Tree, G – Tree Group), species and description	Overall BS 5837 Category Quality Tree Loss (A – High, B- Moderate, C- Low, U – Poor)	Adverse impact onto the surrounding amenity (H -High, M - Medium, L-Low)	Adverse Arboricultural Impact (H -High, M - Medium, - L - Low)	Required Level of Landscape Mitigation (H -High, M -Medium, - L - Low)
T8 - Lime – Small tree adjacent to Channel View Road	С	M/L	M/L	M/L
<b>T7 – Hornbeam</b> – medium sized tree adjacent to Channel View Road	В	М	M	M
<b>T6 – Lime</b> – medium sized tree adjacent to Channel View Road	В	М	M	М
<b>T9- Lime</b> - medium sized tree adjacent to Channel View Road	В	М	M	М
<b>T10 – Lime</b> – medium sized tree adjacent to Channel View Road	В	М	M	М
T11- Lime – medium sized tree adjacent to Channel View Road	В	M	M	M
T12- Cherry – medium sized tree adjacent to Channel View Road	В	М	M	М
T13 Lime – medium sized tree adjacent to Channel View Road	В	М	M	М
T56- Leyland Cypress – small tree adjacent to Channel View Road	С	L	L	L
<b>T17 - Lime</b> – medium to large sized tree adjacent to South Clive Road. Forms first tree in avenue of trees along both side of road.	В	M/H	М/Н	M/H
T14 - Sycamore – medium sized tree within grounds of flats	В	М	М	М
<b>T57 - Sycamore</b> – small sized tree within grounds of flats	С	L	L	L
<b>T19 - Hornbeam –</b> small / medium sized tree alongside cut though footpath	В	M/L	M/L	M/L
<b>T31 - Hornbeam –</b> small / medium sized tree alongside cut though footpath	В	M/L	M/L	M/L
<b>T32 - Hornbeam –</b> small / medium sized tree alongside cut though footpath	В	M/L	M/L	M/L
<b>T33 - Hornbeam</b> – small / medium sized tree alongside cut though footpath	В	M/L	M/L	M/L
T34 - Cherry – medium sized tree within park area	В	M/L	M	М
T35 - Cherry – medium sized tree within park area	В	M/L	М	М
T36 - Cherry – medium sized tree within park area	В	M/L	M	М
T37 - Cherry – medium sized tree within park area	В	M/L	M	М
T38 - Ash – medium to large sized tree within park area	В	М	M	М

Tree ID loss (T – Individual Tree, G – Tree Group), species and description	Overall BS 5837 Category Quality Tree Loss (A – High, B- Moderate, C- Low, U – Poor)	Adverse impact onto the surrounding amenity (H -High, M - Medium, L- Low)	Adverse Arboricultural Impact (H -High, M - Medium, - L - Low)	Required Level of Landscape Mitigation (H -High, M -Medium, - L - Low)
T39 - Ash – medium to large sized tree within park area	В	M	M	М
<b>T40 - Ash</b> – medium to large sized tree within park area	В	М	М	М
<b>T41 – Norway Maple</b> – medium to large sized tree within park area	В	М	М	М
T42 – Aspen – small tree on edge of park area	С	L	L	L
${f G6}$ – 77 m2 small group of mainly short cherry trees in grounds of flat	С	M/L	M/L	M/L
<b>G13</b> – Small group of three trees - birch and ash	С	M/L	M/L	M/L
G12 – Small group of Leyland cypress trees	С	L	L	L
<b>G11</b> – Two Norway Maples forming a whole located on edge of park area and footpath	В	М	М	М
<b>G1</b> – 440m2 Tree group of a mixture of species, overgrown, sprawling with little recent management noted	С	М	M/L	M/L
<b>G9</b> - 140m2 Tree group of a mixture of species, overgrown, sprawling with little recent management noted	С	M/L	M/L	M/L
<b>G7</b> - 110m2 Tree group of a mixture of species, overgrown, sprawling with little recent management noted	С	M/L	M/L	M/L
<b>G3</b> - 400m2 Tree group of a mixture of species, overgrown, sprawling with little recent management noted	С	М	M/L	M/L
<b>G2</b> – 20 metre Tree group of a mixture of species, overgrown, sprawling with little recent management noted	С	M/L	M/L	M / L
<b>G14</b> – 20 metre Tree group of hawthorn, overgrown, sprawling with little recent management noted	С	M/L	M/L	M/L
<b>G4</b> – 480m2 Tree group of a mixture of species, overgrown, sprawling with little recent management noted	С	M/L	M/L	M / L

#### 5.2.2 Overall Tree Loss for Proposed Design –

A number of trees are identified to be removed to facilitate the construction of the proposed development design. 21 B (moderate quality) category trees and 1 B (moderate quality) category tree group are required to be removed to facilitate the construction of the proposed design. In addition, 4 C (low quality) category trees and 10 C (low quality) category tree groups are also required to be removed to facilitate the construction of the proposed design. The removal of these trees can be mitigated for through a proportional compensatory tree planting scheme.

- 5.3 <u>Root Protection Area (RPA)</u> –RPA potential damage can be managed through the installation of temporary ground protection, arboricultural watching brief, excavation method statement and tree protective fencing etc will ensure that no significant long term adverse impact will occur to any of the retained trees' root system or associated soil structure.
- 5.4 <u>Tree surgery work Some general minor maintenance tree pruning through the site</u> will also be expected on a scheme of this nature. This work is to be carried out to the *British Standard 3998:2010 tree work recommendations.* Adhering to this standard will ensure no adverse impact onto the long term health or visual amenity of the trees will occur.
- 5.5.1 AIA Conclusion The site has a number of Arboricultural constraints that needed to be considered in the development design phase. A number of trees are identified to be removed to facilitate the construction of the proposed development design. Many of these trees are low quality that should not present a constraint on developing the site. Through suitable and proportional compensatory tree planting this loss can be offset to an acceptable level.
- 5.5.2 The proposal will not cause a long term adverse impact onto the local amenity of the area through tree loss. Mitigative tree, hedgerow and shrub planting will be required for the loss of the trees on this site through a combination of different diverse tree/shrub species and varied nursery aged stock.
- 5.5.3 The construction of the proposed development whilst complying to a suitable scheme for tree protection will ensure that no significant long term adverse Arboricultural impact occurs onto the health of any retained trees on or adjacent to this site or to the long term amenity of the area.

#### 6.0 Tree Protection

6.1 No Tree Protection Plan or Tree Protection Method Statement are included within this report. An introduction to Tree Protection can be found in Appendix 4.

#### 7.0 Conclusion

7.1 The proposal will not cause a long term adverse impact onto the local amenity of the area through tree loss. Mitigative tree, hedgerow and shrub planting and aftercare will be required for the loss of the trees on this site through a combination of different tree/shrub species and diverse nursery aged stock. Further to this, tree protection methods must be designed and implemented by an Arboriculturist to ensure no adverse impact occurs onto all the retained trees/shrubs during the entire construction phase.

### 8.0 Further Information & Qualifications

Stephen Lucocq has been involved in Arboriculture within South Wales for over twenty years. He has worked as an Arborist for many of these years and has a good working knowledge of the practical side of the profession. He has always taken an active interest in all areas of Arboriculture and kept up to date with current research and developments.

#### Qualifications

- First Class BSc (Hons) Degree Combined Studies Biology and IT
- Arboricultural Association Technicians Certificate Level 4 (Merit)
- PTI Professional Tree Inspection (Lantra Awards)
- 2D Computer Aided Design (City and Guilds Level 3)
- Quantified Tree Risk Assessment (QTRA) Mike Ellison
- Visual Tree Assessment (VTA) Mike Ellison
- Arboriculture and Bats (Lantra)
- Industrial Rope Access Trade Association (IRATA)
- Practical Arboriculture Qualifications (NPTC)

#### Membership

Arboricultural Association Professional Member (M.Arbor.A)

### 9.0 Web Information & Bibliography

#### Web Information

Arboricultural Association

http://www.trees.org.uk/

Cellular Confinement System

GeoWeb - GreenFix

CellWeb - Geosynthetics Cellweb

Underground Utilities Installation

http://www.njug.org.uk/

#### Bibliography

- British Standards 3998 (2010) Recommendations for Tree Work UK; British Standards Intuition
- British Standard 5837:2012, Trees in relation to design, demolition and construction - Recommendations UK; British Standards Intuition
- Coombes, A.J (1992) Trees London; Dorling Kindersley
- Lonsdale, D (1999) Principle of Tree Hazard Assessment and Management Edinburgh; Forestry Commission
- Mattheck, C (2007) Field Guide for Visual Tree Assessment Germany;
   Karlsruhe Research Centre
- Shigo, A.L (1991) Modern Arboriculture USA; Shigo and Trees, Association
- Sterry, P (2007) Collins Complete British Trees London; Collins
- Strouts, R.G (2000) Diagnosis of ill-health in trees Edinburgh; Forestry Commission
- Weber,K & Mattheck, C (2003) Manual of wood decay UK; Arboricultural Association

# 10.0 Appendix 1A -Tree Survey Data

Tree ID	Tree Species	Age	Stems	Stem Diam	Cat	Height + (Lower Branch	Nrth	Est	Sth	Wst	Phys Cond	Struc Cond	Est. Remain	Comments	Preliminary Management Recommendations	Work Priority	RPR (m)	RPA (m2)
A1	Acer pseudoplatanus (Sycamore),Fraxinus excelsior (Ash),Corylus avellana (Hazel)	EM	1	300	C1	Height) 7(0)	5	5	5	5	F	F	Contrib 10+	Surrounding terrain prevented close inspection of the tree therefore all observations and measurements are estimated.  area of small trees and scrub alongside river bank, mainly multistem, short and sprawling in form			` '	40.72
G1	Prunus avium (Wild Cherry),Populus spp (Poplar spp),Fraxinus excelsior (Ash),Buddleja (Buddleja)	EM	1	400	C2	14(0)	4	4	4	4	F	F	10+	Surrounding vegetation prevented close inspection of the tree therefore all observations and measurements are estimated.			4.8	72.39
G2	Betula pendula (Silver Birch),Pinus spp (Pine),Prunus avium (Wild Cherry),Crataegus monogyna (Hawthorn),Alnus glutinosa (Common Alder),Acer campestre (Field Maple)	EM	1	300	C2	10(0)	5	5	5	5	F	F	10+	sprawling area of unmanaged trees and scrub			3.6	40.72
G3	Betula pendula (Silver Birch),Buddleja (Buddleja),Salix caprea (Goat Willow),Sorbus aucuparia (Rowan),Populus tremula (Aspen),Salix fragilis (Crack Willow)	М	1	400	C2	12(0)	4	4	4	4	F	F	10+	Surrounding vegetation prevented close inspection of the tree therefore all observations and measurements are estimated.			4.8	72.39
G4	Betula pendula (Silver Birch),Salix caprea (Goat Willow),Prunus avium (Wild Cherry),Quercus robur (Common Oak)	EM	1	350	C2	10(0)	5	5	5	5	F	F	10+	Surrounding vegetation prevented close inspection of the tree therefore all observations and measurements are estimated.  Sprawling area of trees and scrub, limited access into tree group, appears to have received limited recent management			4.2	55.42
G5	Prunus avium (Wild Cherry)	М	1	250	C2	8(0)	3	3	3	3	G/F	N/A	10+	Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.			3	28.28
G6	Prunus avium (Wild Cherry),Betula pendula (Silver Birch)	М	1	350	C2	6(2)	4	4	4	4	F	F	10+	group of small trees			4.2	55.42
G7	Betula pendula (Silver Birch),Buddleja (Buddleja),Acer campestre (Field Maple),Corylus avellana (Hazel)	EM	1	300	C2	9(0)	4	4	4	4	F	F	10+	sprawling area of unmanaged trees and scrub			3.6	40.72

Tree ID	Tree Species	Age	Stems	Stem Diam (mm)	Cat	Height + (Lower Branch Height)	Nrth	Est	Sth	Wst	Phys Cond	Struc Cond	Est. Remain Contrib	Com	ments	Preliminary Management Recommendations	Work Priority	RPR (m)	RPA (m2)
G8	X Cupressocyparis leylandii (Leyland Cyp),Fruit tree spp (Fruit tree spp)	EM	1	450	C2	11(0)	3.5	3.5	3.5	3.5	G/F	F	10+		unmanaged row of leylandii and one small fruit tree			5.4	91.62
G9	Prunus avium (Wild Cherry),Fraxinus excelsior (Ash),Buddleja (Buddleja),Acer campestre (Field Maple),Corylus avellana (Hazel)	EM	1	250	C2	8(0)	3	3	3	3	F	F	10+	Surrounding vegetation prevented close inspection of the tree therefore all observations and measurements are estimated.				3	28.28
G10	Populus tremula (Aspen)	SM	1	200	C2	7(1)	2.5	2.5	2.5	0.2	G/F	G/F	20+	high C category.	group of two small aspen trees of fair to good form			2.4	18.1
G11	Acer platanoides (Norway Maple)	М	1	420	B2	12(3)	5	5	5	5	G/F	F	20+	low B category. Suckers around stem base.	group of two sycamore trees forming a whole			5.04	79.81
G12	X Cupressocyparis leylandii (Leyland Cyp)	EM	1	300	C2	6(0)	4	4	4	4	F	F	10+	Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.				3.6	40.72
G13	Betula pendula (Silver Birch),Fraxinus excelsior (Ash)	EM	1	250	C2	9(2)	3	3	3	3	G/F	N/A	10+	Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.	group of two birch and one small ash			3	28.28
G14	Crataegus monogyna (Hawthorn)	EM	1	200	C2	4(0)	4	4	4	4	F	F	10+		small sprawling area of unmanaged hawthorn			2.4	18.1
G15	Populus spp (Poplar spp)	EM	1	430	B2	18(3)	3	3	3	3	G/F	G/F	20+	low B category.	row of upright poplar trees, some surface root damage noted			5.16	83.66
G16	Populus spp (Poplar spp)	EM	1	430	B2	18(3)	3	3	3	3	G/F	F	20+	low B category.	row of upright poplar trees, some surface root damage noted, footpath tarmac root damage noted			5.16	83.66
G17	Populus spp (Poplar spp)	EM	1	400	B2	18(3)	3	3	3	3	G/F	F	20+	low B category.	row of upright poplar trees			4.8	72.39

Tree ID #	Tree Species	Age	Stems	Stem Diam (mm)	Cat	Height + (Lower Branch Height)	Nrth	Est	Sth	Wst	Phys Cond	Struc Cond	Est. Remain Contrib	Comments	Preliminary Management Recommendations	Work Priority	RPR (m)	RPA (m2)
G18	Populus spp (Poplar spp)	М	1	1250	B2	27(4)	10	10	10	10	G/F	F	20+	low B category. group of varying poplar tree specie manyy are large in form	5,		15	707
G19	Ulmus spp (Elm spp)	EM	1	350	B2	10(2)	5	5	5	5	G/F	G/F	20+	row of elm trees			4.2	55.42
	Acer platanoides (Norway Maple)	Z	1	490	B2	11(5)	5	5	5	5	G/F	G/F	20+	street tree growing from pavemen planting pit			5.88	108.6
	Tilia X europaea (Common Lime)	М	1	400	B2	12(3)	4	3	4	4	G/F	G/F	20+	street tree growing from pavemen planting pit			4.8	72.39
	Acer platanoides (Norway Maple)	M	1	380	B2	9(4)	4	5	4	3	G/F	F	20+	street tree growing from pavemen planting pit			4.56	65.33
T4	Tilia cordata (Small-leaved Lime)	M	1	400	B2	11(4)	6	5	4	4	G/F	G/F	20+	street tree growing from pavemen planting pit			4.8	72.39
	Tilia platyphyllos (Large- leaved Lime)	M	1	450	B2	12(4)	5	5	5	5	G/F	G/F	20+	street tree growing from pavemen planting pit				91.62
T6	Tilia X europaea (Common Lime)	M	1	350	B2	11(3)	4	4	4	4	G/F	G/F	20+	twin stem, tree of fair to good form			4.2	55.42
Т7	Carpinus betulus (Hornbeam)	M	1	350	B2	11(4)	4	4	4	4	G/F	G/F	20+	tree of fair to good form			4.2	55.42
	Tilia X europaea (Common Lime)	М	1	330	C2	7(3)	2	4	3	4	F	F	10+	high C category. street tree growing from pavemen planting pit, large root growth, sho tree of fair form			3.96	49.27
Т9	Tilia X europaea (Common Lime)	М	1	350	B2	9(2)	4	4	4	4	G/F	G/F	20+				4.2	55.42
	Tilia X europaea (Common Lime)	М	1	350	B2	9(2)	4	4		4	G/F	G/F	20+					55.42
	Tilia X europaea (Common Lime)	М	1	400	B2	9(2)	4.5		4.5	4.5	G	G		high B category.				72.39
T12	Prunus avium (Wild Cherry)	М	1	550	B2	9(2)	5	5	5	5	G/F	G/F	20+	tree of fair to good form and healt			6.6	136.9
T13	Tilia X europaea (Common Lime)	M	1	350	B2	10(3)	4	4	4	4	G/F	G/F	20+	high canopy tree from branch pruning			4.2	55.42

Tree ID	Tree Species	Age	Stems	Stem Diam (mm)	Cat	Height + (Lower Branch Height)	Nrth	Est	Sth	Wst	Phys Cond	Struc Cond	Est. Remain Contrib	Com	ments	Preliminary Management Recommendations	Work Priority	RPR (m)	RPA (m2)
T14	Acer pseudoplatanus (Sycamore)	М	1	500	B2	10(3)	6	6	6	6	G/F	N/A	20+	high B category. Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.	tree of good form			6	113.1
T15	Robinia pseudoacacia (Locust Tree)	М	1	450	B2	10(2)	6	6	6	6	G/F	G/F	20+	Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.				5.4	91.62
T16	Betula pendula (Silver Birch)	М	1	400	B2	12(2)	4	4	4	4	G/F	N/A	20+	low B category. Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.				4.8	72.39
T17	Tilia cordata (Small-leaved Lime)	М	1	500	B2	11(4)	6	6	6	6	G/F	G/F	20+		street tree growing from pavement planting pit, hanging branch in crown, wound to trunk with surrounding reactive growth noted	removing hanging branch from crown	H/M	6	113.1
T18	Tilia cordata (Small-leaved Lime)	М	1	400	B2	11(5)	5	5	5	5	G/F	G/F	20+		street tree growing from pavement planting pit			4.8	72.39
T19	Carpinus betulus (Hornbeam)	М	1	250	B2	8(4)	3	3	4	4	F	F	20+	low B category.	growing within amenity grass area, tree of fair form, twin leader, trunk damage with surrounding callus growth noted			3	28.28
T20	Fruit tree spp (Fruit tree spp)	М	1	310	C2	6(3)	3	3	3	4	F	F	20+		small tree located in the park, wound to trunk with surrounding reactive growth noted			3.72	43.48
T21	Acer platanoides (Norway Maple)	М	1	470	B2	11(2.5)	5	5	5	5	G/F	G/F	20+		tree of fair to good form, some surface root damaged noted, located in the park			5.64	99.95
T22	Acer platanoides (Norway Maple)	М	1	290	B2	8(3)	3	3	3	3	G/F	F	20+		tree of fair form located in the park, some surface root damaged noted			3.48	38.05
T23	Acer platanoides (Norway Maple)	М	1	400	B2	9(2.5)	4	4	4	4	G/F	F	20+		tree of fair form and health, some surface root damaged note, located in the park			4.8	72.39
T24	Acer platanoides (Norway Maple)	М	1	410	B2	10(2.5)	4	5	6	5	G/F	F	20+	low B category. Suppressed growth from large adjacent tree.	small tree located in the park			4.92	76.06

Tree ID #	Tree Species	Age	Stems	Stem Diam (mm)	Cat	Height + (Lower Branch Height)	Nrth	Est	Sth	Wst	Phys Cond	Struc Cond	Est. Remain Contrib	Comme	nents	Preliminary Management Recommendations	Work Priority	RPR (m)	RPA (m2)
T25	Quercus ilex (Holm Oak)	М	1	620	A2	11(2)	5.5	5.5	5.5	5.5	G	G	40+	h sı le	open grown tree of good form and health, wound noted on stem with surrounding reactive growth, twin leader from 2 metres, tree located in the park			7.44	173.9
T26	Fruit tree spp (Fruit tree spp)	EM	1	150	C2	4(2)	2	0	0	2	F	F	10+	Suppressed growth from large adjacent tree.	small tree located in the park			1.8	10.18
T27	Fruit tree spp (Fruit tree spp)	EM	1	160	B2	6(2)	2	2	2	2	G	G	20+		small upright tree of good form located in the park			1.92	11.58
T28	Fruit tree spp (Fruit tree spp)	М	1	270	C2	5(2.5)	3	4	3	3	G/F	F	10+	w	small tree located in the park, wounds to trunk with surrounding reactive growth noted			3.24	32.98
T29	Fruit tree spp (Fruit tree spp)	EM	1	150	C2	3(2)	1	4	2	0	F	F	10+	Suppressed growth from large adjacent tree.	small tree located in the park			1.8	10.18
T30	Fruit tree spp (Fruit tree spp)	EM	1	110	B2	6(2)	2	1	2	2	G	G	20+		small upright tree of good form located in the park			1.32	5.47
T31	Carpinus betulus (Hornbeam)	М	1	250	B2	7(4)	4	3	4	4	F	F	10+		growing within amenity grass area, tree of fair form			3	28.28
T32	Carpinus betulus (Hornbeam)	М	1	370	B2	8(4)	5	4	5	5	G/F	G/F	20+		growing within amenity grass area, tree of fair to good form and health			4.44	61.94
T33	Carpinus betulus (Hornbeam)	М	1	340	B2	8(4)	4	4	4	4	G/F	G/F	20+		growing within amenity grass area, tree of fair to good form and health			4.08	52.3
T34	Prunus avium (Wild Cherry)	М	1	310	B2	9(2.5)	5	3	4	4	G/F	G/F	20+		tree of fair to good form and health located in the park			3.72	43.48
T35	Prunus avium (Wild Cherry)	М	1	300	B2	9(2.5)	4	2	3.5	4	G/F	G/F	20+	1	tree of fair to good form and health located in the park			3.6	40.72
T36	Prunus avium (Wild Cherry)	М	1	310	B2	10(2.5)	4	4	3.5	3	G/F	G/F	20+		tree of fair to good form and health located in the park			3.72	43.48
T37	Prunus avium (Wild Cherry)	М	1	300	B2	10(2.5)	3	3	4	4	G/F	G/F	20+		tree of fair to good form and health located in the park			3.6	40.72
T38	Fraxinus excelsior (Ash)	М	1	600	B2	16(3.5)	6	7	4	5	G/F	G/F	20+	lc c	tree of fair to good form and health located in the park, twin stem, currently no signs of ash dieback disease			7.2	162.9

Tree ID	Tree Species	Age	Stems	Stem Diam (mm)	Cat	Height + (Lower Branch Height)	Nrth	Est	Sth	Wst	Phys Cond	Struc Cond	Est. Remain Contrib	Com	ments	Preliminary Management Recommendations	Work Priority	RPR (m)	RPA (m2)
T39	Fraxinus excelsior (Ash)	М	1	430	B2	14(3.5)	4	6	5	6	G/F	F	20+	low B category. Unbalanced crown shape. Suppressed growth from surrounding trees.	tree of fair to good form and health located in the park, currently no signs of ash dieback disease			5.16	83.66
T40	Fraxinus excelsior (Ash)	М	1	600	B2	15(3.5)	7	7	6	7	G/F	G/F	20+	high B category.	tree of fair to good form and health located in the park, currently no signs of ash dieback disease			7.2	162.9
T41	Acer platanoides (Norway Maple)	М	1	500	B2	13(5)	4	5	5	5	G/F	G/F	20+		tree of fair to good form and health located in the park, occluding northern trunk wound noted, some surface root damage and reactive growth noted			6	113.1
T42	Populus tremula (Aspen)	SM	1	150	C2	7(1)	2	2	1	1	G/F	G/F	10+	Suppressed growth from large adjacent tree.				1.8	10.18
T43	Betula pendula (Silver Birch)	М	1	400	B2	9(2)	4	3	4	3	G/F	N/A	20+	low B category. Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.	tree of fair to good form and health			4.8	72.39
T44	Betula pendula (Silver Birch)	М	1	300	C2	12(1)	3	3	3	3	G/F	F	10+	low B category. Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.	tree of fair form, slender			3.6	40.72
T45	Fruit tree spp (Fruit tree spp)	EM	1	90	C2	3(2)	1	1	1	1	G/F	F	10+		small tree with some trunk damage			1.08	3.66
T46	Fruit tree spp (Fruit tree spp)	EM	1	90	C2	3(2)	2	2	2	2	G/F	F	10+		small tree			1.08	3.66
T47	Fruit tree spp (Fruit tree spp)	EM	1	120	C2	3(2)	2	2	2	2	G/F	G/F	10+		small tree			1.44	6.52
T48	Crataegus monogyna (Hawthorn)	EM	1	220	C2	3(2)	3	3	3	3	G/F	F	10+		small tree, twin stem from near ground level			2.64	21.9
T49	Fruit tree spp (Fruit tree spp)	EM	1	150	B2	6(2)	2	2	2	2	G	G	20+		small upright tree of good form located in the park			1.8	10.18
T50	Ulmus spp (Elm spp)	EM	1	270	B2	6(2)	3	3	3	3	G	G	20+		upright tree of good form located in the park			3.24	32.98
T51	Populus spp (Poplar spp)	EM	1	400	C2	10(3)	3	3	3	3	G/F	F	10+	high C category.				4.8	72.39
T52	Prunus avium (Wild Cherry)	М	1	280	B2	8(3)	3	3.5	3	3.5	G/F	G/F	20+		end tree in row of cherry trees			3.36	35.47

Tree ID #	Tree Species	Age	Stems	Stem Diam (mm)	Cat	Height + (Lower Branch Height)	Nrth	n Est	Sth	Wst	Phys Cond	Struc Cond	Est. Remain Contrib	Comm	nents	Preliminary Managem	ent Recommendations	Work Priority		RPA (m2)
T53	Tilia cordata (Small-leaved Lime)	М	1	550	A2	10(1)	8	8	8	8	G	G	40+		tree of good form and health				6.6	136.9
T54	Populus spp (Poplar spp)	М	1	1100	B2	24(4)	4	4	4	4	G/F	F	20+		tall tree, area of decay noted between buttresses on northern side that penetrates a small distance into the trunk when probed with metal rode, surrounding outer reactive growth on outer buttresses noted		carry out decay detection of trunk to determine residual wall thickness	н/м	13.2	547.5
T55	Populus spp (Poplar spp)	EM	1	350	C2	10(3)	3	3	3	3	G/F	F		high C category. Suckers around stem base.					4.2	55.42
T56	X Cupressocyparis leylandii (Leyland Cyp)	EM	1	200	C2	7(3)	3	3	3	3	F	F	10+						2.4	18.1
T57	Acer pseudoplatanus (Sycamore)	М	1	300	C2	8(3)	4	4	4	4	G/F	N/A		Located on private land preventing a close inspection of the tree therefore all observations and measurements are estimated.	small tree				3.6	40.72

## 10.0 Appendix 1B – Detailed Tree Survey Data Summary

(Please see Appendix 3 - Tree Survey Key)

Field Usage Results.		
Total Records: 77		
		% of
Tree Species	Count	Total
Acer platanoides (Norway Maple)	8	10.4
Tilia X europaea (Common Lime)	7	9.1
Tilia cordata (Small-leaved Lime)	4	5.2
Tilia platyphyllos (Large-leaved Lime)	1	1.3
Carpinus betulus (Hornbeam)	5	6.5
Prunus avium (Wild Cherry)	7	9.1
Acer pseudoplatanus (Sycamore)	2	2.6
Robinia pseudoacacia (Locust Tree)	1	1.3
Betula pendula (Silver Birch)	3	3.9
Fruit tree spp (Fruit tree spp)	10	13
Quercus ilex (Holm Oak)	1	1.3
Fraxinus excelsior (Ash)	3	3.9
Populus tremula (Aspen)	2	2.6
X Cupressocyparis leylandii (Leyland Cyp)	2	2.6
Crataegus monogyna (Hawthorn)	2	2.6
Ulmus spp (Elm spp)	2	2.6
Populus spp (Poplar spp)	7	9.1
		% of
Туре	Count	Total
Т	57	74
G	19	24.7
А	1	1.3
Cat	Count	% of Total
Cat A2	2	2.6
B2	46	59.7
C1	1	1.3
<u>C2</u>	28	36.4
		% of
Age	Count	Total
SM	2	2.6
EM	27	35.1
М	48	62.3

		% of
Average Stem Diameter	Count	Total
<100	2	2.6
<150	2	2.6
<250	9	11.7
<500	54	70.1
<750	8	10.4
<2000	2	2.6
		% of
Height	Count	Total
<5	7	9.1
<10	33	42.9
<15	30	39
<20	5	6.5
<25	1	1.3
<30	1	1.3
		2/ 5
Phy Cond	Count	% of Total
G	7	9.1
		68.8
G/F	53	
F	17	22.1
		% of
Stuc Cond	Count	Total
G	7	9.1
G/F	29	37.7
F	35	45.5
N/A	6	7.8
		% of
Est. Remain Contrib	Count	Total
10+	27	35.1
20+	48	62.3
40+	2	2.6
		% of
RPR	Count	Total
<5	58	75.3
<10	17	22.1
<15	1	1.3
<20	1	1.3
DDA.	Caat	% of
RPA	Count	Total
<5	2	2.6


<10	2	2.6
<15	5	6.5
<20	3	3.9
<25	1	1.3
<30	5	6.5
other	59	76.6

## 10.0 Appendix 2 - Tree Constraints Plan

### An introduction to the Tree Constraints Plan (TCP)

Trees that have been identified to be retained should be treated as constraints to the design of future development. A Tree Constraints Plan has been drawn and can be found over leaf.

- Tree Quality The TCP highlights the above and below ground constraint each tree poses to the design of future development schemes. Further to this the BS5837 tree quality category (A High, B Moderate, C Low and U- Unsuitable for retention) are coloured coded as solid circles at the centre of the trees position.
- Root Protection Area As shown as cyan circle on the TCP sets out root protection area (RPA). Within this area no construction work, alteration in ground levels or site traffic (machinery or persons) should occur. This prevents damage to tree roots and soil compaction. (Where possible an Arboriculturist can design suitable tree protection methods to facilitate construction work/site traffic within these areas).
- Tree Canopy The green circle/oval on the TCP sets out the above ground constraints of tree canopy spread. Within this area no construction work or site traffic (machinery or persons) should occur if the tree is to be retained. This prevents damage to the tree branches and trunk. (Where possible an Arboriculturist can design suitable tree protection methods to facilitate construction work/site traffic within these areas).
- Tree Shading Shade from the retained trees should be considered in the development design. The shade cast, depending on the trees height and width, will be from a North West to East pattern through the main part of the day.
- Tree Future growth Within future development design, consideration should also be given to the ultimate height and extent of the canopy spread of all trees within the site identified to be retained.





## 10.0 Appendix 3 - Tree Survey Data Key

- Tree ID # Identifies the location of individual trees (T-ID Number), Groups of trees (G-ID Number), Area of trees (A-ID Number), Hedgerow (H-ID Number), Woodland (W-ID Number), Row of trees (R-ID Number) and tree Stumps (S-ID Number) on the accompanying plan. (Please note: A group of trees here refers to two or more standing trees that form a visual whole, whereas an area of trees refers to dispersed individual trees standing within the site)
- **Tree Species** Scientific names and common tree name in brackets are generally shown.
- Age
  - o (Y) Young Less than 1/3 of life completed
  - o (SM) Middle Aged 1/3 2/3 of life completed
  - o (EM) Early Mature Just entering Maturity
  - o (M) Mature more than 2/3 of life completed
  - o (OM) Over Mature more than 3/3 of life completed and declining
  - (V) Veteran (v) Veteran Veteran trees have no precise definition but are trees considered to be of biological aesthetic or ecological value because of their age
- Stems Number of tree stems used to calculate the RPR/RPA
- Stem Diam (mm) Diameter of tree stem measured in millimetres for single stem trees or average stem diameter calculated for multi-stemmed trees as detailed in section 4.6 & Annex C of the British Standard 5837:2012, Trees in relation to design, demolition and construction Recommendations. The height above ground level where the stem measurement was taken will be shown if not measured at 1.5 metres above ground level. (Please note: that the stem diameter of certain trees will have to be estimated due to difficulties in taking measurements or for trees with a large number of stems)
- Cat Tree Quality Category British Standard 5837:2012 A, B, C, U + 1, 2, 3

Based on BS5837:2012 categories A, B, C, U provides the basis of prioritising trees for retention:

- o A Those of high quality with an estimated remaining life expectancy of at least 40 years. (\*Most desirable for retention\*)
- o B Those of moderate quality with an estimated remaining life expectancy of at least 20 years. (\*Desirable for retention\*)
- o C Those of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150mm. (\*Optional for retention\*)
- o U Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years. (\*Unsuitable for retention unless provides high conservation value\*)

Retention Criteria Subcategories: Used for identifying subcategories

E.g. A2 = A high quality tree with a high landscape qualities (further details can be found in British Standard 5837:2012, Trees in relation to design, demolition and construction - Recommendations UK; British Standards Intuition)

- o 1 Mainly Arboricultural qualities
- o 2 Mainly landscape qualities
- o 3 Mainly cultural values, including conservation
- Height + (Lower Branch Height) Tree height in metres and in brackets height in metres of the crown (tree branches) clearance at its lowest point above adjacent ground levels.
- Nrth, Est, Sth, Wst Crown Spread (Metres) -Tree branch spread in metres measured in four directions (North, East, South, West) from the trunk.
- Phys Cond Physiological Condition Indicating the health of the tree
  - o (G) Good
  - o (F) Fair
  - o (P) Poor
  - o (D) Dead
- Struc Cond Structural Condition indicting the structural integrity of the tree
  - o (G) Good No, or remediable physical defects or decay
  - o (F) Fair Physical non-remediable defects or decay present, not presenting imminent danger but should be monitored
  - o (P) Poor physical non-remediable defects or decay present, tree liable to imminent collapse or loss of major limbs.
  - o (D) Dead
- Est. Remain Contrib (<10, 10+, 20+, 40+)</li>

The trees estimated remaining contribution in years, recorded as:

- o <10 less than 10 years
- o 10+ at least 10 years
- o 20+ at least 20 years
- o 40+ at least 40 years
- Comments Additional Comments if required
- **Preliminary Management Recommendations** Work Recommendations, including further investigation of suspected defects that require more detailed assessment and pose potential for wildlife habitat.

- **Work Priority** Work Priority This gives a work priority rating of preliminary management for each tree.
  - o H High Urgent work to be carried out as soon as practicable due to safety reasons (Within 14 days).
  - o H/M High Medium Work to be carried out within 6 months/or before construction phase begins
  - o M Medium Work to be carried out in 12 months
  - o L Low After consideration/Re-inspect in 18-24 months
  - o Blank No work required.
- RPR Root protection radius / RPA Root Protection Area Is a layout design tool
  indicating the minimum area around a tree deemed to contain sufficient roots and
  rooting volume to maintain the tree's viability, and where the protection of the roots
  and soil structure is treated as a priority. RPR is a circular area measured as a radius
  in metres from the centre of the tree or RPA is an area in metres squared. Where
  required this area may be changed in shape but not reduced in area whilst providing
  adequate protection of the tree's rooting system.

#### 10.0 Appendix 4 – An Introduction to Tree Protection

For the purpose of this report is to give an introduction is given to tree protection. If required a Tree Protection Plan and Tree Protection Methods Statement can be provided for the finalised development design.

Tree protection methods must be considered and designed by an Arboriculturist. These should then be implemented BEFORE any machinery or materials are bought onto site and before any demolition, development or stripping of soil commences. The Root Protection Area (RPA) (cyan circles/lines) indicated on the Tree Constraints Plan must be set out and the protective barriers and ground protection installed accordingly for retained trees. The protective barriers and ground protection areas shall be regarded as sacrosanct, and shall not be removed or altered without prior recommendation by an Arboriculturist and approval of the LPA.

The areas protected by barrier fencing and ground protection shall be subject to the following restrictions:

- Existing soil levels within the protected areas shall not be altered.
- No excavation of any kind shall take place within the protected areas.
- The protected areas shall not be used for storage of any kind.
- No vehicles or machinery shall be allowed into the areas protected by fencing.
- Should the developer require the above restrictions to be breached for unforeseen reasons, an appropriate method of works must be agreed with the Local Planning Authority prior to any works taking place within the protected areas.

Additional precautions outside protected barrier areas and ground protection:

- All underground services should be installed following NJUG Volume 4
   Guidelines for the Planning, Installation and Maintenance of Utility Apparatus in Proximity to Trees. The full document is available at <a href="http://www.njug.org.uk/">http://www.njug.org.uk/</a>.
- Building materials and fuels such as oil, bitumen or cement should not be stacked or discharged within 10 metres of the trees stem.
- Fires will not be lit beneath any tree or in a place where flames could extend to within 10 metres of the outer canopy of any tree.
- Trees that are to be retained and be protected should not be used as anchorage for services or equipment.
- The use of cranes and large machinery on site should be planned and care taken not to damage the tree during the process.

Visits by an Arboriculturist during the construction process should be conducted to ensure all of the above are being strictly adhered too.

# **10.0** Appendix 5 – Tree Photographs

Tree ID#T20 – T21



Tree ID#G8 + T19



Tree ID#T8, T7, T6



Tree ID#T34 - T37



Tree ID#T38 - T41







Tree ID#G9

Tree ID#G3





Tree ID#A1

Tree ID#G11, T42 + G10





Tree ID#T43

Tree ID#G13





Tree ID#T16 Tree ID#T15





Tree ID#T45 + T46 Tree ID#G3





Tree ID#T48 Tree ID#G14





Tree ID#T49 + T50 Tree ID#T55 + T54





Tree ID#T51 + G15 + G16



Tree ID#T53



Tree ID#G18



Tree ID#G19



Tree ID#T9 + T10



Tree ID#T11 + T12



Tree ID#G5



Tree ID#G6



Tree ID#T1 – T5



Tree ID#T17 + T18



Tree ID#G4



# 10.0 Appendix 6 – Tree Impact Plan

