



November 7, 2022

Herkimer County Industrial Development
Agency
Mr. John Piseck
Executive Director
420 E. German Street, Suite 101A
Herkimer, New York 13350

**RE: PRE-DEMOLITION ASBESTOS SURVEY FOR THE FORMER NEWPORT SCHOOL:
7456 EAST STREET, NEWPORT, NEW YORK (HRP PROJECT #HER1506.BA)**

Dear Mr. Piseck:

On August 22, 2022, Mr. James Charter (NYSDOL Asbestos Handler Certification #14-06730), of HRP Associates Inc. (HRP) completed a pre-demolition asbestos survey of one building located at 7456 East Street, Newport, New York. The purpose of the survey was to assess if ACM was present in the building prior to conducting renovation or demolition activities.

HRP met with the Mayor of the Village of Newport, Mr. Mark Butler, and the Chief Executive Officer at the Herkimer County Industrial Development Agency, Mr. John Piseck. Mr. Butler provided access to the on-site building. HRP visually inspected accessible interior and exterior portions of the on-site building for suspect ACMs. Methodologies used were generally consistent with USEPA publications: "Guidance for Controlling Asbestos Containing Materials in Buildings" (June 1985) and "Asbestos in Buildings: Simplified Sampling Scheme for Friable Surfacing Materials" (dated October 1985). The documents were used for their asbestos survey concepts, such as identifying homogeneous materials, quantifying materials, and evaluating friability (potential to crumble with hand pressure) and condition (good, damaged, or significantly damaged). HRP's inspection of the on-site building is outlined below. No surveys, plans or specifications were available for the surveyed structure.

Asbestos Survey

Former Newport School Building

The building, constructed in 1923, is a 38,016 square foot, three-story structure with concrete and wood floors, steel and wood frame, exterior brick and mortar walls, and an asphalt/rubber roof. HRP surveyed interior and exterior portions of the building consisting of a general school area with administrative and custodial offices, bathrooms, classrooms, an auditorium, and the building roof. Concrete, and wood floors were observed throughout the interior of the building, along with drywall, plaster, and tile walls. Plaster was observed behind the interior walls.

In general, materials sampled include drywall, plaster, concrete skim coat, concrete, brick mortar, roofing material, pipe insulation, and window glazing.

A limitation of the survey includes that areas of building interior walls and ceiling were significantly deteriorated, and large amounts of garbage and debris covered the interior floors, thus limiting inspection of these areas. Following removal of debris, any un-assessed suspect ACM should be sampled by an asbestos building inspector.

Results of Asbestos Survey

A material is considered by the US EPA and NYS DOL to be asbestos containing if at least one sample collected from the homogenous area shows asbestos present in an amount greater than 1%. Results of the asbestos survey are summarized in **Table 1**. Based on a review of the laboratory results, two of the submitted friable and non-friable ACM samples analyzed contain asbestos. These materials are described below:

Former Newport School Building:

- Black built up roof above auditorium (third floor) – 3.9% Chrysotile (Sample #06-32, #06-33)
- White pipe insulation (second floor) – 28.6% Chrysotile (Sample #07-34 through #07-36). Based on the lack of access in the building, pipe insulation throughout the building should be presumed to be an ACM, or further assessed by an asbestos building inspector following the removal of debris from the building.


Based on the results of this survey, HRP has the following recommendations at this time:

- Prior to any renovation or demolition activities, a copy of the asbestos survey should be provided to the demolition contractor and local asbestos control board.
- Maintain a copy of this asbestos survey with the property.
- An ACM Survey should be conducted prior to any renovation or demolition activities that take place on any buildings (other than the building sampled in this survey) located on the 7456 East Street Property.
- If un-assessed suspect ACM is identified during demolition activities, retain an asbestos building inspector to sample the material(s).
- One copy of this report must be immediately transmitted by the building owner, or their agent, to the local government entity charged with issuing a permit for such demolition, renovation, remodeling or repair work under applicable NY State or local laws.
- The completed asbestos survey for controlled demolition (as per Subpart 56-11.5) or pre-demolition asbestos projects shall also be submitted to the appropriate Asbestos Control Bureau district office.

Pre-Demolition Asbestos Survey
Former Newport School
7456 East Street Newport, NY
Mr. John Piseck
Page 3

If you have any questions or require additional information, please feel free to contact HRP at (518) 877-7101.

Sincerely,
HRP Associates, Inc.


A handwritten signature in black ink, appearing to read "Mark Wright", with a stylized flourish extending from the end.

Mark Wright, CSP, PG
Senior Project Manager

Attachments

SAMPLE LOCATION

Path: C:\Users\elliott.jackson\Documents\ArcGIS\Projects\MyProject\MyProject.aprx



Revisions	No.	Date	Designed By:	Drawn By:	Reviewed By:
	No.	Date	EWJ	EWJ	MEW
Issue Date:			10/20/2022	Project No:	HER1506.BA
				Sheet Size:	11x17

**Asbestos Sample
Location Map**

7456-7458 East Street
Newport, New York

Figure No.
1

TABLE 1
Summary of Laboratory
Analytical Results

TABLE 1 – RESULTS SUMMARY

Sample Numbers	Location	Homo-Geneous Area	Description of Material / Area	Asbestos Result		Condition of Material, Friability	Amount
				% by PLM	% by TEM		
01-01	Second floor	1	Gray plaster	NAD	NA	Friable, SD	Throughout building
01-02			Gray plaster	NAD	NA		
01-03			Gray plaster	NAD	NA		
01-04			Gray plaster	NAD	NA		
01-05			Gray plaster	NAD	NA		
01-06	Third floor		Gray plaster	NAD	NA		
01-07			Gray plaster	NAD	NA		
01-08			Gray plaster	NAD	NA		
01-09			Gray plaster	NAD	NA		
02-10			Second floor	2	White skim coat		
02-11	White skim coat	NAD			NA		
02-12	White skim coat	NAD			NA		
02-13	White skim coat	NAD			NA		
02-14	White skim coat	NAD			NA		
02-15	Third floor	White skim coat	NAD		NA	Friable, SD	Throughout building
02-16		White skim coat	NAD		NA		
02-17		White skim coat	NAD		NA		
02-18		White skim coat	NAD		NA		
03-19	Second floor	3	Gray Esbary concrete block		NAD	NA	Friable, SD
03-20			Gray Esbary concrete block	NAD	NA		
04-21	Third floor	4	Gray Pyrobar concrete block	NAD	NA	Friable, SD	Portion of 3 rd floor walls
04-22			Gray Pyrobar concrete block	NAD	NA		

Sample Numbers	Location	Homo-Geneous Area	Description of Material / Area	Asbestos Result		Condition of Material, Friability	Amount
				% by PLM	% by TEM		
05-23	Second floor	5	Gray mortar	NAD	NA	Non-Friable, SD	½ of building walls
05-24			Gray mortar	NAD	NA		
05-25			Gray mortar	NAD	NA		
05-26			Gray mortar	NAD	NA		
05-27			Gray mortar	NAD	NA		
05-28	Third floor		Gray mortar	NAD	NA	Non-Friable, SD	½ of building walls
05-29			Gray mortar	NAD	NA		
05-30			Gray mortar	NAD	NA		
05-31			Gray mortar	NAD	NA		
06-32	Roof above auditorium		6	Built up black roof	NAD	Chrysotile 3.9%	Non-Friable, SD
06-33		Built up black roof		NAD	NA/PS		
07-34	Second floor	7	White pipe insulation	Chrysotile 28.6%	NA	Friable, D	100 LF
07-35			White pipe insulation	NAD	NA/PS		
07-36			White pipe insulation	NAD	NA/PS		
08-37	First floor	8	White window glazing	NAD	NA	Friable, D	1000 LF
08-38			White window glazing	NAD	NA		

TEM = Transmission Electronic Microscope, PLM = Polarized Light Microscopy, HA = Homogenous Area, NA = Not Analyzed
NAD = No Asbestos Detected, PS = Positive Skip, D = Damaged, SD = Significantly Damaged

LABORATORY RESULTS

**AmeriSci New York**

117 EAST 30TH ST.
NEW YORK, NY 10016
TEL: (212) 679-8600 • FAX: (212) 679-3114

PLM Bulk Asbestos Report

HRP Associates, Inc.
Attn: Jesse Zahn
1 Fairchild Square
Suite 110
Clifton Park, NY 12065

Date Received 08/24/22 **AmeriSci Job #** 222083360
Date Examined 08/29/22 **P.O. #** S-NY-02306
ELAP # 11480 **Page** 1 of 7
RE: HERI506.BA Task 2; 7456 East Street, Newport, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
01-01 01	222083360-01 Location: Second Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
01-02 01	222083360-02 Location: Second Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
01-03 01	222083360-03 Location: Second Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
01-04 01	222083360-04 Location: Second Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
01-05 01	222083360-05 Location: Second Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			

PLM Bulk Asbestos Report

HERI506.BA Task 2; 7456 East Street, Newport, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
01-06 01	222083360-06 Location: Third Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
01-07 01	222083360-07 Location: Third Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
01-08 01	222083360-08 Location: Third Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
01-09 01	222083360-09 Location: Third Floor - Gray Plaster	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
02-10 02	222083360-10 Location: Second Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
02-11 02	222083360-11 Location: Second Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			

PLM Bulk Asbestos Report

HERI506.BA Task 2; 7456 East Street, Newport, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
02-12 02	222083360-12 Location: Second Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
02-13 02	222083360-13 Location: Second Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
02-14 02	222083360-14 Location: Second Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
02-15 02	222083360-15 Location: Third Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
02-16 02	222083360-16 Location: Third Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
02-17 02	222083360-17 Location: Third Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			

PLM Bulk Asbestos Report

HERI506.BA Task 2; 7456 East Street, Newport, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
02-18 02	222083360-18 Location: Third Floor - White Skim Coat	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
03-19 03	222083360-19 Location: Second Floor - Gray Ebsary Concrete Block	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 2%, Non-fibrous 98%			
03-20 03	222083360-20 Location: Second Floor - Gray Ebsary Concrete Block	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 5%, Non-fibrous 95%			
04-21 04	222083360-21 Location: Third Floor - Gray Pyrobar Concrete Block	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 5%, Non-fibrous 95%			
04-22 04	222083360-22 Location: Third Floor - Gray Pyrobar Concrete Block	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 5%, Non-fibrous 95%			
05-23 05	222083360-23 Location: Second Floor - Gray Mortar For Brick Masonary Tiles	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			

PLM Bulk Asbestos Report

HERI506.BA Task 2; 7456 East Street, Newport, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
05-24 05	222083360-24	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
05-25 05	222083360-25	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
05-26 05	222083360-26	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
05-27 05	222083360-27	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
05-28 05	222083360-28	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
05-29 05	222083360-29	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			

PLM Bulk Asbestos Report

HERI506.BA Task 2; 7456 East Street, Newport, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
05-30 05	222083360-30 Location: Third Floor - Gray Mortar For Brick Masonary Tiles	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
05-31 05	222083360-31 Location: Third Floor - Gray Mortar For Brick Masonary Tiles	No	NAD (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: Gray, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100%			
06-32 06	222083360-32 Location: Roof Above Auditorium - Black Built Up Roof	No	NAD (by NYS ELAP 198.6) by Kensen Caro on 08/29/22
Analyst Description: Black, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 39.4%			
06-33 06	222083360-33 Location: Roof Above Auditorium - Black Built Up Roof	No	NAD (by NYS ELAP 198.6) by Kensen Caro on 08/29/22
Analyst Description: Black, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 33%			
07-34 07	222083360-34 Location: Second Floor - White Pipe Insulation	Yes	28.6% (by NYS ELAP 198.1) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 28.6 % Other Material: Non-fibrous 71.4%			
07-35 07	222083360-35 Location: Second Floor - White Pipe Insulation		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			

PLM Bulk Asbestos Report

HERI506.BA Task 2; 7456 East Street, Newport, NY

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
07-36 07	222083360-36 Location: Second Floor - White Pipe Insulation		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
08-37 08	222083360-37 Location: 1st Floor - White Window Glazing	No	NAD (by NYS ELAP 198.6) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 18.5%			
08-38 08	222083360-38 Location: 1st Floor - White Window Glazing	No	NAD (by NYS ELAP 198.6) by Kensen Caro on 08/29/22
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 22.9%			

Reporting Notes:

Analyzed by: Kensen Caro
Date: 8/29/2022



Reviewed by: Khaalid W. Perine



*NAD/NSD =no asbestos detected; NA =not analyzed; NA/PS=not analyzed/positive stop, (SOF-V) = Sprayed On Fireproofing containing Vermiculite; (SM-V) = Surfacing Material containing Vermiculite; PLM Bulk Asbestos Analysis using Olympus, Model BH-2 Pol Scope, Microscope, Serial #: 229003, by Appd E to Subpt E, 40 CFR 763 quantified by either CVES or 400 pt ct as noted for each analysis (NVLAP 200546-0), ELAP PLM Method 198.1 for NY friable samples, which includes the identification and quantitation of vermiculite, or ELAP 198.6 for NOB samples, or EPA 400 pt ct by EPA 600-M4-82-020 (NY ELAP Lab 11480); Note:PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non asbestos-containing in NY State (also see EPA Advisory for floor tile, FR 59,146,38970,8/1/94) National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the lab.This PLM report relates ONLY to the items tested. RI Cert AAL-094, CT Cert PH-0186, Mass Cert AA000054, NJ Lab ID #NY031.

_____END OF REPORT_____

Client Name: HRP Associates, Inc.

Table I
Summary of Bulk Asbestos Analysis Results
 HERI506.BA Task 2; 7456 East Street, Newport, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01	01-01	01	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Plaster							
02	01-02	01	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Plaster							
03	01-03	01	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Plaster							
04	01-04	01	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Plaster							
05	01-05	01	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Plaster							
06	01-06	01	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Plaster							
07	01-07	01	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Plaster							
08	01-08	01	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Plaster							
09	01-09	01	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Plaster							
10	02-10	02	----	----	----	----	NAD	NA
	Location: Second Floor - White Skim Coat							
11	02-11	02	----	----	----	----	NAD	NA
	Location: Second Floor - White Skim Coat							
12	02-12	02	----	----	----	----	NAD	NA
	Location: Second Floor - White Skim Coat							
13	02-13	02	----	----	----	----	NAD	NA
	Location: Second Floor - White Skim Coat							
14	02-14	02	----	----	----	----	NAD	NA
	Location: Second Floor - White Skim Coat							
15	02-15	02	----	----	----	----	NAD	NA
	Location: Third Floor - White Skim Coat							
16	02-16	02	----	----	----	----	NAD	NA
	Location: Third Floor - White Skim Coat							

Client Name: HRP Associates, Inc.

Table I
Summary of Bulk Asbestos Analysis Results
 HERI506.BA Task 2; 7456 East Street, Newport, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17	02-17	02	----	----	----	----	NAD	NA
	Location: Third Floor - White Skim Coat							
18	02-18	02	----	----	----	----	NAD	NA
	Location: Third Floor - White Skim Coat							
19	03-19	03	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Ebsary Concrete Block							
20	03-20	03	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Ebsary Concrete Block							
21	04-21	04	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Pyrobar Concrete Block							
22	04-22	04	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Pyrobar Concrete Block							
23	05-23	05	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Mortar For Brick Masonary Tiles							
24	05-24	05	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Mortar For Brick Masonary Tiles							
25	05-25	05	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Mortar For Brick Masonary Tiles							
26	05-26	05	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Mortar For Brick Masonary Tiles							
27	05-27	05	----	----	----	----	NAD	NA
	Location: Second Floor - Gray Mortar For Brick Masonary Tiles							
28	05-28	05	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Mortar For Brick Masonary Tiles							
29	05-29	05	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Mortar For Brick Masonary Tiles							
30	05-30	05	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Mortar For Brick Masonary Tiles							
31	05-31	05	----	----	----	----	NAD	NA
	Location: Third Floor - Gray Mortar For Brick Masonary Tiles							
32	06-32	06	0.351	42.5	18.1	35.5	NAD	Chrysotile 3.9
	Location: Roof Above Auditorium - Black Built Up Roof							

See Reporting notes on last page

Client Name: HRP Associates, Inc.

Table I
Summary of Bulk Asbestos Analysis Results
 HERI506.BA Task 2; 7456 East Street, Newport, NY

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
33	06-33	06	0.363	44.6	22.4	33.0	NAD	NA/PS
Location: Roof Above Auditorium - Black Built Up Roof								
34	07-34	07	----	----	----	----	Chrysotile 28.6	NA
Location: Second Floor - White Pipe Insulation								
35	07-35	07	----	----	----	----	NA/PS	NA
Location: Second Floor - White Pipe Insulation								
36	07-36	07	----	----	----	----	NA/PS	NA
Location: Second Floor - White Pipe Insulation								
37	08-37	08	0.278	9.6	72.0	18.5	NAD	NAD
Location: 1st Floor - White Window Glazing								
38	08-38	08	0.351	14.9	62.2	22.9	NAD	NAD
Location: 1st Floor - White Window Glazing								

Analyzed by: Khaalid W. Perine

Date: 8/30/2022



Reviewed by: Khaalid W. Perine



**Quantitative Analysis (Semi/Full); Bulk Asbestos Analysis - PLM by Appd E to Subpt E, 40 CFR 763 or NYSDOH ELAP 198.1 for New York friable samples or NYSDOH ELAP 198.6 for New York NOB samples; TEM (Semi/Full) by EPA 600/R-93/116 (or NYSDOH ELAP 198.4; for New York samples). Analysis using Hitachi, Model H7000-Noran 7 System, Microscope, Serial #: 747-05-06. NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; (SOF-V) = Sprayed On Fireproofing containing Vermiculite; (SM-V) = Surfacing Material containing Vermiculite; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses): NVLAP (PLM) 200546-0, NYSDOH ELAP Lab 11480, NJ Lab ID #NY031.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogenous materials).



Relinquished By: James Charter Date/Time: 8/23/22 12:00
 Received By: Date/Time:
 Relinquished By: Date/Time:
 Received By: Date/Time:

Company: HRP Associates, Inc.		HRP Project No: HER1506.BA Task 2		AMERISCI #:
Street Address: One Fairchild Square, Suite 110		Project Address: 7456 East Street, Newport, NY		
City: Clifton Park	State: NY	Zip: 12065	Project Manager: Jesse Zahn	
Phone: 518-877-7101	Fax: 518-877-8561	Analysis: <input type="checkbox"/> PLM Only <input checked="" type="checkbox"/> TEM Only <input checked="" type="checkbox"/> NY ELAP PLM/TEM <input type="checkbox"/> ASTM Dust (microvac) <input type="checkbox"/> ASTM Dust (Wipe) <input type="checkbox"/> Other (describe in Comments)		
Site/Secondary Fax #:	Turnaround Time: 5-day		Material Type: <input checked="" type="checkbox"/> Bulk <input type="checkbox"/> Dust <input type="checkbox"/> Water	
Results to: james.charter@hrpassociates.com		Sampled By: James Charter		Date Sampled: 8/22/22
Special Instructions or Comments: Please sample homogenous materials on a positive stop basis				
Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Area (HA #)	
01-01	Second Floor	Gray Plaster	01	
01-02				
01-03				
01-04				
01-05	Second Floor		01	
01-06	Third Floor			
01-07				
01-08				
01-09	Third Floor	Gray Plaster	01	
02-10	Second Floor	White Skim Coat	02	
02-11				
02-12				
02-13				
02-14	Second Floor			
02-15	Third Floor			
02-16	Third Floor	White Skim Coat	02	

222083360

Relinquished By: James Charter	Date/Time: 8/23/27 12:00
Received By:	Date/Time:
Relinquished By:	Date/Time:
Received By:	Date/Time:

Company: HRP Associates, Inc.		HRP Project No: HER1506.BA Task 2		AMERISCI #:	
Street Address: One Fairchild Square, Suite 110		Project Address: 745C East Street, Newport, NY			
City: Clifton Park	State: NY	Zip: 12065	Project Manager: Jesse Zahn		
Phone: 518-877-7101	Fax: 518-877-8561	Analysis: <input type="checkbox"/> PLM Only <input type="checkbox"/> TEM Only <input checked="" type="checkbox"/> NY ELAP PLM/TEM <input type="checkbox"/> ASTM Dust (microvac) <input type="checkbox"/> ASTM Dust (Wipe) <input type="checkbox"/> Other (describe in Comments)			
Site/Secondary Fax #:		Turnaround Time: 5-day		Material Type: <input checked="" type="checkbox"/> Bulk <input type="checkbox"/> Dust <input type="checkbox"/> Water	
Results to: james.charter@hrpassociates.com		Sampled By: James Charter		Date Sampled: 8/22/22	
Special Instructions or Comments: Please sample homogenous materials on a positive stop basis					
Field ID	Location	Sample Description (for dust= size of surface area sampled)	Homogenous Area (HA #)		
02-17	Third Floor	White Skim Coat	02		
02-18	Third Floor	White Skim Coat	02		
03-19	Second Floor	Gray Ebsary Concrete Block	03		
03-20	Second Floor	Gray Ebsary Concrete Block	03		
04-21	Third Floor	Gray Pyrobar Concrete Block	04		
04-22	Third Floor	Gray Pyrobar Concrete Block	04		
05-23	Second Floor	Gray Mortar for Brick Masonry Tiles	05		
05-24					
05-25					
05-26					
05-27	Second Floor				
05-28	Third Floor				
05-29					
05-30					
05-31	Third Floor				
06-32	Root Above Auditorium	Gray Mortar for Brick Masonry Tiles Black Built UP Roof	05 06		

222083360

BULK SAMPLE SHEET
117 EAST 30TH STREET
NEW YORK, NY 10016
TOLL FREE (800) 705-5227
Fax (212) 679-3114


BULK SAMPLE SHEET
117 EAST 30TH STREET
NEW YORK, NY 10016
TOLL FREE (800) 705-5227
Fax (212) 679-3114

Relinquished By: James Charter	Date/Time: 8/23/22 12:00
Received By:	Date/Time:
Relinquished By:	Date/Time:
Received By:	Date/Time:

Company: HRP Associates, Inc.	HRP Project No: HER1506.BA Task 2						AMERISCI #:
Street Address: One Fairchild Square, Suite 110	Project Address: 7456 East Street, Newport, NY						
City: Clifton Park State: NY Zip: 12065	Project Manager: Jesse Zahn						
Phone: 518-877-7101 Fax: 518-877-8561	Analysis: ___ PLM Only ___ TEM Only <input checked="" type="checkbox"/> NY ELAP PLM/TEM ___ ASTM Dust (microvac) ___ ASTM Dust (Wipe)) ___ Other (describe in Comments)						
Site/Secondary Fax #:	Turnaround Time: 5-day						Material Type: <input checked="" type="checkbox"/> Bulk ___ Water
Results to: james.charter@hrpassociates.com	Sampled By: James Charter						Date Sampled: 8/22/22
Special Instructions or Comments: Please sample homogenous materials on a positive stop basis							
Field ID	Location	Sample Description (for dust= size of surface area sampled)				Homogenous Area (HA #)	
06-33	Roof Above Auditorium	Black Built up Roof				06	
07-34	Second Floor	White Pipe Insulation				07	
07-35	↓					07	
07-36	Second Floor	White Pipe Insulation				07	
08-37	1st floor	White window glazing				08	
08-38	1st floor	White window glazing				08	
# 222083360							

CERTIFICATIONS

STATE OF NEW YORK - DEPARTMENT OF LABOR
ASBESTOS CERTIFICATE



JAMES K CHARTER
CLASS(EXPIRES)
D INSP(09/22)

CERT# 14-06730
DMV# 770-447817

MUST BE CARRIED ON ASBESTOS PROJECTS

