

DOWNHOLE VIDEO SURVEY

Well Rehabilitation Services, Inc.

Contractor License No.: CA. 983846 PO Box 80365 Bakersfield, CA. 93380

Phone: 661-587-0914 Fax: 661-587-0981 Web: Shelley@wellrehabservices.com

Client:	New Avenue Mutual Water	Company			Survey Date:	November	28, 2022	
Address:	N/A				Invoice:	pending	Rui	n: 2
City:	Gilroy	State: CA	Zip:	N/A	Well Name:	#3		
Requested By:	David Biasiotti		P.O.:		Well Owner:			
Сору То:			Camer	ra: Aries BT970	0 Color Came	'a		
Reason For Sui	rvey: Post acid treatment				Zero Datum:	Top Of Casing		
_ocation:	.25 miles N/O Bannister Ave	on E/S/O Duke D)r		_			
Field:	Gilroy					Depth: 440 ft.	Vehicle:	W20
County: Santa	Clara	Country:			Type Perfs:	0.032 Horizonta	I Slots	
Perf Intervals:	281.5-321.3 ft. 361.3-421 ft.							
st Csg I.D.:	7.75" PVC Csg Weight:	From: 0 ft. T	o: 440 1	ft. 2nd Csg I.D.:	C	sg Weight:	From:	To:
.D Reference:	Measured Casing	Buildup: None			S.W.L.: 167	ft. P.W.L.:	Pump D	epth: 340 ft.
Operator: Mon	toya Latitude:	37.06006° Lo	ngitude.	: 121.54570°	Section:	Range:	Townsh	ip:
Other Information	on: 03-2003 Drilled by Chapp	pel Pump & Supp	oly Total	l depth 440'				

WELLBORE SNAPSHOTS	DEPTHS (SideScan-Feet)	WELLBORE / CASING INFORMATION
		Downview 16" deeper than sideview
0' (See Other Side) 0' (See Other Side)	0.0 Ft.	Sideview-Zero Datum
	1.3 Ft.	Sideview-Inlet port
	167.0 Ft.	Sideview-Static Water Level, clear
1.3' (See Other Side) 167' (See Other Side)		11-14-22 SWL @ 170'
0001.3F	250.0 Ft.	Downview-Light suspended debris
	281.5 Ft.	Sideview-Top of 1st section of Horizontal Slots
250' (See Other Side) 281.5' (See Other Side)	283.0 Ft.	Sideview-Slots open, no gravel pack visible
	290.0 Ft.	Sideview-Loose debris & mud-like material in slots
9250.0F	293.0 Ft.	Sideview-Slots open, no gravel pack
	310.0 Ft.	Sideview-Loose debris plugging slots
283' (See Other Side) 290' (See Other Side)	319.0 Ft.	Sideview-Slots partially open
0283.GF 0290.OF	321.3 Ft.	Sideview-Bottom of 1st section of slots
THE PERSON NAMED IN COLUMN		
293' (See Other Side) 310' (See Other Side)		
0293.0F 9339.0F		
0423.0F		Will regulate the first of the control of the contr
319' (See Other Side) 321.3' (See Other Side)		
0315.0F		

WELLBORE SNAPSHOT(S)

Depth: 0 Feet




Depth: 0 Feet



Depth: 1.3 Feet



Depth: 167 Feet



Depth: 250 Feet



Depth: 281.5 Feet



Depth: 283 Feet



Depth: 290 Feet



Depth: 293 Feet



Depth: 310 Feet



Depth: 319 Feet



Depth: 321.3 Feet





DOWNHOLE VIDEO SURVEY

Well Rehabilitation Services, Inc.

Contractor License No.: CA. 983846 PO Box 80365 Bakersfield, CA. 93380

Phone: 661-587-0914 Fax: 661-587-0981 Web: Shelley@wellrehabservices.com

Survey Date: _	November 28, 2022						
Client:	New Avenue Mutual Water Company						
Well Name:	#3						
Depth:	440 ft.						
1st Csg I.D.:	7.75 in.	From: 0 ft.	To: 440 ft.				
2nd Csg I.D.:		From:	_To:				
S.W.L.:	167 ft.	_ P.W.L.:	Pump Depth: _340 ft				
Type Perfs:	0.032 Ho						
Perf Intervals: <u>281.5-321.3 ft.</u>			361.3-421 ft.				


WELLBORE S	NAPSHOTS	DEPTHS (SideScan-Feet)	WELLBORE / CASING INFORMATION
		361.2 Ft.	Sideview-Top of 2nd section of slots
361.2' (See Other Side)	364' (See Other Side)	364.0 Ft.	Sideview-Slots plugged with soft debris
(VIST. 21	0364.0F	383.0 Ft.	Sideview-Light scrape-brush marks
		390.0 Ft.	Sideview-Slots mostly plugged
383' (See Other Side)	390' (See Other Side)	401.0 Ft.	Downview-Casing clean
0383.0F	0390.05	415.0 Ft.	Sideview-Soft debris & sand in slots
		419.0 Ft.	Downview-Some gas and-or chemical residual floating
401' (See Other Side)	415' (See Other Side)	421.0 Ft.	Sideview-Bottom of slots
		438.0 Ft.	Downview-Light mud material stuck on casing
0401.0F	0415.0F	438.2 Ft.	Downview-Bottom fill @ 440', partially soft
	THE RESERVE		End of Survey
419' (See Other Side)	421' (See Other Side)		437.8' TD prior to rehab
0419.0F	0421.0F		
	ELECTION OF THE PARTY OF THE PA		
438' (See Other Side)	438.2' (See Other Side)		
	1		
0438.0F	0438.2F		
plant of the second			

WELLBORE SNAPSHOT(S)

Depth: 361.2 Feet



Depth: 364 Feet



Depth: 383 Feet



Depth: 390 Feet




Depth: 401 Feet



Depth: 415 Feet




Depth: 419 Feet



Depth: 421 Feet



Depth: 438 Feet



Depth: 438.2 Feet



Well Rehabilitation Services, Inc.

NEW AVENUE MUTUAL #3 RUN 2

