



## Peace of Mind Automotive Inspection Report.

**Joe Trejo Jr.**  
**210-557-0686**

Peace of Mind Automotive Inspection Report.  
Joe Trejo Jr.  
210-557-0686

**Complete**

| Score                                                                                                         | 4 / 4 (100%) | Flagged items | 0 | Actions | 0                    |
|---------------------------------------------------------------------------------------------------------------|--------------|---------------|---|---------|----------------------|
| Site conducted                                                                                                |              |               |   |         | Unanswered           |
| Customer name                                                                                                 |              |               |   |         | Lmj auto motor sales |
| Date / Time                                                                                                   |              |               |   |         | July 9th             |
| Payment method                                                                                                |              |               |   |         | Invoice              |
| Inspection cost                                                                                               |              |               |   |         | 199                  |
| Vehicle Year / Make / Model / Color                                                                           |              |               |   |         | 2015 Lexus RX350     |
| VIN                                                                                                           |              |               |   |         | 84895 last 5         |
| <div></div> <p>Photo 1</p> |              |               |   |         |                      |
| license plate                                                                                                 |              |               |   |         | Dealer               |
| Mileage                                                                                                       |              |               |   |         | 89794                |
| Color                                                                                                         |              |               |   |         | Black                |

| Interior Electrical Functions    |  | 2 / 2 (100%)     |
|----------------------------------|--|------------------|
| Horn function                    |  | Function correct |
| Interior lighting function       |  | Function correct |
| Power lock function              |  | Function correct |
| Power window function            |  | Function correct |
| Power seat function              |  | Function correct |
| Power Doors / lift gate function |  | Function correct |
| Air conditioning below 60*       |  | Yes              |
| Heater above 90*                 |  | Yes              |
| Climate controls function        |  | Function correct |
| Radio / display screen function  |  | Function correct |
| Speakers performing correctly    |  | Function correct |
| GPS function                     |  | Function correct |
| Satellite radio function         |  | Function correct |
| 12V power supply function        |  | Function correct |
| Wireless charging function       |  | N/A              |
| Cooled seat function             |  | N/A              |
| Heated seat function             |  | N/A              |
| Remote entry function            |  | Function correct |

**ADDITIONAL NOTES**

Vehicle interior electrical functionality is correct, no inoperatable function

| Interior Condition           |                  |
|------------------------------|------------------|
| Seat belt function           | Function correct |
| Front seat condition         | Normal wear      |
| Rear seat condition          | Normal wear      |
| Carpeting condition          | Normal wear      |
| Headliner condition          | Normal wear      |
| Door panel condition         | Normal wear      |
| Dashboard condition          | Normal wear      |
| Headliner condition          | Normal wear      |
| Center console condition     | Normal wear      |
| Glove compartment condition  | Normal wear      |
| Sun visor condition          | Normal wear      |
| Trunk / Cargo area condition | Normal wear      |
| Trim pieces condition        | Normal wear      |

### ADDITIONAL NOTES

Normal wear to the interior as expected for the age and mileage on the vehicle. No water damage to the carpet or carpet installation. No rust on the bottom side of the dash. No evidence of flood damage present. No evidence of the vehicle being smoked inside. no severely damaged or missing panels. See all interior photos for evidence of current condition. 



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40

## Exterior Body / Structural Condition

### Paint depth on metal body panels

There was a little bit of paint and bodywork notice to the vehicle. The front driver, side fender, driver, side door, rear driver side door and driver side quarter panel have all been touched up previously. There is no structural damage present nor any structural damage repair work done. Normal blemish to the exterior as expected for the age and mileage on the vehicle, including chips, scrapes, scratches and dings. See all exterior photos for evidence of condition.



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62




Photo 63




Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72




Photo 73



Photo 74



Photo 75




Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86

|                                                |             |
|------------------------------------------------|-------------|
| Front bumper condition                         | Normal wear |
| Rear bumper condition                          | Normal wear |
| Hood panel condition                           | Normal wear |
| The hood panel prop shocks need to be replaced |             |
| Driver side fender condition                   | Normal wear |
| Passenger side fender condition                | Normal wear |
| Roof panel condition                           | Normal wear |
| Front driver side door Condition               | Normal wear |
| Rear driver side door condition                | Normal wear |
| Front passenger side door condition            | Normal wear |
| Rear passenger side door condition             | Normal wear |
| Driver side quarter panel condition            | Normal wear |
| Passenger side quarter panel condition         | Normal wear |
| Trunk panel condition                          | Normal wear |
| Truck Bed condition                            | N/A         |
| Tail gate condition                            | N/A         |
| Chassis / Frame condition                      | Normal wear |
| Frame rail condition                           | Normal wear |
| Subframe condition                             | Normal wear |
| Engine cradle condition                        | Normal wear |
| Skid / Dust cover condition                    | Normal wear |
| Collapse beam condition                        | Normal wear |
| Window trim condition                          | Normal wear |
| Weather stripping condition                    | Normal wear |

|                              |             |
|------------------------------|-------------|
| Front windshield condition   | Normal wear |
| Other window glass condition | Normal wear |
| Wheel / Hubcap condition     | Normal wear |
| ADDITIONAL NOTES             |             |

## Tire condition

### Front driver side tire

25-50% remaining

Both front tires are a matching set, front tires are dated from 2019 and have only around 30% tread life remaining. Rear tires are a matching set which are a little newer. Rear tire tires have around 60% tread life remaining.



Photo 87



Photo 88



Photo 89

### Front passenger side tire

25-50% remaining



Photo 90



Photo 91



Photo 92

### Rear driver side tire

50-75% remaining



Photo 93



Photo 94

### Rear passenger side tire

50-75% remaining



Photo 95



Photo 96



Photo 97

### Spare tire and equipment

Spare and tools present

Battery / charging system

|                  |      |
|------------------|------|
| Battery date     | Na   |
| Standing voltage | 12.8 |
| Loaded voltage   | 13.4 |

Battery is accepting the charge from the alternator and the alternator charge output is correct



Photo 98

**Engine Testing / Condition**

2 / 2 (100%)

**Internal engine inspection w/ borescope camera**

Engine clean internally, no gunk or sludge presents. Proper signs of maintenance present. Block test passed, no internal combustion leak out. Coolant mixture correct and cooling system functionality is healthy. All external engine accessories in good working. No leaks or seepage from anywhere on the engine. External drive belts in decent condition. Currently no concern in mechanical issues present in relation to the engine or related accessories.



Photo 99



Photo 100



Photo 101



Photo 102



Photo 103



Photo 104



Photo 105



Photo 106



Photo 107



Photo 108

**Engine block test**

Pass



Photo 109



Photo 110



Photo 111

**Coolant mixture test**

Pass

**Air filter condition**

Normal wear

**Engine oil condition**

Normal wear

**Engine oil level**

Healthy

**Engine oil leaks**

None

**Coolant level**

Healthy

**Coolant hoses**

Healthy

**Radiator condition / function**

Healthy

**Engine operating temperature**

Healthy

**Cooling fan function**

Healthy

|                             |         |
|-----------------------------|---------|
| Drive belt condition        | Healthy |
| Abnormal engine knock       | None    |
| Abnormal valve train rattle | None    |
| Abnormal bearing noises     | None    |
| Engine gunk / sludge        | None    |
| Fuel tank                   | Healthy |
| Fuel injectors / lines      | Healthy |
| Valve cover gaskets         | Healthy |
| Intake manifold gasket      | Healthy |
| Cylinder head gasket        | Healthy |
| Oil pan gasket              | Healthy |
| Timing cover gasket         | Healthy |
| Rear main seal              | Healthy |
| Timing belt / components    | Healthy |
| Exhaust manifold            | Healthy |
| External engine accessories | Healthy |

**Transmission / Differentials****Transmission fluid level**

Healthy

**Transmission fluid condition**

Healthy

**Transmission fluid leaks**

None

No transmission fluid leaks from the transmission casing or the transmission pan. Both left and right side axle seals are free of any fluid leaks. Both left and right side CV axle are in healthy condition. Shift transition out on the road is correct.



Photo 112




Photo 113




Photo 114



Photo 115



Photo 116




Photo 117

**Transmission cooler / lines**

Healthy

**Front differential condition**

Healthy

**Center differential condition**

N/A

**Rear differential condition**

N/A

**Differential leaks**

None

**4x4 function / engagement**

N/A

**Clutch engagement**

Healthy

**Gear engagement**

Healthy

**Shift transitions**

Healthy

**Drive shaft condition**

N/A

## Suspension condition

### Front shocks / struts

Healthy

Normal fatigue notice to the suspension components. All of the suspension components seem to be original. None of the suspension components are blown out and due form the replacement. The No excessive surface rust on the exposed metal. No abnormal noise or feedback from the suspension while out on the road. All of the rubber in relation to the mounts, joints and bushings has decent texture.



Photo 118



Photo 119



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124

### Rear shocks / struts

Healthy



Photo 125



Photo 126



Photo 127



Photo 128



Photo 129



Photo 130



Photo 131



Photo 132

### Control arms upper

Healthy

### Control arms lower

Healthy

### Ball joints

Healthy

### Bushings

Healthy

### Torsion bars

Healthy

### Coilover function

N/A

### Air ride function

N/A

### Airbag condition

N/A

**Abnormal rust / corrosion to metals**

None

**Deterioration of rubbers**

None

| Braking system condition                                                                                                                                                                                                                                                                               |                   |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| Brake fluid condition                                                                                                                                                                                                                                                                                  | Healthy           |
| Brake fluid level                                                                                                                                                                                                                                                                                      | Healthy           |
| Brake fluid leaks                                                                                                                                                                                                                                                                                      | None              |
| Moisture content in brake fluid                                                                                                                                                                                                                                                                        | None              |
| Brake lines                                                                                                                                                                                                                                                                                            | Healthy           |
| Brake calipers front                                                                                                                                                                                                                                                                                   | Healthy           |
| Brake calipers rear                                                                                                                                                                                                                                                                                    | Healthy           |
| Brake drums rear                                                                                                                                                                                                                                                                                       | N/A               |
| Brake rotors front                                                                                                                                                                                                                                                                                     | Healthy           |
| Brake rotors rear                                                                                                                                                                                                                                                                                      | Healthy           |
| <b>Front brake pad life remaining</b><br>Recent service to both the front and rear brake system                                                                                                                                                                                                        | 75-100% remaining |
|  <br>Photo 133      Photo 134                                                                                                    |                   |
| <b>Rear brake pad life remaining</b>                                                                                                                                                                                                                                                                   | 75-100% remaining |
|   <br>Photo 135      Photo 136      Photo 137 |                   |
| E-brake function                                                                                                                                                                                                                                                                                       | Healthy           |

| Steering system condition         |         |
|-----------------------------------|---------|
| Steering wheel                    | Healthy |
| Steering column                   | Healthy |
| Steering knuckle / shaft          | Healthy |
| Steering box                      | N/A     |
| Rack and pinion condition         | Healthy |
| Inner tie rods                    | Healthy |
| outer tie rods                    | Healthy |
| Rack boots                        | Healthy |
| Power steering pump               | N/A     |
| power steering lines              | N/A     |
| Power steering leaks              | N/A     |
| Power steering fluid level        | N/A     |
| Electric steering motor           | Healthy |
| Abnormal play / slack in steering | None    |
| Steering alignment on road        | Healthy |

Computer diagnostic scan

Engine control module

Healthy

All of the main control modules on the vehicle were free of the live/active diagnostic fault codes. At the time of the inspection, there were no active warning lights present. All of the live feed diagnostic testing was successfully passed.

Photo 138

Photo 139

Photo 140

Photo 141

Transmission control module

Healthy

Anti lock brake (ABS) module

Healthy

SRS module

Healthy

hybrid control module

N/A

Suspension control module

N/A

## Vehicle road test

### Vehicle road test comments / concerns

Vehicle function was correct out on the road, normal drive characteristics present as expected for the age and mileage on this specific vehicle. No major/concerning drive abnormalities or issues.

---

**Value of vehicle / Diminished value due to repairs or current damage**

No diminished value due to no structural damage presence nor any structural damage repair work done

---

Media summary



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17




Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89



Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101



Photo 102



Photo 103



Photo 104



Photo 105



Photo 106



Photo 107



Photo 108



Photo 109



Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115



Photo 116



Photo 117



Photo 118



Photo 119



Photo 120




Photo 121




Photo 122



Photo 123




Photo 124



Photo 125



Photo 126



Photo 127



Photo 128



Photo 129



Photo 130



Photo 131



Photo 132



Photo 133



Photo 134



Photo 135



Photo 136



Photo 137




Photo 139




Photo 138




Photo 140




Photo 141