


Peace of Mind Automotive Inspection Report.

Joe Trejo Jr.
210-557-0686

Peace of Mind Automotive Inspection Report.
Joe Trejo Jr.
210-557-0686

Complete

Score	4 / 4 (100%)	Flagged items	0	Actions	0
Site conducted					Unanswered
Customer name					Lmj auto motor sales
Date / Time					May 19th
Payment method					Invoice
Inspection cost					199
Vehicle Year / Make / Model / Color					2018 jeep wrangler sport
VIN					76442 last 5
					
Photo 1					
license plate					Dealer
Mileage					57777
Color					Grey

Interior Electrical Functions	2 / 2 (100%)
Horn function	Function correct
Interior lighting function	Function correct
Power lock function	Function correct
Power window function	Function correct
Power seat function	N/A
Power Doors / lift gate function	N/A
Air conditioning below 60*	Yes
Heater above 90*	Yes
Climate controls function	Function correct
Radio / display screen function	Function correct
Speakers performing correctly	Function correct
GPS function	N/A
Satellite radio function	N/A
12V power supply function	Function correct
Wireless charging function	N/A
Cooled seat function	N/A
Heated seat function	N/A
Remote entry function	Function correct

ADDITIONAL NOTES

Vehicle interior electrical functionality is correct across-the-board, no inoperable functions

Interior Condition	0 / 0 (0%)
Seat belt function	Function correct
Front seat condition	Normal wear
Rear seat condition	Normal wear
Carpeting condition	Normal wear
Headliner condition	Normal wear
Door panel condition	Normal wear
Dashboard condition	Normal wear
Headliner condition	Normal wear
Center console condition	Normal wear
Glove compartment condition	Normal wear
Sun visor condition	Normal wear
Trunk / Cargo area condition	Normal wear
Trim pieces condition	Normal wear

ADDITIONAL NOTES

Normal wear to the interior as expected for the age and mileage on the vehicle. No water damage to the carpet or carpet installation. No rust on the bottom side of the dash. No evidence of flood damage present. No evidence of the vehicle being smoked inside. no severely damaged or missing panels. See all interior photos for evidence of current condition.



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38

Exterior Body / Structural Condition

0 / 0 (0%)

Paint depth on metal body panels

Factory, matching paint depth on all exterior metal body panels. All exterior metal body panels are original to the vehicle. No structural damage presents nor any structural damage repair work done. No accident damage presents nor any accident damage repair work done . All window glass is original to the vehicle. Normal wear to the exterior as expected for the age and mileage including chips, scrapes, scratches and dings. Overall vehicle exterior is well-kept. See all exterior photos for evidence of current condition.



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45




Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89

Front bumper condition	Normal wear
Rear bumper condition	Normal wear
Hood panel condition	Normal wear
Driver side fender condition	Normal wear
Passenger side fender condition	Normal wear
Roof panel condition	Normal wear
Front driver side door Condition	Normal wear
Rear driver side door condition	N/A
Front passenger side door condition	Normal wear
Rear passenger side door condition	N/A
Driver side quarter panel condition	Normal wear
Passenger side quarter panel condition	Normal wear
Trunk panel condition	Normal wear
Truck Bed condition	N/A
Tail gate condition	N/A
Chassis / Frame condition	Normal wear
Frame rail condition	Normal wear
Subframe condition	Normal wear
Engine cradle condition	Normal wear
Skid / Dust cover condition	Normal wear
Collapse beam condition	Normal wear
Window trim condition	Normal wear

Weather stripping condition	Normal wear
Front windshield condition	Normal wear
Other window glass condition	Normal wear
Wheel / Hubcap condition	Normal wear

ADDITIONAL NOTES

No excessive rust or corrosion

Tire condition

0 / 0 (0%)

Front driver side tire

75-100% remaining

All four tires are matching. All four tires are in excellent condition and have been recently replaced.



Photo 90



Photo 91



Photo 92

Front passenger side tire

75-100% remaining



Photo 93



Photo 94

Rear driver side tire

75-100% remaining



Photo 95



Photo 96

Rear passenger side tire

75-100% remaining




Photo 97



Photo 98

Spare tire and equipment

Spare and tools present



Photo 99



Photo 100

Battery / charging system 0 / 0 (0%)

Battery date Na

Standing voltage 12.8

Loaded voltage 14.55

Battery is accepting the charge from the alternator and the alternator charge output is correct



Photo 101

Engine Testing / Condition

2 / 2 (100%)

Internal engine inspection w/ borescope camera

Engine clean internally, no gunk or sludge presents. Proper signs of maintenance present. Block test passed, no internal combustion leak out. Coolant mixture correct and cooling system functionality is healthy. All external engine accessories in good working. No leaks or seepage from anywhere on the engine. External drive belts in decent condition. Currently no concern in mechanical issues present in relation to the engine or related accessories.




Photo 102



Photo 103



Photo 104



Photo 105



Photo 106



Photo 107



Photo 108



Photo 109



Photo 110



Photo 111



Photo 112




Photo 113



Photo 114



Photo 115



Photo 116



Photo 117



Photo 118



Photo 119



Photo 120

Engine block test

Pass



Photo 121



Photo 122



Photo 123



Photo 124

Coolant mixture test

Pass

Air filter condition

Normal wear

Engine oil condition

Normal wear

Engine oil level

Healthy

Engine oil leaks

None















Coolant level

Healthy

Coolant hoses

Healthy

Radiator condition / function	Healthy
Engine operating temperature	Healthy
Cooling fan function	Healthy
Drive belt condition	Healthy
Abnormal engine knock	None
Abnormal valve train rattle	None
Abnormal bearing noises	None
Engine gunk / sludge	None
Fuel tank	Healthy
Fuel injectors / lines	Healthy
Valve cover gaskets	Healthy
Intake manifold gasket	Healthy
Cylinder head gasket	Healthy
Oil pan gasket	Healthy
Timing cover gasket	Healthy
Rear main seal	Healthy
Timing belt / components	Healthy
Exhaust manifold	Healthy
External engine accessories	Healthy

Transmission / Differentials	0 / 0 (0%)
Transmission fluid level	Healthy
Transmission fluid condition	Healthy
Transmission fluid leaks	None
<p>No transmission fluid leaks from the transmission casing or the transmission pan area. The tail shaft seal is free of any fluid leaks. The driveshaft is in healthy condition. Shift transitions out on the road are correct across the board. No fluid leak out from the rear differential. 4 x 4 system functionality is correct.</p>	
<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Photo 125</p> </div> <div style="text-align: center;">  <p>Photo 126</p> </div> <div style="text-align: center;">  <p>Photo 127</p> </div> <div style="text-align: center;">  <p>Photo 128</p> </div> <div style="text-align: center;">  <p>Photo 129</p> </div> <div style="text-align: center;">  <p>Photo 130</p> </div> </div> <div style="display: flex; justify-content: space-around; margin-top: 10px;"> <div style="text-align: center;">  <p>Photo 131</p> </div> <div style="text-align: center;">  <p>Photo 132</p> </div> </div>	
Transmission cooler / lines	Healthy
Front differential condition	Healthy
<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Photo 133</p> </div> <div style="text-align: center;">  <p>Photo 134</p> </div> <div style="text-align: center;">  <p>Photo 135</p> </div> </div>	
Center differential condition	Healthy
Rear differential condition	Healthy
<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Photo 136</p> </div> <div style="text-align: center;">  <p>Photo 137</p> </div> <div style="text-align: center;">  <p>Photo 138</p> </div> </div>	
Differential leaks	None
4x4 function / engagement	Healthy
Clutch engagement	Healthy
Gear engagement	Healthy
Shift transitions	Healthy

Drive shaft condition

Healthy

Suspension condition 0 / 0 (0%)

Front shocks / struts

Healthy

Normal fatigue notice to the suspension components. All of the suspension components seem to be original. None of the suspension components are blown out and due form the replacement. The No excessive surface rust on the exposed metal. No abnormal noise or feedback from the suspension while out on the road. All of the rubber in relation to the mounts, joints and bushings has decent texture.



Photo 139



Photo 140



Photo 141



Photo 142



Photo 143



Photo 144



Photo 145



Photo 146



Photo 147

Rear shocks / struts

Healthy



Photo 148



Photo 149



Photo 150



Photo 151



Photo 152



Photo 153



Photo 154



Photo 155

Control arms upper

Healthy

Control arms lower

Healthy

Ball joints

Healthy

Bushings

Healthy

Torsion bars

Healthy

Coilover function

N/A

Air ride function

N/A

Airbag condition







N/A

Abnormal rust / corrosion to metals

None

Deterioration of rubbers

None

Braking system condition	0 / 0 (0%)
Brake fluid condition	Healthy
Brake fluid level	Healthy
Brake fluid leaks	None
Moisture content in brake fluid	None
Brake lines	Healthy
Brake calipers front	Healthy
Brake calipers rear	Healthy
Brake drums rear	N/A
Brake rotors front	Healthy
Brake rotors rear	Healthy
Front brake pad life remaining	75-100% remaining
<p>Right about 75% brake pad light remaining on both the front and rear brake system</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Photo 156</p> </div> <div style="text-align: center;">  <p>Photo 157</p> </div> <div style="text-align: center;">  <p>Photo 158</p> </div> </div>	
Rear brake pad life remaining	75-100% remaining
<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;">  <p>Photo 159</p> </div> <div style="text-align: center;">  <p>Photo 160</p> </div> <div style="text-align: center;">  <p>Photo 161</p> </div> </div>	
E-brake function	Healthy

Steering system condition	0 / 0 (0%)
Steering wheel	Healthy
Steering column	Healthy
Steering knuckle / shaft	Healthy
Steering box	N/A
Rack and pinion condition	Healthy
Inner tie rods	Healthy
outer tie rods	Healthy
Rack boots	Healthy
Power steering pump	Healthy
power steering lines	Healthy
Power steering leaks	None
Power steering fluid level	Healthy
Electric steering motor	N/A
Abnormal play / slack in steering	None
Steering alignment on road	Healthy

Computer diagnostic scan

0 / 0 (0%)

Engine control module

Healthy

At the time of the inspection, there were no active warning lights present. All of the live feed diagnostic testing was successfully passed. All of the live feed emission testing was successfully passed. There was a couple of fault coats in relation to the tail lights, this is due to the aftermarket tail lights installed on the vehicle, the functionality of the tail lights is correct.




Photo 162




Photo 163



Photo 164



Photo 165



Photo 166



Photo 167

Transmission control module

Healthy

Anti lock brake (ABS) module

Healthy

SRS module

Healthy

hybrid control module

N/A

Suspension control module

N/A

Vehicle road test

0 / 0 (0%)

Vehicle road test comments / concerns

Normal drive characteristics present as expected for the Asian mileage on this specific vehicle. No major/concerning drive abnormalities or issues.

Value of vehicle / Diminished value due to repairs or current damage

0 / 0 (0%)

No diminished value due to no structural damage presence or any structural damage repair work done

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5




Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11




Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89



Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101




Photo 102



Photo 103




Photo 104



Photo 105



Photo 106



Photo 107



Photo 108



Photo 109



Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115



Photo 116



Photo 117



Photo 118



Photo 119



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124



Photo 125



Photo 126



Photo 127



Photo 128



Photo 129



Photo 130



Photo 131



Photo 132



Photo 133



Photo 134



Photo 135



Photo 136



Photo 137



Photo 138



Photo 139



Photo 140



Photo 141



Photo 142



Photo 143



Photo 144



Photo 145



Photo 146



Photo 147



Photo 148



Photo 149



Photo 150



Photo 151



Photo 152



Photo 153



Photo 154



Photo 155



Photo 156



Photo 157



Photo 158



Photo 159



Photo 160



Photo 162



Photo 161





Photo 163

Photo 164





Photo 165

Photo 166




Photo 167