



"Buy or sell your next vehicle with peace of mind"

## Peace of Mind Automotive Inspection Report.

**Joe Trejo Jr.**  
**210-557-0686**

**Complete**

Score	4 / 4 (100%)	Flagged items	0	Actions	0
-------	--------------	---------------	---	---------	---

<b>Site conducted</b>	Unanswered
<b>Customer name</b>	LMJ Auto motor sales
<b>Date / Time</b>	Dec 10th
<b>Payment method</b>	Invoice
<b>Inspection cost</b>	199
<b>Vehicle Year / Make / Model / Color</b>	2019 Chevy Colorado

<b>VIN</b>	75203 last 5
	Photo 1

<b>license plate</b>	Dealer
<b>Mileage</b>	27693
<b>Color</b>	White

**Interior Electrical Functions**

2 / 2 (100%)

<b>Horn function</b>	Function correct
<b>Interior lighting function</b>	Function correct
<b>Power lock function</b>	Function correct
<b>Power window function</b>	Function correct
<b>Power seat function</b>	Function correct
<b>Power Doors / lift gate function</b>	N/A
<b>Air conditioning below 60*</b>	Yes
<b>Heater above 90*</b>	Yes
<b>Climate controls function</b>	Function correct
<b>Radio / display screen function</b>	Function correct
<b>Speakers performing correctly</b>	Function correct
<b>GPS function</b>	N/A
<b>Satellite radio function</b>	N/A
<b>12V power supply function</b>	Function correct
<b>Wireless charging function</b>	N/A
<b>Cooled seat function</b>	N/A
<b>Heated seat function</b>	N/A
<b>Remote entry function</b>	N/A

**ADDITIONAL NOTES**

Vehicle interior electrical functionality is correct across-the-board, no in operable functions

## Interior Condition

Seat belt function	Function correct
Front seat condition	Normal wear
Rear seat condition	N/A
Carpeting condition	Normal wear
Headliner condition	Normal wear
Door panel condition	Normal wear
Dashboard condition	Normal wear
Headliner condition	Normal wear
Center console condition	Normal wear
Glove compartment condition	Normal wear
Sun visor condition	Normal wear
Trunk / Cargo area condition	Normal wear
Trim pieces condition	Normal wear

## ADDITIONAL NOTES

Normal wear to the interior as expected for the age and mileage on the vehicle. No water damage to the carpet or carpet installation. No rust on the bottom side of the dash. No evidence of flood damage present. No evidence of the vehicle being smoked inside. no severely damaged or missing panels. See all interior photos for evidence of current condition.



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29

## Exterior Body / Structural Condition

### Paint depth on metal body panels

The majority of the exterior metal body panels have been repainted sometime after factory. The majority of the metal body panels are original to the vehicle. There is no structural damage presents or any structural damage repair work done. There was a little bit of bodywork present on the front driver side fender, as well as the passenger side of the truck bed. All of the other panels were just repainted. The front windshield has been replaced with a non-OE replacement. Normal to exterior as expected for the mileage on the vehicle, including chips, scrapes, scratches. The driver side mayor is missing the plastic cover. See all exterior photos for evidence of current condition.



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89



Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101



Photo 102



Photo 103



Photo 104



Photo 105



Photo 106



Photo 107



Photo 108

<b>Front bumper condition</b>	Normal wear
<b>Rear bumper condition</b>	Normal wear
<b>Hood panel condition</b>	Normal wear
<b>Driver side fender condition</b>	Normal wear
<b>Passenger side fender condition</b>	Normal wear
<b>Roof panel condition</b>	Normal wear
<b>Front driver side door Condition</b>	Normal wear
<b>Rear driver side door condition</b>	Normal wear
<b>Front passenger side door condition</b>	Normal wear
<b>Rear passenger side door condition</b>	Normal wear

<b>Driver side quarter panel condition</b>	N/A
<b>Passenger side quarter panel condition</b>	N/A
<b>Trunk panel condition</b>	N/A
<b>Truck Bed condition</b>	Normal wear
<b>Tail gate condition</b>	Normal wear
<b>Chassis / Frame condition</b>	Normal wear
<b>Frame rail condition</b>	Normal wear
<b>Subframe condition</b>	Normal wear
<b>Engine cradle condition</b>	Normal wear
<b>Skid / Dust cover condition</b>	Normal wear
<b>Collapse beam condition</b>	Normal wear
<b>Window trim condition</b>	Normal wear
<b>Weather stripping condition</b>	Normal wear
<b>Front windshield condition</b>	Normal wear
<b>Other window glass condition</b>	Normal wear
<b>Wheel / Hubcap condition</b>	Normal wear

#### **ADDITIONAL NOTES**

No excessive rust or corrosion to the frame/chassis vehicle has been utilized in a healthy climate throughout its lifespan

## Tire condition

### Front driver side tire

50-75% remaining

This specific tire does not match the other three tires, this tire is dated from 2024 and has a ride around 65% tread life remaining.



Photo 109



Photo 110



Photo 111



Photo 112

### Front passenger side tire

25-50% remaining

The other three tires are matching, tires are dated from 2018 and have only around 35% tread life remaining.



Photo 113



Photo 114




Photo 115



Photo 116

### Rear driver side tire

25-50% remaining



Photo 117



Photo 118



Photo 119

### Rear passenger side tire

25-50% remaining




Photo 120



Photo 121



Photo 122

### Spare tire and equipment

Spare and tools present



Photo 123

## Battery / charging system

**Battery date**

03/25

**Standing voltage**

13.03



Photo 124

**Loaded voltage**

14.6

Battery is accepting the charge from the alternator and the alternator charge output is correct



Photo 125

**Engine Testing / Condition**

2 / 2 (100%)

**Internal engine inspection w/ borescope camera**

Engine clean internally, no gunk or sludge presents. Proper signs of maintenance present. Block test passed, no internal combustion leak out. Coolant mixture correct and cooling system functionality is healthy. All external engine accessories in good working. Small amount of oil seepage notice from the oil pan gasket area, replacement of the oil pan gasket will be a future repair to expect. External drive belts in decent condition. Currently no concern in mechanical issues present in relation to the engine or related accessories.



Photo 126



Photo 127



Photo 128



Photo 129



Photo 130



Photo 131



Photo 132



Photo 133



Photo 134



Photo 135



Photo 136



Photo 137



Photo 138



Photo 139



Photo 140



Photo 141



Photo 142



Photo 143



Photo 144

**Engine block test**

Pass

**Coolant mixture test**

Pass

**Air filter condition**

Normal wear

**Engine oil condition**

Normal wear

**Engine oil level**

Healthy

**Engine oil leaks**

None

Small amount of oil seepage noticed at the oil pan gasket

**Coolant level**

Healthy

**Coolant hoses**

Healthy

**Radiator condition / function**

Healthy

Engine operating temperature	Healthy
Cooling fan function	Healthy
Drive belt condition	Healthy
Abnormal engine knock	None
Abnormal valve train rattle	None
Abnormal bearing noises	None
Engine gunk / sludge	None
Fuel tank	Healthy
Fuel injectors / lines	Healthy
Valve cover gaskets	Healthy
Intake manifold gasket	Healthy
Cylinder head gasket	Healthy
Oil pan gasket	Issue present

Small amount of oil residue/oil seepage noticed at the backside of the oil pan gasket area, a future repair to expect will be a replacement of the oil pan gasket



Photo 145



Photo 146



Photo 147

Timing cover gasket	Healthy
Rear main seal	Healthy
Timing belt / components	Healthy
Exhaust manifold	Healthy
External engine accessories	Healthy

## Transmission / Differentials

**Transmission fluid level**

Healthy

**Transmission fluid condition**

Healthy

**Transmission fluid leaks**

None

No transmission fluid leak out from the transmission casing or the transmission pan area. Drive shaft and seal is free of any fluid leaks. The rear differential is free of any fluid leak out. Shift transitions out on the road are correct across the board. Clutch engagement is correct.



Photo 148



Photo 149



Photo 150



Photo 151



Photo 152



Photo 153



Photo 154



Photo 155

**Transmission cooler / lines**

Healthy

**Front differential condition**

N/A

**Center differential condition**

N/A

**Rear differential condition**

Healthy



Photo 156



Photo 157



Photo 158



Photo 159

**Differential leaks**

None

**4x4 function / engagement**

N/A

**Clutch engagement**

Healthy

**Gear engagement**

Healthy

**Shift transitions**

Healthy

**Drive shaft condition**

Healthy

**Suspension condition****Front shocks / struts**

Healthy

Normal fatigue notice to the suspension components. All of the suspension components seem to be original. None of the suspension components are blown out and due form the replacement. The No excessive surface rust on the exposed metal. No abnormal noise or feedback from the suspension while out on the road. All of the rubber in relation to the mounts, joints and bushings has decent texture.



Photo 160



Photo 161



Photo 162



Photo 163



Photo 164



Photo 165



Photo 166



Photo 167



Photo 168



Photo 169

**Rear shocks / struts**

Healthy



Photo 170



Photo 171



Photo 172



Photo 173



Photo 174



Photo 175



Photo 176



Photo 177



Photo 178



Photo 179

**Control arms upper**

Healthy

**Control arms lower**

Healthy

**Ball joints**

Healthy

**Bushings**

Healthy

**Torsion bars**

Healthy

**Coilover function**

N/A

**Air ride function**

N/A

**Airbag condition**

N/A

**Abnormal rust / corrosion to metals**

None

**Deterioration of rubbers**

None

## Braking system condition

Brake fluid condition	Healthy
Brake fluid level	Healthy
Brake fluid leaks	None
Moisture content in brake fluid	None
Brake lines	Healthy
Brake calipers front	Healthy
Brake calipers rear	Healthy
Brake drums rear	N/A
Brake rotors front	Healthy
Brake rotors rear	Healthy
Front brake pad life remaining	50-75% remaining

There is right about 50% brake pad life remaining on both the front and rear brake system. Brake rotors both front and rear are in healthy condition.



Photo 180



Photo 181



Photo 182

## Rear brake pad life remaining

50-75% remaining



Photo 183



Photo 184



Photo 185

## E-brake function

Healthy

**Steering system condition**

<b>Steering wheel</b>	Healthy
<b>Steering column</b>	Healthy
<b>Steering knuckle / shaft</b>	Healthy
<b>Steering box</b>	N/A
<b>Rack and pinion condition</b>	Healthy
<b>Inner tie rods</b>	Healthy
<b>Outer tie rods</b>	Healthy
<b>Rack boots</b>	Healthy
<b>Power steering pump</b>	N/A
<b>Power steering lines</b>	N/A
<b>Power steering leaks</b>	N/A
<b>Power steering fluid level</b>	N/A
<b>Electric steering motor</b>	Healthy
<b>Abnormal play / slack in steering</b>	None
<b>Steering alignment on road</b>	Healthy

## Computer diagnostic scan

### Engine control module

Healthy

All of the control modules on the vehicle were free of any live/active diagnostic fault codes. All live feed diagnostic testing was successfully passed. All live feed emissions testing was successfully passed.



Photo 186



Photo 187

### Transmission control module

Healthy

### Anti lock brake (ABS) module

Healthy

### SRS module

Healthy

### hybrid control module

N/A

### Suspension control module

N/A

## Vehicle road test

### Vehicle road test comments / concerns

Overall, the vehicle functionality was correct out on the road, across-the-board, no drivability abnormalities or issues present.

---

**Value of vehicle / Diminished value due to repairs or current damage**

No diminished value due to no structural damage presents nor any structural damage repair work done

---

## Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7




Photo 8



Photo 9



Photo 10



Photo 11



Photo 12




Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21




Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89



Photo 90




Photo 91



Photo 92




Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101



Photo 102



Photo 103



Photo 104



Photo 105



Photo 106



Photo 107



Photo 108



Photo 109



Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115



Photo 116



Photo 117



Photo 118



Photo 119



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124



Photo 125



Photo 126



Photo 127




Photo 128



Photo 129



Photo 130



Photo 131



Photo 132



Photo 133



Photo 134




Photo 135




Photo 136



Photo 137



Photo 138



Photo 139



Photo 140



Photo 141



Photo 142



Photo 143




Photo 144



Photo 145



Photo 146




Photo 147



Photo 148



Photo 149



Photo 150




Photo 151



Photo 152



Photo 153



Photo 154



Photo 155



Photo 156



Photo 157



Photo 158



Photo 159



Photo 160



Photo 161



Photo 162



Photo 163



Photo 164



Photo 165



Photo 166



Photo 167



Photo 168



Photo 169



Photo 170



Photo 171



Photo 172



Photo 173




Photo 174



Photo 175



Photo 176



Photo 177



Photo 178



Photo 179




Photo 180




Photo 181



Photo 182



Photo 183



Photo 184




Photo 185

Photo 186




Photo 187