


APPENDIX B
Record Photographs





1

South-East Elevation – Area A



2

South-East Elevation – Area A - Window Lintel



3
South-East Elevation – Area C



4
South-East Elevation – Area C



5
South-East Elevation – Area C



6
South-East elevation – Area C – Door Lintel



7

South-East Elevation – Stable



8

South-East Elevation – Stable – Fragmented Stone



9

South-East Elevation – Stable – Fragmented Stone



10

South-East Elevation – Stable – Defective Lintel



11
South-West Elevation – Area C



12
South-West Elevation – Area C – Door Lintel




13

South-West Elevation – Area C – Corroded Plate



14

South-West Elevation – Area B



15

South-West Elevation – Area B – Vertical Cracking



16

South-West Elevation – Area B – Cracking Above Window



17

North-West Elevation – Area C



18

North-West Elevation – Area A – Cracking near North Corner



19

North-West elevation – Area A – Vertical Cracking



20

North-West Elevation – Area A – Cracking at Junction with Area B



21

North-West Elevation – Area B – Window Lintel



22

North-East Elevation – Area A



23

North-East Elevation – Area A – Vertical Crack



24

North-East Elevation – Area A – Vertical Crack



25

North-East elevation – Area A – Wall Lean




26

Area A – Main Beam



27
Area A – North-East Wall



28
Area A – North-East wall




29

Area A – North-West Wall – Vertical Crack



30

Area A – Truss 1



31
Area A – Truss 1



32
Area A – Truss 1



33
Area A – Truss 2



34
Area A – Truss 2 – Collar Removed



35

Area A – Truss 2 – Bottom Tie Cut Away



36

Area A – North-West Wall – Vertical Crack Near North Corner



37

Area B – Beam to Machinery Frame into North-West wall



38

Area B – Rot in Beam End




39

Area B – Vertical Crack in North-West Wall



40

Area B – Lintel Failure to North-West Window



41
Area B – Truss 4




42
Area B – Truss 3



43

Area B – Vertical Crack in North-West Wall



44

Area C – North-East Wall to Grain Dryer



45

Area C – North-West Wall



46

Area C – North-east Wall Opening



47

Area C – North-East Wall Opening



48

Area C – North-East Wall Opening



49
Area C – Roof Construction



50
Area C – First Floor



51

Area C – North-East Wall Collapse



52

Stable – North-West Wall



53

Stable - North-East Wall



54

Stable - Roof



55

Store – Entrance Door