


Movement around the Building RA 002

Consequence	5	10	15	20	25
	4	8	12	16	20
	3	6	9	12	15
	2	4	6	8	10
	1	2	3	4	5
Likelihood					

- Unacceptable – Stop activity
- Adequate – Monitor for continual compliance
- Acceptable – No further action / monitor

Risk Assessment:	002 Movement
Assessors Name:	Rob Shaw
Signature:	
Date:	November 2023
Review:	November 2024

Location: 6 New Road – PE14-9AB

Likelihood	1 = Very unlikely	2 = Unlikely	3 = Fairly likely	4 = Likely	5 = Very likely
Consequence	1 = Insignificant	2 = Minor	3 = Moderate	4 = Major	5 = Catastrophic

Hazard	Who can be harmed & how	Risk Rating			Control measures in place	Residual Risk		
		L	C	R		L	C	R
Slip , Trips and Falls	Village Hall employees, visitors, hirers and contractors, delivery / collection drivers, trespassers and intruders.	5	3	15	<p>Paths, Steps and Ramps are maintained to prevent any Slips. Trips and falls whilst moving around the building and outside areas.</p> <p>Internal and External Lighting are sufficient to allow safe ingress and egress from the building.</p> <p>Mats are provided at the main entrance to prevent excess rainwater to be brought into the hall should there be bad weather.</p>	2	3	6
Damage to persons	Village Hall employees, visitors and contractors, during an evacuation of the building, trespassers and intruders.	5	3	15	<p>Are entrance areas free from clutter to allow easy ingress and egress.</p> <p>Flooring is fixed and well maintained to prevent accidents.</p> <p>All Glazed doors are fitted with toughened and safety glass.</p>	2	3	6

