



Triangle Pond Management
 405 S Rogers Ln
 Raleigh, NC 27610
 (919)398-3221
 Office@TrianglePondManagement.com
 www.TrianglePondManagement.com
Maintenance Service Report

Customer Name:		Date:	
Chandler Woods MOA		11/29/2022	
Address:			
214 Abbot Pl			
Aquatic Technician:			
Anthony Montefusco			
Time of Arrival:		Time of Departure:	
1:03 PM		3:00 PM	
Drive Time:			
20 minutes			
Type of Device(s) Maintained:			
BMP 1, BMP 2, BMP 3			

Unwanted Vegetation:			
<input type="checkbox"/> Filamentous Algae <input type="checkbox"/> Planktonic Algae <input type="checkbox"/> Emergent Aquatics <input type="checkbox"/> Submersed Aquatics <input type="checkbox"/> Free Floating Aquatics <input type="checkbox"/> Broadleaf/Invasive Grasses <input type="checkbox"/> Other (see additional notes)			
Method of Treatment Used:			
<input type="checkbox"/> Algaecide <input type="checkbox"/> Herbicide <input type="checkbox"/> Dye (Black/Blue) <input type="checkbox"/> Other (see additional notes)			

General Inspection:	Comment:
Was any trash found in or around the devices?	Yes
Were the Inlets & Outlets clear of all debris and functioning properly?	No See notes
Was the Rip Rap clear of any unwanted vegetation?	Yes
Was the required beneficial vegetation healthy and flourishing?	No Dormant
Was any Beaver/Muskrat activity observed?	No
Was the water at the proper elevation?	No See notes
Were the devices draining properly?	Yes
Was the Riser/Trash Rack clear of trash and debris?	Yes
Was any erosion observed during the visit?	No

Optional Services:		Comment:
Were Mowing services completed?	Yes	
Was the Rip Rap in the correct position?	Yes	
Were overseeding services performed this visit?	No	
Was the Drain Valve exercised?	No	
Was the Fountain/Aerator functioning properly?	N/A	

Wildlife Observations

Healthy for Aquatic Environment:		Unhealthy for Aquatic Environment (Removal/Remediation Recommended):
<input type="checkbox"/> Bass	<input type="checkbox"/> Bluegill/Sunfish	<input type="checkbox"/> Geese
<input type="checkbox"/> Grass Carp	<input type="checkbox"/> Minnows/Gambusia	<input type="checkbox"/> Excessive Turtles
<input type="checkbox"/> Cray Fish	<input type="checkbox"/> Turtles	<input type="checkbox"/> Snakes

Repairs?	Comment:
Are repairs required? No	

Overall Condition of Devices:
<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor

Additional Notes:

Mowing and string trimming services were completed today.
 Water levels were higher than normal due to previous rainfall but all devices were draining properly during our visit.
 Walked the perimeter of the device's and picked up trash.
 Removed debris from inlet's outlets and riprap areas.
 All other systems were inspected for proper function and all was in good working condition.

Technician's Signature:

A.M.

Photo 1: **Photo 2:**



BMP3 view

BMP3 view

Photo 3: **Photo 4:**



BMP3 inlet

BMP3 riser

Photo 5:	Photo 6:
	
BMP3 inside riser	BMP2 view
Photo 7:	Photo 8:
	
BMP2 view	BMP2 backside view

<p>Photo 9:</p>	<p>Photo 10:</p>
	
<p>BMP2 inlet</p>	<p>BMP2 riser</p>
<p>Photo 11:</p>	<p>Photo 12:</p>
	
<p>BMP2 inside riser</p>	<p>BMP2 outflow</p>

Photo 13:	Photo 14:
	
BMP1 view	BMP1 view
Photo 15:	Photo 16:
	
BMP1 backside view	

Photo 17:



BMP1 view

Photo 18:



BMP1 riser

Photo 19:



BMP1 inside riser

Photo 20:



BMP1 outflow