



**Triangle Pond Management**  
 405 S Rogers Ln  
 Raleigh, NC 27610  
 (919)398-3221  
 Office@TrianglePondManagement.com  
 www.TrianglePondManagement.com  
**Maintenance Service Report**

|                                      |                           |                    |  |
|--------------------------------------|---------------------------|--------------------|--|
| <b>Customer Name:</b>                |                           | <b>Date:</b>       |  |
| Chandler Woods MOA                   |                           | 2/24/2023          |  |
| <b>Address:</b>                      |                           |                    |  |
| 214 Abbot Pl                         |                           |                    |  |
| <b>Aquatic Technician:</b>           |                           |                    |  |
| Justin Tripp                         |                           |                    |  |
| <b>Time of Arrival:</b>              | <b>Time of Departure:</b> | <b>Drive Time:</b> |  |
| 6:53 AM                              | 10:14 AM                  | 16 min             |  |
| <b>Type of Device(s) Maintained:</b> |                           |                    |  |
| BMP 1, BMP 2, BMP 3                  |                           |                    |  |

|   |  |   |   |
|---|--|---|---|
| <b>Unwanted Vegetation:</b>                           |  |   |   |
| <input checked="" type="checkbox"/> Filamentous Algae | <input type="checkbox"/> Planktonic Algae                      | <input type="checkbox"/> Emergent Aquatics            | <input type="checkbox"/> Submersed Aquatics           |
| <input type="checkbox"/> Free Floating Aquatics       | <input checked="" type="checkbox"/> Broadleaf/Invasive Grasses | <input type="checkbox"/> Other (see additional notes) |   |
| <b>Method of Treatment Used:</b>                      |  |   |   |
| <input type="checkbox"/> Algaecide                    | <input type="checkbox"/> Herbicide                             | <input type="checkbox"/> Dye (Black/Blue)             | <input type="checkbox"/> Other (see additional notes) |

| General Inspection:   |     | Comment:          |
|---|-----|-------------------|
| Was any trash found in or around the devices?                           | Yes | Removed all trash |
| Were the Inlets & Outlets clear of all debris and functioning properly? | No  | Cleared of debris |
| Was the Rip Rap clear of any unwanted vegetation?                       | No  | Controlled        |
| Was the required beneficial vegetation healthy and flourishing?         | No  | Dormant           |
| Was any Beaver/Muskrat activity observed?                               | No  |                   |
| Was the water at the proper elevation?                                  | Yes |                   |
| Were the devices draining properly?                                     | Yes |                   |
| Was the Riser/Trash Rack clear of trash and debris?                     | Yes |                   |
| Was any erosion observed during the visit?                              | Yes | Bare areas        |

| Optional Services:                              |     | Comment: |
|---|-----|----------|
| Were Mowing services completed?                 | No  |          |
| Was the Rip Rap in the correct position?        | Yes |          |
| Were overseeding services preformed this visit? | No  |          |
| Was the Drain Valve exercised?                  | No  |          |
| Was the Fountain/Aerator functioning properly?  | N/A |          |

#### Wildlife Observations

| Healthy for Aquatic Environment:    |   | Unhealthy for Aquatic Environment<br>(Removal/Remediation Recommended): |
|-------------------------------------|---|---|
| <input type="checkbox"/> Bass       | <input type="checkbox"/> Bluegill/Sunfish | <input type="checkbox"/> Geese  |
| <input type="checkbox"/> Grass Carp | <input type="checkbox"/> Minnows/Gambusia | <input type="checkbox"/> Excessive Turtles                              |
| <input type="checkbox"/> Cray Fish  | <input type="checkbox"/> Turtles          | <input type="checkbox"/> Snakes   |

| Repairs?                  | Comment:             |
|---------------------------|----------------------|
| Are repairs required? Yes | See additional notes |

| Overall Condition of Devices:   |
|---|
| <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Poor |


| Additional Notes:   |
|---|
| <p>The devices were walked and all trash was removed.</p> <p>Unwanted vegetation throughout the device was controlled along with filamentous algae.</p> <p>Debris and leaves were cleared from the rip rap areas.</p> <p>Accumulated sediment was removed from the BMP3 inlet.</p> <p>Observed bare areas throughout the basin of BMP3.</p> <p>Please contact our office with any additional questions, concerns, or to schedule repairs.</p> |




| Technician's Signature:   |
|---|
|  |

| Photo 1:  | Photo 2:   |
|---|--|
|    |    |
| BMP3  | BMP3 riser   |
| Photo 3:  | Photo 4:   |
|  |  |
| BMP3 inside riser   | Bare areas at BMP3   |

| Photo 5:  | Photo 6:   |
|---|--|
|    |    |
| BMP3 inlet before   | BMP3 inlet after   |
| Photo 7:  | Photo 8:   |
|  |  |
| BMP3 inlet  | BMP2   |

| Photo 9:  | Photo 10:  |
|---|--|
|    |    |
| BMP2 riser  | BMP2 inside riser  |
| Photo 11:   | Photo 12:  |
|  |  |
| BMP2 inlet  | Backside of dam at BMP2  |

| Photo 13:   | Photo 14:  |
|---|--|
|    |    |
| BMP2 outlet   | BMP3   |
| Photo 15:   | Photo 16:  |
|  |  |
| BMP3  | BMP3 inlet   |

| Photo 17:   | Photo 18:  |
|---|--|
|    |  |
| BMP3 riser  | BMP3 inside riser  |
| Photo 19:   | Photo 20:  |
|  |  |
| BMP3 outlet   |  |