

Additional photos showing the terrible quality of Liscott's door and trim installation.



This image demonstrates, not only the terrible door and trim work performed by Liscott, but also how far out of plumb the walls are. Notice the shape and size of the scabbled in trim that had to be used to get the door to hang plumb



