


- #49 - Leaks along head of CW and Steel - Holes / Gaps Between the Steel, Cladding and CW - missing Insulations . Weatherproof Details Issues - () . Remedial Works required Along Grid B and Curve Area. to Check if 1hr Marine Ply installed and all weatherproof as per own details

Leaks | Peter Mazur | Leaks
Plan: Plan Ground | Location: Lev 1
Tags: #lev_1_cw_canopy, #site_inspection_16.03.23, #zefyr
Created 03-17-2023





Related Tasks
#10 | Leaks | Leaks - Water Ingress from Top , CW , Steel .Steel Erectors - Workmanship To be check Along Grid B and Curved - Installation and Design Review




20 Mar 11:46 AM

Photos - click on it to open in High Quality.



4



5

Davlights



6

Daylight between Steel and Zefyr Flashings




7

Water Marks



8

Daylight between Flashing and Steel



9

External View



10

Externall View



11

Externall View




12

External View



13



14

