

# 4-Point Inspection Form

Insured/Applicant Name: Estate of Diane Devine Application / Policy #: \_\_\_\_\_

Address Inspected: 2820 21st Ln, Vero Beach, FL 32960

Actual Year Built: 1982 Date Inspected: 04/30/2026

## Minimum Photo Requirements:

- ☒ Dwelling: Each side ☒ Roof: Each slope ☒ Plumbing: Water heater (incl TPRV), under cabinet plumbing/drains, exposed valves
- ☒ Main electrical service panel with interior door label
- ☒ Electrical box with panel off
- ☒ All hazards or deficiencies noted in this report

**A Florida-licensed inspector must complete, sign and date this form.**

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

## Electrical System

Separate documentation of any single strand aluminum wiring remediation must be provided and certified by a licensed electrician.

### Main Panel

Type: ☒ Circuit breaker ☐ Fuse

Total Amps: 150

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

### Second Panel

Type: ☒ Circuit breaker ☐ Fuse

Total Amps: 150

Is amperage sufficient for current usage? ☒ Yes ☐ No (explain)

### Indicate presence of any of the following:

- ☐ Cloth wiring
- ☐ Active knob and tube
- ☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum

*\* If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided.*

- ☐ Connections repaired via COPALUM crimp
- ☐ Connections repaired via AlumiConn

### Hazards Present

- ☐ Blowing fuses
- ☐ Tripping breakers
- ☐ Empty sockets
- ☐ Loose wiring
- ☐ Improper grounding
- ☐ Corrosion
- ☐ Over fusing

- ☐ Double taps
- ☐ Exposed wiring
- ☐ Unsafe wiring
- ☐ Improper breaker size
- ☐ Scorching
- ☐ Other (explain)

**General condition of the electrical system:** ☒ Satisfactory ☐ Unsatisfactory (explain)

## Supplemental information

### Main Panel Meter main

Panel age: 6 years

Year last updated: 2020

Brand/Model: Square D

### Second Panel Sub Panel

Panel age: 44 yrs

Year last updated: 1982

Brand/Model: Square D

### Wiring Type(s)

- ☒ Copper ☐ Copper Clad AL ☒ NM, BX or Conduit
- ☐ Single Strand AL ☐ Cloth (Knob & Tube) ☐ Other
- ☐ Multistrand AL ☐ Cloth Jacket Rubber Insulated

## 4-Point Inspection Form

### HVAC System

Central AC: ☒ Yes ☐ No

Central heat: ☒ Yes ☐ No

If not central heat, indicate **primary** heat source and fuel type: \_\_\_\_\_

Are the heating, ventilation and air conditioning systems in good working order? ☒ Yes ☐ No (explain)

Date of last HVAC servicing/inspection: Unknown

#### Hazards Present

Is a wood-burning stove or central gas fireplace present? ☐ Yes ☒ No Was it professionally installed? ☒ Yes ☐ No

Space heater used as primary heat source? ☐ Yes ☒ No

Is the source portable? ☐ Yes ☒ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?

☐ Yes ☒ No

### Supplemental Information

Age of system: 4 years

Year last updated: 2022

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

### Plumbing System

Is there a temperature pressure relief valve on the water heater? ☒ Yes ☐ No

Is there any indication of an active leak? ☐ Yes ☒ No

Is there any indication of a prior leak? ☐ Yes ☒ No

Water heater location: Garage

#### General condition of the following plumbing fixtures and connections to appliances:

|                 | Satisfactory                        | Unsatisfactory           | N/A                      |                     | Satisfactory                        | Unsatisfactory           | N/A                                 |
|-----------------|-------------------------------------|--------------------------|--------------------------|---------------------|-------------------------------------|--------------------------|-------------------------------------|
| Dishwasher      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Toilets             | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| Refrigerator    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Sinks               | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| Washing machine | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Sump pump           | <input type="checkbox"/>            | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Water heater    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Main shut off valve | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |
| Showers/Tubs    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | All other visible   | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/>            |

If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).

### Supplemental Information

Age of Piping Supply System:

X Original to home

\_\_\_\_\_ Completely re-piped

\_\_\_\_\_ Partially re-piped

Age of water heater 2017

(Provide year and extent of renovation in the comments below)

Age of Piping Drain System:

X Original to home

\_\_\_\_\_ Completely re-piped

\_\_\_\_\_ Partially re-piped

#### Type of pipes (check all that apply)

☒ Copper

☐ PEX Year Installed: \_\_\_\_\_

☒ PVC/CPVC

☐ Other (specify)

☐ Galvanized

☐ Cast Iron

☐ Polybutylene

☐ ABS

## 4-Point Inspection Form

**Roof** (With photos of each roof slope, this section can take the place of the *Roof Inspection Form*.)

### Predominant Roof

Covering material: Dim Shingles

Roof age (years): 8 years

Remaining useful life (years): 15 years

Date of last roofing permit: 3/01/18

Date of last update: 2018

If updated (check one):

- ☒ Full replacement  
☐ Partial replacement

% of replacement: \_\_\_\_\_

Overall condition:

- ☒ Satisfactory  
☐ Unsatisfactory (**explain below**)

### Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking  
☐ Cupping/curling  
☐ Excessive granule loss  
☐ Exposed asphalt  
☐ Exposed felt  
☐ Missing/loose/cracked tabs or tiles  
☐ Soft spots in decking  
☐ Visible hail damage

**Any visible signs of leaks?** ☐ Yes ☒ No (If "yes" explain below)

Attic/underside of decking ☐ Yes ☒ No

Interior ceilings ☐ Yes ☒ No

### Secondary Roof

Covering material: \_\_\_\_\_

Roof age (years): \_\_\_\_\_

Remaining useful life (years): \_\_\_\_\_

Date of last roofing permit: \_\_\_\_\_

Date of last update: \_\_\_\_\_

If updated (check one):

- ☐ Full replacement  
☐ Partial replacement

% of replacement: \_\_\_\_\_

Overall condition:

- ☐ Satisfactory  
☐ Unsatisfactory (**explain below**)

### Any visible signs of damage / deterioration?

(check all that apply and explain below)

- ☐ Cracking  
☐ Cupping/curling  
☐ Excessive granule loss  
☐ Exposed asphalt  
☐ Exposed felt  
☐ Missing/loose/cracked tabs or tiles  
☐ Soft spots in decking  
☐ Visible hail damage

**Any visible signs of leaks?** ☐ Yes ☐ No (If "yes" explain below)

Attic/underside of decking ☐ Yes ☐ No

Interior ceilings ☐ Yes ☐ No

**Additional Comments/Observations** (use additional pages if needed):

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  
I certify that the above statements are true and correct.

*dennis guigley*  
Inspector Signature

Owner  
Title

HI 181  
License Number

April 30, 2026  
Date

Windstorm Retrofit, LLC  
Company Name

Home Inspector  
License Type

772 539-2909  
Work Phone

## 4-Point Inspection Form

**Special Instructions:** This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### Photo Requirements

Photos must accompany each *4-Point Inspection Form*. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- **All** hazards or deficiencies

### Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

### Additional Comments or Observations

This section of the *4-Point Inspection Form* must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

### Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



## MGOC-Search Permit Result Export

|                                            |  |                                                     |                               |                                                                                         |                    |
|--------------------------------------------|--|-----------------------------------------------------|-------------------------------|-----------------------------------------------------------------------------------------|--------------------|
| Project Number: 2018030047                 |  | Project Address: 2820 21ST LN , VERO BEACH FL 32960 |                               | Project Description: RE-ROOF - ASPHALT SHINGLES TO ASPHALT SHINGLES, 35 SQS, SLOPE 5:12 |                    |
| Jurisdiction: Indian River County          |  | Project Name: RR RE-ROOF                            |                               | Work Type:                                                                              |                    |
| Project Type Name:                         |  | Status: <b>FINAL</b>                                | Created Date: <b>3/1/2018</b> | Subdivision: MCANSH GROVE SUB                                                           | Unit: Lot: 00014.0 |
| Parcel Number: 33-39-03-00039-0000-00014.0 |  | Designation: Specific Use: VERO BEACH               |                               |                                                                                         |                    |
| Inspection Details:                        |  |                                                     |                               |                                                                                         |                    |
| 999RR - FINAL RE-ROOF                      |  | Scheduled: 3/29/2018                                | Completed: 3/29/2018          | Inspection Result: Final Approved                                                       |                    |
| 154 - ROOF FLASHING                        |  | Scheduled: 3/28/2018                                | Completed: 3/28/2018          | Inspection Result: Partial Approved                                                     |                    |
| 603 - ROOF DRY-IN                          |  | Scheduled: 3/28/2018                                | Completed: 3/28/2018          | Inspection Result: Approved                                                             |                    |
| 606 - INTERMEDIATE ROOF COVERING           |  | Scheduled: 3/28/2018                                | Completed: 3/28/2018          | Inspection Result: Approved                                                             |                    |
| 0021 - REROOF AFFIDAVIT                    |  | Scheduled: 3/1/2018                                 | Completed: 3/21/2018          | Inspection Result: For the Record                                                       |                    |

[insert  
logo  
here]



Front



Right



Rear



Left



Roof



Roof

[insert  
logo  
here]



Roof



Roof




Air Conditioner



Air conditioner label




Heater/Air handler



Heater/Air handler Label



Water Heater




Water Heater label



TPR Valve




Washer Connections




Electrical panel




Electrical panel




Electrical panel



Electrical panel



Electrical panel



Electrical panel



