



“Instant” Block Construction, Site Demolition and Grading

Case Study	
Date	Spring 2017
Location	Residential Site, Marlborough, MA
Facility	Accessory concrete block structure with collapsed roof
Project Scope	Demolition of a concrete block accessory structure and related site work
Time Frame	2 days, start to finish, on time, on budget

Conigliaro Block was tasked with demolishing a concrete block structure that had experienced a roof collapse. The structure was demolished, the concrete block was processed for recycling and the site was cleaned and graded. The project was completed in just two days to meet stringent insurance company requirements.



Call (888) CONIG – 25 for more information