Stormwater Construction Site Inspection Report

Project Name

Rattlesnake Creek Substation

NPDES Tracking Number

CWS-201802602

Location

Allen, NE 68710 United States (42.3741215235017, -96.8290646654524)

Conducted on

31 Aug 2018 03:00 PM

Name

Mario Mendez

Title

Engineer

Contact Information

mmendez@atwell-group.com

Inspector's Qualifications

Registered professional engineer, AZ

Describe Present Phase of Construction

Substation: grounding, terminating. T-line: stringing

Type of Inspection

Regular

Completed on

30 Oct 2018 06:08 PM

Score

1/1.0 - 100.00%

Weather

Question	Response	Details	
Has there been a storm since the last inspection?	No		
Weather at the time of this inspection	Cloudy		
Temperature	68 °F		
Have any discharges occurred since the last inspection?	No		
Are there any discharges at the time of inspection?	No		

31 Aug 2018 -2-

Site BMPs

Question	Response	Details			
Add BMP					
BMP 1					
BMP Number	Substation: Silt fence				
Is BMP Installed?	Yes				
BMP Maintenance Required?	Yes				
Corrective action needed, Notes	Silt fence on east side of Substation was cut and requires replacement. The bottom of portions of the silt fence to the south of the cut silt fence is exposed and requires repair. Silt fence needs to be keyed into soil				
BMP 2					
BMP Number	Substation: Dumpster cover				
Is BMP Installed?	Yes				
BMP Maintenance Required?	No				
BMP 3					
BMP Number	Substation: temp seeding				
Is BMP Installed?	Yes				
BMP Maintenance Required?	No				
BMP 4					
BMP Number	T-line: dumpster cover				
Is BMP Installed?	Yes				
BMP Maintenance Required?	No				

31 Aug 2018 -3-

Overall Site Issues

Question	Response	Details				
Question 1						
Are all slopes and disturbed areas not actively being worked properly stabilized?	Yes					
Maintenance Required?	Yes					
Corrective Action Needed, Notes	See previous section					
Question 2						
Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?						
Question 3						
Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	No					
Maintenance Required?	Yes					
Corrective Action Needed, Notes	See previous section					
Question 4						
Are discharge points and receiving waters free of any sediment deposits?						
Question 5						
Are Storm Drain Inlets properly protected?						
Question 6						
Is the construction exit preventing sediment from being tracked into the street?	Yes					
Maintenance Required?	No					
Question 7						
Is trash/litter from work areas collected and placed in covered dumpsters?	Yes					

31 Aug 2018 -4-

Question	Response	Details
Maintenance Required?	No	
Question 8		
Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?		
Question 9		
Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?		
Question 10		
Are materials that are potential stormwater contaminants stored inside or under cover?		
Question 11		
Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled?		
Question 12		
Describe any other incidents of non-compliance not described above:		

31 Aug 2018 - 5 -

Certification Statement

Questio	n	Resp	onse	Details		
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."						
Name and Title:						
Signature:	Mario Mendez					
Date:		31 Aug 2018				

31 Aug 2018 - **6** -