

# Stormwater Construction Site Inspection Report

**Project Name**

Rattlesnake Creek Substation and T-line

**NPDES Tracking Number**

CWS-201802602

**Location**

86601-86639 586 Ave  
Allen, NE 68710  
United States  
(42.38134224340139, -96.82327569101338)

**Conducted on**

27 Oct 2018 02:09 PM

**Name**

Mario Mendez

**Title**

Engineer

**Contact Information**

mmendez@atwell-group.com

**Inspector's Qualifications**

Registered Professional Engineer, AZ

**Describe Present Phase of Construction**

Substation and T-Line: Mechanically complete

**Type of Inspection**

Regular

**Completed on**

13 Dec 2018 09:25 AM

**Score**

1/1.0 - 100.00%

## Weather

Question	Response	Details
Has there been a storm since the last inspection?	No	
Weather at the time of this inspection	Clear	
Temperature	58 °F	
Have any discharges occurred since the last inspection?	No	
Are there any discharges at the time of inspection?	No	

## Site BMPs


Question	Response	Details
Add BMP		
BMP 1		
BMP Number	Substation: Silt Fence	
Is BMP Installed?	Yes	
BMP Maintenance Required?	Yes	
Corrective action needed, Notes	Silt fence on the East side of the substation is torn down and Mortenson has not been repaired. Silt fence on the West side of the substation is torn and requires repair.	
BMP 2		
BMP Number	Substation: temp seeding	
Is BMP Installed?	Yes	
BMP Maintenance Required?	No	
BMP 3		
BMP Number	Substation: Wattles	
Is BMP Installed?	Yes	
BMP Maintenance Required?	No	

## Overall Site Issues

Question	Response	Details
<b>Question 1</b>		
Are all slopes and disturbed areas not actively being worked properly stabilized?	Yes	
Maintenance Required?	No	
<b>Question 2</b>		
Are natural resource areas (e.g., streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?		
<b>Question 3</b>		
Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	Yes	
Maintenance Required?	Yes	
Corrective Action Needed, Notes	See previous section	
<b>Question 4</b>		
Are discharge points and receiving waters free of any sediment deposits?		
<b>Question 5</b>		
Are Storm Drain Inlets properly protected?		
<b>Question 6</b>		
Is the construction exit preventing sediment from being tracked into the street?	Yes	
Maintenance Required?	No	
<b>Question 7</b>		
Is trash/litter from work areas collected and placed in covered dumpsters?	Yes	
Maintenance Required?	No	

Question	Response	Details
<b>Question 8</b>		
Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?		
<b>Question 9</b>		
Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?		
<b>Question 10</b>		
Are materials that are potential stormwater contaminants stored inside or under cover?		
<b>Question 11</b>		
Are non-stormwater discharges (e.g., wash water, dewatering) properly controlled?		
<b>Question 12</b>		
Describe any other incidents of non-compliance not described above:	Due to unsafe and inaccessible site conditions the regular inspection scheduled for 10/25 was postponed to 10/27	

## Certification Statement

Question		Response	Details
<p>"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."</p>			
Name and Title:		Mario Mendez, Engineer	
Signature:		12 Dec 2018 05:13 PM	
Date:		27 Oct 2018	