Insured/Applicant Name:	ured/Applicant Name: Application / Policy #:				
Address Inspected: 123 Example street, Pompano Beach, FL 33064					
Actual Year Built: 1973					
Actual Year Built.		Date inspected			
Minimum Photo Requirements					
☑ Dwelling: Each side ☑ Roof: Each slope ☑		inder cabinet plumbing/d	rains, exposed valves		
✓ Main electrical service panel with interior doo	or label				
☑ Electrical box with panel off					
☑ All hazards or deficiencies noted in this report					
A Florida-licensed inspector must complete, sign and date this form.					
Be advised that Underwriting will rely on the inform	mation in this sample form	, or a similar form, that is	obtained from the Florida licensed professional of		
your choice. This information only is used to deter			e of the suitability, fitness or longevity of any of the		
systems inspected.					
Electrical System					
Separate documentation of any aluminum wiring r	remediation must be provide	ded and certified by a lice	ensed electrician.		
Main Panel		Second Panel	_		
Type: ☑ Circuit breaker ☐ Fuse		Type: ☐ Circuit breaker ☐ Fuse			
Total Amps: 150 Is amperage sufficient for current usage? ✓ Yes	☐ No (explain)	Total Amps: Is amperage sufficient f	or current usage? ☐ Yes ☐ No (explain)		
Indicate presence of any of the following:					
☐ Cloth wiring					
☐ Active knob and tube					
☐ Branch circuit aluminum wiring (If present, d	escribe the usage of all al	uminum wiring):			
* If single strand (aluminum branch) wiring, prov	ide details of all remediation	on. Separate documenta	tion of all work must be provided.		
☐ Connections repair via COPALUM crimp					
☐ Connections repair via AlumiConn					
Hazards Present		☐ Double taps			
☐ Blowing fuses		Exposed wiring			
☐ Tripping breakers		☐ Unsafe wiring			
☐ Empty sockets		☐ Improper breaker size			
□ Loose Wiring		□ Scoring			
☐ Improper grounding		☐ Other (explain)			
☐ Over fusing					
Li Over idaniy					
General condition of the electrical system: ☑ Satisfactory ☐ Unsatisfactory (explain)					
Supplemental information					
Main Panel	Second Panel		Wiring Type		
Panel age: 5 years	Panel age:		☑ Copper		
Year last updated: 2019	Year last updated:		□ NM, BX or Conduit		

Brand/Model:

Brand/Model: General Electric

HVAC System				
Central AC: ☑ Yes ☐ No				
Central heat: ☑ Yes ☐ No				
If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)			
Date of last HVAC servicing/inspection:				
Hazards Present				
Wood burning stove or central gas fireplace not professionally installed?]Yes ☑No			
Space heater used as primary heat source? ☐ Yes ☑ No				
Is the source portable? ☐ Yes ☑ No				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No				
Supplemental Information				
Age of system: 3 years				
Year last updated: 2021				
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s place)			
Plumbing System				
Is there a temperature pressure relief valve on the water heater? $lacktriangle$ Yes $lacktriangle$] No			
Is there any indication of an active leak? ☐ Yes ☑ No				
Is there any indication of a prior leak? ☐ Yes ☑ No				
Water heater location: closet				
General condition of the following plumbing fixtures and connections	to applicances:			
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A			
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets			
Washing Machine □ □ ☑	Sump pump			
Water Heater ☐ ☐	Main shut off valve ☐ ☐			
Showers/Tubs	All other visible ☐ ☐ ☐			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: X Original to home	Type of pipes (check all that apply)			
-	☑ Copper			
Completely re-piped	☑ PVC/CPVC			
Partially re-piped Galvanized (Provide year and extent of renovation in the comments below)				
□ Polybutylene				
	☐ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)					
Predominant Roof Covering material: EDPM Roof age (years): less than 1 Remaining useful life (years): 30 Date of last roofing permit: 03-30-2024 Date of last update: 03-30-2024 If updated (check one):		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):	Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update:		
☑ Full Replacement ☐ Partial Replacement % of replacement		☐ Full Replacement ☐ Partial Replacement % of replacement	☐ Full Replacement ☐ Partial Replacement % of replacement		
Overall condition: ☑ Satisfactory ☐ Unsatisfactory (explain below)		☐ Satisfactory	Overall condition: Satisfactory Unsatisfactory (explain below)		
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No			
Additional Comments/Observations (use additional pages if needed): All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Inspector Signature	Home Inspector	HI12853 License Number	09/11/2024 Date		
Mikes Home Inspections Company Name	Home Inspection License Type	954-546-0812 Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos





front elevation of building









rear elevation of building






Electrical System

Panel Photos







breaker box with cover on

breaker box label

breaker box with cover removed





left side breakers

right side breakers

HVAC System

HVAC Equipment



air handler

air handler label

Plumbing System

Water Heater



water heate



water heater label

Under cabinet plumbing & drains



kitchen faucet



kitchen under sink plumbing






master under sink plumbing



master toilet valve



master shower valves and drain









guest toilet valve

guest faucet guest under sink plumbing



guest shower valves and drain

Roof

Photos of Each Slope



roof elevation pic # 1

roof elevation pic # 2