

# SCHNEIDER LABORATORIES GLOBAL

INCORPORATED

2512 W. Cary Street • Richmond, Virginia • 23220-5117  
804-353-6778 • 800-785-LABS (5227) • (FAX) 804-359-1475

*Over 25 Years of Excellence in Service and Technology*

AIHA/ELLAP 100527, ISO/IEC 17025, NVLAP 101150-0, VELAP 460135, NYELAP/NELAC 11413

## LABORATORY ANALYSIS REPORT

Asbestos Identification by EPA Method<sup>1</sup> 600/R-93/116, EPA 600/M4-82-020

Using SLI A6

**ACCOUNT #:** 1899-13-2639  
**CLIENT:** Apex Environmental Consultants, Inc.  
**ADDRESS:** 14955 W 101st Terrace  
Lenexa, KS 66215-1161  
**PROJECT NAME:** 4739 Bellvue  
**JOB LOCATION:** Kansas City, MO  
**PROJECT NO.:** 130066A  
**PO NO.:**

**DATE COLLECTED:** 2/20/2013  
**DATE RECEIVED:** 2/21/2013  
**DATE ANALYZED:** 2/21/2013  
**DATE REPORTED:** 2/21/2013

**SampleType:** BULK

| Client<br>Sample<br>No. | SLI<br>Sample/<br>Layer ID                    | Sample<br>Identification/<br>Layer Name | PLM Analysis Results |  |
|-------------------------|---|---|----------------------|--|
|                         |   |   | Asbestos Fibers      | Other Materials                                |
| 1                       | 31789258                                      | Upper Level Park Garage                 |                      |  |
| Layer 1:                | Wallboard/Jnt Cmpd<br>White, Powdery/Granular |   | None Detected        | 3% CELLULOSE FIBER<br>97% NON FIBROUS MATERIAL |
| 2                       | 31789259                                      | 1FL Suite 100 Low Level                 |                      |  |
| Layer 1:                | Cove Base<br>Black, Rubbery                   |   | None Detected        | 100% NON FIBROUS MATERIAL                      |
| Layer 2:                | Mastic<br>Tan, Soft                           |   | None Detected        | 100% NON FIBROUS MATERIAL                      |
| 3                       | 31789260                                      | 1FL Suite 100 Low Level                 |                      |  |
| Layer 1:                | Wallboard/Jnt Cmpd<br>White, Powdery/Granular |   | None Detected        | 3% CELLULOSE FIBER<br>97% NON FIBROUS MATERIAL |
| 4                       | 31789261                                      | 1FL Suite 100 Low Level                 |                      |  |
| Layer 1:                | Granular Material<br>White, Granular          |   | None Detected        | 100% NON FIBROUS MATERIAL                      |

### Total Number of Pages in Report: 6

Results relate only to samples as received by the laboratory.

Visit [www.slabin.com](http://www.slabin.com) for current certifications.

*Samples analyzed by the EPA Test Method are subject to the limitations of light microscopy including matrix interference. Gravimetric reduction and correlative analyses are recommended for all non-friable, organically bound materials. This method has a reporting limit of 1% or greater. Visual estimation contains an inherent range of uncertainty. This report must not be reproduced except in full with the approval of the lab, and must not be used to claim NVLAP or other gov't agency endorsement. The EPA states that any asbestos found in vermiculite is a concern and the sample should be treated as asbestos containing material.*

| Client<br>Sample<br>No. | SLI<br>Sample/<br>Layer ID                   | Sample<br>Identification/<br>Layer Name | PLM Analysis Results |   |
|-------------------------|--|---|----------------------|---|
|                         |  |   | Asbestos Fibers      | Other Materials   |
| 5                       | 31789262                                     | 1FL Suite 100 Up Server Rm              |                      |   |
| Layer 1:                | Vinyl Floor Tile<br>Black, Organically Bound |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                          |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 6                       | 31789263                                     | 1FL Suite 100 Up File Rm                |                      |   |
| Layer 1:                | Vinyl Floor Tile<br>Gray, Organically Bound  |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                          |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 7                       | 31789264                                     | 1FL Suite 100 Low Level                 |                      |   |
| Layer 1:                | Ceiling Panel<br>Tan, Fibrous                |   | None Detected        | 65% CELLULOSE FIBER<br>15% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 8                       | 31789265                                     | 1FL Suite 100 Up Level                  |                      |   |
| Layer 1:                | Fireproofing<br>Beige, Fibrous               |   | None Detected        | 40% CELLULOSE FIBER<br>40% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 9                       | 31789266                                     | 1FL Suite 100 Up Level                  |                      |   |
| Layer 1:                | Fireproofing<br>Beige, Fibrous               |   | None Detected        | 40% CELLULOSE FIBER<br>40% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 10                      | 31789267                                     | 1FL Suite 100 Up Level                  |                      |   |
| Layer 1:                | Fireproofing<br>Beige, Fibrous               |   | None Detected        | 40% CELLULOSE FIBER<br>40% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 11                      | 31789268                                     | 1FL Suite 100 Up By Restrm              |                      |   |
| Layer 1:                | Carpet Mastic<br>Tan, Soft                   |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 12                      | 31789269                                     | 1FL Suite 100 Up Janitor's              |                      |   |
| Layer 1:                | Cove Base<br>Brown, Rubbery                  |   | None Detected        | 100% NON FIBROUS MATERIAL   |

**Total Number of Pages in Report: 6**

Results relate only to samples as received by the laboratory.

Visit [www.slabin.com](http://www.slabin.com) for current certifications.

*Samples analyzed by the EPA Test Method are subject to the limitations of light microscopy including matrix interference. Gravimetric reduction and correlative analyses are recommended for all non-friable, organically bound materials. This method has a reporting limit of 1% or greater. Visual estimation contains an inherent range of uncertainty. This report must not be reproduced except in full with the approval of the lab, and must not be used to claim NVLAP or other gov't agency endorsement. The EPA states that any asbestos found in vermiculite is a concern and the sample should be treated as asbestos containing material.*

| Client<br>Sample<br>No. | SLI<br>Sample/<br>Layer ID                    | Sample<br>Identification/<br>Layer Name | PLM Analysis Results |   |
|-------------------------|---|---|----------------------|---|
|                         |   |   | Asbestos Fibers      | Other Materials   |
| Layer 2:                | Mastic<br>Tan, Soft                           |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 13                      | 31789270                                      | 1FL Suite 100 Up Vending                |                      |   |
| Layer 1:                | Vinyl Floor Tile<br>White, Organically Bound  |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                           |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 14                      | 31789271                                      | 1FL Suite 100 Up Vending                |                      |   |
| Layer 1:                | Cove Base<br>Gray, Rubbery                    |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                           |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 15                      | 31789272                                      | 1FL Suite 100 Up Break Rm               |                      |   |
| Layer 1:                | Granular Material<br>Black, Granular          |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 16                      | 31789273                                      | 1FL Suite 100 Up S Stairs               |                      |   |
| Layer 1:                | Ceiling Panel<br>White, Fibrous               |   | None Detected        | 65% CELLULOSE FIBER<br>15% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 17                      | 31789274                                      | 2FL S Stairs                            |                      |   |
| Layer 1:                | Wallboard/Jnt Cmpd<br>White, Powdery/Granular |   | None Detected        | 3% CELLULOSE FIBER<br>97% NON FIBROUS MATERIAL                            |
| 18                      | 31789275                                      | 2FL Suite 200 S Rm Ent.                 |                      |   |
| Layer 1:                | Wallboard/Jnt Cmpd<br>White, Powdery/Granular |   | None Detected        | 3% CELLULOSE FIBER<br>97% NON FIBROUS MATERIAL                            |
| 19                      | 31789276                                      | 2FL Suite 200 S Rm Ent.                 |                      |   |
| Layer 1:                | Cove Base<br>Light Gray, Rubbery              |   | None Detected        | 100% NON FIBROUS MATERIAL   |

**Total Number of Pages in Report: 6**

Results relate only to samples as received by the laboratory.

Visit [www.slabinc.com](http://www.slabinc.com) for current certifications.

*Samples analyzed by the EPA Test Method are subject to the limitations of light microscopy including matrix interference. Gravimetric reduction and correlative analyses are recommended for all non-friable, organically bound materials. This method has a reporting limit of 1% or greater. Visual estimation contains an inherent range of uncertainty. This report must not be reproduced except in full with the approval of the lab, and must not be used to claim NVLAP or other gov't agency endorsement. The EPA states that any asbestos found in vermiculite is a concern and the sample should be treated as asbestos containing material.*

| Client<br>Sample<br>No. | SLI<br>Sample/<br>Layer ID                   | Sample<br>Identification/<br>Layer Name | PLM Analysis Results |   |
|-------------------------|--|---|----------------------|---|
|                         |  |   | Asbestos Fibers      | Other Materials   |
| Layer 2:                | Mastic<br>Tan, Soft                          |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 20                      | 31789277                                     | 2FL Suite 200 Break Rm                  |                      |   |
| Layer 1:                | Vinyl Floor Tile<br>Black, Organically Bound |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                          |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 21                      | 31789278                                     | 2FL Suite 200 Break Rm                  |                      |   |
| Layer 1:                | Vinyl Floor Tile<br>White, Organically Bound |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                          |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 22                      | 31789279                                     | 2FL Suite 201                           |                      |   |
| Layer 1:                | Leveling Compound<br>White, Granular         |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 23                      | 31789280                                     | 2FL Suite 201                           |                      |   |
| Layer 1:                | Ceiling Panel<br>Beige, Fibrous              |   | None Detected        | 85% CELLULOSE FIBER<br>15% NON FIBROUS MATERIAL                           |
| 24                      | 31789281                                     | 2FL Suite 201                           |                      |   |
| Layer 1:                | Fireproofing<br>Beige, Fibrous               |   | None Detected        | 40% CELLULOSE FIBER<br>40% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 25                      | 31789282                                     | 2FL Suite 201                           |                      |   |
| Layer 1:                | Fireproofing<br>Beige, Fibrous               |   | None Detected        | 40% CELLULOSE FIBER<br>40% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 26                      | 31789283                                     | 3FL Suite 300 NE Center Rm              |                      |   |
| Layer 1:                | Vinyl Floor Tile<br>Tan, Organically Bound   |   | None Detected        | 100% NON FIBROUS MATERIAL   |

**Total Number of Pages in Report: 6**

Results relate only to samples as received by the laboratory.

Visit [www.slabinc.com](http://www.slabinc.com) for current certifications.

*Samples analyzed by the EPA Test Method are subject to the limitations of light microscopy including matrix interference. Gravimetric reduction and correlative analyses are recommended for all non-friable, organically bound materials. This method has a reporting limit of 1% or greater. Visual estimation contains an inherent range of uncertainty. This report must not be reproduced except in full with the approval of the lab, and must not be used to claim NVLAP or other gov't agency endorsement. The EPA states that any asbestos found in vermiculite is a concern and the sample should be treated as asbestos containing material.*

| Client<br>Sample<br>No. | SLI<br>Sample/<br>Layer ID                    | Sample<br>Identification/<br>Layer Name | PLM Analysis Results |   |
|-------------------------|---|---|----------------------|---|
|                         |   |   | Asbestos Fibers      | Other Materials   |
| Layer 2:                | Mastic<br>Tan, Soft                           |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 27                      | 31789284                                      | 3FL Suite 300 NE Center Rm              |                      |   |
| Layer 1:                | Cove Base<br>Tan, Rubbery                     |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                           |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 28                      | 31789285                                      | 3FL Suite 300 S Conf. Rm                |                      |   |
| Layer 1:                | Fireproofing<br>Beige, Fibrous                |   | None Detected        | 40% CELLULOSE FIBER<br>40% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 29                      | 31789286                                      | 3FL Suite 301 S Conf. Rm                |                      |   |
| Layer 1:                | Fireproofing<br>Beige, Fibrous                |   | None Detected        | 40% CELLULOSE FIBER<br>40% MINERAL/GLASS WOOL<br>20% NON FIBROUS MATERIAL |
| 30                      | 31789287                                      | 3FL Suite 303 Break Rm                  |                      |   |
| Layer 1:                | Wallboard/Jnt Cmpd<br>White, Powdery/Granular |   | None Detected        | 3% CELLULOSE FIBER<br>97% NON FIBROUS MATERIAL                            |
| 31                      | 31789288                                      | 3FL Suite 303 Break Rm                  |                      |   |
| Layer 1:                | Granular Material<br>White, Granular          |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 32                      | 31789289                                      | 3FL Suite 304 Server Rm                 |                      |   |
| Layer 1:                | Vinyl Floor Tile<br>Gray, Organically Bound   |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| Layer 2:                | Mastic<br>Tan, Soft                           |   | None Detected        | 100% NON FIBROUS MATERIAL   |
| 33                      | 31789290                                      | 3FL Suite 305 File Rm                   |                      |   |
| Layer 1:                | Cove Base<br>White, Rubbery                   |   | None Detected        | 100% NON FIBROUS MATERIAL   |

**Total Number of Pages in Report: 6**

Results relate only to samples as received by the laboratory.

Visit [www.slabin.com](http://www.slabin.com) for current certifications.

*Samples analyzed by the EPA Test Method are subject to the limitations of light microscopy including matrix interference. Gravimetric reduction and correlative analyses are recommended for all non-friable, organically bound materials. This method has a reporting limit of 1% or greater. Visual estimation contains an inherent range of uncertainty. This report must not be reproduced except in full with the approval of the lab, and must not be used to claim NVLAP or other gov't agency endorsement. The EPA states that any asbestos found in vermiculite is a concern and the sample should be treated as asbestos containing material.*

| Client<br>Sample<br>No. | SLI<br>Sample/<br>Layer ID | Sample<br>Identification/<br>Layer Name | PLM Analysis Results |                           |
|-------------------------|----------------------------|---|----------------------|---------------------------|
|                         |                            |   | Asbestos Fibers      | Other Materials           |
| Layer 2:                | Mastic<br>Tan, Soft        |   | None Detected        | 100% NON FIBROUS MATERIAL |
| 34                      | 31789291                   | Exterior S. Side                        |                      |                           |
| Layer 1:                | Stucco<br>Gray, Granular   |   | None Detected        | 100% NON FIBROUS MATERIAL |



Analyst: **MOHAMMED B. HASHIM**




Reviewed By: **Hind Eldanaf, Microscopy Supervisor**

**Total Number of Pages in Report: 6**

Results relate only to samples as received by the laboratory.

Visit [www.slabin.com](http://www.slabin.com) for current certifications.

*Samples analyzed by the EPA Test Method are subject to the limitations of light microscopy including matrix interference. Gravimetric reduction and correlative analyses are recommended for all non-friable, organically bound materials. This method has a reporting limit of 1% or greater. Visual estimation contains an inherent range of uncertainty. This report must not be reproduced except in full with the approval of the lab, and must not be used to claim NVLAP or other gov't agency endorsement. The EPA states that any asbestos found in vermiculite is a concern and the sample should be treated as asbestos containing material.*



# APEX ENVIRONMENTAL CONSULTANTS, INC.

14955 W. 101<sup>st</sup> Terrace • Lenexa, Kansas 66215 • Tel: (913) 338-2739 • Fax: (913) 338-2741

## ASBESTOS BULK SAMPLE CUSTODY FORM

**CLIENT:** ServPro of Olathe/Lenexa  
15365 S. Keeler  
Olathe, Kansas 66062

**JOB LOCATION:** 4739 Bellvue  
Kansas City, Missouri

**PROJECT No:** 130066A

**CONTACT/PHONE:** Don Sinnett cell 913-908-9262 office 913-338-2739 Lab ID 1899

| DATE    | SAMPLE | LOCATION  | MATERIAL                              | COMMENTS                 |
|---------|--------|---|---------------------------------------|--------------------------|
| 2-20-13 | 1      | Upper Level, Parking Garage                                   | Gypsum Wallboard w/<br>Joint Compound | Analyze as composite     |
| 2-20-13 | 2      | 1 <sup>st</sup> Floor, Suite 100, Lower Level                 | Vinyl Cove Base and<br>Mastic         | 4" Black                 |
| 2-20-13 | 3      | 1 <sup>st</sup> Floor, Suite 100, Lower Level                 | Gypsum Wallboard w/<br>Joint Compound | Analyze as composite     |
| 2-20-13 | 4      | 1 <sup>st</sup> Floor, Suite 100, Lower Level                 | Sink Lining                           | White                    |
| 2-20-13 | 5      | 1 <sup>st</sup> Floor, Suite 100, Upper<br>Level, Server Room | Vinyl Floor Tile and<br>Mastic        | 12" Gray                 |
| 2-20-13 | 6      | 1 <sup>st</sup> Floor, Suite 100, Upper<br>Level, File Room   | Vinyl Floor Tile and<br>Mastic        | 12" Black                |
| 2-20-13 | 7      | 1 <sup>st</sup> Floor, Suite 100, Lower Level                 | Ceiling Panel                         | 2' x 2' Rough<br>Texture |
| 2-20-13 | 8      | 1 <sup>st</sup> Floor, Suite 100, Upper Level                 | Fireproofing                          |                          |
| 2-20-13 | 9      | 1 <sup>st</sup> Floor, Suite 100, Upper Level                 | Fireproofing                          |                          |
| 2-20-13 | 10     | 1 <sup>st</sup> Floor, Suite 100, Upper Level                 | Fireproofing                          |                          |

**ADDITIONAL REMARKS:**

- Please put project number on report.
- Requested Analysis – PLM-DS
- E-mail results to dsinnett@4apex.com

**SAMPLED BY:**

Don Sinnett

PRINTED NAME

**TURNAROUND TIME:** 2 Hour Turnaround

Don Sinnett

SIGNATURE

**CUSTODY**

Relinquished By: Don Sinnett

Date: 2-20-13

Received By: [Signature]

Date: 2-21-13

PLEASE RETURN ORIGINAL TO APEX ENVIRONMENTAL CONSULTANTS, INC.

F 7810 R



# APEX ENVIRONMENTAL CONSULTANTS, INC.

14955 W. 101<sup>st</sup> Terrace • Lenexa, Kansas 66215 • Tel: (913) 338-2739 • Fax: (913) 338-2741

## ASBESTOS BULK SAMPLE CUSTODY FORM

**CLIENT:** ServPro of Olathe/Lenexa  
15365 S. Keeler  
Olathe, Kansas 66062

**JOB LOCATION:** 4739 Bellvue  
Kansas City, Missouri

**PROJECT No:** 130066A

**CONTACT/PHONE:** Don Sinnett cell 913-908-9262 office 913-338-2739 Lab ID 1899

| DATE    | SAMPLE | LOCATION   | MATERIAL                           | COMMENTS                    |
|---------|--------|--|------------------------------------|-----------------------------|
| 2-20-13 | 11     | 1 <sup>st</sup> Floor, Suite 100, Upper Level, by Restrooms          | Mastic for Carpet                  |                             |
| 2-20-13 | 12     | 1 <sup>st</sup> Floor, Suite 100, Upper Level, Janitor's Closet      | Vinyl Cove Base and Mastic         | 4"Brown                     |
| 2-20-13 | 13     | 1 <sup>st</sup> Floor, Suite 100, Upper Level, Vending               | Vinyl Floor Tile and Mastic        | 12" White w/brown streaks   |
| 2-20-13 | 14     | 1 <sup>st</sup> Floor, Suite 100, Upper Level, Vending               | Vinyl Cove Base and Mastic         | 4"Gray                      |
| 2-20-13 | 15     | 1 <sup>st</sup> Floor, Suite 100, Upper Level, Break Room            | Sink Lining                        | Black                       |
| 2-20-13 | 16     | 1 <sup>st</sup> Floor, Suite 100, Upper Level, Entry to South Stairs | Ceiling Panel                      | 2' x 2' Semi-Smooth Texture |
| 2-20-13 | 17     | 2 <sup>nd</sup> Floor, South Stairs                                  | Gypsum Wallboard w/ Joint Compound | Analyze as composite        |
| 2-20-13 | 18     | 2 <sup>nd</sup> Floor, Suite 200, South Room by Entrance             | Gypsum Wallboard w/ Joint Compound | Analyze as composite        |
| 2-20-13 | 19     | 2 <sup>nd</sup> Floor, Suite 200, South Room by Entrance             | Vinyl Cove Base and Mastic         | 4"Light Gray                |
| 2-20-13 | 20     | 2 <sup>nd</sup> Floor, Suite 200, Break Room                         | Vinyl Floor Tile and Mastic        | 12" Black                   |

### ADDITIONAL REMARKS:

- Please put project number on report.
- Requested Analysis – PLM-DS
- E-mail results to dsinnett@4apex.com

SAMPLED BY:

Don Sinnett

PRINTED NAME

TURNAROUND TIME: 2 Hour Turnaround

*Don Sinnett*

SIGNATURE

### CUSTODY

Relinquished By: Don Sinnett

Date: 2-20-13

Received By: Fadi

Date: 2-21-13

PLEASE RETURN ORIGINAL TO APEX ENVIRONMENTAL CONSULTANTS, INC.

F+ 7810 R





# APEX ENVIRONMENTAL CONSULTANTS, INC.

14955 W. 101<sup>st</sup> Terrace • Lenexa, Kansas 66215 • Tel: (913) 338-2739 • Fax: (913) 338-2741

## ASBESTOS BULK SAMPLE CUSTODY FORM

**CLIENT:** ServPro of Olathe/Lenexa  
15365 S. Keeler  
Olathe, Kansas 66062

**JOB LOCATION:** 4739 Bellvue  
Kansas City, Missouri

**PROJECT No:** 130066A

**CONTACT/PHONE:** Don Sinnett cell 913-908-9262 office 913-338-2739 Lab ID 1899

| DATE    | SAMPLE | LOCATION  | MATERIAL                        | COMMENTS                  |
|---------|--------|---|---------------------------------|---------------------------|
| 2-20-13 | 21     | 2 <sup>nd</sup> Floor, Suite 200, Break Room            | Vinyl Floor Tile and Mastic     | 12" White                 |
| 2-20-13 | 22     | 2 <sup>nd</sup> Floor, Suite 201                        | Leveling Compound               |                           |
| 2-20-13 | 23     | 2 <sup>nd</sup> Floor, Suite 201                        | Ceiling Panel                   | 2' x 2' Divot and Pinhole |
| 2-20-13 | 24     | 2 <sup>nd</sup> Floor, Suite 201                        | Fireproofing                    |                           |
| 2-20-13 | 25     | 2 <sup>nd</sup> Floor, Suite 201                        | Fireproofing                    |                           |
| 2-20-13 | 26     | 3 <sup>rd</sup> Floor, Suite 300, Northeast Center Room | Vinyl Floor Tile and Mastic     | 12" Tan                   |
| 2-20-13 | 27     | 3 <sup>rd</sup> Floor, Suite 300, Northeast Center Room | Vinyl Cove Base and Mastic      | 4" Tan                    |
| 2-20-13 | 28     | 3 <sup>rd</sup> Floor, Suite 300, South Conference Room | Fireproofing                    |                           |
| 2-20-13 | 29     | 3 <sup>rd</sup> Floor, Suite 300, Center Room           | Fireproofing                    |                           |
| 2-20-13 | 30     | 3 <sup>rd</sup> Floor, Suite 301, South Conference Room | Gypsum Board and Joint Compound | Analyze as composite      |

**ADDITIONAL REMARKS:**

- Please put project number on report.
- Requested Analysis – PLM-DS
- E-mail results to dsinnett@4apex.com

**SAMPLED BY:**

Don Sinnett

PRINTED NAME

**TURNAROUND TIME:** 2 Hour Turnaround

*Don Sinnett*

SIGNATURE

**CUSTODY**

Relinquished By: Don Sinnett

Date: 2-20-13

Received By: *Fred*

Date: 2-21-13

PLEASE RETURN ORIGINAL TO APEX ENVIRONMENTAL CONSULTANTS, INC.

*G 7810 R*