

# **RV** Inspection Report

# Prepared for:

**RV** Location:



# Inspection Date / RV Model:

VIN Number:

Ranger RV, LLC

Scott Mansito Cibolo. TX 78108



# **Table of Contents**

Table of Contents       3         Life Safety Issue       5         Major Issue       6         Minor Issue       8         Notice / Comment       10         Intro Page       12         1 Vehicle Information       14         2 Hot Skin       16         3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
Major Issue       6         Minor Issue       8         Notice / Comment       10         Intro Page       12         1 Vehicle Information       14         2 Hot Skin       16         3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
Minor Issue       8         Notice / Comment       10         Intro Page       12         1 Vehicle Information       14         2 Hot Skin       16         3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
Notice / Comment       10         Intro Page       12         1 Vehicle Information       14         2 Hot Skin       16         3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
Intro Page       12         1 Vehicle Information       14         2 Hot Skin       16         3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
1 Vehicle Information       14         2 Hot Skin       16         3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
2 Hot Skin       16         3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
3 Roof Exterior       18         4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
4(A) Front Cap / Wall       28         4(B) Curbside Sidewall       31         4(C) Rear Cap / Wall       36         4(D) Streetside Sidewall       38
4(B) Curbside Sidewall31 4(C) Rear Cap / Wall36 4(D) Streetside Sidewall38
4(C) Rear Cap / Wall36 4(D) Streetside Sidewall
4(D) Streetside Sidewall38
5 Entrance Door(s) and Steps41
6 Awnings 43
7 Slideouts 44
8(A) Curbside - Front Wheel Assembly 46
8(B) Curbside - Rear Wheel Assembly 48
8(C) Streetside - Rear Wheel Assembly 50
8(D) Streetside - Front Wheel Assembly 52
8(E) Spare Tire Assembly54
9 Running Gear56
10 Hitch and Stabilizing System 63
11 12-Volt DC Chassis Lights 64
12 Electrical System 120-Volts AC and 12-Volts DC66
13 Water Systems73
14 Propane Container(s), Lines and Connections
15 Appliances: Kitchen 86
16 Appliances: Other 91

17(A) Front Air Conditioner	<u> 94</u>
17(B) Center Air Conditioner	96
18 Interior	98
19 Furniture	
20(A) Living Room Television	122
20(B) Bedroom Television	122
20(C) Radio / Stereo	122
20(D) Blu-Ray Player	122

# Life Safety Issue



Customer
Inspection Date / Year.Make.Model:
VIN Number:

The following items indicate that the condition is a LIFE SAFETY ISSUE. It is recommended that a qualified RV technician correct the identified issue, and before the unit is occupied.

## 15. Appliances: Kitchen

### 15.22 Cooktop - Condition

**Poor** 

The back left burner on the cooktop would not ignite. This is a Life Safety Issue. It is recommended that this be further evaluated by a qualified RV technician prior to occupying the RV.

Prepared Using HomeGauge <a href="http://www.HomeGauge.com">http://www.HomeGauge.com</a> : Licensed To Scott Mansito

# Major Issue



Customer
Inspection Date / Year.Make.Model:
VIN Number:

The following items indicate that the condition is a MAJOR ISSUE. It is recommended that a qualified RV technician correct the identified issue as needed.

## 3. Roof Exterior

#### 3.1 Front Cap, Joints and Seals - Condition

#### **Poor**

- (1) The front cap from side to side has multiple pin holes and cracks in the sealant. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.
- (2) Front cap has a dent in the center front of the RV. The sealant has discoloration in this area and has a softer feel when pressing down on it. This area has multiple pin holes in the sealant. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.

## 4(B). Curbside Sidewall

#### 4.2.B Windows - Condition

#### **Poor**

(1) All of the windows on the curbside sidewall have sealant on the top of the windows and going over the top edges. None of the windows have sealant going down the sides of the windows or on the bottom of the windows. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.

## 4(C) . Rear Cap / Wall

#### 4.2.C Windows - Condition

#### **Poor**

The rear window does not have sealant going down the sides of the window or on the bottom of the window. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.

## 4(D) . Streetside Sidewall

#### 4.2.D Windows - Condition

#### **Poor**

All of the windows on the streetside sidewall have sealant on the top of the windows and going over the top edges. None of the windows have sealant going down the sides of the windows or on the bottom of the windows. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.

## 9. Running Gear

### 9.16 Underbelly - Condition

#### Poor

- (1) The underbelly is broken on the curbside located on the front panel with exposed wood. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.
- (2) The underbelly has holes in it located on the streetside on the second panel. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.
- (4) The underbelly is broken on the streetside on the front panel with exposed wood. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.
- (5) The underbelly has a puncture in it located on the middle on the third panel. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.
- (6) The underbelly is detached in several spots along the rear of the RV. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.

## 13. Water Systems

### 13.1 City Water - System Holds Pressure

#### **Not Inspected**

The city water connection could not be tested because the city water that was available was from a manual pump. The manual pump could not supply a constant flow of water to test the system. It is recommended that this be further evaluated by a qualified RV technician.

Prepared Using HomeGauge <a href="http://www.HomeGauge.com">http://www.HomeGauge.com</a> : Licensed To Scott Mansito

# Minor Issue



Customer
Inspection Date / Year.Make.Model:
VIN Number:

The following items indicate that the condition is a MINOR ISSUE. It is recommended that a qualified RV technician correct the identified issue as needed.

## 3. Roof Exterior

#### 3.0 Roof - Condition

Fair

(3) There is an unidentifiable object sticking up under the roof membrane located on the curbside of the front AC unit. It is recommended that this be further evaluated by a qualified RV technician.

## 4(D). Streetside Sidewall

#### 4.0.D Sidewall - Condition

**Fair** 

(2) The gutter downspout is broken on the streetside gutter. It is recommended that this be further evaluated by a qualified RV technician.

## 9. Running Gear

#### 9.16 Underbelly - Condition

Poor

(3) There is a loose bolt on the mounting bracket for the front stabilizer on the curbside. It is recommended that this be further evaluated by a qualified RV technician.

## 12. Electrical System 120-Volts AC and 12-Volts DC

#### 12.24 Electrical Panel Box - All White, Black and Ground Wires Kept Separate

No

There are double wires connected on the bus bar. It is recommended that this be further evaluated by a qualified RV technician.

## 18. Interior

## 18.4 Ceiling - Discoloration or Stains

Fair

The ceiling has a tacky residue along almost every panel. It is recommended that this be further evaluated by a qualified RV technician.

### 18.5 Ceiling - Trim Work Missing or Damaged

Fair

(1) The trim above the cabinets above the bed is separated from the wall with exposed staples showing. It is recommended that this be further evaluated by a qualified RV technician.

Prepared Using HomeGauge <a href="http://www.HomeGauge.com">http://www.HomeGauge.com</a> : Licensed To Scott Mansito

# Notice / Comment



Customer
Inspection Date / Year Make Model:
VIN Number:

The following items indicate that the condition is a NOTEWORTHY COMMENT.

## 6. Awnings

#### 6.2 Fabric - Condition

#### **Acceptable**

The awning fabric and total operation could not be evaluated because of the location of the awning and the building structure next to it. It is recommended that this be further evaluated by a qualified RV technician.

## 12. Electrical System 120-Volts AC and 12-Volts DC

#### 12.3 Polarity / Voltage Test - Receptacle Behind Refrigerator

#### **Not Inspected**

The receptacle behind the refrigerator was not available to test with out removing the refrigerator.

### 18. Interior

#### 18.28 Walls - Trim Work - Condition

#### Fair

There are multiple locations through the RV that have scuff marks, separation or not aligned, pealing or damage trim. It is recommended that this be further evaluated by a qualified RV technician.

#### 18.37 Cabinets / Pantries - Door Damage / Scratches

#### Fair

Some of the cabinets / pantry trim does not align correctly. It is recommended that this be further evaluated by a qualified RV technician.

#### 18.41 Windows - Condition

#### Acceptable

The bedroom curbside window inner seal / trim is separating from the seal. It is recommended that this be further evaluated by a qualified RV technician.

Prepared Using HomeGauge <a href="http://www.HomeGauge.com">http://www.HomeGauge.com</a> : Licensed To Scott Mansito

# Inspection Date / Year.Make.Model: RV Location: Customer:

This time sensitive document was prepared for the client listed on the Cover Page of this report. Any reproduction, use, or resale of this document by individuals other than who is listed on the report cover page, or their assigns, is not supported by the inspector and company.

## **Comment Key or Definitions**

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this RV home. Any recommendations by the inspector to repair suggests further action by a qualified RV technician. All costs associated with repair or replacement of items and components identified in this report should be considered before purchasing this RV home.

**Acceptable (A)** = A visually observed item, component or unit and if no other comments were made then it appeared to be performing its intended function with little or no deterioration visible.

**Fair (F)**= The item or its components is not in need of immediate repair as it is performing its intended function but deterioration is visible. Some may elect to repair or replace this item now while others may wait.

**Poor (P)** = The item, component or unit is not functioning as intended and replacement is recommended, or needs further action by a qualified RV technician.

**Not Inspected (NI)**= The item, unit or component was not inspected, and no representations were made as to whether or not it was functioning as intended and a statement for the reason for not inspecting may be made.

**Not Present (NP)** = This item, component or unit is not in this RV.

#### **NRVIA Standards of Practice**

#### **Purpose, Scope and General Statements**

- 1 The purpose of the Standards of Practice is to establish a uniform standard for the companies RV Inspector to inspect and report in an objective manner the conditions of a Recreational Vehicle and its components.
- 2 The Standards describe the components, and systems included in an RV Inspection.
- 3 The Standards apply to motorized and towable types of RVs as defined by the RV Industry.
- 4 The Standards apply to a visual inspection of those areas, components and systems that are readily accessible to determine at the time of inspection that they are performing their intended function without regard to life expectancy.
- 5 The purpose of the RV inspection is to identify visible and operational defects as permitted by the current conditions that in the judgment of the RV Inspector will adversely affect the function or integrity of the items, components and systems of the Recreational Vehicle.
- 6 RV Inspections performed under the Standards of Practice are basically visual and rely upon the judgment, education and experience of the RV Inspector and are not intended to be technically exhaustive.
- 7 RV inspections shall be performed on a calendar day which will allow compliance with the provisions of the NRVIA Standards of Practice.

- 8 RV Inspections performed under the Standards shall not be construed as being a compliance inspection of any code, governmental regulation or manufacturer's installation instructions or procedures. In the event a law, statute or ordinance prohibits a procedure recommended in the Standards, the RV Inspector is relieved of the obligation to adhere to the prohibited part of the Standards.
- 9 RV Inspections performed under the Standards are not an expressed, implied warranty or guarantee of adequacy, performance or useful life of any RV, any of its components or systems.
- 10 Only those items specifically listed on the RV Inspection Report will be included in the RV Inspectors evaluation.
- 11 The RV Inspector shall report any system or component included in the Standards of Practice which were present at the time of the RV Inspection but were NOT inspected and provide the reason they were not inspected.

#### **General Limitations and Exclusions**

- 1 RV Inspections performed under the companies Standards of Practice exclude any items concealed or not readily accessible to the RV Inspector. The RV Inspector is not required to move furniture, personal or stored items. Lifting floor covering, accessing interior walls and ceilings in which could damage or destroy the components or systems being evaluated is not part of the RV Inspection.
- 2 The determination of the presence of damage caused by insects or water is only to be evaluated by observation with a statement being rendered by RV Inspector that is to make the client aware of the issue.
- 3 Excluded from the Standards of Practice is the determination of indoor air quality of the RV and it's consequence of physical damage, toxicity, odors, waste products and noxiousness.
- 4 The RV Inspection and report are based upon the visual observation of the existing conditions of the RV at the time of the RV Inspection. The report is not intended to be or construed as a guarantee, warranty or any form of insurance. The RV Inspector will not be responsible for any repairs or replacement with regard to the RV or its contents.
- 5 The RV Inspector is not required to enter any premises that visibly show a threat to the safety of the RV Inspector or others nor inspect any area or component that poses a danger to the RV Inspector or others.
- 6 The NRVIA Certified RV Inspector inspected and reported on the RV items listed in this report and their condition during the RV Inspection. Any additional items of inspection were dependent upon any agreements that were made between the client and the RV Inspector.

Weather:Type of Inspection:Style of RV:ClearBuyer: Pre-Purchase RV InspectionTravel Trailer

RV Status: Client Is Present: Start Temperature:

Vacant: RV Dealership No 80 degrees

## 1. Vehicle Information

## **Styles & Materials**

Photo Included

VIN::

**Gross Vehicle Weight Rating** (GVWR):

From Data Plate

Specify in lbs or kg: 9810 lbs

**RV - Model Number:** 

**RV** Designation

Model Number :

**VIN Location:** 

Streetside Front

**RV - Manufacturer Name and** 

**Date of Manufacturer:** 

November Year:

**RVIA Seal Number:** 

Located by Entrance Door

**RV** - Brand:

Manufacturer's Brand Name


Brand Name:

#### Items

#### 1.0 VIN Number / VIN Data Plate Photo

Yes

VIN Data Plate



### 1.1 RVIA Seal Photo

Yes

**RVIA Data Plate** 



## 1.3 State Inspection Sticker Photo

Not Inspected

The RV has never been sold and does not have a State Inspection sticker.

## 1.5 State License Plate Photo

Not Inspected

The RV has never been sold and does not have a State Inspection sticker.

### 1.8 Manuals

Yes

## 2. Hot Skin

NOTE: Hot Skin is when stray or leak voltage from the 120 voltage AC system is somehow redirected from its normally safe path to some metal component(s) of your RV.

NOTE: Most hot skin issues may not be a direct short of power to ground but rather a high resistive short. In many cases, they may not trip the circuit breakers or blow fuses. However, the frame, chassis, copper tubing and metal trim pieces on the coach can conduct voltage.

NOTE: Any reading below 5 volts is considered safe. Conversely, any reading above 5 volts can be dangerous.

#### **Items**

2.0 Hot Skin Test - Frame and Running Gear Voltage

Acceptable

Hot Skin Test Photo



Hot Skin Test Photo

- **2.1 Hot Skin Test Exterior Wall Surface Voltage**Acceptable
- **2.2 Hot Skin Test Door Handles and Frames Voltage**Acceptable
- **2.3 Hot Skin Test Window Frames and Trim Voltage**Acceptable

## 3. Roof Exterior

NOTE: Lap sealant should appear soft, pliable and rubbery. If the lap sealant around roof edges, skylights, vents and appliances looks cracked, brittle, loose or turned up at the edges, it is very possible that this could allow water intrusion which can become a major issue.

NOTE: It is recommended that the roof and seams be checked, at a minimum, every 6 months and repaired whenever necessary to prevent water intrusion.

## **Styles & Materials**

Roof Type: Areas of Possible Water Intrusion: PVC (Rubber) Yes Roof Ladder Type: Not Present

**Number of Solar Panels:** 

One


Quantity: : 1

#### **Items**

#### 3.0 Roof - Condition

Fair

(1) Front to Back




Front to Back

(2) Back to Front



Back to Front

(3) There is an unidentifiable object sticking up under the roof membrane located on the curbside of the front AC unit. It is recommended that this be further evaluated by a qualified RV technician.



Object next to Front AC




Object Under Membrane


## 3.1 Front Cap, Joints and Seals - Condition

Poor


(1) The front cap from side to side has multiple pin holes and cracks in the sealant. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Front Cap Sealant



Front Cap Sealant



Front Cap Sealant

(2) Front cap has a dent in the center front of the RV. The sealant has discoloration in this area and has a softer feel when pressing down on it. This area has multiple pin holes in the sealant. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Dent in Front Cap

3.2 Trim Rail (Curbside) - Condition Acceptable

3.3 Rear Cap, Joints and Seals - Condition Acceptable

**3.4 Trim Rail (Streetside) - Condition** Acceptable

3.5 Vents - Powered (14 x 14) - Condition Acceptable

3.6 Vents - Manual Crank (14 x 14) - Condition Acceptable

- 3.7 Exterior Vent Covers Condition Acceptable
- **3.8 Plumbing Vent Covers Condition**Acceptable
- **3.9 Roof Refrigerator Vent Condition**Acceptable
- 3.10 Skylights Condition

Acceptable Skylight



**3.11 Front Air Conditioner - Shroud** Acceptable

Front AC Shroud



**3.12 Front Air Conditioner - Exterior Coils**Acceptable

# **3.13 Center Air Conditioner - Shroud**Acceptable

Center AC Shroud



- **3.14 Center Air Conditioner Exterior Coils**Acceptable
- **3.17 TV Antenna Exterior Roof Unit Condition**Acceptable
- **3.18 TV Antenna Cleaned and Maintained**Acceptable
- 3.23 Solar Panels Condition Acceptable

Solar Panel



# 4(A) . Front Cap / Wall

## **Styles & Materials**

**Exterior Wall -Construction Type:** .040 Smooth Aluminum

Type: : .040 Smooth Aluminum

**Windows:** None

**Exterior Wall - Surface** 

**Type:** Other

Cargo/Access Doors:

None

Any Damage or Discoloration or **Delamination?:** 

Yes

## **Items**

4.0.A Sidewall - Condition

Fair


(1) Front Cap



(2) Front cap has a dent on the top curve on the streetside. It is recommended that this be further evaluated by a qualified RV technician.



Front Cap Streetside



4.1.A Paint and/or Decals - Condition

Acceptable

## 4(B) . Curbside Sidewall

## **Styles & Materials**

Exterior Wall -Construction Type: Hung Fiberglass Panel

.040 Smooth Aluminum

**Windows:**Glass with Frame

Exterior Wall - Surface

Type:

Fiberglass with Decals

Cargo/Access Doors:
Doors with Keyed Twist Latch

Any Damage or Discoloration or Delamination?:

No

### **Items**

4.0.B Sidewall - Condition

Acceptable

Curbside Exterior



Curbside Exterior

## 4.1.B Paint and/or Decals - Condition

Acceptable

The '29VIEW' decal is pealing on the top on the decal located next to the entry door.



4.2.B Windows - Condition

Poor

(1) All of the windows on the curbside sidewall have sealant on the top of the windows and going over the top edges. None of the windows have sealant going down the sides of the windows or on the bottom of the windows. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Curbside Window

(2) Large Window to the Rear of the Entry Door



**4.3.B Cargo/Access Doors - Condition**Acceptable

Curbside Front Cargo Door



Curbside Front Cargo Door

## 4.5.B Cargo Interior Compartment - Condition

Acceptable

## 4(C). Rear Cap / Wall

## **Styles & Materials**

**Exterior Wall -Construction Type:** Hung Fiberglass Panel .040 Smooth Aluminum

**Windows:** 

Glass with Frame

**Exterior Wall - Surface** 

Fiberglass with Decals

Cargo/Access Doors:

None

Any Damage or Discoloration or **Delamination?:** 

No

## Items

4.0.C Sidewall - Condition

Acceptable

Rear Cap



Rear Cap

# 4.1.C Paint and/or Decals - Condition

Acceptable

### 4.2.C Windows - Condition

Poor

The rear window does not have sealant going down the sides of the window or on the bottom of the window. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Rear Window

# 4(D) . Streetside Sidewall

#### **Styles & Materials**

Exterior Wall -Construction Type: Hung Fiberglass Panel

Hung Fiberglass Panel .040 Smooth Aluminum

Windows:
Glass with Frame

Exterior Wall - Surface Type:

Fiberglass with Decals

Cargo/Access Doors:
Doors with Keyed Twist Latch

Any Damage or Discoloration or Delamination?:

Nο

#### Items

#### 4.0.D Sidewall - Condition


Fair

# (1) Streetside Sidewall



Streetside Sidewall

(2) The gutter downspout is broken on the streetside gutter. It is recommended that this be further evaluated by a qualified RV technician.




**Gutter Downspout** 

# **4.1.D Paint and/or Decals - Condition**Acceptable

# **4.2.D Windows - Condition**

Poor

All of the windows on the streetside sidewall have sealant on the top of the windows and going over the top edges. None of the windows have sealant going down the sides of the windows or on the bottom of the windows. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Streetside Window

### 4.3.D Cargo/Access Doors - Condition

Acceptable

#### 4.5.D Cargo Interior Compartment - Condition

Acceptable

# 5. Entrance Door(s) and Steps

# Styles & Materials

**Entrance Door - Type:** 

**Fiberglass** 

**Grab Bar - Type:** 

D-Ring Handle

**Step System - Type:**Manual

**Number of Steps:** 

Three

#### **Items**

#### 5.0 Door - Condition

Acceptable

**Entry Door** 





Entry Door Steps

5.1 Door - Operation

Acceptable

5.2 Screen Door - Condition

Acceptable

5.3 Screen Door - Operation

5.4 Keyed Door Lock - Operation

Acceptable

5.5 Keyed Door Lock - Deadbolt Operation

Acceptable

5.7 Steps - Condition

Acceptable

5.8 Steps - Operation

Acceptable

5.9 Grab Bar - Condition

Acceptable

5.10 Grab Bar - Operation

Acceptable

# 6. Awnings

### **Styles & Materials**

**Awning - Brand:** 

Dometic / A&E Brand: : Dometic

**Awning - Length:** 

22 Feet

Length in Feet: : 22

Awning - Type: Electric Awning - Material:

Vinyl

#### **Items**

6.0 Awning - Operation

Acceptable

6.1 Frame and Latching Mechanism - Operation

Acceptable

6.2 Fabric - Condition

The awning fabric and total operation could not be evaluated because of the location of the awning and the building structure next to it. It is recommended that this be further evaluated by a qualified RV technician.



**Awning Location** 

### 6.3 Awning - Lights

Acceptable

# 7. Slideouts

# **Styles & Materials**

Slideout Roof Type:

TPO (Rubber)

### **Slideout Drive System:**

Electric Motor / Gear and Rack System

### Items

# 7.0 Slideout - Operation

Acceptable

Slideout



Slideout

7.1 Slideout - Alignment

Acceptable

7.2 Slideout - Roof

Acceptable

7.3 Slideout - Sidewall

Acceptable

7.4 Slideout - T-Molding Trim

7.5 Seals, Sweeps and Gaskets

Acceptable

7.6 Slideout - Override System

Acceptable

7.7 Slide Rail - Gear Rack System

Acceptable

7.8 Wiring Harness under Slideout

Acceptable

7.9 12-Volt DC Control and Switches

Acceptable

# 8(A) . Curbside - Front Wheel Assembly

NOTE: The National Transportation Safety Board (NTSB) and some tire manufacturers are recommending that all tires older than six years should be replaced, regardless of their condition.

#### Styles & Materials

**Tire Brand:** 

Tamarack

Brand: Tamarack

**Load Capacity:** 

Single Tire Rating

lbs or kg: 1375

Tire - RV Manufacturer's Recommended

**Inflation Pressure:** 

80 PSI

Tire Size:

ST225/75R15

**Load Range:** 

DOT Date Code (WWYY): 3523

**Tire - Maximum Cold** 

Visually Verified

**DOT Date:** 

**Inflation Pressure:** 

80 PSI

**Tire - Current Air Pressure:** 

Tire Gauge Reading

PSI: 76

#### Items

8.0.A Tire - Age

Curbside Front Tire



Curbside Front Tire

8.1.A Tire/Rim - Condition Acceptable

**8.2.A Tire Tread - Condition**Acceptable

8.3.A Valve Extensions - Condition Acceptable

# 8(B). Curbside - Rear Wheel Assembly

# **Styles & Materials**

Tire Brand:

Tamarack

Brand : Tamarake

**Load Capacity:** 

Single Tire Rating lbs or kg: 1375

Tire - RV Manufacturer's Recommended Inflation Pressure:

80 PSI

**Tire Size:** ST225/75R15

**DOT Date:**Visually Verified

DOT Date Code (WWYY): 2723

Load Range:

Ε

**Tire - Maximum Cold Inflation Pressure:** 

80 PSI

Tire - Current Air Pressure:

Tire Gauge Reading

PSI: 76

#### **Items**

8.0.B Tire - Age

Curbside Rear Tire



Curbside Rear Tire

8.1.B Tire/Rim - Condition Acceptable

**8.2.B Tire Tread - Condition**Acceptable

8.3.B Valve Extensions - Condition Acceptable

# 8(C) . Streetside - Rear Wheel Assembly

# **Styles & Materials**

**Tire Brand:** 

Tamarack

Brand : Tamarack

**Load Capacity:** 

Single Tire Rating lbs or kg: 1375 lbs

Tire - RV Manufacturer's Recommended Inflation Pressure:

80 PSI

**Tire Size:** ST225/75R15

**DOT Date:**Visually Verified

DOT Date Code (WWYY): 3523

**Load Range:** 

Е

**Tire - Maximum Cold Inflation Pressure:** 

80 PSI

Tire - Current Air Pressure:

Tire Gauge Reading

PSI: 76

#### **Items**

8.0.C Tire - Age

Streetside Rear Tire



Streetside Rear Tire

8.1.C Tire/Rim - Condition Acceptable

8.2.C Tire Tread - Condition Acceptable

8.3.C Valve Extensions - Condition Acceptable

# 8(D) . Streetside - Front Wheel Assembly

# **Styles & Materials**

**Tire Brand:** 

Tamarack Brand : Tamarack

**Load Capacity:** 

Single Tire Rating lbs or kg: 1375 lbs

Tire - RV Manufacturer's Recommended Inflation Pressure:

80 PSI

**Tire Size:** ST225/75R15

**DOT Date:**Visually Verified

DOT Date Code (WWYY): 2723

Load Range:

F

**Tire - Maximum Cold Inflation Pressure:** 

80 PSI

Tire - Current Air Pressure:

Tire Gauge Reading

PSI: 76

#### **Items**

8.0.D Tire - Age

Streetside Front Tire



Streetside Front Tire

8.1.D Tire/Rim - Condition Acceptable

**8.2.D Tire Tread - Condition**Acceptable

8.3.D Valve Extensions - Condition Acceptable

# 8(E) . Spare Tire Assembly

# **Styles & Materials**

**Tire Brand:** 

Tamarack

Brand: Tamarack

**Load Capacity:** Single Tire Rating

lbs or kg: 1375 lbs

**Tire - RV Manufacturer's Recommended Inflation Pressure:** 

80 PSI

Tire Size: ST225/75R15

**Load Range:** 

**DOT Date:** Visually Verified

DOT Date Code (WWYY): 3323

**Tire - Maximum Cold Inflation Pressure:** 

80 PSI

**Tire - Current Air Pressure:** 

Tire Gauge Reading

PSI: 76

#### **Items**

8.0.E Tire - Age

Spare Tire



Spare Tire

8.1.E Tire/Rim - Condition Acceptable

8.2.E Tire Tread - Condition
Acceptable

8.3.E Valve Extensions - Condition Acceptable

8.5.E Spare Tire Mounting Rack - Condition Acceptable

# 9. Running Gear

NOTE: Due to the lack of clearance under the RV and safety concerns, the inspector will conduct the following visual inspections from the outer perimeter of the RV.

#### **Styles & Materials**

Axle - Type:

Leaf Spring with Shackles

**Rear Axle Weight Rating:** 

lbs

Weight Rating: 4400

**Underbelly - Type:** 

Enclosed

**Pin Connector Type:** 

7 Pin

**Axle - Quantity:** 

**Brake Type:** 

Two

ity: Front Axle Weight Rating:

IDS

Weight Rating: 4400

**Suspension Bolts - Type:** 

Without Zerk Fittings

Hitch Receiver - Brand: Hitch

Unknown

Electric

Hitch - Weight Rating:

Unknown

#### **Items**

#### 9.0 Frame - Condition

#### Acceptable

Front to Rear Rear to Front



Front to Rear



Rear to Front

9.1 Frame - Visible Signs of Rust

Acceptable

**9.2 Frame - Visible Signs of Bent or Damaged Components**Acceptable

9.3 Frame - Visible Signs of Oil Stains Acceptable

9.4 Running Gear (Axles, Springs, Rims, other Components) - Condition Acceptable

**9.5 Running Gear - Scraping or Drag Damage**Acceptable

9.6 Axle - Visible Signs of Rust Acceptable

**9.7 Axle - Visible Signs of Bent or Damaged Components**Acceptable

9.8 Axle - Visible Signs of Oil Stains Acceptable

9.9 U-Bolts and Nuts - Condition Acceptable

9.10 Leaf Springs - Condition Acceptable

9.11 Hangers - Condition Acceptable

9.12 Shackles - Condition

Acceptable

9.13 Spring Equalizers - Condition

### 9.14 Suspension Bolts - Condition

Acceptable

### 9.16 Underbelly - Condition


Poor

(1) The underbelly is broken on the curbside located on the front panel with exposed wood. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



**Underbelly Curbside Front** 

(2) The underbelly has holes in it located on the streetside on the second panel. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.




Holes in Underbelly

(3) There is a loose bolt on the mounting bracket for the front stabilizer on the curbside. It is recommended that this be further evaluated by a qualified RV technician.



Loose Nut

(4) The underbelly is broken on the streetside on the front panel with exposed wood. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Broken Underbelly Panel

(5) The underbelly has a puncture in it located on the middle on the third panel. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



Puncture in Underbelly

(6) The underbelly is detached in several spots along the rear of the RV. This could allow water intrusion. It is recommended that this be further evaluated by a qualified RV technician.



**Detached Underbelly** 



**Detached Underbelly** 



**Detached Underbelly** 

# 10. Hitch and Stabilizing System

# **Styles & Materials**

**Travel Trailer - Tongue Jack:** 

Electric

Travel Trailer - Stabilizer:
Electric

Travel Trailer - Weight Distribution System:
Not Present

Travel Trailer - Sway Control System:

Not Present

### Items

10.0 Travel Trailer - Tongue Jack - Condition

Overview



Tongue Jack

10.1 Travel Trailer - Coupler - Operation

Acceptable

10.2 Travel Trailer - Safety Chains - Condition

Acceptable

# 11. 12-Volt DC Chassis Lights

NOTE: The inspector has verified all the items in this section are functional.

The inspector tested the Break Away switch by pulling the break away cable and checked DC amperage at the Break Away switch. However, this does not indicate that the brakes engaged at all wheel assemblies. It is recommended that the trailer be attached to a tow vehicle and with the Break Away switch engaged, test resistance to movement. The best way to be sure this system is functioning is to have the wheels pulled and the brakes be evaluated by a qualified RV technician.

### **Styles & Materials**

Chassis Light Bulbs - Type: LED

**Trailer Brake Amp Draw:** 


Amps

DC Amps: 15

#### **Items**

11.0 Break Away Switch

Overview



**Break Away Switch** 

#### 11.1 Trailer Brakes

Acceptable

### 11.2 Front Clearance Lights

Acceptable

#### 11.3 Rear Clearance Lights

Acceptable

#### 11.4 Tail Lights

Acceptable

#### 11.5 Curbside - Marker Lights

Acceptable

#### 11.6 Streetside - Marker Lights

Acceptable

### 11.7 Left Turn - Brake Light - Marker Light

Acceptable

### 11.8 Right Turn - Brake Light - Marker Light

Acceptable

### 11.11 Utility Lights

Acceptable

#### 11.12 Hitch Lights

Acceptable

#### 11.13 Compartment Lights

Acceptable

#### 11.14 Porch Lights

### 12. Electrical System 120-Volts AC and 12-Volts DC

### **Styles & Materials**

**Power Source:** 

50 Amp Plug - 120/240 VAC

-12,000 Watts

**Inverter - Serial:** 

Not Visable

**Inverter - Brand:** 

Unkown

**Inverter - Voltage Output:** 

Measured Under 50% Load

Voltage Reading in AC Volts: 120

**Inverter - Model:** 

Not Visible

**Inverter - Frequency** 

**Output:** 

Measured Under 50% Load Frequency Reading in

Hertz: 60

12 Volt DC House Battery -

Location:

Trailer Tongue

12-Volt DC House Battery Disconnect **Switch Present:** 

Yes

#### **Items**

#### 12.0 Polarity / Voltage Test - All Exterior Receptacles

Acceptable

Overview



**Exterior Outlet** 

#### 12.2 Polarity / Voltage Test - Bedroom Receptacles

Overview



Bedroom Outlet

#### 12.3 Polarity / Voltage Test - Receptacle Behind Refrigerator

Not Inspected

The receptacle behind the refrigerator was not available to test with out removing the refrigerator.

- 12.4 Polarity / Voltage Test Kitchen Receptacles
  Acceptable
- **12.5 Polarity / Voltage Test Living Room Receptacles**Acceptable
- 12.6 Polarity / Voltage Test Dining Area Receptacles
  Acceptable
- 12.7 Polarity / Voltage Test Bath and Toilet Area Receptacles Acceptable


- 12.8 Polarity / Voltage Test Receptacles Behind all Electronics and Appliances Acceptable
- 12.9 Voltage Test 12-Volt Power Outlet Condition and Operation Acceptable
- 12.10 Voltage Test USB Ports Condition and Operation Acceptable
- 12.11 GFCI Trip Testing Bathroom Receptacles

Acceptable

Overview



Trip Test - Off



Trip Test - On

**12.12 GFCI Trip Testing - Kitchen Receptacles**Acceptable

12.14 GFCI Trip Testing - All Exterior Receptacles
Acceptable

12.15 GFCI Trip Testing - All Receptacles Behind Electronics and Appliances Acceptable

**12.16 GFCI Trip Testing - Bedroom Receptacle**Acceptable


12.17 GFCI Trip Testing - Circuit Breaker in Panel Box Acceptable

**12.18 Power Cord - Condition**Acceptable

#### 12.19 Electrical Panel Box - Condition

Acceptable


Overview



Panel Box

- 12.20 Electrical Panel Box Signs of Repair or Service Acceptable
- 12.21 Electrical Panel Box Circuit Breakers in Place Acceptable
- 12.22 Electrical Panel Box Wiring with Signs of Discoloration from Heat Acceptable

Overview




Wire Condidtion

12.23 Electrical Panel Box - Wiring Secure
Acceptable

12.24 Electrical Panel Box - All White, Black and Ground Wires Kept Separate No

There are double wires connected on the bus bar. It is recommended that this be further evaluated by a qualified RV technician.



**Double Wiring** 

12.25 12 Volt DC Fuse Panel - Condition

Acceptable

12.26 12 Volt DC Fuse Panel - Wires and Terminals Tight Acceptable

12.27 12 Volt DC Fuse Panel - Fuse Connections - Condition Acceptable

12.28 12 Volt DC Fuses - Condition Acceptable

12.29 Power Converter - AC On

Acceptable

12.30 Power Converter - AC Off

Acceptable

12.31 Power Converter - Operation - Minimum 0.5 Volt DC Drop
Acceptable

12.32 12 Volt DC Coach Battery(s) - Condition Acceptable

12.33 12 Volt DC Coach Battery Box(es) - Condition Acceptable

12.34 12 Volt DC Coach Battery Box(es) - Vented and Secured

Acceptable

12.35 12-Volt DC Coach Battery(s) - Matched for Size and Age

Acceptable

12.36 12-Volt DC Coach Battery(s) - Cables and Terminals - Condition

Acceptable

12.37 12-Volt DC Coach Battery(s) - Positive and Negative Cables Matched for Load

Acceptable

12.38 12-Volt DC Coach Battery(s) - Have They Been Maintained?

Acceptable

12.39 12-Volt DC Coach Battery(s) - Operational

Acceptable

12.40 12 Volt DC Coach Battery - Water Level

Acceptable

12.41 Cable and Satellite TV Hookup Visually Acceptable

Acceptable

12.42 Inverter - Condition

Acceptable

12.43 Inverter - Cables, Wiring and Fuses - Condition

Acceptable

### 13. Water Systems

NOTE: Due to the inability to determine the age and quality of the water in the fresh water tank, the tank should be drained and sanitized before refilling for use.

NOTE: Due to the types of materials and waste used in the tanks and depending on previous maintenance, fresh and waste monitor sensor probes may perform inaccurately between applications due to build up.

NOTE: The onboard in-line water filter will be visually inspected but the canister assembly will not be removed to verify the presence of a filter or to determine its condition at the time of the inspection.

### Styles & Materials

Black Water Tank #1 - Valve

Type:

Manual Pull T-Handle

**Gray Water Tank #2 - Valve** 

Fresh Water Tank Reading:

Type:

**Empty** 

Manual Pull T-Handle

**Black Tank Flush - Present and** Labeled:

**Gray Tank Flush - Present and** 

Labeled?:

Black Water Tank #1 Reading:

**Empty** 

Gray Water Tank #1 -Valve Type:

Manual Pull T-Handle

**Battery Monitor Reading:** 

Full

**Gray Water Tank #1** 

Reading: **Empty** 

Gray Water Tank #2 / Galley

Reading: **Empty** 

#### **Items**


13.0 City Water - Connection - Condition

Acceptable

13.1 City Water - System Holds Pressure

#### Not Inspected

The city water connection could not be tested because the city water that was available was from a manual pump. The manual pump could not supply a constant flow of water to test the system. It is recommended that this be further evaluated by a qualified RV technician.



City Water Connection

- 13.2 City Water Pressure Regulator Available
  No
- 13.3 City Water Food Grade Hose Available for Test
- 13.4 Outside Shower Operation and Condition Acceptable
- 13.6 On-Board Water System Tank, Water Pump and Fixtures for Tank Fill Condition Acceptable
- 13.7 On-Board Water System Tested Fresh Water Fill

Λ	_	_	_	n	ta	h	ما
м	L	L	ᆫ	ν	Lа	v	ı

13.8 On-Board Water System - Pump Creates and Holds Pressure Acceptable

13.9 In-Line Check Valve - Operation

Acceptable

13.10 Waste Water - Sewer / Hose Fittings

Acceptable

13.11 Black Water Tank #1 - Condition

Acceptable

13.12 Black Water Tank #1 - Valve Operation and Condition

Acceptable

13.13 Black Water Tank #1 - Tank or Valve or Line Leaks

Acceptable

13.14 Black Water Tank #1 - Drain Cap Condition

Acceptable

13.15 Black Water Tank #1 - Drain Cap in Place

Acceptable

13.16 Black Water Tank #1 - Drain Cap Holds Waste Water Back

Acceptable

13.23 Gray Water Tank #1 - Condition

Acceptable

13.24 Gray Water Tank #1 - Valve Operation and Condition

Acceptable

13.25 Gray Water Tank #1 - Tank or Valve or Line Leaks

Acceptable

13.26 Gray Water Tank #1 - Drain Cap Condition

Acceptable

13.27 Gray Water Tank #1 - Drain Cap in Place

Acceptable

13.28 Gray Water Tank #1 - Drain Cap Holds Waste Water Back

Acceptable

13.29 Gray Water Tank #2 - Condition

Acceptable

13.30 Gray Water Tank #2 - Valve Operation and Condition

Acceptable

13.31 Gray Water Tank #2 - Tank or Valve or Line Leaks

Acceptable

13.32 Gray Water Tank #2 - Drain Cap Condition

Acceptable

13.33 Gray Water Tank #2 - Drain Cap in Place

Acceptable

13.34 Gray Water Tank #2 - Drain Cap Holds Waste Water Back

Acceptable

13.46 Battery / Waste / Water Monitor Panel - Condition

## 14. Propane Container(s), Lines and Connections

NOTE: Liquid Propane gas detectors have an estimated service life of five years after which time it is recommended they be replaced.

NOTE: Carbon Monoxide detectors have an estimated service life of five years after which time it is recommended they be replaced.

NOTE: Smoke Detectors have an estimated service life of five to ten years after which time it is recommended they be replaced.

#### Styles & Materials

**DOT - Cylinder Location:** 

Tonque

**DOT Cylinder Location : Tongue** 

**DOT #1 - Cylinder Size:** 

20 LBS

DOT #2 - Date of Manufacture:

2023

Month: July

LP Leak / Drop Test - Did **Pressure Drop During Leak** 

Test: No

Combination LP / CO Detector -**Test Method:** 

Tested by Pushing Button

Smoke Detector - Brand / **Model / Serial Number:** 

Kidde

Model / Serial # : Kidde / 0940-71112-00

Smoke Detector - Test Result:

Pass

Fire Extinguisher - Size:

Travel Trailer or 5th Wheel without

Generator 1A-10B:C Size: : 1A-10B:C

**Fire Extinguisher - Mounted** within 24 Inches of Entrance

Door: Yes

**DOT - Cylinder Arrangement:** 

Dual

DOT #1 - Date of Manufacture:

2023

Month: July

LP Leak / Drop Test - Begin

Time: Begin Time

Enter Start Time: 3:13 pm

Combination LP / CO Detector -**Brand / Model / Serial Number:** 

Safe-T-Alert

Model / Serial #: Safe-T-Alert / 85-741

Combination LP / CO Detector -

Test Result:

Pass

Smoke Detector - Date:

Three Years Old

Manufacture Date: Oct 23, 2020

**Smoke Detector - Alarm During** 

Test:

Yes, by Pushing the Button

Fire Extinguisher - Minimum

Size Installed:

Yes

Fire Extinguisher - Gauge **Indicates Charged State:** 

Yes

DOT - Regulator Type:

Dual Input - Auto Change Over

**DOT #2 - Cylinder Size:** 

20 LBS

**LP Leak / Drop Test - End** 

Time:

Stop Time

Enter Stop Time: 3:18 pm

Combination LP / CO **Detector - Date:** 

Less Than One Year Old

Manufacture Date: OCt 4, 2023

Combination LP / CO **Detector - Alarm During** 

Test: Yes

**Smoke Detector - Test** 

Method:

Tested by Pushing Button

Fire Extinguisher -**Brand:** 

Kidde

Brand: Kidde

Fire Extinguisher -Secure in Bracket:

#### Items

#### 14.7 DOT Cylinder(s) - Condition

Overview



Curbside DOT Tank



Streetside DOT Tank

14.8 DOT Tank #1 - Rust or Damage

Acceptable

14.9 DOT Tank #1 - Regulator Vents Downward

Acceptable

14.10 DOT Tank #2 - Rust or Damage

### 14.11 DOT Tank #2 - Regulator Vents Downward Acceptable

# **14.17 DOT - Hoses and Regulators - Condition**Acceptable

## 14.18 LP Leak System Test

Acceptable



Time Pressure Drop Test - Start



Time Pressure Drop Test - 3 Minutes



Time Pressure Drop Test - 5 Minutes - End

## 14.21 Combination LP / CO Detector



CO / LP Detector - Front



CO / LP Detector - Back

#### 14.22 Smoke Detector



Smoke Detector Location



Smoke Detector - Back

#### 14.23 Fire Extinguisher



Fire Extinguisher



Fire Extinguisher Size

## 15. Appliances: Kitchen

NOTE: Refrigerators need to be on for a minimum of 12 hours to be at full cooling condition. This inspection may not reveal a problem if during the inspection the refrigerator was not on for the minimum recommended time.

#### Styles & Materials

**Refrigerator - Brand:** 

**Refrigerator - Type:** 

**Refrigerator - Cooling** 

Furrion

Residential Style - 12 VDC Compressor

Source(s): 12 Volts DC

None

Model # / Serial # : FCR10DCGTA / **Refrigerator - Control Panel** 

**Refrigerator - Current** 

**Refrigerator - Freezer -**

Location:

Interior Wall in Refrigerator

Refrigerator - Has Unit been **Running 12 + Hours:** 

Yes

**Cooktop - Brand:** 

Furrion

Oven - Brand:

Furrion

**Microwave - Type:** 

Microwave Only

**Cooktop Exhaust Vent - Part** 

of Microwave: Yes

**Temperature:** 

Degrees F Degrees: 32

**Refrigerator - Thermister** 

**Sensor Type:** 

Adjustable

**Cooktop - Regulator Installed** 

on Propane Line?:

**Oven - Burner Ignition Source:** 

Piezo Ignition - Turn Knob to Create a

Spark

Microwave - Temperature of Water after 60 Seconds:

Degrees F Degrees: 119

**Cooktop Exhaust Vent -**

Venting: Re-Circulates Air **Current Temperature:** 

Degrees F

**Refrigerator - Location of** 

**Vent Panels:** Not Present

**Cooktop - Burner Ignition** 

Source:

Piezo Ignition - Turn Knob to Create

a Spark

Microwave - Brand:

Furrion

Microwave - Rack and **Turntables are Installed:** 

Yes

## **Items**

15.4 Refrigerator - Operates on all Available Sources

Acceptable

15.5 Refrigerator - Condition

Overview



Refrigerator

15.6 Refrigerator - User Control Panel Acceptable

- 15.7 Refrigerator Front Side Door Panels Acceptable
- **15.8 Refrigerator Front Side Door Frame**Acceptable
- **15.9 Refrigerator Front Side Door Seals**Acceptable
- 15.10 Refrigerator Door Latch Secure Acceptable
- 15.11 Refrigerator Inside Light Operation

Acceptable

**15.12 Refrigerator - Thermostat Sensor - Control Mounted on Fins**Acceptable

15.13 Refrigerator - Inside Walls

Acceptable

15.14 Refrigerator - Shelves / Door Racks

Acceptable

**15.15 Refrigerator - Crisper Trays and Drawers** 

Acceptable

15.16 Refrigerator - Odor Detectable

Acceptable

15.19 Refrigerator - Freezer - Inside Walls

Acceptable

15.20 Refrigerator - Freezer - Shelves / Door Racks

Acceptable


15.21 Refrigerator - Freezer - Odor Detectable

Acceptable

15.22 Cooktop - Condition

Poor

The back left burner on the cooktop would not ignite. This is a Life Safety Issue. It is recommended that this be further evaluated by a qualified RV technician prior to occupying the RV.



Cooktop

15.23 Cooktop - Condition of Knobs / Controls
Acceptable

**15.24 Cooktop - Burner Grate / Cover Condition**Acceptable

15.25 Cooktop - Cover Matches Countertop Material Acceptable

**15.26 Cooktop - Rubber Grommets for Stovetop Grate**Acceptable

15.27 Cooktop - All Burners Operate No

15.28 Cooktop - Color of Burner Flame

Acceptable

15.29 Oven - Condition

Acceptable

15.30 Oven - Racks Condition

Acceptable

15.31 Oven - Burner Lights

Acceptable

Overview



Oven Burner

15.32 Oven - Color of Burner Flame

Acceptable

15.33 Microwave - Condition

Acceptable

15.34 Microwave - Convection Mode - Fan Blower Comes On

Acceptable

15.36 Cooktop Exhaust Vent - Condition

Acceptable

15.37 Cooktop Exhaust Vent - Filter and Lighting Condition

Acceptable

15.38 Cooktop Exhaust Vent - Fan Speeds and Vent Condition

Acceptable

## 16. Appliances: Other

NOTE: Mud Dauber screens are stainless steel screens and springs that are designed to keep mud daubers, wasps and spiders from nesting in the appliances. Verify the appliance manufacturers approve of their use prior to installation.

### **Styles & Materials**

Water Heater - Brand:

Suburban

Model # / Serial # : ST60 /

194417

Water Heater - Type of Ignition:

Direct Spark Ignition (DSI) and Electric

Furnace #1 - Brand:

Suburban

Water Heater - Type:

Tankless

Water Heater - Water Output **Temperature:** 

Degrees F Degrees: 120

**Electric Fireplace - Brand:** 

Unknown

Model # / Serial # : Unknown

**Water Heater - Heat Source(s):** 

Propane and Electric

Water Heater - Bypass Valves in **Correct Position:** 

Yes

#### **Items**

#### 16.0 Water Heater - Condition

Acceptable

Overview



Water Heater

16.1 Water Heater - Operates on all Sources

Acceptable

16.2 Water Heater - Exterior - Condition of Burner Assembly Area Acceptable

16.3 Water Heater - Exterior - Rubber Grommet Around Gas Line Sealed

Acceptable

16.4 Water Heater - Exterior - Dauber Screens Installed

No

16.5 Water Heater - Exterior - Leaks at Pressure Relief Valve

Yes

16.6 Water Heater - Exterior - Proper Drain Plug Installed Yes

#### 16.7 Furnace #1 - Operation

Acceptable Overview



Furnance

16.8 Furnace #1 - Floor Vents Blocked or Covered No

**16.9 Furnace #1 - Warm Air Discharge out of Vents**Acceptable

**16.10 Furnace #1 - Air Intake / Exhaust Area Condition**Acceptable

16.11 Furnace #1 - Exterior - Dauber Screens Installed No

**16.23 Electric Fireplace - Condition**Acceptable

Overview



**Fireplace** 

#### 16.24 Electric Fireplace - Operation

Acceptable

## 17(A) . Front Air Conditioner

NOTE: The Delta-T average acceptable performance range is 14 to 22 degrees F (8 to 12 degrees C). In high humidity areas the range may be lower, 12 to 16 degrees F (12 to 16 degrees C) and in desert areas, it may be higher, 23 to 26 degrees F (13 to 15 degrees C).

### **Styles & Materials**

Air Conditioner - Brand:

Coleman

**Air Conditioner - Thermostatic Controls:** 

Stand Alone

Air Conditioner - Options:
Air Conditioner

Air Conditioner - Delta-

T:

Degrees F Degrees: 16

### Items

#### 17.0.A Air Conditioner - Condition



Front AC - Intake



Front AC - Outlet

#### 17.1.A Air Conditioner - Filter Condition

Accerptable

#### 17.2.A Air Conditioner - Exhaust Condition

Accerptable

## 17(B) . Center Air Conditioner

## **Styles & Materials**

Air Conditioner - Brand:

Coleman

Model # / Serial # : Unknown

**Air Conditioner - Thermostatic** 

**Controls:**Dual with Furnace

Air Conditioner - Options:
Air Conditioner

**Air Conditioner - Delta-**

T:

Degrees F Degrees : 14

#### **Items**

#### 17.0.B Air Conditioner - Condition



Center AC - Intake



Center AC - Outlet

#### 17.1.B Air Conditioner - Filter Condition

Accerptable

### 17.2.B Air Conditioner - Exhaust Condition

Accerptable

### 17.3.B Heat Mode - Operation

Accerptable

## 18. Interior

## **Styles & Materials**

Ceiling Vents - Type:

**Lights - Light Bulb - Type:** Cabinets / Pantries - Types of

Manual Crank Vent - Handle / Knob

LED

Hinges:

Double Bowl

Exposed / Hidden

Window Coverings / Blinds -

Type:

Single Roller - not attached at

bottom

Plastic

**Bathroom Sink - Style:** 

Vinyl Tile

**Bathroom Sink - Type:** 

**Kitchen Sink - Style:** 

Plastic

**Shower / Tub - Style:** 

**Kitchen Sink - Type:** 

Shower Stall

Single Bowl

**Shower / Tub - Enclosure** 

Type:

Plastic Accordion

Flooring - Type:

#### Items

#### 18.0 Interior - Overview



Front to Rear



Rear to Front

18.1 Ceiling - Condition

Acceptable

18.2 Ceiling - Panels Loose

Acceptable


18.3 Ceiling - Water Damaged Ceiling Panels

Acceptable

18.4 Ceiling - Discoloration or Stains

Fair


The ceiling has a tacky residue along almost every panel. It is recommended that this be further evaluated by a qualified RV technician.



Ceiling Panels


# **18.5 Ceiling - Trim Work Missing or Damaged**Fair

(1) The trim above the cabinets above the bed is separated from the wall with exposed staples showing. It is recommended that this be further evaluated by a qualified RV technician.




Trim Above the Bed


(2) There are multiple place in the bedroom ceiling trim that is separating from the wall. It is recommended that this be further evaluated by a qualified RV technician.



Streetside Bedroom Ceiling Trim



Streetside Bedroom Ceiling



Curbside Bedroom Ceiling

- **18.6 Ceiling Vents and Skylights Condition**Acceptable
- **18.7 Ceiling Vents and Skylights Thermostatic Controls and Switches Work**Acceptable
- **18.8 Ceiling Vents and Skylights Trim Ring Around Vents and Skylights**Acceptable
- 18.9 Ceiling Vents and Skylights Stains Around Roof Vents and Skylights
  Acceptable
- 18.10 Ceiling Vents Manual Operation Acceptable
- 18.11 Ceiling Vents 12-Volt DC Fans Operation Acceptable
- 18.12 Ceiling Vents 120-Volt AC Fans Operation Acceptable
- **18.13 Lights and Light Fixtures Condition**Acceptable
- 18.14 Lights and Light Fixtures 12-Volt DC Lights Operation Acceptable
- 18.15 Lights and Light Fixtures 120-Volt AC Lights Operation Acceptable
- 18.20 Lights and Light Fixtures Entry Lights inside RV Acceptable
- 18.21 Lights and Light Fixtures Missing or Broken Lenses
- 18.23 Walls Condition

18.24 Walls - Panels Loose

Acceptable

18.25 Walls - Water Damaged Wall Panels

Acceptable

18.26 Walls - Panels Discolored or Stained

Acceptable

18.27 Walls - Soft Spots

Acceptable

18.28 Walls - Trim Work - Condition

Fair

There are multiple locations through the RV that have scuff marks, separation or not aligned, pealing or damage trim. It is recommended that this be further evaluated by a qualified RV technician.




Trim Between Pantry and Entertainment Unit



Trim Next to Pantry




Trim on Left Side of Entertainment Center



Trim on Left Side of Entertainment Center




Trim on Front of the Entertainment Center



Trim on the Top Right of the Entertainment Center



Trim Located by the Bedroom Door



Trim by the Bedroom Door

**18.29 Walls - Damage Repairs Performed**Acceptable

18.30 Walls - Holes or Wall Repairs
Acceptable

18.31 Interior Doors - Condition Acceptable

**18.32 Interior Doors - Operation**Acceptable

18.33 Privacy Curtains / Screens - Condition Acceptable

**18.34 Privacy Curtains / Screens - Operation**Acceptable

**18.35 Cabinets / Pantries - Condition** 

Acceptable

18.36 Cabinets / Pantries - Operation

Acceptable


### 18.37 Cabinets / Pantries - Door Damage / Scratches

Fair

Some of the cabinets / pantry trim does not align correctly. It is recommended that this be further evaluated by a qualified RV technician.



Pantry



Pantry Door Panel



Bunkroom Trim



Bathroom Cabinet

18.38 Cabinets / Pantries - Wood Rot or Broken Acceptable

18.39 Cabinets / Pantries - Drawer Damage / Scratches Acceptable

18.40 Cabinets / Pantries - Countertop Damage / Scratches Acceptable

18.41 Windows - Condition Acceptable

The bedroom curbside window inner seal / trim is separating from the seal. It is recommended that this be further evaluated by a qualified RV technician.



Curbside Bedroom Window

#### 18.42 Windows - Operation

Acceptable Overview



**Emergency Exit Window** 

### **18.43 Windows - Screens - Condition**

Acceptable

Ranger RV, LLC
18.44 Windows - Emergency Exit Windows - Operation Acceptable
18.45 Windows - Emergency Exit Windows - Installed Acceptable
18.46 Windows - Window Coverings / Blinds - Operation Acceptable
18.47 Windows - Window Coverings / Blinds - Condition Acceptable
18.48 Flooring - Sheet Vinyl - Condition Acceptable
<b>18.54 Flooring - Floor Covering Discolored or Stained</b> No
18.55 Flooring - Water Damage No
18.57 Flooring - Sheet Vinyl Stained No
18.58 Flooring - Soft Spots in Floor No
18.59 Flooring - Previous Repairs Performed No
18.61 Kitchen Sink - Condition Acceptable
18.62 Kitchen Faucet - Operation and Condition Acceptable
18.63 Kitchen Sink - Hot and Cold Water Available Acceptable
18.64 Kitchen Faucet - Leaks at Stem No
18.65 Kitchen Sink - Sink(s) Holds Water Yes
18.66 Kitchen Sink - P-Trap Holds Water Yes
18.67 Kitchen Sink - Under Sink Condition Acceptable
18.68 Toilet - Operation and Condition Acceptable
18.69 Toilet - Bowl Holds Water Yes
18.70 Toilet - Mounting Problems No
18.71 Toilet - Water Leaks

18.72 Toilet - Indication of Previous Damage or Repair

No

18.78 Shower / Tub - Condition

Acceptable

18.79 Shower / Tub - Operation

Acceptable

18.80 Shower / Tub - Hot and Cold Water Available

Acceptable

18.81 Shower / Tub - Stains, Chemical Buildup in Stall / Tub

No

18.82 Shower / Tub - Discoloration

No

18.83 Shower / Tub - Water Damage or Leaks

No

18.85 Shower / Tub - Door and Frame and Seals Condition

Acceptable

18.87 Shower / Tub - Curtain with Rod - Operation

Acceptable

18.90 Bathroom Sink - Condition

Acceptable

18.91 Bathroom Faucet - Operation and Condition

Acceptable

18.92 Bathroom Faucet - Hot and Cold Water Available

Yes

18.93 Bathroom Sink - Faucet Leaks at Stem

No

18.94 Bathroom Sink - Sink(s) Holds Water

Yes

18.95 Bathroom Sink - P-Trap Holds Water

Yes

18.96 Bathroom Sink - Under Sink Condition

Acceptable

#### 19. Furniture

#### **Styles & Materials**

Mattress - Type: Closets / Cabinets / Dressers - Types of Hinges:

Unknown Exposed / Hidden

Sofa(s) - Type:
Pull out Bed

#### **Items**

19.0 Chairs - Condition

Acceptable

19.1 Chairs - Fabric Tears or Separation

No

19.2 Chairs - Fabric Discolored or Stains

No

19.3 Chairs - Signs of Excess Wear

No

Ranger RV, LLC
19.4 Chairs - Water Damage No
19.5 Sofa(s) - Condition  Acceptable
19.6 Sofa(s) - Operation  Acceptable
19.7 Sofa(s) - Fabric Tears or Separation No
19.8 Sofa(s) - Fabric Discolored or Stains Yes
19.9 Sofa(s) - Signs of Excess Wear No
19.10 Sofa(s) - Water Damage No
19.20 Bed(s) - Condition Acceptable
19.21 Bed(s) - Fabric Tears or Separation No
19.22 Bed(s) - Fabric Discolored or Stains No
19.23 Bed(s) - Signs of Excess Wear No
19.24 Bed(s) - Bed Covers Present Yes
19.25 Bed(s) - Covers Match Decor Yes
19.26 Closets / Cabinets / Dressers - Condition Acceptable
19.27 Closets / Cabinets / Dressers - Operation Acceptable
19.28 Closets / Cabinets / Dressers - Door Damage or Scratches  Acceptable
19.29 Closets / Cabinets / Dressers - Counter Top Damage or Scratches  Acceptable
19.30 Closets / Cabinets / Dressers - Wood Rot or Broken No
19.31 Closets / Cabinets / Dressers - Drawer Damage or Scratches No
19.32 Closets Doors / Cabinets Door / Drawers - Pull-Out - Condition Acceptable
19.33 Closets Doors / Cabinets Door / Drawers - Pull-Out - Operation Acceptable
19.34 Closets Doors / Cabinets Door / Drawers - Previous Repairs Performed No
19.35 Desk / Vanity - Condition Acceptable

# 19.36 Desk / Vanity - Operation Acceptable 20(A) . Living Room Television **Items** 20(B) . Bedroom Television Items 20(C) . Radio / Stereo **Styles & Materials Unit Brand:** Furrion Model # / Serial # : Unknown Items **20.0.C Unit Works Properly** Acceptable 20.1.C Unit Cleaned and Maintained Acceptable

Acceptable

20.2.C Unit Properly Mounted and Secured

20.5.C Antenna - Picks Up Local Channels

Items