Inspection Report for Mike Hill

Provided by: Aerial View Solutions LLC



Aerial View Solutions LLC.

Inspector: Oscar Gregory Jr Oscar Gregory Jr Phone: 770-467-7805 Email: aerialviewsolutionsllc@gmail.com (CEO) Oscar Gregory Jr 4922 Summersun Drive Morrow Ga 30260

Property Address: 7809 Bell Tower Lane Fairburn Ga 30213

7809 Bell Tower Lane Fairburn Ga 30213 GA MLS # 6965916




1 Report Information

Property Photo

1) Aerial Photography of said property

Aerial Photography of said property.



Client Information

Client Name	Mike Hill	
Client Phone		000-000-0000
Property Information		
Approximate Year Built	2010	
Approximate Square Footage	2170	
Number of Bedroom	4	
Number of Bath	2.5	
Direction House Faces	North	
Inspection Information		
Inspection Date	11/10/2021	
Inspection Time	10:30 AM	
Weather Conditions	Dry	
Outside Temperature	71	
Price for Inspection	\$375	

Sample Inspection Agreement

WITHIN THE SCOPE OF THE INSPECTION

The scope of this inspection and report is limited to a visual inspection of the systems and components as listed below, in order to identify those, if any, which may need replacement or repair. See Standards of Practice for a detailed description of the scope of inspection.

Exterior:

Landscaping, Retaining Walls, Gutters, Downspouts, Sidewalks and Driveways (both the condition of and as they affect foundation drainage,) Roof, Chimney, Flashing, and Valleys, (for evidence of water penetration and a description of materials,) Siding, Fascia, Soffit, Walls, Widows, Doors, Foundation, Attached Porches/ Decks/ Balconies/ Patios/ Garages (both structural and condition of.)

Interior:

Plumbing System: Water Supply/Drains/Vents/Water Heaters/Fixtures, and Locating (But Not Testing) Shut Off Valves; Electrical System: Service Drop, Service Panel, Ground Wire, GFCI Plugs, Switches, Receptacles, Installed Fixtures, and Smoke Detectors; Heating/Cooling System: Permanent Systems, Operating Controls/Filters/Ducts, Insulation, Vapor Barrier, and Ventilation; Bathrooms/Kitchen/Other Rooms: Doors/Windows/Walls/Floors (as to general condition), Cabinets, Counter tops, and Installed Fixtures; Structure: Ceilings/Walls/Floors, Stairs/Basements/Attic/Crawl Spaces (if readily accessible) (as to evidence of water damage and general condition.)

- The scope of the inspection is limited to the description and the general condition of the above systems.

OUTSIDE THE SCOPE OF THE INSPECTION

-Any area which is not exposed to view or is inaccessible because of soil, walls, floors, carpets, ceilings, furnishings, lack of access or crawl spaces or any major system (water or electrical systems, heating system, or air conditioner) that is not currently functional is not included in this inspection. -The inspection does not include any destructive testing or dismantling. Client agrees to assume all the risk for all conditions which are concealed from view at the time of the inspection. This is not a home warranty, guarantee, insurance policy, or substitute for real estate disclosures which may be required by law. Whether or not they are concealed, the following are outside the scope of the inspection;

- Building code or zoning ordinance violations - Thermostatic or time clock controls or Low Voltage wiring systems - Geological stability or soils conditions - Water softener or water purifier systems or solar heating systems - Structural stability or engineering analysis - Saunas, steam baths, or fixtures and equipment - Building value appraisal or cost estimates - Pools or spa bodies or sprinkler systems and underground piping - Radio-controlled devices, automatic gates, elevators, lifts, and dumbwaiters - Furnace heat exchanger, freestanding appliances, security alarms or personal property - Specific components noted as being excluded on the individual system inspection form - Adequacy or efficiency of any system or component - Prediction of life expectancy of any item.

- The Inspector is a home inspection generalist and is not acting as an engineer or expert in any craft or trade. If the Inspector recommends consulting other specialized experts, Clients do so at Client's expense.

CONFIDENTIAL REPORT

-The written report to be prepared by the Inspector shall be considered the final and exclusive findings of the Inspector/Inspection Company regarding the home inspection at the Inspection Address. The inspection report to be prepared for the Client is solely and exclusively for the Client's own information and may not be relied upon by any other person. Client agrees to maintain the confidentiality of the inspection report and agrees not to disclose any part of it to any other person with the exception of the seller and/or the real estate agents directly involved in this transaction. Client(s) or the inspector may distribute copies of the inspection report to the seller and real estate agents directly involved in this transaction, but neither the seller nor the real estate agent are intended beneficiaries of this Agreement or the inspection report. Client agrees to indemnify, defend, and hold the Inspector/inspection Company

Aerial View Solutions LLC.

harmless from any third party claims arising out of the Client's or Inspectors distribution of the inspection report.

DISPUTES

• Client understands and agrees that the Inspector/Inspection Company is not an insurer, that the price paid for the subject inspection and report is based solely on the service provided. Client also agrees that any claim of failure in the accuracy of the report shall be reported to the Inspector/Inspection Company within five business days of discovery and that failure to notify the inspector within that time period shall constitute a waiver of any and all claims. The Inspector/Inspection Company shall have five business days to respond to the claim. If the Inspector/Inspection Company fails to satisfy the claim, liability shall be limited to a refund of the price paid for the Inspection and Report.

Definition of conditions:

AS = Appears Serviceable: The item appeared to be in working or usable condition with no major discrepancies noted.

R = Repair: The item was at or near the end of its useful lifespan. A certified professional should be contacted for further evaluation and repair.

S = Safety Issue: The item is considered a safety hazard and can cause harm to people or property. These items need to be repaired as soon as possible.

NI = Not Inspected: The item was not inspected during the inspection.

2 Grounds

Grading

Grading Slope

The site is moderately sloped.

2) Grading Conditions



Grading of the soil near the foundation appears to be in serviceable condition.







Driveways - Sidewalks - Walkways

Driveway Material

Concrete

- 3) Driveway Conditions
- AS The driveway appeared to be in serviceable condition at the time of the



Sidewalk Material

Concrete

4) Sidewalk Conditions



The visible areas of the sidewalk appeared to be in serviceable condition at the time of the inspection.





<u>Retaining Wall</u>	
Retaining Wall	

5) Retaining Wall

Material

Conditions

N/A
NI

		_
Ext	eri	$\mathbf{n}\mathbf{r}$

Front - Back E	<u>ntrance</u>
----------------	----------------

Front	Entrance	Туре
I I UIIt	Lintrance	1 JPC

6) Front Entrance Conditions



Patio

N/A

The visible portions of the patio appeared to be in serviceable condition at the time of the inspection.



Back Entrance Type

Patio

7) Back Entrance Conditions



The visible portions of the patio appeared to be in serviceable condition at the time of the inspection.



Exterior Walls

Conditions

Structure Type

Exterior Wall Covering

Wood frame


8) Exterior Wall

shingles.

Damaged siding was observed at. Due to conditions observed, further evidence may exist in areas not readily visible or accessible. Water penetration may have occurred.

The visible and accessible areas of the exterior siding material are wood







Exterior Windows - Doors

Window	Туре
--------	------

Double Hung

Window Material

Vinyl

9) Window Conditions

AS

All the home window appears serviceable at the time of inspection.



10) Exterior Door Conditions



The door(s) appeared to be in serviceable condition at the time of the inspection.







Exterior Water Faucet(s)

Faucet Location

11) Faucet Conditions



North side of home. South side of home.

The hose faucets appeared to be in serviceable condition at the time of the inspection. These should be drained prior to freezing temperatures. Front side of home PSI pressure 140. The home back side of home 80 PSI.

Chimney

12) Chimney Conditions



The visible and accessible portions of the chimney(s) appeared to be in serviceable condition at the time of the inspection.





4 Roofing

Roof Covering

Method of Inspection	The roof was inspected by observing from a ladder placed at the edge of the roof.
Roof Style	Gable
Roof Covering Material	Asphalt composition shingles.
Number of Layers	One
13) Roof Covering	AS The roof covering shows normal wear for its age and appeared to be

Condition



covering shows normal wear for its age and appeared to be in serviceable condition at the time of the inspection.







14) Flashing Conditions



The exposed flashings appeared to be in serviceable condition at the time of inspection.







15) Gutter & Downspout Conditions



The gutter system appeared to be in serviceable condition at the time of the inspection.





Attic Area

Attic Access	Hallway
Method of Inspection	Entered attic area.
Roof Frame Type	The roof framing is constructed with rafter framing.
16) Attic Conditions	AS The visible and accessible portions of the attic appeared to be in serviceable condition at the time of the inspection.











Attic Ventilation Type

Attic Ventilation Conditions Attic Insulation Type

17) Attic Insulation Conditions Soffit vents

The attic screens appears serviceable at the time of inspection.

Loose fill



The attic has fiberglass batt insulation. The approximate depth of the insulation is 8 to 10 inches. This appears adequate.





10/11/2021 12:29

RALIZER 12:27

18) Attic Ladder

The home Attic appears serviceable at the time of inspection.






5 Heating - Air

Heating

Location of Unit	Attic
Heating Type	Forced Air
Energy Source	Geothermal
Approximate BTU Rating	280,000
19) Unit Conditions	The heating attic







Distribution Type

The visible areas of the heat distribution system is ductwork with registers.

20) Distribution Conditions



The visible and accessible areas of the distribution system appeared to be in serviceable condition at the time of inspection.



21) Ventilation Conditions



The visible and accessible portion of the venting flue appeared to be in serviceable condition at the time of the inspection.



22) Thermostat Condition



The home thermostat is not working down stair in the kitchen. The thermostat up stairs is working





23) Home Heating Unit

The home unit type- Lennox The unit manufacturer date 12/6/2009





Air Condition - Cooling

Type of Cooling System	Geothermal
------------------------	------------

AC Unit Power 240V

24) AC Unit Conditions



The home Ac unit appears serviceable at the time of inspection. The unit is a Tirane Manufacturer date 07/20/12





6 Electrical

The electrical service is underground.

Service Drop - Weatherhead

Electrical Service Type	
Electrical Service	
Material	

Copper

Number of Conductors

25) Electrical Service Conditions



Three

The main service entry appeared to be in serviceable condition at the time of inspection.



Main Electrical Panel

Main Disconnect	At Main Panel
Location	
Electric Panel Location	The main electric panel is located at the garage.
Panel Amperage Rating	The electrical capacity of main breaker was listed / labeled as amps.
Circuit Protection Type	Breakers
26) Wiring Methods	AS The main power cable is copper. The branch cables are copper.



27) Electrical Panel Conditions



AS

The main panel appeared to be in serviceable condition at the time of the inspection.





28) Electrical Outlets Outside

The home outside electrical outlets appears serviceable at the time of inspection.





Electrical Subpanel

Subpanel Location

A sub panel is located at the garage.

29) Subpanel Conditions



The sub panel appeared to be in serviceable condition at the time of inspection.





7 Plumbing

The visible material used for the supply lines is plastic.

Water Main Line

Main Line Material

Main Shutoff Location In the front yard

AS

The visible material of the main line / pipe appears to be galvanized.

30) Main Line & Valve Conditions

The visible portion of the main pipe and valve appeared to be in serviceable condition at the time of the inspection.





Water Supply Lines

Supply Line Material

31) Supply Line Conditions



The visible portions of the supply lines appeared to be in serviceable condition at the time of inspection. All of the supply lines were not fully visible or accessible at the time of the inspection.



Drain - Waste Lines

Drain Line Material

32) Drain Line Conditions



The visible portions of the waste lines are plastic.

The visible portions of the waste lines appeared to be in serviceable condition at the time of inspection. All of the waste lines were not fully visible or accessible at the time of the inspection.



Water Heater(s)

Water Heater Type	Electric
Water Heater Location	Garage
Water Heater Capacity	40 Gallon
33) Water Heater Conditions	AS The how

The water heater was operable at the time of inspection. This does not however guarantee future performance, operation, or condition. Manufacturer Dates 07/20/12 Type of unit Rheem




Walls - Ceilings - Floors

34) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.







35) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.









36) Floor Conditions

AS

The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.











37) Heat Source Conditions



All the home register appears serviceable at the time of inspection.








Windows - Doors

38) Interior Window Conditions



Some of the window screens were missing or not installed at time of inspection.







39) Interior Door Conditions

AS

The interior doors appeared to be in serviceable condition at the time of the inspection.



Electrical Conditions

40) Electrical Conditions



The home door bell appears serviceable at the time of indpection.



41) Lighting Conditions



Light(s) were out or inoperative at. Dismantling and testing of all light fixtures is not performed as part of this inspection. Recommend all lights be operable prior to close.





42) Ceiling Fan Conditions



The ceiling fan(s) were operational at the time of the inspection. Mounting hardware of fans, light fixtures, and / or chandeliers was not visible or accessible for inspection.



43) Smoke Detector Conditions



The home smoke detector appear serviceable at the time of inspection.








Fireplace

Fireplace Location

Fireplace materials

44) Fireplace Conditions



A fireplace is located at the family room.

The fireplace is gas fired and was operable at the time of inspection. Client is advised to obtain information from the manufacturer regarding use, maintenance, and carbon monoxide risks if any.





9 Kitchen

Walls - Ceilings - Floors

45) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.



46) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



47) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.





48) Heat Source Conditions



The kitchen registers appears serviceable at the time of inspection.



Aerial View Solutions LLC.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

Windows - Doors

49) Kitchen Window Conditions



Some of the window screens were missing or not installed at time of inspection.



50) Kitchen Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.



Electrical Conditions

51) Electrical Conditions



The kitchen outsets appears serviceable at the time of inspection.



52) Lighting Conditions



The kitchen lighting appears serviceable at the time of inspection.



53) Ceiling Fan NI Conditions

Kitchen Sink - Counter tops - Cabinets

54) Counter Conditions

AS

N/A

The visible portion kitchen counters appeared to be in serviceable condition at the time of the inspection.







55) Cabinet Conditions



The kitchen cabinets appeared to be in serviceable condition at the time of inspection.







56) Sink Plumbing Conditions



The kitchen sink appeared to be in serviceable condition at the time of the inspection. The faucet appeared to be in serviceable condition at the time of the inspection. The visible areas of the plumbing under the kitchen sink appeared to be in serviceable condition at the time of the inspection.



57) Garbage Disposal Condition



The sink disposal was operable at the time of the inspection. Client should consult a licensed plumber, manufacturer, or disposal supply company for information on proper usage and safety related concerns.



Appliances

Stove - Range Type

The oven is electric.

58) Stove - Range Condition



The oven was in operational condition at the time of the inspection. This does not however guarantee future conditions after the time of inspection.

Manufacture name Whirlpool







59) Hood Fan Conditions



The fan / hood and light were in operational condition at the time of the inspection.



60) Dishwasher Conditions



The dishwasher appeared to be in serviceable condition at the time of the inspection. This does not however guarantee future performance or conditions.

The dishwasher Manufacture Samsung.



10 Bath(s)

Walls - Ceilings - Floors

61) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.











62) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.









63) Floor Conditions



The general condition of the visible and accessible portions of the floors appeared to be in serviceable condition at the time of the inspection.











64) Heat Source Conditions



All the bathroom Registers appears serviceable at the time of inspection.







Windows - Doors

65) Bathroom Window Conditions



Some of the window screens were missing or not installed at time of inspection.



66) Bathroom Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.







Electrical Conditions

67) Electrical Conditions



The bathroom electrical outlets working at the time of the inspection.







AS

- 68) Lighting Conditions
- All the bathroom lights appears serviceable at the time of inspection.







69) Vent Fan Conditions



The bathroom vent fan was working at the time of inspection







Bathroom Sink

70) Counter - Cabinet Conditions



All the bathroom counter appears serviceable at the time of inspection.







10 Bath(s)

71) Sink Conditions



The sink appeared to be in serviceable condition at the time of inspection in bath










Shower - Tub - Toilet

72) Shower - Tub Conditions








73) Toilet Conditions



The toilet appeared to be in serviceable condition at the time of inspection in bath









Walls - Ceilings - Floors

74) Basement Stair Conditions	NI N/A
75) Wall Conditions	AS N/A
76) Ceiling Conditions	NI N/A
77) Floor Conditions	NI N/A
78) Heat Source Conditions	NI N/A
Windows - Doors	
79) Basement Window Conditions	AS N/A
80) Basement Door Conditions	NI N/A
Electrical Conditions	
81) Electrical Conditions	NI N/A
82) Lighting Conditions	NI N/A
83) Sump Pump Conditions	NI N/A
Other Conditions	
84) Other Conditions	NI N/A


12 Garage - Laundry

Walls - Ceilings - Floors

Garage Type

(if detached)

Number of cars is two.



The visible and accessible portions of the exterior wall coverings appeared to be in serviceable condition at the time of the inspection. .





86) Roof Conditions (if detached)



The roof covering shows normal wear for its age and appeared to be in serviceable condition at the time of the inspection.



87) Wall Conditions



The general condition of the walls appeared to be in serviceable condition at the time of the inspection.







88) Ceiling Conditions



The general condition of the ceilings appeared to be in serviceable condition at the time of the inspection.



89) Floor Conditions



The general condition of the visible and accessible portions of the floors

 \frown appeared to be in serviceable condition at the time of the inspection.



90) Window Conditions



91) Door Conditions



The interior doors appeared to be in serviceable condition at the time of the inspection.



92) Vehicle Door Conditions



10/11/2021 12:1

The vehicle door(s) appeared to be in serviceable condition at the time of the inspection.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected





93) Electrical Conditions



The garage electrical outlets appears serviceable at the time of inspection.





94) Lighting Conditions



All the garage lights was working at the time of inspection.





12 Garage - Laundry

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

Laundry Room

Location

The laundry facilities are located at the upper level.

95) Laundry Room Conditions



The visible and accessible portions of the laundry plumbing components appeared to be in serviceable condition at the time of inspection.







13 Foundation - Crawl Space

Foundation

Foundation Type

Foundation Material

96) Foundation Conditions Slab on grade

Block Brick Concrete Stone



The home foundation appears serviceable at the time of inspection.







Flooring Structure

Flooring Support Type

97) Flooring Support Conditions



Slab on grade

The visible and accessible areas of the wood framing system appeared to be in serviceable condition at the time of the inspection.





