HowItBrok	e.com	1		T	•	ı	10/24/2019	-				. Ho	owItBroke.com
								PHASE BY:					
								Accident/Damaged,					
								During Operaton,					
								Charging,					
								Parked/Stationary,					
						AZE A D		Not the battery or no	D 1				
DATE	COLDIEDA	CT ATE	CITY	MAKE	MODEL	YEAR	DETAIL C	fire, Insufficient info	_	F . 1	r · 1		
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:	
9/24/19	USA	UT	Carlin	Tesla	Multiple	2019	Tractor trailer loaded with 5 Teslas and a Subaru caught fire. Tesla claims cars were not responsible but with no evidence and despite fire propagating.	I	1	0	0	https://www.autoblog.com/2019/10/02/traile r-loaded-with-teslas-burns/#slide-2174002 and https://elkodaily.com/news/local/truck-hauling-electric-vehicles-catches-fire-on-i-near/article_312d08e4-1250-56a0-bf5f-7d7eadb8c378.html	
7.217	0511		Cuilli	Testa	ampre	2017	evidence and despite fire propagating. Owner charged the car, drove for 10		-	Ü	-	, a, sado os , omem	
9/20/19	Ukraine		Kyiv	Chevrolet	Bolt		minutes, then about 15 minutes later it caught fire while parked. Witnesses saw initial smoke from area of rear wheels.	P	0	0	0	https://www.youtube.com/watch?v=okO5nn _aHgM and https://insideevs.com/news/373630/ukrainia n-chevy-bolt-caught-fire/	
			-				Car was in Tesla authorized repair shop						
							and on lift at night when it caught fire.	P				1	
0/10/10	GI.		** 1				Firefighters had to break in.	•				https://insideevs.com/news/366082/video-	
8/18/19	China		Hangzhou	Tesla	S		Firefighting took 1.5 hours.		0	0	0	tesla-fire-china-repair-shop/ https://www.tellerreport.com/business/2019-	
8/13/19	Korea		Sejong City	Hyundai	Kona		Parked and charging in garage under apartment building. Flame began at battery.	P	0	0	0	08-13soaring-flames-from-an-electric-car fault-possibility-investigation- .ByePCmxEH.html	
							drive assist mode when it struck a					russia-fire/tesla-electric-car-catches-fire-after-	
							parked tow truck and caught fire.	A/D				hitting-tow-truck-in-moscow-	
8/10/19	Russia		Moscow	Tesla	3	2019	Videos show occasional explosions.		3	0	3	idUSKCN1V10BB	
0.20.27				2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			Parked and charging in garage under						
		Gyeongg					apartment building. Flame began at	P				http://www.hani.co.kr/arti/english_edition/e	
8/9/19	Korea	i	Bucheon	Hyundai	Kona		battery.		0	0	0	_business/912588.html	
												https://www.supertipp-	
								P				online.de/2019/07/30/brandursache-unklar-	
7/29/19	Germany		Ratingen	Tesla	S		Parked in street when it caught fire		0	0	0	tesla-geht-in-flammen-auf/	
							Parked in garage. Purchased 4 months	P				https://www.carsguide.com.au/car- news/another-electric-car-catches-fire- 75570 and https://www.cbc.ca/news/canada/mon treal/electric-car-catches-fire-and- explodes-in-fle-bizard-garage-	
7/29/19	Canada	Quebec	Montreal	Hyundai	Kona	2019	earlier.		0	0	0	1.5227665	
>,,		2		,			Parked and charging in garage under			,			
		Gyeongg					apartment building. Flame began at	P				http://www.hani.co.kr/arti/english_edition/e	
7/28/19	Korea	i	Bucheon	Hyundai	Kona		battery.		0	0	0	business/912588.html	
7/16/19	USA	CA	Encinitas	Tesla	3		Inebriated driver damaged bottom of car during crash and car caught on fire.	A/D	1	0		https://www.nbcsandiego.com/news/local/Tesla-Crashes-Bursts-Into-Flames-in-Cardiff-Neighborhood-512826991.html	
7/11/19	USA	FL	Tanpa	Tesla	X		Single car crash. Bystanders extricated occupants. An EV website claims color of fire indicates battery pack was not involved, but photos closely replicate fires known to be from battery.	A/D	3	0	3	https://www.abcactionnews.com/news/regio n-hillsborough/tpd-fiery-crash-shuts-down- part-of-n-dale-mabry-hwy-in-tampa	

lowItBrok	o.com						10/24/201	n				How	wItBroke.c
OWILDIOK	c.com						10/24/201	PHASE BY:				l low	VIEDIORC.C
								Accident/Damaged,					
								During Operaton,					
								Charging,					
								Parked/Stationary,					
								• • • • • • • • • • • • • • • • • • • •					
						XIE A D		Not the battery or no	D 1				
						YEAR		fire, Insufficient info	_				
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:	
							extensively damaged home while					https://www.dailynews.com/2019/06/29/2-	
							occupants slept. Continued to burn	_				story-toluca-lake-house-catches-fire/ and	
							after removed from garage and with	P				https://www.flickr.com/photos/lafd/albums/	
6/29/19	USA	CA	Toluca Lake	BMW	i3		firefighters pouring on water.		0	0	0	72157709346051342/	
0/29/19	USA	CA	Toruca Lake	DIVI W	15				U	- 0	U	1	
					77.0		Smoke, fire, and small explosion	P				qz.com/1645678/new-york-listed-nios-	
6/14/19	China		Wuhan	Nio	ES8	2019	reported. Began to burn in a parking lot and had		0	0	0	electric-suv-keeps-catching-fire/	
							to be put in a dump truck filled with	D				https://www.moto.ch/gefaehrliche-	
(15/10			D 4 1	G	F1			P		0	0	1	
6/5/19	Germany		Dortmund	Smart	Electric		water.		0	0	0	elektrofahrzeuge/ https://www.news.com.au/technology/innov	
												ation/motoring/motoring-news/teslas-horror-	
6/1/10								C				year-continues-as-another-car-mysteriously-	
6/1/19							Fire while at hotal Community	С				catches-fire/news-	
	D 1 :						Fire while at hotel Supercharger and						
	Belgium		Antwerpen	Tesla	S		put in water tank		0	0	0	story/42f2a68a747cf3bd6c057c03acfbe2b0	
												http://enschede.1twente.nl/elektrische-auto-	
5/23/19							Car began to burn in showroom. Fire	P				ontploft-zomaar-in-enschede-staat-ons-dat-	
	Netherland		Enschede	BMW	i3	2018	department put in tank to extinguish.		0	0	0	vaker-te-wachten/content/item?1132863	
							third response to this vehicle on June						
							13. First fire was in a garage with 9						
							other collector vehicles; all of which						
							burned. Cause of original fire currently						
							undetermined. Vehicle moved to tow						
							yard June 4 and covered. Tow yard	ī					
							reported that insurance appraiser	1					
							examined vehicle June 13 and re-					Miami FD, Tow yard, insurance	
							covered it hours before it began to					representative plus www.sun-	
							smoke and was in flames when fire					sentinel.com/local/broward/fort-lauderdale/fl-	
							department arrived. After extinguishing					ne-luxury-cars-garage-fire-20190522-	
5/21/10	TICA		3.61	T. 1	37	2010			_	0	0		
5/21/19	USA	FL	Miami	Tesla	X	2018	it and departing, the vehicle caught fire Smoke and fire while parked. Took 2		0	0	0	tkwu3bxghbcthgmuem7usah3y4-story.html	
5/1/6/10							hours to extinguish. Firefighting took	D				insideevs.com/new/350022/nio-es8-fire-	
5/16/19	China		C11:	NI:-	ECO	2010		P	0	0	0	china/	
	China		Shanghai	Nio	ES8	2019	4 hours.		U	0	U	https://www.haz.de/Nachrichten/Der-	
5/16/19			Schleswig-				Fire was not extinguished until the car	n				Norden/Elektro-Autos-stellen-Feuerwehr-vor-	
5/16/19	Germany		Holstein	Mini	Hybrid			P	0	0	0	neue-Herausforderungen	
	Germany		1101810111	IVIIIII	Hybliu		was submerged in water.		U	U	U	incuc-i iciausioiuciungcii	
							vehicle into Park while launching						
							boat. Vehicle rolled into saltwater,						
5/15/19							towtruck pulled vehicle out, and then	A/D				https://bc.ctvnews.ca/i-m-so-lucky-	
					Outlander		it caught fire on ramp. Took hours to					boater-who-escaped-runaway-suv-with-	
	Canada	BC	Vancouver	Mitsubishi	PHEV	2019	extinguish.		0	0	0	scratches-admits-mistake-1.4427648	
	Cariatia	DC	v ancouver	TVITESGUISIII	1 1115 V	2017	venicle me started in a shopping mair		,	J	0	SCI ateries-aumitis-mistake-1.442/048	
							parking lot after being parked for 30						
							minutes, 3 explosions seen on CCTV						
5/12/19							footage. Took 45 minutes to	P					
							extinguish. Tesla subsequently pushed					https://hk.news.appledaily.com/local/daily/a	
	China		Hong Vone	Tesla	S85				0	0	0	rticle/20190514/20677780	
	China		Hong Kong	Tesla	383		thermal management software update. Parked and not plugged in at about		U	U	U	111016/20190314/20077/80	
							midnight when it was noticed smoking					www.thedrive.com/news/27823/another-tesla-	
5/3/19							in a garage. SFFD pulled car from	P				model-s-randomly catches-fire-in-san-	
	USA	CA	C E	т. 1			garage and doused flames.			0			
		CA	San Francisco	Tesla	S		garage and doused flames.		0	0	0	francisco-garage-report	

owItBrol	e.com						10/24/201	,			1	,
							10,2 1,201	PHASE BY:				
								Accident/Damaged,				
								During Operaton,				
								Charging,				
								Parked/Stationary,				
								Not the battery or no				
						YEAR		fire, Insufficient info				
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:
							Fire first noticed in trunk and	H HOM EV				
1/24/19							unknown if battery itself was involved	N				autonews.gasgoo.com/china news/70015883
	China		Shanghai	ByD	e5	2019	in half hour fire.			0	0	.html
•			·	-			impact damaged battery and front					
							bumper. Battery was not known to be					
							damaged and vehicle was waiting for					
/22/19								A/D				
							pickup by owner. Post fire inspection					
							found accident deformation to left rear			_	_	insideeves.com/news/347796/nio-es8-fire-
	China		Shanghai	Nio	ES8	2019	of battery casing. Video of unoccupied vehicle burning		0	0	0	crash/ https://jalopnik.com/surveillance-video-of-
/21/10							in parking garage. Adjacent Audi A6	D				tesla-exploding-in-shanghai-parki-
/21/19	Chi		Chan-l-:	Tesla	S			P	0	0	0	1834211204
	China		Shanghai	1 esta	3		was also destroyed.		U	U	U	https://pittsburgh.cbslocal.com/2019/04/17/
							Tesla engineer removed fuse from					
							battery pack prior to transport. On					monroeville-tesla-fire/ and
4/8/19							2/8/2019 car was unloaded at Fox	P				https://electrek.co/2019/04/18/tesla-fire-
			Monroeville				Chapel shop 3:30pm and caught fire at					investigation/ and
			and Fox				6:20pm.					https://pittsburgh.cbslocal.com/2019/02/08/f
	USA	PA	Chapel	Tesla	X		0.20рии		0	0	0	ox-chapel-sweet-water-lane-fire/
												https://www.brandweer.nl/brandweernederlan
3/25/19								P				d/nieuws/cases/accubrand-in-auto
23/19							Battery began to smoke in dealer lot.	Г				https://www.autoevolution.com/news/bmw-
							Car put in water tank to extinguish.					i8-catches-fire-in-the-netherlands-firefighters-
	Netherland		Tilburg	BMW	i8	2018			0	0	0	drop-it-in-water-container-133267.html
							Area of range extending gas engine					https://insideevs.com/news/337258/bmw-i3-
/19/19							appears to have burned out while	P				rex-burns-after-catching-fire-while-parked-in-
1,,1,	Spain			BMW	i3		parked.	-	0	0	0	spain/
	Брин			Bittit	15		puriou.		Ů	0	V	https://bc.ctvnews.ca/driver-dead-after-tesla-
18/19								A/D				crashes-into-pole-on-lougheed-highway-
10/19	C1-	BC	V	T1-	X		Standa liabta ala and annaht fina Dairea		,	1	0	1.4340542
	Canada	ВС	Vancouver	Tesla	Λ		Struck lightpole and caught fire. Driver Began to burn while charging.		1	1	U	ttps://www.upsbatterycenter.com/blog/beiqi-
					WeiWang		Reported to be third since January.					weiwang-407ev-catching-fire/ and
/11/10					_		1	C				
/11/19					407EV		May 10 report stated that State	С				ttps://www.upsbatterycenter.com/blog/beiqi-
	GI.		C.I.	.	delivery		investigation into the group of three					weiwang-407ev-catching-fire/ and
	China		Shenzen	Beiqi	van		attributed cause to the battery supplier		0	0	0	http://www.xinhuanet.com/english/2019-
							Reported to be second since January.					weiwang-407ev-catching-fire/ and
					WeiWang		May 10 report stated that State					ttps://www.upsbatterycenter.com/blog/beigi-
?/2019					407EV		investigation into the group of three	C				weiwang-407ev-catching-fire/ and
					delivery		attributed cause to the battery supplier					http://www.xinhuanet.com/english/2019-
	China		Shanzan	Beiqi	-		quality control.		0	0	0	07/12/c 138221297.htm
	Ciiina		Shenzen	Deiqi	van		i i		U	U	U	ttps://www.upsoutterycenter.com/orog/ociqi-
							Began to burn while charging.					weiwang-407ev-catching-fire/ and
					WeiWang		Reported to be first since January. May					ttps://www.upsbatterycenter.com/blog/beiqi-
?/2019					407EV		10 report stated that State investigation	С				weiwang-407ev-catching-fire/ and
					delivery		into the group of three attributed cause					http://www.xinhuanet.com/english/2019-
	China		Shenzen	Beiqi	van		to the battery supplier quality control.		0	0	0	07/12/c 138221297.htm
	China		2.112.112.011	25141	. 411		1		,	,		
							began in Tesla dealership. Building					
3/2/19							destroyed. Fire service believes fire	N				
-		West					began in store room and spread to					https://www.getsurrey.co.uk/news/uk-world-
					S, 3, X	2019			0	0	0	news/live-fire-crawley-tesla-smoke-15910986

lowItBrok	e.com	1			1	1	10/24/2019	,	1	ı	1	HowItBrok
							, ,	PHASE BY:				
								Accident/Damaged,				
								During Operaton,				
								Charging,				
								Parked/Stationary,				
						YEAR		Not the battery or no fire, Insufficient info	People			
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:
DATE	COUNTRI	SIAIL	CITT	WAKE	WODEL	WILC	DETAILS	II HOIH EV	IIIvoived	1 atai	nijuicu	https://www.burlingtonfreepress.com/story/n
2/24/2010							Burned while on Lake Champlain ice.	. 5				ews/local/2019/03/01/tesla-model-x-burned-
2/24/2019.							Owner believes he may have damaged	A/D				lake-champlain-what-next-steps-
	USA	VT	Burlington	Tesla	X	2019	the battery by hitting something.		0	0	0	fire/3026364002/
												https://www.detroitnews.com/story/business
2/24/19	TIC A	E	ъ.	T 1	G.		D 1 . C	A/D			0	/autos/2019/02/25/tesla-model-crash-
	USA	FL	Davie	Tesla	S		Post crash fire		1	1	0	florida/39112467/
2/18/19							Fatigued driver departed road and hit	A /D				sanfrancisco.cbslocal.com/2019/02/18/tesla-
2/10/19	USA	CA	Freemont	Tesla	X	2016	tree, exited vehicle before it began to burn. Firefighting took 3 hours.	A/D	1	0	1	model-x-crashes-burns-freemont/
	USA	CA	ricemont	16814	Λ	2010	Speeding vehicle departed road and		1	U	1	moder-x-crasnes-burns-neemont/
							struck tree then caught fire with three					patch.com/new-hampshire/milford-nh/3-nh-
12/26/18							occupants. Two suffered serious	A/D				teens-hurt-after-tesla-crashes-splits-half
							injuries and the third (19 year old) died					www.ledgertranscript.com/New-Ipswich-teen-
	USA	NH	Rindge	Tesla	X	2017	a month later of burn injuries.		3	1	2	passes-22902528
							shop and fire began while parked. First					
							fire response at 2pm, about 5 or 10					
							min after vehicle was dropped off from					https://sanfrancisco.cbslocal.com/2018/12/1
12/18/18							tow truck, then reignited while being	P				8/officials-investigate-mysterious-tesla-fire-
12/10/10							towed at 10:30pm. Total fire	Г				los-gatos/ and
							department involvement of 16 hours,					https://abcnews.go.com/Technology/tesla-
							using over 2,000 gallons.					opens-investigation-car-burst-flames-
	USA	CA	Los Gatos	Tesla	S				0	0	0	times/story?id=59930420
							#5 Postman left van to deliver					
							something and it was on fire when he					
							returned. Fire department could not put					
11/?/2018							fire out until putting van in container	P				
		~ .			Deutsche		of water. The fires were always from					
		Bad-		G	Post		the battery." and "The cause is highly					https://www.daserste.de/information/wirtsch
	C	Wurttem	C:	Streetscooter	delivery	2019	likely by the subcontractor not performed joint welds in the traction		0	0	0	aft-boerse/plusminus/sendung/risiko-
	Germany	burg	Singen	GmbH	van	2018	#4 Postman left van to deliver		U	0	U	elektroautos-100.html
							something and it was on fire when he					
							returned. Battery acid melted the shoes					
							of people on scene during fire fighting					
11/0/5015							and toxic vapors were encountered.					
11/?/2018							"The fires were always from the	P				
					Deutsche		battery." and "The cause is highly					
					Post		likely by the subcontractor not					https://www.daserste.de/information/wirtsch
		Saxony-		Streetscooter	delivery		performed joint welds in the traction					aft-boerse/plusminus/sendung/risiko-
	Germany	Anhalt	Teuchern	GmbH	van	2018	batteries." Three prior fires were in		0	0	0	elektroautos-100.html
0.006.330							Bus lost power and came to a stop in a					www.msn.com/en-us/video/d/battery-fault-
8/26/18	Ch:	Anhui	Tongling		D		tunnel then video shows the battery explode in a fireball.	О	,	0	0	causes-electric-bus-to-explode-in-chinese- tunnel/vp-BBMy64t
	China	Province	rongiing		Bus		ехрюче и а птеран.		3	0	U	
												https://electrek.co/2018/08/22/tesla-
							T	A/D				model-s-caught-fire-driving-highway/
0/20/10	TIC :			T. 1			Fire after hitting road debris per reports				_	and NJ State police report, press
8/22/18	USA	NJ		Tesla	S		from owner and NJ State police.		1	0	0	photos, and articles.
0/1/10	***							P	_		_	http://www.hani.co.kr/arti/english_edition/e
8/1/18	Korea		Daegu	Hyundai	Ioniq		Fire brgan in battery beneath trunk.		0	0	0	_business/912588.html

HowItBrok	e com						10/24/2019					How	vItBroke.com
TIOWILDION							10/24/2013	PHASE BY:				l low	VIEDIORE.COIII
								Accident/Damaged,					
								During Operaton,					
								Charging,					
								Parked/Stationary,					
								Not the battery or no					
						YEAR		fire, Insufficient info	People				
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:	
							Not attributed to vehicle. Parked in						
							garage when fire began in house	N				globalnews.ca/news/4327463/house-fire-west-	
7/12/18	Canada	BC	Kelowna	Tesla	S	2017	electric sytem.		0	0	0	kelowna/	
							Caught fire spontaneously (?) while in	О				https://www.businessinsider.com/ntsb-	
6/15/18	USA	CA	Los Angeles	Tesla	S		traffic on Santa Monica Blvd.	ŭ	1	0	0	releases-report-on-model-s-fire-2018-9	
								A/D				www.focus.de/auto/news/in-der-schweiz-	
			near Monte				Lost control on autobahn and car	100				deutscher-verunglueckt-toedlich-im-tesla-	
5/15/18	Switzerland	Ticino	Ceneri tunnel	Tesla	S		flipped over then burned.		1	1	0	feuerwehr-untersucht-akku id 8930883.html	
							NO fire. Crashed into back of fire					https://kutv.com/news/local/police-	
							truck. Police report and info obtained	N				investigate-tesla-model-s-crash-on-bangerter-	
5/11/18	USA	UT	South Jordan	Tesla	S		from tow company		1	0	1	highway	
		_										https://www.latimes.com/local/lanow/la-me-	
							Struck wall at high speed, opening	A/D				In-tesla-fire-20180617-story.html and	
							front of battery is where initial fire was	AD				https://electrek.co/2018/09/05/tesla-battery-	
5/8/18	USA	FL	Fort Lauderdale	Tesla	S		photographed.		3	2	1	fire-la-without-crash/	
					XC90 T8		Arson during charge captured by	N				https://www.driving.co.uk/news/fire-	
4/19/18	UK		Birmingham	Volvo	Hybrid	2017	CCTV	IN.	0	0	0	destroys-plug-hybrid-volvo-xc90-charging/	
							Collision at highway speed opened					https://www.ntsb.gov/news/press-	
							front of battery and damaged cells,	A/D					
	***						creating fire. Reignition well beyond					releases/Pages/nr20180607.asp	
3/23/18	USA	CA	Mountain View	Tesla	X		suggested 48 hour quarantine period.		1	l	0	X	
3/15/18					Panamera			С				https://www.bangkokpost.com/news/general	
	Thailand		Bangkok	Porsche	PHEV		Caught fire on home charger		0	0	0	/1429518/porsche-catches-fire-while-charging	
												https://www.torquenews.com/1/2-teslas-set-	
1/10/18							One of two Tesla arsons on street at	N				fire-amsterdam-within-few-hundred-feet-tesla-	
	Netherlands		Amsterdam	Tesla	S		4:30 am		0	0	0	haters	
								_				https://www.torquenews.com/1/2-teslas-set-	
1/10/18							One of two Tesla arsons on street at	N				fire-amsterdam-within-few-hundred-feet-tesla-	
	Netherlands		Amsterdam	Tesla	S		4:30 am Initiation unknown. Reported as fire		0	0	0	haters	
							with high voltage battery. After nine						
							fire groups responded over two hours,	D				www.waz-	
							the car was placed in container of	P				online.de/Gifhorn/Sassenburg/Feuerwehr-	
12/7/17	Germany		Triangel	VW	eGolf		water. Fire led to recall of model.		0	0	0	loescht-brennenden-E-Golf	
14//1/	Gamany		THAIIgG	v VV	COOII		Collision with concrete barrier at		U	U	U	www.ff-landeck.at/cms/index.php/83-	
							highway speed. The 35 firefighters					aktuelle-beitrage-blog/einsatze/532-2017-	
							with 5 trucks were unable to	A/D				brand-eines-elektrofahrzeuges-auf-der-	
10/18/17	Austria	Tirol	Landeck	Tesla	S		extinguish until cut-loop was severed.		1	0	0	s16.html	
					† Ť		Departed road at high speed and struck		<u> </u>				
							house. In addition to injuries of driver	A /D				https://www.ntsb.gov/investigations/Accide	
							and passenger, tow truck operator had	A/D				ntReports/Pages/HWY18FH014-	
8/25/17	USA	CA	Lake Forest	Tesla	X		minor burns.		2	0	3	preliminary.aspx	
							Chicago Transit bus caught fire on					09/DSC06321.png.c4b395ab99f1b8191216	
							Route 52. Bus #700. Unknown	T				c14701651d5d.png and	
					electric		component burned beneath bus where	1				https://chitransit.org/topic/153-the-	
8/16/17	USA	IL	Chicago		bus		battery and motor are located.					breakdown-thread/?page=15	
0.10/1/	5571		- Cinougo		Cub		una motor are roomea.		L	1	1		

lowItBrok	e.com				1		10/24/201	9	1		ı	H owItBr
							1, , ,	PHASE BY:				
								Accident/Damaged,				
								During Operaton,				
								Charging,				
								Parked/Stationary,				
								Not the battery or no				
						YEAR		fire, Insufficient info	People			
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:
								II Hom E v			,	https://www.thesun.co.uk/motors/3983899/s
												mart-fortwo-electric-car-totally-destroyed-and-
					ForTwo		Charging next to office when it began	С				left-gutted-by-flames-after-it-set-on-fire-while-
7/9/17	UK	Essex	Wickford	Smart	Electric	2017	to burn from bottom.		0	0	0	charging-outside-office/
1/9/1/	UK	LSSCA	WICKIOIU	Siliait	Electric	2017	Fire in parking garage with smoke		U	U	U	charging-outside-office/
												144 - 7/1 - 4
							injury to one person. Fire could not be					https://boostyourcity.de/elektroauto-renault-
			Mainz-				stopped until car was submerged in					twizy-in-mainzer-tiefgarage-ausgebrannt-eine-
6/17/19	Germany		Laubenheim	Renault	Twizy		water. Fire test, found that car would not		0	0	1	person-verletzt
		NT 1					easily ignite upon crushing, but when					
		Nedre						. —				
		Romerik					pierced battery, fire initiated and was	A/D				
		e (test)				• • • •	difficult to put out, fire consumed car.					
5/30/17	Norway			BMW	i3	2017	Source: video and letter from the FD		0	0	0	Report from Norwegian test institute
												https://carnewschina.com/2017/08/09/visitin
				Anhui Ankai			Charging station fire destroyed 55	С				g-scene-may-1-beijing-ev-bus-charging-
5/1/17	China		Beijing	Automobile	City bus		busses and damaged 20.		0	0	0	station-fire/
							Caught fire while stationary after					
							disconnection from supercharger. Fire					
							burned adjacent Tesla Model S. Tesla	С				https://www.chinamoneynetwork.com/2017/
							attributed initiaion to voltage					03/06/tesla-model-s-caught-on-fire-at-
3/4/17	China		Shanghai	Tesla	S P85		instability when first vehicle had been Accident and fire on highway left rear		0	0	0	supercharger-station-in-shanghai
							doors inoperative. Rear seat passengers	A/D				1
							escaped through front doors with	100				https://electrek.co/2017/04/23/tesla-model-x-
2/?/2017	China		Guangzhou	Tesla	X		injuries.		3	0	3	fire-crash-falcon-wing-doors-stuck/
												https://www.washingtonpost.com/cars/tesla-
												irvine-fire-dept-disagree-over-cause-of-garage-
							Fire appears to have begun at wall end	С				fire/2016/10/12/2dba9ef4-90b6-11e6-bc00-
							of charging cable while car was in					1a9756d4111b story.html?utm term=.53fd
11/15/16	USA	CA	Tomaino a	T1-	S				0	0	0	
1/15/16	USA	CA	Irvine	Tesla	5		garage being charged.		U	0	0	8d2da53a
							Struck tree, breached battery, and cells					
							caught fire rapidly. Driver death	A/D				www.indystar.com/story/news/crime/2017/0
							attributed to smoke inhalation and					2/08/tesla-model-s-crash-investigation-
11/3/16	USA	Indiana	Indianapolis	Tesla	S	2015	burns.		2	2	0	drunken-driving-indianapolis/97597708/
							battery. Burned while unoccupied and					
							not charging. Tesla attributed cause to					
							minor accident two months prior.					
								A/D				
							Owner claims only the bumper and					
							hood had been damaged in 10 mph					https://electrek.co/2017/03/31/tesla-model-s-
10/8/16	UK		Yorkshire	Tesla	S 70		collision.		0	0	0	fire-manchester-crash/
												www.fredericknewspost.com/news/politics_a
												nd_government/levels_of_government/count
							Failure of an improperly manufactured	О				y/report-confirms-sensor-failure-caused-
				Complete	TransIT		electrical connection cause fire.					electric-bus-fire/article 7689d9d5-7ded-5586-
9/27/16	USA	MD	Frederick	Coach Works	Bus		Software prevented alarm		1	0	0	b6d9-b2b2519ca568.html
-							Durined after 70 mph comision with					
							tree and battery breached. Firefighters					
							had trouble putting it out. Due to	A/D				https://metro.co.uk/2016/09/08/tesla-
							concern about electrocution, body of					investigating-fatal-crash-involving-self-
9/7/16	Netherland		Baarn	Tesla	S		victim remained in car for hours.		1	1	0	driving-car-in-holland-6117031/

lowItBrok	e.com		ı				10/24/2019	PHASE BY:				T H owli
								Accident/Damaged,				
								During Operaton,				
								Charging,				
								Parked/Stationary,				
								Not the battery or no				
						YEAR		fire, Insufficient info	People			
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:
							Caught fire spontaneously during					
							promotional tour. Tesla reported that a	О				
							loose bolted battery connection from	O				www.teslarati.com/tesla-model-s-fire-france-
8/13/16	France	Bayonne	Biarritz	Tesla	S 90D	2016	an assembly error was found.		3	0	0	test-drive/ www.autoevorution.com/news/omw-13-
												police-car-catches-fire-in-rome-bad-news-for-
							D 'II d IGE (1					1
							Possibly was the ICE range extender.	О				the-lapd-109367.html and
							Police vehicle fire began spontaneously					www.motor1.com/news/65205/the-roman-
7/12/16	Italy	D 1	Rome	BMW	i3		and could not be extinguished.		2	0	0	polices-bmw-i3-goes-up-in-smoke/
		Pudong					Plug-in hybrid caught fire while					
		New			_		driving. BYD claimed source was an	О				http://www.autonewschina.com/en/article.as
5/14/16	China	District	Shanghai	BYD	Tang		owner modification to the car.		1	0	0	p?id=14904
												https://www.thedrive.com/news/28420/parke
							Tesla connected to Supercharger began	С				d-teslas-keep-catching-on-fire-randomly-and-
6/8/16	Norway		Oslo	Tesla	S	2016	to burn. Firefighters used foam.		0	0	0	theres-no-recall-in-sight www.businesskorea.co.kr/news/articleView.
							Dowland washings had an artist					
							Parked vehicle had spontaneous	P				html?idxno-15135 and
							combustion attributable to high	1				http://www.autonewschina.com/en/article.as
6/?/2016	China		Beijing	JAC	iEV5	2016	temperature		0	0	0	p?id=14904
							Collision with truck led to fire. Driver	A/D				http://www.autonewschina.com/en/article.as
2/18/16	China		Fuzhou	BYD	Qin		was alive and could not be extricated.	TUD	1	1	0	p?id=14904
							Fire began while driving with 3-4					http://www.hani.co.kr/arti/english_edition/e
		Gyeongg					small explosions. One report relates	I				business/912588.html and
1/15/16	S.Korea	i	Gwangju	Renault	SM3.Z.E	2013	cause not believed in battery		1	0	1	http://www.ipnomics.net/?p=14858
							Caught fire while charging. Tesla					
							reported fire originated in distribution	С				www.teslarati.com/tesla-short-circuit-cause-
1/1/16	Norway		Gjerstad	Tesla	S	2015	box of vehicle, not in battery case.		0	0	0	for-model-s-norway-norway-fire/
	Ĭ		,									-
							Car got stuck at rail crossing, driver					<u>full-fyr-etter-togkrasj-jeg-matte-bare-lope-</u>
							exited, and car was severely damaged					vekk/s/5-59-326762 and
							when hit by train carrying 189	A/D				https://insideevs.com/news/326262/train-
			Fredrikstad				passengers. Extensive fire happened					collides-with-volkswagen-e-up-explosion-fire-
12/15/15	Norway		Raadesletta	VW	e-Up!		after when about to recover the car.		190	0	0	follows-w-video/
-					1							https://www.wmcactionnews5.com/st
					II.,.L		Unayer if origin was better	I				ory/26718503/out-of-service-mata-bus-
10/5/15	IIC A	TNI	M1:	Cilli	Hybrid		Unsure if origin was battery or	1		0	0	
10/5/15	USA	TN	Memphis	Gillig	Bus		wheel/tire.		0	0	0	catches-fire/
							"The driver pulled over after hearing a					
							strange sound coming from the back of					
							the vehicle, according to the local bus					
							group.					
							Nine people were injured by broken	О				
							glasses as they escaped the bus, they					
							were taken to hospital." Fire					
							department called at 7:04pm and fire					
							extinguished at 7:22 pm.					
9/17/15	Chin-	7haiian -	Honorb		Bus		http://www.globaltimes.cn/content/942			0	9	www.globaltimes.cn/content/942964.shtml
7/1//13	China	Zhejiang	Hangzhou		BUS		ittp://www.giobattimes.cn/content/942			U	9	
610.515.5	****		** .				,	О	,_			https://order-order.com/2015/06/25/huge-
6/25/15	UK		York		Bus		Fire began while in service.		12	0	0	electric-bus-fire-in-york/
							Went off cliff, damaged battery on					www.dailynews.com/2015/06/23/man-who-
							rocks, then caught fire. Ignited grass	A/D				died-in-fiery-malibu-crash-of-tesla-is-53-year-
6/22/15	USA	CA	Malibu Canyon	Tesla	S	2013	fire which burned for nine hours.		1 1	1 1	0	old-from-calabasas/

HowItBrok	e.com						10/24/2019	2				HowItBro
							10,2 1,201	PHASE BY:				
								Accident/Damaged,				
								During Operaton,				
								Charging,				
								Parked/Stationary,				
						MEAD		Not the battery or no	D 1			
D. I TE	COLDIEDI	CT LTE	CYTTY	3.6.177	MODEL	YEAR	DET LES	fire, Insufficient info	_			
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	MFG	DETAILS	if from EV	involved	Fatal	Injured	Sources:
								3.7				https://sanfrancisco.cbslocal.com/2015/06/1
6/0/15	TIC A	G.4	N T (CI I	37.1.	2015	Four Chevrolet Volts set on fire by	N	0	0	0	1/46-year-old-man-arrested-on-suspicion-of-
6/9/15	USA	CA	Novato	Chevrolet	Volt	2015	arson		0	0	0	arson-at-car-dealership/
							Detterm over investment in a first of the					
							Battery was involved in a fire at the					
							factory. An accident investigator	P				
				7 T I.	C 1		determined fire began in pack of cells					144 - 1/2
10/26/14	TICA	C A	C A	Zero Truck	Google	2014	from Chinese supplier Xalt. Several		0	0	0	https://ww2.energy.ca.gov/2019publications /CEC-600-2019-023/CEC-600-2019-023.pdf
10/26/14	USA	CA	Santa Ana	Corp	truck	2014	potential failure modes were identified.		0	0	0	
			W/				Car stolen from dealer struck light	A /D				www.nbclosangeles.com/news/local/Stolen-
7/4/14	TIC A	CA	West	т. 1	C	2014	pole, split, caught fire. Driver and two police injured.	A/D	,	0	2	Tesla-High-Speed-Chase-Fiery-Crash-in- West-Hollywood-265813821.html
7/4/14	USA	CA	Hollywood	Tesla	S	2014	1 3		1	0	3	
							Not caused by primary battery. Driver reported fire started beneath dash. No					owner: www.mynissanleaf.com/viewtopic.php?f=15
							*					&t=20476&sid=df33b8cede8cfcd036fa7986
							known primary battery fires, other than	N				
							in testing at U of MD. Following					6bc96682&start=10 press:
2/1/14	TICA	TV	El M 1	NU	T C		2011 tsunami, no Leaf batteries have		١,	0	0	https://insideevs.com/news/326403/nissan-
2/1/14	USA	TX	Flower Mound	Nissan	Leaf		caught fire.		1	0	0	leaf-fire-in-flower-mound-texas/
												https://leftlanenews.com/tesla/model-s/tesla-
								N				investigates-model-s-garage-fire-in-toronto/
								N				and https://driving.ca/tesla/auto-
2/1/14	G 1		Т	T . 1	C		A		0	0	0	news/news/tesla-investigating-cause-of-
2/1/14	Canada		Toronto	Tesla	S		Arson in garage		0	0	0	toronto-garage-fire-with-model-s
11/6/13	USA	TN	C	T . 1	C	2012	Collision with road debris (tow hitch) on highway	A/D	,	0	0	https://www.businessinsider.com/third-tesla- model-s-catches-fire-2013-11
11/0/13	USA	IIN	Smyrna	Tesla	S	2013	Collided with road debris. Firefighters		1	0	0	model-s-catches-fire-2013-11
							reportedly used a saw to access battery					
							interior to apply water which was	A/D				https://www.seattletimes.com/business/tesla-
10/1/13	USA	WA	Seattle	Tesla	S		successful.		1	0	0	says-car-fire-began-in-battery-after-crash/
							Crashed into concrete wall and hit tree.			-	-	3
							Reported top speed of 115 mph and	A/D				https://business.financialpost.com/transporta
10/18/13	Mexico	Yucatan	Merida	Tesla	S	2013	alcohol involvement.		1	0	0	tion/tesla-fire-crash-mexico
							Struck by train, caught fire a few hours					
							later during investigation of the crash.	A/D				
8/1/13	Norway		Ostfold	Nissan	Leaf		Source: Norwegian AIB report		0	0	0	
	ĺ						1					1
							after standing for one day.	A/D				http://www.myelectriccarforums.com/mitsub
2/21/12			**		Outlander		Investigation found some batteries had	TVD				ishi-outlander-phev-production-restarts-after-
3/21/13	Japan		Yokohama	Mitsubishi	PHEV		been dropped in production.		0	0	0	5-months/
2/16/12							GS-Yuasa battery caught fire while	С				https://www.greencarcongress.com/2013/03/
3/18/13	Japan		Mizushima	Mitsubishi	i-MiEV		connected to charger at factory.		0	0	0	mmc-20130327.html
							Karmas caught fire, attributed fires to					
							saltwater reaching electrical	P				
							components. Fisker stated that the 12V	r				https://www.businessinsider.com/why-fisker-
10/29/12	USA	NJ	Newark	Fisker	Karma	2012			0	0	0	karmas-burned-during-sandy-2012-11
	-311	- 10					battery burned not the HV battery.				Ť	
							Prius PHEV caught fire and two					
1							smoked which Toyota attributed to	P				https://www.autoguide.com/auto-
							saltwater reaching electrical					news/2012/11/toyota-prius-burns-after-being-
10/29/12	USA	NJ	Newark	Toyota	Prius	2012	components.		0	0	0	flooded-by-sandy.html

HowItBrok	e.com	1	T T		ı		10/24/2019					HowItB	tBroke.com
DATE	COUNTRY	STATE	СІТҮ	MAKE	MODEL	YEAR MFG	DETAILS	PHASE BY: Accident/Damaged, During Operaton, Charging, Parked/Stationary, Not the battery or no fire, Insufficient info if from EV	People involved	Fatal	Injured	Sources:	
9/1/12	USA	STATE	CHT	Dodge	RAM	WII G	overheated in test program, followed by Chrysler suspending the program. Also withdrawn were 23 Chrysler Town & Country plug-in hybrids.	I I I I I I I I I I I I I I I I I I I	0	0	0	https://www.greencarreports.com/news/1079 368_chrysler-yanks-plug-in-hybrid-test-fleet- off-roads-will-replace-batteries	
9/1/12	USA	WI		Chevrolet	Volt	2011	Side impact crash test was 5/12/2013. Vehicle rolled to check for leakage then stored. Caught fire 6/5/2011	A/D	0	0	0	NHTSA Report DOT HS 811 573 and press reports with photos plus www.autoblog.com/2011/11/11/chevy-volt-battery-catches-fire-in-nhtsa-lab/ and https://greentransportation.info/ev-ownership/safer/chevy-volt-battery-pack-fire-2011.html	
8/10/12	USA	CA	Woodside	Fisker	Karma		Owner went into store and car began to burn in parking lot. Car had both battery and ICE.	I	0	0	0	https://www.greencarreports.com/news/1078 412_second-fisker-karma-fire-casts-fresh-doubt-on-plug-in-hybrid	
5/26/12	China		Shenzhen	BYD	e6 taxi	2012	After a Nissan GTR crashed into the back of a BYD e6 taxi in Shenzhen and the electric taxi caught fire, killing all three taxi occupants. The Chinese investigative team concluded that the cause of the fire was that "electric arcs caused by the short-circuiting of high voltage lines of the high voltage distribution box ignited combustible material in the vehicle including the interior materials and part of the power batteries." The team also noted that the battery pack did not explode; 75% of the single cell batteries did not catch fire; and no flaws in the safety design	A/D	3	3	0	https://af.reuters.com/article/commoditiesNe ws/idAFL2E8J33CB20120803 and www.shenzhenparty.com/byd-electric-taxi- explosion-fire	
5/3/12	USA	Texas	Houston Sugar Land	Fisker	Karma		Unoccupied vehicle in garage was not plugged in and battery functioned after the fire.	N	0	0	0	https://www.houstonchronicle.com/business/article/Fisker-fire-leads-to-federal-inquiry-3570347.php and https://www.reuters.com/article/karma-houston/fisker-karma-battery-did-not-cause-houston-fire-idUSL1E8G8FNS20120508	
2/8/12	USA	PA	Allentown	Zero Truck Corp	Hybrid truck	2012	24 cell 400 volt lithium battery pack caught fire twice	P	0	0	0	https://www.mcall.com/news/mc-xpm-2012- 02-08-mc-allentown-electric-truck-fire- 20120208-story.html	
7/18/11	China		Shanghai	Shanghai Leibo	City bus	2011	Capacitor bus fire while in service	O				fire-idAFL3E7IK0LB20110720 and www.autoblog.com/2011/07/22/report-electric-bus-catches-fire-in-shanghai/	
4/14/11	USA	CT	Barkhamsted	Chevrolet	Volt	2011	Flammable material in garage destroyed car according to fire official and vehicle owner. Re-ignited spontaneously 5 days later	N	0	0	0	ownership/safer/chevy-volt-battery-pack-fire- 2011.html and https://gm- volt.com/2011/05/18/exclusive-chevrolet- volt-unofficially-cleared-in-connecticut- garage-fire/ and https://www.thetruthaboutcars.com/2011/04/ gm-to-investigate-volt-blaze-re-ignition/	

HowItBrok	e.com					_	10/24/2019	9					HowItBroke.com
							13,21,231	PHASE BY:					
			[1		Accident/Damaged,	Ì				
			[1		During Operaton,	Ì				
			[1		Charging,	Ì				
								Parked/Stationary,					
						YEAR		Not the battery or no					
DATE	COUNTRY	STATE	CITY	MAKE	MODEL		DETAILS	fire, Insufficient info	People involved	Fatal	Injured	Sources	
DATE	COUNTRY	SIAIE	CILI	IVIANE	MODEL	MFG	DETAILS raxi nie attributed to defective battery	if from EV	invoived	гана	mjurea	Sources.	\dashv
							pack assembly and production quality						
					M300EV		control. Cell construction not found at	О					
				_	Lanyue		fault. Driver and passenger able to exit					chinaautoweb.com/2011/06/battery-pack-	
4/11/11	China		Hangzhou	Zotye	EV	2011	vehicle. Converted vehicle was charging on car		2	0	0	defects-blamed-for-zotye-ev-fire/	\dashv
							ferry Pearl of Scandinavia when fire		No.				
							began in battery pack. Owner was		No.			Danish Fire Report IU10676 by Thomas	
					Qashqai		company owner who was returning	С	No.			Balleby, dated 2011-03-09. Press photos	
				A Future EV	conversio		from obtaining production approval.		No.			and articles, including owner report:	
11/17/10	Denmark		Copenhagen	(Nissan)	n	2010	The company name was A Future EV		0	0	0	soerenekelund.dk/oslo-ferry-fire-2010/	
Copart nat	ionwide sear	ches of 6/	21/2019 from a	a total of 152,	035 vehic	les in 2011	-2019 model years						
											_		
		Burns of				Burned							
		all types				percent					ļ		
		(Interio				of							
			Burned	Hybrid or	Burned	hybrid/							
				electric									
					hybrid /	battery							
Acura	Total Count 371	overall) 5	overall fleet 1.3	count 4	electric 0	fleet 0.0		+		 	 		\dashv
BMW	1466	27				1.9				 	 		
Cadillac	590	6						†	 		 		\dashv
Infinity	677	7						 	 	 	 		-
Jaguar	121	1	0.8					 	 	 	 		-
Lexus	822	5				0.8		 	 	\vdash	 		-
Mercedes	022	3	0.0	122		0.8		+	 	 	 		\dashv
	1267	10	1.2	_		0.0							
Benz	1367	16	1.2	5	0	0.0	1	+	-	 	 		-
Tesla							1						
(Note 1)	141	1	0.7	141	1	0.7	<u> </u>	1	1	1	1		4
Toyota							1		Ì				
Prius (all													
versions)	679	5	0.7	679	5	0.7		<u></u>		<u> </u>			_
Volvo							1		Ì				
(Note 2)	283	5											_
Overall	6517	78	1.2	1018	9	0.9							
All hybrid													
and							1		Ì				
electric							1		Ì				
cars				1018	19	1.9							
Natar				1010	15	1.5	ļ	+	 	 		 	-

Notes:

HowItBrok	e.com		T	T			10/24/201	9	T				HowItBroke.com
DATE	COUNTRY	STATE	CITY	MAKE	MODEL	YEAR MFG	DETAILS	PHASE BY: Accident/Damaged, During Operaton, Charging, Parked/Stationary, Not the battery or no fire, Insufficient info if from EV	People involved	Fatal	Injured		
1) Does													
not													
include Miami													
Copart													
Model X													
being held for													
insurance													
2)													
Deleted													
dueto													
skewing effect													
single													
digit has													
on all other													
data, plus													
fire was													
the													
vehicle interior													
		Hybrid											
		or Flectric	Hybrid/Elect Percent of										
		Count	Fleet										
Acura	371	4	1.1										
BMW	1466	54											4
Cadillac Infinity	590 677		0.2 1.3										+
Jaguar	121	1	0.8										1
Lexus	822	122	14.8										
Mercedes	125-	_											
Benz Tesla	1367	5	0.4										+
(100%)	141	141											
Toyota													
Prius	6=2	670											
(100%) Volvo	679 283	679 2											+
Overall	6517	1018											1
									•	1	1	j.	