PROPERTY INSPECTION REPORT



onald D&Angelo Certification#263416

Big Bear Home Inspectors

436 Dorset Drive

Inspection Prepared For: Angel Fuerte

Agent: Rose Holmstrom - Re/Max Big Bear Village

Date of Inspection: 10/30/2020

Age of House: Built in 1983. 37 Yrs.old Size: 1,616 SqFt.

Weather: Clear & Cool

Report Introduction

We appreciate the opportunity to conduct this inspection for you! Please carefully read your entire Inspection Report. Call us after you have reviewed your report if you have any questions. Remember, when the inspection is completed and the report is delivered, we are still available for any questions you may have.

Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure; inspection may be limited by vegetation and possessions. Depending upon the age of the property, some items like GFCI outlets may not be installed; this report will focus on safety and function, not current code. This report identifies specific non-code, non-cosmetic concerns that the inspector feels may need further investigation or repair.

For your safety and liability purposes, we recommend that licensed contractors evaluate and repair any critical concerns and defects. Note that this report is a snapshot in time. We recommend that you or your representative carry out a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

Video In Your Report –The inspector may have included videos of issues within the report. If you are opening the PDF version of the report make sure you are viewing the PDF in the free Adobe Reader PDF program. If you're viewing the report as a web page the videos will play in any browser. Click on any video within the report to start playing.

Throughout the report we utilize icons to make things easier to find and read. Use the legend below to understand each rating icon.



Acceptable – This item was inspected and is in acceptable condition for it's age and use.



Repair/Replace - Items with this rating should be examined by a professional and be repaired or replaced.



Safety Issue - Items with this rating should be examined immediately and fixed. Even though the item is marked as a safety issue it could be a very inexpensive fix. Please make sure to read the narrative to completely understand the issue.



Monitor - Items with this rating should be monitored periodically to ensure that the issue hasn't become worse, warranting a repair or replacement.



Not Accessible - Items with this rating were not able to be fully inspected because access was blocked off or covered.

Our report contains a unique pop-up glossary feature. When you see words highlighted in yellow hover your mouse over the term. The definition or a tip about the item will appear!



Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

There are 3 Colors used in this summary with there meanings:

Green--Client can do work on their own.

Blue--Client and I both are aware of the issue. This is not a serious issue but should be resolved when possible

Red--Client should have a professional involved with this issue and should be addressed as soon as possible

Interior Areas		
Page 14 Item: 5	Smoke Detectors	• Smoke detector missing in the Hallway. Replace with a New Hard Wired One



Hallway--No Smoke Detector. Needs new one

Bedrooms					
Page 18 Item: 8	Smoke Detectors	 **Smoke Detectors** There were no smoke detectors present in the bedrooms 			
Bathroom					
Page 21 Item: 5	Floor Condition	 Bathroom#2Damaged grout observed, suggest re-grouting as necessary. Bathroom#2Recommend sealing cracks/voids. Bathroom#2Recommend caulking at the tub and shower areas 			



Bathroom#2 Caulking Needed

Page 22 Item: 11 GFCI

• GFC is Looking pretty Old in the Master Bathroom. This could be why Bathroom#2 is not protected. As of 1975 all bathrooms should be GFCI protected. So either the Master Bathroom is going bad or another needs to be installed in Bathroom#2

 Bathroom#2--No GFCI protection present, suggest installing GFCI protected receptacles for safety.



Bathroom#2 not Protected



Master Bathroom--Kind of old Might want to replace

Page 23 Item: 16 Shower Walls

- Caulking needed around perimeter.
- Missing/damaged grout observed, suggest regrouting as necessary.



Bsthroom#2



Bathroom#2

Kitchen

Page 30 Item: 15 Floor Condition

Numerous cracked tiles noted.



Cracks in the Kitchen Tile Flooring

Heat/AC

Page 37 Item: 9
Thermostats

• Thermostat only turns unit On & Off and is not being controlled by the temperature at all. Walked into a very warm house. Turned down still would not go off had to physically Turn off the Unit for it to go Off. Thermostat needs to be

replaced to work correctly.



This is Bad it needs to be replaced it only turns On & Off and does not function correctly with temperature.

Garage

Page 38 Item: 1 Roof Condition

Clean roof areas: Significant amounts of organic debris



South Side

Page 38 Item: 4 Floor Condition • Common cracks noted.



Crack in the Garage Flooring

Page 40 Item: 10 Fire Door

 The automatic closure device does not close the door properly. This could allow a fire to enter the home. Recommend adjusting or replacing the hinges to allow for proper closure of the door.



Does not close completely.

Page 41 Item: 13 Garage Opener Status

- There appears to be an older model garage door opener without safety features.
- Garage Door only goes up about 4 inches and stops motor still trying but stops. Cannot figure out what was holding it up. Either door in tracks has issue or older door opener just cannot do it anymore.



Something is wrong with Garage Door Opener. Either it is too old to do the job anymore or, Something is wrong in the Tracks or wheels because it stops after about 6 inches.

Page 42 Item: 15 Stairs & Handrails

Condition

- Handrail is a Little Loose
- Landing Area may not be tall enough to need a railing. Recommend placing one along the yellow line just for the safety factor of someone falling off.



Not Actually required but recommend railing around the Landing Deck

lectri	

Page 44 Item: 4 Cable Feeds

 When utility company wires coming into the service mast are sagging, frayed, strung through trees, or otherwise appear improper, the client is advised to contact the utility company prior to closing to correct the condition or verify its safety.



Tree interfering with drop Line.

Roof

Page 45 Item: 1

Roof Condition

· Clean roof areas: Significant amounts of organic debris evident.



East Side



East Side

Page 46 Item: 6

Gutter

Clean gutters: Significant amounts of debris evident.Extensions / Splash blocks missing or insufficient: Install to divert water away from the foundation.



Gutters are filled with Pine Needles. These should be cleared.



Northeast Corner



Southeast Corner--Monitor the area and see if water builds up here at the Foundation wall, if it does need to make it move along as too not continually soak the Foundation Wall



South Side

Exterior Areas

Page 49 Item: 2

Window Condition

• Peeling paint observed, suggest scraping and painting as necessary.



South Side--Peeling Paint & Bare Wood Observed

Page 49 Item: 3

Siding Condition

- Caulk and seal all gaps, cracks and openings.
- Some siding deterioration noted. Have repaired as necessary.
- Brick Veneer Top Concrete Pour is cracked the entire Length along the Garage North Wall




Cracked across the top of the brick veneer



Garage North Wall--Wood Pecker Activity



East Side by Rear Door



South Side--More Wood Pecker Activity

Foundation

Page 51 Item: 3 Foundation Walls

• Efflorescence observed; this is a mineral deposit left behind from exterior water infiltration.



Efflorescence Observed

Page 51 Item: 4

Cripple Walls

• Big Crack in the Stem Wall. Recommend further evaluation by a handyman or General Contractor for Answers & Options to this Issue.




Big Crack in the Stem Wall

Grounds

Page 56 Item: 3

Driveway and

- Minor settlement, or "hairline" cracks in driveways, are Walkway Condition normal for properties of any age. They should, however, be monitored for expansion and sealed as necessary.
 - Concrete spalling noted at driveway. This loosening of the top, smooth layer of the cement is a common occurrence, possibly due to an improper curing process, age, or use of snow-melting materials.
 - Potential Trip Hazard(s) at driveway; monitor / repair as necessarv



Spalling on the Driveway



Possible tripping hazard going in garage

Page	57	Item:	5
------	----	-------	---

Vegetation Observations

- Prune or remove any plants that are in contact or proximity to home to eliminate pathways of wood destroying insects.
- Tree limbs within 10 feet of roof should be trimmed away to provide air and sunlight to roof, while minimizing debris & dampness.
- Trim trees that are in contact or proximity to home, as branches can abrade roofing or siding.
- Tree branches overhanging roof and/or against siding. Trim trees that are in contact or proximity to home, as branches can abrade siding and damage roofing.
- Trees that grow too close, or overhang property, should be trimmed back. This will help reduce the frequency of having to clean out the gutters, which should be done on a regular basis.







South Side

Page 58 Item: 7 Patio and Porch Deck

Deck Railing is Loose



Railing Loose



Rear Deck Railing is Loose

Page 58 Item: 8 Stairs & Handrail

Handrails are loose



Handrail is Loose



Rear Deck Both Handrails

Page 61 Item: 17 Fence Condition

- RETAINING/GARDEN WALL
- Retaining wall is leaning.
 Damaged/ missing mortar observed, suggest tuckpointing as necessary.
- Recommend review by a qualified professional for repair or replacement, as necessary.



Back Yard--Brick Garden Wall next to Walkway Crack in the Wall



Rear Yard Major Crack in the Stone Veneer



1. Attendance

In Attendance: Client present • Buyer Agent present

2. Home Type

Home Type: GARAGE: • Attached • HOME STYLE: • Single Family Home

3. Occupancy

Occupancy: Vacant • The utilities were on at the time of inspection.



Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. General Picture Condition



Observations:

No Apparent Issues with the General Picture



Living Room



Hallway

2. Ceiling Fans



Observations:

• Operated normally when tested, at time of inspection.



3. Closets



Observations:

• The closet is in serviceable condition.



Living Room

4. Electrical



Observations:

• No Apparent Issues with the Electrical

5. Smoke Detectors



Observations:

- **SMOKE DETECTORS**
- Smoke detector missing in the Hallway. Replace with a New Hard Wired One



Hallway--No Smoke Detector. Needs new one

6. CO₂ Detector Condition



Observations:

No Apparent Issues with the Interior CO2 Detector(s)



Hallway

7. Flooring Condition



Materials: Carpet Observations:

No Apparent Issues with the Interior Flooring



Living Room

8. Ceiling Condition



Materials: There are drywall ceilings noted. • Open beam ceiling construction noted. Observations:

No Apparent Issues with the Ceilings

9. Patio Doors



Observations:

- **Hinged Patio Doors**
- Functioned Correctly at the time of the Inspection



Dining Are

10. Screen Doors



11. Wall Condition



Materials: Drywall walls noted.

Observations:

· No Apparent Issues with the Walls

12. Fireplace



Materials: Living Room

Materials: Masonry fireplace noted.

Observations:

- **Wood Fireplaces**
- Damper was opened and closed several times.
- Functional.







Gas Log Lighter Assist System--Gas Valve & Key

13. Window Condition



Materials: Aluminum framed sliding window noted. • Wood framed fixed window noted. Observations:
• No Apparent Issues with the windows.



Living Room



The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

1. Locations

Locations: MAIN FLOOR: • Master Bedroom#1 • Bedroom#2 • Bedroom#3

2. General Pictures Condition



Observations:

No Apparent Issues in General







Bedroom#3



Master Bedroom

3. Ceiling Fans



Observations:

• Operated normally when tested, at time of inspection.



Master Bedroom

4. Closets



Observations:

• The closet is in serviceable condition.



Bedroo.#2

5. Doors



Observations:

No Apparent Issues with the Doors



Bedroom#2

6. Electrical



Observations:

No Apparent Issues with the Electrical

7. Floor Condition



Flooring Types: Carpet is noted. Observations:

· No Apparent Issues with the Flooring

8. Smoke Detectors



Observations:

- **Smoke Detectors**
- There were no smoke detectors present in the bedrooms

9. Wall Condition



Materials: Drywall walls noted.

Observations:

No Apparent Issues with the Walls

10. Window Condition



Materials: Aluminum framed sliding window noted.

Observations:

No apparent Issues with the Windows

11. Ceiling Condition



Materials: There are drywall ceilings noted. Observations:
• No Apparent Issues with the Ceilings



Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

1. Locations

Locations: MAIN FLOOR: • Master Bathroom#1 • Bathroom#2

2. General Pictures Condition

Observations:

~

No Apparent General Issues with the bathrooms



Bathroom#2



Master Bathroom

3. Cabinets



Observations:

• Appeared functional and in satisfactory condition, at time of inspection.



Bathroom#2



Bathroom#2

4. Ceiling Condition



Materials: There are drywall ceilings noted. Observations:

No Apparent Issues with the Ceilings

5. Floor Condition



Materials: Ceramic tile is noted. Observations:

- Bathroom#2--Damaged grout observed, suggest re-grouting as necessary.
 Bathroom#2--Recommend sealing cracks/voids.
 Bathroom#2--Recommend caulking at the tub and shower areas



Bathroom#2 Caulking Needed

6. Bathroom Wall(s) Condition



Observations:

- No Apparent Issues with the Bathroom Wall(s) in either Bathroom
- Drywall
- Rock Veneer



Master Bathroom

7. Counters



Observations:

- Ceramic Tile
- No discrepancies noted.



Bathroom#2 Ceramic Tile

8. Sinks



Observations:

- **DRAINS**
- No Apparent Issues with the Drains
- **SUPPLY**
- No Apparent Issues with the Supply

9. Toilets



Observations:

- Observed as functional and in good visual condition.
- Operated when tested. No deficiencies noted.



Bathroom#2

10. Electrical



Observations:

No Apparent Issues with the Electrical

11. GFCI



Observations:

- GFCI in place and operational
- GFCI is Looking pretty Old in the Master Bathroom. This could be why Bathroom#2 is not protected. As of 1975 all bathrooms should be GFCI protected. So either the Master Bathroom is going bad or another needs to be installed in Bathroom#2
- Bathroom#2--No GFCI protection present, suggest installing GFCI protected receptacles for safety.



Bathroom#2 not Protected



Master Bathroom--Kind of old Might want to replace

12. Mirrors



Observations:

No Apparent Issues with the Mirrors

13. Heating



Observations:

• Central heating noted in this room. At the time of the inspection, all appeared to be functioning and in serviceable condition.

14. Plumbing



Observations:

No Apparent Issues with the Plumbing



Bathroom#2



Master Bathroom

15. Showers



Observations:

- **SHOWER BASE**
- functional
- **SHOWER FAUCET**
- Functional
- **SHOWER DOORS**
- Functional



Bathroom#2

16. Shower Walls



Observations:

- **MATERIALS**
- · Ceramic tile noted.
- Caulking needed around perimeter.
- Missing/damaged grout observed, suggest regrouting as necessary.



Bsthroom#2



Bathroom#2

17. Enclosure



Observations:

• The shower enclosure was functional at the time of the inspection.

18. Bath Tubs



Observations:

- Tub
- No Apparent Issues with the TubWhirlpool
- No Apparent Issues with the Whirlpool Tub




Bathroom#2



Master Bathroom

19. Window Condition







Bathroom#2

20. Doors



Observations:

No Apparent Issues with the Doors



Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

1. Refrigerator Condition



Observations:

- REFRIGERATOR OVERALL:
- COOLER PORTION:
- Excellent
- FREEZER PORTION:
- Excellent



2. Cabinets



Observations:

• Appeared functional and in satisfactory condition, at time of inspection.



3. Counters



Observations:

- Ceramic Tile
- No discrepancies noted.



4. Dishwasher



Observations:

Operated.

5. Garbage Disposal



Observations:

• Operated - appeared functional at time of inspection.



6. Microwave



Observations:

• Built-in microwave ovens are tested using normal operating controls. Unit was tested and appeared to be serviceable at time of inspection. Leak and/or efficiency testing is beyond the scope of this inspection. If concerned, client should seek further review by qualified technician prior to closing.



7. Double Oven Condition



Materials: ELECTRIC Observations:

- UPPER OVEN:
- Functioned Correctly at the time of the Inspection
- LOWER OVEN:
- Functioned Correctly at the Time of the Inspection



8. Sinks



Observations:

- **DRAINS**
- No Apparent Issues with the Drains
- **SUPPLY**
- · No Apparent Issues with the Supply



9. Drinking Fountain



Observations:

• There was no drinking fountain present in this kitchen.

10. Spray Wand



Observations:

• The spray wand was operated and was functional.



11. Hot Water Dispenser



Observations:

No Hot water Dispenser

12. Soap Dispenser



Observations:

• The soap dispenser was functional.



13. Vent Condition



Materials: Recirculating

Observations:

No Apparent Issues with the Venting

14. Window Condition



Materials: Aluminum framed sliding window noted.



15. Floor Condition



Materials: Ceramic tile is noted. Observations:

- No Apparent Issues with the Flooring
- Numerous cracked tiles noted.





Cracks in the Kitchen Tile Flooring

16. Plumbing



Observations:

No Apparent Issues with the Plumbing



17. Ceiling Condition



Materials: There are drywall ceilings noted. • There is panel lighting present in the ceiling. Observations:

· No Apparent issues with the Ceilings

18. Electrical



Observations:

No Apparent Issues with the Electrical

19. GFCI



Observations:

• GFCI protected receptacles may not have been required when the house was built. We suggest buyer consider upgrading with GFCI's at all receptacles near water sources.

20. Wall Condition



Materials: Drywall walls noted.

Observations:

No Apparent Issues with the Walls



Laundry

1. Locations

Locations: Laundry Room

2. Cabinets



Observations:

Appeared functional and in satisfactory condition, at time of inspection.



3. Laundry Units Condition



Materials: SIDE-BY-SIDE • Washer & Gas Dryer Observations:

• No Apparent Issues with the Side-By-Side Units



4. Dryer Vent



Observations:

No Apparent Issues with the Dryer vent



5. Electrical



Observations:

No Apparent Issues with the Electrical



6. GFCI



Observations:

• The receptacles near laundry machines are polarized and should be GFCI

7. Gas Valves



Observations:

• Gas shut off valves were present and functional.



8. Plumbing



Observations:

• No Apparent Issues with the Plumbing



9. Floor Condition



Materials: Sheet vinyl flooring is noted.



10. Wall Condition



Materials: Drywall walls noted.

Observations:

No Apparent Issues with the walls

11. Ceiling Condition



Materials: There are drywall ceilings noted.

Observations:

• No Apparent Issues with the Ceilings

12. Doors



Observations:

No Apparent Issues with the Doors





The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Heater Condition



Materials: Location: • The furnace is located in the crawlspace Observations:

• Fuel Furnace: Last service date is over one year ago, or is unable to be determined. Although this unit appears to be operating properly from controls, there are areas which cannot be seen without specialized equipment and training. One such area is the combustion chamber / heat exchanger where cold air blows across the "fire box", becoming the hot air that circulates throughout your home. During the life span of any furnace, this metal wall may develop a crack or a broken weld, allowing carbon monoxide to circulate throughout the home. This is why furnace specialists recommend a complete inspection annually; consider having unit inspected by certified HVAC technician.

2. Heater Base



Observations:

The heater base appears to be functional.

3. Enclosure



Observations:

No Apparent Issues with the Enclosure



4. Venting



Observations:

- **VENTING OBSERVATIONS**
- The visible portions of the vent pipes appeared functional.



5. Gas Valves



Observations:
• Gas shut off valves were present and functional.



6. Air Supply



Observations:

• The return air supply system appears to be functional.



7. Registers



Observations:

• The return air supply system appears to be functional.



Living Room





Bathroom#2



Bedroom#3

8. Filters



Location: Located in a filter grill in a hall area wall. Observations:

• MAINTENANCE: The air filter(s) should be inspected at least monthly and cleaned or replaced as required. There are two types of filters commonly used: (1) Washable filters, (constructed of aluminum mesh, foam, or reinforced fibers) these may be cleaned by soaking in mild detergent and rising with water. Or (2) Fiberglass disposable filters that must be REPLACED before they become clogged. Remember that dirty filters are the most common cause of inadequate heating or cooling performance.



Size of Filter--14X30X1.

9. Thermostats



Observations:

- Location: Hallway
- Analog, non-programmable type.
- Functional at the time of inspection.
- IMPROVE: Non-programmable thermostats have no energy saving capabilities as do digital setback-type thermostats. Recommend an upgrade to a modern, digital programmable thermostat. This could yield a saving of up to \$180 per year in energy costs.
- Thermostat only turns unit On & Off and is not being controlled by the temperature at all. Walked into a very warm house. Turned down still would not go off had to physically Turn off the Unit for it to go Off. Thermostat needs to be replaced to work correctly.



This is Bad it needs to be replaced it only turns On & Off and does not function correctly with temperature.



Garage

1. Roof Condition



Materials: Inspected from ladder. Materials: Asphalt shingles noted.

Observations:

• Clean roof areas: Significant amounts of organic debris evident.



South Side

2. Walls



Observations:

• Appeared satisfactory, at time of inspection.



Firewall Complete

3. Anchor Bolts



Observations:

• The anchor bolts were not visible, obscured by drywall.

4. Floor Condition



Materials: Bare concrete floors noted. Observations:

Observations.

Common cracks noted.



Crack in the Garage Flooring

5. Rafters & Ceiling



Observations:

• Limited review due to finished ceilings.



6. Electrical



Observations:

No apparent issues with the Electrical

7. GFCI



Observations:

GFCI in place and operational



8. 240 Volt



Observations:

• The 240 volt outlets tested functional.



Functions correctly

9. Exterior Door



Observations:

• No Apparent Issues with the water Heater



10. Fire Door



Observations:

• The automatic closure device does not close the door properly. This could allow a fire to enter the home. Recommend adjusting or replacing the hinges to allow for proper closure of the door.



Does not close completely.

11. Garage Door Condition



Materials: Sectional door noted.

- Observations:
 No Apparent Issues with the Garage Door
 No deficiencies observed.



12. Garage Door Parts

Observations:



• The garage door appeared functional during the inspection.



Garage Door Handle is not secured to the door it just falls out when touched

13. Garage Opener Status



Observations:

- Screw drive opener noted.
- There appears to be an older model garage door opener without safety features.
- Garage Door only goes up about 4 inches and stops motor still trying but stops. Cannot figure out what was holding it up. Either door in tracks has issue or older door opener just cannot do it anymore.



Screw Driven



Something is wrong with Garage Door Opener. Either it is too old to do the job anymore or, Something is wrong in the Tracks or wheels because it stops after about 6 inches.

14. Garage Door's Reverse Status



15. Stairs & Handrails Condition



Observations:

- No Apparent Issues with the Steps
 Handrail is a Little Loose
- Landing Area may not be tall enough to need a railing. Recommend placing one along the yellow line just for the safety factor of someone falling off.



Handrail is a Little loose



Not Actually required but recommend railing around the Landing Deck



Electrical

This report describes the amperage and voltage rating of the service, the location of the main disconnect and any sub panel(s), the presence of solid conductor aluminum branch circuit wiring, the presence or absence of smoke detectors and wiring methods. Inspectors are required to inspect the viewable portions of the service drop from the utility to the house, the service entrance conductors, cables and raceways, the service equipment and main disconnects, the service grounding, the interior components of the service panels and sub panels, the conductors, the over-current protection devices (fuses or breakers), ground fault circuit interrupters and a representative number of installed lighting fixtures, switches and receptacles. All issues or concerns listed in this Electrical section should be construed as current and a potential personal safety or fire hazard. Repairs should be a priority, and should be made by a qualified, licensed electrician.

1. Electrical Panel



Location: Main Location: • North side of the house. Observations:

No Apparent Issues with the Electrical Panel



2. Main Amp Breaker



Observations:

• 100 amp



3. Breakers in off position



Observations:

• 0



Zero

4. Cable Feeds



Observations:

- There is an overhead service drop noted.
- When utility company wires coming into the service mast are sagging, frayed, strung through trees, or otherwise appear improper, the client is advised to contact the utility company prior to closing to correct the condition or verify its safety.





Tree interfering with drop Line.

5. Breakers



Materials: Copper non-metallic sheathed cable noted. Observations:

• All of the circuit breakers appeared serviceable.



1. Roof Condition



Materials: Inspected from ladder. Materials: Asphalt shingles noted.

Observations:

• Clean roof areas: Significant amounts of organic debris evident.



East Side



East Side

2. Flashing



Observations:

• No Apparent Issues with the Flashing

3. Chimney



Observations:

No Apparent Issues with the Chimney





4. Spark Arrestor



Observations:

• No Apparent Issues with the Spark Arrestor.



5. Vent Caps



Observations:


No Apparent Issues with the Vent Caps

6. Gutter



Observations:

- No Apparent Issues with the Gutters
 Clean gutters: Significant amounts of debris evident.
 Extensions / Splash blocks missing or insufficient: Install to divert water away from the foundation.



Gutters are filled with Pine Needles. These should be cleared.



Northeast Corner



Southeast Corner--Monitor the area and see if water builds up here at the Foundation wall, if it does need to make it move along as too not continually soak the Foundation Wall



South Side



Attic

This report describes the method used to inspect any accessible attics; and describes the insulation and vapor retarders used in unfinished spaces when readily accessible and the absence of insulation in unfinished spaces at conditioned surfaces. Inspectors are required to inspect insulation and vapor retarders in unfinished spaces when accessible and passive/mechanical ventilation of attic areas, if present.

1. Access



Observations:

- **Location of access**
- Bedroom#2 Closet.

2. Structure



Observations:

• No Apparent Issues with the Structure





3. Ventilation



Observations:

No Visible Ventilation noted.

4. Vent Screens



5. Electrical



Observations:

No Apparent Issues with the Electrical



6. Attic Plumbing



Observations:

• ABS (Acrylonitrile-Butadiene-Styrene)(black in color) - plumbing vent piping



7. Insulation Condition



Materials: Unfinished fiberglass batts noted. Depth: Insulation averages about 6-8 inches in depth







Exterior Areas

This section describes the exterior wall coverings and trim. Inspectors are required to inspect the exterior wall coverings, flashing, trim, all exterior doors, the stoops, steps porches and their associated railings, any attached decks and balconies and eaves, soffits and fascias accessible from ground level.

1. Doors



Observations:

• Appeared in functional and in satisfactory condition, at time of inspection.



Front door

2. Window Condition



Observations:

- No Apparent Issues with the Windows
- Peeling paint observed, suggest scraping and painting as necessary.





South Side--Peeling Paint & Bare Wood Observed

3. Siding Condition



Materials: Wood siding, wood frame construction, concrete / block foundation • Brick veneer noted.

Observations:


- Caulk and seal all gaps, cracks and openings.
- Some siding deterioration noted. Have repaired as necessary.
- Brick Veneer Top Concrete Pour is cracked the entire Length along the Garage North Wall



Cracked across the top of the brick veneer




Garage North Wall--Wood Pecker Activity



North House Wall--More Wood **Pecker Activity**



East Side by Rear Door



South Side--More Wood Pecker Activity

4. Eaves & Facia



Observations:

• No Apparent Issues with the Eaves



5. Exterior Paint



Observations:

- No Apparent Issues with the Paint
 Peeling paint observed, suggest scraping and painting as necessary.



Foundation

This report describes the foundation, floor, wall, ceiling and roof structures and the method used to inspect any accessible under floor crawlspace areas. Inspectors inspect and probe the structural components of the home, including the foundation and framing, where deterioration is suspected or where clear indications of possible deterioration exist. Probing is not done when doing so will damage finished surfaces or when no deterioration is visible or presumed to exist. Inspectors are not required to offer an opinion as to the structural adequacy of any structural systems or components or provide architectural services or an engineering or structural analysis of any kind. Despite all efforts, it is impossible for a home inspection to provide any guaranty that the foundation, and the overall structure and structural elements of the building is sound.

1. Slab Foundation



Observations:

Raised Foundation Only.

2. Foundation Perimeter



Observations:

- No Apparent Issues with the Foundation Perimeter
- Cracks and deterioration observed.

3. Foundation Walls



Observations:

- Normal settlement.
- Efflorescence observed; this is a mineral deposit left behind from exterior water infiltration.



Efflorescence Observed

4. Cripple Walls



Observations:

Concrete block/wood piers support floor above.

• Big Crack in the Stem Wall. Recommend further evaluation by a handyman or General Contractor for Answers & Options to this Issue.





Big Crack in the Stem Wall

5. Ventilation



Observations:

• Screened openings noted.



West Side



6. Vent Screens



Observations:

• Vent screens noted as functional.



North Side

7. Access Panel



Observations:

• The foundation access panel installed and functional during the inspection.

North Side

8. Post and Girders



Observations:

Concrete block/wood piers support floor above.





436 Dorset Drive, Big Bear City, CA

9. Sub Flooring



- Observations:
 DECKING
- Plywood sheathing sub floor.



10. Anchor Bolts



Observations:

• The anchor bolts were inspected and appear to be serviceable.



11. Foundation Electrical



Observations:

No Apparent Issues with the Electrical



12. Foundation Plumbing



Observations: • **SUPPLY**

- 1 inch Copper
 DRAIN, WASTE, VENT
 Acrylonitrile-Butadiene-Stryrene "ABS" waste and vent pipes noted.
 OBSERVATIONS
- Appears Functional at time of inspection.



Copper



A.B.S. Piping



13. Foundation Insulation Condition




Observations:

No Apparent Issues with the Insulation



14. Ducting





Observations:
• Appeared functional, at time of inspection.







Grounds

Inspectors shall inspect adjacent or entryway walkways, patios, and driveways; vegetation, grading, surface drainage, and retaining walls that are likely to adversely affect the building.

1. City Main Water Valve Condition



Observations:

• No Apparent Issues with the City Main Water Valve



How says facing West facing house far right side of garage 2' from driveway


2. Stop & Waste Valve Condition



Observations:

Multiple Stop & Waste Valves all working Correctly







Left of the Front Stairs Yellow T Handle

3. Driveway and Walkway Condition



Materials: Concrete driveway noted. Observations:

- Minor settlement, or "hairline" cracks in driveways, are normal for properties of any age. They should, however, be monitored for expansion and sealed as necessary.
- Concrete spalling noted at driveway. This loosening of the top, smooth layer of the cement is a common occurrence, possibly due to an improper curing process, age, or use of snow-melting materials.
- Potential Trip Hazard(s) at driveway; monitor / repair as necessary



Concrete Driveway



Spalling on the Driveway



Possible tripping hazard going in garage



4. Grading



Observations:

• The exterior drainage is generally away from foundation.

5. Vegetation Observations



Observations:

- Prune or remove any plants that are in contact or proximity to home to eliminate pathways of wood destroying insects.
 Tree limbs within 10 feet of roof should be trimmed away to provide air and sunlight to
- roof, while minimizing debris & dampness.
- Trim trees that are in contact or proximity to home, as branches can abrade roofing or sidina.
- Tree branches overhanging roof and/or against siding. Trim trees that are in contact or proximity to home, as branches can abrade siding and damage roofing.
- Trees that grow too close, or overhang property, should be trimmed back. This will help reduce the frequency of having to clean out the gutters, which should be done on a regular basis.









South Side

6. Gate Condition



Materials: Wood • Wrought iron

Observations:

• No Apparent Issues with the Gates



7. Patio and Porch Deck



Observations:

- Appeared functional at time of inspection.Deck Railing is Loose



Front Deck



Railing Loose



Rear Deck Railing is Loose

8. Stairs & Handrail



Observations:

Handrails are loose



Handrail is Loose



Stair Steps are good



Rear Deck Both Handrails

9. Grounds Electrical



Observations:

- No Apparent Issues with the ElectricalOUTLETS:
- No Apparent Issues with the Outlets



10. GFCI



Observations:

None visible.

11. Main Gas Valve Condition



Materials: South side.

Observations:

• Meter located at exterior. All gas appliances have cut-off valves in line at each unit. No gas odors detected.



South Side

12. Gas Line Condition



Observations:

• No Apparent Issues with the Gas Line on the Back Deck For the BBQ.



Back Deck

13. Plumbing



Observations:

- No Apparent Issues with the PlumbingThe Clean Out was Observed



Clean Out Left of the T Handle

14. Exterior Faucet Condition



Location: East side of house. • West side of house.

Observations:

Appears Functional.



West Side



East Side

15. Balcony



16. Patio Enclosure



Observations:

• Appears in satisfactory and functional condition with normal wear for its age. Appears to be sound structure.



Front Porch Covering

17. Fence Condition



Materials: Stone • Brick Observations:

- RETAINING/GARDEN WALL

- Retaining wall is leaning.
 Damaged/ missing mortar observed, suggest tuckpointing as necessary.
 Recommend review by a qualified professional for repair or replacement, as necessary.



Front Yard--Garden Wall Coming Apart.



Back Yard--Brick Garden Wall next to Walkway Crack in the Wall





Rear Yard Major Crack in the Stone Veneer

18. Sprinklers



Observations:

• Home is equipped with an underground sprinkler system. The inspector recommends client consult with home owner for operation instructions and proper winterizing information. Sprinkler systems are beyond the scope of a Home Inspection, due to most of its parts/piping not visible for inspection.



Next to front Steps



Behind Front Steps



West Side



Tankless Water Heater

1. Enclosure Condition



Observations:

No Apparent Issues with the Enclosure



2. Electrical Condition



Observations:

• No Apparent Issues with the Gas valve



3. Gas Valve Condition



Observations:

• No Apparent Issues with the Gas Valve



4. Plumbing Condition



Observations:

• No Apparent Issues with the Plumbing



5. Tank-Less Venting Condition



Observations:

No Apparent Issues with the Venting



6. T.P.R.Valve Condition



Observations:

• No Apparent Issues with the T.P.R. Valve



7. Overflow Condition



Observations:

No Apparent Issues with the Overflow Piping



Kitchen Island

1. Island Top Condition



Materials: Ceramic Tile

Observations:

No Apparent Issues with the Island Top

2. Island Storage Condition



Observations:

• No Apparent Issues with the Storage



3. Island Cook Top Condition



Observations:

No Apparent Issues with the Cook Top



Breakfast Bar

1. Breakfast Bar Top Condition



Materials: Ceramic Tile Observations:

No Apparent Issues with the Top





2. Breakfast Bar Electrical Condition



Observations:

• No Apparent Issues with the Electrical

3. Breakfast Bar GFCI Condition



Observations:

• No GFCI's Observed

4. Breakfast Bar Storage Condition



Observations:

· No Apparent Issues with the Storage







Glossary

Term	Definition
ABS	Acronym for acrylonitrile butadiene styrene; rigid black plastic pipe used only for drain lines.
GFCI	A special device that is intended for the protection of personnel by de-energizing a circuit, capable of opening the circuit when even a small amount of current is flowing through the grounding system.

Big Bear Home Inspectors Utilities & Service Providers List						
909-547-4017 Don D'Angelo bigbearhomeinspectors.com bigbearhomeinspectors@gmail.com						
Appliance Sales & Re		Glass Companies				
A & S Appliance	909-547-0809	Bear City Glass	909-585-2037			
Big Bear Appliance	909-866-3838	Best Windows & Doors	909-838-8354			
Kimbo's	909-585-2244	Handyman	303-030-0334			
Audio & Video Te		Cesar Garcia	909-709-7240			
Hot Sounds	909-518-0239	David Silva	909-255-2786			
Carpet Cleaning / Water Dam		Big Bear Hanyman - John Reeves	909-746-7595			
Adavance Carpet (Randy)	909-585-7451	big bear framyman - John Reeves	303-740-7333			
Bear Valley Carpet (Andy)	909-866-8303	Heating & Air				
Chimney Cleaner		J & M Mechanical - Jeff	909-936-3361			
Chimney Krikket's	909-866-5692	Bear Valley Heating - Tony	909-585-1232			
Mountain Top Chimney	909-585-3724	Patriot Bear Heating - Chase	909-261-4609			
Sweep Lucky Chimmey & Duct Cleaning	909-337-0256	House Cleaning	303-201-4003			
Electric	303-337-0230	Suzy Morals	909-708-7595			
Bob Ludecke	909-866-1900	Marabel Bernal	909-838-4084			
Bolt Electric	909-585-2272	Nicole Kosic	909-944-3610			
Danny Lopez	909-831-4437	Tina Blackwell	909-915-5606			
Don Collins	951-751-8922	Landscape	303 313 3000			
Rich Electric	909-584-7653	Raul Bernal Landscaping	909-890-6346			
Excavating Contract		Jesus Bernal Landscaping	909-838-4084			
Acosta Corporation	909-866-9634	Stalcup	909-866-9696			
Hallstead Constriction	909-866-3632	Locksmith	303 000 3030			
Ken Willis	909-585-3224	A-Kenn's	909-866-8336			
Fencing	303 303 322 1	ABC Lock & Key - Alan	909-732-4724			
All Fence	909-585-9011	Masonry Contracto				
Leoco	909-585-2139	Gordon Equipment	909-584-4606			
Flooring		Jack's Masonry 951-233-077				
A Class Flooring - Christian	909-800-2946	Marty's Masonry	909-585-6480			
Carpet Barn (Sales)	909-366-5021	Painting				
Interiors (Sales)	909-866-2252	Carlos Navaro	909-709-9233			
Garage Doors		Chango's Painting	909-744-0396			
Garage Door Kings	909-440-0305	EG Painting - Edgar Guevara	909-534-6374			
General Contracto	rs	Plumbing				
Auer Construction - Hans Auer	760-803-8545	J & M Mechanical -Jeff	909-936-3361			
Bain Constuction - Mike Bain	909-838-8892	Joe Nickles	909-866-5363			
Farrar Construction -Dean Farrar	909-725-8897	Ron Ewell	909-936-3053			
Home Improvments -Michael Beveri	_	AR Joens Plumbing	909-496-6324			
Joshua Hastings Construction Pfeiffer Construction - John	909-273-0130 909-520-8246	Leon's Drain & Plumbing (Camera) 909-496-2358			

Big Bear Home Inspectors Utilities & Service Providers List						
Vacation Rental Management Companies		Tree Trimmers				
Big Bear Vacations - Christina	909-866-8200	Sailin Perrin	909-380-1954			
Cool Cabins - Karie Davis	800-550-8779	John Reeves	909-746-7595			
Denstination Big Bear	909-752-0234	Bear Valley Tree Care - Ed Brush	909-584-7862			
Smaller Vacation Rental Management Companies		Raul Bernal	909-890-6346			
TurnKey Vacation Rental	909-345-0930	Utilities				
Village Reservation-Melissa Karne	s 909-379-2870	Big Bear City Community Service Dist.	909-585-2565			
Vacation Rental Air B & B Managers		Big Bear Lake City Hall	909-866-5831			
Nick Pacuilli	909-436-0526	Bear Valley Electric	909-866-4678			
Shon & Tina Blackwell	909-915-5606	Bear City Water (BBC CSD)	909-585-2565			
Roofers		Big Bear City(Building & Safety) 9	09-866-5831			
David Quijas	909-648-9481	Dept. of Water & Power (BB Lake)	909-866-5050			
Dave Beckett	909-991-9537	Big Bear Disposal	909-866-3942			
MJ Roofing	909-380-1038	Connelly Pumping Sewage Holding tank	909-584-9365			
Sturdy Roofing	909-585-2508	Mountain Water (Holding tank & Bottled)	909-866-4765			
Spa/Hot Tub		Southwest Gas	877-860-6020			
Mike Raphael - Spa service	909-648-4211	Thomas Gas (Propane)	909-866-3513			
Olson Spa's - Sale, Service & Repairs	909-366-5309	Ferrell Gas (Propane)	909-866-4605			
Snow Removal		CSA (Fawnskin Sewer)	800-554-0565			
Cesar Garcia	909-709-7240	Spectrum Cable,TV, Interent & Phone	866-499-8080			
Mike Bain	909-838-8892	Verizon Interent & Phone	800-483-4000			
Raul Bernal	909-890-6346					
Security System Companies		Water Systems / Home Fire Sprinkler System Testing				
All Protection Alarm	909-866-6586	Bear Valley Backflow	909-677-7875			
Termite Companie		Martin Fire & BackFlow	909-659-4699			
Burkitt's Bugs	909-337-9528	Water/Fire/Smoke/Mold Damage				
Empire Termite	909-744-8890	Servpro 90	09-866-3278			
Transfer & Storage		Action Response Team 9	09-585-9019			
Barstow Transfer & Storage	800-726-7211	Well Inspection & Certification				
Surveyors			09-866-6644			
· · · · · · · · · · · · · · · · · · ·	909-866-8400	Window Cleaning				
Smith Surveying	909-584-7911	Shon Blackwell	909-915-5606			
Rental Management Companies - Full Time		Above All Window Cleaning	909-269-0315			
Bear Lake Resort Rental	909-585-2556					
Blue Skies	909-866-8600		Page 2 of 2			