



External Refurbishment Works

- Lower Ground Steps / Structural Underpinning
- Raised Ground Floor
- First Floor Balustrade



Collapsing Steps [before]



Structurally Supported Reclad Steps [after]



Collapsing Vault Lintels Internal [before]



New Vault Lintels Internal [after]




Collapsing Vault Lintels External [before]



New Vault Lintels External [after]




Collapsing LG Steps [before]



New Supported LG Steps [after]



Dilapidated External Vaults Collapsing Supporting Walls & Steps [before]



Structurally Rebuilt External Vaults Walls & Steps [after]



Dilapidated Unsupported Underside Portico [before]



Structurally Underpinned Underside Portico [after]

F. Structurally Underpinned Portico [after]



Dilapidated Unsupported LG Steps [before]



Reclad Supported LG Steps with safety lighting [after]



Destroyed Listed Sill Detail [before]



Restored Listed Sill Detail [after] including cable management



Existing LGF Entrance [before]



Existing LGF Entrance Reclad With Added Molding [during]



Existing LGF Entrance Finished [after]

LGF Entrance
[before & after] plywood
paneling & beading
added to match main
entrance street level door.



Existing LGF Gas Meter Cupboard [before]



Existing LGF Gas Meter Cupboard Reclad With Added Molding [during]



Existing LGF Gas Meter Cupboard [finished]

LGF gas meter cupboards
[before & after] removed
and saved during flooring
works reclad and reinstalled.



General Construction Photos





General Construction Photos





General Construction Photos





General Construction Photos

