Lateral Inspection Report

Measured from MH **Tap Location** Material Lateral Seg. Ref. City Polyvinyl Chloride ACS Building - Old C36 Elbow Lake, Mn Building **Building Address** Surveyed By **Certificate Number** Street Chase Johnson U-312-14864 Central Avenue N Direction **Purpose** Weather **Date** Length Surveyed Routine Assessment 4/28/2021 Upstream 2:36 PM **Additional Information** 2021 Sanitary Sewer - Elbow Lake, MN Ftg. Code Description **Position Comment** 53.6 MSA Survey Abandoned Cleanout could be busted and leaking water •53.6 DNGV Deposits Ingress: Gravel 4 to 9 43.6 IW Infiltration - Weeper 6 to 6 **4**1.5 Infiltration - Runner 3 to 5 37.3 MGO General Observation Pipe joint connection with fernco. Could be leaking some water LR Line - Right [™]0.0 MWL Water Level

⁰0.0 ACOM Access Point - Cleanout: Mainline

ACS Building - Old Building